

Bennington Armory Indoor Firing Range

PO BOX 6893, DOUGLASVILLE, GEORGIA 30154
PHONE: 678.596.8509 • FAX: 770.234.6297

Table of Contents

Executive Summary.....	Page 1
Subject	Page 2
Background	
Introduction	
Site Description	
Scope of Work	
Health effects and hazard determination	
Findings, Discussion, and Recommendations	Page 3
Appendices	
A. References	
B. RAC Table	
C. Decontamination and Cleaning Protocol	
D. Photographs, Range Drawings	
E. Wipe Sampling Results	

EXECUTIVE SUMMARY

FINDINGS	RECOMMENDATIONS	RAC
<i>The Bennington indoor firing range has not been fired on since 1992. The range is listed as active, however offices have been put in this area as well as storage items to include lockers</i>	An official decision as to the status of this range should be immediately determined. If the range is to remain active, it must meet requirements set forth in NGR 385-15. If the range is to be converted, it must be adequately cleaned and decontaminated before employee use can resume.	RAC 2
<i>Seven out of eighteen wipe sample results were above the maximum allowable limit of 200 micrograms per square foot. It is unclear what type of protocol janitors cleaning this range used.</i>	If the range is to be converted, it must be cleaned in accordance with National Guard Regulations before employee use can resume.	RAC 2

SUBJECT: Industrial Hygiene Survey of the Bennington Indoor Firing Range Survey performed 17 October 2000 at Bennington Armory, VT.

BACKGROUND:

Introduction. At the request of Ms. [Non-Responsive] of the National Guard Bureau Region North Industrial Hygiene Office, an industrial hygiene survey was performed at the Bennington Indoor Firing Range at the Bennington Armory in Vermont. Ms. [Non-Responsive] and Mr. [Non-Responsive] Regional Industrial Hygienists, and CPT [Non-Responsive] Occupational Health Nurse, Vermont Army National Guard, conducted the survey on 17 October 2000. The purpose of the survey was to perform a comprehensive industrial hygiene survey to evaluate range characteristics, ventilation, and quantify employee exposure to lead dust.

Site Description. The Bennington Indoor Firing Range was cleaned in March or April of 2000. The sand and bullet trap were removed at the same time. After cleaning, contractors painted the range, however, it is unknown whether a sealant was used. The range is now used as a supply room and office area. The range has not officially been closed and is still listed as an active range.

Scope of Work. The Indoor Firing Range was visually examined and personnel were consulted to accurately assess potential hazards present. The range was evaluated using the wipe sampling protocol used in the National Guard Pamphlet 385-16, which addresses Indoor Firing Range conversion to other uses. Reference information, Instrumentation, Methodology, and Assessment Criteria can be found in Appendix A.

Health Effects and Hazard Determination. The most significant hazard present to employees and users of the indoor firing range is lead dust. Shooters using ammunition with lead primers or bullets manufactured with lead are exposed to lead fumes and dust during the firing process. Furthermore, the lead found in the primer, the melting of the bullet base by hot powder gasses, the shaving and abrasion of the bullet during firing, and fragmentation of the bullet at the point of impact are all potential sources for lead. Further exposure to lead may occur during cleaning of the range, guns, or bullet trap where lead dust is deposited. Lead deposits resulting from firing activities can build up in a firing range over time and must be adequately cleaned and sealed before the range is used for other purposes. If the range is not properly cleaned, the potential for exposure to employees who use the converted area remains.

Lead affects the nervous, circulatory, digestive, excretory, and reproductive systems of both men and women. Lead can build up in the body affecting the blood, heart, and immune systems, if the amount absorbed and stored in the body exceeds the body's ability to expel it. In children, slowed cognitive development and reduced growth are results of overexposure. Pregnant women overexposed to lead are more prone to spontaneous abortions or may give birth to babies with a low birth weight and slowed postnatal neurological development.

FINDINGS, DISCUSSION, AND RECOMMENDATIONS

Seven out of the eighteen wipe samples taken inside the range exceeded the limit of 200 micrograms per square foot. It is unknown, what type of protocol was used by janitors cleaning this range and it is apparent that lead contamination still exists. Light fixtures, walls, and beams, as well as a wipe sample taken in the office show high levels of contamination. The range is still listed as active, but has been converted to a supply office and storage area. If the range is to remain active, then all stored and office items must be removed and the range cannot be used for any other purpose than as a firing range. If the range will be officially closed and converted, the indoor firing range should be cleaned so that it is as free of lead dust as possible before the area is used for other purposes to include office space and storage. The protocol found in Appendix C should be used to clean the range and decontaminate items currently stored inside.

Recommendations.

1. Post signs restricting personnel from the range until it has been appropriately cleaned. (RAC 2)
2. No stored items should be handled or used until they have been thoroughly decontaminated. (RAC 2)
3. No eating, drinking, or use of tobacco products should occur in the area. [29 CFR 1910.1025 (i)(1)] (RAC 2)
4. Decide whether the range will be used for range activities (i.e. weapons qualification and firing) or if it would be better suited for storage and office space. The indoor firing range should not be used for both activities. [NGR 385-15, NG PAM 385-16] (RAC 2)
 - a. If the range is to remain active, the range cannot be used for any purpose other than firing. No equipment or furniture can be stored or maintained in the range. The range must meet all requirements of the National Guard Regulation 385-15 regarding Indoor Firing Ranges. Contact the Regional Industrial Hygiene Office regarding requirements. [NGR 385-15 1-18a, 1-17d] (RAC 2)
 - b. If the range is to be used as a storage area and office space, it must be thoroughly decontaminated, reevaluated, and approved prior to its use. Follow all described procedures for cleaning and decontamination of the range and all stored items found in Appendix C. **Contact the Regional Industrial Hygiene Office for approval and reevaluation prior to and after cleaning.** (RAC 2)

Non-Responsive

Industrial Hygienist

APPENDIX A

Environmental Management Solutions

REFERENCES

AR 40-5, Preventative Medicine, 15 October 1990.

AR 385-10, The Army Safety Program, 23 May 1988.

National Guard Regulation (NGR) 385-10, Army National Guard Safety and Occupational Health Program, 29 December 1989.

National Guard Regulation (NGR) 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges, 18 September 2000..

National Guard Pamphlet (NG PAM) 385-16, Guidelines for Converting Firing Ranges to Other Uses, 31 January 1994.

TB MED 503, The Army Industrial Hygiene Program, February 1985.

TB MED 502, Occupational Safety and Health Respiratory Protection Program..

Title 29 Code of Federal Regulations (CFR) 1910.1025, Lead.

Instrumentation

The industrial hygiene survey was conducted utilizing the following pieces of equipment:

Rite Aid Towelettes with Benzalkonium Chloride 1:750, 5% Denatured Alcohol
4" X 4" Template

Methodology:

- A. *Wipe Samples.* Wipe samples were taken utilizing the protocol as set forth by NG PAM 385-16, Guidelines for Converting Firing Ranges to Other Uses. Details of locations where wipe samples were taken can be found in Appendix D.

Assessment Criteria.

- A. *Wipe Samples.* Wipe sample results were compared with Ventilation rates were compared with the NG PAM 385-16, Guidelines for Converting Firing Ranges to Other Uses. See previous page for Reference information.
- B. *Risk Assessment Codes.* Risk Assessment Codes (RACs) are included in this report to quantify the risk of particular operations to employees and to establish funding priorities for corrective actions. RACs are assigned with regard to hazard severity and mishap probability. The type, length, and route of exposure are taken into consideration, as are the medical effects that would occur with such exposures. RAC criteria can be found in Appendix B.

APPENDIX B

Environmental Management Solutions

**DERIVING RISK ASSESSMENT CODES (RACs)
FOR HEALTH HAZARDS
(Ref: DOD Instruction 6055.1)**

STEP 1. Using the following procedures to assess points, determine the health hazard severity category (HHSC). The HHSC reflects the magnitude of exposure to a physical, chemical, or biological agent and the medical effects of exposure.

A. Exposure Points Assessed

		Exposure Conditions			
		<CT	Occasionally - >CT Always - <STD	>CT =STD	>STD
AER	NO	0	3	5	7
POSSIBLE?	YES	1-2	4	6	8

AER = Alternate exposure route, such as skin absorption, ingestion

CT = DoD component threshold that triggers surveillance actions, such as microWatts/cm², dB, parts per million

STD = DoD exposure limit, such as Threshold Limit Value and Permissible Exposure Limit

B. Medical Effects Points Assessed

<u>Condition</u>	<u>Points</u>
No medical effect, such as nuisance noise and nuisance odor	0
Temporary reversible illness requiring supportive treatment, such as eye irritation and sore throat	1-2
Temporary reversible illness with a variable but limited period of disability such as metal fume fever	3-4
Permanent, nonsevere illness or loss of capacity, such as permanent hearing loss	5-6
Permanent, severe, disabling, irreversible illness or death, such as asbestosis and lung cancer	7-8

C. Determine the HHSC by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>HHSC</u>
13-16	I
9-12	II
5-8	III
0-4	IV

STEP 2. Using the following guides to assess points, determine the mishap probability category (MPC) for health hazards. The probability of mishap reflects the duration of exposure and the number of exposed personnel.

A. Duration of Exposure Points Assessed

		<u>Length of Exposure</u>		
		1-8 hr/wk	>8 hr/wk continuous	not continuous
<u>Type of Exposure</u>	Irregular, intermittent	1-2	4-6	-
	Regular, periodic	2-3	5-7	8

B. Number of Exposed Personnel Points Assessed

<u>Number of Exposed Personnel</u>	<u>Points</u>
<5	1-2
5 to 9	3-4
to 49	5-6
>49	7-8

C. Determine the MPC for health hazards by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>MPC</u>
14-16	A
10-13	B
5-9	C
<5	D

STEP 3. Determine the RAC for health hazards by using the following matrix to measure health hazard severity and mishap probability factors.

		MISHAP PROBABILITY			
		A	B	C	D
HAZARD SEVERITY	I	1	1	2	3
	II	1	2	3	4
	III	2	3	4	5
	IV	3	4	5	5

APPENDIX C

Environmental Management Solutions

Decontamination and Cleaning Protocol

1. Ensure that all procedures listed below comply all federal, state, and local regulations. Consult the Regional Industrial Hygiene Office and State Environmental Office for further guidance.

2. **Ventilation System**
 - i. The range ventilation system must be in operation during all cleaning activities. If no ventilation system is available all doors and windows must be kept sealed to prevent contamination of other areas.

3. **Materials**
 - i. A High Efficiency Particulate Air (HEPA) filtered vacuum system is the preferred method of cleanup. If a HEPA vacuum cannot be obtained a wet method, detailed below, should be utilized. **A high-pressure water system or dry sweeping may not be used.**
 - ii. A cleaning solution containing detergent and water is recommended. New solutions of detergent and water should be mixed frequently.
 - iii. Two containers should be used; one for wetting the applicator (rags, sponge, mop) and the other for rinsing once the dust has been wiped from the surfaces.
 - iv. Wastewater in containers can be left to evaporate. Any waste left in the buckets and applicators should be disposed of as hazardous waste. Consult the Environmental Office for appropriate disposal instructions.
 - v. Personnel responsible for decontamination of the range and stored items should be provided with a full face air purifying respirator with a N100 filter or HEPA filter cartridge providing that all requirements for placing employees in respiratory protection have been met as detailed in 29 CFR 1910.134. Employees should be provided with protective coveralls with hood and shoe covers (i.e. Tyvek™ full body suit). Protective clothing should be hanged daily at the end of the shift and more frequently if the suit becomes grossly contaminated. If cotton coveralls are provided then the employer must provide for maintenance and laundering of protective clothing. Protective clothing should not be taken home and prior to leaving the work area, personnel should thoroughly HEPA vacuum clothing to prevent lead dust from leaving the area. Work and street clothing should not be stored together.

4. **Order of Cleaning**
 - i. A progression of cleaning from top to bottom and from behind the steel backstop to the firing line should be used. All surface areas in the range must be cleaned. Stored items must be decontaminated prior to removal.
 - ii. After removing the sand and the steel backstop, areas in front of and behind the bullet trap along with the steel backstop plates should be cleaned.
 - iii. The ceiling, lights, baffles, retrieval system, heating systems, and ventilation ducts should be cleaned.
 - iv. Acoustical material should be vacuumed instead of being painted over, A Toxic Characteristic Leaching Procedure (TCLP) may need to be used for


- acoustical material and the like to determine if the material need to be classified as hazardous and disposed of accordingly. The Environmental Office should be contacted regarding this testing.
- v. The floor should be the last surface cleaned starting at the bullet trap and ending behind the firing line. Concrete floors should be sealed with deck enamel and linoleum on tile floors should be waxed.
 - vi. All walls should be painted, preferably with a sealant, that will help prevent leaching of lead after covering.
 - vii. Following the wet cleaning of the area and after all surfaces have been allowed to dry thoroughly, a HEPA vacuum should be used on all surfaces, until no dust or residue can be seen. A through inspection to detect surface dust should be made following cleanup.
 - viii. The Regional Industrial Hygiene Office should be contacted for clearance sampling and to approve the range for converted use.
5. **Decontamination of stored items.**
- i. All stored items must be decontaminated before removing them from the range. Stored equipment next to the bullet trap and firing line should be decontaminated first.
 - ii. A HEPA vacuum or wet cleaning method should be used. Every attempt should be made to clean the item before disposing as hazardous waste to reduce cost and waste.
 - iii. Porous items such as canvas tents or other fabrics may be laundered at companies, which specialize in industrial laundry services. Office partitions and carpeting present during firing should be considered grossly contaminated and disposed of as hazardous waste. Consult the Environmental office before removing and disposing of items.
6. **Medical Surveillance.**
- i. A preplacement medical examination is required for all individuals involved with range cleanup operations.
7. **Air Monitoring.**
- i. Worker breathing zone air samples must be collected during range cleanup to ensure that workers are not overexposed and to evaluate clean up procedures.
8. **Hazard Training**
- i. A training program must be instituted for all individuals who are subject to exposure to lead at or above the action level of for whom the possibility of skin or eye irritation exists. This training should be provided for all personnel currently involved in rang cleanup operations at least annually.

APPENDIX D

Environmental Management Solutions

Bennington Indoor Firing Range

N →



Environmental Management Solutions

Bennington Indoor Firing Range



1. Supply Storage Area
2. Office Area
3. Office Area



APPENDIX E

Environmental Management Solutions

Sample Number	Location	Micrograms/Sample	Micrograms/Square Foot	Within Allowable Limits?
BEN-01	Back Wall 5' (East)	5.0	45.0	Y
BEN-02	Next to Back Wall Door 8'	<3	<27	Y
BEN-03	Back Wall 8"	5.4	48.6	Y
BEN-04	North Side Wall 6'	<3	<27	Y
BEN-05	North Side Wall 7'	<3	<27	Y
BEN-06	North Side Wall 10"	53	477	N
BEN-07	West Front Wall 6'	<3	<27	Y
BEN-08	West Front Wall 8'	<3	<27	Y
BEN-09	West Front Wall 8"	<3	<27	Y
BEN-10	South Side Wall 8'	<3	<27	Y
BEN-11	South Side Wall 10"	14	126	Y
BEN-12	South Side Wall 5'2"	25	225	N
BEN-13	East End Floor Under Small Desk (Floor)	100	900	N
BEN-14	Mid/Corner (Floor)	170	1530	N
BEN-15	Front Floor	77	693	N
BEN-16	Overhead Wood Beam (Center)(Ceiling)	48000	432000	N
BEN-17	On Top Light Fixture	52	468	N
BEN-18	On Top of Partition Wall 2X4 Support	11	99	Y
BEN-19	Blank	<3	<27	Y
BEN-20	Blank	<3	<27	Y

Environmental Management Solutions

NATIONAL GUARD BUREAU
ARMY NATIONAL GUARD
REGION NORTH INDUSTRIAL HYGIENE OFFICE
ATTN: NGB-AVN-SI
301-IH OLD BAY LANE
HAVRE DE GRACE, MD 21078-4094

NGB-AVN-SI (40-5f)

12 January 2001

MEMORANDUM FOR The Adjutant General, VT ARNG, ATTN: State Safety
Office (LTC **Non-Responsive**, G.M.A., Camp Johnson,
Colchester, VT 05446-3004

SUBJECT: Indoor Firing Range Survey at Bennington Armory

1. Enclosed is the industrial hygiene survey report prepared by Environmental Management Solutions. I concur with the overall recommendations made by Ms **Non-Responsive**
2. Please call me at 410/942-0273 ext. 17 if you have any questions or comments about this report.

Non-Responsive

Encl
Survey Report

Regional Industrial Hygienist

CF:
Unit Commander
Facility Engineer, COL **Non-Responsive**

Gosse Court Armory Indoor Firing Range

PO BOX 6892, DOUGLASVILLE, GEORGIA 30134
PHONE: 678.596.8509 • FAX: 770.234.6297

Table of Contents

Executive Summary.....	Page 1
Subject	Page 3
Background	
Introduction	
Site Description	
Scope of Work	
Health effects and hazard determination	
Findings and Recommendations	
a. Building envelope.....	Page 4
b. Range lighting.....	Page 4
c. Bullet traps.....	Page 5
d. Targets and target carriers.....	Page 5
e. Range use	Page 5
f. Range maintenance	Page 6
g. Personal protective equipment	Page 6
h. Posting of signs	Page 7
i. Range SOP.....	Page 7
j. Record keeping	Page 8
k. Ventilation.....	Page 9
l. Air sampling	Page 9
Range Status	Page 10
Appendices	
A. References	
B. RAC Table	
C. Photographs, Range Drawings	
D. Ventilation Measurements	
E. Air Sampling Results	

EXECUTIVE SUMMARY

FINDINGS	RECOMMENDATIONS	RAC
<i>This range has been classified as unsafe due to deficiencies in the building envelope and is limited use based on ventilation measurements and air sampling.</i>	Further use of this range is restricted until deficiencies in the building envelope have been corrected, reinspected, and approved. Range is classified as limited use on lanes 1, 2, and 5 after building envelope deficiencies have been corrected and until ventilation deficiencies are corrected, reinspected, and approved.	RAC 2
BUILDING ENVELOPE		
<i>All firing lanes are less than 4 feet wide.</i>	Re-mark firing lanes so that they are no less than 4 feet wide.	RAC 3
<i>Interior mortar joints are not flush with the interior surface of the range.</i>	Make all mortar joints flush with the interior surface.	RAC 2
<i>Access doors are not weather-stripped.</i>	Access doors should be weather-stripped and the locks should be fixed so that the door closes and locks properly.	RAC 2
RANGE LIGHTING		
<i>No emergency lights are provided in the range and exit lighting is burned out.</i>	Emergency exits and lights should be provided behind the firing line.	RAC 3
RANGE USE		
<i>Lockers, tables, chairs, and other items were found stored in the range.</i>	No items should be stored in the firing range at any time. Stored items should be decontaminated and removed.	RAC 2
<i>Stored items were found in front of the plenum wall.</i>	All items in front of the plenum wall should be decontaminated and removed from the range.	RAC 2
<i>Persons using the range are allowed to walk downrange.</i>	Only range custodians are allowed access downrange. Unauthorized personnel should not be permitted downrange.	RAC 2
<i>A fire extinguisher is not provided in the range.</i>	An ABC type fire extinguisher should be kept at the firing line in case of emergencies.	RAC 3
RANGE MAINTENANCE		
<i>Dry sweeping of the range is permitted and brooms indicating such were found in the area.</i>	Dry sweeping of indoor firing ranges is prohibited and should not be permitted.	RAC 2
POSTING OF SIGNS		
<i>Warning signs were not posted in the range.</i>	Post appropriate signs in the vicinity of the range and on the entrance door.	RAC 2

FINDINGS	RECOMMENDATIONS	RAC
RANGE SOP		
<i>Gasse Court Armory has no approved standing operation procedure</i>	Develop and implement a standing operation procedure.	RAC 2
RECORDKEEPING		
<i>No records of range training, maintenance, or cleaning are maintained.</i>	Maintain appropriate records regarding range operations and procedures	RAC 2
VENTILATION		
<i>Supply and exhaust fans are not interlocked with range lighting.</i>	Interlock supply and exhaust fans with range lighting.	RAC 3
<i>Ventilation flow rates were found below 50 fpm in different positions in the firing lanes.</i>	Holes in the plenum wall should be one inch in diameter and extended over the entire surface of the plenum wall.	RAC 2
<i>Flow rates at the plenum wall were less than the required 400 to 600 fpm</i>		
<i>More than 10 to 15% of the plenum wall is open.</i>		
<i>The plenum wall extends 4/5 of the way across the back wall.</i>	The plenum wall should extend across the entire back wall.	RAC 2
<i>Smoke tests revealed turbulence at the firing line observable in three and four.</i>	Correct ventilation system deficiencies to provide a uniform and even flow rate.	RAC 2
AIR SAMPLING		
<i>Air sampling results ranged from <0.014 to 0.093 mg/m³.</i>	Range is classified as limited use based on results of air sampling. Appropriate records must be kept for all persons using the range.	RAC 2

SUBJECT: Industrial Hygiene Survey of the Gosse Court Indoor Firing Range Survey performed 19 October 2000 at Gosse Court Armory, VT.

BACKGROUND:

Introduction. At the request of Ms. [Non-Responsive] of the National Guard Bureau Region North Industrial Hygiene Office, an industrial hygiene survey was performed at the Gosse Court Indoor Firing Range at the Gosse Court Armory in Vermont. [Non-Responsive] contract industrial hygienist, Ms. [Non-Responsive] and Mr. [Non-Responsive] Regional Industrial Hygienists, and CPT [Non-Responsive] Occupational Health Nurse, Vermont Army National Guard, conducted the survey on 19 October 2000. The purpose of the survey was to perform a comprehensive industrial hygiene survey to evaluate range characteristics, ventilation, and quantify employee exposure to lead dust.

Site Description. The Gosse Court Indoor Firing Range is used for weapons firing and qualification. The range is used by local gun clubs approximately two to three nights per week, by the air guard once per week, and by the National Guard one to two times per month. The range has five lanes and a mechanical ventilation system with a plenum that extends 4/5 of the way across the back wall.

Scope of Work. The Indoor Firing Range was visually examined and evaluated to assess potential hazards present. A range inspection checklist found in National Guard Regulation 385-15, which addresses Indoor Firing Range use and maintenance, was completed for the range. Smoke candles were utilized to observe airflow patterns in the range. Ventilation studies and air sampling was performed to quantify performance of the range and its effectiveness in reducing employee exposure to lead dust. Reference information and Instrumentation, Methodology, and Assessment Criteria can be found in Appendix A.

Health Effects and Hazard Determination. The most significant hazard present to employees and users of the indoor firing range is lead dust. Shooters using ammunition with lead primers or bullets manufactured with lead are exposed to lead fumes and dust during the firing process. Furthermore, the lead found in the primer, the melting of the bullet base by hot powder gasses, the shaving and abrasion of the bullet during firing, and fragmentation of the bullet at the point of impact are all potential sources for lead. Further exposure to lead may occur during cleaning of the range, guns, or bullet trap where lead dust is deposited.

Lead affects the nervous, circulatory, digestive, excretory, and reproductive systems of both men and women. Lead can build up in the body affecting the blood, heart, and immune systems, if the amount absorbed and stored in the body exceeds the body's ability to expel it. In children, slowed cognitive development and reduced growth are results of overexposure. Pregnant women overexposed to lead are more prone to spontaneous abortions or may give birth to babies with a low birth weight and slowed postnatal neurological development.

FINDINGS, DISCUSSION, AND RECOMMENDATIONS

a. Building Envelope. This indoor firing range measures 50' from the firing line, 70' in total length, 18' wide, and 11' high. The five firing lanes are less than four feet wide and are numbered only at the firing line. Interior mortar joints are not flush with the interior surface and do not create a smooth, even surface downrange. Pipes and conduits are adequately sealed and the walls and ceiling are adequately protected against projectiles. The access door to the range is not adequately weather-stripped.

Recommendations.

1. All firing lanes should be no less than 4 feet wide and marked at both the firing line and bullet trap to prevent accidental cross firing. [CEHND 1110-1-18, 2-1 (C) 2] (RAC 3)
2. All interior mortar joints should be flush with the interior surface of the range. [CEHND 111-1-18, 3-1d(3)] (RAC 2)
3. Weather-strip all access doors to the range to prevent leakage of lead dust and debris into outlying areas. [385-15 2-2a(2)(b)] (RAC 2)
4. **The range is classified as unsafe due to deficiencies found concerning the building envelope. All deficiencies should be corrected before firing may resume.**

b. Range Lighting. Range lighting is relatively uniform and does not cause shadows. Lighting measures an average 111 FC at the targets and 44 FC in all other areas. All lighting is adequately protected by baffles. No emergency lights are provided for the range and exit lighting is burned out. Access behind the bullet trap could not be obtained during the survey and it is unknown whether the appropriate lighting is provided in this area.

Recommendations.

1. Emergency and exit lights should be provided behind the firing line to adequately protect personnel from shooting accidents and to guide them out of the range in the case of an emergency or power outage. [CEHND 110-1-18, 3-4c(c)] (RAC 3)

- c. **Bullet Traps.** An inclined plate bullet trap is permanently installed and is designed for .22 caliber use, which is all that is permitted for firing on this range. The bullet trap measures ¼" thick and adequately prevents ricochets. The bullet trap is in good shape and is smooth without any seams or overlapping. Access behind the bullet trap could not be obtained.

Recommendations.

1. The bullet trap should be adequately maintained. Rust or paint chips may cause ricochets. A thin coating of oil should be applied every 3 months for moderate firing, sooner if heavy firing occurs (10W30 or 3 in 1). **DO NOT APPLY GREASE. (RAC 3)**
 2. Bullet collection bins should not be allowed to get over ¾ full. Contact the VT ARNG State Environmental Office prior to emptying for disposal instructions. **(RAC 3)**
- d. **Targets and Target Carriers.** Target retrieval systems were provided for each lane and are in good working order. Paper targets are used for personnel during firing procedures.

Recommendations.

1. There are no recommendations for targets or target retrieval systems at this time.
- e. **Range Use.** Firing in the firing range occurs two to three nights per week by local gun clubs. The air guard fires approximately once per week. National Guard use occurs one to two times per month. Lockers, tables, chairs, and other items are stored in the range. Additional clothing and equipment is brought in for storage. Items were stored in front of the plenum wall. Personnel cite the reason for storing items in the ranges are lack of space in the facility. Persons using the range are reportedly allowed to walk downrange. An appropriate fire extinguisher is not provided in the range.

Recommendations.

1. No items should be stored in the firing range at any time. Stored items can become contaminated with lead dust and will increase the exposure to anyone who moves or touches them. [NGR 385-15 2-3a, 2-4h] **(RAC 2)**
2. No items should be stored in front of the plenum wall, which will disturb air flow while the ventilation system is running. [NGR 385-15 2-4a] **(RAC 2)**

3. Only range custodians are allowed access downrange. Unauthorized personnel should not be permitted downrange in order to minimize their exposure to lead dust. [NGB 385-15 2-4f] (RAC 2)
4. Eating, drinking, and use of tobacco products without washing hands and face prior to these activities can lead to ingestion of lead dust that have settled on hands, surfaces, or food and drink. Oral ingestion may represent a major route of exposure in contaminated workplaces. All personnel should be strictly prohibited from consuming food and beverages in the area, using tobacco products, or applying cosmetics (i.e. lip balm). [29 CFR 1910.1025 (i)(1)]. (RAC 2)
5. A hand held ABC-type fire extinguisher should be kept at the firing line in case of emergencies. [DCI 415-1, App. A, 4-5] (RAC 3)

f. *Range Maintenance.* Dry sweeping of the range was reported and brooms were found in the area to indicate any dry sweeping of the area.

Recommendations.

1. The indoor firing range should be cleaned with the ventilation system operating to prevent dust and debris from entering the worker's breathing zone. Floor areas from behind the firers to the firing line and 15 feet downrange should be cleaned at the end of each firing day. [NIOSH 76-130, p.24, II, 1, NGR 385-15 1-32f] (RAC 2)
 2. Dry sweeping and cleaning bullet traps by pouring or shoveling bullet debris into waste buckets causes settled lead dust to become airborne and possibly inhaled. **Dry sweeping of indoor firing ranges is prohibited.** A High Efficiency Particulate Air (HEPA) filtered vacuum system is the recommended choice for range cleanup of lead dust and particles only (no bullet casings). If a HEPA vacuum cannot be acquired a wet method should be used, which includes a solution of detergent and water. Two containers should be used; one to wet the area, and the other to rinse the applicator after the dust has been wiped from the surface. Water should be changed often to prevent reapplication of contaminated water. Wastewater should be left to evaporate and the residue and any applicators should be disposed under guidance from the VT ARNG Environmental Office. [29 CFR 1910.1025(h)(ii), NIOSH 76-130, P.24, II, 2] (RAC 2)
 3. One person, preferably the range custodian, should be responsible for cleaning the range and discarding debris. The range should be cleaned **ONLY** with a HEPA vacuum system or utilizing a wet method. [29 CFR 1910.1025(h)(ii)] (RAC 2)
- g. *Personal Protective Equipment (PPE).* Personnel were observed wearing appropriate hearing and eye protection.

Recommendations.

1. There are no recommendations for personal protective equipment at this time.
- h. **Posting of Signs.** No warning signs are posted in the area. An illuminated warning sign to alert personnel while range is in use and is visible at the outside door. The illuminated sign is interlocked with range lighting. An acknowledgement book is provided covering the Standing Operation Procedures (SOP) items. No warning signs are posted outside of the access door to the bullet trap, warning personnel not to enter during range operation.

Recommendations.

1. The following signs should be posited in or in the vicinity of the range and of the access door to the bullet trap. [NGR 385-15 3-6a,b] (RAC 2):
 - a. Eating, drinking, and Smoking are Prohibited
 - b. Dry Sweeping is Prohibited
 - c. Wash Hands and Face Immediately Following Firing
 - d. The Following Ammunition is Authorized for use on this Range
 - e. Hearing Protection Must Be Properly Worn During Firing
 - f. Proper Safety Glasses/Goggles Must Be Worn During Firing
 - g. No Furniture or Storage of Items Permitted in the Range
2. The Following Signs must be posted on the entrance door to the range and to the access door of the bullet trap:
 - a. Noise Hazardous Area
 - b. Danger Lead Hazard Area
 - c. Pregnant Females are Not Permitted in this Area
2. An illuminated sign should be interlocked with the range ventilation switch and located outside of the firing range to alert individuals outside when the range is in use. [NGR 385-15 2-6c] (RAC 4)
 - i. **Range Standing Operation Procedure (SOP).** A Range SOP, with all requirements, is not available for this facility as approved by the State Safety Office. A visitor's log, instructive guidance, and personal protective requirements are addressed during briefings of representatives of groups using the firing range.

Recommendations.

1. A Range Standing Operation Procedure should be written for this facility which includes the following (RAC 2):

- i. Requirements for establishment and maintenance of a visitor's log indicating date, age, and ammunition fired
 - ii. Requirements for safety briefing for all individuals before entrance to the range given by a designated range safety officer
 - iii. Work practices
 - iv. Instructive guidance
 - v. Personnel responsibilities for performing, supervising, reviewing, and updating the SOP
 - vi. Authorized ammunition
 - vii. Posting of signs
 - viii. Cleaning and maintenance requirements
 - ix. PPE requirements for maintenance, firing, and cleaning of the range.
- i. **Recordkeeping.** Records kept by range custodian are a visitor's log with name and age of firer, organization and sign in and sign out times. The type of ammunition used is not documented. Range custodian was not available to provide copies of initial and previous inspection information and any air-sampling data. No OSHA compliance program is in place. Range custodian has not been trained on lead hazards specific to firing and cleaning of the range.

Recommendations.

1. A visitor's log must be maintained that contains the name and age of firer, organization, sign in and out time, type of ammunition, and number of rounds fired. [NGR 385-15 1-16c] (RAC 2)
2. A copy of this and any other inspections should be maintained. [NGR 385-15 3-6] (RAC 2)
3. An OSHA compliance program must be established and maintained. The written plan should include a description of the operation, ammunition and weapons used, existing controls, groups using the firing range, employee job responsibilities, operating procedures and maintenance practices. A record of previous inspections and air sampling data must also be retained. [29 CFR 1910.1025(c)(3)(i-ii)]. (RAC 2)
4. All individuals utilizing the range must be provided with a copy of the SOP or have been briefed on the units' requirements and must sign an agreement to follow the rules. [NGR 385-15 1-15h] (RAC 2)
5. State maintenance officers and custodians must be fully trained on an annual basis on the health effects from exposure to lead dust and the appropriate precautions that must be taken. Records verifying this training must be kept by the range custodian. Each employee who works in a place in which there is a potential exposure to airborne lead at any level shall inform employees of the Content of Appendix A Substance Data Sheet for Occupational Exposure to Lead, and Appendix B Employee Standard Summary of OSHA regulation

1910.1025. Initial training should be performed at least 180 days from date of initial job assignment and annually thereafter. [29 CFR 1910.1025(j)(1)(I-iv), 29 CFR 1910.1200(h)] (RAC 2)

6. A range safety officer and custodian should be designated in writing. [NGR 385-15 1-17d] (RAC 2)

j. **Ventilation.** The range is equipped with an operational ventilation system, with 100% of the make-up air exhausted at the bullet trap. Supply and exhaust fans are not interlocked with range lighting. Ventilation Flow rates were found below 50 fpm in the standing positions in lanes 1, 3, and 4 and in the kneeling position in lane 4. (See diagram in Appendix D for detailed measurements). Flow rates measured greater than 75 fpm.

The plenum wall extends approximately 4/5 of the way across the back wall and flow rates at the plenum wall did not have the required 400 to 600 fpm. More than 10-15% of the plenum wall is open. Smoke tests revealed turbulence at the firing line, observable in lanes three and four. Smoke originating at the firing line curled back behind the firing line instead of moving downrange. This indicates that during firing, lead dust would blow back into the firer's face.

Recommendations.

1. Interlock supply and exhaust fans with range lighting so that the ventilation system operates at all times during occupancy of the range. [CFRND 110-1-18, 3-4a] (RAC 3)
2. Results of ventilation and smoke tests indicate that adequate flow rates are being provided by the fan but are not evenly and uniformly distributed to move lead dust downrange and away from firer's breathing zone. The purpose of the plenum wall is to provide enough resistance to straighten the airflow and allow it to be distributed evenly and uniformly downrange. The plenum wall should be retrofitted so that it extends the entire length of the back wall. The holes should be made one inch in diameter and evenly distributed across the surface of the plenum wall and centered in a four-inch square area. The airflow must measure at least 50 fpm at all positions in the firing lane. (RAC 2)

k. **Air Sampling.** Air sampling was conducted to simulate weapons qualifications. Sampling was conducted on three personnel in lanes 1, 2, and 5, and in the supply office, where supply personnel have complained of smelling fumes. Lanes in 3 and 4 were not sampled due to turbulence noted during smoke tests. Air sampling results for lead ranged from <0.014 to 0.093 mg/m³. According to National Guard regulations, Guardsmen exposed to lead at these levels in the range less than thirty days per year are permitted to use the range up to four hours per day. Guardsmen utilizing the range for over thirty days per year and all non-military personnel are limited to 2.25 hours

per day at these lead levels. Range users under 17 are limited to one hour per day. Air sampling results for copper and barium were well below allowable ACGIH, NIOSH, and OSHA limits.

Recommendations.

1. This range is classified as limited use based on sampling results collected during the survey. Only lanes 1, 2, and 5 are available for use. (RAC 2)
2. A record must be maintained for time spent on the range for all personnel using limited use firing ranges as recorded by the range custodian. [NGR 385-15 1-15 b] (RAC 2)
3. Air Sampling should again be conducted after changes required in the ventilation system have been made. [NGR 385-15 1-27 c] (RAC 2)

Range Status. This range has been classified as unsafe due to deficiencies in the building envelope. After these deficiencies have been corrected, the range can be classified as limited use based on the ventilation system measurements and air sample results.

Recommendations.

1. Further use of this range is restricted until deficiencies in the building envelope have been corrected, reinspected, and approved. The range is then classified as limited use until ventilation deficiencies are corrected, reinspected, and approved. [NGR 385-15 1-17; a, 2 a and f; b 2 a; and f 2 a and b] (RAC 2)

Non-Responsive

Industrial Hygienist

APPENDIX A

Environmental Management System

REFERENCES

- American Conference of Governmental Industrial Hygienists (ACGIH), Industrial Ventilation, A Manual of Recommended Practice, 23rd Edition, 1998.
- American Conference of Governmental Industrial Hygienists (ACGIH), Threshold Limit Values for Chemical Substances and Physical Agents and Biological Indices for 2000.
- AR 40-5, Preventative Medicine, 15 October 1990.
- AR 385-10, The Army Safety Program, 23 May 1988.
- National Safety Council, Fundamentals of Industrial Hygiene, 4th edition, 1996.
- National Guard Regulation (NGR) 385-10, Army National Guard Safety and Occupational Health Program, 29 December 1989.
- National Guard Regulation (NGR) 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges, 18 September 2000..
- National Guard Pamphlet (NG PAM) 385-16, Guidelines for Converting Firing Ranges to Other Uses, 31 January 1994.
- National Institute for Occupational Safety and Health, Pocket Guide to Chemical Exposures, 2000.
- TB MED 503, The Army Industrial Hygiene Program, February 1985.
- TB MED 502, Occupational Safety and Health Respiratory Protection Program..
- Title 29 Code of Federal Regulations (CFR) 1910.1025, Lead.

Instrumentation

The industrial hygiene survey was conducted utilizing the following pieces of equipment:

Ametek Air Sampling Pumps, M/N P4LC
 BIOS DryCal DC-1 Flow Calibrator.
 TSI Air Velocity Meter, M/N VelociCalc 8360
 Light Meter

Methodology.

- A. *Ventilation.* Ventilation measurements were taken by taking readings at the standing, kneeling, and prone positions at the firing line. Details of locations where ventilation measurements were made can be found in Appendix D.

Assessment Criteria.

- A. *Ventilation Standards.* Ventilation rates were compared with the NGR 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges. See previous page for Reference information.
- B. *Exposure Standards.* Air sampling results for lead were compared with the NGR 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges. See previous page for Reference information. Air sampling results for copper and barium were compared to the Occupational Safety and Health Administration (OSHA) Permissible Exposure Levels (PELs), the American Conference of Governmental Industrial Hygienists (ACGIH) Threshold Limit Values (TLVs), and the National Institute of Occupational Safety and Health (NIOSH) Recommended Exposure Levels (RELs). See previous page for reference information.
- C. *Illumination Standards.* Illumination measurements were taken in all areas. Measurements were compared with the NGR 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges. See previous page for Reference information.
- D. *Risk Assessment Codes.* Risk Assessment Codes (RACs) are included in this report to quantify the risk of particular operations to employees and to establish funding priorities for corrective actions. RACs are assigned with regard to hazard severity and mishap probability. The type, length, and route of exposure are taken into consideration, as are the medical effects that would occur with such exposures. RAC criteria can be found in Appendix B.

APPENDIX B

Environmental Management Solutions

**DERIVING RISK ASSESSMENT CODES (RACs)
FOR HEALTH HAZARDS
(Ref: DOD Instruction 6055.1)**

STEP 1. Using the following procedures to assess points, determine the health hazard severity category (HHSC). The HHSC reflects the magnitude of exposure to a physical, chemical, or biological agent and the medical effects of exposure.

A. Exposure Points Assessed

		Exposure Conditions			
		<CT	Occasionally - >CT Always - <STD	>CT =STD	>STD
AER	NO	0	3	5	7
POSSIBLE?	YES	1-2	4	6	8

AER = Alternate exposure route, such as skin absorption, ingestion

CT = DoD component threshold that triggers surveillance actions, such as microWatts/cm², dB, parts per million

STD = DoD exposure limit, such as Threshold Limit Value and Permissible Exposure Limit

B. Medical Effects Points Assessed

Condition	Points
No medical effect, such as nuisance noise and nuisance odor	0
Temporary reversible illness requiring supportive treatment, such as eye irritation and sore throat	1-2
Temporary reversible illness with a variable but limited period of disability such as metal fume fever	3-4
Permanent, nonsevere illness or loss of capacity, such as permanent hearing loss	5-6
Permanent, severe, disabling, irreversible illness or death, such as asbestosis and lung cancer	7-8

C. Determine the HHSC by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>HHSC</u>
13-16	I
9-12	II
5-8	III
0-4	IV

STEP 2. Using the following guides to assess points, determine the mishap probability category (MPC) for health hazards. The probability of mishap reflects the duration of exposure and the number of exposed personnel.

A. Duration of Exposure Points Assessed

		<u>Length of Exposure</u>		
		1-8 hr/wk	>8 hr/wk continuous	not continuous
<u>Type of Exposure</u>	Irregular, intermittent	1-2	4-6	-
	Regular, periodic	2-3	5-7	8

B. Number of Exposed Personnel Points Assessed

<u>Number of Exposed Personnel</u>	<u>Points</u>
<5	1-2
5 to 9	3-4
to 49	5-6
>49	7-8

C. Determine the MPC for health hazards by totaling the points assessed and using the following guide:


<u>Total Points (sum of A and B, above)</u>	<u>MPC</u>
14-16	A
10-13	B
5-9	C
<5	D

STEP 3. Determine the RAC for health hazards by using the following matrix to measure health hazard severity and mishap probability factors.

		<u>MISHAP PROBABILITY</u>			
		<u>A</u>	<u>B</u>	<u>C</u>	<u>D</u>
<u>HAZARD SEVERITY</u>	<u>I</u>	1	1	2	3
	<u>II</u>	1	2	3	4
	<u>III</u>	2	3	4	5
	<u>IV</u>	3	4	5	5

APPENDIX C

Environmental Management Solutions




Gosse Court Indoor Firing Range


↳ Denotes turbulence

Environmental Management Solutions

Gosse Court Indoor Firing Range



Results of Smoke Tests Show Turbulence in Lanes Three and Four.



Warning Signs and Illuminated "In Use" Sign Posted at the Range Entrance



Range Rules and Sign In Sheet



Plenum Wall Extends 4/5 of the way across the back wall. More than 10 to 15% open of the wall is open which may be responsible for the turbulence observed..

APPENDIX D

Environmental Management Solutions

**Ventilation Measurements
Indoor Firing Range Lanes**

	Lane 1	Lane 2	Lane 3	Lane 4	Lane 5
<i>Standing</i>	40	104	19	45	113
<i>Kneeling</i>	97	114	55	40	101
<i>Prone</i>	135	115	109	65	114

Environmental Management Solutions

APPENDIX E

Environmental Management Solutions

**Air Sampling Results
Indoor Firing Range**

<i>LEAD</i>				
<i>Sample Number</i>	<i>Results mg/m³</i>	<i>Maximum Hours of Allowable Exposure Per Day Guardsmen exposed less than 30 days per year</i>	<i>Maximum Hours of Allowable Exposure Per Day Guardsmen exposed more than 30 days per year</i>	<i>Maximum Hours of Allowable Exposure Per Day Range Users Under 17 Year s of Age</i>
<i>GC-01</i>	0.093	4	2.25	1
<i>GC-02</i>	0.035			
<i>GC-03</i>	0.022			
<i>GC-04</i>	<0.037			
<i>GC-05</i>	<0.014			
<i>GC-06</i>	0.019			
<i>GC-BL1</i>	NA	NA	NA	NA
<i>GC-BL2</i>	NA	NA	NA	NA

<i>Sample Number</i>	<i>Copper</i>			<i>Barium</i>		
	<i>Results mg/m³</i>	<i>Time Weighted Average (TWA)</i>	<i>Within allowable Limits?</i>	<i>Results mg/m³</i>	<i>Time Weighted Average (TWA)</i>	<i>Within Allowable Limits?</i>
<i>GC-01</i>	0.0036	0.00027	Y	<0.028	0.0021	Y
<i>GC-02</i>	<0.0019	0.00014	Y	<0.029	0.0021	Y
<i>GC-03</i>	<0.0020	0.00016	Y	<0.029	0.0020	Y
<i>GC-04</i>	<0.0037	0.00028	Y	<0.056	0.0042	Y
<i>GC-05</i>	0.013	0.0013	Y	<0.021	0.0021	Y
<i>GC-06</i>	0.0028	0.00029	Y	<0.020	0.0021	Y
<i>GC-BL1</i>	NA	NA	NA	NA	NA	NA
<i>GC-BL2</i>	NA	NA	NA	NA	NA	NA

Environmental Management Solutions



Date 11/16/00
Laboratory Group Name 00I-2206-01
Account No. 07003

Environmental Management Solutions
Attention: **Non-Responsive**
P.O. Box 6893
Douglasville, GA 30154

FAX (770) 234-6297
Telephone (678) 596-8509

Sampling Collection and Shipment

Sampling Site Gosse Court Armory Date of Collection October 19, 2000
Date Samples Received at Laboratory November 01, 2000

Analysis

Method of Analysis NMAM 7300
Date(s) of Analysis November 15, 2000

Analytical Results

Field Sample Number	Laboratory Number	Sample Type	Lead $\mu\text{g}/\text{sample}$	Copper $\mu\text{g}/\text{sample}$	Barium $\mu\text{g}/\text{sample}$	Lead mg/m^3	Copper mg/m^3	Barium mg/m^3	Air Volume L
GC-01	00I16038	MCE	10.	0.39	ND	0.093	0.0036	<0.028	108.
GC-02	00I16039	MCE	3.7	ND	ND	0.035	<0.0019	<0.029	105.
GC-03	00I16040	MCE	2.2	ND	ND	0.022	<0.0020	<0.029	102.
GC-04	00I16041	MCE	ND	ND	ND	<0.037	<0.0037	<0.056	54.
GC-05	00I16042	MCE	ND	1.8	ND	<0.014	0.013	<0.021	141.
GC-06	00I16043	MCE	2.8	0.42	ND	0.019	0.0028	<0.020	150.
GC-BL1	00I16044	MCE	ND	ND	ND	**	**	**	**
GC-BL2	00I16045	MCE	ND	ND	ND	**	**	**	**
Reporting Limit			2.	0.2	3.				

* See comment on last page.
ND Parameter not detected above LOD.
NR Parameter not requested.

** See comment on last page.

Non-Responsive



Date 11/16/00
Laboratory Group Name 001-2206-01

General Set Comments

Results cannot be reported in mg/m³ or ppm for samples with no air volume.



ANALYTICAL REQUEST FORM

BEST AVAILABLE COPY

1. REGULAR Status 2015-22010-01

RUSH Status Requested - ADDITIONAL CHARGE

RESULTS REQUIRED BY _____ DATE _____

CONTACT DATACHEM LABS PRIOR TO SENDING SAMPLES.

2. Date 27 04 00 Purchase Order No. _____

3. Company Name NATIONAL GUARD BUREAU
 Address _____
ATTN: NGB-AVN-SI
301-IH Old Bay Lane
 Person to Contact Havre de Grace, MD 21078-4094
 Telephone (_____) phone: (410) 942-0273
 Fax Telephone (fax) (410) 942-0254

Non-Responsive

Industrial Hygienist _____

4. Quote No. 102700 - RP (2956)
 DCL Project Manager _____

5. Sample Collection
 Sampling Site 270550 Ocean Blvd
 Industrial Process WATER TREATMENT PLANT
 Date of Collection 04/20/15
 Time Collected _____
 Date of Shipment _____
 Chain of Custody No. _____
 Collector's Name / Signature **Non-Responsive**

Non-Responsive

6. REQUEST FOR ANALYSES

Laboratory Use Only	Client Sample Number	Media Type*	Sample Volume (Liters)	ANALYSES REQUESTED - Use Method Number if Known
	412-01	NCE	108 l	Lead, Copper, Barium (MOSH 7307)
	412-02	CE	105 l	
	412-03	CE	102 l	
	412-04	CE	54 l	
	412-05	CE	141 l	
	412-06	CE	150 l	
	412-07	CE	blank	
	412-08	CE	blank	
		SIC		
		PH 225-501		
		Lot _____		

*Specify: Solid sorbent tube, e.g. Charcoal; Filter type; Impinger solution; Bulk Sample; Blood; Urine; Tissue; Soil; Water; Other

6. Q C REQUIREMENTS

MUST BE COMPLETED FOR ENVIRONMENTAL SAMPLES - See General Services Terms and Conditions: QC samples billed at regular sample rate

METHOD QC SAMPLES (Lab QC according to published methods)

PROJECT PLAN QC SAMPLES (Lab QC according to provided QA/QC Plan)

NO QC SAMPLES REQUESTED (May not conform to Agency requirements)

OTHER (as specified below) _____

Comments Air samples collected during firing of .22 jacketed ammo in an indoor firing range.

Possible Contamination and/or Chemical Hazards _____

7. Requested by **Non-Responsive**

960 West LeVoy Drive / Salt Lake City, UT 84123 800-356-9135 or 801-268-7700 / FAX: 801-268-9992
 4388 Glendale-Milford Road / Cincinnati, OH 45242 900-458-1493 or 513-733-5036 / FAX: 513-733-5047

DATACHEM LABORATORIES - A SORENSON COMPANY

INDUSTRIAL HYGIENE SAMPLING RESULT NOTIFICATION SHEET

DATA REQUIRED BY THE PRIVACY ACT

AUTHORITY: Sections 133, 1071 87, 3012, 5031, and 8012, title 10, United States Code, Executive Order 9397 and AR 40 6.

PRINCIPAL PURPOSE: The Social Security Number of the individual is required to identify, record, and retrieve occupational medical surveillance records.

ROUTINE USE: The primary use of this information is to provide, plan, and coordinate occupational health medical surveillance and care.

DISCLOSURE: In the case of military personnel and Federal employees, the requested information is mandatory because of the need to document all occupational injuries and illnesses in view of future rights and benefits. If the requested information is not furnished comprehensive medical surveillance may not be possible, but **AUTHORIZED CARE WILL NOT BE DENIED.**

NAME: Non-Responsive	SOCIAL SECURITY NO.: Non-Responsive	OPERATION: Weapons Firing	BLDG: Gosse Court Indoor Firing Ran	DIRECTORATE/COLOCATED ACT
--------------------------------	---	------------------------------	--	---------------------------

Air sampling took place on 19 October 2000 to determine workplace exposure to:

SUBSTANCE	PERMISSIBLE EXPOSURE LIMIT	YOUR RESULTS	EXP CATEGOR (See Below)
1. Lead	0.050 mg/m ³ (OSHA)	0.007 mg/m ³	1
2. Copper	1 mg/m ³ (OSHA)	0.00027 mg/m ³	1
3. Barium	0.5 mg/m ³ (OSHA)	<0.0021 mg/m ³	1
4.			
5.			
6.			

EXPOSURE CATEGORY

1. Airborne levels are below permissible limits; no work changes necessary.
2. Airborne levels are close to permissible limits; additional sampling necessary; temporary use of respiratory protection during this operation
3. Airborne levels are above permissible limits and the following actions are indicated (where feasible) to prevent overexposure:
 - a. Ventilation system improvements required (general and/or local exhaust).
 - b. Engineering controls required.
 - c. Employee work practices need improvement.
 - d. Improve housekeeping.
 - e. Personal protective equipment mandatory until exposure is below permissible limits.

COMMENTS:

INDUSTRIAL HYGIENE SAMPLING RESULT NOTIFICATION SHEET

DATA REQUIRED BY THE PRIVACY ACT

AUTHORITY: Sections 193, 1071 87, 3012, 5031, and 8012, title 10, United States Code, Executive Order 9397 and AR 40 5.

PRINCIPAL PURPOSE: The Social Security Number of the individual is required to identify, record, and retrieve occupational medical surveillance records.

ROUTINE USE: The primary use of this information is to provide, plan, and coordinate occupational health medical surveillance and care.

DISCLOSURE: In the case of military personnel and Federal employees, the requested information is mandatory because of the need to document all occupational injuries and illnesses in view of future rights and benefits. If the requested information is not furnished comprehensive medical surveillance may not be possible, but **AUTHORIZED CARE WILL NOT BE DENIED.**

NAME: Non-Responsive	SOCIAL SECURITY NO.: Non-Responsive	OPERATION: Weapons Firing	BLDG.: Gosse Court	DIRECTORATE/COLLOCATED ACT: Indoor Firing Range
---------------------------------------	--	-------------------------------------	------------------------------	---

Air sampling took place on 19 October 2000 to determine workplace exposure to:

SUBSTANCE	PERMISSIBLE EXPOSURE LIMIT	YOUR RESULTS	EXP CATEGORY (See Below)
1. Lead	0.050 mg/m ³ (OSHA)	0.003 mg/m ³	1
2. Copper	1 mg/m ³ (OSHA)	0.00014 mg/m ³	1
3. Barium	0.5 mg/m ³ (OSHA)	<0.0021 mg/m ³	1
4.			
5.			
6.			

EXPOSURE CATEGORY

1. Airborne levels are below permissible limits; no work changes necessary.
2. Airborne levels are close to permissible limits; additional sampling necessary; temporary use of respiratory protection during this operation.
3. Airborne levels are above permissible limits and the following actions are indicated (where feasible) to prevent overexposure:
 - a. Ventilation system improvements required (general and/or local exhaust).
 - b. Engineering controls required.
 - c. Employee work practices need improvement.
 - d. Improve housekeeping.
 - e. Personal protective equipment mandatory until exposure is below permissible limits.

COMMENTS:

Non-Responsive

INDUSTRIAL HYGIENE SAMPLING RESULT NOTIFICATION SHEET

DATA REQUIRED BY THE PRIVACY ACT

AUTHORITY: Sections 133, 1071 87, 3012, 5031, and 8012, title 10, United States Code, Executive Order 9397 and AR 405.

PRINCIPAL PURPOSE: The Social Security Number of the individual is required to identify, record, and retrieve occupational medical surveillance records.

ROUTINE USE: The primary use of this information is to provide, plan, and coordinate occupational health medical surveillance and care.

DISCLOSURE: In the case of military personnel and Federal employees, the requested information is mandatory because of the need to document all occupational injuries and illnesses in view of future rights and benefits. If the requested information is not furnished comprehensive medical surveillance may not be possible, but **AUTHORIZED CARE WILL NOT BE DENIED.**

NAME: Non-Responsive	SOCIAL SECURITY NO.: Non-Responsive	OPERATION: Weapons Firing	BLDG: Gosse Court Indoor Firing Ran	DIRECTORATE/COLOCATED ACT:
--------------------------------	---	------------------------------	--	----------------------------

Air sampling took place on 19 October 2000 to determine workplace exposure to:

SUBSTANCE	PERMISSIBLE EXPOSURE LIMIT	YOUR RESULTS	EXP CATEGORY (See Below)
1. Lead	0.050 mg/m ³ (OSHA)	0.002 mg/m ³	1
2. Copper	1 mg/m ³ (OSHA)	0.00016 mg/m ³	1
3. Barium	0.5 mg/m ³ (OSHA)	<0.0020 mg/m ³	1
4.			
5.			
6.			

EXPOSURE CATEGORY

1. Airborne levels are below permissible limits; no work changes necessary.
2. Airborne levels are close to permissible limits; additional sampling necessary; temporary use of respiratory protection during this operation.
3. Airborne levels are above permissible limits and the following actions are indicated (where feasible) to prevent overexposure:
 - a. Ventilation system improvements required (general and/or local exhaust).
 - b. Engineering controls required.
 - c. Employee work practices need improvement.
 - d. Improve housekeeping.
 - e. Personal protective equipment mandatory until exposure is below permissible limits.

COMMENTS:

SIGNATURE: **Non-Responsive**
May

NATIONAL GUARD BUREAU
ARMY NATIONAL GUARD
REGION NORTH INDUSTRIAL HYGIENE OFFICE
ATTN: NGB-AVN-SI
301-IH OLD BAY LANE
HAVRE DE GRACE, MD 21078-4094

NGB-AVN-SI (40-5f)

12 January 2001

MEMORANDUM FOR The Adjutant General, VT ARNG, ATTN: State Safety
Office (LTC **Non-Responsive**, G.M.A., Camp Johnson,
Colchester, VT 05446-3004

SUBJECT: Indoor Firing Range Survey at Goss Court Armory

1. Enclosed is the industrial hygiene survey report prepared by Environmental Management Solutions. I concur with the overall recommendations made by Ms. Aisha-Zakiya Boyd.
2. Please call me at 410/942-0273 ext. 17 if you have any questions or comments about this report.

Non-Responsive

Encl
Survey Report

Regional Industrial Hygienist

CF:
Unit Commander
Facility Engineer, COL **Non-Responsive**

ENVIRONMENTAL MANAGEMENT SOLUTIONS
INDUSTRIAL HYGIENE CONSULTING

Campbell Armory
Indoor Firing Range

PO BOX 6899, DOUGLASVILLE, GEORGIA 30134
PHONE 678 396 8309 • FAX 770 204 6297

Table of Contents

Executive Summary.....	Page 1
Subject.....	Page 3
Background	
Introduction	
Site Description	
Scope of Work	
Health effects and hazard determination	
FINDINGS AND RECOMMENDATIONS	
a. Building envelope.....	Page 4
b. Range lighting.....	Page 4
c. Bullet traps.....	Page 5
d. Targets and target carriers.....	Page 5
e. Range use.....	Page 5
f. Range maintenance.....	Page 6
g. Personal protective equipment.....	Page 7
h. Posting of signs.....	Page 7
i. Range SOP.....	Page 8
j. Record keeping.....	Page 8
k. Ventilation.....	Page 9
l. Air sampling.....	Page 9
Range Status.....	Page 10
Appendices	
A. References	
B. RAC Table	
C. Photographs	

EXECUTIVE SUMMARY

FINDINGS	RECOMMENDATIONS	RAC
<i>This range has been classified as unsafe due to deficiencies in the building envelope, target retrieval system, and ventilation system</i>	Further use of this range is restricted until deficiencies have been corrected, reinspected, and approved	RAC 2
BUILDING ENVELOPE		
<i>Access doors are not weather-stripped and must be propped closed.</i>	Access doors should be weather-stripped and the locks should be fixed so that the door closes and locks properly.	RAC 2
<i>A roll up door is installed at the firing line</i>	No access doors or windows should be forward of the firing line.	RAC 2
RANGE LIGHTING		
<i>Lighting causes shadows and glare</i>	Consult the FMO to resolve shadows and glare caused by lighting.	RAC 4
<i>No emergency or exit lights are provided in the range</i>	Emergency and exit lights should be provided behind the firing line.	RAC 3
BULLET TRAPS		
<i>Bullet traps were found full.</i>	Bullet collection bins should not be allowed to get over ¼ full. Contact the VT ARNG State Environmental Office prior to emptying for disposal instructions.	RAC 3
TARGET AND TARGET CARRIERS		
<i>There is no target retrieval system installed.</i>	A target retrieval system should be installed.	RAC 2
RANGE USE		
<i>Furniture, lockers, storage cabinets and other items were found stored in the range.</i>	No items should be stored in the firing range at any time. Stored should be decontaminated and removed.	RAC 2
RANGE MAINTENANCE		
<i>No target retrieval system is provided in the range.</i>	A target retrieval system should be installed to prevent personnel from having to walk down range to retrieve targets and disturb lead dust that has settled in the area.	RAC 2
<i>The range has not been cleaned since 1998.</i>	The range should be cleaned at least every three months or after firing if the range is not used as often.	RAC 2
PERSONAL PROTECTIVE EQUIPMENT		
<i>Personnel did not have adequate eye protection.</i>	All personnel should wear ANSI approved eye protection. Have additional eye protection and hearing protection available for those that do not have their own.	RAC 2
POSTING OF SIGNS		

FINDINGS	RECOMMENDATIONS	RAC
<i>Signs were not posted in the range.</i>	Post appropriate signs in the vicinity of the range and on the entrance door.	RAC 2
RANGE SOP		
<i>Campbell Armory has no approved standing operation procedure</i>	Develop and implement a standing operation procedure	RAC 2
RECORDKEEPING		
<i>No records of range training, maintenance, or cleaning are maintained.</i>	Maintain appropriate records regarding range operations and procedures	RAC 2
VENTILATION		
<i>Ventilation system is inadequate. Results of smoke test reveal stagnant air</i>	Contact the FMO to replace the current ventilation system so that it meets NGR 385-15 specifications.	RAC 2

SUBJECT: Industrial Hygiene Survey of the Campbell Indoor Firing Range Survey performed 18 October 2000 at Campbell Armory, VT.

BACKGROUND:

Introduction. At the request of Ms. [Non-Responsive] of the National Guard Bureau Region North Industrial Hygiene Office, an industrial hygiene survey was performed at the Campbell Indoor Firing Range at the Campbell Armory in Vermont. [Non-Responsive] contract industrial hygienist, Ms. [Non-Responsive] and Mr. [Non-Responsive] Regional Industrial Hygienists, and CPT [Non-Responsive] Occupational Health Nurse, Vermont Army National Guard, conducted the survey on 18 October 2000. The purpose of the survey was to perform a comprehensive industrial hygiene survey to evaluate range characteristics, ventilation, and quantify employee exposure to lead dust.

Site Description. The Campbell Indoor Firing Range was constructed in the 1950s and is used for weapons firing and qualification. The range is used approximately three to four times per month mainly on Tuesday evenings and weekends by the JROTC, and the local high school rifle teams. Military use is limited to approximately once per month. There is no plenum provided for make up air and two exhaust fans in the side wall carry out exhaust.

Scope of Work. The Indoor Firing Range was visually examined and personnel were consulted to accurately assess potential hazards present. A range inspection checklist found in National Guard Regulation 385-15, which addresses Indoor Firing Range use and maintenance, was completed for the range. Smoke candles were utilized to observe airflow patterns in the range. Reference information, Instrumentation, Methodology, and Assessment Criteria can be found in Appendix A.

Health Effects and Hazard Determination. The most significant hazard present to employees and users of the indoor firing range is lead dust. Shooters using ammunition with lead primers or bullets manufactured with lead are exposed to lead fumes and dust during the firing process. Furthermore, the lead found in the primer, the melting of the bullet base by hot powder gasses, the shaving and abrasion of the bullet during firing, and fragmentation of the bullet at the point of impact are all potential sources for lead. Further exposure to lead may occur during cleaning of the range, guns, or bullet trap where lead dust is deposited.

Lead affects the nervous, circulatory, digestive, excretory, and reproductive systems of both men and women. Lead can build up in the body affecting the blood, heart, and immune systems, if the amount absorbed and stored in the body exceeds the body's ability to expel it. This particular indoor firing range is of particular concern due to its use by adolescent firers. In children, slowed cognitive development and reduced growth are results of overexposure. Pregnant women overexposed to lead are more prone to spontaneous abortions or may give birth to babies with a low birth weight and slowed postnatal neurological development.

FINDINGS, DISCUSSION, AND RECOMMENDATIONS

a. Building Envelope. This indoor firing range measures 50' from the firing line, 22'6" wide and 11' high. Firing lanes are not marked or numbered. No protruding surfaces are installed to cause bullet ricochets, and walls and ceiling are adequately protected against projectiles. A roll-up door is present in the area, which may allow lead dust or debris to escape from the range to the outdoors. The access door to the range is not weather-stripped and must be propped closed with a wooden doorstop.

Recommendations.

1. All firing lanes should be no less than 4 feet wide and marked at both the firing line and bullet trap. [CEHND 1110-1-18, 2-1 (C) 2] (RAC 3)
2. Weather-strip all access doors to the range to prevent leakage of lead dust and debris into outlying areas. [385-15 2-2a(2)(b)] (RAC 2)
3. No access doors or windows should be forward of the firing line in order to prevent leakage of contaminated air and dust into other areas. [NGR 385-15 2-2a(2)(E)] (RAC 2)
4. Fix and weather-strip the access door so that it closes and locks properly during range operations and provides adequate security for the range when not in use. [CEHND 1110-1-18, 3-1e] [DG 415-1, App. A, 3-1h] (RAC 2)
5. **The range is classified as unsafe due to deficiencies found concerning the building envelope. All deficiencies should be corrected before firing may resume.**

b. Range Lighting. Range lighting leaves shadows and may cause glare at the firing line but is otherwise adequate, measuring 110 FC at the bullet trap and 40-50 FC in other areas. All lighting is adequately protected and is appropriately placed throughout the range. No emergency lights or exit lights are provided for the range.

Recommendations.

1. Consult the FMO to resolve shadows and glare caused by lighting. (RAC 4)
2. Emergency and exit lights should be provided behind the firing line to adequately protect personnel from shooting accidents and to guide them out of the range in the case of an emergency or power outage. [CEHND 110-1-18, 3-4c(c)] (RAC 3)

- c. **Bullet Traps.** An escalator type bullet trap is permanently installed and is designed for .22 caliber use, which is all that is permitted for firing on this range. The bullet trap measures ¼" thick and adequately prevents ricochets. The bullet trap is in good shape and is smooth without any seams or overlapping. There is no access behind the bullet trap. Bullet debris was found in the catch tray.

Recommendations.

1. The bullet trap should be adequately maintained. Rust or paint chips may cause ricochets. A thin coating of oil should be applied every 3 months for moderate firing, sooner if heavy firing occurs (10W30 or 3 in 1). **DO NOT APPLY GREASE. (RAC 3)**
2. Bullet collection bins should not be allowed to get over ¾ full. Contact the VT ARNG State Environmental Office prior to emptying for disposal instructions. **(RAC 3)**

- d. **Targets and Target Carriers.** No target retrieval system is available. Paper targets are used for personnel during firing procedures. After firing, weapons are cleared and all firers walk down the range together to retrieve targets.

Recommendations.

1. A target retrieval system should be installed to prevent firers from walking downrange to retrieve targets, further contaminating themselves and other areas of the range. [385-15 2-2e (1)(a)] **(RAC 2)**
2. **The range is classified as unsafe due to deficiencies found concerning the target retrieval system. All deficiencies should be corrected before firing may resume.**

- e. **Range Use.** Firing in the firing range occurs three to four times per month, mainly on Tuesday evenings and on weekends. The Junior ROTC, and rifle teams from the local high school utilize the range, typically, from September through March. Military use occurs approximately once per month. The firing range is used very infrequently for firing and personnel utilize the space for storage. Chairs, tables, a blackboard, bicycles, lockers, tables, cases, and paints were found stored in the range. Some of these items were found forward of the firing line. Personnel reportedly remove all stored items before firing operations commence. Beverage containers were also found. Tents have been laid out on the firing range floor to let dry before packing them up. No maintenance or cleaning of the range is performed before storage of items. Personnel site the reason for storing items in the ranges are lack of space in the facility. An appropriate fire extinguisher is provided in the range.

Recommendations.

1. No items should be stored in the firing range at any time. Stored items can become contaminated with lead dust and will increase the exposure to anyone who moves or touches them. [NGR 385-15 2-3a, 2-4h] (RAC 2)
2. Eating, drinking, and use of tobacco products without washing hands and face prior to these activities can lead to ingestion of lead dust that have settled on hands, surfaces, or food and drink. Oral ingestion may represent a major route of exposure in contaminated workplaces. All personnel should be strictly prohibited from consuming food and beverages in the area, using tobacco products, or applying cosmetics (i.e. lip balm). [29 CFR 1910.1025 (i)(1)]. (RAC 2)

- f. **Range Maintenance.** No dry sweeping of the range was reported and no brooms were found in the area to indicate any dry sweeping. The range has been cleaned once since 1998. After firing, weapons are cleared and all firers walk down the range together to retrieve targets.

Recommendations.

1. A target retrieval system should be installed to prevent personnel from having to walk down range to retrieve targets and disturb lead dust that has settled in the area, further contaminating clothes and skin and adding to employee exposure to lead dust. All personnel should be prohibited from walking downrange. [NGR 385-15 2-4f] (RAC 2)
2. The indoor firing range should be cleaned with the ventilation system operating to prevent dust and debris from entering the worker's breathing zone. Floor areas from behind the firers to the firing line and 15 feet downrange should be cleaned at the end of each firing day. [NIOSH 76-130, p.24, II, 1; NGR 385-15 1-32f]] (RAC 2)
3. Dry sweeping and bullet traps cleaned by pouring or shoveling bullet debris into waste buckets causes settled lead dust to become airborne and possible inhaled. A High Efficiency Particulate Air (HEPA) filtered vacuum system is the recommended choice for range cleanup of lead dust and particles only (no bullet casings). If a HEPA vacuum cannot be acquired a wet method should be used which includes a solution of detergent and water. Two containers should be used; one to wet the area, and the other to rinse the applicator after the dust has been wiped from the surface. Water should be changed often to prevent reapplication of contaminated water. Wastewater should be left to evaporate and the residue and any applicators should be disposed under guidance from the VT ARNG Environmental Office. [29 CFR 1910.1025(h)(ii), NIOSH 76-130, P.24, II, 2] (RAC 2)
4. One person, preferably the range custodian, should be responsible for cleaning the range and discarding debris. The range should be cleaned

ONLY with a HEPA vacuum system or utilizing a wet method. [29 CFR 1910.1025(h)(ii)] (RAC 2)

- g. Personal Protective Equipment (PPE).** Personnel were observed wearing appropriate hearing protection but did not have safety glasses for firing. Reportedly, the high school units that come to fire utilize their own equipment.

Recommendations.

1. All personnel should wear ANSI approved eye protection. Have additional eye protection and hearing protection available for those that do not have their own. [NGR 385-15, 2-5a, 29 CFR 1910.133 (a-b)]. (RAC 2)
- h. Posting of Signs.** No warning signs are posted in the area. No illuminated warning signs to alert personnel while range is in use are available.

Recommendations.

1. The following signs should be posited in or in the vicinity of the range. [NGR 385-15 3-6a,b] (RAC 2):
 - a. Eating, drinking, and Smoking are Prohibited
 - b. Dry Sweeping is Prohibited
 - c. Wash Hands and Face Immediately Following Firing
 - d. The Following Ammunition is Authorized for use on this Range
 - e. Hearing Protection Must Be Properly Worn During Firing
 - f. Proper Safety Glasses/Goggles Must Be Worn During Firing
 - g. No Furniture or Storage of Items Permitted in the Range
2. The Following Signs must be posted on the entrance Door:
 - a. Noise Hazardous Area
 - b. Danger Lead Hazard Area
 - c. Pregnant Females are Not Permitted in this Area
2. An illuminated sign should be interlocked with the range ventilation switch and located outside of the firing range to alert individuals outside when the range is in use. [NGR 385-15 2-6c] (RAC 2)

i. Range Standing Operation Procedure (SOP). No Range SOP is available for this facility.

Recommendations.

1. A Range Standing Operation Procedure should be written for this facility which includes the following (RAC 2):
 - i. Requirements for establishment and maintenance of a visitor's log indicating date, age, and ammunition fired
 - ii. Requirements for safety briefing for all individuals before entrance to the range given by a designated range safety officer
 - iii. Work practices
 - iv. Instructive guidance
 - v. Personnel responsibilities for performing, supervising, reviewing, and updating the SOP
 - vi. Authorized ammunition
 - vii. Posting of signs
 - viii. Cleaning and maintenance requirements
 - ix. PPE requirements for maintenance, firing, and cleaning of the range.

- i. **Recordkeeping.** No compliance program is in place. Range custodian has only been trained on Hazardous Materials and not on lead hazards specific to firing and cleaning of the range.

Recommendations.

1. A visitors log must be maintained that contains the name and age of firer, organization, sign in and out time, type of ammunition, and number of rounds fired. [NGR 385-15 1-16c] (RAC 2)
2. A copy of this and any other inspections should be maintained. [NGR 385-15 3-6] (RAC 2)
3. An OSHA compliance program must be established and maintained to reduce exposure to or below the permissible exposure limit by means of engineering and work practice controls The written plan should include a description of the operation, ammunition and weapons used, existing controls, groups using the firing range, employee job responsibilities, operating procedures and maintenance practices. A record of previous inspections and air sampling data must also be retained. [29 CFR 1910.1025(c)(3)(i-ii)]. (RAC 2)
4. All individuals utilizing the range must be provided with a copy of the SOP or have been briefed on the units' requirements and must sign an agreement to follow the rules. [NGR 385-15 1-15h] (RAC 2)
5. State maintenance officers and custodians must be fully trained on an annual basis on the health effects from exposure to lead dust and the appropriate precautions that must be taken. Records verifying this

training must be kept by the range custodian. Each employee who works in a place in which there is a potential exposure to airborne lead at any level shall inform employees of the Content of Appendix A Substance Data Sheet for Occupational Exposure to Lead, and Appendix B Employee Standard Summary of OSHA regulation 1910.1025. Initial training should be performed at least 180 days from date of initial job assignment and annually thereafter. [29 CFR 1910.1025(l)(1)(i-iv), 29 CFR 1910.1200(h)] (RAC 2)

6. A range safety officer and custodian should be designated in writing. [NGR 385-15 1-17d] (RAC 2)

- j. **Ventilation.** The firing range has no plenum or make-up air provided for the exhaust ventilation system. Exhaust fans are located at the firing line and at the bullet trap on the side wall. Smoke tests displayed stagnant air that flowed back behind the firing line and hung in the air. Smoke remained in the firing range after five minutes. Airflow at the firing line was not measured due to the results of the smoke tests. A negative pressure atmosphere is not provided. One heater is used especially during winter months.

Recommendations.

1. The range must have an operational ventilation system that provides makeup air behind the firers and exhausts it at or behind the bullet trap. The airflow must measure at least 50 fpm at all positions in the firing lane. Contact the FMO to replace the current ventilation system so that it meets NGR 385-15 specifications. (RAC 2)
2. **The range is classified as unsafe due to deficiencies found concerning the ventilation system. All deficiencies should be corrected before firing may resume.**

- k. **Air Sampling.** No air sampling was conducted due to observations of the ventilation system and storage of items in the range area. Request air sampling after other deficiencies have been corrected.

Range Status. This range has been classified as unsafe due to deficiencies in the building envelope, target retrieval system, and ventilation system.

Recommendations.

1. Further use of this range is restricted until deficiencies have been corrected, reinspected, and approved. (RAC 2)

Non-Responsive

Industrial Hygienist

APPENDIX A

Environmental Management Solutions

REFERENCES

- American Conference of Governmental Industrial Hygienists (ACGIH), Industrial Ventilation, A Manual of Recommended Practice, 23rd Edition, 1998.
- American Conference of Governmental Industrial Hygienists (ACGIH), Threshold Limit Values for Chemical Substances and Physical Agents and Biological Indices for 2000.
- AR 40-5, Preventative Medicine, 15 October 1990.
- AR 385-10, The Army Safety Program, 23 May 1988.
- National Safety Council, Fundamentals of Industrial Hygiene, 4th edition, 1996.
- National Guard Regulation (NGR) 385-10, Army National Guard Safety and Occupational Health Program, 29 December 1989.
- National Guard Regulation (NGR) 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges, 18 September 2000..
- National Guard Pamphlet (NG PAM) 385-16, Guidelines for Converting Firing Ranges to Other Uses, 31 January 1994.
- National Institute for Occupational Safety and Health, Pocket Guide to Chemical Exposures, 2000.
- TB MED 503, The Army Industrial Hygiene Program, February 1985.
- TB MED 502, Occupational Safety and Health Respiratory Protection Program..
- Title 29 Code of Federal Regulations (CFR) 1910.1025, Lead.

Instrumentation

The industrial hygiene survey was conducted utilizing the following pieces of equipment:

Ametek Air Sampling Pumps, M/N P4LC
BIOS DryCal DC-1 Flow Calibrator.
TSI Air Velocity Meter, M/N VelociCalc 8360
Light Meter

Methodology.

- A. *Ventilation.* Ventilation measurements were taken by taking readings at the standing, kneeling, and prone positions at the firing line. Details of locations where ventilation measurements were made can be found in Appendix D.

Assessment Criteria.

- A. *Ventilation Standards.* Ventilation rates were compared with the NGR 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges. See previous page for Reference information.
- B. *Exposure Standards.* Air sampling results for lead were compared with the NGR 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges. See previous page for Reference information. Air sampling results for copper and barium were compared to the Occupational Safety and Health Administration (OSHA) Permissible Exposure Levels (PELs), the American Conference of Governmental Industrial Hygienists (ACGIH) Threshold Limit Values (TLVs), and the National Institute of Occupational Safety and Health (NIOSH) Recommended Exposure Levels (RELs). See previous page for reference information.
- C. *Illumination Standards.* Illumination measurements were taken in all areas. Measurements were compared with the NGR 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges. See previous page for Reference information.
- D. *Risk Assessment Codex.* Risk Assessment Codes (RACs) are included in this report to quantify the risk of particular operations to employees and to establish funding priorities for corrective actions. RACs are assigned with regard to hazard severity and mishap probability. The type, length, and route of exposure are taken into consideration, as are the medical effects that would occur with such exposures. RAC criteria can be found in Appendix B.

APPENDIX B

Environmental Management Solutions

**DERIVING RISK ASSESSMENT CODES (RACs)
FOR HEALTH HAZARDS
(Ref: DOD Instruction 6055.1)**

STEP 1. Using the following procedures to assess points, determine the health hazard severity category (HHSC). The HHSC reflects the magnitude of exposure to a physical, chemical, or biological agent and the medical effects of exposure.

A. Exposure Points Assessed

		Exposure Conditions			
		<CT	Occasionally - >CT Always - <STD	>CT =STD	>STD
AER	NO	0	3	5	7
POSSIBLE?	YES	1-2	4	6	8

AER = Alternate exposure route, such as skin absorption, ingestion

CT = DoD component threshold that triggers surveillance actions, such as microWatts/cm², dB, parts per million

STD = DoD exposure limit, such as Threshold Limit Value and Permissible Exposure Limit

B. Medical Effects Points Assessed

<u>Condition</u>	<u>Points</u>
No medical effect, such as nuisance noise and nuisance odor	0
Temporary reversible illness requiring supportive treatment, such as eye irritation and sore throat	1-2
Temporary reversible illness with a variable but limited period of disability such as metal fume fever	3-4
Permanent, nonsevere illness or loss of capacity, such as permanent hearing loss	5-6
Permanent, severe, disabling, irreversible illness or death, such as asbestosis and lung cancer	7-8

C. Determine the HHSC by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>HHSC</u>
13-16	I
9-12	II
5-8	III
0-4	IV

STEP 2. Using the following guides to assess points, determine the mishap probability category (MPC) for health hazards. The probability of mishap reflects the duration of exposure and the number of exposed personnel.

A. Duration of Exposure Points Assessed

		<u>Length of Exposure</u>		
		1-8 hr/wk	>8 hr/wk continuous	not continuous
<u>Type of Exposure</u>	<u>Irregular, intermittent</u>	1-2	4-6	-
	<u>Regular, periodic</u>	2-3	5-7	8

B. Number of Exposed Personnel Points Assessed

<u>Number of Exposed Personnel</u>	<u>Points</u>
<5	1-2
5 to 9	3-4
10 to 49	5-6
>49	7-8

C. Determine the MPC for health hazards by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>MPC</u>
14-16	A
10-13	B
5-9	C
<5	D


STEP 3. Determine the RAC for health hazards by using the following matrix to measure health hazard severity and mishap probability factors.

		MISHAP PROBABILITY			
		A	B	C	D
HAZARD SEVERITY	I	1	1	2	3
	II	1	2	3	4
	III	2	3	4	5
	IV	3	4	5	5


APPENDIX C

Environmental Management Solutions


Campbell Indoor Firing Range




Flammable Storage Cabinets Stored Behind the Firing Line.
Roll Up Door is at the Firing Line




Campbell Indoor Firing Range



Bullet Trap




Campbell Indoor Firing Range




Stored items behind the firing line.



Campbell Indoor Firing Range



Ventilation system exhaust through the side wall.
Smoke tests revealed very little air movement.



NATIONAL GUARD BUREAU
ARMY NATIONAL GUARD
REGION NORTH INDUSTRIAL HYGIENE OFFICE
ATTN: NGB-AVN-SI
301-IH OLD BAY LANE
HAVRE DE GRACE, MD 21078-4094

NGB-AVN-SI (40-5f)

12 January 2001

MEMORANDUM FOR The Adjutant General, VT ARNG, ATTN: State Safety
Office (LTO **Non-Responsive**, G.M.A., Camp Johnson,
Colchester, VT 05446-3004

SUBJECT: Indoor Firing Range Survey at Campbell Armory

1. Enclosed is the industrial hygiene survey report prepared by Environmental Management Solutions. I concur with the overall recommendations made by Ms **Non-Responsive**
2. Please call me at 410/942-0273 ext. 17 if you have any questions or comments about this report.

Non-Responsive

Encl
Survey Report

Regional Industrial Hygienist

CF:
Unit Commander
Facility Engineer, CO **Non-Responsive**

ENVIRONMENTAL MANAGEMENT SOLUTIONS
INDUSTRIAL HYGIENE CONSULTING

Green Mountain Armory
Indoor Firing Range

PO BOX 6895, DOUGLASVILLE, GEORGIA 30154
PHONE: 678.596.8509 * FAX: 770.234.6297

Table of Contents

Executive Summary..... Page 1

Subject..... Page 3

Background

- Introduction
- Site Description
- Scope of Work
- Health effects and hazard determination

FINDINGS AND RECOMMENDATIONS

- a. Building envelope..... Page 4
- b. Range lighting..... Page 4
- c. Bullet traps..... Page 5
- d. Targets and target carriers..... Page 5
- e. Range use..... Page 5
- f. Range maintenance..... Page 6
- g. Personal protective equipment..... Page 7
- h. Posting of signs..... Page 7
- i. Range SOP..... Page 8
- j. Record keeping..... Page 8
- k. Ventilation..... Page 9
- l. Air sampling..... Page 10

Range Status Page 10

Appendices

- A. References
- B. RAC Table
- C. Photographs, Shop Drawings
- D. Ventilation Measurements
- E. Wipe Sampling Results

EXECUTIVE SUMMARY

FINDINGS	RECOMMENDATIONS	RAC
<i>This range has been classified as unsafe due to deficiencies in the building envelope, range use, and ventilation measurements.</i>	Further use of this range is restricted until deficiencies in the building envelope, range use, and ventilation measurements have been corrected, reinspected, and approved.	RAC 2
BUILDING ENVELOPE		
<i>Water infiltration is a significant problem in the range.</i>	Water infiltration needs to be adequately controlled and the floor drain permanently sealed.	RAC 3
<i>Items are stored in the plenum room and in front of the plenum in the range.</i>	All stored items should be removed from the range and plenum room and decontaminated.	RAC 2
<i>Access doors have bent weather-stripping.</i>	Repair weather stripping on access doors.	RAC 2
<i>The distance from the firing line to the plenum wall is less than 14'</i>	Move firing line two feet forward to provide the recommended 15 feet between the plenum wall and firing line while maintaining the recommended 50 feet between the firing line and bullet trap.	RAC 3
RANGE LIGHTING		
<i>Lighting causes some shadows just forward of the firing line</i>	Consult FMO to resolve shadows and glare caused by lighting.	RAC 4
<i>No exit lights are provided in the range</i>	Exit lighting should be provided behind the firing line.	RAC 3
BULLET TRAPS		
<i>.177 pellets and air rifles are used on this range and it is unknown whether all of these items are permitted for use on this range.</i>	Contact FMO to obtain information on the caliber weapons that are authorized for firing in this range.	RAC 2
RANGE USE		
<i>Chairs, shelving, and fibrous materials are stored in the plenum. Stored items were wiped and found grossly contaminated.</i>	No items should be stored in the firing range at any time. Stored should be decontaminated and removed.	RAC 2
<i>Mats are brought in by firers for use during firing.</i>	No fibrous items should be brought in during firing as they may become contaminated with lead dust.	RAC 2
<i>The lock to the plenum room door is taped open.</i>	Personnel should not be permitted in the plenum area during firing at any time.	RAC 2
<i>Food and beverage items were found in a waste can within the range. Cigarette butts were found in a labeled can.</i>	Eating, drinking, and use of tobacco products should be strictly prohibited in the firing range.	RAC 3
RANGE MAINTENANCE		
<i>Dry sweeping of the range is</i>	Dry sweeping of indoor firing ranges	RAC 2

FINDINGS	RECOMMENDATIONS	RAC
<i>permitted and brooms indicating such were found in the area.</i>	is prohibited and should not be permitted.	
PERSONAL PROTECTIVE EQUIPMENT		
<i>No personal protective equipment was observed in the area.</i>	All personnel should wear ANSI approved hearing and eye protection.	RAC 2
POSTING OF SIGNS		
<i>Warning signs were not posted in the range.</i>	Post appropriate signs in the vicinity of the range and on the entrance door.	RAC 2
RANGE SOP		
<i>Green Mountain Armory has no approved standing operation procedure</i>	Develop and implement a standing operation procedure	RAC 2
RECORDKEEPING		
<i>No records of range training, maintenance, or cleaning are maintained.</i>	Maintain appropriate records regarding range operations and procedures	RAC 2
VENTILATION		
<i>Supply and exhaust fans are not interlocked with range lighting.</i>	Interlock supply and exhaust fans with range lighting.	RAC 3
<i>Ventilation flow rates were found below 50 fpm in different positions in the firing lanes. The static pressure in the range measured ~.33" wg.</i>	Holes in the plenum wall should be one inch in diameter and extended over the entire surface of the plenum wall.	RAC 2
<i>The plenum wall extends 4/5 of the way across the back wall.</i>	The plenum wall should extend across the entire back wall.	RAC 2
<i>Flow rates at the plenum wall were less than the required 400 to 600 fpm</i>	Holes in the plenum wall should be one inch in diameter and extended over the entire surface of the plenum wall.	RAC 2
<i>More than 10 to 15% of the plenum wall is open.</i>	Holes in the plenum wall should be one inch in diameter and extended over the entire surface of the plenum wall.	RAC 2
<i>Smoke tests revealed turbulence at the firing line observable in lanes three and four.</i>	Correct ventilation system deficiencies to provide a uniform and even flow rate.	RAC 2

SUBJECT: Industrial Hygiene Survey of the Green Mountain Indoor Firing Range
Survey performed 19 October 2000 at Green Mountain Armory, VT.

BACKGROUND:

Introduction. At the request of Ms. [Non-Responsive] of the National Guard Bureau Region North Industrial Hygiene Office, an industrial hygiene survey was performed at the Green Mountain Indoor Firing Range at the Green Mountain Armory in Vermont. [Non-Responsive] contract industrial hygienist, with assistance from Ms. [Non-Responsive] Regional Industrial Hygienist, Mr. [Non-Responsive] Regional Industrial Hygienist, and CPT [Non-Responsive] Occupational Health Nurse, Vermont Army National Guard, conducted the survey on 19 October 2000. The purpose of the survey was to perform a comprehensive industrial hygiene survey to evaluate range characteristics, ventilation, and quantify employee exposure to lead dust.

Site Description. The Green Mountain Indoor Firing Range is used for weapons firing and qualification. The range is used approximately two nights per week by the Burlington rifle and pistol club, of which some members are 12 and 13 year old firers. The range has six lanes and a mechanical ventilation system with a plenum that extends 4/5 of the way across the back wall.

Scope of Work. The Indoor Firing Range was visually examined and personnel were consulted to accurately assess potential hazards present. A range inspection checklist found in National Guard Regulation 385-15, which addresses Indoor Firing Range use and maintenance, was completed for the range. Smoke candles were utilized to observe airflow patterns in the range. Ventilation studies and air sampling was performed to quantify performance of the range and its effectiveness in reducing employee exposure to lead dust. Reference information, Instrumentation, Methodology, and Assessment Criteria can be found in Appendix A.

Health Effects and Hazard Determination. The most significant hazard present to employees and users of the indoor firing range is lead dust. Shooters using ammunition with lead primers or bullets manufactured with lead are exposed to lead fumes and dust during the firing process. Furthermore, the lead found in the primer, the melting of the bullet base by hot powder gasses, the shaving and abrasion of the bullet during firing, and fragmentation of the bullet at the point of impact are all potential sources for lead. Further exposure to lead may occur during cleaning of the range, guns, or bullet trap, where lead dust is deposited.

Lead affects the nervous, circulatory, digestive, excretory, and reproductive systems of both men and women. Lead can build up in the body affecting the blood, heart, and immune systems, if the amount absorbed and stored in the body exceeds the body's ability to expel it. This particular indoor firing range is of particular concern due to its use by adolescent firers. In children, slowed cognitive development and reduced growth are results of overexposure. Pregnant women overexposed to lead are more prone to spontaneous abortions or may give birth to babies with a low birth weight and slowed postnatal neurological development.

Environmental Management Solutions

FINDINGS, DISCUSSION, AND RECOMMENDATIONS

a. Building Envelope. Pipes, conduits, and other projecting surfaces are adequately baffled. Water infiltration was noticeable and confirmed by personnel. There is one covered floor drain in the area, but personnel report that water seeps into the range and drains during very rainy weather. Chairs, shelving, and fibrous materials, such as canvas items and clothing, are stored in the plenum. The entrance door to the range is not adequately weather-stripped. The current weather stripping is bent and would not adequately prevent leakage out of the range. The distance from the firing line to the plenum wall is less than 14'. For optimum air distribution, a minimum of 15 feet from the firing line to the plenum wall is recommended.

Recommendations.

1. Water infiltration into the range needs to be controlled so that wastewater contaminated with lead does not leak into other areas of the building. Bent weather-stripping should be replaced to help prevent infiltration of contaminated dust and water into areas outside of the range. The floor drain should be completely sealed to prevent water from the range from draining into the sewer system and to prevent water leaking into the range through the drain. Any water should be immediately cleaned up using appropriate maintenance protocol and disposed of accordingly. (RAC 2)
2. Weather-strip all access doors to the range to prevent leakage of lead dust and debris into outlying areas. [385-15 2-2a(2)(b)] (RAC 2)
3. No items should be stored in the firing range at any time. Stored items can become contaminated with lead dust and will increase the exposure to anyone who moves or touches stored items. Remove and decontaminate items using a trisodium phosphate and water solution (See below in section concerning Range Maintenance)[NGR 385-15 2-3a, 2-4h; NGR 385-15 2-4] (RAC 2)
4. Move firing line two feet forward to provide the recommended 15 feet between the plenum wall and firing line. The distance from the firing line to the bullet trap should remain at least 50 feet. [NIOSH 76-130, p. 13] (RAC 3)
5. The range is classified as unsafe due to deficiencies found concerning the building envelope. All deficiencies should be corrected before firing may resume.

b. Range Lighting. Range lighting is relatively uniform but does cause some shadows down range. Lighting measures an average 100 FC at the targets and 55 FC in all other areas. All lighting is adequately protected by baffles. No exit lights are provided for the range.

Recommendations.

1. Consult the FMO to resolve shadows and glare caused by lighting. **(RAC 4)**
 2. Exit lights should be provided behind the firing line to adequately guide personnel out of the range in the case of an emergency or power outage. [CEHND 110-1-18, 3-4c(c)] **(RAC 3)**
- c. ***Bullet Traps.*** An inclined plate bullet trap is permanently installed and is designed for .22-caliber use. .22 caliber pistols and long rifles, .177 pellets, and air rifles are used on the range. It is unknown whether all of these items are permitted for use on this range. The bullet trap measures ¼ " thick and adequately prevents ricochets. The bullet trap is in good shape and is smooth without any seams or overlapping.

Recommendations.

1. Contact FMO to obtain the calibers that may be used with the installed bullet trap to be sure that all ammunition used is authorized for firing. [NGR 385-15 2-2d(1)(a)] **(RAC 2)**
 2. The bullet trap should be adequately maintained. Rust or paint chips may cause ricochets. A thin coating of oil should be applied every 3 months for moderate firing, sooner if heavy firing occurs (10W30 or 3 in 1). **DO NOT APPLY GREASE. (RAC 3)**
 3. Bullet collection bins should not be allowed to get over ¾ full. Contact the VT ARNG State Environmental Office prior to emptying for disposal instructions. **(RAC 3)**
- d. ***Targets and Target Carriers.*** Target retrieval systems were provided for each lane and are in good working order. Large cardboard targets are used for personnel during firing procedures.

Recommendations.

1. There are no recommendations for targets or target retrieval systems at this time.
- e. ***Range Use.*** The range is used approximately two nights per week by the Burlington rifle and pistol club which allows 12 and 13 year old firers. Chairs, shelving, and fibrous materials, to include canvas items and clothing, are stored in the plenum. Tables, chairs, and computer items are stored in front of the plenum. Stored items were wiped to test for lead contamination. Samples show that these items are grossly contaminated, ranging from 549 to 54000 micrograms/square foot. Personnel site the reason for storing items in the ranges are lack of space in the facility. Mats are brought in by firers during shooting and are removed after shooting. The lock to the plenum room

door is taped to keep the door open. Food and beverage items were found in a waste can within the range. Cigarette butts were found in a labeled can on the table stored in front of the plenum.

Recommendations.

1. No items should be stored in the firing range at any time. Stored items can become contaminated with lead dust and will increase the risk of exposure to anyone who moves or touches stored items. [NGR 385-15 2-3a, 2-4h] (RAC 2)
2. No items should be stored in front of the plenum wall, which will disturb air flow while the ventilation system is running. [NGR 385-15 2-4a] (RAC 2)
3. No fibrous items such as mats or carpeting should be brought in during shooting as they may become contaminated with lead dust. [NGR 385-15 2-3a, 2-4h] (RAC 2)
4. All items currently stored in the range and plenum area must be thoroughly decontaminated before storage and use by other personnel. Items should be discarded as hazardous waste only as a last resort. [NG PAM 385-16 , 10](RAC 2)
5. Personnel should not be permitted in the plenum area during firing at any time. [NGR 385-15 2-4a] (RAC 2)
6. Only range custodians are allowed access downrange. Unauthorized personnel should not be permitted downrange in order to minimize their exposure to lead dust. [NGB 385-15 2-4] (RAC 2)
7. Immediately remove the cigarette butt can from the indoor firing range. Eating, drinking, and use of tobacco products without washing hands and face prior to these activities can lead to ingestion of lead dust that have settled on hands, surfaces, or food and drink. Oral ingestion may represent a major route of exposure in contaminated workplaces. All personnel should be strictly prohibited from consuming food and beverages in the area, using tobacco products, or applying cosmetics (i.e. lip balm). [29 CFR 1910.1025 (i)(1)]. (RAC 2)

- f. *Range Maintenance.* Dry sweeping of the range was reported and brooms were found in the range that indicate dry sweeping of the area.

Recommendations.

1. The indoor firing range should be cleaned with the ventilation system operating to prevent dust and debris from entering the worker's breathing zone. Floor areas from behind the firers to the firing line and 15 feet downrange should be cleaned at least every three months or after firing if the range is not used as often. [NIOSH 76-130, p.24, II, 1] (RAC 2)

2. **Dry sweeping and cleaning bullet traps by pouring or shoveling bullet debris into waste buckets causes settled lead dust to become airborne and possible inhaled. Dry sweeping of indoor firing ranges is prohibited.** A High Efficiency Particulate Air (HEPA) filtered vacuum system is the recommended choice for range cleanup of lead dust and particles only (no bullet casings). If a HEPA vacuum cannot be acquired a wet method should be used which includes a solution of detergent and water. Two containers should be used; one to wet the area, and the other to rinse the applicator after the dust has been wiped from the surface. Water should be changed often to prevent reapplication of contaminated water. Wastewater should be left to evaporate and the residue and any applicators should be disposed under guidance from the VT ARNG Environmental Office. [29 CFR 1910.1025(h)(ii), NIOSH 76-130, P.24, II, 2] **(RAC 2)**
3. One person, preferably the range custodian, should be responsible for cleaning the range and discarding debris. The range should be cleaned **ONLY** with a HEPA vacuum system or utilizing a wet method. [NGR 385-15 2-2b, 29 CFR 1910.1025(h)(ii)] **(RAC 2)**

g. Personal Protective Equipment (PPE). No personal protective equipment was observed in the area.

Recommendations.

1. All personnel should wear ANSI approved hearing and eye protection. Have additional eye protection and hearing protection available for those that do not have their own. [NGR 385-15, 2-5a, 2-5 b, 29 CFR 1910.133 (a-b), 29 CFR 1910.95 a]. **(RAC 2)**
- h. Posting of Signs.** No warning signs are posted in the area. An illuminated warning sign to alert personnel while range is in use is present and visible at the outside door. The illuminated sign is interlocked with range lighting. An acknowledgement book is provided covering the Standing Operation Procedures (SOP) items. Firing lanes are numbered only at the firing line. No signs are posted outside of the access door to the bullet trap, warning personnel not to enter during range operation.

Recommendations.

1. The following signs should be posited in or in the vicinity of the range and of the access door to the bullet trap. [NGR 385-15 3-6a,b] **(RAC 2)**:
 - a. Eating, drinking, and Smoking are Prohibited
 - b. Dry Sweeping is Prohibited
 - c. Wash Hands and Face Immediately Following Firing
 - d. The Following Ammunition is Authorized for use on this Range

Environmental Management Solutions

- e. Hearing Protection Must Be Properly Worn During Firing
 - f. Proper Safety Glasses/Goggles Must Be Worn During Firing
 - g. No Furniture or Storage of Items Permitted in the Range
2. The Following Signs must be posted on the entrance door to the range and to the access door of the bullet trap:
 - a. Noise Hazardous Area
 - b. Danger Lead Hazard Area
 - c. Pregnant Females are Not Permitted in this Area
 3. An illuminated sign should be interlocked with the range ventilation switch and located outside of the firing range to alert individuals outside when the range is in use. [NGR 385-15 2-6c] (RAC 4)
 4. Firing lanes should be numbered at both the firing line and at the bullet trap. [NGR 385-15 2-6d] (RAC 4)
- i. Range Standing Operation Procedure (SOP).** No Range SOP with all requirements is available for this facility as approved by the State Safety Office.

Recommendations.

3. A Range Standing Operation Procedure should be written for this facility which includes the following (RAC 2):
 - i. Requirements for establishment and maintenance of a visitor's log indicating date, age, and ammunition fired
 - ii. Requirements for safety briefing for all individuals before entrance to the range given by a designated range safety officer
 - iii. Work practices
 - iv. Instructive guidance
 - v. Personnel responsibilities for performing, supervising, reviewing, and updating the SOP
 - vi. Authorized ammunition
 - vii. Posting of signs
 - viii. Cleaning and maintenance requirements
 - ix. PPE requirements for maintenance, firing, and cleaning of the range.
- j. Recordkeeping.** Records kept by range custodian are a visitor's log with name of firer, organization, sign in and sign out times, and types of ammunition fired. Range regulations are posted above the log in sheet. Range custodian was not available to provide copies of initial and previous inspection information and any air-sampling data. No OSHA compliance program is in place. Range custodian has not been trained on lead hazards specific to firing and cleaning of the range.

Recommendations.

- a. A visitor's log must be maintained that contains the name and age of firer, organization, sign in and out time, and type of ammunition, and number of rounds fired. [NGR 385-15 1-16e] (RAC 2)
 - b. A copy of the visitor's log and any other inspections should be maintained. [NGR 385-15 3-6] (RAC 2)
 - c. An OSHA compliance program must be established and maintained. The written plan should include a description of the operation, ammunition and weapons used, existing controls, groups using the firing range, employee job responsibilities, operating procedures and maintenance practices. A record of previous inspections and air sampling data must also be retained. [29 CFR 1910.1025(e)(3)(i-ii)]. (RAC 2)
 - d. All individuals utilizing the range must be provided with a copy of the SOP or have been briefed on the units' requirements and must sign an agreement to follow the rules. [NGR 385-15 1-15h] (RAC 2)
 - e. State maintenance officers and custodians must be fully trained on an annual basis on the health effects from exposure to lead dust and the appropriate precautions that must be taken. Records verifying this training must be kept by the range custodian. Each employee who works in a place in which there is a potential exposure to airborne lead at any level shall inform employees of the Content of Appendix A, Substance Data Sheet for Occupational Exposure to Lead, and Appendix B, Employee Standard Summary, of OSHA regulation 1910.1025. Initial training should be performed at least 180 days from date of initial job assignment and annually thereafter. [29 CFR 1910.1025(l)(1)(I-iv), 29 CFR 1910.1200(h)] (RAC 2)
 - f. A range safety officer and custodian should be designated in writing. [NGR 385-15 1-17d] (RAC 2)
- k. Ventilation.** The range is equipped with an operational ventilation system, with 100% of the make-up air exhausted at the bullet trap. Supply and exhaust fans are not interlocked with range lighting. Ventilation Flow rates were found below 50 fpm in the standing positions in lanes 1, 3, and 4, in the kneeling position in lanes 2,3,4 and in the prone position in lane 2. (See diagram in Appendix D for detailed measurements). Flow rates were found greater than 75 fpm in lane 6. The static pressure in the range measured $-.33''$ wg. The recommended static pressure range is $-.05$ to $.15''$ wg.
- The plenum wall extends approximately 4/5 of the way across the back wall and flow rates at the plenum wall did not have the required 400 to 600 fpm. More than 10-15% of the plenum wall is open. Smoke tests revealed turbulence at the firing line, observable in lanes one, two, and three. Smoke originating at the firing line curled back behind the firing line instead of moving downrange. This indicates that during firing, lead dust would blow back into the firer's face.

Recommendations.

- a. Interlock supply and exhaust fans with range lighting so that the ventilation system operates at all times during occupancy of the range. [CEHND 110-1-18, 3-4a] (RAC 3)
- b. Results of ventilation and smoke tests indicate that adequate flow rates are being provided by the fan but are not being evenly and uniformly distributed to move lead dust downrange and away from firer's breathing zone. The purpose of the plenum wall is to provide enough resistance to straighten the airflow and allow it to be distributed evenly and uniformly downrange. The plenum wall should be retrofitted so that it extends the entire length of the back wall. The holes should be made one inch in diameter and evenly distributed across the surface of the plenum wall and centered in a four-inch square area. The airflow must measure at least 50 fpm at all positions in the firing lane. (RAC 2)

1. **Air Sampling.** Air sampling was not conducted due to ventilation results and the amount of storage in the plenum and range. Stored items could not easily be moved to accommodate firing.

Recommendations.

- a. Air Sampling should be conducted after changes required in the ventilation system have been made and stored items have been removed and decontaminated. [NGR 385-15 1-27 c] (RAC 2)

Range Status. This range has been classified as unsafe due to deficiencies in the building envelope and ventilation systems.

Recommendations.

1. Further use of this range is restricted until deficiencies have been corrected, reinspected, and approved. (RAC 2)

Non-Responsive

Industrial Hygienist

APPENDIX A

Management Standards

REFERENCES

- American Conference of Governmental Industrial Hygienists (ACGIH), Industrial Ventilation, A Manual of Recommended Practice, 23rd Edition, 1998.
- American Conference of Governmental Industrial Hygienists (ACGIH), Threshold Limit Values for Chemical Substances and Physical Agents and Biological Indices for 2000.
- AR 40-5, Preventative Medicine, 15 October 1990.
- AR 385-10, The Army Safety Program, 23 May 1988.
- National Safety Council, Fundamentals of Industrial Hygiene, 4th edition, 1996.
- National Guard Regulation (NGR) 385-10, Army National Guard Safety and Occupational Health Program, 29 December 1989.
- National Guard Regulation (NGR) 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges, 18 September 2000..
- National Guard Pamphlet (NG PAM) 385-16, Guidelines for Converting Firing Ranges to Other Uses, 31 January 1994.
- National Institute for Occupational Safety and Health, Pocket Guide to Chemical Exposures, 2000.
- TB MED 503, The Army Industrial Hygiene Program, February 1985.
- TB MED 502, Occupational Safety and Health Respiratory Protection Program..
- Title 29 Code of Federal Regulations (CFR) 1910.1025, Lead.

Instrumentation

The industrial hygiene survey was conducted utilizing the following pieces of equipment:

Ametek Air Sampling Pumps, M/N P4LC
BIOS DryCal DC-1 Flow Calibrator.
TSI Air Velocity Meter, M/N VelociCalc 8360
Light Meter

Methodology.

- A. *Ventilation.* Ventilation measurements were taken by taking readings at the standing, kneeling, and prone positions at the firing line. Details of locations where ventilation measurements were made can be found in Appendix D.

Assessment Criteria.

- A. *Ventilation Standards.* Ventilation rates were compared with the NGR 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges. See previous page for Reference information.
- B. *Exposure Standards.* Air sampling results for lead were compared with the NGR 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges. See previous page for Reference information. Air sampling results for copper and barium were compared to the Occupational Safety and Health Administration (OSHA) Permissible Exposure Levels (PELs), the American Conference of Governmental Industrial Hygienists (ACGIH) Threshold Limit Values (TLVs), and the National Institute of Occupational Safety and Health (NIOSH) Recommended Exposure Levels (RELs). See previous page for reference information.
- C. *Illumination Standards.* Illumination measurements were taken in all areas. Measurements were compared with the NGR 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges. See previous page for Reference information.
- D. *Risk Assessment Codes.* Risk Assessment Codes (RACs) are included in this report to quantify the risk of particular operations to employees and to establish funding priorities for corrective actions. RACs are assigned with regard to hazard severity and mishap probability. The type, length, and route of exposure are taken into consideration, as are the medical effects that would occur with such exposures. RAC criteria can be found in Appendix B.

APPENDIX D

Management Practices

**DERIVING RISK ASSESSMENT CODES (RACs)
FOR HEALTH HAZARDS
(Ref: DOD Instruction 6055.1)**

STEP 1. Using the following procedures to assess points, determine the health hazard severity category (HHSC). The HHSC reflects the magnitude of exposure to a physical, chemical, or biological agent and the medical effects of exposure.

A. Exposure Points Assessed

		Exposure Conditions			
		<CT	Occasionally ->CT Always - <STD	>CT =STD	>STD
AER	NO	0	3	5	7
POSSIBLE?	YES	1-2	4	6	8

AER = Alternate exposure route, such as skin absorption, ingestion

CT = DoD component threshold that triggers surveillance actions, such as microWatts/cm², dB, parts per million

STD = DoD exposure limit, such as Threshold Limit Value and Permissible Exposure Limit

B. Medical Effects Points Assessed

<u>Condition</u>	<u>Points</u>
No medical effect, such as nuisance noise and nuisance odor	0
Temporary reversible illness requiring supportive treatment, such as eye irritation and sore throat	1-2
Temporary reversible illness with a variable but limited period of disability such as metal fume fever	3-4
Permanent, nonsevere illness or loss of capacity, such as permanent hearing loss	5-6
Permanent, severe, disabling, irreversible illness or death, such as asbestosis and lung cancer	7-8

C. Determine the HHSC by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>HHSC</u>
13-16	I
9-12	II
5-8	III
0-4	IV

STEP 2. Using the following guides to assess points, determine the mishap probability category (MPC) for health hazards. The probability of mishap reflects the duration of exposure and the number of exposed personnel.

A. Duration of Exposure Points Assessed

		<u>Length of Exposure</u>		
		1-8 hr/wk	>8 hr/wk continuous not continuous	
<u>Type of Exposure</u>	Irregular, intermittent	1-2	4-6	-
	Regular, periodic	2-3	5-7	8

B. Number of Exposed Personnel Points Assessed

<u>Number of Exposed Personnel</u>	<u>Points</u>
<5	1-2
5 to 9	3-4
10 to 49	5-6
>49	7-8

C. Determine the MPC for health hazards by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>MPC</u>
14-16	A
10-13	B
5-9	C
<5	D


STEP 3. Determine the RAC for health hazards by using the following matrix to measure health hazard severity and mishap probability factors.

		MISHAP PROBABILITY			
		A	B	C	D
HAZARD SEVERITY	I	1	1	2	3
	II	1	2	3	4
	III	2	3	4	5
	IV	3	4	5	5

APPENDIX C


Environmental Management Solutions

Green Mountain Indoor Firing Range¹




¹ Denotes turbulence.

Green Mountain Armory




Floor drain allows water seepage into the range.






"Range In Use" Illuminated Sign.
Warning signs posted on entrance door.

Cardboard Targets.



Cigarette Butt Cans




Food and Beverage Items Found in Waste Can





Both the range and plenum areas are used for storage.



APPENDIX D

Environmental Management Solutions

**Ventilation Measurements
Indoor Firing Range Lanes**

	<i>Lane 1</i>	Lane 2	Lane 3	Lane 4	Lane 5	Lane 6
<i>Standing</i>	3	61	31	15	72	121
<i>Kneeling</i>	74	16	14	13	53	129
<i>Prone</i>	40	3	53	67	67	143

Environmental Management Solutions

APPENDIX E

Environmental Management Solutions

**Wipe Sampling Results
Green Mountain IFR**

<i>Sample Number</i>	<i>Location</i>	<i>Micrograms/Sample</i>	<i>Micrograms/sq. ft.</i>
<i>GM-01</i>	Table at plenum wall	94	79524
<i>GM-02</i>	Computer cart at plenum wall	1400	12600
<i>GM-03</i>	Top of locker plenum room	4800	43200
<i>GM-04</i>	Storage shelving, 5 th shelf in plenum room	6000	54000
<i>GM-05</i>	In bathroom on top of towel dispenser	210	1890
<i>GM-06</i>	On floor outside of plenum door	240	2160
<i>GM-07</i>	On floor outside of the range	180	1620
<i>GM-08</i>	Blank	61	549

Environmental Management Solutions

NATIONAL GUARD BUREAU
ARMY NATIONAL GUARD
REGION NORTH INDUSTRIAL HYGIENE OFFICE
ATTN: NGB-AVN-SI
301-IH OLD BAY LANE
HAVRE DE GRACE, MD 21078-4094

NGB-AVN-SI (40-5f)

12 January 2001

MEMORANDUM FOR The Adjutant General, VT ARNG, ATTN: State Safety
Office (LTC **Non-Responsive**), G.M.A., Camp Johnson,
Colchester, VT 05446-3004

SUBJECT: Indoor Firing Range Survey at Green Mountain Armory

1. Enclosed is the industrial hygiene survey report prepared by Environmental Management Solutions. I concur with the overall recommendations made by Ms **Non-Responsive**
2. Please call me at 410/942-0273 ext. 17 if you have any questions or comments about this report.

Non-Responsive

Encl
Survey Report

Regional Industrial Hygienist

CF:
Unit Commander
Facility Engineer, COL **Non-Responsive**

ENVIRONMENTAL MANAGEMENT SOLUTIONS
INDUSTRIAL HYGIENE CONSULTING

Ludlow Armory Indoor Firing Range

PO BOX 6898 DUBLINGVILLE GEORGIA 30134
PHONE 678 596 8529 FAX 770 244 5797

Table of Contents

Executive Summary..... Page 1

Subject Page 2

Background

- Introduction
- Site Description
- Scope of Work
- Health effects and hazard determination

Findings, Discussion, and Recommendations..... Page 3

Appendices

- A. References
- B. RAC Table
- C. Decontamination and Cleaning Protocol
- D. Photographs, Range Drawings
- E. Wipe Sampling Results

EXECUTIVE SUMMARY

FINDINGS

The Ludlow indoor firing range has not been fired on since 1992. The range is listed as active, however offices have been put in this area as well as storage items to include lockers.

Ten out of twenty wipe sample results were above the maximum allowable limit of 200 micrograms per square foot. It is unclear what type of protocol janitors cleaning this range used.

RECOMMENDATIONS

An official decision as to the status of this range should be immediately determined. If the range is to remain active, it must meet requirements set forth in NGR 385-15. If the range is to be converted, it must be adequately cleaned and decontaminated before employee use can resume.

If the range is to be converted, it must be cleaned in accordance with National Guard Regulations before employee use can resume.

RAC
RAC 2

RAC 2

SUBJECT: Industrial Hygiene Survey of the Ludlow Indoor Firing Range Survey performed 17 October 2000 at Ludlow Armory, VT.

BACKGROUND:

Introduction. At the request of Ms. [Non-Responsive] of the National Guard Bureau Region North Industrial Hygiene Office, an industrial hygiene survey was performed at the Ludlow Armory in Vermont. [Non-Responsive] contract industrial hygienist, Ms. [Non-Responsive] and Mr. [Non-Responsive] Regional Industrial Hygienists, and CPT [Non-Responsive] Occupational Health Nurse, Vermont Army National Guard, conducted the survey on 17 October 2000. The purpose of the survey was to perform a comprehensive industrial hygiene survey to evaluate range characteristics, ventilation, and quantify employee exposure to lead dust.

Site Description. The Ludlow Indoor Firing Range has not been fired on since 1992 and was converted for office use approximately two years ago. The range has not officially been closed and is still listed as an active range. The offices are used during weekends approximately once per month. Janitors cleaned the range and painted the walls three to four times, however, the protocol used by the janitorial staff was not documented. It was unclear during the time of the survey whether or not the ventilation system had been removed.

Scope of Work. The Indoor Firing Range was visually examined and personnel were consulted to accurately assess potential hazards present. The range was evaluated using the wipe sampling protocol used in the National Guard Pamphlet 385-16, which addresses Indoor Firing Range conversion to other uses. Reference information, Instrumentation, Methodology, and Assessment Criteria can be found in Appendix A.

Health Effects and Hazard Determination. The most significant hazard present to employees and users of the indoor firing range is lead dust. Shooters using ammunition with lead primers or bullets manufactured with lead are exposed to lead fumes and dust during the firing process. Furthermore, the lead found in the primer, the melting of the bullet base by hot powder gasses, the shaving and abrasion of the bullet during firing, and fragmentation of the bullet at the point of impact are all potential sources for lead. Further exposure to lead may occur during cleaning of the range, guns, or bullet trap where lead dust is deposited. Lead deposits resulting from firing activities can build up in a firing range over time and must be adequately cleaned and sealed before the range is used for other purposes. If the range is not properly cleaned, the potential for exposure to employees who use the converted area remains.

Lead affects the nervous, circulatory, digestive, excretory, and reproductive systems of both men and women. Lead can build up in the body affecting the blood, heart, and immune systems, if the amount absorbed and stored in the body exceeds the body's ability to expel it. In children, slowed cognitive development and reduced growth are results of overexposure. Pregnant women overexposed to lead are more prone to spontaneous abortions or may give birth to babies with a low birth weight and slowed postnatal neurological development.

FINDINGS, DISCUSSION, AND RECOMMENDATIONS

Ten of the twenty wipe samples taken inside the range exceeded the limit of 200 micrograms per square foot. It is unknown, what type of protocol was used by janitors cleaning this range and it is apparent that lead contamination still exists. Lockers and offices were found in this area and wipe sample results show high levels of contamination. The range is still listed as active, but has been converted to an office and storage area. If the range is to remain active, then all stored and office items must be removed and the range cannot be used for any other purpose than as a firing range. If the range will be officially closed and converted, the indoor firing range should be cleaned so that it is as free of lead dust as possible before the area is used for other purposes to include office space and storage. The following protocol should be used to clean the range and decontaminate items currently stored inside.

Recommendations.

1. Post signs restricting personnel from the range until it has been appropriately cleaned. (RAC 2)
2. No stored items should be handled or used until they have been thoroughly decontaminated. (RAC 2)
3. No eating, drinking, or use of tobacco products should occur in the area. [29 CFR 1910.1025 (i)(1)] (RAC 2)
4. Decide whether the range will be used for range activities (i.e. weapons qualification and firing) or if it would be better suited for storage and office space. The indoor firing range should not be used for both activities. [NGR 385-15, NG PAM 385-16] (RAC 2)
 - a. If the range is to remain active, the range cannot be used for any purpose other than firing. No equipment or furniture can be stored or maintained in the range. The range must meet all requirements of the National Guard Regulation 385-15 regarding Indoor Firing Ranges. Contact the Regional Industrial Hygiene Office regarding requirements. [NGR 385-15 1-18a, 1-17d] (RAC 2)
 - b. If the range is to be used as a storage area and office space, it must be thoroughly decontaminated, reevaluated, and approved prior to its use. Follow all described procedures for cleaning and decontamination of the range and all stored items found in Appendix C. **Contact the Regional Industrial Hygiene Office for approval and reevaluation prior to and after cleaning.** (RAC 2)

Non-Responsive

Industrial Hygienist

APPENDIX A

Environmental Management Solutions

REFERENCES

AR 40-5, Preventative Medicine, 15 October 1990.

AR 385-10, The Army Safety Program, 23 May 1988.

National Guard Regulation (NGR) 385-10, Army National Guard Safety and Occupational Health Program, 29 December 1989.

National Guard Regulation (NGR) 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges, 18 September 2000..

National Guard Pamphlet (NG PAM) 385-16, Guidelines for Converting Firing Ranges to Other Uses, 31 January 1994.

TB MED 503, The Army Industrial Hygiene Program, February 1985.

TB MED 502, Occupational Safety and Health Respiratory Protection Program..

Title 29 Code of Federal Regulations (CFR) 1910.1025, Lead.

Instrumentation

The industrial hygiene survey was conducted utilizing the following pieces of equipment:

Rite Aid Towelettes with Benzalkonium Chloride 1:750, 5% Denatured Alcohol
4" X 4" Template

Methodology.

- A. *Wipe Samples.* Wipe samples were taken utilizing the protocol as set forth by NG PAM 385-16, Guidelines for Converting Firing Ranges to Other Uses. Details of locations where wipe samples were taken can be found in Appendix D.

Assessment Criteria.

- A. *Wipe Samples.* Wipe sample results were compared with Ventilation rates were compared with the NG PAM 385-16, Guidelines for Converting Firing Ranges to Other Uses. See previous page for Reference information.
- B. *Risk Assessment Codes.* Risk Assessment Codes (RACs) are included in this report to quantify the risk of particular operations to employees and to establish funding priorities for corrective actions. RACs are assigned with regard to hazard severity and mishap probability. The type, length, and route of exposure are taken into consideration, as are the medical effects that would occur with such exposures. RAC criteria can be found in Appendix B.

APPENDIX B

Environmental Management Solutions

APPENDIX C

Environmental Management Solutions

Decontamination and Cleaning Protocol

1. Ensure that all procedures listed below comply all federal, state, and local regulations. Consult the Regional Industrial Hygiene Office and State Environmental Office for further guidance.
2. **Ventilation System**
 - i. The range ventilation system must be in operation during all cleaning activities. If no ventilation system is available all doors and windows must be kept sealed to prevent contamination of other areas.
3. **Materials**
 - i. A High Efficiency Particulate Air (HEPA) filtered vacuum system is the preferred method of cleanup. If a HEPA vacuum cannot be obtained a wet method, detailed below, should be utilized. **A high-pressure water system or dry sweeping may not be used.**
 - ii. A cleaning solution containing detergent and water is recommended. New solutions of detergent and water should be mixed frequently.
 - iii. Two containers should be used; one for wetting the applicator (rags, sponge, mop) and the other for rinsing once the dust has been wiped from the surfaces.
 - iv. Wastewater in containers can be left to evaporate. Any waste left in the buckets and applicators should be disposed of as hazardous waste. Consult the Environmental Office for appropriate disposal instructions.
 - v. Personnel responsible for decontamination of the range and stored items should be provided with a full face air purifying respirator with a N100 filter or HEPA filter cartridge providing that all requirements for placing employees in respiratory protection have been met as detailed in 29 CFR 1910.134. Employees should be provided with protective coveralls with hood and shoe covers (i.e. Tyvek™ full body suit). Protective clothing should be hanged daily at the end of the shift and more frequently if the suit becomes grossly contaminated. If cotton coveralls are provided then the employer must provide for maintenance and laundering of protective clothing. Protective clothing should not be taken home and prior to leaving the work area, personnel should thoroughly HEPA vacuum clothing to prevent lead dust from leaving the area. Work and street clothing should not be stored together.
4. **Order of Cleaning**
 - i. A progression of cleaning from top to bottom and from behind the steel backstop to the firing line should be used. All surface areas in the range must be cleaned. Stored items must be decontaminated prior to removal.
 - ii. After removing the sand and the steel backstop, areas in front of and behind the bullet trap along with the steel backstop plates should be cleaned.
 - iii. The ceiling, lights, baffles, retrieval system, heating systems, and ventilation ducts should be cleaned.
 - iv. Acoustical material should be vacuumed instead of being painted over, A Toxic Characteristic Leaching Procedure (TCLP) may need to be used for


acoustical material and the like to determine if the material need to be classified as hazardous and disposed of accordingly. The Environmental Office should be contacted regarding this testing.

- v. The floor should be the last surface cleaned starting at the bullet trap and ending behind the firing line. Concrete floors should be sealed with deck enamel and linoleum on tile floors should be waxed.
 - vi. All walls should be painted, preferably with a sealant, that will help prevent leaching of lead after covering.
 - vii. Following the wet cleaning of the area and after all surfaces have been allowed to dry thoroughly, a HEPA vacuum should be used on all surfaces, until no dust or residue can be seen. A through inspection to detect surface dust should be made following cleanup.
 - viii. The Regional Industrial Hygiene Office should be contacted for clearance sampling and to approve the range for converted use.
5. **Decontamination of stored items.**
- i. All stored items must be decontaminated before removing them from the range. Stored equipment next to the bullet trap and firing line should be decontaminated first.
 - ii. A HEPA vacuum or wet cleaning method should be used. Every attempt should be made to clean the item before disposing as hazardous waste to reduce cost and waste.
 - iii. Porous items such as canvas tents or other fabrics may be laundered at companies, which specialize in industrial laundry services. Office partitions and carpeting present during firing should be considered grossly contaminated and disposed of as hazardous waste. Consult the Environmental office before removing and disposing of items.
6. **Medical Surveillance.**
- i. A preplacement medical examination is required for all individuals involved with range cleanup operations.
7. **Air Monitoring.**
- i. Worker breathing zone air samples must be collected during range cleanup to ensure that workers are not overexposed and to evaluate clean up procedures.
8. **Hazard Training**
- i. A training program must be instituted for all individuals who are subject to exposure to lead at or above the action level of for whom the possibility of skin or eye irritation exists. This training should be provided for all personnel currently involved in rang cleanup operations at least annually.

APPENDIX D

Environmental Management Solutions


Ludlow Indoor Firing Range



Environmental Management Solutions

Ludlow Indoor Firing Range


Office Area



Lockers and other storage items downrange.



Ludlow Indoor Firing Range



1. Ventilation System
2. Bullet Trap Area
3. Wipe Samples

APPENDIX E

Environmental Management Solutions

Sample Number	Location	Micrograms/Sample	Micrograms/Square Foot	Within Allowable Limits?
LW-01	Back wall, left side 8'	<3	<27	Y
LW-02	Back wall, middle 5'	<3	<27	Y
LW-03	Back wall, right side 1'	4.3	38.7	Y
LW-04	Floor, corner left side	11	99	Y
LW-05	Floor, corner backstop	Destroyed during analysis	NA	NA
LW-06	Floor, middle, center of room	45	405	N
LW-07	Left wall, second office	<3	<27	Y
LW-08	Left wall, middle 5'	<3	<27	Y
LW-09	Left wall, 1'	240	2160	N
LW-10	Right wall near backstop 10'	71	639	N
LW-11	Right wall, middle 5'	<3	<27	Y
LW-12	Right wall bottom 1'	6.3	56.7	Y
LW-13	Ceiling, middle, by backstop	58	522	N
LW-14	Ceiling, light fixture, left, middle of room	7.1	63.9	Y
LW-15	Ceiling, baffle, right side near door	27	243	N
LW-16	2 nd storage locker 1 st office	56	504	N
LW-17	Back top, right side 8'	69	621	N
LW-18	Back stop, middle, 4'	400	3600	N
LW-19	Backstop, left side (facing) 2'	380	3420	N
LW-20	Top of locker, near backstop	37	333	N
LW-21	Blank	<3	<27	N
LW-22	Blank	<3	<27	N

Environmental Management Solutions

NATIONAL GUARD BUREAU
ARMY NATIONAL GUARD
REGION NORTH INDUSTRIAL HYGIENE OFFICE
ATTN: NGB-AVN-SI
301-IH OLD BAY LANE
HAVRE DE GRACE, MD 21078-4094

NGB-AVN-SI (40-5f)

12 January 2001

MEMORANDUM FOR The Adjutant General, VT ARNG, ATTN: State Safety
Office (LTC **Non-Responsive**), G.M.A., Camp Johnson,
Colchester, VT 05446-3004

SUBJECT: Indoor Firing Range Survey at Ludlow Armory

1. Enclosed is the industrial hygiene survey report prepared by Environmental Management Solutions. I concur with the overall recommendations made by Ms. **Non-Responsive**
2. Please call me at 410/942-0273 ext. 17 if you have any questions or comments about this report.

Encl
Survey Report

Non-Responsive

Regional Industrial Hygienist

CF:
Unit Commander
Facility Engineer, COL **Non-Responsive**

Lyndonville Armory Indoor Firing Range

PO BOX 6893, DOUGLASVILLE, GEORGIA 30154
PHONE: 678.596.8509 • FAX: 770.234.6297

Table of Contents

Executive Summary.....	Page 1
Subject	Page 2
Background	
Introduction	
Site Description	
Scope of Work	
Health effects and hazard determination	
Findings, Discussion, and Recommendations	Page 3
Appendices	
A. References	
B. RAC Table	
C. Decontamination and Cleaning Protocol	
D. Photographs, Range Drawings	
E. Wipe Sampling Results	

EXECUTIVE SUMMARY

FINDINGS	RECOMMENDATIONS	RAC
<i>The Lydonville indoor firing range is listed as active, however this area is used as storage space.</i>	An official decision as to the status of this range should be immediately determined. If the range is to remain active, it must meet requirements set forth in NGR 385-15. If the range is to be converted, it must be adequately cleaned and decontaminated before employee use can resume.	RAC 2
<i>Ten out of twenty wipe sample results were above the maximum allowable limit of 200 micrograms per square foot. It is unclear what type of protocol janitors cleaning this range used.</i>	If the range is to be converted, it must be cleaned in accordance with National Guard Regulations before employee use can resume.	RAC 2

SUBJECT: Industrial Hygiene Survey of the Lydonville Indoor Firing Range Survey performed 18 October 2000 at Lydonville Armory, VT.

BACKGROUND:

Introduction. At the request of Ms. [Non-Responsive] of the National Guard Bureau Region North Industrial Hygiene Office, an industrial hygiene survey was performed at the Lydonville Indoor Firing Range at the Lydonville Armory in Vermont. [Non-Responsive] contract industrial hygienist, Ms. [Non-Responsive] and Mr. [Non-Responsive] Regional Industrial Hygienists, and CPT [Non-Responsive] Occupational Health Nurse, Vermont Army National Guard, conducted the survey on 18 October 2000. The purpose of the survey was to perform a comprehensive industrial hygiene survey to evaluate range characteristics, ventilation, and quantify employee exposure to lead dust.

Site Description. The Lydonville Indoor Firing Range is currently listed as an active range but is being used as a storage area for lockers, computer equipment, and other materials. The target retrieval system, sand trap, and bullet stop are all still in place.

Scope of Work. The Indoor Firing Range was visually examined and personnel were consulted to accurately assess potential hazards present. The range was evaluated using the wipe sampling protocol used in the National Guard Pamphlet 385-16, which addresses Indoor Firing Range conversion to other uses. Reference information, Instrumentation, Methodology, and Assessment Criteria can be found in Appendix A.

Health Effects and Hazard Determination. The most significant hazard present to employees and users of the indoor firing range is lead dust. Shooters using ammunition with lead primers or bullets manufactured with lead are exposed to lead fumes and dust during the firing process. Furthermore, the lead found in the primer, the melting of the bullet base by hot powder gasses, the shaving and abrasion of the bullet during firing, and fragmentation of the bullet at the point of impact are all potential sources for lead. Further exposure to lead may occur during cleaning of the range, guns, or bullet trap where lead dust is deposited. Lead deposits resulting from firing activities can build up in a firing range over time and must be adequately cleaned and sealed before the range is used for other purposes. If the range is not properly cleaned, the potential for exposure to employees who use the converted area remains.

Lead affects the nervous, circulatory, digestive, excretory, and reproductive systems of both men and women. Lead can build up in the body affecting the blood, heart, and immune systems, if the amount absorbed and stored in the body exceeds the body's ability to expel it. In children, slowed cognitive development and reduced growth are results of overexposure. Pregnant women overexposed to lead are more prone to spontaneous abortions or may give birth to babies with a low birth weight and slowed postnatal neurological development.

FINDINGS, DISCUSSION, AND RECOMMENDATIONS

Ten out of twenty wipe samples taken inside the range exceeded the limit of 200 micrograms per square foot. It is unknown, what type of protocol was used by janitors cleaning this range and it is apparent that lead contamination still exists. Light fixtures, walls, and beams, as well as a wipe sample taken in the office are show high levels of contamination. The range is still listed as active, but has been converted to a storage area. If the range is to remain active, then all stored items must be removed and the range cannot be used for any other purpose than as a firing range. If the range will be officially closed and converted, the indoor firing range should be cleaned so that it is as free of lead dust as possible before the area is used for other purposes to include storage. The following protocol should be used to clean the range and decontaminate items currently stored inside.

Recommendations

1. Post signs restricting personnel from the range until it has been appropriately cleaned. (RAC 2)
2. No stored items should be handled or used until they have been thoroughly decontaminated. (RAC 2)
3. No eating, drinking, or use of tobacco products should occur in the area. [29 CFR 1910.1025 (i)(1)] (RAC 2)
4. Decide whether the range will be used for range activities (i.e. weapons qualification and firing) or if it would be better suited for storage and office space. The indoor firing range should not be used for both activities. [NGR 385-15, NG PAM 385-16] (RAC 2)
 - a. If the range is to remain active, the range cannot be used for any purpose other than firing. No equipment or furniture can be stored or maintained in the range. The range must meet all requirements of the National Guard Regulation 385-15 regarding Indoor Firing Ranges. Contact the Regional Industrial Hygiene Office regarding requirements. [NGR 385-15 1-18a, 1-17d] (RAC 2)
 - b. If the range is to be used as a storage area and office space, it must be thoroughly decontaminated, reevaluated, and approved prior to its use. Follow all described procedures for cleaning and decontamination of the range and all stored items found in Appendix C. **Contact the Regional Industrial Hygiene Office for approval and reevaluation prior to and after cleaning.** (RAC 2)

Non-Responsive

Industrial Hygienist

APPENDIX A

Environmental Management Solutions

REFERENCES

AR 40-5, Preventative Medicine, 15 October 1990.

AR 385-10, The Army Safety Program, 23 May 1988.

National Guard Regulation (NGR) 385-10, Army National Guard Safety and Occupational Health Program, 29 December 1989.

National Guard Regulation (NGR) 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges, 18 September 2000..

National Guard Pamphlet (NG PAM) 385-16, Guidelines for Converting Firing Ranges to Other Uses, 31 January 1994.

TB MED 503, The Army Industrial Hygiene Program, February 1985.

TB MED 502, Occupational Safety and Health Respiratory Protection Program..

Title 29 Code of Federal Regulations (CFR) 1910.1025, Lead.

Instrumentation

The industrial hygiene survey was conducted utilizing the following pieces of equipment:

Rite Aid Towelettes with Benzalkonium Chloride 1:750, 5% Denatured Alcohol
4" X 4" Template

Methodology

- A. *Wipe Samples.* Wipe samples were taken utilizing the protocol as set forth by NG PAM 385-16, Guidelines for Converting Firing Ranges to Other Uses. Details of locations where wipe samples were taken can be found in Appendix D.

Assessment Criteria

- A. *Wipe Samples.* Wipe sample results were compared with Ventilation rates were compared with the NG PAM 385-16, Guidelines for Converting Firing Ranges to Other Uses. See previous page for Reference information.
- B. *Risk Assessment Codes.* Risk Assessment Codes (RACs) are included in this report to quantify the risk of particular operations to employees and to establish funding priorities for corrective actions. RACs are assigned with regard to hazard severity and mishap probability. The type, length, and route of exposure are taken into consideration, as are the medical effects that would occur with such exposures. RAC criteria can be found in Appendix B.

APPENDIX B

Environmental Management Solutions

**DERIVING RISK ASSESSMENT CODES (RACs)
FOR HEALTH HAZARDS
(Ref: DOD Instruction 6055.1)**

STEP 1. Using the following procedures to assess points, determine the health hazard severity category (HHSC). The HHSC reflects the magnitude of exposure to a physical, chemical, or biological agent and the medical effects of exposure.

A. Exposure Points Assessed

		Exposure Conditions			
		<CT	Occasionally - >CT Always - <STD	>CT =STD	>STD
AER	NO	0	3	5	7
POSSIBLE?	YES	1-2	4	6	8

AER = Alternate exposure route, such as skin absorption, ingestion

CT = DoD component threshold that triggers surveillance actions, such as microWatts/cm², dB, parts per million

STD = DoD exposure limit, such as Threshold Limit Value and Permissible Exposure Limit

B. Medical Effects Points Assessed

<u>Condition</u>	<u>Points</u>
No medical effect, such as nuisance noise and nuisance odor	0
Temporary reversible illness requiring supportive treatment, such as eye irritation and sore throat	1-2
Temporary reversible illness with a variable but limited period of disability such as metal fume fever	3-4
Permanent, nonsevere illness or loss of capacity, such as permanent hearing loss	5-6
Permanent, severe, disabling, irreversible illness or death, such as asbestosis and lung cancer	7-8

C. Determine the HHSC by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>HHSC</u>
13-16	I
9-12	II
5-8	III
0-4	IV

STEP 2. Using the following guides to assess points, determine the mishap probability category (MPC) for health hazards. The probability of mishap reflects the duration of exposure and the number of exposed personnel.

A. Duration of Exposure Points Assessed

		<u>Length of Exposure</u>		
		1-8 hr/wk	>8 hr/wk continuous	not continuous
<u>Type of Exposure</u>	Irregular, intermittent	1-2	4-6	-
	Regular, periodic	2-3	5-7	8

B. Number of Exposed Personnel Points Assessed

<u>Number of Exposed Personnel</u>	<u>Points</u>
<5	1-2
5 to 9	3-4
to 49	5-6
>49	7-8

C. Determine the MPC for health hazards by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>MPC</u>
14-16	A
10-13	B
5-9	C
<5	D

STEP 3. Determine the RAC for health hazards by using the following matrix to measure health hazard severity and mishap probability factors.

		<u>MISHAP PROBABILITY</u>			
		<u>A</u>	<u>B</u>	<u>C</u>	<u>D</u>
<u>HAZARD SEVERITY</u>	<u>I</u>	1	1	2	3
	<u>II</u>	1	2	3	4
	<u>III</u>	2	3	4	5
	<u>IV</u>	3	4	5	5

APPENDIX C

Environmental Management Solutions

Decontamination and Cleaning Protocol

1. Ensure that all procedures listed below comply all federal, state, and local regulations. Consult the Regional Industrial Hygiene Office and State Environmental Office for further guidance.
2. **Ventilation System**
 - i. The range ventilation system must be in operation during all cleaning activities. If no ventilation system is available all doors and windows must be kept sealed to prevent contamination of other areas.
3. **Materials**
 - i. A High Efficiency Particulate Air (HEPA) filtered vacuum system is the preferred method of cleanup. If a HEPA vacuum cannot be obtained a wet method, detailed below, should be utilized. **A high-pressure water system or dry sweeping may not be used.**
 - ii. A cleaning solution containing detergent and water is recommended. New solutions of detergent and water should be mixed frequently.
 - iii. Two containers should be used; one for wetting the applicator (rags, sponge, mop) and the other for rinsing once the dust has been wiped from the surfaces.
 - iv. Wastewater in containers can be left to evaporate. Any waste left in the buckets and applicators should be disposed of as hazardous waste. Consult the Environmental Office for appropriate disposal instructions.
 - v. Personnel responsible for decontamination of the range and stored items should be provided with a full face air purifying respirator with a N100 filter or HEPA filter cartridge providing that all requirements for placing employees in respiratory protection have been met as detailed in 29 CFR 1910.134. Employees should be provided with protective coveralls with hood and shoe covers (i.e. Tyvek™ full body suit). Protective clothing should be hanged daily at the end of the shift and more frequently if the suit becomes grossly contaminated. If cotton coveralls are provided then the employer must provide for maintenance and laundering of protective clothing. Protective clothing should not be taken home and prior to leaving the work area, personnel should thoroughly HEPA vacuum clothing to prevent lead dust from leaving the area. Work and street clothing should not be stored together.
4. **Order of Cleaning**
 - i. A progression of cleaning from top to bottom and from behind the steel backstop to the firing line should be used. All surface areas in the range must be cleaned. Stored items must be decontaminated prior to removal.
 - ii. After removing the sand and the steel backstop, areas in front of and behind the bullet trap along with the steel backstop plates should be cleaned.
 - iii. The ceiling, lights, baffles, retrieval system, heating systems, and ventilation ducts should be cleaned.
 - iv. Acoustical material should be vacuumed instead of being painted over, A Toxic Characteristic Leaching Procedure (TCLP) may need to be used for

acoustical material and the like to determine if the material need to be classified as hazardous and disposed of accordingly. The Environmental Office should be contacted regarding this testing.

- v. The floor should be the last surface cleaned starting at the bullet trap and ending behind the firing line. Concrete floors should be sealed with deck enamel and linoleum on tile floors should be waxed.
- vi. All walls should be painted, preferably with a sealant, that will help prevent leaching of lead after covering.
- vii. Following the wet cleaning of the area and after all surfaces have been allowed to dry thoroughly, a HEPA vacuum should be used on all surfaces, until no dust or residue can be seen. A through inspection to detect surface dust should be made following cleanup.
- viii. The Regional Industrial Hygiene Office should be contacted for clearance sampling and to approve the range for converted use.

5. Decontamination of stored items.

- i. All stored items must be decontaminated before removing them from the range. Stored equipment next to the bullet trap and firing line should be decontaminated first.
- ii. A HEPA vacuum or wet cleaning method should be used. Every attempt should be made to clean the item before disposing as hazardous waste to reduce cost and waste.
- iii. Porous items such as canvas tents or other fabrics may be laundered at companies, which specialize in industrial laundry services. Office partitions and carpeting present during firing should be considered grossly contaminated and disposed of as hazardous waste. Consult the Environmental office before removing and disposing of items.

6. Medical Surveillance.

- i. A preplacement medical examination is required for all individuals involved with range cleanup operations.

7. Air Monitoring.

- i. Worker breathing zone air samples must be collected during range cleanup to ensure that workers are not overexposed and to evaluate clean up procedures.

8. Hazard Training


- i. A training program must be instituted for all individuals who are subject to exposure to lead at or above the action level of for whom the possibility of skin or eye irritation exists. This training should be provided for all personnel currently involved in rang cleanup operations at least annually.

APPENDIX D


Environmental Management Solutions

Lyndonville Indoor Firing Range

Stored items behind the firing line




Bullet Trap



Lockers downrange

Lyndonville Indoor Firing Range



Environmental Management Solutions

APPENDIX E

Environmental Management Solutions

Sample Number	Location	Micrograms/Sample	Micrograms/Square Foot	Within Allowable Limits?
LY-01	Back wall, left corner 8'	4.5	40.5	Y
LY-02	Back wall, right corner, 1'	<3	<27	Y
LY-03	Back wall, middle 5' from floor, 4' from right wall	<3	<27	Y
LY-04	Right wall, 5' from floor toward, 10' from back wall	<3	<27	Y
LY-05	Right wall, 5' from floor between 1 st and 2 nd baffle	<3	<27	Y
LY-06	Right wall, 18" from floor	320	2880	N
LY-07	Ceiling, 18" from left wall, 3' from back wall	<3	<27	Y
LY-08	Ceiling, middle, 2 nd baffle	19	171	Y
LY-09	Ceiling, 1 st light from left wall	1800	16200	N
LY-10	Left wall, 5' from floor	<3	<27	Y
LY-11	Left wall, 1' from floor, between 2 nd and 3 rd baffles	<3	<27	Y
LY-12	Left wall, 8' from floor, near backstop	77	693	N
LY-13	Back stop, left corner, 1' from floor, 2' from left wall	4000	36000	N
LY-14	Back stop, middle 8' from floor	1407	1260	N
LY-15	Back stop, right corner, 5' from floor	2700	24300	N
LY-16	Floor, left corner, 1' from wall, behind storage lockers	120	1080	N
LY-17	Floor, under 10 th locker from front, 12' from wall	100	900	N
LY-18	Floor, just inside door, 1' from right wall	81	729	N
LY-19	Top of locker, toward back stop	48	432	N
LY-20	Right side of locker toward back of wall	7.9	71.1	Y
LY-21	Blank	<3	<27	Y

NATIONAL GUARD BUREAU
ARMY NATIONAL GUARD
REGION NORTH INDUSTRIAL HYGIENE OFFICE
ATTN: NGB-AVN-SI
301-IH OLD BAY LANE
HAVRE DE GRACE, MD 21078-4094

NGB-AVN-SI (40-5f)

12 January 2001

MEMORANDUM FOR The Adjutant General, VT ARNG, ATTN: State Safety
Office (LTC **Non-Responsive**, G.M.A., Camp Johnson,
Colchester, VT 05446-3004

SUBJECT: Indoor Firing Range Survey at Lyndonville Armory

1. Enclosed is the industrial hygiene survey report prepared by Environmental Management Solutions. I concur with the overall recommendations made by Ms **Non-Responsive**
2. Please call me at 410/942-0273 ext. 17 if you have any questions or comments about this report.

Encl
Survey Report

Non-Responsive

Regional Industrial Hygienist

CF:
Unit Commander
Facility Engineer, COL **Non-Responsive**

Morrisville Armory Indoor Firing Range

PO BOX 6893, DOUGLASVILLE, GEORGIA 30154
PHONE: 678.596.8509 • FAX: 770.234.6297

Table of Contents

Executive Summary Page 1

Subject Page 2

Background

- Introduction
- Site Description
- Scope of Work
- Health effects and hazard determination

Findings, Discussion, and Recommendations Page 3

Appendices

- A. References
- B. RAC Table
- C. Decontamination and Cleaning Protocol
- D. Photographs, Range Drawings
- E. Wipe Sampling Results

SUBJECT: Industrial Hygiene Survey of the Morrisville Indoor Firing Range Survey performed 19 October 2000 at Morrisville Armory, VT.

BACKGROUND:

Introduction. At the request of Ms. [Non-Responsive] of the National Guard Bureau Region North Industrial Hygiene Office, an industrial hygiene survey was performed at the Morrisville Indoor Firing Range at the Morrisville Armory in Vermont. Ms. [Non-Responsive] [Non-Responsive] contract industrial hygienist, Ms. [Non-Responsive] and Mr. [Non-Responsive] [Non-Responsive] Regional Industrial Hygienists, and CPT [Non-Responsive] Occupational Health Nurse, Vermont Army National Guard, conducted the survey on 19 October 2000. The purpose of the survey was to perform a comprehensive industrial hygiene survey to evaluate range characteristics, ventilation, and quantify employee exposure to lead dust.

Site Description. The Morrisville Indoor Firing Range has not been officially used for approximately nine years. It was last cleaned approximately two years ago and painting occurred before the range was cleaned. The floor has not been sealed. The ventilation system, target retrieval, system, and firing lanes are still present in the range. The area is currently used as a storage area with open boxes and food serving equipment inside. The range has not officially been closed and is still listed as an active range.

Scope of Work. The Indoor Firing Range was visually examined and personnel were consulted to accurately assess potential hazards present. The range was evaluated using the wipe sampling protocol used in the National Guard Pamphlet 385-16, which addresses Indoor Firing Range conversion to other uses. Reference information, Instrumentation, Methodology, and Assessment Criteria can be found in Appendix A.

Health Effects and Hazard Determination. The most significant hazard present to employees and users of the indoor firing range is lead dust. Shooters using ammunition with lead primers or bullets manufactured with lead are exposed to lead fumes and dust during the firing process. Furthermore, the lead found in the primer, the melting of the bullet base by hot powder gasses, the shaving and abrasion of the bullet during firing, and fragmentation of the bullet at the point of impact are all potential sources for lead. Further exposure to lead may occur during cleaning of the range, guns, or bullet trap where lead dust is deposited. Lead deposits resulting from firing activities can build up in a firing range over time and must be adequately cleaned and sealed before the range is used for other purposes. If the range is not properly cleaned, the potential for exposure to employees who use the converted area remains.

Lead affects the nervous, circulatory, digestive, excretory, and reproductive systems of both men and women. Lead can build up in the body affecting the blood, heart, and immune systems, if the amount absorbed and stored in the body exceeds the body's ability to expel it. In children, slowed cognitive development and reduced growth are results of overexposure. Pregnant women overexposed to lead are more prone to spontaneous abortions or may give birth to babies with a low birth weight and slowed postnatal neurological development.

FINDINGS, DISCUSSION, AND RECOMMENDATIONS

Nine out of twenty-two wipe samples taken inside the range exceeded the limit of 200 micrograms per square foot. It is unknown, what type of protocol was used by janitors cleaning this range and it is apparent that lead contamination still exists. Areas near the backstop and a table stored in the range show high levels of contamination. The range is listed as active but is used for storage of boxes and food service equipment. If the range is to remain active, then all stored items must be removed and the range cannot be used for any other purpose than as a firing range. If the range will be officially closed and converted, the indoor firing range should be cleaned so that it is as free of lead dust as possible before the area is used for other purposes to include office space and storage. The following protocol should be used to clean the range and decontaminate items currently stored inside.

Recommendations

1. Post signs restricting personnel from the range until it has been appropriately cleaned. **(RAC 2)**
2. No stored items should be handled or used until they have been thoroughly decontaminated. **(RAC 2)**
3. No eating, drinking, or use of tobacco products should occur in the area. [29 CFR 1910.1025 (i)(1)] **(RAC 2)**
4. Decide whether the range will be used for range activities (i.e. weapons qualification and firing) or if it would be better suited for storage and office space. The indoor firing range should not be used for both activities. [NGR 385-15, NG PAM 385-16] **(RAC 2)**
 - a. If the range is to remain active, the range cannot be used for any purpose other than firing. No equipment or furniture can be stored or maintained in the range. The range must meet all requirements of the National Guard Regulation 385-15 regarding Indoor Firing Ranges. Contact the Regional Industrial Hygiene Office regarding requirements. [NGR 385-15 1-18a, 1-17d] **(RAC 2)**
 - b. If the range is to be used as a storage area and office space, it must be thoroughly decontaminated, reevaluated, and approved prior to its use. Follow all described procedures for cleaning and decontamination of the range and all stored items found in Appendix C. **Contact the Regional Industrial Hygiene Office for approval and reevaluation prior to and after cleaning. (RAC 2)**

Non-Responsive

Industrial Hygienist

APPENDIX A

Environmental Management Solutions

REFERENCES

AR 40-5, Preventative Medicine, 15 October 1990.

AR 385-10, The Army Safety Program, 23 May 1988.

National Guard Regulation (NGR) 385-10, Army National Guard Safety and Occupational Health Program, 29 December 1989.

National Guard Regulation (NGR) 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges, 18 September 2000..

National Guard Pamphlet (NG PAM) 385-16, Guidelines for Converting Firing Ranges to Other Uses, 31 January 1994.

TB MED 503, The Army Industrial Hygiene Program, February 1985.

TB MED 502, Occupational Safety and Health Respiratory Protection Program..

Title 29 Code of Federal Regulations (CFR) 1910.1025, Lead.

Instrumentation

The industrial hygiene survey was conducted utilizing the following pieces of equipment:

Rite Aid Towelettes with Benzalkonium Chloride 1:750, 5% Denatured Alcohol
4" X 4" Template

Methodology

- A. *Wipe Samples.* Wipe samples were taken utilizing the protocol as set forth by NG PAM 385-16, Guidelines for Converting Firing Ranges to Other Uses. Details of locations where wipe samples were taken can be found in Appendix D.

Assessment Criteria

- A. *Wipe Samples.* Wipe sample results were compared with Ventilation rates were compared with the NG PAM 385-16, Guidelines for Converting Firing Ranges to Other Uses. See previous page for Reference information.
- B. *Risk Assessment Codes.* Risk Assessment Codes (RACs) are included in this report to quantify the risk of particular operations to employees and to establish funding priorities for corrective actions. RACs are assigned with regard to hazard severity and mishap probability. The type, length, and route of exposure are taken into consideration, as are the medical effects that would occur with such exposures. RAC criteria can be found in Appendix B.

APPENDIX D

Environmental Management Solutions

**DERIVING RISK ASSESSMENT CODES (RACs)
FOR HEALTH HAZARDS
(Ref: DOD Instruction 6055.1)**

STEP 1. Using the following procedures to assess points, determine the health hazard severity category (HHSC). The HHSC reflects the magnitude of exposure to a physical, chemical, or biological agent and the medical effects of exposure.

A. Exposure Points Assessed

		Exposure Conditions			
		<CT	Occasionally - >CT Always - <STD	>CT =STD	>STD
AER	NO	0	3	5	7
POSSIBLE?	YES	1-2	4	6	8

AER = Alternate exposure route, such as skin absorption, ingestion

CT = DoD component threshold that triggers surveillance actions, such as microWatts/cm², dB, parts per million

STD = DoD exposure limit, such as Threshold Limit Value and Permissible Exposure Limit

B. Medical Effects Points Assessed

<u>Condition</u>	<u>Points</u>
No medical effect, such as nuisance noise and nuisance odor	0
Temporary reversible illness requiring supportive treatment, such as eye irritation and sore throat	1-2
Temporary reversible illness with a variable but limited period of disability such as metal fume fever	3-4
Permanent, nonsevere illness or loss of capacity, such as permanent hearing loss	5-6
Permanent, severe, disabling, irreversible illness or death, such as asbestosis and lung cancer	7-8

C. Determine the HHSC by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>HHSC</u>
13-16	I
9-12	II
5-8	III
0-4	IV

STEP 2. Using the following guides to assess points, determine the mishap probability category (MPC) for health hazards. The probability of mishap reflects the duration of exposure and the number of exposed personnel.

A. Duration of Exposure Points Assessed

		<u>Length of Exposure</u>		
		1-8 hr/wk	>8 hr/wk continuous not continuous	
<u>Type of Exposure</u>	Irregular, intermittent	1-2	4-6	-
	Regular, periodic	2-3	5-7	8

B. Number of Exposed Personnel Points Assessed

<u>Number of Exposed Personnel</u>	<u>Points</u>
<5	1-2
5 to 9	3-4
to 49	5-6
>49	7-8

C. Determine the MPC for health hazards by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>MPC</u>
14-16	A
10-13	B
5-9	C
<5	D

STEP 3. Determine the RAC for health hazards by using the following matrix to measure health hazard severity and mishap probability factors.

		<u>MISHAP PROBABILITY</u>			
		<u>A</u>	<u>B</u>	<u>C</u>	<u>D</u>
<u>HAZARD SEVERITY</u>	<u>I</u>	1	1	2	3
	<u>II</u>	1	2	3	4
	<u>III</u>	2	3	4	5
	<u>IV</u>	3	4	5	5

APPENDIX C

Environmental Management Solutions

Decontamination and Cleaning Protocol

1. Ensure that all procedures listed below comply all federal, state, and local regulations. Consult the Regional Industrial Hygiene Office and State Environmental Office for further guidance.

2. **Ventilation System**
 - i. The range ventilation system must be in operation during all cleaning activities. If no ventilation system is available all doors and windows must be kept sealed to prevent contamination of other areas.

3. **Materials**
 - i. A High Efficiency Particulate Air (HEPA) filtered vacuum system is the preferred method of cleanup. If a HEPA vacuum cannot be obtained a wet method, detailed below, should be utilized. **A high-pressure water system or dry sweeping may not be used.**
 - ii. A cleaning solution containing detergent and water is recommended. New solutions of detergent and water should be mixed frequently.
 - iii. Two containers should be used; one for wetting the applicator (rags, sponge, mop) and the other for rinsing once the dust has been wiped from the surfaces.
 - iv. Wastewater in containers can be left to evaporate. Any waste left in the buckets and applicators should be disposed of as hazardous waste. Consult the Environmental Office for appropriate disposal instructions.
 - v. Personnel responsible for decontamination of the range and stored items should be provided with a full face air purifying respirator with a N100 filter or HEPA filter cartridge providing that all requirements for placing employees in respiratory protection have been met as detailed in 29 CFR 1910.134. Employees should be provided with protective coveralls with hood and shoe covers (i.e. Tyvek™ full body suit). Protective clothing should be hanged daily at the end of the shift and more frequently if the suit becomes grossly contaminated. If cotton coveralls are provided then the employer must provide for maintenance and laundering of protective clothing. Protective clothing should not be taken home and prior to leaving the work area, personnel should thoroughly HEPA vacuum clothing to prevent lead dust from leaving the area. Work and street clothing should not be stored together.

4. **Order of Cleaning**
 - i. A progression of cleaning from top to bottom and from behind the steel backstop to the firing line should be used. All surface areas in the range must be cleaned. Stored items must be decontaminated prior to removal.
 - ii. After removing the sand and the steel backstop, areas in front of and behind the bullet trap along with the steel backstop plates should be cleaned.
 - iii. The ceiling, lights, baffles, retrieval system, heating systems, and ventilation ducts should be cleaned.
 - iv. Acoustical material should be vacuumed instead of being painted over, A Toxic Characteristic Leaching Procedure (TCLP) may need to be used for

- acoustical material and the like to determine if the material need to be classified as hazardous and disposed of accordingly. The Environmental Office should be contacted regarding this testing.
- v. The floor should be the last surface cleaned starting at the bullet trap and ending behind the firing line. Concrete floors should be sealed with deck enamel and linoleum on tile floors should be waxed.
 - vi. All walls should be painted, preferably with a sealant, that will help prevent leaching of lead after covering.
 - vii. Following the wet cleaning of the area and after all surfaces have been allowed to dry thoroughly, a HEPA vacuum should be used on all surfaces, until no dust or residue can be seen. A through inspection to detect surface dust should be made following cleanup.
 - viii. The Regional Industrial Hygiene Office should be contacted for clearance sampling and to approve the range for converted use.
5. **Decontamination of stored items.**
- i. All stored items must be decontaminated before removing them from the range. Stored equipment next to the bullet trap and firing line should be decontaminated first.
 - ii. A HEPA vacuum or wet cleaning method should be used. Every attempt should be made to clean the item before disposing as hazardous waste to reduce cost and waste.
 - iii. Porous items such as canvas tents or other fabrics may be laundered at companies, which specialize in industrial laundry services. Office partitions and carpeting present during firing should be considered grossly contaminated and disposed of as hazardous waste. Consult the Environmental office before removing and disposing of items.
6. **Medical Surveillance.**
- i. A preplacement medical examination is required for all individuals involved with range cleanup operations.
7. **Air Monitoring.**
- i. Worker breathing zone air samples must be collected during range cleanup to ensure that workers are not overexposed and to evaluate clean up procedures.
8. **Hazard Training**
- i. A training program must be instituted for all individuals who are subject to exposure to lead at or above the action level of for whom the possibility of skin or eye irritation exists. This training should be provided for all personnel currently involved in rang cleanup operations at least annually.

APPENDIX D

Environmental Management Solutions

Morrisville Indoor Firing Range


Stored items behind the firing line.



Downrange.



Morrisville Indoor Firing Range



Environmental Management Solutions

APPENDIX E

Environmental Management Solutions

Sample Number	Location	Micrograms/Sample	Micrograms/Square Foot	Within Allowable Limits?
MV-01	Back wall, 9', right corner	<3	<27	Y
MV-02	Back wall, 5', middle	<3	<27	Y
MV-03	Back wall, 1', left corner	<3	<27	Y
MV-04	Right wall, 1', just inside entrance to the left	<3	<27	Y
MV-05	Left wall, 5', middle of range	320	2880	N
MV-06	Right wall, 9', near back stop	<3	<27	Y
MV-07	Left wall, 9', left corner	<3	<27	Y
MV-08	Right wall, 5', middle of range	<3	<27	Y
MV-09	Left wall, 9', near backstop	<3	<27	Y
MV-10	Ceiling, right corner	<3	<27	Y
MV-11	Ceiling, 2 nd baffle, middle of range	24	216	N
MV-12	Ceiling, left most light fixture	170	1530	N
MV-13	Floor, 1' from each wall, left corner	3.7	33.3	Y
MV-14	Floor, middle of room, between 2 nd and 3 rd baffle	180	1620	N
MV-15	Floor, right corner, near backstop	4000	36000	N
MV-16	Backstop, 8'	100	900	N
MV-17	Backstop, 5'	280	2520	N
MV-18	Backstop 3'	310	2790	N
MV-19	Right table middle of room	34	306	N
MV-20	BLANK	<3	<27	Y
MV-21	Left wall, 1' near backstop	3.9	35.1	Y
MV-22	BLANK	<3	<27	Y
MV-23	Outside of door, left, underneath locker	6.8	61.2	Y
MV-24	Food server, steam table, left of room	<3	<27	Y

Environmental Management Solutions

ENVIRONMENTAL MANAGEMENT SOLUTIONS
INDUSTRIAL HYGIENE CONSULTING

North Springfield Armory
Indoor Firing Range

PO BOX 6893, DOUGLASVILLE, GEORGIA 30154
PHONE: 678.596.8509 • FAX: 770.234.6297

Table of Contents

Executive Summary..... Page 1

Subject Page 2

Background

Introduction

Site Description

Scope of Work

Health effects and hazard determination

Findings, Discussion, and Recommendations Page 3

Appendices

A. References

B. RAC Table

C. Decontamination and Cleaning Protocol

D. Photographs, Range Drawings

E. Wipe Sampling Results

EXECUTIVE SUMMARY

FINDINGS	RECOMMENDATIONS	RAC
<p><i>The North Springfield indoor firing range has not been fired on for fifteen to twenty years. The range is listed as active, however offices have been put in this area as well as storage items to include lockers and other equipment.</i></p>	<p>An official decision as to the status of this range should be immediately determined. If the range is to remain active, it must meet requirements set forth in NGR 385-15. If the range is to be converted, it must be adequately cleaned and decontaminated before employee use can resume.</p>	RAC 2
<p><i>Four of the twenty-four wipe sample results were above the maximum allowable limit of 200 micrograms per square foot. It is unclear what type of protocol janitors cleaning this range used.</i></p>	<p>If the range is to be converted, it must be cleaned in accordance with National Guard Regulations before employee use can resume.</p>	RAC 2

SUBJECT: Industrial Hygiene Survey of the North Springfield Indoor Firing Range Survey performed 17 October 2000 at North Springfield Armory, VT.

BACKGROUND:

Introduction. At the request of Ms. [Non-Responsive] of the National Guard Bureau Region North Industrial Hygiene Office, an industrial hygiene survey was performed at the North Springfield Armory in Vermont. Ms. [Non-Responsive] contract industrial hygienist, Ms. [Non-Responsive] and Mr. [Non-Responsive] Regional Industrial Hygienists, and CPT [Non-Responsive] Occupational Health Nurse, Vermont Army National Guard, conducted the survey on 17 October 2000. The purpose of the survey was to perform a comprehensive industrial hygiene survey to evaluate range characteristics, ventilation, and quantify employee exposure to lead dust.

Site Description. The North Springfield Indoor Firing Range was cleaned with clearance samples below 200 micrograms in late 1998 to early 1999. The range was painted, but personnel are unsure if the range was sealed after painting. The range has been used for a storage area for at least fifteen to twenty years. The ventilation system is present from the original range. The range has not officially been closed and is still listed as an active range.

Scope of Work. The Indoor Firing Range was visually examined and personnel were consulted to accurately assess potential hazards present. The range was evaluated using the wipe sampling protocol used in the National Guard Pamphlet 385-16, which addresses Indoor Firing Range conversion to other uses. Reference information, Instrumentation, Methodology, and Assessment Criteria can be found in Appendix A.

Health Effects and Hazard Determination. The most significant hazard present to employees and users of the indoor firing range is lead dust. Shooters using ammunition with lead primers or bullets manufactured with lead are exposed to lead fumes and dust during the firing process. Furthermore, the lead found in the primer, the melting of the bullet base by hot powder gasses, the shaving and abrasion of the bullet during firing, and fragmentation of the bullet at the point of impact are all potential sources for lead. Further exposure to lead may occur during cleaning of the range, guns, or bullet trap where lead dust is deposited. Lead deposits resulting from firing activities can build up in a firing range over time and must be adequately cleaned and sealed before the range is used for other purposes. If the range is not properly cleaned, the potential for exposure to employees who use the converted area remains.

Lead affects the nervous, circulatory, digestive, excretory, and reproductive systems of both men and women. Lead can build up in the body affecting the blood, heart, and immune systems, if the amount absorbed and stored in the body exceeds the body's ability to expel it. In children, slowed cognitive development and reduced growth are results of overexposure. Pregnant women overexposed to lead are more prone to spontaneous abortions or may give birth to babies with a low birth weight and slowed postnatal neurological development.

FINDINGS, DISCUSSION, AND RECOMMENDATIONS

Four out of the twenty-four wipe samples taken inside the range exceeded the limit of 200 micrograms per square foot. High levels were concentrated around the bullet trap still present in the range. It is unknown, what type of protocol was used by janitors cleaning this range, and it is apparent that some lead contamination still exists. The range is still listed as active, but is being used as storage space for lockers and other equipment. If the range is to remain active, then all stored items must be removed and the range cannot be used for any other purpose than as a firing range. If the range will be officially closed and converted, the indoor firing range should be cleaned so that it is as free of lead dust as possible before the area is used for other purposes to include office space and storage. The following protocol should be used to clean the range and decontaminate items currently stored inside.

Recommendations.

1. Post signs restricting personnel from the range until it has been appropriately cleaned. **(RAC 2)**
2. No stored items should be handled or used until they have been thoroughly decontaminated. **(RAC 2)**
3. No eating, drinking, or use of tobacco products should occur in the area. [29 CFR 1910.1025 (i)(1)] **(RAC 2)**
4. Decide whether the range will be used for range activities (i.e. weapons qualification and firing) or if it would be better suited for storage and office space. The indoor firing range should not be used for both activities. [NGR 385-15, NG PAM 385-16] **(RAC 2)**
 - a. If the range is to remain active, the range cannot be used for any purpose other than firing. No equipment or furniture can be stored or maintained in the range. The range must meet all requirements of the National Guard Regulation 385-15 regarding Indoor Firing Ranges. Contact the Regional Industrial Hygiene Office regarding requirements. [NGR 385-15 1-18a, 1-17d] **(RAC 2)**
 - b. If the range is to be used as a storage area and office space, it must be thoroughly decontaminated, reevaluated, and approved prior to its use. Follow all described procedures for cleaning and decontamination of the range and all stored items found in Appendix C. **Contact the Regional Industrial Hygiene Office for approval and reevaluation prior to and after cleaning. (RAC 2)**

Non-Responsive

Industrial Hygienist

APPENDIX A

Environmental Management Solutions

REFERENCES

AR 40-5, Preventative Medicine, 15 October 1990.

AR 385-10, The Army Safety Program, 23 May 1988.

National Guard Regulation (NGR) 385-10, Army National Guard Safety and Occupational Health Program, 29 December 1989.

National Guard Regulation (NGR) 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges, 18 September 2000..

National Guard Pamphlet (NG PAM) 385-16, Guidelines for Converting Firing Ranges to Other Uses, 31 January 1994.

TB MED 503, The Army Industrial Hygiene Program, February 1985.

TB MED 502, Occupational Safety and Health Respiratory Protection Program..

Title 29 Code of Federal Regulations (CFR) 1910.1025, Lead.

Instrumentation

The industrial hygiene survey was conducted utilizing the following pieces of equipment:

Rite Aid Towelettes with Benzalkonium Chloride 1:750, 5% Denatured Alcohol
4" X 4" Template

Methodology.

- A. *Wipe Samples.* Wipe samples were taken utilizing the protocol as set forth by NG PAM 385-16, Guidelines for Converting Firing Ranges to Other Uses. Details of locations where wipe samples were taken can be found in Appendix D.

Assessment Criteria.

- A. *Wipe Samples.* Wipe sample results were compared with Ventilation rates were compared with the NG PAM 385-16, Guidelines for Converting Firing Ranges to Other Uses. See previous page for Reference information.
- B. *Risk Assessment Codes.* Risk Assessment Codes (RACs) are included in this report to quantify the risk of particular operations to employees and to establish funding priorities for corrective actions. RACs are assigned with regard to hazard severity and mishap probability. The type, length, and route of exposure are taken into consideration, as are the medical effects that would occur with such exposures. RAC criteria can be found in Appendix B.

APPENDIX B

Environmental Management Solutions

**DERIVING RISK ASSESSMENT CODES (RACs)
FOR HEALTH HAZARDS
(Ref: DOD Instruction 6055.1)**

STEP 1. Using the following procedures to assess points, determine the health hazard severity category (HHSC). The HHSC reflects the magnitude of exposure to a physical, chemical, or biological agent and the medical effects of exposure.

A. Exposure Points Assessed

		Exposure Conditions			
		<CT	Occasionally ->CT Always - <STD	>CT =STD	>STD
AER	NO	0	3	5	7
POSSIBLE?	YES	1-2	4	6	8

AER = Alternate exposure route, such as skin absorption, ingestion

CT = DoD component threshold that triggers surveillance actions, such as microWatts/cm², dB, parts per million

STD = DoD exposure limit, such as Threshold Limit Value and Permissible Exposure Limit

B. Medical Effects Points Assessed

<u>Condition</u>	<u>Points</u>
No medical effect, such as nuisance noise and nuisance odor	0
Temporary reversible illness requiring supportive treatment, such as eye irritation and sore throat	1-2
Temporary reversible illness with a variable but limited period of disability such as metal fume fever	3-4
Permanent, nonsevere illness or loss of capacity, such as permanent hearing loss	5-6
Permanent, severe, disabling, irreversible illness or death, such as asbestosis and lung cancer	7-8

C. Determine the HHSC by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>HHSC</u>
13-16	I
9-12	II
5-8	III
0-4	IV

STEP 2. Using the following guides to assess points, determine the mishap probability category (MPC) for health hazards. The probability of mishap reflects the duration of exposure and the number of exposed personnel.

A. Duration of Exposure Points Assessed

		<u>Length of Exposure</u>		
		1-8 hr/wk	>8 hr/wk continuous not continuous	
<u>Type of Exposure</u>	Irregular, intermittent	1-2	4-6	-
	Regular, periodic	2-3	5-7	8

B. Number of Exposed Personnel Points Assessed

<u>Number of Exposed Personnel</u>	<u>Points</u>
<5	1-2
5 to 9	3-4
to 49	5-6
>49	7-8

C. Determine the MPC for health hazards by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>MPC</u>
14-16	A
10-13	B
5-9	C
<5	D

STEP 3. Determine the RAC for health hazards by using the following matrix to measure health hazard severity and mishap probability factors.

		<u>MISHAP PROBABILITY</u>			
		<u>A</u>	<u>B</u>	<u>C</u>	<u>D</u>
<u>HAZARD SEVERITY</u>	<u>I</u>	1	1	2	3
	<u>II</u>	1	2	3	4
	<u>III</u>	2	3	4	5
	<u>IV</u>	3	4	5	5

APPENDIX C

Environmental Management Solutions

Decontamination and Cleaning Protocol

1. Ensure that all procedures listed below comply all federal, state, and local regulations. Consult the Regional Industrial Hygiene Office and State Environmental Office for further guidance.

2. **Ventilation System**
 - i. The range ventilation system must be in operation during all cleaning activities. If no ventilation system is available all doors and windows must be kept sealed to prevent contamination of other areas.

3. **Materials**
 - i. A High Efficiency Particulate Air (HEPA) filtered vacuum system is the preferred method of cleanup. If a HEPA vacuum cannot be obtained a wet method, detailed below, should be utilized. **A high-pressure water system or dry sweeping may not be used.**
 - ii. A cleaning solution containing detergent and water is recommended. New solutions of detergent and water should be mixed frequently.
 - iii. Two containers should be used; one for wetting the applicator (rags, sponge, mop) and the other for rinsing once the dust has been wiped from the surfaces.
 - iv. Wastewater in containers can be left to evaporate. Any waste left in the buckets and applicators should be disposed of as hazardous waste. Consult the Environmental Office for appropriate disposal instructions.
 - v. Personnel responsible for decontamination of the range and stored items should be provided with a full face air purifying respirator with a N100 filter or HEPA filter cartridge providing that all requirements for placing employees in respiratory protection have been met as detailed in 29 CFR 1910.134. Employees should be provided with protective coveralls with hood and shoe covers (i.e. Tyvek™ full body suit). Protective clothing should be hanged daily at the end of the shift and more frequently if the suit becomes grossly contaminated. If cotton coveralls are provided then the employer must provide for maintenance and laundering of protective clothing. Protective clothing should not be taken home and prior to leaving the work area, personnel should thoroughly HEPA vacuum clothing to prevent lead dust from leaving the area. Work and street clothing should not be stored together.


4. **Order of Cleaning**
 - i. A progression of cleaning from top to bottom and from behind the steel backstop to the firing line should be used. All surface areas in the range must be cleaned. Stored items must be decontaminated prior to removal.
 - ii. After removing the sand and the steel backstop, areas in front of and behind the bullet trap along with the steel backstop plates should be cleaned.
 - iii. The ceiling, lights, baffles, retrieval system, heating systems, and ventilation ducts should be cleaned.
 - iv. Acoustical material should be vacuumed instead of being painted over, A Toxic Characteristic Leaching Procedure (TCLP) may need to be used for

- acoustical material and the like to determine if the material need to be classified as hazardous and disposed of accordingly. The Environmental Office should be contacted regarding this testing.
- v. The floor should be the last surface cleaned starting at the bullet trap and ending behind the firing line. Concrete floors should be sealed with deck enamel and linoleum on tile floors should be waxed.
 - vi. All walls should be painted, preferably with a sealant, that will help prevent leaching of lead after covering.
 - vii. Following the wet cleaning of the area and after all surfaces have been allowed to dry thoroughly, a HEPA vacuum should be used on all surfaces, until no dust or residue can be seen. A through inspection to detect surface dust should be made following cleanup.
 - viii. The Regional Industrial Hygiene Office should be contacted for clearance sampling and to approve the range for converted use.
5. **Decontamination of stored items.**
- i. All stored items must be decontaminated before removing them from the range. Stored equipment next to the bullet trap and firing line should be decontaminated first.
 - ii. A HEPA vacuum or wet cleaning method should be used. Every attempt should be made to clean the item before disposing as hazardous waste to reduce cost and waste.
 - iii. Porous items such as canvas tents or other fabrics may be laundered at companies, which specialize in industrial laundry services. Office partitions and carpeting present during firing should be considered grossly contaminated and disposed of as hazardous waste. Consult the Environmental office before removing and disposing of items.
6. **Medical Surveillance.**
- i. A preplacement medical examination is required for all individuals involved with range cleanup operations.
7. **Air Monitoring.**
- i. Worker breathing zone air samples must be collected during range cleanup to ensure that workers are not overexposed and to evaluate clean up procedures.
8. **Hazard Training**
- i. A training program must be instituted for all individuals who are subject to exposure to lead at or above the action level of for whom the possibility of skin or eye irritation exists. This training should be provided for all personnel currently involved in rang cleanup operations at least annually.

APPENDIX D



Environmental Management Solutions

North Springfield Indoor Firing Range




Weight Room
behind the
firing line

Bicycles stored at
the bullet trap



Downrange

North Springfield Indoor Firing Range



Environmental Management Solutions

APPENDIX E

Environmental Management Solutions

Sample Number	Location	Micrograms/Sample	Micrograms/Square Foot	Within Allowable Limits?
NS-01	Back Wall 8' from floor	<3	<27	Y
NS-02	Back Wall 1' from floor	<3	<27	Y
NS-03	Back wall 5' from floor	<3	<27	Y
NS-04	Left Wall 2' from floor	<3	<27	Y
NS-05	Left Wall 8' from floor	<3	<27	Y
NS-06	Left Wall 6' from floor	<3	<27	Y
NS-07	Right Wall 5'	<3	<27	Y
NS-08	Right Wall 2'	<3	<27	Y
NS-09	Right Wall 8' from floor, above door	<3	<27	Y
NS-10	Bullet Stop 5'	30	270	N
NS-11	Bullet Stop 1'	800	7200	N
NS-12	Bullet Stop 8'	37	333	N
NS-13	Leftmost light fixture, first baffle	44	396	N
NS-14	Floor, 4' from left wall, under sand table	11	99	Y
NS-15	Fourth baffle, middle of room	13	117	Y
NS-16	Floor middle of room between 3 rd and 4 th baffle.	10	90	Y
NS-17	Light fixture, far right side, two feet from right wall	10	90	Y
NS-18	Floor 6" from right wall, just inside door	7.3	65.7	Y
NS-19	Top of lockers, fourth locker, right side	6.4	57.6	Y
NS-20	Drill floor, left side of door (exiting) outside	3.5	31.5	Y
NS-21	Blank	<3	<27	Y
NS-22	Blank	<3	<27	Y
NS-23	Drill floor, center	<3	<27	Y
NS-24	Far wall drill floor outside of classroom door	<3	<27	Y
NS-25	Far wall, drill floor outside of classroom door	<3	<27	Y
NS-26	Outside of and in front of second range access door	3.1	27.9	Y

NATIONAL GUARD BUREAU
ARMY NATIONAL GUARD
REGION NORTH INDUSTRIAL HYGIENE OFFICE
ATTN: NGB-AVN-SI
301-IH OLD BAY LANE
HAVRE DE GRACE, MD 21078-4094

NGB-AVN-SI (40-5f)

17 January 2001

MEMORANDUM FOR The Adjutant General, VT ARNG, ATTN: State Safety
Office (LTC **Non-Responsive**), G.M.A., Camp Johnson,
Colchester, VT 05446-3004

SUBJECT: Indoor Firing Range Survey at North Springfield Armory

1. Enclosed is the industrial hygiene survey report prepared by Environmental Management Solutions. I concur with the overall recommendations made by Ms. **Non-Responsive**
2. Please call me at 410/942-0273 ext. 17 if you have any questions or comments about this report.

Encl
Survey Report

Non-Responsive

Regional Industrial Hygienist

CF:
Unit Commander
Facility Engineer, COL **Non-Responsive**

Industrial Hygiene Survey Report

Vermont Army National Guard

Rutland Armory Indoor Firing Range

P.O. Box 788

Rutland, VT 05701

Prepared by:

National Guard Bureau

Army National Guard

Region North Industrial Hygiene Office

301-IH Old Bay Lane

Havre de Grace, MD 21078

10 August 1999

Table of Contents

I. Executive Summary	1
II. Table of Findings and Recommendations	2
III. Report	3
A. Introduction	3
B. Scope of Work	3
C. Health Effects of Lead	3
D. Methodology and Assessment Criteria	4
E. Findings and Discussion	4
F. Recommendations	6

Appendices

- A. References
- B. Health Hazard Risk Assessment Code Table
- C. IFR Diagram with Airflow Patterns

I. Executive Summary

Ms **Non-Responsive** Regional Industrial Hygienist, performed an indoor firing range (IFR) survey at the Rutland Armory on 13 January 1999. The survey was scheduled in accordance with NGR 385-15 (reference 3) which requires biennial inspections of all active indoor firing ranges. The range was recently cleaned as part of a periodic cleaning program. It had been used for firing during the weekend prior to the survey, which was the only time it was used since the cleaning was performed.

The make-up air for the range was disconnected at the time of the survey. This caused the air to be circulated around the firing line through a forced air heater hanging from the ceiling. The lack of make-up air causes the range to be unsafe for firing because lead dust is carried directly into the breathing zone of the firers. In addition, the area behind the firing line is contaminated allowing lead dust to be carried out of the range on the firers' clothes and shoes. Once the recommendations in this report are completed, the range should be reevaluated to ensure it is safe for firing. This evaluation should include ventilation measurements to check for the minimum airflow of 50 feet per minute (fpm) across the firing line and air sampling for lead during firing.

II. Table of Findings and Recommendations

Location		
Findings	Recommendations	RAC
Ventilation		
The smoke test demonstrated that the airflow in the range is not laminar and that during firing, lead dust is most likely carried back through the firers' breathing zone and behind the firing line.	Reconnect the make-up air system and ensure that the firing range is not used unless the system is functioning properly.	RAC 2
	This range should not be used for firing until the ventilation system is corrected and this office has evaluated the range.	No RAC Assigned.
The supply and exhaust ventilation systems were not interlocked.	Ensure the make-up and exhaust systems are interlocked to prevent the use of one without the other.	RAC 2
The only make-up air was coming from a hot water heater system with forced air, which was located behind the firing line on the end furthest from the door.	Remove the small forced-air heater from the range. Check with the VT Environmental Office to see if the heater must be disposed of as hazardous waste.	RAC 3
Lead Tests		
The lead test kits gave immediate and strong positive results for lead in the following areas. - on the door knob on the inside of the range door - on the plenum wall - floor outside of the range - front louver of the space heater	Completely clean the area behind the firing line, including the plenum wall, prior to reopening the range.	RAC 3
	Ensure a HEPA vacuum or wet method of cleaning is used to clean the firing line and the area behind the firing line after each day of firing.	RAC 3
Other		
The entrance door to the range is not sealed.	Install weather stripping on the entrance door to the range.	RAC 4
At the time of the survey, a broom was being stored in the range	Stop the practice of dry sweeping the range.	RAC 3
Some ceiling tiles were missing from the ceiling in the range as well as in the storage closet off of the range.	Replace the missing ceiling tiles in the range and in the storage closet off of the range.	No RAC Assigned
There was some concern about the sump-pump located in the range.	Request that the VTARNG Environmental Office evaluate the potential for release of lead dust through the sump-pump in the event of excess water in the range.	No RAC Assigned

III. Report

A. Introduction

1) Ms. **Non-Responsive** Regional Industrial Hygienist, performed an industrial hygiene survey of the IFR at the Rutland Armory on 13 January 1999. The survey was scheduled in accordance with NGR 385-15 (reference 3) which requires biennial inspections of all active indoor firing ranges.

2) Advanced Abatement Technologies, Inc (AAT) cleaned the Rutland Armory IFR in December 1998. This was a routine cleaning of all surfaces, excluding the bullet trap, which MAJ **Non-Responsive** of the VTARNG Environmental Office arranged for all IFRs in the state of Vermont. The cleaning process was scheduled as periodic cleaning and was not accomplished to convert the IFRs to any other use.

3) The firing range was used during the weekend prior to this survey. That was the first time the firing range was fired on after it was cleaned by AAT.

B. Scope of Work

Smoke candles were used in to visualize the airflow in the range. In addition, a lead test kit was used to test for any evidence of lead in the range.

C. Health Effects of Lead

Lead is a cumulative poison that collects in the blood, bones and organs of the body such as the kidneys, brain and liver. Prolonged absorption of lead can result in severe gastrointestinal disturbances and anemia, with more serious intoxication leading to neuromuscular dysfunction. Lead can remain in the bones for decades and may be introduced into other parts of the body at a later date given the right circumstances. In indoor firing ranges, lead can enter the body by inhalation (breathing) and ingestion (by not washing hands before eating, drinking, smoking, or applying make-up or lip balm). Since children are particularly susceptible to lead's toxic effects, children and pregnant females should not be allowed to enter lead-contaminated areas such as indoor firing ranges. Soldiers, especially those with small children, should be aware of the potential for lead dust to be carried home on their clothing.

D. Methodology and Assessment Criteria

1) Evaluation criteria are the most stringent of those found in NGR 385-15, Policy, Responsibilities and Procedures for Inspection/Evaluation and Use of ARNG Indoor Firing Ranges, 30 March 1990.

2) Health Hazard Risk Assessment Codes (RACs) are assigned to recommendations to help quantify risks to personnel and to aid in the establishment of funding priorities for corrective actions. RACs are determined by using the RAC Table from Department of Defense Instruction (DODI) 6055.1. The table is provided as Appendix B.

E. Findings and Discussion

1) Smoke Test and Ventilation.

a) The smoke test demonstrated that the airflow in the range is not laminar and that during firing, lead dust is most likely carried back through the firers' breathing zone and behind the firing line. This is not in accordance with the guidelines of NGR 385-15, which states that the airflow should be uniform from wall to wall and floor to ceiling moving downrange, with an average minimum airflow at the firing line of 50 feet per minute (fpm). This means that there shouldn't be turbulence in the range and that all of the air should be exhausted downrange. Unfortunately, in this range, the air seemed to circle around the firing line with none of the air being exhausted downrange. See Appendix C for a diagram of the range with airflow patterns.

b) Once this problem was identified, it was determined that the actual make-up air was disconnected because there was not any propane for the system that heats the air. The only make-up air was coming from a hot water heater system with forced air, which was located behind the firing line on the end furthest from the door. Given the lack of make-up air, this system was simply circulating the air in the range and contaminating the area behind the firing line with lead dust. The range should never be used if the make-up air system is not functioning properly, because the firers' are not protected from lead dust. Range personnel stated that the system had been operating this way for 2 or more years.

c) The exhaust air above the bullet trap was working and was connected with the downrange lighting as recommended. However, the supply and exhaust ventilation systems were obviously not interlocked as required. This is meant to prevent soldiers' from firing with only one ventilation system in use. In addition, the exhaust air should exceed the make-up air to provide a slightly negative pressure in relation to adjacent areas. This is to prevent lead dust from exiting the range and entering other areas. Since the make-up air was disconnected, we were

unable to measure the static pressure of the range to make sure it was under negative pressure.

2) Lead Tests.

a) As part of this survey, we conducted qualitative tests for lead dust using Lead Check Swabs®. Although this test does not quantify the amount of lead dust present, the speed of reaction and the darkness of the color expressed, give a good indication of the level of lead contamination. The lead test kits gave immediate and strong positive results for lead in the following areas:

- on the door knob on the inside of the range door
- on the plenum wall
- on the floor outside of the range
- on the front louver of the space heater

b) Generally we do not expect to find high levels of lead behind the firing line, if the ventilation is working correctly. I would have especially not expected to find lead in the Rutland IFR since it had been recently cleaned. However, these results indicate that the lead dust is definitely contaminating the area behind the firing line, as well as migrating outside of the range. This contamination most likely came from the weekend of firing after the range was cleaned. The strong result from the lead test is the effect of all of the lead-contaminated air being circulated behind the firing line. Once the ventilation system is operational, I suggest that the area behind the firing line be cleaned again to prevent personnel from tracking the lead dust and causing contamination of other areas of the building. A wet method would be best in this case to ensure a thorough cleaning. To prevent buildup of lead dust, a HEPA vacuum or wet method should be used to clean the firing line and the area behind the firing line after each day of firing.

3) Other.

a) The entrance door to the range is not sealed. Weather stripping on the door prevents any air from entering or exiting the range under the door. If the range becomes under positive pressure, weather stripping helps prevent lead dust from exiting the range. When the range is under negative pressure, weather stripping keeps air from entering around the door, which can disturb the airflow in the firing lane closest to the door.

b) At the time of the survey, a broom was being stored in the range. In accordance with NGR 385-15, dry sweeping of the range is not authorized. The only authorized cleaning methods are a HEPA vacuum or wet method. In addition, anything that has been stored in the range is considered to be contaminated with lead dust and must be disposed of as hazardous waste.

c) Some ceiling tiles were missing from the ceiling in the range as well as in the storage closet off of the range. These missing tiles could allow lead dust to migrate to other areas of the building and should therefore be replaced.

d) There was some concern about the sump-pump located in the range. The pump is covered with steel sheeting, which will prevent ricochets, and it seems to be fairly well sealed. However, I suggest checking with the state Environmental Office to ensure that in case of a flood or broken water pipe, the sump pump is sealed enough to prevent lead dust from flowing into a water source.

F. Recommendations

1) Reconnect the make-up air system and ensure that the firing range is not used unless the system is functioning properly. (RAC 2) [NGR 385-15, 3-2c(2)(a)]

2) Ensure the make-up and exhaust systems are interlocked to prevent the use of one without the other. (RAC 2) [NGR 385-15, (E-2b (1)(d))]

3) Remove the small forced-air heater from the range. Check with the VT Environmental Office to see if the heater must be disposed of as hazardous waste. (RAC 3)

4) Completely clean the area behind the firing line, including the plenum wall, prior to reopening the range. (RAC 3)

5) Install weather stripping on the entrance door to the range. (RAC 4) [Draft NGR 385-15 dated 23 July 1999]

6) Stop the practice of dry sweeping the range. (RAC 3) [NGR 385-15, Appendix B, paragraph 3d]

7) Replace the missing ceiling tiles in the range and in the storage closet off of the range. (No RAC Assigned)

8) Request that the VTARNG Environmental Office evaluate the potential for release of lead dust through the sump-pump in the event of excess water in the range. (No RAC Assigned)

9) Ensure a HEPA vacuum or wet method of cleaning is used to clean the firing line and the area behind the firing line after each day of firing. (RAC 3) [NGR 385-15, Appendix B, paragraph 4a]

10) This range should not be used for firing until the ventilation system is corrected and this office has evaluated the range.

APPENDIX A

REFERENCES

1. Department of Defense Instruction 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, October 1984.
2. TB MED 503, Occupational and Environmental Health, The Army Industrial Hygiene Program, February 1985.
3. NGR 385-15, Policy, Responsibilities, and Procedures for Inspection/Evaluation and Use of ARNG Indoor Firing Ranges, 30 March 1990.
4. Draft NGR 385-15, Policy, Responsibilities, and Procedures for Inspection/Evaluation and Use of ARNG Indoor Firing Ranges, 23 July 1999.
5. Occupational Safety and Health Administration (OSHA) Code of Federal Regulations (CFR), Title 29, Part 1910.1025, 1999 edition, Government Printing Office.

A

**APPENDIX B
DERIVING RISK ASSESSMENT CODES (RACs)
FOR HEALTH HAZARDS
(Ref: DOD Instruction 6055.1)**

STEP 1. Using the following procedures to assess points, determine the health hazard severity category (HHSC). The HHSC reflects the magnitude of exposure to a physical, chemical, or biological agent and the medical effects of exposure.

A. Exposure Points Assessed

		Exposure Conditions			
		<CT	Occasionally - >CT Always - <STD	>CT ≤STD	>STD
AER	NO	0	3	5	7
POSSIBLE?	YES	1-2	4	6	8

AER = Alternate exposure route, such as skin absorption, ingestion

CT = DoD component threshold that triggers surveillance actions, such as microWatts/cm², dB, \ parts per million

STD = DoD exposure limit, such as Threshold Limit Value and Permissible Exposure Limit

B. Medical Effects Points Assessed

<u>Condition</u>	<u>Points</u>
No medical effect, such as nuisance noise and nuisance odor	0
Temporary reversible illness requiring supportive treatment, such as eye irritation and sore throat	1-2
Temporary reversible illness with a variable but limited period of disability such as metal fume fever	3-4
Permanent, nonsevere illness or loss of capacity, such as permanent hearing loss	5-6
Permanent, severe, disabling, irreversible illness or death, such as asbestosis and lung cancer	7-8

C. Determine the HHSC by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>HHSC</u>
13-16	I
9-12	II
5-8	III
0-4	IV

STEP 2. Using the following guides to assess points, determine the mishap probability category (MPC) for health hazards. The probability of mishap reflects the duration of exposure and the number of exposed personnel.

A. Duration of Exposure Points Assessed

	<u>Length of Exposure</u>		
	<u>1-8 hr/wk</u>	<u>>8 hr/wk not continuous</u>	<u>continuous</u>
<u>Type of Exposure</u>	<u>Irregular, intermittent</u>	<u>1-2</u>	<u>4-6</u>
	<u>Regular, periodic</u>	<u>2-3</u>	<u>5-7</u>
			<u>8</u>

B. Number of Exposed Personnel Points Assessed

<u>Number of Exposed Personnel</u>	<u>Points</u>
<5	1-2
5 to 9	3-4
to 49	5-6
>49	7-8

C. Determine the MPC for health hazards by totaling the points assessed and using the following guide:


<u>Total Points (sum of A and B, above)</u>	<u>MPC</u>
14-16	A
10-13	B
5-9	C
<5	D

STEP 3. Determine the RAC for health hazards by using the following matrix to measure health hazard severity and mishap probability factors.

		MISHAP PROBABILITY			
		A	B	C	D
HAZARD SEVERITY	I	1	1	2	3
	II	1	2	3	4
	III	2	3	4	5
	IV	3	4	5	5

APPENDIX C

IFR DIAGRAM WITH AIRFLOW PATTERN



C

NATIONAL GUARD BUREAU
REGION NORTH INDUSTRIAL HYGIENE OFFICE
ATTN: NGB-AVN-SI
301-IH OLD BAY LANE
STATE MILITARY RESERVATION
HAVRE DE GRACE, MARYLAND 21078

NGB-AVN-SI (40-5f)

10 August 1999

MEMORANDUM FOR Commander, HHC, 2/172 Armor, ATTN: CPT [Redacted] Non-Responsive
Armory, P.O Box 788, Rutland, VT 05701

SUBJECT: Indoor Firing Range (IFR), Rutland Armory

1. Enclosed is the industrial hygiene survey report on the Rutland Armory IFR completed by this office.
2. Please contact me at (410) 942-0273 or 1-800-550-6967 if you have questions or comments about this report.

[Redacted] Non-Responsive

Encl
Survey Report

[Redacted] Industrial Hygienist

CF:
Chief of Staff, VTARNG, ATTN: COL [Redacted] Non-Responsive
State Safety Manager, VTARNG, ATTN: LTC [Redacted] Non-Responsive
Occupational Health Nurse, VTARNG, ATTN: LTC [Redacted] Non-Responsive
Environmental Protection Manager, VTARNG: ATTN: MAJ [Redacted] Non-Responsive

NATIONAL GUARD BUREAU
REGION NORTH INDUSTRIAL HYGIENE OFFICE
ATTN: NGB-AVN-SI
301-IH OLD BAY LANE
STATE MILITARY RESERVATION
HAVRE DE GRACE, MARYLAND 21078

NGB-AVN-SI (40-5f)

4 December 2000

MEMORANDUM FOR The Adjutant General, VT ARNG, G.M.A., Camp Johnson,
Colchester, VT 05446-3004

SUBJECT: Indoor Firing Range (IFR), Rutland Armory

1. Enclosed is the industrial hygiene survey report on the Rutland Armory IFR completed by this office.
2. Please contact me at (410) 942-0273 ext. 17 or 1-800-550-6967 if you have questions or comments about this report.

Non-Responsive

Encl
Survey Report

Industrial Hygienist

CF:

HQ 2/172 AR Bn, Rutland Armory, VTARNG, ATTN: 1LT **Non-Responsive**
State Safety Manager, VTARNG, ATTN: LTC **Non-Responsive**
Occupational Health Nurse, VTARNG, ATTN: LTC **Non-Responsive**
Environmental Protection Manager, VTARNG: ATTN: LTC **Non-Responsive**

Industrial Hygiene Survey Report

Vermont Army National Guard

Rutland Armory Indoor Firing Range

P.O. Box 788

15 West Street

Rutland, VT 05701

Prepared by:

National Guard Bureau

Army National Guard

Region North Industrial Hygiene Office

301-IH Old Bay Lane

Havre de Grace, MD 21078

4 December 2000

Table of Contents

I. Executive Summary	1
II. Table of Findings and Recommendations	2
III. Report	3
A. Introduction	3
B. Scope of Work	3
C. Health Effects of Lead	3
D. Methodology and Assessment Criteria	3
E. Findings and Discussion	4
F. Recommendations	5

Appendices

- A. References
- B. Health Hazard Risk Assessment Code Table
- C. IFR Diagram with Airflow Patterns
- D. Photographs

I. Executive Summary

Ms **Non-Responsive** Regional Industrial Hygienist, performed an indoor firing range (IFR) survey at the Rutland Armory on 16 October 2000. The survey was scheduled as a follow-up visit to the last survey, which was performed in January 1999.

The make-up air ventilation system is still not working properly in this range. The system did not function at all on the winter setting. On the summer setting, the system creates excessive turbulence at the firing line. One problem is that the air is circulated around the firing line through a forced air heater hanging from the ceiling. Once the recommendations in this report are completed, the range should be reevaluated to ensure it is safe for firing. This evaluation should include ventilation measurements to check for the minimum airflow of 50 feet per minute (fpm) across the firing line and air sampling for lead during firing.

II. Table of Findings and Recommendations

Findings	Recommendations	RAC
Ventilation		
The smoke test demonstrated that the airflow in the range is not laminar and that during firing, lead dust would most likely be carried back through the firers' breathing zone and behind the firing line.	Perform maintenance on the make-up air system. Ensure the system works in the summer and winter settings, and that the airflow is laminar across the firing line with a minimum average of 50 fpm in each firing lane.	RAC 2
	Ensure the make-up and exhaust air systems are interlocked to prevent the use of one without the other.	RAC 2
	Install an automatic switch on the forced air heater to ensure it does not run while the firing range is in use.	RAC 3
	This range should not be used for firing until the ventilation system is corrected and this office has evaluated the range.	No RAC Assigned.
Other		
Many items are stored in the indoor firing range.	Remove all items currently stored in the range. These items must either be cleaned or disposed of as hazardous waste.	RAC 3
The entrance door to the range is not sealed.	Install weather stripping on the entrance door to the range.	RAC 4
At the time of the survey, a broom was stored in the range	Stop the practice of dry sweeping the range.	RAC 3
	Ensure a HEPA vacuum or wet method of cleaning is used to clean the firing line and the area behind the firing line after each day of firing.	RAC 3
There was some concern about the sump-pump located in the range.	Request that the VTARNG Environmental Office evaluate the potential for release of lead dust through the sump-pump in the event of excess water in the range.	No RAC Assigned

III. Report

A. Introduction

Ms. **Non-Responsive** Regional Industrial Hygienist, performed an industrial hygiene survey of the IFR at the Rutland Armory on 16 October 2000. The survey was scheduled as a follow-up visit to the last survey, which was performed in January 1999.

B. Scope of Work

Smoke candles were used to visualize the airflow in the range. In addition, ventilation measurements were taken to approximate the airflow through the plenum wall.

C. Health Effects of Lead

Lead is a cumulative poison that collects in the blood, bones and organs of the body such as the kidneys, brain and liver. Prolonged absorption of lead can result in severe gastrointestinal disturbances and anemia, with more serious intoxication leading to neuromuscular dysfunction. Lead can remain in the bones for decades and may be introduced into other parts of the body at a later date given the right circumstances. In indoor firing ranges, lead can enter the body by inhalation (breathing) and ingestion (by not washing hands before eating, drinking, smoking, or applying make-up or lip balm). Since children are particularly susceptible to lead's toxic effects, children and pregnant females should not be allowed to enter lead-contaminated areas such as indoor firing ranges. Soldiers, especially those with small children, should be aware of the potential for lead dust to be carried home on their clothing.

D. Methodology and Assessment Criteria

1) Evaluation criteria are the most stringent of those found in All States Log Number P00-0059 – Policy and Responsibilities for Inspection, Evaluation, and Operation of ARNG Indoor Firing Ranges (IFR).

2) Health Hazard Risk Assessment Codes (RACs) are assigned to recommendations to help quantify risks to personnel and to aid in the establishment of funding priorities for corrective actions. RACs are determined by using the RAC Table from Department of Defense Instruction (DODI) 6055.1. The table is provided as Appendix B.

E. Findings and Discussion

1) Smoke Test and Ventilation.

a) The make-up air ventilation system is still not working properly in this range. On the winter setting, the system would run for approximately 60 seconds and then turn off. Maintenance personnel were not available at the time of the survey to determine if there is a problem with the temperature setting or if possibly the heating coils are not properly connected.

b) The system functioned on the summer setting. However, the smoke test demonstrated that the airflow in the range is not laminar and that during firing, lead dust would most likely be carried back through the firers' breathing zone and behind the firing line. This is not in accordance with the guidelines of All States Log Number P00-0059 – Policy and Responsibilities for Inspection, Evaluation, and Operation of ARNG Indoor Firing Ranges (IFR), which states that the airflow should be uniform from wall to wall and floor to ceiling, moving downrange, with an average minimum airflow at the firing line of 50 feet per minute (fpm). This means that there shouldn't be turbulence in the range and that all of the air should be exhausted downrange. Unfortunately, in this range, the air at the firing line is very turbulent. Average airflow measurements at the firing line were not taken since the turbulence in the range would cause these measurements to be invalid.

c) The small forced air heater located in the range, which causes much of the air to circulate around the firing line, causes part of the turbulence in the range. Although this heater cannot be removed since it is needed to keep the pipes from freezing in the winter, a switch of some kind is needed to prevent the operation of this heater during firing. Otherwise, the airflow at the firing line will always be disrupted.

d) The air exiting the plenum wall is also not laminar. At 3 ½ feet, the average airflow was 300 fpm and at 5 feet, the average was 85 fpm. This problem was discussed with Harold Aksdale of VTARNG facilities engineering who stated that the airflow was laminar when the system was tested before being accepted. It is possible that all of the fans were not working at the time of the survey. If the fans are in fact working properly, one solution would be to add louvers to the end of the ventilation duct to evenly distribute the air behind the plenum wall.

2) Other.

a) The entrance door to the range is not sealed. Weather stripping on the door prevents any air from entering or exiting the range under the door. If the range becomes under positive pressure, weather stripping helps prevent lead dust

from exiting the range. When the range is under negative pressure, weather stripping keeps air from entering around the door, which can disturb the airflow in the firing lane closest to the door.

b) At the time of the survey, a broom was stored in the range. In accordance with All States Log Number P00-0059, dry sweeping of the range is not authorized. The only authorized cleaning methods are a HEPA vacuum or wet method. In addition, anything that has been stored in the range is considered to be contaminated with lead dust and must be disposed of as hazardous waste.

c) Many items are stored in the indoor firing range (i.e. chair, cart, safety goggles, etc.) These items should be removed for two reasons. One, they interfere with the airflow in the range and two, they become contaminated with lead dust. When these items are moved in and out of the range, the lead dust is carried through other parts of the building or to wherever the items are taken. See Section C of this report for the health effects of lead.

d) There was some concern about the sump-pump located in the range. The pump is covered with steel sheeting, which will prevent ricochets, and it seems to be fairly well sealed. There is another rectangle cutout in the floor, which had several holes in the cover that we were not able to remove. I suggest checking with the state Environmental Office to ensure that in case of a flood or broken water pipe, neither of these will allow lead dust from the range to flow into a water source.

F. Recommendations

1) Perform maintenance on the make-up air system and ensure that the firing range is not used unless the system is functioning properly. Ensure the system works in the summer and winter settings, and that the airflow is laminar across the firing line. (RAC 2) [All States Log Number P00-0059, 1-17b]

2) Ensure the make-up and exhaust systems are interlocked to prevent the use of one without the other. (RAC 2) [All States Log Number P00-0059, 1-17b(1)(m)]

3) Install an automatic switch on the forced air heater to ensure it does not run while the firing range is in use. (RAC 3)

4) Stop the practice of dry sweeping the range. (RAC 3) [All States Log Number P00-0059, 1-19e]

5) Remove all items currently stored in the range. These items must either be cleaned or disposed of as hazardous waste. (RAC 3) [All States Log Number P00-0059, 1-18a and 1-19c]

6) Install weather stripping on the entrance door to the range. (RAC 4) [DG 415-1, Appendix A]

7) Request that the VTARNG Environmental Office evaluate the potential for release of lead dust through the sump-pump in the event of excess water in the range. (No RAC Assigned)

8) Ensure a HEPA vacuum or wet method of cleaning is used to clean the firing line and the area behind the firing line after each day of firing. (RAC 3) [All States Log Number P00-0059, 1-33f]

9) This range should not be used for firing until the ventilation system is corrected and this office has evaluated the range.

APPENDIX A

REFERENCES

1. Department of Defense Instruction 6055.1, Department of Defense Occupational Safety and Health (OSI) Program, October 1984.
2. TB MED 503, Occupational and Environmental Health, The Army Industrial Hygiene Program, February 1985.
3. NGR 385-15, Policy, Responsibilities, and Procedures for Inspection/Evaluation and Use of ARNG Indoor Firing Ranges, 30 March 1990.
4. All States Log Number P00-0059 – Policy and Responsibilities for Inspection, Evaluation, and Operation of ARNG Indoor Firing Ranges (IFR).
5. Occupational Safety and Health Administration (OSHA) Code of Federal Regulations (CFR), Title 29, Part 1910.1025, 1999 edition, Government Printing Office.

**APPENDIX B
DERIVING RISK ASSESSMENT CODES (RACs)
FOR HEALTH HAZARDS
(Ref: DOD Instruction 6055.1)**

STEP 1. Using the following procedures to assess points, determine the health hazard severity category (HHSC). The HHSC reflects the magnitude of exposure to a physical, chemical, or biological agent and the medical effects of exposure.

A. Exposure Points Assessed

		Exposure Conditions			
		<CT	Occasionally - >CT Always - <STD	>CT ≤STD	>STD
AER	NO	0	3	5	7
POSSIBLE?	YES	1-2	4	6	8

AER = Alternate exposure route, such as skin absorption, ingestion

CT = DoD component threshold that triggers surveillance actions, such as microWatts/cm², dB, \ parts per million

STD = DoD exposure limit, such as Threshold Limit Value and Permissible Exposure Limit

B. Medical Effects Points Assessed

<u>Condition</u>	<u>Points</u>
No medical effect, such as nuisance noise and nuisance odor	0
Temporary reversible illness requiring supportive treatment, such as eye irritation and sore throat	1-2
Temporary reversible illness with a variable but limited period of disability such as metal fume fever	3-4
Permanent, nonsevere illness or loss of capacity, such as permanent hearing loss	5-6
Permanent, severe, disabling, irreversible illness or death, such as asbestosis and lung cancer	7-8

B-1

C. Determine the HHSC by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>HHSC</u>
13-16	I
9-12	II
5-8	III
0-4	IV

STEP 2. Using the following guides to assess points, determine the mishap probability category (MPC) for health hazards. The probability of mishap reflects the duration of exposure and the number of exposed personnel.

A. Duration of Exposure Points Assessed

		<u>Length of Exposure</u>		
		<u>1-8 hr/wk</u>	<u>>8 hr/wk not continuous</u>	<u>continuous</u>
<u>Type of Exposure</u>	<u>Irrregular, intermittent</u>	1-2	4-6	-
	<u>Regular, periodic</u>	2-3	5-7	8

B. Number of Exposed Personnel Points Assessed

<u>Number of Exposed Personnel</u>	<u>Points</u>
<5	1-2
5 to 9	3-4
to 49	5-6
>49	7-8

C. Determine the MPC for health hazards by totaling the points assessed and using the following guide:


<u>Total Points (sum of A and B, above)</u>	<u>MPC</u>
14-16	A
10-13	B
5-9	C
<5	D

STEP 3. Determine the RAC for health hazards by using the following matrix to measure health hazard severity and mishap probability factors.

		MISHAP PROBABILITY			
		A	B	C	D
HAZARD SEVERITY	I	1	1	2	3
	II	1	2	3	4
	III	2	3	4	5
	IV	3	4	5	5

APPENDIX C

IFR DIAGRAM WITH AIRFLOW PATTERN



C

APPENDIX D
PHOTOGRAPHS

D-1




Figure 1. Misc items stored near plenum wall



Figure 2. Forced air heater and misc items near plenum wall




Figure 3. Rectangle cutout in floor




Figure 4. Sump pump

Roll #1 Film # 11-15 IFA Rutland, VT

16 Oct 00

Ventilation not working correctly on winter setting.
 Runs for about 60 seconds + turns off. Have
 to hit reset. (temperature setting? if it doesn't reach the
 temp it kicks off?) maybe heat coils aren't turned on.
 Works fine on summer setting.

Small forced air heater still in range.

At plenum wall, at 3 1/2 ft high, approx 300 fpm.



At 5 ft, approx 80 or 90 fpm.

Can we add louvers behind plenum wall? Or are
 all fans working?


17 Oct 00 - Spoke w/ Harold Akedale - facilities eng.
 he would like a copy of the report so he can
 respond & try to get the ventilation fixed.







BEST AVAILABLE COPY



ENVIRONMENTAL MANAGEMENT SOLUTIONS
INDUSTRIAL HYGIENE CONSULTING

Waterbury Armory
Indoor Firing Range

PO BOX 6893, DOUGLASVILLE, GEORGIA 30154
PHONE: 678.596.8509 • FAX: 770.234.6297

Table of Contents

Executive Summary.....	Page 1
Subject.....	Page 2
Background	
Introduction	
Site Description	
Scope of Work	
Health effects and hazard determination	
Findings, Discussion, and Recommendations.....	Page 3
Appendices	
A. References	
B. RAC Table	
C. Decontamination and Cleaning Protocol	
D. Photographs, Range Drawings	
E. Wipe Sampling Results	

EXECUTIVE SUMMARY

FINDINGS	RECOMMENDATIONS	RAC
<i>The Waterbury indoor firing range is listed as active, however it is currently being used as storage space.</i>	An official decision as to the status of this range should be immediately determined. If the range is to remain active, it must meet requirements set forth in NGR 385-15. If the range is to be converted, it must be adequately cleaned and decontaminated before employee use can resume.	RAC 2
<i>Five of the twenty wipe sample results were above the maximum allowable limit of 200 micrograms per square foot. It is unclear what type of protocol janitors cleaning this range used.</i>	If the range is to be converted, it must be cleaned in accordance with National Guard Regulations before employee use can resume.	RAC 2

SUBJECT: Industrial Hygiene Survey of the Waterbury Indoor Firing Range Survey performed 19 October 2000 at Waterbury Armory, VT.

BACKGROUND:

Introduction. At the request of Ms. [Non-Responsive] of the National Guard Bureau Region North Industrial Hygiene Office, an industrial hygiene survey was performed at the Waterbury Indoor Firing Range at the Waterbury Armory in Vermont. Ms. [Non-Responsive] [Non-Responsive] contract industrial hygienist, Ms. [Non-Responsive] and Mr. [Non-Responsive] Regional Industrial Hygienists, and CPT [Non-Responsive] Occupational Health Nurse, Vermont Army National Guard, conducted the survey on 19 October 2000. The purpose of the survey was to perform a comprehensive industrial hygiene survey to evaluate range characteristics, ventilation, and quantify employee exposure to lead dust.

Site Description. The Waterbury Indoor Firing Range has not officially been closed and is still listed as an active range. The ventilation system, sand trap, and baffles are all still in place. Covered food items were present in the range.

Scope of Work. The Indoor Firing Range was visually examined and personnel were consulted to accurately assess potential hazards present. The range was evaluated using the wipe sampling protocol used in the National Guard Pamphlet 385-16, which addresses Indoor Firing Range conversion to other uses. Reference information, Instrumentation, Methodology, and Assessment Criteria can be found in Appendix A.

Health Effects and Hazard Determination. The most significant hazard present to employees and users of the indoor firing range is lead dust. Shooters using ammunition with lead primers or bullets manufactured with lead are exposed to lead fumes and dust during the firing process. Furthermore, the lead found in the primer, the melting of the bullet base by hot powder gasses, the shaving and abrasion of the bullet during firing, and fragmentation of the bullet at the point of impact are all potential sources for lead. Further exposure to lead may occur during cleaning of the range, guns, or bullet trap where lead dust is deposited. Lead deposits resulting from firing activities can build up in a firing range over time and must be adequately cleaned and sealed before the range is used for other purposes. If the range is not properly cleaned, the potential for exposure to employees who use the converted area remains.

Lead affects the nervous, circulatory, digestive, excretory, and reproductive systems of both men and women. Lead can build up in the body affecting the blood, heart, and immune systems, if the amount absorbed and stored in the body exceeds the body's ability to expel it. In children, slowed cognitive development and reduced growth are results of overexposure. Pregnant women overexposed to lead are more prone to spontaneous abortions or may give birth to babies with a low birth weight and slowed postnatal neurological development.

FINDINGS, DISCUSSION, AND RECOMMENDATIONS

Five of the twenty wipe samples taken inside the range exceeded the limit of 200 micrograms per square foot. High levels were concentrated on the surfaces and lockers at or around the bullet trap, still present in the range. It is unknown, what type of protocol was used by janitors cleaning this range, and it is apparent that some lead contamination still exists. The range is still listed as active, but is being used as storage space for lockers and other equipment. If the range is to remain active, then all stored items must be removed and the range cannot be used for any other purpose than as a firing range. If the range will be officially closed and converted, the indoor firing range should be cleaned so that it is as free of lead dust as possible before the area is used for other purposes to include office space and storage. The following protocol should be used to clean the range and decontaminate items currently stored inside.

Recommendations.

1. Post signs restricting personnel from the range until it has been appropriately cleaned. (RAC 2)
2. No stored items should be handled or used until they have been thoroughly decontaminated. (RAC 2)
3. No eating, drinking, or use of tobacco products should occur in the area. [29 CFR 1910.1025 (i)(1)] (RAC 2)
4. Decide whether the range will be used for range activities (i.e. weapons qualification and firing) or if it would be better suited for storage and office space. The indoor firing range should not be used for both activities. [NGR 385-15, NG PAM 385-16] (RAC 2)
 - a. If the range is to remain active, the range cannot be used for any purpose other than firing. No equipment or furniture can be stored or maintained in the range. The range must meet all requirements of the National Guard Regulation 385-15 regarding Indoor Firing Ranges. Contact the Regional Industrial Hygiene Office regarding requirements. [NGR 385-15 1-18a, 1-17d] (RAC 2)
 - b. If the range is to be used as a storage area and office space, it must be thoroughly decontaminated, reevaluated, and approved prior to its use. Follow all described procedures for cleaning and decontamination of the range and all stored items found in Appendix C. **Contact the Regional Industrial Hygiene Office for approval and reevaluation prior to and after cleaning.** (RAC 2)

Non-Responsive

Industrial Hygienist

APPENDIX A

Environmental Management Solutions

REFERENCES

AR 40-5, Preventative Medicine, 15 October 1990.

AR 385-10, The Army Safety Program, 23 May 1988.

National Guard Regulation (NGR) 385-10, Army National Guard Safety and Occupational Health Program, 29 December 1989.

National Guard Regulation (NGR) 385-15 Policy Responsibilities, and Procedures for Inspection/Evaluation and use of ARNG Indoor Firing Ranges, 18 September 2000..

National Guard Pamphlet (NG PAM) 385-16, Guidelines for Converting Firing Ranges to Other Uses, 31 January 1994.

TB MED 503, The Army Industrial Hygiene Program, February 1985.

TB MED 502, Occupational Safety and Health Respiratory Protection Program..

Title 29 Code of Federal Regulations (CFR) 1910.1025, Lead.

Instrumentation

The industrial hygiene survey was conducted utilizing the following pieces of equipment:

Rite Aid Towelettes with Benzalkonium Chloride 1:750, 5% Denatured Alcohol
4" X 4" Template

Methodology

- A. *Wipe Samples.* Wipe samples were taken utilizing the protocol as set forth by NG PAM 385-16, Guidelines for Converting Firing Ranges to Other Uses. Details of locations where wipe samples were taken can be found in Appendix D.

Assessment Criteria

- A. *Wipe Samples.* Wipe sample results were compared with Ventilation rates were compared with the NG PAM 385-16, Guidelines for Converting Firing Ranges to Other Uses. See previous page for Reference information.
- B. *Risk Assessment Codes.* Risk Assessment Codes (RACs) are included in this report to quantify the risk of particular operations to employees and to establish funding priorities for corrective actions. RACs are assigned with regard to hazard severity and mishap probability. The type, length, and route of exposure are taken into consideration, as are the medical effects that would occur with such exposures. RAC criteria can be found in Appendix B.

APPENDIX B

Environmental Management Solutions

**DERIVING RISK ASSESSMENT CODES (RACs)
FOR HEALTH HAZARDS
(Ref: DOD Instruction 6055.1)**

STEP 1. Using the following procedures to assess points, determine the health hazard severity category (HHSC). The HHSC reflects the magnitude of exposure to a physical, chemical, or biological agent and the medical effects of exposure.

A. Exposure Points Assessed

		Exposure Conditions			
		<CT	Occasionally ->CT Always - <STD	>CT =STD	>STD
AER	NO	0	3	5	7
POSSIBLE?	YES	1-2	4	6	8

AER = Alternate exposure route, such as skin absorption, ingestion

CT = DoD component threshold that triggers surveillance actions, such as microWatts/cm², dB, parts per million

STD = DoD exposure limit, such as Threshold Limit Value and Permissible Exposure Limit

B. Medical Effects Points Assessed

<u>Condition</u>	<u>Points</u>
No medical effect, such as nuisance noise and nuisance odor	0
Temporary reversible illness requiring supportive treatment, such as eye irritation and sore throat	1-2
Temporary reversible illness with a variable but limited period of disability such as metal fume fever	3-4
Permanent, nonsevere illness or loss of capacity, such as permanent hearing loss	5-6
Permanent, severe, disabling, irreversible illness or death, such as asbestosis and lung cancer	7-8

C. Determine the HHSC by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>HHSC</u>
13-16	I
9-12	II
5-8	III
0-4	IV

STEP 2. Using the following guides to assess points, determine the mishap probability category (MPC) for health hazards. The probability of mishap reflects the duration of exposure and the number of exposed personnel.

A. Duration of Exposure Points Assessed

		<u>Length of Exposure</u>		
		1-8 hr/wk	>8 hr/wk continuous	not continuous
<u>Type of Exposure</u>	Irregular, intermittent	1-2	4-6	-
	Regular, periodic	2-3	5-7	8

B. Number of Exposed Personnel Points Assessed

<u>Number of Exposed Personnel</u>	<u>Points</u>
<5	1-2
5 to 9	3-4
10 to 49	5-6
>49	7-8

C. Determine the MPC for health hazards by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>MPC</u>
14-16	A
10-13	B
5-9	C
<5	D

STEP 3. Determine the RAC for health hazards by using the following matrix to measure health hazard severity and mishap probability factors.

		<u>MISHAP PROBABILITY</u>			
		<u>A</u>	<u>B</u>	<u>C</u>	<u>D</u>
<u>HAZARD SEVERITY</u>	<u>I</u>	1	1	2	3
	<u>II</u>	1	2	3	4
	<u>III</u>	2	3	4	5
	<u>IV</u>	3	4	5	5

APPENDIX C

Environmental Management Solutions

Decontamination and Cleaning Protocol

1. Ensure that all procedures listed below comply all federal, state, and local regulations. Consult the Regional Industrial Hygiene Office and State Environmental Office for further guidance.

2. **Ventilation System**
 - i. The range ventilation system must be in operation during all cleaning activities. If no ventilation system is available all doors and windows must be kept sealed to prevent contamination of other areas.

3. **Materials**
 - i. A High Efficiency Particulate Air (HEPA) filtered vacuum system is the preferred method of cleanup. If a HEPA vacuum cannot be obtained a wet method, detailed below, should be utilized. **A high-pressure water system or dry sweeping may not be used.**
 - ii. A cleaning solution containing detergent and water is recommended. New solutions of detergent and water should be mixed frequently.
 - iii. Two containers should be used; one for wetting the applicator (rags, sponge, mop) and the other for rinsing once the dust has been wiped from the surfaces.
 - iv. Wastewater in containers can be left to evaporate. Any waste left in the buckets and applicators should be disposed of as hazardous waste. Consult the Environmental Office for appropriate disposal instructions.
 - v. Personnel responsible for decontamination of the range and stored items should be provided with a full face air purifying respirator with a N100 filter or HEPA filter cartridge providing that all requirements for placing employees in respiratory protection have been met as detailed in 29 CFR 1910.134. Employees should be provided with protective coveralls with hood and shoe covers (i.e. Tyvek™ full body suit). Protective clothing should be hanged daily at the end of the shift and more frequently if the suit becomes grossly contaminated. If cotton coveralls are provided then the employer must provide for maintenance and laundering of protective clothing. Protective clothing should not be taken home and prior to leaving the work area, personnel should thoroughly HEPA vacuum clothing to prevent lead dust from leaving the area. Work and street clothing should not be stored together.

4. **Order of Cleaning**
 - i. A progression of cleaning from top to bottom and from behind the steel backstop to the firing line should be used. All surface areas in the range must be cleaned. Stored items must be decontaminated prior to removal.
 - ii. After removing the sand and the steel backstop, areas in front of and behind the bullet trap along with the steel backstop plates should be cleaned.
 - iii. The ceiling, lights, baffles, retrieval system, heating systems, and ventilation ducts should be cleaned.
 - iv. Acoustical material should be vacuumed instead of being painted over, A Toxic Characteristic Leaching Procedure (TCLP) may need to be used for

Environmental Management Solutions

- acoustical material and the like to determine if the material need to be classified as hazardous and disposed of accordingly. The Environmental Office should be contacted regarding this testing.
- v. The floor should be the last surface cleaned starting at the bullet trap and ending behind the firing line. Concrete floors should be sealed with deck enamel and linoleum on tile floors should be waxed.
 - vi. All walls should be painted, preferably with a sealant, that will help prevent leaching of lead after covering.
 - vii. Following the wet cleaning of the area and after all surfaces have been allowed to dry thoroughly, a HEPA vacuum should be used on all surfaces, until no dust or residue can be seen. A through inspection to detect surface dust should be made following cleanup.
 - viii. The Regional Industrial Hygiene Office should be contacted for clearance sampling and to approve the range for converted use.

5. Decontamination of stored items.

- i. All stored items must be decontaminated before removing them from the range. Stored equipment next to the bullet trap and firing line should be decontaminated first.
- ii. A HEPA vacuum or wet cleaning method should be used. Every attempt should be made to clean the item before disposing as hazardous waste to reduce cost and waste.
- iii. Porous items such as canvas tents or other fabrics may be laundered at companies, which specialize in industrial laundry services. Office partitions and carpeting present during firing should be considered grossly contaminated and disposed of as hazardous waste. Consult the Environmental office before removing and disposing of items.

6. Medical Surveillance.

- i. A preplacement medical examination is required for all individuals involved with range cleanup operations.

7. Air Monitoring.

- i. Worker breathing zone air samples must be collected during range cleanup to ensure that workers are not overexposed and to evaluate clean up procedures.

8. Hazard Training

- i. A training program must be instituted for all individuals who are subject to exposure to lead at or above the action level of for whom the possibility of skin or eye irritation exists. This training should be provided for all personnel currently involved in rang cleanup operations at least annually.

APPENDIX D

Environmental Management Solutions

Waterbury Indoor Firing Range


Downrange storage.
Note food items wrapped in plastic.



Stored items in front of the firing line.



Waterbury Indoor Firing Range



Environmental Management Solutions

APPENDIX E

Environmental Management Solutions

Sample Number	Location	Micrograms/Sample	Micrograms/ Square Foot	Within Allowable Limits?
WB-01	Left wall, 9', Left corner	<3	<27	Y
WB-02	Left wall, 2' before lockers	<3	<27	Y
WB-03	Left wall, 5', near bullet stop	<3	<27	Y
WB-04	Back wall, 9', right corner	<3	<27	Y
WB-05	Back wall, 5', middle	<3	<27	Y
WB-06	Back wall, 1', left corner	<3	<27	Y
WB-07	Right wall, 2', right corner before door	<3	<27	Y
WB-08	Right wall, 5', before lockers	<3	<27	Y
WB-09	Right wall, 8', in front of bullet trap	<3	<27	Y
WB-10	Ceiling, left corner	<3	<27	Y
WB-11	Ceiling, 2 nd baffle, middle	9.7	87.3	Y
WB-12	Ceiling, light fixture, right corner	14	126	Y
WB-13	Floor, right corner, in front of door	8.4	75.6	Y
WB-14	Floor, middle between 2 nd and 3 rd baffles	<3	<27	Y
WB-15	Floor, near bullet stop behind locker	150	1350	N
WB-16	Bullet stop, 3', right	860	7740	N
WB-17	Bullet stop, 5', middle	2000	18000	N
WB-18	Bullet stop, 8', left	190	1710	N
WB-19	Top of locker, near bullet stop in front of the 4 th baffle, right corner	180	1620	N
WB-20	Outside of door, left (exiting) 6" from wall	16	144	Y
WB-21	BLANK	<3	<27	Y
WB-22	BLANK	<3	<27	Y

Environmental Management Solutions

NATIONAL GUARD BUREAU
ARMY NATIONAL GUARD
REGION NORTH INDUSTRIAL HYGIENE OFFICE
ATTN: NGB-AVN-SI
301-IH OLD BAY LANE
HAVRE DE GRACE, MD 21078-4094

NGB-AVN-SI (40-5f)

12 January 2001

MEMORANDUM FOR The Adjutant General, VT ARNG, ATTN: State Safety
Office (LTC **Non-Responsive**, G.M.A., Camp Johnson,
Colchester, VT 05446-3004

SUBJECT: Indoor Firing Range Survey at Waterbury Armory

1. Enclosed is the industrial hygiene survey report prepared by Environmental Management Solutions. I concur with the overall recommendations made by Ms. **Non-Responsive**
2. Please call me at 410/942-0273 ext. 17 if you have any questions or comments about this report.

Non-Responsive

Encl
Survey Report

Regional Industrial Hygienist

CF:
Unit Commander
Facility Engineer, COL **Non-Responsive**

NATIONAL GUARD BUREAU
REGION NORTH INDUSTRIAL HYGIENE OFFICE
ATTN: NGB-AVN-SI
301-IH OLD BAY LANE
STATE MILITARY RESERVATION
HAVRE DE GRACE, MARYLAND 21078

NGB-AVN-SI (40-5f)

27 May 1999

MEMORANDUM FOR Commander, Company B, 2/172 AR Bn, P.O. Box 125,
Westminster, VT 05158

SUBJECT: Indoor Firing Range (IFR), Westminster Armory

1. Enclosed is the industrial hygiene survey report on the Westminster Armory IFR completed by this office. This survey was scheduled to be a complete evaluation of the range since it was my understanding at the time that the range was still being used for firing. Since this is not the case, the survey was conducted to establish the exposure potential based on the current use of the IFR.

2. Please contact me at (410) 942-0273 or 1-800-550-6967 if you have questions or comments about this report.

Non-Responsive

Encl
Survey Report

Industrial Hygienist

CF:

Chief of Staff, VTARNG, ATTN: COL **Non-Responsive**

Occupational Health Nurse, VTARNG, ATTN: LTC **Non-Responsive**

Environmental Protection Manager, VT ARNG, ATTN: MAJ **Non-Responsive**

**Industrial Hygiene Survey Report
for
Vermont Army National Guard
(VTARNG)**

**at
Westminster Armory Indoor Firing Range
P.O. Box 125
Westminster, VT 05158**

**Prepared by:
National Guard Bureau
Army National Guard
Region North Industrial Hygiene Office
301-III Old Bay Lane
Havre de Grace, MD 21078**

27 May 1999

Table of Contents

I. Executive Summary	2
II. Table of Findings and Recommendations	3
III. Report	4
A. Introduction	4
B. Scope of Work	4
C. Health Effects of Lead	4
D. Methodology and Assessment Criteria	5
E. Findings and Discussion	5
F. Recommendations	6

Appendices

- A. References
- B. Health Hazard Risk Assessment Code Table
- C. Sample Locations and Results
- D. Wipe Sample Analytical Report

I. Executive Summary

Ms. **Non-Responsive** Regional Industrial Hygienist, performed an indoor firing range (IFR) survey at the Westminster Armory on 12 January 1999. The survey was scheduled in accordance with NGR 385-15 (reference 3) which requires biennial inspections of all active indoor firing ranges. Upon arrival at the Westminster Armory, armory personnel reported that the IFR would not be used for firing since the range has not been retrofitted to meet current ventilation and building requirements. The current plan is to use the range for training and storage of various items. At that time, it was decided to evaluate the range to ensure it met the standards for conversion to other uses.

A physical inspection of the IFR showed that the conditions for conversion of the IFR to other uses had not been met based on the fact that the bullet trap and baffles had not been removed from the range. In addition, wipe sample results indicate levels of lead dust which are too high to meet the requirements for conversion of the range. The IFR does not currently meet safety and health requirements for firing or for conversion to other uses. Some type of action must be taken to ensure the firing range is used for an authorized purpose. The recommendations in the report include the steps to take if the goal is 1) to re-open the range for firing, or 2) to convert the range for other uses.

II. Table of Findings and Recommendations

Westminster Armory Indoor Firing Range P.O. Box 125 Westminster, Vermont		
Findings	Recommendations	RAC
Range Use		
This range is not being utilized in accordance with the requirements of NGR 385-15, paragraph 3-4, which states that ranges will not be used for anything other than firing.	Discontinue the practice of storing items and training soldiers in the Westminster IFR. [NGR 385-15, paragraph 3-4]	RAC 2
	For conversion of the range to other uses, such as storage, follow the guidance in NG PAM 385-16.	No RAC Assigned
None of the 9 wipe samples taken were below 200 $\mu\text{g}/\Omega^2$. The sample with the highest concentration of lead was taken on the bullet trap, which had not been cleaned.	Post a DA Form 4753, Notice of Unsafe or Unhealthy Working Condition, on the entrance to the range. [29 CFR 1919.1025(h), NG Pam 385-16, NGR 385-10 and AR 385-10]	RAC 2
Ventilation		
The ventilation system was not evaluated due to items being stored in the range. However, based on the facts that 1) there is no plenum wall to ensure laminar flow in the range and 2) there is not a sealed door between the stairs and the entrance to the range, it is fairly certain that the range would not be considered safe for firing. In order to reopen the range for firing, it would have to be retrofitted and re-evaluated based on current standards.	Do not allow firing on the Westminster IFR unless the range has been retrofitted to meet current requirements. [NGR 385-15, 3-3c and DG 415-1, Appendix A]	RAC 3
	A re-evaluation of the range to include air sampling must be accomplished prior to opening the range for firing and biennially thereafter. [NGR 385-15, Chapter 4]	No RAC assigned

III. Report

A. Introduction

1) Ms. [Non-Responsive] Regional Industrial Hygienist, performed an industrial hygiene survey of the IFR at the Westminster Armory on 12 January 1999. The survey was scheduled in accordance with NGR 385-15 (reference 3) which requires biennial inspections of all active indoor firing ranges.

2) Advanced Abatement Technologies, Inc (AAT) cleaned the Westminster Armory IFR in December 1998. This was a routine cleaning of all surfaces, excluding the bullet trap, which MAJ [Non-Responsive] of the VTARNG Environmental Office arranged for all IFRs in the state of Vermont. The cleaning process was scheduled as periodic cleaning and was not accomplished to convert the IFRs to any other use. In a memorandum from the VTARNG Environmental Office to all command and staff elements dated 13 November 1998, MAJ [Non-Responsive] makes it clear that use of firing ranges for anything other than firing is unauthorized.

B. Scope of Work

Wipe samples were taken to characterize the exposure potential to lead for personnel using the indoor firing range. In accordance with 29 CFR 1910.1025(h), "all surfaces shall be maintained as free as practicable of accumulations of lead". NG Pam 385-16 (reference 4) requires that ranges converted to other uses have lead levels less than 200 $\mu\text{g}/\text{ft}^2$.

C. Health Effects of Lead

Lead is a cumulative poison that collects in the blood, bones and organs of the body such as the kidneys, brain and liver. Prolonged absorption of lead can result in severe gastrointestinal disturbances and anemia, with more serious intoxication leading to neuromuscular dysfunction. Lead can remain in the bones for decades and may be introduced into other parts of the body at a later date given the right circumstances. In indoor firing ranges, lead can enter the body by inhalation (breathing) and ingestion (by not washing hands before eating, drinking, smoking, or applying make-up or lip balm). Since children are particularly susceptible to lead's toxic effects, children and pregnant females should not be allowed to enter lead-contaminated areas such as indoor firing ranges. Soldiers, especially those with small children, should be aware of the potential for lead dust to be carried home on their clothing.

D. Methodology and Assessment Criteria

1) Exposure standards used in this report are the most stringent of those found in NG PAM 385-16, Guidelines for Converting Indoor Firing Ranges to Other Uses.

2) Health Hazard Risk Assessment Codes (RACs) are assigned to recommendations to help quantify risks to personnel and to aid in the establishment of funding priorities for corrective actions. RACs are determined by using the RAC Table from Department of Defense Instruction (DODI) 6055.1. The table is provided as Appendix B.

E. Findings and Discussion

1) Range Use

a) This range is not being utilized in accordance with the requirements of NGR 385 -15, paragraph 3-4 which states that ranges will not be used for anything other than firing. The range is currently being used for storage of various tables and shelves as well as two armored tanks. In addition, due to severe winter weather conditions, soldiers are being trained on the tanks in the indoor firing range.

b) In accordance with NG Pam 385-16, sample results must be below 200 $\mu\text{g}/\text{ft}^2$ before the range will be approved as being properly cleaned for conversion to another use. None of the 9 wipe samples taken were below 200 $\mu\text{g}/\text{ft}^2$. The sample with the highest concentration of lead was taken on the bullet trap, which had not been cleaned. See Appendix C for wipe sample results.

c) Given the fact that the range has not been properly decontaminated for conversion to another use, the practices of storing items and training soldiers in the range is unsafe. For proper conversion, the bullet trap must be completely removed. In addition, the entire range (including the area behind the bullet trap) must be cleaned and painted with an encapsulating sealant prior to conversion. The cleaning contract with AAT did not include cleaning or removal of the bullet trap. [For more guidance on conversion of IFRs, see NG Pam 385-16 (reference 4)].

2) Ventilation

The ventilation system was not evaluated due to items being stored in the range which would interfere with proper airflow. However, based on the facts that 1) there is no plenum wall to ensure laminar flow in the

range and 2) there is not a sealed door between the stairs and the entrance to the range, it is fairly certain that the range would not meet current ventilation requirements to be considered safe for firing. In order to reopen the range for firing, it would have to be retrofitted and re-evaluated based on current standards.

F. Recommendations

1) Discontinue the practice of storing items and training soldiers in the Westminster IFR. (RAC 2) [NGR 385-15, paragraph 3-4]

2) Post a DA Form 4753, Notice of Unsafe or Unhealthy Working Condition, on the entrance to the range. (RAC 2) [29 CFR 1919.1025(h), NGR 385-10 and AR 385-10]

3) For conversion of the range to other uses, such as storage, follow the guidance in NG PAM 385-16. (No RAC Assigned)

4) Do not allow firing on the Westminster IFR unless the range has been retrofitted to meet current requirements. (RAC 3) [NGR 384-15, Chapter 43-2c]

5) A re-evaluation of the range, to include air sampling, must be accomplished prior to opening the range for firing and biennially thereafter. (No RAC assigned) [NGR 384-15, Chapter 4]

APPENDIX A

REFERENCES

1. Department of Defense Instruction 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, October 1984.
2. TB MED 503, Occupational and Environmental Health, The Army Industrial Hygiene Program, February 1985.
3. NGR 385-15, Policy, Responsibilities, and Procedures for Inspection/Evaluation and Use of ARNG Indoor Firing Ranges, 30 March 1990.
4. NG Pam (AR) 385-16/ANGPAM 91-101, Guidelines for Converting Indoor Firing Ranges to Other Uses.
5. NGB Design Guide (DG) 425-1, Design Guide for Armories, 1 June 1997.
6. HQDA LTR 385-93-1, Inspection and Evaluation of U.S. Army Indoor Firing Ranges, 26 March 1993.
7. Occupational Safety and Health Administration (OSHA) Code of Federal Regulations (CFR), Title 29, Part 1910.1025, 1998 edition, Government Printing Office.
8. National Institute of Occupational Safety and Health (NIOSH) Technical Information, December 1975, subject: Lead Exposure and Design Considerations for Indoor Firing Ranges.

**APPENDIX B
DERIVING RISK ASSESSMENT CODES (RACs)
FOR HEALTH HAZARDS
(Ref: DOD Instruction 6055.1)**

STEP 1. Using the following procedures to assess points, determine the health hazard severity category (HHSC). The HHSC reflects the magnitude of exposure to a physical, chemical, or biological agent and the medical effects of exposure.

A. Exposure Points Assessed

		Exposure Conditions			
		<CT	Occasionally - >CT Always - <STD	>CT ≤STD	>STD
AER	NO	0	3	5	7
POSSIBLE?	YES	1-2	4	6	8

AER = Alternate exposure route, such as skin absorption, ingestion

CT = DoD component threshold that triggers surveillance actions, such as microWatts/cm², dB, \ parts per million

STD = DoD exposure limit, such as Threshold Limit Value and Permissible Exposure Limit

B. Medical Effects Points Assessed

<u>Condition</u>	<u>Points</u>
No medical effect, such as nuisance noise and nuisance odor	0
Temporary reversible illness requiring supportive treatment, such as eye irritation and sore throat	1-2
Temporary reversible illness with a variable but limited period of disability such as metal fume fever	3-4
Permanent, nonsevere illness or loss of capacity, such as permanent hearing loss	5-6
Permanent, severe, disabling, irreversible illness or death, such as asbestosis and lung cancer	7-8

C. Determine the HHSC by totaling the points assessed and using the following guide:

<u>Total Points (sum of A and B, above)</u>	<u>HHSC</u>
13-16	I
9-12	II
5-8	III
0-4	IV

STEP 2. Using the following guides to assess points, determine the mishap probability category (MPC) for health hazards. The probability of mishap reflects the duration of exposure and the number of exposed personnel.

A. Duration of Exposure Points Assessed

		<u>Length of Exposure</u>		
		<u>1-8 hr/wk</u>	<u>>8 hr/wk not continuous</u>	<u>continuous</u>
<u>Type of Exposure</u>	<u>Irregular, intermittent</u>	1-2	4-6	-
	<u>Regular, periodic</u>	2-3	5-7	8

B. Number of Exposed Personnel Points Assessed

<u>Number of Exposed Personnel</u>	<u>Points</u>
<5	1-2
5 to 9	3-4
to 49	5-6
>49	7-8

C. Determine the MPC for health hazards by totaling the points assessed and using the following guide:


<u>Total Points (sum of A and B. above)</u>	<u>MPC</u>
14-16	A
10-13	B
5-9	C
<5	D

STEP 3. Determine the RAC for health hazards by using the following matrix to measure health hazard severity and mishap probability factors.

		<u>MISHAP PROBABILITY</u>			
		<u>A</u>	<u>B</u>	<u>C</u>	<u>D</u>
<u>HAZARD SEVERITY</u>	<u>I</u>	1	1	2	3
	<u>II</u>	1	2	3	4
	<u>III</u>	2	3	4	5
	<u>IV</u>	3	4	5	5

APPENDIX C

INDOOR FIRING RANGE WIPE SAMPLE LOCATIONS



WIPE SAMPLE RESULTS

SAMPLE NO.	LOCATION	Reported Results (µg/sample)	Converted Results* (µg/ft ²)
1	Front plate of bullet trap	250	2250
2	Center of bullet trap	14,000	126,000
3	3 ft up on wall opposite entrance, 2/3 downrange	52	468
4	Floor in front of the bullet trap	270	2430
5	Baffle closest to bullet trap	53	477
6	Floor near entrance to IFR	26	234
7	3 ft up on roll-up door	24	216
8	Floor on landing outside IFR	150	1350
9	Mid-way up stairs outside range	35	325

* Samples were taken of 4 in. x 4 in. (16 in²) area
 µg/sample – micrograms per wipe sample
 µg/ft² - micrograms per square foot

APPENDIX D
WIPE SAMPLE ANALYTICAL REPORT



ANALYTICAL REPORT

Form ARF-AL
 Page 1 of 2
 Part 1 of 1
 01289915464315

Date JAN 29 1999
 Laboratory Group Name 99I-0164-01
 Account No. 07003

National Guard Bureau
 Attention: **Non-Responsive**
 Attn: NGB-AVN-SI
 301-IH Old Bay Lane
 Havre de Grace, MD 21078

FAX (410) 942-0254
 Telephone (410) 942-0273

Sampling Collection and Shipment

Sampling Site VT ARNG Date of Collection January 12, 1999
 Date Samples Received at Laboratory January 26, 1999

Analysis

Method of Analysis NMAM 7082
 Date(s) of Analysis January 28, 1999

Analytical Results

Field Sample Number	Laboratory Number	Sample Type	Lead µg/sample							
01	99I00947	WIPE	250							
02	99I00948	WIPE	14000							
03	99I00949	WIPE	52.							
04	99I00950	WIPE	270							
05	99I00951	WIPE	53.							
06	99I00952	WIPE	26.							
07	99I00953	WIPE	24.							
08	99I00954	WIPE	150							
09	99I00955	WIPE	35.							
10	99I00956	WIPE	5.3							
Limit of Detection			3.							

† See comment on last page.
 ND Parameter not detected above LOD.
 NR Parameter not requested.

** See comment on last page.
 () Parameter between LOD and LOQ.

Non-Responsive

Anal [Redacted]
 Rev [Redacted]



ANALYTICAL REPORT

Form ARF-C

Page 2 of 2
01289915464315

JAN 29 1999

Date _____

Laboratory Group Name 99I-0164-01

General Set Comments

Method Reference: NIOSH Manual of Analytical Methods (NMAM), Fourth Edition,
8/15/1994.

The following samples were diluted as indicated:

5X: 99I00947.

10X: 99I00950.

100X: 99I00948.

Shaw Environmental, Inc.

312 Directors Drive
Knoxville, TN 37923
865.690.3211
Fax 865.690.3626



Shaw Environmental, Inc.

**National Guard Armory
Bennington Readiness Center – Bennington, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

19 February 2004

**National Guard Armory
Bennington Readiness Center – Bennington, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

19 February 2004

Prepared by:

Non-Responsive

Industrial Hygienist

Reviewed by:

Non-Responsive

Business Line Manager

Table of Contents

<i>Table of Contents</i>	<i>i</i>
<i>List of Tables</i>	<i>ii</i>
<i>List of Appendices</i>	<i>ii</i>
<i>Executive Summary</i>	<i>E-1</i>
<i>1.0 Introduction</i>	<i>1-1</i>
<i>2.0 Findings, Discussion, and Interpretation of Results</i>	<i>2-1</i>
<i>2.1 Sampling for Lead</i>	<i>2-1</i>
<i>2.1.1 Wipe Sampling</i>	<i>2-1</i>
<i>2.1.2 Air Sampling for Lead</i>	<i>2-2</i>
<i>2.2 Physical Condition of Facility</i>	<i>2-2</i>
<i>2.2.1 Peeling Paint - Lead</i>	<i>2-2</i>
<i>2.2.2 Visual Inspection - Asbestos</i>	<i>2-3</i>
<i>2.2.3 Visual Inspection - Water Damage and Mold</i>	<i>2-3</i>
<i>2.2.4 Visual Inspection - Housekeeping</i>	<i>2-3</i>
<i>2.3 Building Concerns</i>	<i>2-3</i>
<i>2.3.1 Ergonomic Concerns</i>	<i>2-3</i>
<i>2.3.2 Indoor Air Quality</i>	<i>2-4</i>
<i>2.4 Safety and Industrial Hygiene Programs</i>	<i>2-4</i>
<i>2.5 Ventilation</i>	<i>2-5</i>
<i>2.5.1 Ventilation System Evaluation</i>	<i>2-5</i>
<i>2.5.2 Contamination of Clean Air Sources</i>	<i>2-5</i>
<i>2.6 Noise Exposure</i>	<i>2-5</i>
<i>2.7 Lighting</i>	<i>2-5</i>
<i>2.8 Converted Indoor Firing Ranges</i>	<i>2-5</i>
<i>2.9 HVAC Systems</i>	<i>2-6</i>
<i>2.10 IHHM</i>	<i>2-6</i>
<i>3.0 Conclusions</i>	<i>3-1</i>
<i>Tables</i>	<i>Follows Section 3.0</i>
<i>Appendices</i>	<i>Follows Tables</i>

List of Tables

Table 1	Wipe Sampling for Lead
Table 2	Air Sampling for Lead
Table 3	Peeling Paint Sampling for Lead
Table 4	Indoor Air Quality Measurements
Table 5	Illumination Readings
Table 6	Indoor Firing Ranges – Wipe Sampling

List of Appendices

Appendix A	HHM Data Form
Appendix B	Building Layout
Appendix C	Sampling Sheets and Laboratory Analyses
Appendix D	References
Appendix E	Recommendations for Surface Lead Dust in Armories

Executive Summary

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Bennington Readiness Center in Bennington, Vermont. **Non-Responsive** performed the evaluation on 04 August 2003 and 10 October 2003. The point of contact at the readiness center was SFC **Non-Responsive**.

The following industrial hygiene concerns were evaluated.

- Wipe Sampling for Lead
- Air Sampling for Lead
- Peeling Paint – Lead
- Suspected Asbestos Containing Material
- Water Damage
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Indoor Air Quality
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- Lighting
- Converted Indoor Firing Range
- HVAC Systems

The following items were either not applicable to the armory or the evaluation resulted in a conclusion that there were no industrial hygiene concerns.

- Air Sampling for Lead
- Suspected Asbestos Containing Material
- Housekeeping
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources

- Noise Exposure
- HVAC Systems

Areas where there were industrial hygiene concerns are as follows:

- Wipe sampling for lead revealed a concentration above a level of 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) in the assembly hall. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.
- Peeling paint was observed in the men's shower room and second floor bathroom, and bulk sampling results revealed this paint to be a lead-based paint. Anyone who may perform repair and/or maintenance activities on these surfaces should be made aware of the presence of the lead-based paint so appropriate precautions (control of exposures, personal protective equipment, training, etc.) can be taken.
- Water damage was observed at several locations at the armory. The source of the water damage was likely from roof leaks or condensation and humidity. The source of the water should be confirmed and actions taken to eliminate the source in order to prevent the possibility of mold growth that may lead to indoor air quality problems.
- Visual mold was observed in the armory in the men's shower room and wooden floors on the first floor. The area where the mold is located should be thoroughly cleaned with 0.5% sodium hypochlorite solution (1 part household bleach to nine parts water) or equivalent in order to eliminate the potential mold/indoor air quality problem. In addition, the source of the mold should be identified and actions taken to eliminate the source.
- Interviews with employees revealed a musky odor (possibly mold) as an indoor air quality concern at the armory, specifically in the rooms on the first floor with wooden floors. The musky odor is accompanied by a discoloration (possibly mold bloom) in the wooden floors. The staff has experienced nausea and stomach problems when the odor and wood discoloration is present. A comprehensive indoor air quality investigation, with atmospheric sampling for mold, should be conducted to determine the extent of the potential mold problem.
- Interviews with employees revealed that there are ergonomic concerns at the armory. The office workstations should be further evaluated to determine if they could be modified in order to improve working conditions.
- Indoor air quality measurements revealed that the humidity and temperature at the armory exceeded the recommended levels. Since there is no HVAC system at the

armory, it is recommended that a dehumidification system be installed at the armory. In addition, a fan can be used for cooling purposes and to circulate air in the armory.

- Lighting measurements were conducted at the armory. The lighting did not meet minimum requirements in some areas; therefore consideration should be given to providing more lighting in these areas. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.
- Wipe sampling for lead in the converted firing range revealed concentrations above the recommended level at four of the locations sampled. These areas must be decontaminated by a thorough cleaning until surface lead concentrations are reduced to below recommended levels. In addition, employees should not be allowed to work in these areas without protective clothing until the areas have been cleaned and re-sampled.

1.0 Introduction

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Bennington Readiness Center in Bennington, Vermont **Non-Responsive** performed the evaluation on 04 August 2003 and 10 October 2003. The point of contact at the readiness center was SFC **Non-Responsive**

The findings, discussion, and interpretation of results are provided in Section 2.0. The conclusions are provided in Section 3.0. The HHIM data form for the facility is provided in Appendix A. The building layout is provided in Appendix B. Sampling sheets and laboratory analyses are provided in Appendix C. References are provided in Appendix D. The *Recommendations for Surface Lead Dust in Armories* document is provided in Appendix E.

The statements, opinions, and conclusions contained in this report are based solely upon the services performed by Shaw as described in the report. In performing these services and preparing the report, Shaw Environmental, Inc. relied upon the work and information provided by others, including public agencies, whose information is not guaranteed by Shaw Environmental, Inc.

2.0 Findings, Discussion, and Interpretation of Results

The results, discussion, and interpretation of results are provided in the following sections.

2.1. Sampling for Lead

2.1.1 Wipe Sampling

Wipe samples were collected for lead from the drill floor/assembly area. Also, wipe samples were collected for lead in rooms, hallways, foyers, etc. The sampling in rooms, hallways, foyers, etc. represented approximately 25% of the building. Approximately half of the samples were collected from surfaces in common areas, such as surfaces of a desk. The remaining samples were collected from uncommon surface areas, such as a supply vent or the top of a file cabinet. The samples were collected and analyzed in accordance with the Instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

The only samples initially submitted for analysis were those from the drill floor/assembly hall. If there were any positive results from the drill floor/assembly hall, the other samples would be submitted for analysis.

Results of the wipe sampling are provided in Table 1. The results revealed lead at all locations sampled at concentrations below recommended level of 200 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$).

Wipe sampling for lead revealed a concentration above a level of $40 \mu\text{g}/\text{ft}^2$ collected from the soda machine top surface in the assembly hall. Please note that the *Recommendations for Surface Lead Dust in Armories* (Appendix E) states that all areas should be cleaned that will be accessible to children. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.

2.1.2 Air Sampling for Lead

Breathing zone air sampling was conducted on one (2) full-time building occupants. (Please note that no state employees were monitored.) The samples were collected and analyzed in accordance with Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods.

The results of the sampling are provided in Table 2. The results revealed non-detectable concentrations of lead in the breathing zone of the employee and in the general area of the converted firing range; therefore, no actions are necessary.

2.2 Physical Condition of Facility

2.2.1 Peeling Paint - Lead

Peeling paint was observed at in many locations in the armory. Peeling paint was observed in the men's shower room ceiling, first floor office (office left of entrance), III/V Team Office, two bathrooms on the second floor, and the stairwell between the 1st and 2nd floor. The Department of Housing and Urban Development (HUD) defines lead-based paint as paint or other surface coatings that contain lead equal to or exceeding 0.5 percent by weight. Bulk sampling results revealed lead at concentrations exceeding 0.5 percent by weight at 2 locations. The lead concentration of the paint sample collected from the men's shower room ceiling was 19.0 percent by weight. The lead concentration of the paint sample taken from the ceiling in the second floor bathroom was 3.6 percent by weight. Both ceilings were constructed with similar material. In addition, the ceiling above the stairwell between the first and second floor and the women's bathroom on the second floor have some cracks and it appears to be the same material as the men's shower room and 2nd floor bathrooms. The results of the sampling are provided in Table 3.

Anyone who may perform repair and/or maintenance activities on surfaces coated with lead-based paint should be made aware of the presence of the lead-based paint so appropriate precautions (control of exposures, personal protective equipment, training, etc.) can be taken.

2.2.2 Visual Inspection - Asbestos

A visual inspection was made to determine if there was any suspected asbestos-containing material at the armory. Materials suspected of containing asbestos were not observed.

2.2.3 Visual Inspection – Water Damage and Mold

A visual inspection was made to determine if there was any water damage or visible mold at the armory. Water damage and mold were observed at the armory. Water damage was observed on the men's shower room ceiling, men's latrine pipes, III/V Team Office ceiling and wall, and first floor office (first office left of the entrance) wall. The source of the water damage in the men's shower room was likely from a pipe leak or humidity and condensation. A water leak in the roof above the III/V Team Office was likely the source of water damage to both the III/V Team office and the office directly below it (first office left of the entrance). The sources of the water damage should be confirmed and actions taken to eliminate the source in order to prevent the possibility of mold growth that may lead to indoor air quality problems.

Mold was observed in the men's shower room ceiling and in the wooden floors of the first floor offices (SFC Non-Responsive Office and the Administrative Office). The source of the mold in the men's shower room is likely from the humidity and condensation. The source of the mold in the wooden floors is undetermined. The area where the mold is located should be thoroughly cleaned with 0.5% sodium hypochlorite solution (1 part household bleach to nine parts water) or equivalent in order to eliminate the potential mold/indoor air quality problem. In addition, the source of the mold should be identified and actions taken to eliminate it.

2.2.4 Visual Inspection - Housekeeping

The housekeeping was determined to be good.

2.3. Building Concerns

2.3.1 Ergonomic Concerns

Interviews with employees and observation of work activities revealed that there are ergonomic concerns at the armory. The supply SGT indicated that he experienced "tingling of hands", a common symptom of a musculoskeletal disorder, and suffers from back pain, possibly due to the chair. The workstations should be further

evaluated to determine if they could be modified in order to improve working conditions.

2.3.2 Indoor Air Quality

Interviews with employees revealed a musky odor (possibly mold) as an indoor air quality concern at the armory, specifically in the rooms on the first floor with wooden floors (SFC Non-Responsive Office and the Administrative Office). The musky odor is accompanied by a discoloration (possibly mold bloom) in the wooden floors. The staff has experienced nausea and stomach problems when the odor and wood discoloration is present. A comprehensive indoor air quality investigation, with atmospheric sampling for mold, should be conducted to determine the extent of the potential mold problem.

Measurements for humidity revealed that levels exceeded the American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommended level of 60% in the armory. ASHRAE also recommends that the acceptable temperature range be 68 degrees Fahrenheit to 74 degrees Fahrenheit in the winter and 73 degrees Fahrenheit to 79 degrees Fahrenheit in the summer. The temperature on the first and second floor exceeded the acceptable range. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory. In addition, a fan can be used for cooling purposes and to circulate air in the armory.

The results of the measurements for carbon dioxide, humidity, and temperature are provided in Table 4.

2.4. Safety and Industrial Hygiene Programs

An evaluation was performed to determine the applicability of the following programs.

- Confined Spaces
- Hearing Conservation
- Respiratory Protection
- Hazard Communication (HAZCOM)
- Personal Protective Equipment (PPE)

It was determined that the HAZCOM program was the only program listed above that was applicable at the facility. The HAZCOM program was evaluated and it was determined that the program met minimum requirements.

2.5. Ventilation

2.5.1 Ventilation System Evaluation

There were no local exhaust ventilation systems at this armory; therefore, no ventilation studies were performed.

2.5.2 Contamination of Clean Air Sources

Since there were no local exhaust ventilation systems at the armory, there was no possibility that clean air sources could be contaminated by exhaust air.

2.6. Noise Exposure

An evaluation was performed to determine if there were any hazardous noise areas at the armory. It was determined that there were no areas at the armory that would exceed the permissible exposure limit for noise.

2.7 Lighting

Lighting measurements were conducted at the armory. Results of the lighting evaluation are provided in Table 5. As can be seen from the results, the lighting did not meet the minimum requirements in some areas, including the kitchen, garage/storage room, and the office opposite of SFC Non-Responsive Office.

Consideration should be given to providing more lighting to the areas listed above. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

2.8. Converted Indoor Firing Ranges

There was a converted indoor firing range at the facility; therefore, wipe samples were taken for lead at various locations in or near the converted range. The space was converted into a supply room and office. The results are provided in Table 5. The results revealed lead, with associated concentrations, at the following locations:

- floor outside the range at 240 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$);
- floor at 710 $\mu\text{g}/\text{ft}^2$;
- stored item, shelf top in the supply room area at $< 110 \mu\text{g}/\text{ft}^2$;
- overhead heaters at 1500 $\mu\text{g}/\text{ft}^2$;
- light fixture at 490 $\mu\text{g}/\text{ft}^2$; and
- stored item, desktop in the supply office area at $< 110 \mu\text{g}/\text{ft}^2$.

The lead levels at these locations were above the recommended level of 200 $\mu\text{g}/\text{ft}^2$, a level recommended in the *Guidelines for Converting Indoor Firing Ranges to Other Uses* document (Department of Army). These areas must be decontaminated by a thorough cleaning until surface lead concentrations are reduced to below recommended levels. For guidance on the proper method of cleaning, please refer to NCG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, employees should not be allowed to work in these areas without protective clothing until the areas have been cleaned and re-sampled.

2.9. HVAC System

There was not a HVAC system at the armory.

2.10. HHIM

A Health Hazard Information Module (HHIM) form was completed for the armory. The completed form is provided in Appendix A.

3.0 Conclusions

It is concluded that there were no industrial hygiene concerns at the armory with regards to atmospheric exposure to lead, suspected asbestos-containing material, housekeeping, safety and industrial hygiene programs, ventilation systems or contamination of clean air sources, noise exposure, and HVAC systems.

There were industrial hygiene concerns at the armory with regards to lead surface contamination, peeling lead-based paint, water damage, visual mold, indoor air quality, ergonomic conditions, surface lead contamination in the converted firing range, and lighting. These concerns are discussed in detail in Section 2.0 of this report.

TABLES

Table 1
Wipe Sampling for Lead
National Guard Armory
Bennington, Vermont
Dates of Sampling: 04 August 2003 and 10 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTBEN216-1	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTBEN216-2	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTBEN216-3	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTBEN216-4	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTBEN216-5	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTBEN216-6	Field Blank	< 12 μg
VTBEN284-1	Assembly Room - soda machine top surface (See Building Layout - Appendix B)	110
VTBEN284-2	Assembly Room - stereo system top surface (See Building Layout - Appendix B)	21
VTBEN284-3	Assembly Room - television top surface (See Building Layout - Appendix B)	7.6
VTBEN284-4	Assembly Room - windowsill (See Building Layout - Appendix B)	21
VTBEN284-5	Assembly Room - candy machine top surface (See Building Layout - Appendix B)	25
VTBEN284-6	Field Blank	<0.3 μg

^aMicrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of Army National Guard Armories* procedure.

In armories that do not contain childcare facilities, the NGB Region North Industrial Hygiene Office recommends cleaning the areas with lead concentrations greater than 200 $\mu\text{g}/\text{ft}^2$.

Table 2
Breathing Zone Air Samples for Lead
National Guard Armory
Bennington, Vermont
Date of Sampling: 04 August 2003

Sample Number	Employee	Sampling Information			Results (mg/m ³) ^a
		Time Sampled / Minutes	Flow Rate (lpm) ^b	Volume (liters)	
VTBEN216-A1	Non-Responsive	0814-1056/162	2.486	402.71	< 0.002
VTBEN216-A2		0812-1055/163	2.483	404.73	< 0.002
VTBEN216-A3	Field Blank	-	-	-	None Detected

^a Milligrams lead per cubic meter of air.

^b Liters of air per minute.

Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods was followed for sampling for lead.

Table 3
Peeling Paint Sampling for Lead
National Guard Armory
Bennington, Vermont
Date of Sampling: 04 August 2003

Sample Number	Location	Results, % By Weight
VTBEN216-B1	Basement-men's shower room (2)-ceilings	19.0
VTBEN216-B2	1 st floor-1 st office left of entrance-wall	0.40
VTBEN216-B3	2 nd floor-III/V Team Office-wall/ceiling	0.44
VTBEN216-B4	2 nd floor-bathroom (left of stairwell)-ceiling	3.6
VTBEN216-B5	1 st floor Non-Responsive Office-door	0.24

The Department of Housing and Urban Development (HUD) defines lead-based as paint or other surface coatings that contain lead equal to or exceeding 0.5 percent by weight.

Table 4
Indoor Air Quality Measurements for Carbon Dioxide, Humidity, and Temperature
National Guard Armory
Bennington, Vermont
Date of Sampling: 04 August 2003

Location	Occupants in Area	Carbon Dioxide, parts per million parts of air (ppm)	Percent (%) Humidity	Temperature (°F)
1 st Floor -- copier room	1	545	74.2	80.1
2 nd Floor - foyer	1	570	64.8	81.1
Basement - classroom	1	602	71.4	72.7
Outdoors	1	448	78.7	78.6

Carbon dioxide, humidity, and temperature measurements were taken with a TSI Q Trak Plus, Model 8554, Indoor Air Quality Meter, calibrated in April 2003.

American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommends that indoor carbon dioxide levels be less than 700 ppm above outdoor levels.

ASHRAE recommends that the relative humidity levels be maintained between 30 to 60 percent.

ASHRAE recommends that the acceptable temperature range be 68 degrees Fahrenheit to 74 degrees Fahrenheit in the winter and 73 degrees Fahrenheit to 79 degrees Fahrenheit in the summer.

Table 5
Illumination Readings
National Guard Armory
Bennington, Vermont
Date of Sampling: 04 August 2003

Location	Luminance (fc) ^a	Standard (fc) ^a	Standard Met
Basement-Classroom	19.4-78.7	70	Some areas
Basement-Kitchen	14.2-67.6	70	No
Basement-Maintenance Office	20.1-75.6	70	Some areas
Basement-Garage/Storage	3.9-19.3	30	No
Basement-Converted Firing Range Supply Office Area	28.5-78.3	70	Some areas
Basement-Converted Firing Range Supply Storage Area	11.2-58.4	30	Some areas
Men's Latrine	5.4-72.3	40	Some areas
1 st Floor Non-Responsive Office	40.1-74.3	70	Some areas
1 st Floor-Copier Room	19.1-75.3	70	Some areas
1 st Floor-Office (opposite Non-Responsive office)	17.1-60.1	70	No
Stairwell to 2 nd Floor	8.7-54.3	7.5	Yes
2 nd Floor-Office (above Non-Responsive office)	31.3-71.6	70	Some areas
2 nd Floor-Bathroom	34.2-64.3	40	Some areas

^a fc - Footcandles

The readings were taken with a Cooke Corporation cal-LIGHT 400 Calibrated Precision Lightmeter, calibrated on 19 Aug 2002.

The standards listed above are from ANSI/IES RP-1 and RP-7.

Table 6
Wipe Sampling for Lead – Converted Firing Range
National Guard Armory
Bennington, Vermont
Date of Sampling: 04 August 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTBEN216-7	Floor Outside the Range	240
VTBEN216-8	Floor	710
VTBEN216-9	Stored Item – shelf top	< 110
VTBEN216-10	Overhead heaters	1500
VTBEN216-11	Light Fixture	490
VTBEN216-12	Field Blank	< 12 μg
VTBEN216-13	Stored Item – desktop (office area)	< 110

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of Army National Guard Armories* procedure.

Appendix A

HHIM Data Form(s)

HEALTH HAZARD INFORMATION MODULE: INDUSTRIAL HYGIENE SURVEY

(For use of this form, see HHIM User's Guide)

SECTION 1. DEMOGRAPHIC DATA

RLOC Bennington Vermont		INSTALLATION Bennington Army Vermont ARNG		BLDG/RM NO. Bennington	
LOCATION/CODE Administrative Areas / AA			OPERATION/CODE Administrative OP/APO		
SURVEY DATE 04 August 2003			EVALUATOR (Initials) MS.		
MACOM/CODE Army National Guard		SUBMACOM/CODE XX		SUPERVISOR Non-Responsive SFC	
TELEPHONE/DSN NO. 802-447-2795		UNIT/ORGANIZATION Company C 2nd. BN 172d. Armor		RAC 4	FREQUENCY (hrs/day) 8
NO. CIV(S) 1	NO. MIL 4	NO. CONTRACTOR(S) 0	NO. LOC(S) 0	NO. OTHER 0	

SECTION 2. FACILITY DATA

FAB HOODS <input type="checkbox"/>	VAPOR DEGREASERS <input type="checkbox"/>	SPRAY BOOTHS <input type="checkbox"/>
MAINTENANCE BAYS <input type="checkbox"/>	OPEN SURFACE TANKS <input type="checkbox"/>	VENTILATION UNITS <input type="checkbox"/>

SECTION 3. SURVEY DATA

CONTROLS PRESENT	EVALUATION	UNIT CODE	CONTROLS REQUIRED	STATUS

PERSONAL PROTECTIVE EQUIPMENT (R = Required; U = Utilized)

GLOVES			RESPIRATOR			NOSH TC NO.		MANUFACTURER		R	U
ACID			AIRLINE								
COLD SURFACES			ABRASIVE BLASTING HOOD								
HOT SURFACES			DISPOSABLE								
NBC AGENTS			FULL FACE AIR PURIFYING								
OIL			1/2 FACE AIR PURIFYING								
SOLVENTS			POWERED AIR PURIFYING								
SURGICAL GLOVES			1/4 FACE AIR PURIFYING								
			SELF CONTAINED								

EYES/FACE			HEARING			BODY			HEAD/FIT		
CHEMICAL SPLASH	R	U	CANAL CAPS	R	U	APRONS	R	U	COLD WEATHER BOOTS/HATS	R	U
FULL FACE SHIELD			EAR PLUGS			COLD WEATHER CLOTHING			HARD HATS		
CHEMICAL/SAFETY			HELMETS			COVERALLS			IMPERMEABLE BOOTS		
SAFETY/IMPACT			MUFFS			FULL BODY SUIT			SAFETY/CONDUCTIVE SHOES		
WELDING HELMET			MUFF/EARPLUG COMBO			HEAT REFLECTIVE VEST/SUIT			SAFETY/NON-CONDUCTIVE SHOES		

SECTION 4. HAZARD INVENTORY DATA

CAS CODE	HAZARD DESCRIPTION	PAC	EPC
POVDTXXX	Video display terminal	3-low	Uncontrolled D Physical
7439-92-1	Lead, inorganic dusts and fumes, as Pb	2-moderate	Uncontrolled C Respiratory
POHEATSTR	Heat Stress	3-low	Uncontrolled D Physical

SECTION 5. PERSONNEL DATA

LAST NAME	FIRST NAME	MI	SEX	SSN	CATEGORY
Non-Responsive		T	M	Non-Responsive	MIL
		W			CIV

SECTION 6. COMMENTS

No comments
 Survey conducted by Michele Sewan: Building contains 4 military full-time staff and civilian custodian full-time staff performs mainly administrative functions. In addition, please note mold is a concern at the armory, specifically on the first floor and basement.
 See attached sheet

PRIVACY ACT STATEMENT

Title 5 US Code, Section 301; Executive Order 9397 authorizes the use of your Social Security Number as an identification number. The purpose of this information is to identify and monitor data relating each DA civilian and military employee exposed to a hazardous workplace or operation. The use of this information is to provide histories of exposures for any given worker.

Disclosure of your Social Security Number is not mandatory; however, nondisclosures may result in untimely provision of proper medical monitoring.

DEPARTMENT OF THE ARMY
CO C 2nd BN 172d ARMOR
National Guard Armory, 100 Franklin Lane
Bennington, Vermont 05201

4 August 2003

WPXFCO

MEMORANDUM FOR RECORD

SUBJECT: Industrial Hygiene Inspection

1. The following personnel are full time members of the Vermont National Guard workforce located at the State Armory in Bennington, Vermont:

NAME:

Non-Responsive
[Redacted]

RANK:

SSG
Custodian
SFC
MSG
SFC
SSG

2. POC for this matter is the undersigned at (802)447-2795.

FOR THE COMMANDER:

Non-Responsive
[Redacted]

SFC, VTARNG
Readiness NCO

Appendix B

Building Layout

$62.08 \times 22.08 \times 19.42 = 26,619.51 \text{ SF.}$
 $76.58 \times 62.08 \times 22.58 = 107,347.27 \text{ SF.}$
 $65.0 \times 28.0 \times 10.33 = 18,800.60 \text{ SF.}$
 $51.33 \times 0.67 \times 10.33 = 355.26 \text{ SF.}$
 $9.5 \times 4.0 \times 10.33 \times 2 = 785.08 \text{ SF.}$
 1ST FL. TOTAL = 153,907.72 SF.


$98 \frac{3}{4}$
 (98.29)

$76-7$
 (76.58)

$\frac{HT}{22.71}$
 (22.58)

$\frac{HT}{19.5}$
 (19.42)

(80.29)
 $1-2.9$



$98.29 \times 62.08 = 6101.84 \text{ SF.}$
 $65.0 \times 28.0 = 1820.00 \text{ SF.}$
 $51.33 \times 0.67 = 34.39 \text{ SF.}$
 $4.0 \times 9.5 \times 2 = 76.00 \text{ SF.}$


1ST FL. TOTAL = 8032.23 SF.

Sample date: 04 August 2002
 Sample date: 10 October 2003

SPACE CRITERIA -
1ST FLOOR PLAN
BENNINGTON ARMORY
SCALE: 1" = 20' 26/NOV/80

$65.0 \times 28.0 \times 10.0 = 18,200 \text{ CF.}$
 $51.33 \times 0.67 \times 10.0 = 343.91 \text{ CF.}$
 $9.5 \times 4.0 \times 10.0 \times 2 = 760.00 \text{ CF.}$

 2ND FL. TOTAL = 19,303.91 CF.




$65.0 \times 28.0 = 1820.00 \text{ SF.}$
 $51.33 \times 0.67 = 34.39 \text{ SF.}$
 $9.5 \times 4.0 \times 2 = 76.00 \text{ SF.}$

 2ND FL. TOTAL = 1930.39 SF.

-SPACE CENTER-
 2ND FLOOR PLAN
 BENNINGTON ARMORY
 SCALE: 1"=20' 5/DEC/80

$62.67 \times 22.375 \times 10.83 = 15,186.27 \text{ SF.}$
 $62.67 \times 75.92 \times 9.5 = 45,200.11 \text{ SF.}$
 $27.67 \times 28.58 \times 11.29 = 8,978.23 \text{ SF.}$
 $20.83 \times 6.67 \times 11.29 = 157.56 \text{ SF.}$
 $9.42 \times 4.09 \times 11.29 = 425.41 \text{ SF.}$
 $28.58 \times 37.92 \times 9.5 = 10,295.66 \text{ SF.}$
 $31.08 \times 6.67 \times 9.5 = 197.82 \text{ SF.}$
 $10.75 \times 4.00 \times 9.5 = 408.50 \text{ SF.}$



BSM'T. TOTAL = 80,799.56

$62.67 \times 98.29 = 6159.83 \text{ SF.}$
 $28.58 \times 65.58 = 1874.28 \text{ SF.}$
 $51.92 \times 6.67 = 34.79 \text{ SF.}$
 $4.0 \times 10.08 \times 2 = 80.64 \text{ SF.}$
 BSM'T. TOTAL = 8149.54 SF

- SPACE CRITERIA -
 BSM'T. FLOOR PLAN
 BENNINGTON ARMORY
 SCALE: 1" = 20' 2/DEC/80

Appendix C

Sampling Sheets and Laboratory Analyses

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
 Address: 301-1H Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTBN216
 Job Location: Not Provided
 Job Number: Not Provided
 P.O. Number: 07-01

Chain Of Custody: 115913
 Date Analyzed: 8/15/2003
 Person Submitting: [Redacted]
 Report Date: 15-Aug-03

Page 1 of 2

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0362242	VTBN216-1	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362243	VTBN216-2	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362244	VTBN216-3	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362245	VTBN216-4	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362246	VTBN216-5	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362247	VTBN216-6	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0362248	VTBN216-7	Flame	Wipe	****	0.111	108.00 ug/ft ²	240 ug/ft ²	
0362249	VTBN216-8	Flame	Wipe	****	0.111	108.00 ug/ft ²	710 ug/ft ²	
0362250	VTBN216-9	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362251	VTBN216-10	Flame	Wipe	****	0.111	108.00 ug/ft ²	1500 ug/ft ²	
0362252	VTBN216-11	Flame	Wipe	****	0.111	108.00 ug/ft ²	490 ug/ft ²	
0362253	VTBN216-12	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0362254	VTBN216-13	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

An AIHA (#8863), NVLAP (# 101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

CERTIFICATE OF ANALYSIS

Chain Of Custody: 115913
Date Analyzed: 8/15/2003
Person Submitting: [REDACTED]
Report Date: 15-Aug-03

Job Name: VTBEN216
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01

Client: National Guard Bureau
Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SI,
State Military Reservation
Havre de Grace, Maryland 21078

Page 2 of 2

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B
N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per billion (ppb)
%Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)
Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [REDACTED] Technical Manager: [REDACTED]

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

An AIHA (#8863), NVLAP (# 101143), & New York ELAP (#10920) Accredited Laboratory

4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

Client: National Guard Bureau
Address: 301-1H Old Bay Lane, Attn: NGB-AVN-SI,
 State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTBEN284
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 0701

Chain Of Custody: 118722
Date Analyzed: 10/21/2003

Person Submitting: [Redacted]
Report Date: 21-Oct-03

Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0402941	VTBEN284 -1	Furnace	Wipe	****	0.111	27.00 ug/ft ²	1.10 ug/ft ²	
0402942	VTBEN284 -2	Furnace	Wipe	****	0.111	2.70 ug/ft ²	21 ug/ft ²	
0402943	VTBEN284 -3	Furnace	Wipe	****	0.111	2.70 ug/ft ²	7.6 ug/ft ²	
0402944	VTBEN284 -4	Furnace	Wipe	****	0.111	2.70 ug/ft ²	21 ug/ft ²	
0402945	VTBEN284 -5	Furnace	Wipe	****	0.111	2.70 ug/ft ²	25 ug/ft ²	
0402946	VTBEN284 -6	Furnace	Wipe Blank	****	N/A	0.30 ug	<	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)

%Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Non-Responsive

Non-Responsive

Technical Manager:

Analyst:

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

All rights reserved. AMA Analytical Services, Inc.



Submitted To: **Non-Responsive**
Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTBEN216-B1 through VTRUT217-B6
P.O. No.:	Not Available
Sample Location:	VT
Sample Type:	Paint Chip
Method Reference:	3050B/6010B
DCL Set ID No.:	03-S-3834
DCL Sample ID No.:	03-23432 through 03-23448
Sample Receipt Date:	8/8/2003
Preparation Date:	8/8/2003
Analysis Date:	8/12/2003

The samples were prepared in accordance with EPA method 3050B. Sample condition was acceptable upon receipt except where noted. The samples were then analyzed in accordance with EPA method 6010B using a Jarrell Ash Trace ICP.

The results are provided in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive

Non-Responsive
Analyst

Non-Responsive

Reviewer

CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 260-8071, FAX 415 893-0469

Results Lead

Client #	DCL #	mg/Kg (ppm)	% by weight
VTBEN216-B1	03-23432	190000.	19.
VTBEN216-B2	03-23433	4000.	0.40
VTBEN216-B3	03-23434	4400.	0.44
VTBEN216-B4	03-23435	36000.	3.6
VTBEN216-B5	03-23436	2400.	0.24
VTWES216-B1	03-23439	35.	0.0035
VTRUT217-B1	03-23443	1600.	0.16
VTRUT217-B2	03-23444	440.	0.044
VTRUT217-B3	03-23445	5800.	0.58
VTRUT217-B4	03-23446	97000.	9.7
VTRUT217-B5	03-23447	53000.	5.3
VTRUT217-B6	03-23448	8700.	0.87
	Prep Blank	ND	
% Recovery	LCS	93.	
% Recovery	23303MS	98.	
% Recovery	23303MSD	96.	
RPL		25.	0.0025

ND = not detected at or above the reporting limit (RPL).

LCS = laboratory control sample.

MS/MSD = matrix spike/matrix spike duplicate.

Non-Responsive

Analyst

Non-Responsive

Reviewer



Submitted To: **Non-Responsive**
Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTBEN216-A1 through VTRUT217-A3
P.O. No.:	Not Available
Sample Location:	VT
Sample Type:	Filter
Method Reference:	NIOSH 7300
DCL Set ID No.:	03-S-3834
DCL Sample ID No.:	03-23429 through 03-23442
Sample Receipt Date:	8/8/2003
Preparation Date:	08/11/03
Analysis Date:	08/11/03

The samples were prepared and analyzed in accordance with NIOSH method 7300 using a Perkin Elmer 3000XL ICP.

The sample condition upon receipt was acceptable except where noted.

The results are in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive

Analyst

Non-Responsive

Reviewer

CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 280-8071, FAX 415 893-9469

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTBEN216-A1	03-23429	402.71	ND	<0.002
VTBEN216-A2	03-23430	404.73	ND	<0.002
VTBEN216-A3	03-23431	0	ND	-
VTWES216-A1	03-23437	294.35	ND	<0.003
VTWES216-A2	03-23438	0	ND	-
VTRUT217-A1	03-23440	420.05	ND	<0.002
VTRUT217-A2	03-23441	412.99	ND	<0.002
VTRUT217-A3	03-23442	0	ND	-
	Prep Blank		ND	
% Recovery	LCS		100.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).
LCS = laboratory control sample.

Non-Responsive



Analyst

Non-Responsive



Reviewer

Industrial Hygiene Sampling Calculation Worksheet

National Guard Armory Location: BEN
Date: 8/4/2002

Sample 1

Sample Number: VTBEN216-A1

Pump: 647615

	Pre Flow Rate	Post Flow Rate
	2.525	2.444
	2.523	2.456
	2.515	2.458
	2.506	2.46
Average	2.517	2.455

Average Pre and Post 2.4859

Time 1 8:14

Time 2 10:56

Total Time Sampled 2:42

Minutes Sampled 162.00

Volume 402.71 Liters

Sample 2

Sample Number: VTBEN216-A2

Pump: 648339

	Pre Flow Rate	Post Flow Rate
	2.517	2.436
	2.512	2.457
	2.518	2.446
	2.522	2.456
Average	2.517	2.449

Average Pre and Post 2.4830

Time 1 8:12

Time 2 10:55

Total Time Sampled 2:43

Minutes Sampled 163.00

Volume 404.73 Liters

Appendix D

References

References

- Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration (current edition)
- American Society of Heating, Refrigerating and Air-Conditioning Engineers, Inc (ASHRAE) 62-2002, Ventilation for Acceptable Indoor Air Quality
- Instructions for Completing the Sampling of Army National Guard Armories, Lead Wipe Sampling Procedure included with the Request for Proposal
- Air Sampling for Lead - Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods
- Design Guide DG-415-2, Logistics Facilities, National Guard Bureau Installation Division, 14 December 1999
- Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998
- Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, 15 October 1990
- AR 385-10, The Army Safety Program, 29 February 2000
- Department of the Army Pamphlet (DA PAM) 40-501, Medical Services, Hearing Conservation Program, 10 December 1998
- DA PAM 40-503, Medical Services, Industrial Hygiene Program, 30 October 2000
- Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH) (current edition)
- Guidelines for Converting Indoor Firing Ranges to Other Uses, Headquarters, Department of the Army and the Air Force, NG PAM (AR) 385-16/ANGPAM 91-101, 31 January 1994
- 24 CFR, Part 35, Subpart B, Section 35-110, Definition of Lead-Based Paint, Housing and Urban Development, U. S. Department of Housing

Appendix E
Recommendations for
Surface Lead Dust in Armories

Subject: Recommendations for Surface Lead Dust in Armories

1. In armories that do not contain childcare facilities, the National Guard Bureau (NGB) Region North Industrial Hygiene Office recommends cleaning the areas in which sample results are greater than 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$). If a special function will be held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function. This guidance is based on professional judgment, risk assessments, adaptation of Occupational Safety and Health Administration (OSHA) guidance, and feasibility of cleaning to a certain level.

a. Environmental Protection Agency (EPA) standards (40 Code of Federal Regulations (CFR) 745.227(b)(3)) are not directly applicable because they are criteria for dust-lead hazards developed for floors ($40 \mu\text{g}/\text{ft}^2$) and windowsills ($250 \mu\text{g}/\text{ft}^2$) in residential dwellings and child occupied facilities. A child occupied facility is defined as a building, or portion of a building, constructed prior to 1978, visited regularly by the same child, 6 years of age or under, on at least two different days within any week (Sunday through Saturday period), provided that each day's visit lasts at least 3 hours and the combined weekly visit lasts at least 6 hours, and the combined annual visits last at least 60 hours. Most of the wipe samples in armories were collected in undisturbed areas and therefore, results are worst case scenarios and do not correlate to these standards.

b. OSHA has no specific requirement for work area surfaces. The lead standard (29 CFR 1910.1025(h)) states that all surfaces shall be maintained as free as practicable of accumulations of lead dust. In workplaces where lead dust is generated, surface levels may be much higher, but personnel exposures can be controlled by limiting airborne lead levels and following good cleanup and hygienic practices.

c. OSHA used to cite a level of $200 \mu\text{g}/\text{ft}^2$ in their Technical Manual and 29 CFR 1926.62 as guidance to its own inspectors for evaluating the cleanliness of lunchroom and locker room surfaces that are supposed to be kept as clean as possible.

d. In a report titled Derivation of Wipe Surface Screening Levels for Environmental Chemicals, the US Army Center for Health Promotion and Preventive Medicine (USACUHPM) has determined that $200 \mu\text{g}/\text{ft}^2$ is a safe surface contamination level. They have also applied these standards as the decontamination levels for surfaces in administrative offices.

e. It should be noted that levels above these recommendations do not necessarily mean there is a significant hazard to workers who are following good cleaning and hygienic practices since there is no correlation between wipe and air samples. Rather, we recommend these levels as a precautionary measure.

2. The NGB Occupational Health Branch is developing guidance for armories that are used as childcare facilities. All states will receive this guidance when it is completed. In the interim, we recommend the following actions:

- a. Clean all areas that will be accessible to children to the EPA dust-lead standard for children 6 years of age or under ($40 \mu\text{g}/\text{ft}^2$ on floors and $250 \mu\text{g}/\text{ft}^2$ on windowsills).
 - b. Refer to the local authorities' regulations since they can be more stringent than federal regulations.
 - c. Post signs in the area to inform people of the presence of lead dust and its effects.
 - d. If soldiers clean weapons in the facility change the policy so that they cannot clean their weapons in the facility, or if they are allowed to clean their weapons indoors, they must clean the area by wet wiping and mopping the area when they are done.
 - e. If the paint is peeling, contact the state Environmental Office to test for lead content and provide recommendations.
3. Air samples collected on individuals in the armory were well below OSHA's permissible exposure limit for lead (29 CFR 1910.1025(e)) of $0.05 \text{ mg}/\text{m}^3$ averaged over an 8-hour day. Therefore, based on these conditions there is currently no overexposure to personnel from lead dust in this building.

Industrial Hygiene Survey

Vermont Army National Guard (VT ARNG)

Prepared For: NGB ARNG– Region North IH Office

Survey Location:

Bennington Readiness Center
100 Franklin Lane
Bennington, VT 05201

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 25, 2011

AEI Project #: 12685 4L VT Bennington RC

Non-Responsive
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Bennington Readiness Center**

Table of Contents

Executive Summary ii

1 Introduction 1

2 Evaluation Methods 1

3 Operations 1

4 Noise Hazards 1

5 Hazard Controls 1

Ventilation Systems 1

6 Physical Condition of the Facility and Personnel Concerns 2

Paint Chip and Dust Wipe Samples for Lead Contamination 2

Visual Inspection for Damaged Asbestos-Containing Materials 3

Visual Inspection for Water Damage and Mold Growth 3

Visual Inspection for Housekeeping Concerns 3

Lighting 3

Indoor Air Quality (IAQ) 4

Temperature and Relative Humidity 4

Carbon Dioxide (CO₂) and Carbon Monoxide (CO) 4

7 Conclusions 5

8 Limitations 5

List of Tables and Appendices

Table 1 - Results of Dust Wipe Sampling for the VT ARNG Bennington Readiness Center on October 25, 2012.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

Appendix A – Building Layout

Appendix B – Certificates of Analysis for Air, Dust Wipe and Bulk Samples

Appendix C – Photo Documentation

Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Bennington Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Bennington Readiness Center located at 100 Franklin Lane, Bennington VT 05201. **Non-Responsive** performed the evaluation on October 24, 2011. The point of contact for the facility was **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Paint Chip and Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed in men's bathroom and shower located in the basement of the facility. A sample of the peeling paint was found to contain 0.19% lead by weight. The shower and bathroom paint chip sample would not be considered lead-based by the Environmental Protection Agency (EPA) and State of Vermont definitions (>0.5% by weight). Results of dust wipe samples collected from the former firing range and one sample from the window sill in the Drill Hall were above the recommended maximum levels for adult exposures with results ranging from 520 to 2500 µg/ft². All additional wipe samples collected from the facility were below the recommended maximum levels for adult exposures.

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there were any suspect asbestos-containing material and its condition. No damaged suspect asbestos-containing materials were observed.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or evidence of mold growth was observed on the day of the inspection. However, staff at the facility indicated that a crack in the foundation in the Supply Room does lead to water intrusion during times of wet weather.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping was good.

Lighting: A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in the Drill Hall and Stage/Weight Room. The illumination measurements indoors ranged from 17.7 foot candles (fc) to 148 fc.

Indoor Air Quality: Temperature and relative humidity measurements were mostly within the comfort ranges for the winter season on the day of the survey. The outdoor temperature and relative humidity were 610.9° F and 44.1% on the day of monitoring. Indoor concentrations of carbon dioxide (CO₂) and carbon monoxide (CO) were below the guidelines in all areas.

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updated MSDSs are required per OSHA 29 CFR 1910.1200. It is recommended that a copy of the written hazard communication program

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Bennington Readiness Center**

be placed in every MSDS notebook. MSDSs for some new custodial products are required per OSHA 29 CFR 1910.1200.

Overall, the Bennington Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Bennington Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Bennington Readiness Center located at 100 Franklin Lane, Bennington VT 05201. Non-Responsive performed the evaluation on October 25, 2011. The point of contact for the facility was Non-Responsive. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

The Bennington Readiness Center was built in 1926. The readiness center is staffed by 8 administrative personnel. The operations conducted at the facility include supply and administrative duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the Bennington Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) evaluations of operations including operation description, sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the Bennington facility consist exclusively of supply and administrative duties. No other maintenance of vehicles or other physical tasks are performed at the facility. A small garage exists in the facility basement but it is only used for storage.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Bennington Readiness Center**

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were collected in select areas.

Paint Chip and Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed in men's bathroom and shower located in the basement of the facility. A paint chip samples were submitted to AMA Analytical Services, Inc. of Lanham, MD for lead analysis. The samples were found to contain 0.19% lead by weight. The shower and bathroom paint chip sample would not be considered lead-based by the Environmental Protection Agency (EPA) and State of Vermont definitions (>0.5% by weight). Certificates of analysis are included in Appendix B

To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected using ghost wipes and 10 centimeter (cm) x 10cm templets. The Environmental Protection Agency (EPA) and the State of Vermont limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. Several wipe samples collected from the former firing range and one sample from the window sill in the Drill Hall were above the recommended maximum levels for adult exposures with results ranging from 520 to 2500 $\mu\text{g}/\text{ft}^2$. All additional wipe samples collected from the facility were below the recommended maximum levels for adult exposures. Results are given in Table 1 and certificates of analysis are included in Appendix B.

**Table 1 –Dust Wipe Sampling Data Sheet for VT ARNG
Bennington Readiness Center on October 25, 2012.**

Wipe Sample #	Wipe Sample Location	Lead Result ($\mu\text{g}/\text{ft}^2$)
BEN-01	Supply Room/ Former Indoor Firing Range, Former bullet trap	<110
BEN-02	Supply Room/ Former Indoor Firing Range, Light fixture	590
BEN-03	Supply Room/ Former Indoor Firing Range, Overhead Heater	520
BEN-04	Supply Room/ Former Indoor Firing Range, Stored totes	<110
BEN-05	Supply Room/ Former Indoor Firing Range, Floor	2,500
BEN-06	Supply Room/ Former Indoor Firing Range, Floor immediately outside	530
BEN-07	Supply Office, Work station	<110

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Bennington Readiness Center**

**Table 1 –Dust Wipe Sampling Data Sheet for VT ARNG
Bennington Readiness Center on October 25, 2012.**

Wipe Sample #	Wipe Sample Location	Lead Result ($\mu\text{g}/\text{ft}^2$)
BEN-08	Kitchen, Counter	<110
BEN-09	Drill Hall, Table	<110
BEN-10	Drill Hall, Middle of floor	<110
BEN-11	Drill Hall, Window sill	580
BEN-12	Room 12, Supply vent	<110
BEN-13	Stage, Middle of stage	<110
BEN-14	Room 14, Top of cabinet	<110
BEN-15	Room 23, Middle of Entry floor	<110
BEN-16	Break Room, Table	<110
BEN-17	Room 19, Window Sill	<110

*The recommended maximum level for adult exposures is 200 $\mu\text{g}/\text{ft}^2$ lead on surfaces.

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). No damaged suspect asbestos-containing materials were observed.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or evidence of mold growth was observed on the day of the inspection. However, staff at the facility indicated that a crack in the foundation in the Supply Room does lead to water intrusion during times of wet weather.

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping was good. Most areas were clean and tidy.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on April 16, 2012, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in a few areas. The illumination measurements indoors ranged from 17.7 foot candles (fc) to 148 fc. The complete results of the evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Bennington Readiness Center**

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Model 7575x, factory calibrated in July, 2012. Temperature, relative humidity and carbon dioxide (CO₂) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 2. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30 and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 62.8 to 73.3° F and 39.9 to 62.0% Rh. Temperatures and relative humidity were mostly within the winter comfort ranges in the areas monitored. The outdoor temperature and relative humidity was 61.9° F and 44.1% on the day of monitoring.

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1–2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 458 to 851 parts per million (ppm). Outdoor CO₂ levels were 492 ppm. CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange.

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 0.5 to 1.1 ppm; therefore, concentrations are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Bennington Readiness Center**

Additional Information

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updated MSDSs are required per OSHA 29 CFR 1910.1200. It is recommended that a copy of the written hazard communication program be placed in every MSDS notebook. MSDSs for some new custodial products are required per OSHA 29 CFR 1910.1200.

7 Conclusions

The results of the evaluation indicated no concerns with the following at the facility: contamination of clean air sources, the presence of damaged suspect asbestos-containing materials, water intrusion, peeling lead-based paint, noise hazards, visible mold and housekeeping. The results of the evaluation indicated industrial hygiene concerns in the following areas: accumulated lead-containing dust, the hazard communication program and lighting. Overall, the Bennington Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.


9 References

1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.
3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Bennington Readiness Center**


4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.
5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2011.
6. Army Regulation (AR) 420-70 Buildings and Structures, 11 November 1997.
7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 13 December 2007.
8. Army Regulation (AR) 420-1 Army Facilities Management, 12 February 2008, RAR 24 August 2012.
9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.
10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.
12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.
13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".
15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.

Appendix A Building Layout




2ND FLOOR PLAN
BENNINGTON ARMORY
SCALE: 1" = 20' 5/DEC./80

EMERGENCY EVACUATION



1st FLOOR PLAN
BENNINGTON ARMORY
SCALE: 1" = 20' E/DEC./80

EMERGENCY EVACUATION



BSMT. FLOOR PLAN
BENNINGTON ARMORY
SCALE: 1" = 20' 2/DEC/83

EMERGENCY EVACUATION

Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	Bennington RC	Chain Of Custody:	514392
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Bennington, VT	Date Submitted:	11/2/2012
Attention:	Non-Responsive	Job Number:	12685	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/7/2012
				Report Date:	11/9/2012

Summary of Atomic Absorption Analysis for Lead

Page 1 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
13011040	BEN-1	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13011041	BEN-2	Flame	Wipe	****	0.108	110 ug/ft ²	64	590 ug/ft ²	
13011042	BEN-3	Flame	Wipe	****	0.108	110 ug/ft ²	56	520 ug/ft ²	
13011043	BEN-4	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13011044	BEN-5	Flame	Wipe	****	0.108	110 ug/ft ²	270	2500 ug/ft ²	
13011045	BEN-6	Flame	Wipe	****	0.108	110 ug/ft ²	57	530 ug/ft ²	
13011046	BEN-7	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13011047	BEN-8	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13011048	BEN-9	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13011049	BEN-10	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13011050	BEN-11	Flame	Wipe	****	0.108	110 ug/ft ²	63	580 ug/ft ²	
13011051	BEN-12	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13011052	BEN-13	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13011053	BEN-14	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13011054	BEN-15	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13011055	BEN-16	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13011056	BEN-17	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13011057	BEN-18	Flame	Paint Chip	****	N/A	0.0086 %Pb		0.19 %Pb	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	Bennington RC	Chain Of Custody:	514392
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Bennington, VT	Date Submitted:	11/2/2012
Attention:	Non-Responsive	Job Number:	12685	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/7/2012
				Report Date:	11/9/2012

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	----------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm)
 %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb)

See QC Summary for analytical results of quality control samples associated with these samples.

Note: All samples were received in good condition unless otherwise noted.

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Air and Wipe results are not corrected for any blank results

Final results for air and wipe samples are based on client supplied information nor verified by this laboratory.

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Analyst: **Non-Responsive**

Technical Manager: **Non-Responsive**

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



AMA Analytical Services, Inc.

Focused on Results www.amalab.com
ΔIHA (#100470) NVLAP (#101143-0) NY ELAP (10920)
4475 Forbes Blvd. • Lanham, MD 20706
(301) 459-2640 • (800) 346-0961 • Fax (301) 459-2643

BEST AVAILABLE COPY

CHAIN OF CUSTODY

(Please Refer To This Number For Inquires)

514392

Mailing/Billing Information:

- Client Name: National Guard Bureau
- Address 1: 301-IH Old Bay Lane
- Address 2: Attn: NGB-AVN-SI, State Military Reservation
- Address 3: Havre de Grace, Maryland 21078
- Phone #: (410) 942-0273 Fax #: (410) 942-0254

Submittal Information:

- Job Name: BENNINGTON RC
- Job Location: BENNINGTON, VT
- Job #: 12155 P.O. #: W912K6-09-A-0003
- Contact Person: **Non-Responsive**
- Submitted by: **Non-Responsive**

Reporting Info (Results provided as soon as technically feasible). If no TAT/Reporting Info is provided, AMA will assign defaults of 5-Day and email/fax to contacts on file.

AFTER HOURS (must be pre-scheduled) <input type="checkbox"/> Immediate Date Due: _____ <input type="checkbox"/> 24 Hours Time Due: _____ Comments: _____		NORMAL BUSINESS HOURS <input type="checkbox"/> Immediate <input type="checkbox"/> 3 Day <input type="checkbox"/> Results Required By Noon <input type="checkbox"/> Next Day <input checked="" type="checkbox"/> 5 Day + <input type="checkbox"/> 2 Day Date Due: <u>11/9/12</u>		REPORT TO: <input checked="" type="checkbox"/> Include Non-Responsive with Report <input checked="" type="checkbox"/> Email: <u>@ariaenviro.com</u> <input type="checkbox"/> Fax: <u>@us.army.mil</u> <input type="checkbox"/> Verbal: <u>@us.army.mil</u>	
--	--	---	--	--	--

Asbestos Analysis

- *PCM Air - Please Indicate Filter Type:
 NIOSH 7400 (QTY)
 Fiberglass (QTY)
- TEM Air* - Please Indicate Filter Type:
 AHERA (QTY)
 NIOSH 7402 (QTY)
 Other (specify _____) (QTY)
- PLM Bulk
 EPA 600 - Visual Estimate (QTY)
 EPA Point Count (QTY)
 NY State Friable 198.1 (QTY)
 Grav. Reduction ELAP 198.6 (QTY)
 Other (specify _____) (QTY)

TEM Bulk

-
- ELAP 198.4/Chatfield (QTY)
-
-
- NY State PLM/TEM (QTY)
-
-
- Residual Ash (QTY)

TEM Dust*

-
- Qual. (pres/abs) Vacuum/Dust (QTY)
-
-
- Quan. (s/area) Vacuum D5755-95 (QTY)
-
-
- Quan. (s/area) Dust D6480-99 (QTY)

TEM Water

-
- Qual. (pres/abs) (QTY)
-
-
- ELAP 198.2/EPA 100.2 (QTY)
-
-
- EPA 100.1 (QTY)

All samples received in good condition unless otherwise noted.
(TEM Water samples _____°C)

Metals Analysis

-
- Pb Paint Chip
- 1
- (QTY)
-
-
- Pb Dust Wipe (wipe type
- etc ST
-)
- 17
- (QTY)
-
-
- Pb Air (QTY)
-
-
- Pb Soil/Solid (QTY)
-
-
- Pb TCLP (QTY)
-
-
- Drinking Water
-
- Pb (QTY)
-
- Cu (QTY)
-
- As (QTY)
-
-
- Waste Water
-
- Pb (QTY)
-
- Cu (QTY)
-
- As (QTY)
-
-
- Pb Furnace (Media _____) (QTY)

Fungal Analysis

- Collection Apparatus for Spore Traps/Air Samples: _____
 Collection Media _____
-
- *Spore-Trap (QTY)
-
- Surface Vacuum Dust (QTY)
-
-
- *Surface Swab (QTY)
-
- Culturable ID Genus (Media _____) (QTY)
-
-
- *Surface Tape (QTY)
-
- Culturable ID Species (Media _____) (QTY)
-
-
- Other (Specify _____) (QTY)

MISC

-
- Vermiculite
-
-
- Asbestos Soil PLM (Qual) PLM (Quan) PLM/TEM (Qual) PLM/TEM (Quan)
-
- *It is recommended that blank samples be submitted with all air and surface samples. If field data sheets are submitted, there is no need to complete bottom section.

CLIENT ID #	SAMPLE INFORMATION SAMPLE LOCATION/ID	DATE/ TIME	VOL (L)/ Wipe Area	ANALYSIS										CLIENT CONTACT (LABORATORY STAFF ONLY)					
				TEM	PCM	PLM	LEAD	MOLD	AIR	BULK	DUST	MATRIX WATER AND OTHER	SPORE TRAP	TAPE	SWAB	Date/Time:	Contact:	By:	
	SEE ATTACHED FIELD DATA SHEETS																		

LABORATORY STAFF ONLY:
(CUSTODY)
Posted to NGB FOIA Reading Room
May, 2018

- Date/Time RCVD: 11/2/12 @ TedEx Via: TedEx By (Print): **Non-Responsive** Sign:
- Date/Time Analyzed: _____ @ _____ By (Print): _____ Sign: _____
- Results Reported To: _____ Via: _____ Date: _____ / _____ / _____ Time: _____ Initials: _____

BEST AVAILABLE COPY

FOIA Requested Record #J-15-0085 (VT)

Released by National Guard Bureau

Page 328 of 1352

Date Collected: October 25, 2012
Location: Bennington Readiness Center
Project No: 1120695
Inspector: Non-Responsive

**Table 1 –Dust Wipe Sampling Data Sheet for VT ARNG
Bennington Readiness Center on October 25, 2012.**

Wipe Sample #	Sample Location	Area
BEN-01	Supply Room/ Former Indoor Firing Range, Former bullet trap	10 cm x 10 cm
BEN-02	Supply Room/ Former Indoor Firing Range, Light fixture	10 cm x 10 cm
BEN-03	Supply Room/ Former Indoor Firing Range, Overhead Heater	10 cm x 10 cm
BEN-04	Supply Room/ Former Indoor Firing Range, Stored totes	10 cm x 10 cm
BEN-05	Supply Room/ Former Indoor Firing Range, Floor	10 cm x 10 cm
BEN-06	Supply Room/ Former Indoor Firing Range, Floor immediately outside	10 cm x 10 cm
BEN-07	Supply Office, Work station	10 cm x 10 cm
BEN-08	Kitchen, Counter	10 cm x 10 cm
BEN-09	Drill Hall, Table	10 cm x 10 cm
BEN-10	Drill Hall, Middle of floor	10 cm x 10 cm
BEN-11	Drill Hall, Window sill	10 cm x 10 cm
BEN-12	Room 12, Supply vent	10 cm x 10 cm
BEN-13	Stage, Middle of stage	10 cm x 10 cm
BEN-14	Room 14, Top of cabinet	10 cm x 10 cm
BEN-15	Room 23, Middle of Entry floor	10 cm x 10 cm
BEN-16	Break Room, Table	10 cm x 10 cm
BEN-17	Room 19, Window Sill	10 cm x 10 cm

BEN-18 PAINT CHIP SAMPLE FROM SHOWER

Appendix C Photo Documentation

Bennington RC



Photo 1: Bennington RC Front Entrance



Photo 2: Storage Area



Photo 3: Storage Area



Photo 4: Storage Area

Bennington RC



Photo 5: Supply Room



Photo 6: Supply Room



Photo 7: Peeling Paint in Men's Basement Shower



Photo 8: Peeling Paint in Men's Basement Shower

Bennington RC



Photo 9: Men's Basement Restroom



Photo 10: Break Room



Photo 11: Kitchen



Photo 12 Mechanical Room:

Bennington RC



Photo 13: Basement Hallway to Garage



Photo 14: Office



Photo 15: Drill Hall and Stage



Photo 16: Stage

Bennington RC



Photo 17: Drill Hall Balcony



Photo 18: Drill Hall



Photo 19: Computer Room



Photo 20: Bunk Room

Bennington RC




Photo 21: Office



Photo 22: Office

Appendix D IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Bennington	IAQ								Light		
Date	10/25/2012	Inspector	Non-Responsive	Instrument				Q-trak 7565-X				Instrument	Cal-Light 400L	
Facility Description	Bennington RC			Serial Number				7575x1228011				Serial Number	4980243	
Weather Conditions				Last Calibration				Jul-12				Last Calibration	16-Apr-12	
Location	Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
1	Classroom/Break Room			62.8	X	61.4	X	523		1.1		51.8		30-50
2	Kitchen			64.2	X	51.8		482		0.7		64.1		50
3	Boiler Room			65.9	X	49.8		474		0.6		32.9		30
4	Locker Room			68.2		51.0		517		0.7		144.7		7
5	Garage			68.4		40.3		523		1.0		28.8	X	30
6	Supply Room			72.6		50.2		745		0.9		109.9		30
7	Latrine			69.0		59.0		648		0.9		148.0		5
8	Janitor's Closet			68.9		62.0	X	677		0.9		53.9		30
9	Trainer's Storage			71.4		51.4		704		0.7		152.6		30
10	Maintenance Storage			70.9		46.9		583		0.9		105.5		30
11	Stairwell			70.3		47.5		596		0.6		140.1		5
12	Office			71.4		45.0		847		0.9		85.6		30-50
13	Office			71.6		45.0		851		0.9		96.8		30-50
14	Recruiters Office			72.2		44.1		669		0.9		86.3		30-50
15	Drill Hall			73.1		43.3		551		0.8		29.2	X	50
16	Stage/Weight Room			72.5		43.8		545		0.9		17.7	X	30
17	Office			69.6		50.4		699		0.6		120.6		30-50
18	Office			70.6		50.5		458		0.5		60.9		30-50
19	Bunk Room			72.3		46.4		658		0.6		38.5		5
20	Computer Room			72.6		44.8		616		0.6		57.8		30-50
21	Medic Room			73.0		42.7		741		0.8		28.6		30-50

Shaw Environmental, Inc.

312 Directors Drive
Knoxville, TN 37923
865.690.3211
Fax 865.690.3626



**National Guard Armory
Gosse Court/Moulton Readiness Center – Burlington,
Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

13 May 2004

National Guard Armory
Gosse Court/Moulton Readiness Center – Burlington,
Vermont

Industrial Hygiene Evaluation

Prepared for:

National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078

Prepared by:

Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923

13 May 2004

Prepared by:

Non-Responsive

Industrial Hygienist

Reviewed by:

Non-Responsive

Business Line Manager

Table of Contents

<i>Table of Contents</i>	<i>i</i>
<i>List of Tables</i>	<i>ii</i>
<i>List of Appendices</i>	<i>ii</i>
<i>Executive Summary</i>	<i>E-1</i>
<i>1.0 Introduction</i>	<i>1-1</i>
<i>2.0 Findings, Discussion, and Interpretation of Results</i>	<i>2-1</i>
<i>2.1 Sampling for Lead</i>	<i>2-1</i>
<i>2.1.1 Wipe Sampling</i>	<i>2-1</i>
<i>2.1.2 Air Sampling for Lead</i>	<i>2-2</i>
<i>2.2 Physical Condition of Facility</i>	<i>2-2</i>
<i>2.2.1 Peeling Paint - Lead</i>	<i>2-2</i>
<i>2.2.2 Visual Inspection - Asbestos</i>	<i>2-2</i>
<i>2.2.3 Visual Inspection - Water Damage and Mold</i>	<i>2-3</i>
<i>2.2.4 Visual Inspection - Housekeeping</i>	<i>2-3</i>
<i>2.3 Building Concerns</i>	<i>2-3</i>
<i>2.3.1 Ergonomic Concerns</i>	<i>2-3</i>
<i>2.3.2 Indoor Air Quality</i>	<i>2-3</i>
<i>2.4 Safety and Industrial Hygiene Programs</i>	<i>2-4</i>
<i>2.5 Ventilation</i>	<i>2-4</i>
<i>2.5.1 Ventilation System Evaluation</i>	<i>2-4</i>
<i>2.5.2 Contamination of Clean Air Sources</i>	<i>2-4</i>
<i>2.6 Noise Exposure</i>	<i>2-4</i>
<i>2.7 Lighting</i>	<i>2-4</i>
<i>2.8 Indoor Firing Ranges</i>	<i>2-5</i>
<i>2.9 HVAC Systems</i>	<i>2-5</i>
<i>2.10 IHIM</i>	<i>2-5</i>
<i>3.0 Conclusions</i>	<i>3-1</i>
<i>Tables</i>	<i>Follows Section 3.0</i>
<i>Appendices</i>	<i>Follows Tables</i>

List of Tables

Table 1	Wipe Sampling for Lead
Table 2	Air Sampling for Lead
Table 3	Indoor Air Quality Measurements
Table 4	Illumination Readings
Table 5	Indoor Firing Ranges Wipe Sampling

List of Appendices

Appendix A	HUM Data Form
Appendix B	Building Layout
Appendix C	Sampling Sheets and Laboratory Analyses
Appendix D	References
Appendix E	Recommendations for Surface Lead Dust in Armories

Executive Summary

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Gosse Court/Moulton Readiness Center in Burlington, Vermont.

Non-Responsive performed the evaluation on 21 July 2003 and 8 October 2003. The point of contact at the readiness center was SGT **Non-Responsive**

The following industrial hygiene concerns were evaluated.

- Wipe Sampling for Lead
- Air Sampling for Lead
- Peeling Paint – Lead
- Suspected Asbestos Containing Material
- Water Damage
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Indoor Air Quality
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- Lighting
- Converted Indoor Firing Range
- HVAC Systems

The following items were either not applicable to the armory or the evaluation resulted in a conclusion that there were no industrial hygiene concerns.

- Air Sampling for Lead
- Peeling Paint – Lead
- Water Damage
- Presence of Mold
- Housekeeping
- Ergonomic Concerns

- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- HVAC Systems

Areas where there were industrial hygiene concerns are as follows:

- Wipe sampling for lead revealed concentrations above the recommended level at three locations (assembly hall, kitchen, and floor outside the firing range) in the armory. It is recommended that these surfaces and the areas immediately around these surfaces be thoroughly cleaned to reduce the lead level. In addition, any other dusty/dirty areas in the assembly area/drill floor and kitchen should be thoroughly cleaned.
- Wipe sampling for lead revealed concentrations above a level of 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) in the assembly hall, kitchen, classroom, and floor outside the firing range. Areas with lead concentrations above $40 \mu\text{g}/\text{ft}^2$ that will be accessible to children should be cleaned. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.
- Materials (boiler room insulation and floor tiles) suspected of containing asbestos were observed. A bulk sample collected from the lobby floor revealed that the brown compact material did contain asbestos. An operations and maintenance plan should be followed when performing any activities that may disturb the asbestos-containing and suspected asbestos-containing materials.
- Indoor air quality measurements revealed that humidity at the armory exceeded the recommended levels. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory. In addition, interviews with employees revealed ventilation as an indoor air quality concern at the armory, specifically in the latrines where there is a minimal fresh air supply. A fan can be used for circulating air in the latrines.
- Lighting measurements were conducted at the armory. The lighting did not meet minimum requirements in some areas; therefore consideration should be given to providing more lighting in these areas. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter

color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

- There was not a converted firing range at the facility; however, there was an inactive indoor firing range. For informational purposes, wipe samples were taken for lead at various locations in or near the range. As expected, the results revealed lead at extremely high concentrations. This inactive firing range should not be used for any purposes, except as a firing range (if approved as a fully operating range), until the lead levels are reduced below the recommended level. In addition, employees should not be allowed to work in these areas without protective clothing until the areas have been cleaned.

1.0 Introduction

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Gosse Court/Moulton Readiness Center in Burlington, Vermont. **Non-Responsive** performed the evaluation on 21 July 2003 and 8 October 2003. The point of contact at the readiness center was SGT **Non-Responsive**

The findings, discussion, and interpretation of results are provided in Section 2.0. The conclusions are provided in Section 3.0. The HHIM data form for the facility is provided in Appendix A. The building layout is provided in Appendix B. Sampling sheets and laboratory analyses are provided in Appendix C. References are provided in Appendix D. The *Recommendations for Surface Lead Dust in Armories* document is provided in Appendix E.

The statements, opinions, and conclusions contained in this report are based solely upon the services performed by Shaw as described in the report. In performing these services and preparing the report, Shaw Environmental, Inc. relied upon the work and information provided by others, including public agencies, whose information is not guaranteed by Shaw Environmental, Inc.

2.0 Findings, Discussion, and Interpretation of Results

The results, discussion, and interpretation of results are provided in the following sections.

2.1. Sampling for Lead

2.1.1 Wipe Sampling

Wipe samples were collected for lead from the drill floor/assembly area. Also, wipe samples were collected for lead in rooms, hallways, foyers, etc. The sampling in rooms, hallways, foyers, etc. represented approximately 25% of the building. Approximately half of the samples were collected from surfaces in common areas, such as surfaces of a desk. The remaining samples were collected from uncommon surface areas, such as a supply vent or the top of a file cabinet. The samples were collected and analyzed in accordance with the Instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

The only samples initially submitted for analysis were those from the drill floor/assembly hall. If there were any positive results from the drill floor/assembly hall, the other samples would be submitted for analysis.

Results of the wipe sampling are provided in Table I. The results revealed lead at all locations sampled at concentrations below recommended level of 200 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$) (See Appendix E) except at three locations. The sample collected in the assembly room at the soda machine top surface location had a lead concentration of 580 $\mu\text{g}/\text{ft}^2$. The sample collected from the kitchen counter had a lead concentration of 770 $\mu\text{g}/\text{ft}^2$. The sample collected from the floor outside the firing range had a lead concentration of 60,000 $\mu\text{g}/\text{ft}^2$. It is recommended that these surfaces and the immediate areas around the surfaces be thoroughly cleaned to reduce the lead level to below 200 $\mu\text{g}/\text{ft}^2$. For guidance on the proper method of cleaning, please refer to NG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.

In addition, wipe sampling for lead revealed concentrations above a level of $40 \mu\text{g}/\text{ft}^2$ in the assembly room, classroom, kitchen, and floor outside the firing range. Please note that the *Recommendations for Surface Lead Dust in Armories* (Appendix E) states that all areas with lead concentrations above $40 \mu\text{g}/\text{ft}^2$ that will be accessible to children should be cleaned. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.

2.1.2 Air Sampling for Lead

Breathing zone air sampling was conducted on one (1) full-time building occupant. (Please note that no state employees were monitored.) The samples were collected and analyzed in accordance with Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods.

The results of the sampling are provided in Table 2. The results revealed non-detectable concentrations of lead in the breathing zone of the employee; therefore, no actions are necessary.

2.2 Physical Condition of Facility

2.2.1 Peeling Paint - Lead

Peeling paint was not observed at the armory.

2.2.2 Visual Inspection - Asbestos

A visual inspection was made to determine if there was any suspected asbestos-containing material at the armory. Materials suspected of containing asbestos were floor tiles (approximately 2563 square feet) and boiler room insulation material (approximately 18.5 linear feet). The floor tiles were observed in the front offices, inclusive of the three front offices, training room, two offices adjacent to the training room, classroom, meeting room, and lobby. Please note that two offices adjacent to the lobby latrine are assumed to have the suspected asbestos-containing floor tiles; therefore, the estimate of square feet of floor tiles material is greater than 2563 square feet.

The condition of the boiler room insulation materials was considered good (no rips, tears, or other damage). The condition of the floor tiles materials was considered

average to poor since there were many broken tiles in the lobby and meeting rooms and many loose tiles through out the facility. A bulk sample was collected from the lobby floor, the results revealed asbestos in the form of chrysotile of between 1% and 3 % in the brown compact material.

An operation and maintenance plan should be followed when performing any activities that may disturb the asbestos-containing and suspected asbestos-containing materials.

2.2.3 Visual Inspection – Water Damage and Mold

A visual inspection was made to determine if there was any water damage or visible mold at the armory. Water damage and visible mold were not observed at the armory. Please note that the ceilings in the meeting room and classroom are stained due to old water damage. The source of the water damage was roof leaks and the roof was replaced last year.

2.2.4 Visual Inspection - Housekeeping

The housekeeping was determined to be good.

2.3. Building Concerns

2.3.1 Ergonomic Concerns

Interviews with employees and observation of work activities revealed no ergonomic concerns at the armory.

2.3.2 Indoor Air Quality

Interviews with employees revealed ventilation as an indoor air quality concern at the armory, specifically in the latrines where there is a minimal fresh air. In addition, measurements for humidity revealed a level that exceeded the American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommended level of 60% in the armory. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory. In addition a fan can be used for circulating air in the latrines.

The results of the measurements for carbon dioxide, humidity, and temperature are provided in Table 3.

2.4. Safety and Industrial Hygiene Programs

An evaluation was performed to determine the applicability of the following programs.

- Confined Spaces
- Hearing Conservation
- Respiratory Protection
- Hazard Communication (HAZCOM)
- Personal Protective Equipment (PPE)

It was determined that the HAZCOM program was the only program listed above that was applicable at the facility. The HAZCOM program was evaluated and it was determined that the program met minimum requirements.

2.5. Ventilation

2.5.1 Ventilation System Evaluation

There were no local exhaust ventilation systems at this armory; therefore, no ventilation studies were performed.

2.5.2 Contamination of Clean Air Sources

Since there were no local exhaust ventilation systems at the armory, there was no possibility that clean air sources could be contaminated by exhaust air.

2.6. Noise Exposure

An evaluation was performed to determine if there were any hazardous noise areas at the armory. It was determined that there were no areas at the armory that would exceed the permissible exposure limit for noise.

2.7 Lighting

Lighting measurements were conducted at the armory. Results of the lighting evaluation are provided in Table 4. As can be seen from the results, the lighting did not meet the minimum requirements in some areas, including the two front offices.

Consideration should be given to providing more lighting to the areas listed above. This may be accomplished by replacing burnt out luminaries, cleaning fixtures,

cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

2.8 Indoor Firing Ranges

There was not a converted firing range at the facility; however, there was an inactive indoor firing range. For informational purposes, wipe samples were taken for lead at various locations in or near the range. The results are provided in Table 5. As expected, the results revealed lead at extremely high concentrations. This inactive firing range should not be used for any purposes, except as a firing range (if approved as a fully operating range), until the lead levels are reduced below the recommended level of 200 $\mu\text{g}/\text{ft}^2$, a level recommended in the *Guidelines for Converting Indoor Firing Ranges to Other Uses* document (Department of Army). For guidance on the proper method of cleaning, please refer to NG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, employees should not be allowed to work in these areas without protective clothing until the areas have been cleaned and re-sampled.

2.9. HVAC System

There was not a HVAC system at the armory.

2.10. HHIM

A Health Hazard Information Module (HHIM) form was completed for the armory. The completed form is provided in Appendix A.

3.0 Conclusions

It is concluded that there were no industrial hygiene concerns at the armory with regards to atmospheric exposure to lead, peeling lead-based paint, water damage, visible mold, housekeeping, ergonomic conditions, safety and industrial hygiene programs, ventilation systems or contamination of clean air sources, noise exposure, and HVAC systems.

There were industrial hygiene concerns at the armory with regards to lead surface contamination, suspected asbestos-containing material, indoor air quality, surface lead contamination in the inactive firing range, and lighting. These concerns are discussed in detail in Section 2.0 of this report.

TABLES

Table 1
Wipe Sampling for Lead
National Guard Armory
Burlington, Vermont
Dates of Sampling: 21 July 2003 and 8 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTGOS202-1	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTGOS202-2	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTGOS202-3	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTGOS202-4	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTGOS202-5	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTGOS202-6	Field Blank	< 12 μg
VTGOS202-15	Office- coat hanger top surface	39
VTGOS202-16	Classroom - window sill	79
VTGOS202-17	Office desktop	5.5
VTGOS202-18	Field Blank	0.42 μg
VTGOS202-19	Kitchen - counter top	770
VTGOS202-20	Supply Room (office area) filing cabinet top surface	31
VTGOS202-21	Meeting Room - table top	8.1
VTGOS202-22	Supply Room - wall	7.7
VTGOS282-1	Assembly Room - soda machine top surface (See Building Layout - Appendix B)	580
VTGOS282-2	Assembly Room - flammable cabinet top surface (See Building Layout - Appendix B)	31
VTGOS282-3	Assembly Room - cabinet top surface (See Building Layout - Appendix B)	26

^aMicrograms lead per square foot

Table 1 Continued
Wipe Sampling for Lead
National Guard Armory
Burlington, Vermont
Dates of Sampling: 21 July 2003 and 8 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTGOS282-4	Assembly Room -- Old supply room service windowsill (See Building Layout -- Appendix B)	130
VTGOS282-5	Assembly Room -- New supply room service windowsill (See Building Layout -- Appendix B)	74
VTGOS282-6	Field Blank	< 0.3 μg

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of Army National Guard Armories* procedure.

In armories that do not contain childcare facilities, the NGB Region North Industrial Hygiene Office recommends cleaning the areas with lead concentrations greater than 200 $\mu\text{g}/\text{ft}^2$.

Table 2
Breathing Zone Air Samples for Lead
National Guard Armory
Burlington, Vermont
Date of Sampling: 21 July 2003

Sample Number	Employee	Sampling Information			Results (mg/m ³) ^a
		Time Sampled / Minutes	Flow Rate (lpm) ^b	Volume (liters)	
VTGOS202-A1	Steffan Defeo	1339-1449 / 70	2.5043	175.30	< 0.006
VFLUD212-A2	Field Blank	.	-	-	None Detected

^a Milligrams lead per cubic meter of air.

^b Liters of air per minute.

Only one employee was sampled because there were no other employees at the armory on the date of the survey.

Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods was followed for sampling for lead.

Table 3
Indoor Air Quality Measurements for Carbon Dioxide, Humidity, and Temperature
National Guard Armory
Burlington, Vermont
Date of Sampling: 21 July 2003

Location	Occupants in Area	Carbon Dioxide, parts per million parts of air (ppm)	Percent (%) Humidity	Temperature (°F)
1 st Floor	1	463	68.6	75.4
Outdoors	0	402	57.3	78.1

Carbon dioxide, humidity, and temperature measurements were taken with a TSI Q Trak Plus, Model 8554, Indoor Air Quality Meter, calibrated in April 2003.

American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommends that indoor carbon dioxide levels be less than 700 ppm above outdoor levels.

ASHRAE recommends that the relative humidity levels be maintained between 30 to 60 percent.

ASHRAE recommends that the acceptable temperature range be 68 degrees Fahrenheit to 74 degrees Fahrenheit in the winter and 73 degrees Fahrenheit to 79 degrees Fahrenheit in the summer.

Table 4
Illumination Readings
National Guard Armory
Burlington, Vermont
Date of Sampling: 21 July 2003

Location	Luminance (fc) ^a	Standard (fc) ^a	Standard Met
Kitchen	43.0-85.2	70	Some areas
Meeting Room	43.2-115.3	70	Some areas
Classroom	61.4-79.3	70	Some areas
Front office	40.1-53.6	70	No
Front office (adjacent to lobby)	21.2-44.3	70	No

^a fc - Footcandles

The readings were taken with a Cooke Corporation cal-LIGHT 400 Calibrated Precision Lightmeter, calibrated on 19 Aug 2002.

The standards listed above are from Design Guide DG-415-2, Logistics Facilities, published by the National Guard Bureau Installation Division.

Table 5
Wipe Sampling for Lead – Firing Range
National Guard Armory
Burlington, Vermont
Date of Sampling: 21 July 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VT.UJ212-7	Exhaust ventilation system (taken outside)	320000
VT.UJ212-8	Bullet Trap	330000
VT.UJ212-9	Light Fixtures	11000
VT.UJ212-10	Overhead Heaters	220000
VT.UJ212-11	Stored Item	4100
VT.UJ212-12	Field Blank	< 12 μg
VT.UJ212-13	Floor	30000
VT.UJ212-14	Floor Outside the Range	60000

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of Army National Guard Armories* procedure.

Appendix A

HFIM Data Form(s)

HEALTH HAZARD INFORMATION MODULE: INDUSTRIAL HYGIENE SURVEY

(For use of this form, see HHIM User's Guide)

SECTION 1. DEMOGRAPHIC DATA

ARLOC	INSTALLATION Moulton/Goss Court Armory, Vermont ARNG	BLDG/RM NO. Burlington
LOCATION/CODE Administrative Areas / AA	OPERATION/CODE Administrative Operations / ADO	
SURVEY DATE 21 July 2003	EVALUATOR (Initials) MS	
MACOM/CODE Army National Guard	SUBMACOM/CODE XX	SUPERVISOR Non-Responsive SGT
TELEPHONE/DSN NO. 802 863-7677	UNIT/ORGANIZATION Company B 4th Battalion	RAC
NO. CIV(S) 0	NO. MIL 4	NO. CONTRACTOR(S) 0
	NO. LOC(S) 0	NO. OTHER 0
		FREQUENCY (hrs/day) 8

SECTION 2. FACILITY DATA

LAB HOODS 0	VAPOR DEGREASERS 0	SPRAY BOOTHS 0
MAINTENANCE BAYS 0	OPEN SURFACE TANKS 0	VENTILATION UNITS 0

SECTION 3. SURVEY DATA

CONTROLS PRESENT	EVALUATION	UNIT CODE	CONTROLS REQUIRED	STATUS

PERSONAL PROTECTIVE EQUIPMENT (R = Required; U = Utilized)

GLOVES	R	U	RESPIRATOR	NIOSH NO.	MANUFACTURER	R	U
ACID			AIRLINE				
COLD SURFACES			ABRASIVE BLASTING HOOD				
HOT SURFACES			DISPOSABLE				
NBC AGENTS			FULL FACE AIR PURIFYING				
OIL			1/2 FACE AIR PURIFYING				
SOLVENTS			POWERED AIR PURIFYING				
SURGICAL GLOVES			1/4 FACE AIR PURIFYING				
			SELF CONTAINED				

EYES/FACE	R	U	HEARING	R	U	BODY	R	U	HEAD/TIT	R	U
CHEMICAL SPLASH			CANAL CAPS			APRONS			COLD WEATHER BOOTS/HATS		
FULL FACE SHIELD			EAR PLUGS			COLD WEATHER CLOTHING			HARD HATS		
CHEMICAL/SAFETY			HELMETS			COVERALLS			IMPERMEABLE BOOTS		
SAFETY/IMPACT			MUFFS			FULL BODY SUIT			SAFETY/CONDUCTIVE SHOES		
WELDING HELMET			MUFF/EARPLUG COMBO			HEAT REFLECTIVE VEST/SUIT			SAFETY/NON-CONDUCTIVE SHOES		
			MUFF/EARPLUG W/TIME LIMIT			SAFETY BELT/HARNES					

SECTION 4. HAZARD INVENTORY DATA

CAS CODE	HAZARD DESCRIPTION	PAC	EPC
PVODTKXX	Video display unit	low	D Uncontrolled Physical
1332-21-4	Asbestos other	2-moderate	C Uncontrolled Respiratory
7439-92-1	Lead in products and fumes, as Pb	2-moderate	C Uncontrolled Respiratory
12001-29-5	Asbestos (Chrysotile)		C Uncontrolled Respiratory

SECTION 5. PERSONNEL DATA

LAST NAME	FIRST NAME	MI	SEX	SSN	CATEGORY
Non-Responsive			M	Non-Responsive	MIL
		A.			
		P.			
		A			

SECTION 6. COMMENTS

No comments. See attached sheet
 Survey conducted by Michele Sevan, Building contractor for (4) fulltime military staff members. Staff performs mainly administrative functions. Please note as youth program is based at the base, court assembly and both military and youth program staff and children utilize drill hall/assembly room.

PRIVACY ACT STATEMENT

Title 5 US Code, Section 301; Executive Order 9397 authorizes the use of your Social Security Number as an identification number. The purpose of this information is to identify and monitor data relating each DA civilian and military employee exposed to a hazardous workplace or operation. The use of this information is to provide histories of exposures for any given worker.


Disclosure of your Social Security Number is not mandatory; however, nondisclosures may result in untimely provision of proper medical monitoring.

Gosse Court Armory Full Time Personnel

Non-Responsive E5 **Non-Responsive**
[Redacted]
[Redacted] G/E6
[Redacted] SG/E6
[Redacted] SFC/E7 (Recruiter)

Appendix B

Building Layout



Appendix C

Sampling Sheets and Laboratory Analyses

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau Job Name: VTGOS202 Chain Of Custody: 115811
 Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation Job Location: Not Provided Date Analyzed: 08/05/2003
 Havre de Grace, Maryland 21078 Job Number: Not Provided Person Submitting: [REDACTED]
 P.O. Number: 07-01 Report Date: 18-Aug-03

Attention: [REDACTED] Page 1 of 2

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft²)	Reporting Limit	Final Result	Comments
0359501	VTGOS202-1	Flame	Wipe	****	0.111	108.00 ug/ft²	< 110 ug/ft²	
0359502	VTGOS202-2	Flame	Wipe	****	0.111	108.00 ug/ft²	< 110 ug/ft²	
0359503	VTGOS202-3	Flame	Wipe	****	0.111	108.00 ug/ft²	< 110 ug/ft²	
0359504	VTGOS202-4	Flame	Wipe	****	0.111	108.00 ug/ft²	< 110 ug/ft²	
0359505	VTGOS202-5	Flame	Wipe	****	0.111	108.00 ug/ft²	< 110 ug/ft²	
0359506	VTGOS202-6	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0359507	VTGOS202-7	Flame	Wipe	****	0.111	108.00 ug/ft²	320000 ug/ft²	
0359508	VTGOS202-8	Flame	Wipe	****	0.111	108.00 ug/ft²	330000 ug/ft²	
0359509	VTGOS202-9	Flame	Wipe	****	0.111	108.00 ug/ft²	11000 ug/ft²	
0359510	VTGOS202-10	Flame	Wipe	****	0.111	108.00 ug/ft²	220000 ug/ft²	
0359511	VTGOS202-11	Flame	Wipe	****	0.111	108.00 ug/ft²	4100 ug/ft²	
0359512	VTGOS202-12	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0359513	VTGOS202-13	Flame	Wipe	****	0.111	108.00 ug/ft²	30000 ug/ft²	
0359514	VTGOS202-14	Flame	Wipe	****	0.111	108.00 ug/ft²	60000 ug/ft²	

BEST AVAILABLE COPY

BEST AVAILABLE COPY

FOIA Requested Record #J-15-0085 (VTGOS202-14)
Released by National Guard Bureau

Page 368 of 1352

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

All rights reserved. AMA Analytical Services, Inc.

An AIHA (#8863), NVLAP (#101143), & New York ELAP (#10920) Accredited Laboratory
4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643



CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation
Havre de Grace, Maryland 21078

Job Name: VTGOS202
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01

Chain Of Custody: 115811
Date Analyzed: 08/05/2003

Person Submitting: [Redacted]
Report Date: 18-Aug-03

Attention: [Redacted] Page 2 of 2

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)
 Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] Non-Responsive

Technical Manager: [Redacted]

[Redacted] Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

All rights reserved. AMA Analytical Services, Inc.

Client: National Guard Bureau
 Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation
 Havre de Grace, Maryland 21078
 Job Name: VTGOS202
 Job Location: Not Provided
 Job Number: Not Provided
 P.O. Number: Not Provided
 Chain Of Custody: 118933
 Date Analyzed: 10/30/2003
 Person Submitting: [Redacted]
 Report Date: 30-Oct-03

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft²)	Reporting Limit	Final Result	Comments
0404847	VTGOS202-15	Furnace	Wipe	****	0.111	6.75 ug/ft²	39 ug/ft²	
0404848	VTGOS202-16	Furnace	Wipe	****	0.111	13.50 ug/ft²	79 ug/ft²	
0404849	VTGOS202-17	Furnace	Wipe	****	0.111	2.70 ug/ft²	5.5 ug/ft²	
0404850	VTGOS202-18	Furnace	Wipe Blank	****	N/A	0.30 ug	0.42 ug	
0404851	VTGOS202-19	Furnace	Wipe	****	0.111	135.01 ug/ft²	770 ug/ft²	
0404852	VTGOS202-20	Furnace	Wipe	****	0.111	5.40 ug/ft²	31 ug/ft²	
0404853	VTGOS202-21	Furnace	Wipe	****	0.111	2.70 ug/ft²	8.1 ug/ft²	
0404854	VTGOS202-22	Furnace	Wipe	****	0.111	2.70 ug/ft²	7.7 ug/ft²	

Analysis Method For Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] Technical Manager: [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

Client: National Guard Bureau Job Name: VTGOS282 Chain Of Custody: 118713
 Address: 3014H Old Bay Lane, Attn: NGB-AVN-SI, Static Military Reservation Job Location: Not Provided Date Analyzed: 10/21/2003
 Havre de Grace, Maryland 21078 Job Number: Not Provided Person Submitting: [Redacted]
 P.O. Number: 0701 Report Date: 21-Oct-03

Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0402886	VTGOS282-1	Furnace	Wipe	****	0.111	67.51 ug/ft ²	580 ug/ft ²	
0402887	VTGOS282-2	Furnace	Wipe	****	0.111	5.40 ug/ft ²	31 ug/ft ²	
0402888	VTGOS282-3	Furnace	Wipe	****	0.111	2.70 ug/ft ²	26 ug/ft ²	
0402889	VTGOS282-4	Furnace	Wipe	****	0.111	67.51 ug/ft ²	130 ug/ft ²	
0402890	VTGOS282-5	Furnace	Wipe	****	0.111	13.50 ug/ft ²	74 ug/ft ²	
0402891	VTGOS282-6	Furnace	Wipe Blank	****	N/A	0.30 ug	< 0.3 ug	

Analysis Method for Flame, Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per billion (ppb)
 %Pb = percent lead by weight ug = micrograms

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] Technical Manager: [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of brick samples and transmission electron microscopy of AHERA air samples.

An AIHA (#8863), NVLAP (# 101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643



Submitted To: **Non-Responsive**
Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTCAM205-A1 through VTAAS204-A3
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Filter
Method Reference:	NIOSH 7300
DCL Set ID No.:	03-S-3621
DCL Sample ID No.:	03-22309 through 03-22345
Sample Receipt Date:	7/28/2003
Preparation Date:	07/29/03
Analysis Date:	07/31/03

The samples were prepared and analyzed in accordance with NIOSH method 7300 using a Perkin Elmer 3000XL ICP.

The sample condition upon receipt was acceptable except where noted.

The results are in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.


This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive



Analyst

Non-Responsive



Reviewer

CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 280-8071, FAX 415 893-9469

**Results
Lead**

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTCAM205-A1	03-22309	407.54	ND	<0.002
VTCAM205-A2	03-22310	377.66	ND	<0.003
VTCAM205-A3	03-22311	0	ND	-
VTWIN202-A1	03-22313	152.91	ND	<0.007
VTWIN202-A2	03-22314	0	ND	-
VTENO196-A1	03-22316	150.55	ND	<0.007
VTENO196-A2	03-22317	0	ND	-
VTWIL197-A1	03-22319	199.78	ND	<0.005
	Prep Blank 1		ND	
% Recovery	LCS 1		96.	
% Recovery	LCS 2		96.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).
LCS = laboratory control sample.

Non-Responsive



Analyst

Non-Responsive



Reviewer

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTWIL197-A2	03-22320	149.76	ND	<0.007
VTWIL197-A3	03-22321	0	ND	-
VTSWA196-A1	03-22322	149.24	ND	<0.007
VTSWA196-A2	03-22323	0	ND	-
VTSTA196-A1	03-22324	165.20	ND	<0.006
VTSTA196-A2	03-22325	151.74	ND	<0.007
VTSTA196-A3	03-22326	0	ND	-
VTWAT203-A1	03-22328	194.90	ND	<0.005
VTWAT203-A2	03-22329	0	ND	-
VTGOS202-A1	03-22332	175.30	ND	<0.006
VTGOS202-A2	03-22333	0	ND	-
VTMOR203-A1	03-22335	346.43	ND	<0.003
VTMOR203-A2	03-22336	348.65	ND	<0.003
VTMOR203-A3	03-22337	0	ND	-
VTGRE197-A1	03-22340	240.55	ND	<0.004
VTGRE197-A2	03-22341	250.76	ND	<0.004
VTGRE197-A3	03-22342	0	ND	-
VTAAS209-A1	03-22343	748.92	ND	<0.001
VTAAS209-A2	03-22344	507.55	ND	<0.002
VTAAS209-A3	03-22345	0	ND	-
	Prep Blank 2		ND	
% Recovery	LCS 3		96.	
% Recovery	LCS 4		95.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).

LCS = laboratory control sample.

Non-Responsive



Analyst

Non-Responsive



Reviewer



7/30/03
Page 1 of 2

SUBMITTED TO:
Non-Responsive

Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

REFERENCE DATA:

Client Sample No.:	VTG05202-B1
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Bulk
Method Reference:	EPA-600/R-93/116
DCL Set ID No.:	03-A-3621
DCL Sample ID No.:	03-22334
Sample Receipt Date:	7/28/03
Analysis Date:	7/30/03

We certify that the following samples were prepared and analyzed by Polarized Light Microscopy for asbestos and other fibrous constituents using EPA-600/R-93/116. The samples were acceptable upon receipt except where noted. The samples were examined under a stereomicroscope in a laboratory fume hood for general composition and phase separation. If needed, portions of the sample were removed and ground with a mortar and pestle before being mounted on a glass microscope slide. Mountings of representative portions of the material are prepared in one or more appropriate refractive index liquids (1.550, 1.605, 1.680) and examined by Polarized Light Microscopy*. Estimates of concentration are made on an area basis. The results of the analysis apply only to the materials analyzed and are summarized on the attached bulk asbestos analysis data sheets. DataChem Laboratories will dispose of all bulk samples after 60 days unless other arrangements are made.

Non-Responsive

Analyst

Non-Responsive

Reviewer

*Floor tiles, decorative paints, joint compounds, and cement materials require additional treatment in order to evaluate the concentration of small asbestos fibers bound in the material. Some samples may contain fibers that are not visible by PLM and can only be detected by electron microscopy techniques. Floor tiles are analyzed as homogeneous materials if insufficient mastic is present or if phases have been cross contaminated.

DataChem Laboratories NVLAP Lab ID: 101917. Laboratory accreditation by the National Institute of Standards and Technology does not in any way constitute approval or endorsement by NIST.

CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 280-8071, FAX 415 893-9469

7/30/03

**DataChem Laboratories
Polarized Light Microscopy
Asbestos Analytical Report**

Client: Shaw Environmental, Inc.

Location: VT

Set ID: 03-A-3621

Client Sample ID:	VTG05202-B1	VTG05202-B1
DCL Sample ID:	03-22334A	03-22334B
Macroscopic Examination		
Accepted/Rejected:	Accepted	Accepted
Homogeneity:	Layered	Layered
Color:	Brown	Black
Texture:	Compact	Resinous
Description:	Tile	Mastic
Analysis:	PLM	PLM
Asbestiform Minerals		
% Chrysotile:	>1≤3	
% Amosite:		
% Crocidolite:		
% Tremolite - Actinolite:		
% Anthophyllite:		
% Total Asbestos:	>1≤3	ND
Other Materials		
% Cellulose:		
% Fiberglass:		
% Other Fibers:		
% Resin/Binder:	>10≤20	>70≤80
% Non Fibrous:	>70≤80	>10≤20

ND = None Detected Trace = <1%

Special Prep Procedures: None.

*Notes: P. O. #: 07-02.

Non-Responsive

Microscopist

All values are in area percent by visual estimate. The Federal Register Vol. 55 No. 224 Tuesday Nov. 20 1990 Rules and Regulations states "... If the asbestos content is estimated to be less than 10% by a method other than point counting,... (the analysis) be repeated using the point counting technique by PLM." Any of the above samples can be reanalyzed by point counting at the client's request. Wherever possible, separate phases are analyzed and reported individually.

Page 2 of 2

Industrial Hygiene Sampling Calculation Worksheet

National Guard Armory Location: GOS
 Date: 202

Sample 1

Sample Number: VTGOS202-A1
 Pump: 648339

	Pro Flow Rate	Post Flow Rate
	2.537	2.476
	2.521	2.485
	2.524	2.486
	2.519	2.486
Average	2.525	2.483

Average Pre and Post **2.5043**

Time 1 13:39
 Time 2 14:49
Total Time Sampled 1:10
Minutes Sampled 70.00

Volume **175.30 Liters**

Sample 2

Sample Number: N/A
 Pump: N/A

	Pre Flow Rate	Post Flow Rate
	N/A	N/A
Average	N/A	N/A

Average Pre and Post **N/A**

Time 1 N/A
 Time 2 N/A
Total Time Sampled N/A
Minutes Sampled N/A

Volume **N/A Liters**

Appendix D

References

References

Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration (current edition)

American Society of Heating, Refrigerating and Air-Conditioning Engineers, Inc (ASHRAE) 62-2002, Ventilation for Acceptable Indoor Air Quality

Instructions for Completing the Sampling of Army National Guard Armories, Lead Wipe Sampling Procedure included with the Request for Proposal

Air Sampling for Lead - Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods

Design Guide DG-415-2, Logistics Facilities, National Guard Bureau Installation Division, 14 December 1999

Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998

Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, 15 October 1990

AR 385-10, The Army Safety Program, 29 February 2000

Department of the Army Pamphlet (DA PAM) 40-501, Medical Services, Hearing Conservation Program, 10 December 1998

DA PAM 40-503, Medical Services, Industrial Hygiene Program, 30 October 2000

Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH) (current edition)

Guidelines for Converting Indoor Firing Ranges to Other Uses, Headquarters, Department of the Army and the Air Force, NG PAM (AR) 385-16/ANGPAM 91-101, 31 January 1994

24 CFR, Part 35, Subpart B, Section 35-110, Definition of Lead-Based Paint, Housing and Urban Development, U. S. Department of Housing

Appendix E
Recommendations for
Surface Lead Dust in Armories

Subject: Recommendations for Surface Lead Dust in Armories

1. In armories that do not contain childcare facilities, the National Guard Bureau (NGB) Region North Industrial Hygiene Office recommends cleaning the areas in which sample results are greater than 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$). If a special function will be held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function. This guidance is based on professional judgment, risk assessments, adaptation of Occupational Safety and Health Administration (OSHA) guidance, and feasibility of cleaning to a certain level.

a. Environmental Protection Agency (EPA) standards (40 Code of Federal Regulations (CFR) 745.227(b)(3)) are not directly applicable because they are criteria for dust-lead hazards developed for floors ($40 \mu\text{g}/\text{ft}^2$) and windowsills ($250 \mu\text{g}/\text{ft}^2$) in residential dwellings and child occupied facilities. A child occupied facility is defined as a building, or portion of a building, constructed prior to 1978, visited regularly by the same child, 6 years of age or under, on at least two different days within any week (Sunday through Saturday period), provided that each day's visit lasts at least 3 hours and the combined weekly visit lasts at least 6 hours, and the combined annual visits last at least 60 hours. Most of the wipe samples in armories were collected in undisturbed areas and therefore, results are worst case scenarios and do not correlate to these standards.

b. OSHA has no specific requirement for work area surfaces. The lead standard (29 CFR 1910.1025(h)) states that all surfaces shall be maintained as free as practicable of accumulations of lead dust. In workplaces where lead dust is generated, surface levels may be much higher, but personnel exposures can be controlled by limiting airborne lead levels and following good cleanup and hygienic practices.

c. OSHA used to cite a level of $200 \mu\text{g}/\text{ft}^2$ in their Technical Manual and 29 CFR 1926.62 as guidance to its own inspectors for evaluating the cleanliness of lunchroom and locker room surfaces that are supposed to be kept as clean as possible.

d. In a report titled Derivation of Wipe Surface Screening Levels for Environmental Chemicals, the US Army Center for Health Promotion and Preventive Medicine (USACHPPM) has determined that $200 \mu\text{g}/\text{ft}^2$ is a safe surface contamination level. They have also applied these standards as the decontamination levels for surfaces in administrative offices.

e. It should be noted that levels above these recommendations do not necessarily mean there is a significant hazard to workers who are following good cleaning and hygienic practices since there is no correlation between wipe and air samples. Rather, we recommend these levels as a precautionary measure.

2. The NGB Occupational Health Branch is developing guidance for armories that are used as childcare facilities. All states will receive this guidance when it is completed. In the interim, we recommend the following actions:

a. Clean all areas that will be accessible to children to the EPA dust-lead standard for children 6 years of age or under ($40 \mu\text{g}/\text{ft}^2$ on floors and $250 \mu\text{g}/\text{ft}^2$ on windowsills).

b. Refer to the local authorities' regulations since they can be more stringent than federal regulations.

c. Post signs in the area to inform people of the presence of lead dust and its effects.

d. If soldiers clean weapons in the facility change the policy so that they cannot clean their weapons in the facility, or if they are allowed to clean their weapons indoors, they must clean the area by wet wiping and mopping the area when they are done.

e. If the paint is peeling, contact the state Environmental Office to test for lead content and provide recommendations.

3. Air samples collected on individuals in the armory were well below OSHA's permissible exposure limit for lead (29 CFR 1910.1025(c)) of $0.05 \text{ mg}/\text{m}^3$ averaged over an 8-hour day. Therefore, based on these conditions there is currently no overexposure to personnel from lead dust in this building.

Shaw Environmental, Inc.

312 Directors Drive
Knoxville, TN 37923
865.690.3211
Fax 865.690.3626



Shaw® Shaw Environmental, Inc.

**National Guard Armory
Green Mountain Readiness Center – Colchester, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

24 May 2004

National Guard Armory
Green Mountain Readiness Center – Colchester, Vermont

Industrial Hygiene Evaluation

Prepared for:

National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078

Prepared by:

Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923

24 May 2004

Prepared by:

Non-Responsive

Industrial Hygienist

Reviewed by:

Non-Responsive

Business Line Manager

Table of Contents

<i>Table of Contents</i>	<i>i</i>
<i>List of Tables</i>	<i>ii</i>
<i>List of Appendices</i>	<i>ii</i>
<i>Executive Summary</i>	<i>F-1</i>
<i>1.0 Introduction</i>	<i>1-1</i>
<i>2.0 Findings, Discussion, and Interpretation of Results</i>	<i>2-1</i>
<i>2.1 Sampling for Lead</i>	<i>2-1</i>
<i>2.1.1 Wipe Sampling</i>	<i>2-1</i>
<i>2.1.2 Air Sampling for Lead</i>	<i>2-2</i>
<i>2.2 Physical Condition of Facility</i>	<i>2-2</i>
<i>2.2.1 Peeling Paint - Lead</i>	<i>2-2</i>
<i>2.2.2 Visual Inspection - Asbestos</i>	<i>2-2</i>
<i>2.2.3 Visual Inspection - Water Damage and Mold</i>	<i>2-2</i>
<i>2.2.4 Visual Inspection - Housekeeping</i>	<i>2-3</i>
<i>2.3 Building Concerns</i>	<i>2-3</i>
<i>2.3.1 Ergonomic Concerns</i>	<i>2-3</i>
<i>2.3.2 Indoor Air Quality</i>	<i>2-4</i>
<i>2.4 Safety and Industrial Hygiene Programs</i>	<i>2-4</i>
<i>2.5 Ventilation</i>	<i>2-5</i>
<i>2.5.1 Ventilation System Evaluation</i>	<i>2-5</i>
<i>2.5.2 Contamination of Clean Air Sources</i>	<i>2-5</i>
<i>2.6 Noise Exposure</i>	<i>2-5</i>
<i>2.7 Lighting</i>	<i>2-5</i>
<i>2.8 Converted Indoor Firing Ranges</i>	<i>2-5</i>
<i>2.9 HVAC Systems</i>	<i>2-6</i>
<i>2.10 IHMM</i>	<i>2-6</i>
<i>3.0 Conclusions</i>	<i>3-1</i>
<i>Tables</i>	<i>Follows Section 3.0</i>
<i>Appendices</i>	<i>Follows Tables</i>

List of Tables

Table 1	Wipe Sampling for Lead
Table 2	Air Sampling for Lead
Table 3	Indoor Air Quality Measurements
Table 4	Illumination Readings
Table 5	Firing Ranges -- Wipe Sampling

List of Appendices

Appendix A	IIIM Data Form
Appendix B	Building Layout
Appendix C	Sampling Sheets and Laboratory Analyses
Appendix D	References
Appendix E	Recommendations for Surface Lead Dust in Armories

Executive Summary

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Green Mountain Readiness Center in Colchester, Vermont. [Non-Responsive] [Non-Responsive] performed the evaluation on 16 and 17 July 2003 and 9 October 2003. The point of contact at the readiness center was LTC [Non-Responsive]

The following industrial hygiene concerns were evaluated.

- Wipe Sampling for Lead
- Air Sampling for Lead
- Peeling Paint – Lead
- Suspected Asbestos Containing Material
- Water Damage
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Indoor Air Quality
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- Lighting
- Converted Indoor Firing Range
- HVAC Systems

The following items were either not applicable to the armory or the evaluation resulted in a conclusion that there were no industrial hygiene concerns.

- Air Sampling for Lead
- Peeling Paint – Lead
- Suspected Asbestos Containing Material
- Housekeeping
- Safety and Industrial Hygiene Programs
- Contamination of Clean Air Sources

- Noise Exposure
- HVAC Systems

Areas where there were industrial hygiene concerns are as follows:

- Wipe sampling for lead revealed concentrations above the recommended level in the assembly area/drill floor, rooms on the second floor, and the floor outside the firing range. It is recommended that these surfaces and the areas immediately around these surfaces be thoroughly cleaned to reduce the lead level. In addition, any other dusty/dirty areas in the assembly area/drill floor and rooms on the second floor should be thoroughly cleaned.
- Wipe sampling for lead revealed concentrations above a level of 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) in the assembly hall, rooms E249, E236, E209, E203, and E228 located on the second floor, rooms B159 and C110 located on the first floor, the HVAC system providing air to the second floor of the building, and the floor outside the firing range. Areas with lead concentrations above $40 \mu\text{g}/\text{ft}^2$ that will be accessible to children should be cleaned. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.
- Water damage was observed at several locations at the armory. The source of the water damage was likely from roof leaks or condensation from the HVAC unit. The source of the water damage should be confirmed and actions taken to eliminate the source in order to prevent the possibility of mold growth that may lead to indoor air quality problems.
- Visual mold was observed in the armory. The area where the mold is located should be thoroughly cleaned with 0.5% sodium hypochlorite solution (1 part household bleach to nine parts water) or equivalent in order to eliminate the potential mold/indoor air quality problem. In addition, the source of the mold should be identified and actions taken to eliminate the source of the mold.
- Interviews with employees revealed that one employee is currently experiencing tingling of hands and other symptoms of carpal tunnel syndrome. Note that the employee has been fitted with an ergonomically correct keyboard. In addition, ergonomic concerns have occurred in the past year and have been corrected. Two employees have been fitted with new chairs due to back pain, and an employee in the personnel department has had carpal tunnel surgery. An extensive evaluation should

be performed to determine if the workstations should be improved from an ergonomic standpoint.

- Indoor air quality measurements revealed that the humidity at the armory exceeded the recommended levels. These areas should be evaluated to determine if the humidity could be controlled by the use of de-humidifiers or similar devices. In addition, interviews with employees revealed ventilation as an indoor air quality concern at the armory, specifically in the men and women's shower rooms, Room C115 (Band Rehearsal Hall), and in the A156 rooms. It is recommended that air circulation and ventilation be improved at the armory in the locations noted above.
- The exhaust ventilation system in the active firing range should be evaluated because it appears that the airflow is slow to exhaust due to the firing range floor plan. Lane 1 is directly in front of the entrance to the room and the remaining lanes are directly in front of the ventilation system.
- The lighting did not meet the minimum requirements in many areas of the armory. Consideration should be given to providing more lighting to these areas. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.
- There was not a converted firing range at the facility; however, there was an active indoor firing range. For informational purposes, wipe samples were taken for lead at various locations in or near the range. As expected, the results revealed lead at extremely high concentrations. This active firing range should not be used for any purposes except as a firing range.

1.0 Introduction

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Green Mountain Readiness Center in Colchester, Vermont. [Non-Responsive] performed the evaluation on 16 and 17 July 2003 and 8 October 2003. The point of contact at the readiness center was LTC [Non-Responsive].

The findings, discussion, and interpretation of results are provided in Section 2.0. The conclusions are provided in Section 3.0. The HHIM data form for the facility is provided in Appendix A. The building layout is provided in Appendix B. Sampling sheets and laboratory analyses are provided in Appendix C. References are provided in Appendix D. The *Recommendations for Surface Lead Dust in Armories* document is provided in Appendix E.

The statements, opinions, and conclusions contained in this report are based solely upon the services performed by Shaw as described in the report. In performing these services and preparing the report, Shaw Environmental, Inc. relied upon the work and information provided by others, including public agencies, whose information is not guaranteed by Shaw Environmental, Inc.

2.0 Findings, Discussion, and Interpretation of Results

The results, discussion, and interpretation of results are provided in the following sections.

2.1. Sampling for Lead

2.1.1 Wipe Sampling

Wipe samples were collected for lead from the drill floor/assembly area. Also, wipe samples were collected for lead in rooms, hallways, foyers, etc. The sampling in rooms, hallways, foyers, etc. represented approximately 25% of the building. Approximately half of the samples were collected from surfaces in common areas, such as surfaces of a desk. The remaining samples were collected from uncommon surface areas, such as a supply vent or the top of a file cabinet. The samples were collected and analyzed in accordance with the Instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

The only samples initially submitted for analysis were those from the drill floor/assembly hall. If there were any positive results from the drill floor/assembly hall, the other samples would be submitted for analysis.

Results of the wipe sampling are provided in Table I. The results revealed lead at all locations sampled at concentrations below recommended level of 200 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$) (See Appendix E) except at four locations. One sample collected from the drill hall floor had a lead concentration of 300 $\mu\text{g}/\text{ft}^2$. The sample obtained from the air grille located on the second floor in Room E238 had a lead concentration of 990 $\mu\text{g}/\text{ft}^2$. Both samples obtained from cabinet top surfaces located on the second floor in rooms E259 and E221 had lead concentrations of 210 $\mu\text{g}/\text{ft}^2$. The sample obtained from the floor outside the firing range had a lead concentration of 1900 $\mu\text{g}/\text{ft}^2$. It is recommended that these surfaces and the immediate areas around the surfaces be thoroughly cleaned to reduce the lead level to below 200 $\mu\text{g}/\text{ft}^2$. For guidance on the proper method of cleaning, please refer to NG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, any

other dusty/dirty areas in the assembly area/drill floor and second floor rooms indicated above should be thoroughly cleaned.

In addition, wipe sampling for lead revealed concentrations above a level of $40 \mu\text{g}/\text{ft}^2$ in the assembly hall, rooms E249, E236, E209, E203, and E228 located on the second floor, rooms B159 and C110 located on the first floor, and the HVAC system providing air to the second floor of the building. Please note that the *Recommendations for Surface Lead Dust in Armories* (Appendix E) states that all areas with lead concentrations above $40 \mu\text{g}/\text{ft}^2$ that will be accessible to children should be cleaned. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.

2.1.2 Air Sampling for Lead

Breathing zone air sampling was conducted on two (2) full-time building occupants. (Please note that no state employees were monitored.) The samples were collected and analyzed in accordance with Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods.

The results of the sampling are provided in Table 2. The results revealed non-detectable concentrations of lead in the breathing zone of the employees; therefore, no actions are necessary.

2.2 Physical Condition of Facility

2.2.1 Peeling Paint - Lead

Peeling paint was not observed at the armory; therefore, bulk samples for lead in paint were not taken.

2.2.2 Visual Inspection - Asbestos

A visual inspection was made to determine if there was any suspected asbestos-containing material at the armory. The inspection did not reveal any materials suspected of containing asbestos.

2.2.3 Visual Inspection – Water Damage and Mold

A visual inspection was made to determine if there was any water damage or visible mold at the armory. Water damage and visible mold were observed at the armory. Water damage was observed on the ceilings in the medical wing located on the second floor in Rooms E250, E251, E253, E260, E256 and E259. Water damage was also observed on the ceiling of the second floor hallway. Water damage was observed on ceilings on the first floor in the men's latrine/shower room, room C115 and adjacent to the door to room C114. Mold was observed on the ceilings of men's latrine/shower room, room E256, and room E259.

The source of the water damage was likely from roof leaks, or condensation from the HVAC unit concerning the medical wing water damage. Please note that the AC unit is continually in use in the medical wing area for equipment preservation. The source of the water damage should be confirmed and actions taken to eliminate the source in order to prevent the possibility of mold growth that may lead to indoor air quality problems.

The area where the mold is located should be thoroughly cleaned with 0.5% sodium hypochlorite solution (1 part household bleach to nine parts water) or equivalent in order to eliminate the potential mold/indoor air quality problem. In addition, the source of the mold should be identified and actions taken to eliminate it.

2.2.4 Visual Inspection - Housekeeping

The housekeeping was determined to be good.

2.3. Building Concerns

2.3.1 Ergonomic Concerns

Interviews with employees revealed that one employee is currently experiencing tingling of hands and other symptoms of carpal tunnel syndrome. Note that the employee has been fitted with an ergonomically correct keyboard. In addition, ergonomic concerns have occurred in the past year and have been corrected. Two employees have been fitted with new chairs due to back pain, and an employee in the personnel department has had carpal tunnel surgery. An extensive evaluation should be performed to determine if the workstations should be improved from an ergonomic standpoint.

2.3.2 Indoor Air Quality

Interviews with employees revealed ventilation as an indoor air quality concern at the armory, specifically in the men and women's shower rooms, Room C115 (Band Rehearsal Hall), and A156. Please note that the employees who occupy Room A156 have complained of sicknesses due to air quality issues. In addition, measurements for humidity revealed a level on the second floor exceeded the American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommended level of 60% in the armory. These areas should be evaluated to determine if the humidity could be controlled by the use of de-humidifiers or similar devices. The HVAC system is not utilized on a continual basis due to energy conservation practices; fans are mounted on office walls to circulate air. It is recommended that air circulation and ventilation be improved at the armory in the locations noted above.

The results of the measurements for carbon dioxide, humidity, and temperature are provided in Table 3.

2.4. Safety and Industrial Hygiene Programs

An evaluation was performed to determine the applicability of the following programs.

- Confined Spaces
- Hearing Conservation
- Respiratory Protection
- Hazard Communication (HAZCOM)
- Personal Protective Equipment (PPE)

It was determined that the hearing conservation, HAZCOM, and PPE programs were applicable at the facility. The programs were evaluated and it was determined that the program met minimum requirements. Please note that the hearing conservation and PPE programs are applicable only when the firing range located at the facility is in use. The hearing conservation program may also be applicable during band rehearsal.

2.5. Ventilation

2.5.1 Ventilation System Evaluation

There was a local exhaust ventilation system located in the active firing range at the armory. The exhaust ventilation system in the active firing range should be evaluated because it appears that the airflow is slow to exhaust due to the firing range floor plan. Lane 1 is directly in front of the entrance to the room and the remaining lanes are directly in front of the ventilation system.

2.5.2 Contamination of Clean Air Sources

There is no evidence that clean air sources could be contaminated by exhaust air.

2.6. Noise Exposure

An evaluation was performed to determine if there were any hazardous noise areas at the armory. It was determined that there were no areas at the armory that would exceed the permissible exposure limit for noise except in the firing range. Personal protective equipment is required by those using the firing range.

2.7 Lighting

Lighting measurements were conducted at the armory. Results of the lighting evaluation are provided in Table 4. As can be seen from the results, the lighting did not meet the minimum requirements in many areas. Consideration should be given to providing more lighting to the areas listed above. This may be accomplished by replacing burnt out luminaires, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

2.8 Indoor Firing Ranges

There was not a converted firing range at the facility; however, there was an active indoor firing range. For informational purposes, wipe samples were taken for lead at various locations in or near the range. The results are provided in Table 5. As expected, the results revealed lead at extremely high concentrations. This active firing range should not be used for any purposes except as a firing range.

2.9. HVAC System

The maintenance schedule for the HVAC system was evaluated to verify that maintenance occurs on a regular basis. Also, the condition of the HVAC system was evaluated to determine if the maintenance performed is effective. It was deemed that maintenance occurs on a regular basis, and the maintenance performed is effective. Note that the HVAC system is not utilized on a continual basis due to energy conservation practices.

2.10. HHIM

A Health Hazard Information Module (HHIM) form was completed for the armory. The completed form is provided in Appendix A.

3.0 Conclusions

It is concluded that there were no industrial hygiene concerns at the armory with regards to atmospheric exposure to lead, peeling lead-based paint, suspected asbestos-containing material, housekeeping, safety and industrial hygiene programs, noise exposure, and HVAC systems.

There were industrial hygiene concerns at the armory with regards to lead surface contamination, water damage, visible mold, ergonomic conditions, indoor air quality, ventilation systems, contamination of clean air sources, lighting, and surface lead contamination in the firing range. These concerns are discussed in detail in Section 2.0 of this report.

TABLES

Table 1
Wipe Sampling for Lead
National Guard Armory
Colchester, Vermont
Dates of Sampling: 16 and 17 July 2003 and 9 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTGRE197-1	Drill Floor - On Floor (See Building Layout - Appendix B)	300
VTGRE197-2	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTGRE197-3	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTGRE197-4	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTGRE197-5	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTGRE197-6	Field Blank	< 12 μg
VTGRE197-13	Second Floor - Room E238 - air grille	990
VTGRE197-14	Second Floor - Room E249 - desktop	170
VTGRE197-15	Second Floor - Room E259 - cabinet top surface	210
VTGRE197-16	Second Floor - Room E236 - desktop	190
VTGRE197-17	Second Floor - Room E221 - cabinet top surface	210
VTGRE197-18	Field Blank	< 12 μg
VTGRE197-19	Second Floor - Room E209 - desktop	120
VTGRE197-20	Second Floor - Room E203 - shelf top surface	170
VTGRE197-21	Second Floor - Room E215 - desktop	< 110
VTGRE197-22	Second Floor - Room E228 - Classroom tabletop	< 110
VTGRE198-23	Second Floor - Room E216 - desk shelf top surface	< 110
VTGRE198-24	Field Blank	< 12 μg
VTGRE198-25	Second Floor - Room E211 - desktop	< 110
VTGRE198-26	Second Floor - Room E223 - television top surface	< 110
VTGRE198-27	Second Floor - Room E228 - windowsill	160
VTGRE198-28	First Floor - Room B159 - tabletop	170
VTGRE198-29	First Floor - Room B131A - bookshelf top surface	< 110
VTGRE198-30	Field Blank	< 12 μg
VTGRE198-31	First Floor - Room B133 - desktop	< 110
VTGRE198-32	First Floor - Room C108 - desktop	< 110

^a Micrograms lead per square foot

Table 1 Continued
Wipe Sampling for Lead
National Guard Armory
Colchester, Vermont
Dates of Sampling: 16 and 17 July 2003 and 9 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTGRE198-33	First Floor -- Room C115 -- heating vent top surface	< 110
VTGRE198-34	First Floor -- Room C110 -- counter top surface	< 110
VTGRE198-35	First Floor -- Room B140 -- top surface of stored item	< 110
VTGRE198-36	Field Blank	< 12 μg
VTGRE198-37	First Floor -- Room B109 -- desktop	< 110
VTGRE198-38	First Floor -- Room B122 -- kitchen bottom shelf surface	< 110
VTGRE198-39	First Floor -- Room B100A -- desk cabinet surface	< 110
VTGRE198-40	First Floor -- Room A174 -- desk shelf top surface	< 110
VTGRE198-41	First Floor -- Room A172 -- desktop	< 110
VTGRE198-42	Field Blank	< 12 μg
VTGRE198-43	First Floor -- lobby -- tabletop	< 110
VTGRE198-44	First Floor -- Room A117 -- bookshelf top surface	< 110
VTGRE198-45	First Floor -- Room A103 -- table top	< 110
VTGRE198-46	First Floor -- Room A134 -- cabinet top surface	< 110
VTGRE198-47	First Floor -- Room A142 -- desktop	< 110
VTGRE198-48	Field Blank	< 12 μg
VTGRE198-49	First Floor -- Room A158 -- coat hanger top surface	< 110
VTGRE198-50	First Floor -- Room A157 -- desktop	< 110
VTGRE198-51	First Floor -- Room A152 -- cabinet top surface	< 110
VTGRE198-52	First Floor -- Room A151 -- desktop	< 110
VTGRE198-53	First Floor -- Room A156 -- table top	< 110
VTGRE198-54	Field Blank	< 12 μg
VTGRE198-55	First Floor -- Room A156B -- cabinet top surface	< 110
VTGRE198-56	First Floor -- Room A156D -- cabinet top	< 110
VTGRE198-57	First Floor -- Room A178 -- table top	< 110
VTGRE198-58	First Floor -- Room B102 -- table top	< 110

^aMicrograms lead per square foot

Table 1 Continued
Wipe Sampling for Lead
National Guard Armory
Colchester, Vermont
Dates of Sampling: 16 and 17 July 2003 and October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTGRE198-59	First Floor – Room C112 – cabinet top surface	< 110
VTGRE198-60	Field Blank	< 12 μg
VTGRE198-61	First Floor – Assembly hall – serving cart top surface	< 110
VTGRE198-62	First Floor – Room A166 – table top	< 110
VTGRE198-63	First Floor – Room A167 – desktop	< 110
VTGRE283-1	HVAC system-supply air grille (fan side of filter) Room E236	22
VTGRE283-2	HVAC system-supply side of filter	78
VTGRE283-3	Assembly Room – desk surface (See Building Layout – Appendix B)	52
VTGRE283-4	HVAC system-supply air grille (filter side) Room A134	13
VTGRE283-5	HVAC system-supply air grille (filter side) Room C110	150
VTGRE283-6	Field Blank	0.35 μg

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of Army National Guard Armories* procedure.

In armories that do not contain childcare facilities, the NGB Region North Industrial Hygiene Office recommends cleaning the areas with lead concentrations greater than 200 $\mu\text{g}/\text{ft}^2$.

Table 2
Breathing Zone Air Samples for Lead
National Guard Armory
Colchester, Vermont
Date of Sampling: 16 July 2003

Sample Number	Employee	Sampling Information			Results (mg/m ³) ^a
		Time Sampled / Minutes	Flow Rate (lpm) ^b	Volume (liters)	
VTGRE197-A1	Non-Responsive	1343-1520/97	2.4799	240.55	< 0.004
VTGRE197-A2		1357-1537/100	2.5076	250.76	< 0.004
VTGRE197-A3	Field Blank	-	-	-	None Detected

^a Milligrams lead per cubic meter of air.

^b Liters of air per minute.

Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods was followed for sampling for lead.

Table 3
Indoor Air Quality Measurements for Carbon Dioxide, Humidity, and Temperature
National Guard Armory
Colchester, Vermont
Date of Sampling: 16 August 2003

Location	Occupants in Area	Carbon Dioxide, parts per million parts of air (ppm)	Percent (%) Humidity	Temperature (°F)
Outdoors	0	358	52.6	85.8
1 st Floor	1	422	57.0	77.7
2 nd Floor	1	379	71.6	76.5

Carbon dioxide, humidity, and temperature measurements were taken with a TSI Q Trak Plus, Model 8554, Indoor Air Quality Meter, calibrated in April 2003.

American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommends that indoor carbon dioxide levels be less than 700 ppm above outdoor levels.

ASHRAE recommends that the relative humidity levels be maintained between 30 to 60 percent.

ASHRAE recommends that the acceptable temperature range be 68 degrees Fahrenheit to 74 degrees Fahrenheit in the winter and 73 degrees Fahrenheit to 79 degrees Fahrenheit in the summer.

Table 4
Illumination Readings
National Guard Armory
Colchester, Vermont
Date of Sampling: 16 and 17 July 2003

Location	Luminance (fc) ^a	Standard (fc) ^a	Standard Met
Second Floor – Room E238 Office	30.3-142.3	70	Some areas
Second Floor – Room E249 Exam Room	40.7-142.3	70	Some areas
Second Floor – Room E251 Exam Room	32.1-100.1	70	Some areas
Second Floor – Room E236 Office	33.9-111.1	70	Some areas
Second Floor – Room E221 Office	8.0-134.6	70	Some areas
Second Floor – Room E209 Office	20.1-135.5	70	Some areas
Second Floor – Room E216 Office	18.1-118.3	70	Some areas
Second Floor – E211 Room Office	22.1-110.7	70	Some areas
First Floor – Room B159 Office	17.4-141.3	70	Some areas
First Floor – Room C115 Band Rehearsal Room	3.6-201	70	Some areas
First Floor – Room C112 Office	30.1-143.2	70	Some areas
First Floor – Room B122 Kitchen	63.2-117.1	70	Some areas
First Floor – Room B100A Office	48.3-119.6	70	Some areas
First Floor – Room A174 Office	84.1-143.3	70	Yes
First Floor – Room A172 Office	51.2-134.6	70	Some areas
First Floor – Room A103 Office	23.1-102.5	70	Some areas
First Floor – Room C108 Office	24.5-113	70	Some areas
First Floor – Room B131A Office	18.1-141	70	Some areas

^a fc - Footcandles

The readings were taken with a Cooke Corporation cal-LIGHT 400 Calibrated Precision Lightmeter, calibrated on 19 Aug 2002.

The standards listed above are from Design Guide DG-415-2, Logistics Facilities, published by the National Guard Bureau Installation Division.

Table 5
Wipe Sampling for Lead – Firing Range
National Guard Armory
Colchester, Vermont
Date of Sampling: 16 and 17 July 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTGRE197-7	Bullet Trap	260000
VTGRE197-8	Overhead Heaters	260000
VTGRE197-9	Stored Item (table top)	1500
VTGRE197-10	Floor	260000
VTGRE197-11	Floor Outside the Range	1900
VTGRE197-12	Blank	< 12 μg

^aMicrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

Appendix A

HHIM Data Form(s)

HEALTH HAZARD INFORMATION MODULE: INDUSTRIAL HYGIENE SURVEY

(For use of this form, see HHIM User's Guide)

SECTION 1. DEMOGRAPHIC DATA

ARLOC	INSTALLATION Green Mountain Armory Vermont ARNG	BLDG/RM NO. Colchester
LOCATION/CODE Administrative Areas/AA	OPERATION/CODE Administrative Operations/ADO	
SURVEY DATE 16 and 17 July 2003	EVALUATOR (Initials) ND	
MACOM/CODE Army National Guard	SUBMACOM/CODE XX	SUPERVISOR Non-Responsive LTC
TELEPHONE/DSN NO. 802-338-3337	UNIT/ORGANIZATION Headquarters Vermont National Guard	RAC 4
		FREQUENCY (hrs/day) 8
NO. CIV(S) 11	NO. MIL 123	NO. CONTRACTOR(S) 0
		NO. LOC(S) 0
		NO. OTHER 0

SECTION 2. FACILITY DATA

LAB HOODS 0	VAPOR DEGREASERS 0	SPRAY BOOTHS 0
MAINTENANCE BAYS 0	OPEN SURFACE TANKS 0	VENTILATION UNITS 1

SECTION 3. SURVEY DATA

CONTROLS PRESENT	EVALUATION	UNIT CODE	CONTROLS REQUIRED	STATUS

PERSONAL PROTECTIVE EQUIPMENT (R = Required; U = Utilized)

GLOVES	R	U	RESPIRATOR	NOSH TC NO.	MANUFACTURER	R	U
ACID			AIRLINE				
COLD SURFACES			ABRASIVE BLASTING HOOD				
HOT SURFACES			DISPOSABLE				
NBC AGENTS			FULL FACE AIR PURIFYING				
OIL			1/2 FACE AIR PURIFYING				
SOLVENTS			POWERED AIR PURIFYING				
SURGICAL GLOVES			1/4 FACE AIR PURIFYING				
			SELF CONTAINED				

EYES/FACE	R	U	HEARING	R	U	BODY	R	U	HEAD/FIT	R	U
CHEMICAL SPLASH			CANAL CAPS			APRONS			COLD WEATHER BOOTS/HATS		
FULL FACE SHIELD			EAR PLUGS			COLD WEATHER CLOTHING			HARD HATS		
CHEMICAL/SAFETY			HELMETS			COVERALLS			IMPERMEABLE BOOTS		
SAFETY/IMPACT			MUFFS			FULL BODY SUIT			SAFETY/CONDUCTIVE SHOES		
WELDING HELMET			MUFF/EARPLUG COMBO			HEAT REFLECTIVE VEST/SUIT			SAFETY/NON-CONDUCTIVE SHOES		
			MUFF/EARPLUG W/TIME LIMIT			HEAT REFLECTIVE VEST/SUIT					
						SAFETY BELT/HARNES					

SECTION 4. HAZARD INVENTORY DATA

CAS CODE	HAZARD DESCRIPTION	PAC	EPC
POVSTXXX	Video display Terminal	3-low	D-Uncontrolled Physical
7439-92-1	Lead, Inorganic dust & fumes, as Pb	2-moderate	C Uncontrolled Respiratory

SECTION 5. PERSONNEL DATA

LAST NAME	FIRST NAME	MI	SEX	SSN	CATEGORY
see attached list					

SECTION 6. COMMENTS

No comments See attached sheet
 Michele Sowan conducted survey. Building contains military
 staff. Employee perform liability Administrative functions. Please note
 most was observed in offices on the second floor and the men's
 bathroom on the first floor. **PRIVACY ACT STATEMENT** of the building

Title 5 US Code, Section 301; Executive Order 9397 authorizes the use of your Social Security Number as an identification number. The purpose of this information is to identify and monitor data relating each DA civilian and military employee exposed to a hazardous workplace or operation. The use of this information is to provide histories of exposures for any given worker.

Disclosure of your Social Security Number is not mandatory; however, nondisclosure may result in untimely provision of proper medical monitoring.

Non-Responsive

LTC	338-3160		STAFF JAG	GMA	VT-JAG
MSGT	338-3145		HRO	GMA	VT-HRO
SFC	338-3151		DCSOPS	GMA	VT- DCSOPS-R
SPC	338-3050		VT-EOC	GMA	VT-EOC
SFC	338-3050		VT-EOC	GMA	VT-EOC
MAJ	338-3150		DCSOPS	GMA	VT- DCSOPS-R
CW2	338-3144		HRO	GMA	VT-HRO
CW2	338-3347		DPA	GMA	VT-DPA-FP
SFC	338-3437		RRO	GMA	VT-DPA-R
1LT	338-3131		DPA & TQM	GMA	VT- DPA/TQM
SGM	338-3176		RRO	GMA	VT-DPA-R
MAJ	338-3449		RRO	GMA	VT-DPA-R
LTC	338-3242		SRAAG	GMA	AFKA-A-VT
MR	338-3021		HRO	GMA	VT-HRO
LTC	338-3160		JAG	GMA	VT-JAG
SGM	338-3163		DCSOPS	GMA	VT- DCSOPS- TA
CPT	338-3397		COUNTER DRUG	GMA	VT-CD- DDR
MSG	338-3126		HQ VTANG	GMA	VTANG-CS
SGT	338-3456		STATE MEDICAL CMD	GMA	W77950
SPC	338-3333		DPA	GMA	VT-DPA-O
SPC	338-3471		PUBLIC AFFAIRS	GMA	VT-PAO
SSG	338-3143		HRO	GMA	VT-HRO
COL	338-3140		HRO	GMA	VT-HRO
SFC	338-3173		RRO	GMA	VT-DPA-R
SSG	338-3465		131 ENGR CO	GMA	WP8JAA

m-DAY

Non-Responsive

CSM	338-3123		TAGO-VT	GMA	VT-CSM
MRS	338-3423		DPA	GMA	VT-DPA
SSG	338-3152		DCSOPS	GMA	VT-DCSOPS
LTC	338-3431		HQ-VTANG	GMA	VTANG-CS
SFC	338-3132		DPA	GMA	VT-DPA-E
COL	338-3122		CHIEF OF STAFF	GMA	VT-CS
SFC	338-3480		BAND/PAD	GMA	WQJBAA
SGT	655-0542		RRO	GMA	VT-DPA-R
LTC	338-3130		DCSPER	GMA	VT-DCSPER
SSG	338-3135		DPA	GMA	VT-DPA-E
MR	338-3124		TAGO-VT	GMA	VT-AG
1SG	338-3421		Med. Residency RRO	GMA	VT-DPA-ME VT-DPA-R
LTC	338-3453		INSPECTOR GENERAL	GMA	VT-IG
SSG	338-3475		COUNTER DRUG	GMA	VT-CD
TSGT	338-3245		HRO	GMA	VT-HRO
SFC	338-3153		DCSOPS	GMA	VT-DCSOPS-TA
SFC	338-3174		RRO	GMA	VT-DPA-R
CPT	338-3163		DSCOPS	GMA	VTPDCSOPS
MAJ	338-3440		DRUG DEMAND REDUCTION	GMA	VT-CD-DDR
SFC	338-3146		HRO	GMA	VT-HRO-ST
SSG	338-3166		INFO MGMT OFFICE	GMA	VT-IM-AS
CPT	338-3151		DCSOPS	GMA	VT-DCSOPS-R
TSGT	338-3478		HQ VTANG	GMA	VT-PAO
SFC	338-3450		HQ STARC (-)	GMA	W8BFAA
SFC	338-3172		RRO	GMA	VT-DPA-R
MSG	338-3133		SIDPERS	GMA	VT-DPA-S

m-day

gone to Afghanistan

Non-Responsive

SFC	338-3454		RRO	GMA	VT-DPA-R
SFC	338-3456		STATE MEDICAL OMB	GMA	W99750
SGT	338-3152		DCSOPS	GMA	VT- DCSOPS
SPC	338-3430		INFO MGMT OFFICE	GMA	VT-IM-AS
SSG	338-3452		HQ STARC (-)	GMA	W8BFAA
SGT	338-3171		RRO	GMA	VT-DPA-R
SPC	338-3137		DPA-O	GMA	VT-DPA-O
SSG	338-3197		HRO	GMA	VT-HRO
SFC	338-3254		HRO	GMA	VT-HRO
LTC	338-3337		SAFTEY	GMA	VT-DPA- VPP
MRS	338-3241		SRAAG	GMA	AFKA-A-VT
2LT	338-3488		POMSO	GMA	VT-PTS- MS
BG	338-3492		HQ VTANG	GMA	VTANG-CS
SMS	338-3249		HQ VTANG	GMA	VTANG-CS
SFC	338-3155		DCSOPS	GMA	VT- DCSOPS- TA
SFC	338-3330		INFO MGMT OFFICE	GMA	VT-IM-AS
MSG	338-3451		COUNTER DRUG	GMA	VT-CD- DDR
SGT	338-3297		DPA	GMA	VT-DPA-P
GMS	338-3128		HQ VTANG	GMA	VTANG- GMS
MSG	338-3126		HQ ANG	GMA	VTANG-CS
SGT	338-3476		40th ARMY BAND	GMA	WQJ8AA
BG	338-3121		TAGO-VT	GMA	VT-DAG
LTC	338-3157		DCSOPS	GMA	VT- DCSOPS- TA
MSG	338-3142		HRO	GMA	VT-HRO
2LT	338-3448		RRO	GMA	VT-DPA-R

*gmc to Afghanistan**m Day*

Non-Responsive

MSG	338-3292		TELECOM MUNICATI ONS	GMA	VT-IM-CE
SSG	338-3082		STATE JAG OFFICE	GMA	VT-JAG
COL	338-3179		ESSO, ST HQ/ AIR STAFF	GMA	VT-ESSO
MAJ	338-3131		DPA	GMA	VT-DPA-O
CW4	338-3136		DPA	GMA	VT-DPA- HS
SGM	338-3159		POMSO	GMA	VT-PTS- MS
MAJ	338-3350		COUNTER DRUG	GMA	VT-CD
COL	338-3140		HRO	GMA	VT-HRO
LTC	338-3348		DCSPER	GMA	VT-DPA-ES
SGT	338-3476		BAND/PAD	GMA	WQJ8AA
MG	338-3124		TAGO-VT	GMA	VT-AG
SSG	338-3061		STATE MEDICAL CMD	GMA	W77950
SPC	338-3191		DPA	GMA	VT-DPA-E
SPC	338-3058		VTNG EOC	GMA	VT-EOC
SFC	338-3344		COUNTER DRUG	GMA	VT-CD
SFC	338-3346		DPA (SRIP)	GMA	VT-DPA
OPT	338-3246		PAO	GMA	VT-PAO
MRS	338-3154		MEDICAL REDINESS	GMA	VT-DPA- MR
MS	338-3314		ACCT & PERSONN EL	GMA	VT-AG
CW3	338-3052		VTNG EOC	GMA	VT-EOC
PFC	338-3000		INFO MGMT OFFICE	GMA	VT-IM-AS
MSG	338-3349		INFO MGMT OFFICE	GMA	VT-IM-IS
MAJ	338-3163		DCSOPS	GMA	VT- DCSOPS- TA
LTC	338-3129		CHIEF OF STAFF	GMA	VT-CS

Agustin

Non-Responsive

BG	338-3424	HQ VTANG	GMA	VT-ANG-AAG
MRS	338-3116	TAGO-VT	GMA	VT-AG
MS	338-3158	DCSOPS	GMA	VT-DCSOPS
CPT	338-3141	HRO	GMA	VT-HRO
CWO	338-3488	POMSO	GMA	VT-PTS-MS
SFC	338-3139	SIDPERS	GMA	VT-DPA-S
SSG	338-3458	131 ENGR CO	GMA	WP8JAA
LTC	338-3342	POMSO	GMA	VT-PTS-MS
SSG	338-3138	SIDPERS	GMA	VT-DPA-S
MRS	338-3310	ACCT & PERSONNEL	GMA	VT-AG
MSG	338-3128	HQ ANG	GMA	VTANG-CS
COL	338-3127	HQ VTANG	GMA	VTANG-CS
CWO	338-3177	HRO	GMA	VT-HRO
CMS	338-3148	HRO	GMA	VT-HRO
SFC	338-3171	RRO	GMA	VT-DPA-R
COL	338-3458	INSPECTOR GENERAL	GMA	VT-MS
SGT	338-3419	DPA - ID CARD SECTION	GMA	VT-DPA-ID
SFC	338-3486	131 ENGR CO	GMA	WP8JAA
LTC	338-3147	HRO	GMA	VT-HRO
COL	338-3156	POTO/DCS OPS	GMA	VT-PTS
MAJ	338-3172	OSM	GMA	VT-DPA-R
SPC	338-3125	CHIEF OF STAFF	GMA	VT-CS
SGT	338-3458	131 ENGR CO	GMA	WP8JAA
SGT	338-3162	DPA	GMA	VT-DPA-E
SGT	338-3351	COUNTER DRUG	GMA	VT-CD
MAJ	338-3336	SAFETY OFFICE	GMA	VT-SOHM

retired


retired

retired


gone to Afghanistan

Appendix B

Building Layout



C.J. ARMORY
FIRST FLOOR



C.J. ARMORY
 SECOND FLOOR
 N.T.S.

4

Appendix C

Sampling Sheets and Laboratory Analyses

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301-TH Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation
 .Havre de Grace, Maryland 21078
Job Name: VTGRE197
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01
Chain Of Custody: 115805
Date Analyzed: 8/5/2003
Person Submitting: [REDACTED]
Report Date: 05-Aug-03

Page 1 of 2

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft²)	Reporting Limit	Final Result	Comments
0359444	VTGRE197-1	Flame	Wipe	****	0.111	108.00 ug/ft²	300 ug/ft²	
0359445	VTGRE197-2	Flame	Wipe	****	0.111	108.00 ug/ft²	< 110 ug/ft²	
0359446	VTGRE197-3	Flame	Wipe	****	0.111	108.00 ug/ft²	< 110 ug/ft²	
0359447	VTGRE197-4	Flame	Wipe	****	0.111	108.00 ug/ft²	< 110 ug/ft²	
0359448	VTGRE197-5	Flame	Wipe	****	0.111	108.00 ug/ft²	< 110 ug/ft²	
0359449	VTGRE197-6	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0359450	VTGRE197-7	Flame	Wipe	****	0.111	108.00 ug/ft²	260000 ug/ft²	
0359451	VTGRE197-8	Flame	Wipe	****	0.111	108.00 ug/ft²	260000 ug/ft²	
0359452	VTGRE197-9	Flame	Wipe	****	0.111	108.00 ug/ft²	1500 ug/ft²	
0359453	VTGRE197-10	Flame	Wipe	****	0.111	108.00 ug/ft²	260000 ug/ft²	
0359454	VTGRE197-11	Flame	Wipe	****	0.111	108.00 ug/ft²	1900 ug/ft²	
0359455	VTGRE197-12	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	

BEST AVAILABLE COPY

BEST AVAILABLE COPY

FOIA Requested Record #J-15-0085 (V)

Released by National Guard Bureau

Page 418 of 1352

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

All rights reserved. AMA Analytical Services, Inc.

An AIHA (#8863), NVLAP (# 101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

Client: National Guard Bureau
 Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SL, State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTGRE197
 Job Location: Not Provided
 Job Number: Not Provided
 P.O. Number: 07-01

Chain Of Custody: 115805
 Date Analyzed: 8/5/2003
 Person Submitting: [Redacted]
 Report Date: 05-Aug-03

Attention: [Redacted]

Page 2 of 2

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per billion (ppb)
 %Pb = percent lead by weight ug = micrograms

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] Non-Responsive

Technical Manager: [Redacted] Non-Responsive

Client: National Guard Bureau
Address: 301-4H Old Bay Lane, Attn: NGB-AVN-SI,
 State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTGRE197
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01

Chain Of Custody: 116377
Date Analyzed: 08/18/2003
Person Submitting: [Redacted]
Report Date: 18-Aug-03

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft²)	Reporting Limit	Final Result	Comments
0363166	VTGRE197-13	Flame	Wipe	****	0.111	108.01 ug/ft²	990 ug/ft²	
0363167	VTGRE197-14	Flame	Wipe	****	0.111	108.01 ug/ft²	170 ug/ft²	
0363168	VTGRE197-15	Flame	Wipe	****	0.111	108.01 ug/ft²	210 ug/ft²	
0363169	VTGRE197-16	Flame	Wipe	****	0.111	108.01 ug/ft²	190 ug/ft²	
0363170	VTGRE197-17	Flame	Wipe	****	0.111	108.01 ug/ft²	210 ug/ft²	
0363171	VTGRE197-18	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0363172	VTGRE197-19	Flame	Wipe	****	0.111	108.01 ug/ft²	120 ug/ft²	
0363173	VTGRE197-20	Flame	Wipe	****	0.111	108.01 ug/ft²	170 ug/ft²	
0363174	VTGRE197-21	Flame	Wipe	****	0.111	108.01 ug/ft²	< 110 ug/ft²	
0363175	VTGRE197-22	Flame	Wipe	****	0.111	108.01 ug/ft²	< 110 ug/ft²	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Fumace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Non-Responsive

Non-Responsive

Analyst: [Redacted]
 Technical Manager: [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. All rights reserved. AMA Analytical Services, Inc.

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation
 Havre de Grace, Maryland 21078
Job Name: VTGRE198
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01
Chain Of Custody: 115916
Date Analyzed: 08/15/2003
Person Submitting: [Redacted]
Report Date: 15-Aug-03

Attention: [Redacted]

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (l)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0362642	VTGRE198-23	Flame	Wipe	****	0.111	108.11 ug/ft ²	< 110 ug/ft ²	
0362643	VTGRE198-24	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0362644	VTGRE198-25	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362645	VTGRE198-26	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362646	VTGRE198-27	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 160 ug/ft ²	
0362647	VTGRE198-28	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 170 ug/ft ²	
0362648	VTGRE198-29	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362649	VTGRE198-30	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0362650	VTGRE198-31	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362651	VTGRE198-32	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362652	VTGRE198-33	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362653	VTGRE198-34	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362654	VTGRE198-35	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362655	VTGRE198-36	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362656	VTGRE198-37	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0362657	VTGRE198-38	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362658	VTGRE198-39	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362659	VTGRE198-40	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362660	VTGRE198-41	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362661	VTGRE198-42	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.



CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301-HI Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation
Havre de Grace, Maryland 21078

Job Name: VTGRE198
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01

Chain Of Custody: 115916
Date Analyzed: 08/15/2003

Person Submitting: [Redacted]
Report Date: 15-Aug-03

Attention: [Redacted]

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0362662	VTGRE198-43	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362663	VTGRE198-44	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362664	VTGRE198-45	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362665	VTGRE198-46	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362666	VTGRE198-47	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362667	VTGRE198-48	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0362668	VTGRE198-49	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362669	VTGRE198-50	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362670	VTGRE198-51	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362671	VTGRE198-52	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362672	VTGRE198-53	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362673	VTGRE198-54	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0362674	VTGRE198-55	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362675	VTGRE198-56	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362676	VTGRE198-57	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362677	VTGRE198-58	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362678	VTGRE198-59	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362679	VTGRE198-60	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0362680	VTGRE198-61	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362681	VTGRE198-62	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

An AIHA (#8863), NVLAP (#101143), & New York ELAP (#10920) Accredited Laboratory

All rights reserved. AMA Analytical Services, Inc.

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301-TH Old Bay Lane, Attn: NGB-AVN-SI,
 State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTGRE198
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01

Chain Of Custody: 115916
Date Analyzed: 08/15/2003

Person Submitting: [Redacted]
Report Date: 15-Aug-03

Attention: [Redacted]

Page 3 of 3

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0362682	VTGRE198-63	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	[Redacted]

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnaces: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)
 Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted]

Technical Manager: [Redacted]

[Redacted] Non-Responsive

[Redacted] Non-Responsive



Client: National Guard Bureau Job Name: VTAAS282 Chain Of Custody: 118711
 Address: 301 IH Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation Job Location: Not Provided Date Analyzed: 10/21/2003
 Havre de Grace, Maryland 21078 Job Number: Not Provided Person Submitting: [Redacted]
 P.O. Number: 0701 Report Date: 21-Oct-03

Attention: [Redacted]

Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0402874	VTAAS282-1	Furnace	Wipe	****	0.111	2.70 ug/ft ²	22 ug/ft ²	
0402875	VTAAS282-2	Furnace	Wipe	****	0.111	13.50 ug/ft ²	78 ug/ft ²	
0402876	VTAAS282-3	Furnace	Wipe	****	0.111	13.50 ug/ft ²	52 ug/ft ²	
0402877	VTAAS282-4	Furnace	Wipe	****	0.111	2.70 ug/ft ²	18 ug/ft ²	
0402878	VTAAS282-5	Furnace	Wipe	****	0.111	33.75 ug/ft ²	150 ug/ft ²	
0402879	VTAAS282-6	Furnace	Wipe Blank	****	N/A	0.30 ug	0.55 ug	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-311B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per million (ppm)

%Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] Technical Manager: [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. All rights reserved. AMA Analytical Services, Inc.



Submitted To: **Non-Responsive**
Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTCAM205-A1 through VTAAS204-A3
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Filter
Method Reference:	NIOSH 7300
DCL Set ID No.:	03-S-3621
DCL Sample ID No.:	03-22309 through 03-22345
Sample Receipt Date:	7/28/2003
Preparation Date:	07/29/03
Analysis Date:	07/31/03

The samples were prepared and analyzed in accordance with NIOSH method 7300 using a Perkin Elmer 3000XL ICP.

The sample condition upon receipt was acceptable except where noted.

The results are in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive

Analyst

Non-Responsive

Reviewer

CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 280-8071, FAX 415 893-9469

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTCAM205-A1	03-22309	407.54	ND	<0.002
VTCAM205-A2	03-22310	377.66	ND	<0.003
VTCAM205-A3	03-22311	0	ND	-
VTWIN202-A1	03-22313	152.91	ND	<0.007
VTWIN202-A2	03-22314	0	ND	-
VTENO196-A1	03-22316	150.55	ND	<0.007
VTENO196-A2	03-22317	0	ND	-
VTWIL197-A1	03-22319	199.78	ND	<0.005
	Prep Blank 1		ND	
% Recovery	LCS 1		96.	
% Recovery	LCS 2		96.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).
 LCS = laboratory control sample.

Non-Responsive



Analyst

Non-Responsive



Reviewer

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTWIL197-A2	03-22320	149.76	ND	<0.007
VTWIL197-A3	03-22321	0	ND	-
VTSWA196-A1	03-22322	149.24	ND	<0.007
VTSWA196-A2	03-22323	0	ND	-
VTSTA196-A1	03-22324	165.20	ND	<0.006
VTSTA196-A2	03-22325	151.74	ND	<0.007
VTSTA196-A3	03-22326	0	ND	-
VTWAT203-A1	03-22328	194.90	ND	<0.005
VTWAT203-A2	03-22329	0	ND	-
VTGOS202-A1	03-22332	175.30	ND	<0.006
VTGOS202-A2	03-22333	0	ND	-
VTMOR203-A1	03-22335	346.43	ND	<0.003
VTMOR203-A2	03-22336	348.65	ND	<0.003
VTMOR203-A3	03-22337	0	ND	-
VTGRE197-A1	03-22340	240.55	ND	<0.004
VTGRE197-A2	03-22341	250.76	ND	<0.004
VTGRE197-A3	03-22342	0	ND	-
VTAAS209-A1	03-22343	748.92	ND	<0.001
VTAAS209-A2	03-22344	507.55	ND	<0.002
VTAAS209-A3	03-22345	0	ND	-
	Prep Blank 2		ND	
% Recovery	LCS 3		96.	
% Recovery	LCS 4		95.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).
LCS = laboratory control sample.

Non-Responsive



Analyst

Non-Responsive



Industrial Hygiene Sampling Calculation Worksheet

National Guard Armory Location: GRE
 Date: 197

Sample 1

Sample Number: VTGRE197-A1

Pump: 648339

Pre Flow Rate	Post Flow Rate
---------------	----------------

2.512	2.446
-------	-------

2.509	2.458
-------	-------

2.507	2.449
-------	-------

2.502	2.456
-------	-------

Average	2.508	2.452
----------------	--------------	--------------

Average Pre and Post	2.4799
-----------------------------	---------------

Time 1	13:43
--------	-------

Time 2	15:20
--------	-------

Total Time Sampled	1:37
---------------------------	-------------

Minutes Sampled	97.00
------------------------	--------------

Volume	240.55 Liters
---------------	----------------------

Sample 2

Sample Number: VTGRE197-A2

Pump: 647615

Pre Flow Rate	Post Flow Rate
---------------	----------------

2.544	2.475
-------	-------

2.539	2.483
-------	-------

2.541	2.478
-------	-------

2.534	2.467
-------	-------

Average	2.540	2.476
----------------	--------------	--------------

Average Pre and Post	2.5076
-----------------------------	---------------

Time 1	13:57
--------	-------

Time 2	15:37
--------	-------

Total Time Sampled	1:40
---------------------------	-------------

Minutes Sampled	100.00
------------------------	---------------

Volume	250.76 Liters
---------------	----------------------

Appendix D

References

References

Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration (current edition)

American Society of Heating, Refrigerating and Air-Conditioning Engineers, Inc (ASHRAE) 62-2002, Ventilation for Acceptable Indoor Air Quality

Instructions for Completing the Sampling of Army National Guard Armories, Lead Wipe Sampling Procedure included with the Request for Proposal

Air Sampling for Lead - Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods

Design Guide DG-415-2, Logistics Facilities, National Guard Bureau Installation Division, 14 December 1999

Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998

Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, 15 October 1990

AR 385-10, The Army Safety Program, 29 February 2000

Department of the Army Pamphlet (DA PAM) 40-501, Medical Services, Hearing Conservation Program, 10 December 1998

DA PAM 40-503, Medical Services, Industrial Hygiene Program, 30 October 2000

Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH) (current edition)

Guidelines for Converting Indoor Firing Ranges to Other Uses, Headquarters, Department of the Army and the Air Force, NG PAM (AR) 385-16/ANGPAM 91-101, 31 January 1994

24 CFR, Part 35, Subpart B, Section 35-110, Definition of Lead-Based Paint, Housing and Urban Development, U. S. Department of Housing

Appendix E
Recommendations for
Surface Lead Dust in Armories

Subject: Recommendations for Surface Lead Dust in Armories

1. In armories that do not contain childcare facilities, the National Guard Bureau (NGB) Region North Industrial Hygiene Office recommends cleaning the areas in which sample results are greater than 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$). If a special function will be held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function. This guidance is based on professional judgment, risk assessments, adaptation of Occupational Safety and Health Administration (OSHA) guidance, and feasibility of cleaning to a certain level.

a. Environmental Protection Agency (EPA) standards (40 Code of Federal Regulations (CFR) 745.227(h)(3)) are not directly applicable because they are criteria for dust-lead hazards developed for floors ($40 \mu\text{g}/\text{ft}^2$) and windowsills ($250 \mu\text{g}/\text{ft}^2$) in residential dwellings and child occupied facilities. A child occupied facility is defined as a building, or portion of a building, constructed prior to 1978, visited regularly by the same child, 6 years of age or under, on at least two different days within any week (Sunday through Saturday period), provided that each day's visit lasts at least 3 hours and the combined weekly visit lasts at least 6 hours, and the combined annual visits last at least 60 hours. Most of the wipe samples in armories were collected in undisturbed areas and therefore, results are worst case scenarios and do not correlate to these standards.

b. OSHA has no specific requirement for work area surfaces. The lead standard (29 CFR 1910.1025(h)) states that all surfaces shall be maintained as free as practicable of accumulations of lead dust. In workplaces where lead dust is generated, surface levels may be much higher, but personnel exposures can be controlled by limiting airborne lead levels and following good cleanup and hygienic practices.

c. OSHA used to cite a level of $200 \mu\text{g}/\text{ft}^2$ in their Technical Manual and 29 CFR 1926.62 as guidance to its own inspectors for evaluating the cleanliness of lunchroom and locker room surfaces that are supposed to be kept as clean as possible.

d. In a report titled Derivation of Wipe Surface Screening Levels for Environmental Chemicals, the US Army Center for Health Promotion and Preventive Medicine (USACHPPM) has determined that $200 \mu\text{g}/\text{ft}^2$ is a safe surface contamination level. They have also applied these standards as the decontamination levels for surfaces in administrative offices.

e. It should be noted that levels above these recommendations do not necessarily mean there is a significant hazard to workers who are following good cleaning and hygienic practices since there is no correlation between wipe and air samples. Rather, we recommend these levels as a precautionary measure.

2. The NGB Occupational Health Branch is developing guidance for armories that are used as childcare facilities. All states will receive this guidance when it is completed. In the interim, we recommend the following actions:

a. Clean all areas that will be accessible to children to the EPA dust-lead standard for children 6 years of age or under ($40 \mu\text{g}/\text{ft}^2$ on floors and $250 \mu\text{g}/\text{ft}^2$ on windowsills).

b. Refer to the local authorities' regulations since they can be more stringent than federal regulations.

c. Post signs in the area to inform people of the presence of lead dust and its effects.

d. If soldiers clean weapons in the facility change the policy so that they cannot clean their weapons in the facility, or if they are allowed to clean their weapons indoors, they must clean the area by wet wiping and mopping the area when they are done.

e. If the paint is peeling, contact the state Environmental Office to test for lead content and provide recommendations.

3. Air samples collected on individuals in the armory were well below OSHA's permissible exposure limit for lead (29 CFR 1910.1025(e)) of $0.05 \text{ mg}/\text{m}^3$ averaged over an 8-hour day. Therefore, based on these conditions there is currently no overexposure to personnel from lead dust in this building.

Industrial Hygiene Survey

Vermont Army National Guard (VT ARNG)

Prepared For: NGB ARNG– Region North IH Office

Survey Location:

Green Mountain Readiness Center
789 Vermont National Guard Road
Colchester, VT 05446

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 21, 2011

AEI Project #: J11-601 4L VT Green Mountain RC

Non-Responsive CIH, CSP
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Green Mountain Readiness Center**

Table of Contents

Executive Summary ii

1 Introduction 1

2 Evaluation Methods 1

3 Operations 1

4 Noise Hazards 1

5 Hazard Controls 2

Ventilation Systems 2

6 Physical Condition of the Facility and Personnel Concerns 2

Paint Chip and Dust Wipe Samples for Lead Contamination 2

Visual Inspection for Damaged Asbestos-Containing Materials 4

Visual Inspection for Water Damage and Mold Growth 4

Visual Inspection for Housekeeping Concerns 4

Lighting 4

Indoor Air Quality (IAQ) 4

Temperature and Relative Humidity 5

Carbon Dioxide (CO₂) and Carbon Monoxide (CO) 5

7 Conclusions 5

8 Limitations 6

List of Tables and Appendices

Table 1 - Results of Dust Wipe Sampling for the VT ARNG Green Mountain Readiness Center on October 21, 2011.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

Appendix A – Building Layout

Appendix B – Certificates of Analysis for Air, Dust Wipe and Bulk Samples

Appendix C – Photo Documentation

Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Green Mountain Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Green Mountain Readiness Center located at 789 Vermont National Guard Road, Colchester, VT 05446. Non-Responsive, CIH, CSP performed the evaluation on October 21, 2011. The point of contact for the facility was Non-Responsive" Non-Responsive, the caretaker for the readiness center. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Paint Chip and Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. No peeling paint was observed in the facility. The former firing range was being renovated and layers of old paint were exposed when some boards were removed. The lead check test kit was used to test this layer and found to be positive for lead. The readiness center caretaker called an immediate meeting with the construction contractor and the environmental compliance manager, Ms. Lee Ann Banks, to discuss lead-based paint and dust in the room. It was determined that records of lead testing during and after the conversion of the firing range were available and measures were being taken to control lead dust hazards during the renovation. The firing range had been converted approximately one year ago but had not been used in many years. Results of dust wipe samples taken throughout the facility were below the recommended maximum criterion for surface contamination of lead (200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$)) in all areas sampled except for two samples collected from the floor in the former firing range (2,000 – 3,100 $\mu\text{g}/\text{ft}^2$). The recent renovation activities in the former firing range may have disturbed lead-containing dust from building materials that had remained after the conversion.

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there were any suspect asbestos-containing material and its condition. Damaged insulation was observed in the boiler room, and damaged floor tiles were observed in Room 233 that was under renovation. Bulk samples containing layers of insulation and pipe wrap from the boiler room were analyzed, and no asbestos was detected in any layer. No asbestos was detected in the floor tile or mastic samples from Room 233.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. Occasional roof leaks were reported by the caretaker, and a moldy ceiling tile was observed in Room E234.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping was good. Most areas were clean and tidy.

Lighting: A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in several areas. Light fixtures were installed too far apart so that light was deficient in between fixtures in some rooms and most hallways. The illumination measurements indoors ranged from 1.7 foot candles (fc) to 168 fc.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Green Mountain Readiness Center**

Indoor Air Quality: Temperature and relative humidity measurements were mostly within the comfort ranges for the winter season on the day of the survey. The outdoor temperature and relative humidity were 58.6° F and 47.3% on the day of monitoring. Indoor concentrations of carbon dioxide (CO₂) and carbon monoxide (CO) were below the guidelines in all areas.

Emergency Eyewash and Shower Maintenance: Plumbed emergency eyewash stations located on sink faucets in the medical department were not being inspected and flushed on a weekly basis in accordance with ANSI Z358.1-2009. Weekly flushing and a general cleaning of the fountains are recommended. An inspection tag or list should be posted nearby to record the weekly flushing.

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updated MSDSs are required per OSHA 29 CFR 1910.1200. It is recommended that a copy of the written hazard communication program be placed in every MSDS notebook. This is a large readiness center with several departments with a variety of chemical products including those for maintenance, medical, and kitchen cleaning supplies. MSDSs should be stored near the chemical products and in a central location where they can be accessed at any time. Bleach was being stored next to an ammoniated product in the kitchen. This issue was reported immediately and the products were separated.

Overall, the Green Mountain Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Green Mountain Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Green Mountain Readiness Center located at 789 Vermont National Guard Road, Colchester, VT 05446. Non-Responsive, CIH, CSP performed the evaluation on October 21, 2011. The point of contact for the facility was Non-Responsive" Non-Responsive the caretaker for the readiness center. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

The 76,800 square foot, Green Mountain Readiness Center was built in 1989. The operations conducted at the facility include supply, administrative and military medical duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the Green Mountain Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the Green Mountain facility consist of supply and administrative duties in addition to military medical exams and some medical laboratory tasks. No maintenance of vehicles or other physical tasks are performed at the facility. Ground maintenance and upkeep of the building are the responsibility of the state employed Armorer and not part of the duties of National Guard personnel.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Green Mountain Readiness Center**

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility.

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for water damage or mold problems; potential ergonomic problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were taken in select areas.

Paint Chip and Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. No peeling paint was observed. The former firing range was being renovated and layers of old paint were exposed when some boards were removed. The lead check test kit was used to test this layer and found to be positive for lead. The readiness center caretaker called an immediate meeting with the construction contractor and the environmental compliance manager, Ms. Lee Ann Banks, to discuss lead-based paint and dust in the room. It was determined that records of lead testing during and after the conversion of the firing range were available and measures were being taken to control lead dust hazards during the renovation. The firing range had been converted approximately one year ago but had not been used in many years.

To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected using ghost wipes and 10 centimeter (cm) x 10cm templates. The Environmental Protection Agency (EPA) and the Commonwealth of Pennsylvania limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. All wipe samples collected from the facility were below the recommended maximum except for the two samples collected from the floor in the former firing range (2,000 – 3,100 $\mu\text{g}/\text{ft}^2$). The recent renovation activities in the former firing range may have disturbed lead-containing dust from building materials that had remained after the conversion. Results are given in Table 1 and certificates of analysis are included in Appendix B.

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
Green Mountain Readiness Center on October 21, 2011.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
GMA – 01	Foyer – floor	<110
GMA – 02	Drill Hall – floor	<110
GMA – 03	Drill Hall – metal safe	<110
GMA – 04	Drill Hall – exercise mats	<110

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Green Mountain Readiness Center**

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
Green Mountain Readiness Center on October 21, 2011.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
GMA – 05	Drill Hall – vending machine	160
GMA – 06	Drill Hall – serving counter	<110
GMA – 07	Kitchen – mixer	<110
GMA – 08	Kitchen – stove	<110
GMA – 09	Hallway – floor	<110
GMA – 10	Maintenance Shop – work bench	150
GMA – 11	Maintenance Shop – floor	<110
GMA – 12	Former Firing Range – bullet trap floor	3,100
GMA – 13	Former Firing Range – floor in center	2,000
GMA – 14	Room E259 – floor	<110
GMA – 15	Room E260 – floor	<110
GMA – 16	Room E256 – exam chair	<110
GMA – 17	Room E251A – floor	<110
GMA – 18	Room E260 – counter	<110
GMA – 19	Hallway – floor	<110
GMA – 20	Hallway – water fountain	<110
GMA – 21	Conference Room – shelf	<110
GMA – 22	Room E203 – window sill	<110
GMA – 23	Room E203 – floor	<110
GMA – 24	Room E222 – counter	<110
GMA – 25	Room C101 – floor	<110
GMA – 26	Hallway – water fountain	<110
GMA – 27	Band Rehearsal Room – table	<110
GMA – 28	Band Rehearsal Room – storage locker	<110
GMA – 29	Room A129A – water fountain	<110
GMA - 30	Room A124 – floor	<110

*The recommended maximum level for adult exposures is 200 $\mu\text{g}/\text{ft}^2$ lead on surfaces.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Green Mountain Readiness Center**

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). Damaged insulation was observed in the boiler room and damaged floor tiles were observed in Room 233 that was under renovation. Bulk samples containing layers of insulation and pipe wrap from the boiler room and a floor tile and mastic sample from room E233 were submitted to AMA Analytical Services, Inc. of Lanham, MD 20706 (NIST-NVLAP Accreditation No. 101143-0) for analysis by Polarized Light Microscopy (PLM). No asbestos was detected in any sample.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. The caretaker reported occasional roof leaks, and a moldy ceiling tile was observed in Room E234.

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping was good. Most areas were clean and tidy.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on March 9, 2011, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in several areas. Light fixtures were installed too far apart so that light was deficient in between fixtures in some rooms and most hallways. The illumination measurements indoors ranged from 1.7 foot candles (fc) to 168 fc. The complete results of the evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Plus Model 8554, factory calibrated in February, 2011. Temperature, relative humidity and carbon dioxide (CO₂) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 2. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30 and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Green Mountain Readiness Center**

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 66.8 to 73.3° F and 41.9 to 48.9% Rh. Temperatures and relative humidity were mostly within the winter comfort ranges in the areas monitored. The outdoor temperature and relative humidity was 58.6° F and 47.3% on the day of monitoring.

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1–2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 518 to 813 parts per million (ppm). CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange.

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 0.4 to 1.2 ppm; therefore, concentrations are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

Additional Information

Emergency Eyewash and Shower Maintenance: Plumbed emergency eyewash stations located on sink faucets in the medical department were not being inspected and flushed on a weekly basis in accordance with ANSI Z358.1-2009. Weekly flushing and a general cleaning of the fountains are recommended. An inspection tag or list should be posted nearby to record the weekly flushing.

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updated MSDSs are required per OSHA 29 CFR 1910.1200. It is recommended that a copy of the written hazard communication program be placed in every MSDS notebook. This is a large readiness center with several departments with a variety of chemical products including those for maintenance, medical, and kitchen cleaning supplies. MSDSs should be stored near the chemical products and in a central location where they can be accessed at any time. Bleach was being stored next to an ammoniated product in the kitchen. This issue was reported immediately and the products were separated.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Green Mountain Readiness Center**

7 Conclusions

The results of the evaluation indicated no concerns with the following at the facility: contamination of clean air sources, peeling potentially lead-based paints, noise hazards, the presence of damaged asbestos-containing materials and housekeeping. The results of the evaluation indicated industrial hygiene concerns in the following areas: accumulated lead-containing dust in the former firing range, a moldy ceiling tile in one room, lighting, hazard communication and MSDS updates and eyewash station maintenance. Overall, the Green Mountain Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.


9 References

1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.
3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.
4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.
5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2011.
6. Army Regulation (AR) 420-70 Buildings and Structures, 10 October 1997.
7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 28 March 2009.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Green Mountain Readiness Center**

8. Army Regulation (AR) 420-1 Army Facilities Management, 28 March 2009.
9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.
10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.
12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.
13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".
15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.


Appendix A Building Layout



115'5"

First Floor

1" = 30'



GMA Second Floor

1" = 20'

Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	Green Mountain Army	Chain Of Custody:	511726
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Colchester, VT	Date Submitted:	11/1/2011
Attention:	Non-Responsive	Job Number:	J11-601	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/5/2011
				Report Date:	11/7/2011

Summary of Atomic Absorption Analysis for Lead

Page 1 of 3

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
12010483	GMA-01	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010484	GMA-02	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010485	GMA-03	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010486	GMA-04	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010487	GMA-05	Flame	Wipe	****	0.108	110 ug/ft ²	17	160 ug/ft ²	
12010488	GMA-06	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010489	GMA-07	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010490	GMA-08	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010491	GMA-09	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010492	GMA-10	Flame	Wipe	****	0.108	110 ug/ft ²	16	150 ug/ft ²	
12010493	GMA-11	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010494	GMA-12	Flame	Wipe	****	0.108	110 ug/ft ²	340	3100 ug/ft ²	
12010495	GMA-13	Flame	Wipe	****	0.108	110 ug/ft ²	210	2000 ug/ft ²	
12010496	GMA-14	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010497	GMA-15	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010498	GMA-16	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010499	GMA-17	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010500	GMA-18	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010501	GMA-19	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	Green Mountain Armory	Chain Of Custody:	511726
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Colchester, VT	Date Submitted:	11/1/2011
Attention:	Non-Responsive	Job Number:	J11-601	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/5/2011
				Report Date:	11/7/2011

Summary of Atomic Absorption Analysis for Lead

Page 2 of 3

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
12010502	GMA-20	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010503	GMA-21	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010504	GMA-22	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010505	GMA-23	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010506	GMA-24	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010507	GMA-25	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010508	GMA-26	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010509	GMA-27	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010510	GMA-28	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010511	GMA-29	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010512	GMA-30	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	Green Mountain Armory	Chain Of Custody:	511726
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Colchester, VT	Date Submitted:	11/1/2011
Attention:	Non-Responsive	Job Number:	J11-601	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/5/2011
				Report Date:	11/7/2011

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	----------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm)
 %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb)

See QC Summary for analytical results of quality control samples associated with these samples.

Note: All samples were received in good condition unless otherwise noted.
 Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Air and Wipe results are not corrected for any blank results
 Final results for air and wipe samples are based on client supplied information nor verified by this laboratory.

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Non-Responsive

Non-Responsive

Technical Manager:

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS

Client:	National Guard Bureau	Job Name:	Green Mountain Armory	Chain Of Custody:	511726
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Colchester, VT	Date Analyzed:	11/8/2011
		Job Number:	J11-601	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003		

Attention: Non-Responsive

Summary of Polarized Light Microscopy

AMA Sample Number	Client Sample #	Total Asbestos	Chrysotile Percent	Amosite Percent	Crocidolite Percent	Other Asbestos Percent	Mineral Wool Percent	Fiberglass Percent	Organic Percent	Synthetic Percent	Other Percent	Particulate Percent	Sample Type	Sample Color	Homogeneity	Analyst ID	Comments
12010480	GMA-Bik-01	NAD	--	--	--	--	--	--	--	5	--	95	TSI	White	Homogeneous	PC	
12010481	GMA-Bik-02	NAD	--	--	--	--	25	5	--	--	--	70	Fitting	Gray	Homogeneous	PC	
12010482	GMA-Bik-03	NAD	--	--	--	--	--	--	--	--	--	100	FT	Multi	Homogeneous	PC	
12010685	GMA-Bik-03 M	NAD	--	--	--	--	--	--	TR	--	--	100	MS	Yellow	Homogeneous	PC	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS

Client:	National Guard Bureau	Job Name:	Green Mountain Armory	Chain Of Custody:	511726
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Colchester, VT	Date Analyzed:	11/8/2011
Attention:	Non-Responsive	Job Number:	J11-601	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003		

Summary of Polarized Light Microscopy

AMA Sample Number	Client Sample #	Total Asbestos	Chrysofile Percent	Amosite Percent	Crocidolite Percent	Other Asbestos Percent	Mineral Wool Percent	Fiberglass Percent	Organic Percent	Synthetic Percent	Other Percent	Particulate Percent	Sample Type	Sample Color	Homogeneity	Analyst ID	Comments
-------------------	-----------------	----------------	--------------------	-----------------	---------------------	------------------------	----------------------	--------------------	-----------------	-------------------	---------------	---------------------	-------------	--------------	-------------	------------	----------

The following footnotes only apply to those samples which the total asbestos result is flagged with a note number.

- 1 TEM RECOMMENDATION** - Please note, due to resolution limitations with optical microscopy and/or interference from matrix components of this sample, results which are reported via PLM as negative or trace (<1%) for asbestos may contain a significant quantity of asbestos. It is recommended that the additional analytical technique of TEM be used to check for asbestos fibers below the resolution limits of optical microscopy.
- 2 MATRIX REDUCTION RECOMMENDATION** - Please note, due to interference from the matrix components of this sample, results which are reported via PLM as negative or trace (<1%) for asbestos may contain a significant quantity of asbestos which is obscured from view. It is recommended that the additional preparation technique of gravimetric reduction be performed on this sample to minimize the obscuring effects of matrix components, followed by reanalysis by PLM and/or TEM.

Analysis Method - EPA/600/R-93/116 dated July 1993

NAD = "No Asbestos Detected" TR = "Trace equals less than 1% of this component"

Uncertainty: For samples containing asbestos in range of 1-10% the CV is 0.43, 11-35% CV=0.55, >35 CV=0.23

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Technical Director

Non-Responsive

Analyst(s)

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



AMA Analytical Services, Inc.

Focused on Results www.amalab.com
AIHA (#100470) NVLAP (#101143-0) NY ELAP (10920)
4475 Forbes Blvd. • Lanham, MD 20706
(301) 459-2640 • (800) 346-0961 • Fax (301) 459-2643

CHAIN OF CUSTODY

(Please Refer To This Number For Inquiries)

511726

page 1 of 3

Mailing/Billing Information:

- Client Name: National Guard Bureau
- Address 1: 301-H Old Bay Lane
- Address 2: Attn: NGB-AVN-SI, State Military Reservation
- Address 3: Havre de Grace, Maryland 21078
- Phone #: (410) 942-0273 Fax #: (410) 942-0254

Submittal Information:

- Job Name: Green Mountain Armory
- Job Location: Colchester, VT
- Job #: 11-001 NO. WB12K6-09-A-0003
- Contact Person: Non-Responsive @ (410) 942-0273
- Submitted By: Non-Responsive Signature: Non-Responsive

Reporting Information (Results will be provided as soon as technically feasible):

AFTER HOURS (must be pre-scheduled)		NORMAL BUSINESS HOURS		REPORT TO:	
<input type="checkbox"/> Immediate Date Due: _____	<input type="checkbox"/> 24 Hours Time Due: _____	<input type="checkbox"/> Immediate	<input type="checkbox"/> 3 Day	<input type="checkbox"/> Include COC/MS/MSR with Report	ariaenviro.com us.army.mil us.army.mil
Comments: _____		<input type="checkbox"/> Next Day	<input type="checkbox"/> 5 Day + Date Due: <u>11/8/11</u>	<input type="checkbox"/> Results Required By Noon (Every Attempt Will Be Made to Accommodate)	
		<input type="checkbox"/> 2 Day		<input type="checkbox"/> Fax: _____ <input type="checkbox"/> Verbo: _____	

Asbestos Analysis

- PCM Air** - Please Indicate Filter Type:
- NIOSH 7400 (QTY)
 - Fiberglass (QTY)
- TEM Air** - Please Indicate Filter Type:
- AHERA (QTY)
 - NIOSH 7402 (QTY)
 - Other (specify) _____ (QTY)
- PLM Bulk**
- EPA 600 - Visual Estimate 2 (QTY)
 - EPA Point Count (QTY)
 - NY State Friable 198.1 (QTY)
 - Grav. Reduction ELAP 198.6 (QTY)
 - Other (specify) _____ (QTY)

TEM Bulk

- ELAP 198.4/Charfield (QTY)
- NY State PLM/TEM (QTY)
- Residual Ash (QTY)

TEM Dust

- Qual. (pres/abs) Vacuum/Dust (QTY)
- Quan. (s/area) Vacuum D5735-95 (QTY)
- Quan. (s/area) Dust D6490-99 (QTY)

TEM Water

- Qual. (pres/abs) (QTY)
- ELAP 198.2/EPA 100.2 (QTY)
- EPA 100.1 (QTY)

All samples received in good condition unless otherwise noted.
(TEM Water samples _____ °C)

- Spore Analysis**
- Pb Paint Chip (QTY) ghost
 - Pb Dust Wipe (wipe type 10X/Gen) 10 (QTY) (30 total)
 - Pb Air (QTY)
 - Pb Soil/Solid (QTY)
 - Pb TCLP (QTY)
 - Drinking Water Pb (QTY) Cu (QTY) As (QTY)
 - Waste Water Pb (QTY) Cu (QTY) As (QTY)
 - Pb Furnace (Media _____) (QTY)

- Collection Apparatus for Spore Trap/Air Samples: _____
Collection Media _____
- Spore-Trap (QTY)
 - Surface Vacuum Dust (QTY)
 - Surface Swab (QTY)
 - Surface Tape (QTY)
 - Other (Specify) _____ (QTY)
 - Culturable ID Genus (Media _____) (QTY)
 - Culturable ID Species (Media _____) (QTY)

CLIENT ID NUMBER	SAMPLE INFORMATION		VOLUME (LITERS)	WIPE AREA	ANALYSIS										CLIENT CONTACT		
	SAMPLE LOCATION/ IDENTIFICATION	DATE			ITEM	PCM	PLM	LEAD	MOLD	AIR	BULK	DUST	WATER	SPORE TRAP	TAPE	SWAB	(LABORATORY STAFF ONLY)
GMA-blk-01	GMA bulk	10/21															Date/Time: 11/3/11 Contact: JB By: NDM
GMA-blk-02	"	"															Sample # GMA-blk-03 Submitted but not listed on COC.
GMA-01	11 wipe			10x10													Date/Time: 11/3 Contact: NDM By: JB
GMA-02	"	"															
GMA-03	"	"															
GMA-04	"	"															
GMA-05	"	"															
GMA-06	"	"															
GMA-07	"	"															
GMA-08	"	"															
GMA-09	"	"															
GMA-10	"	"															

LABORATORY STAFF ONLY: (CUSTODY)

- Date/Time RCVD: 11/1/11 @ 015 Via: FedEx By (Print): Non-Responsive Sign: _____
- Date/Time Analyzed: _____ / _____ / _____ @ _____ By (Print): _____ Sign: _____
- Results Reported To: _____ Via: _____ Date: _____ / _____ / _____ Time: _____ Initials: _____
- Comments: 1952 1173 2377



AMA Analytical Services, Inc.
Focused on Results www.amalab.com
AIHA (#100470) NVLAP (#101143-0) NY ELAP (10920)
4475 Forbes Blvd. • Lanham, MD 20706
(301) 459-2640 • (800) 346-0961 • Fax (301) 459-2643

CHAIN OF CUSTODY

(Please Refer To This Number For Inquiries)

5117ab

P2/B

Mailing/Billing Information:

- 1. Client Name: National Guard Bureau
2. Address 1: 301-JH Old Bay Lane
3. Address 2: Attn: NGB-AVN-SI, State Military Reservation
4. Address 3: Havre de Grace, Maryland 21078
5. Phone #: (410) 942-0273 Fax #: (410) 942-0254

Submission Information:

- 1. Job Name: Green Mountain Armory
2. Job Location: Colchester, VT
3. Job #: TN-601 # W912K6-09-A-0003
4. Contact Person: Non-Responsive
5. Submitted by: Non-Responsive

Reporting Information (Results will be provided as soon as technically feasible)

Form with sections: AFTER HOURS (must be pre-scheduled), NORMAL BUSINESS HOURS, REPORT TO: (Include COC Field Data Sheet with Report)

Asbestos Analysis

- ECM Air - Please Indicate Filter Type:
- NIOSH 7400 (QTY)
- Fiberglass (QTY)
TEM Air - Please Indicate Filter Type:
- AHJRA (QTY)
- NIOSH 7402 (QTY)
- Other (specify) (QTY)
ELM Bulk
- EPA 600 - Visual Estimate (QTY)
- EPA Point Count (QTY)
- NY State Friable 198.1 (QTY)
- Grav. Reduction ELAP 198.6 (QTY)
- Other (specify) (QTY)

TEM Bulk

- ELAP 198.4/Chatfield (QTY)
NY State PLM/TEM (QTY)
Residual Ash (QTY)

TEM Dust

- Qual. (pres/abs) Vacuum/Dust (QTY)
Quan. (s/area) Vacuum DS755-95 (QTY)
Quan. (s/area) Dust D6480-99 (QTY)

TEM Water

- Qual. (pres/abs) (QTY)
ELAP 198.2/EPA 100.2 (QTY)
EPA 100.1 (QTY)

Miscellaneous

- Pb Paint Chip (QTY)
Pb Dust Wipe (wipe type 10x10) 12 (QTY) (30 total)
Pb Air (QTY)
Pb Sol/Solid (QTY)
Pb TCLP (QTY)
Drinking Water Pb (QTY) Cu (QTY) As (QTY)
Waste Water Pb (QTY) Cu (QTY) As (QTY)
Pb Furnace (Media) (QTY)

MISC

- Vermiculite
Asbestos Soil PLM (Qual) PLM (Quan) PLM/TEM (Qual) PLM/TEM (Quan)

All samples received in good condition unless otherwise noted, (TEM Water samples: °C)

Table with columns: CLIENT ID NUMBER, SAMPLE INFORMATION, VOLUME, WIPES AREA, ANALYSIS (TEM, PCM, PLM, LEAD, MOLD, AIR, BULK, DUST, WATER, SWAB), CLIENT CONTACT (LABORATORY STAFF ONLY)

LABORATORY STAFF ONLY: (CUSTODY)

- 1. Date/Time RCVD: @ Via: By (Print): Sign:
2. Date/Time Analyzed: @ By (Print): Sign:
3. Results Reported To: Via: Date: Time: Initials:
4. Comments:

Appendix C Photo Documentation

Green Mountain, VT Readiness Center



Front Lobby



Front Lobby



Front Lobby



Kitchen

Green Mountain, VT Readiness Center



Incorrect storage of chemical products in kitchen



Hallway



Maintenance Office

Posted to NGB FOIA Reading Room
May, 2018



Drill Hall

Green Mountain, VT Readiness Center



Drill Hall



Drill Hall



Boiler Room – damaged insulation



Boiler Room

Green Mountain, VT Readiness Center



Kitchen Storage



Kitchen Storage



Former Firing Range under renovation
Posted to NGB FOIA Reading Room
May, 2018



Former Firing Range

Green Mountain, VT Readiness Center



Eyewash station in Medical Department



Medical Laboratory



Medical Exam Room



Another Eyewash Station

Green Mountain, VT Readiness Center



Dental Room with Xray



Conference Room



Conference Room



Hallway

Green Mountain, VT Readiness Center




Break room with server in back



Coffee station in an electrical room



Band practice room



Water Damage on Suspended Ceiling Tiles in Band Room

Green Mountain, VT Readiness Center



Musical Instrument Storage

Appendix D
IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Colchester	IAQ								Light		
Date	10/21/2011	Inspector	Non-Responsive	Instrument	Q-trak 7565-X								Instrument	Cal-Light 400
Facility Description	Green Mountain Armory (GMA)			Serial Number	7565X0839020								Serial Number	K070003
Weather Conditions	Cold, Damp, Cloudy			Last Calibration	Feb-11								Last Calibration	9-Mar-11
Location/Function		No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
Foyer		2	9:12	66.8	X	46.8		530		0.7		10-83		10
Hallway to Drill Hall		1	9:18									2.3-36	X	5
Drill Hall		1	9:20	68.9		48.9		518		1.0		38-65		30-50
Maintenance Room		1	9:59	70.5		47.2		558		0.4		40-60		30-50
Mechanical Room		2	10:02									35-68		30
Locker Room		1	10:08									10-62		7
Supply Room		2	10:09									1.7	X	30
Boiler Room	B114	2	10:26									3-41	X	30
Kitchen Office	B119	2	10:35									2-10	X	30-50
Medical Waiting Room		1	11:16	70.2		42.4		588		0.8		11-45	X	30-50
Med Lab	E260	1	11:18									45-120		30-50
Med Exam Room	E259	1	11:20									50-120		30-50
Dental Xray Room	E256	1	11:28									50-126		30-50
Eye Exam Room	E258	1	11:40									98-168		30-50
Hallway to Exam Rooms		1	11:47									2-57	X	5
Hallway to E235		1	12:15	70.6		45.1		687		0.7		17-30		5
Med Office	E238	8	12:17	71.2		45.2		813		0.8		50-90		30-50
Conference Room	E228	1	12:36	73.3		43.5		638		0.7		35-103		30-50
Stairway		1										10-30		5
Chapel		1										15-35	X	30
Hall near E213		1	12:44									10-49		5
Hall Near E203		1	12:51	72.6		41.9		645		1.2		10-43		5
Office	E203	3										60-132		30-50
Office	E207											60-90		30-50
Office	E213											32-100		30-50
Conference Room	E215B											30-75		30-50

Industrial Hygiene Survey

Vermont Army National Guard (VTARNG)

Prepared For: NGB ARNG– Region North IH Office

Survey Location:

Green Mountain Readiness Center
789 Vermont National Guard Road
Colchester, VT 05446

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 19, 2012

AEI Project #: J12-685 3m VT Green Mountain RC

Non-Responsive, CIH, CSP
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Green Mountain Readiness Center**

Table of Contents

Executive Summary ii

1 Introduction 1

2 Evaluation Methods 1

3 Operations 1

4 Noise Hazards 1

5 Hazard Controls 2

Ventilation Systems 2

6 Physical Condition of the Facility and Personnel Concerns 2

Paint Chip and Dust Wipe Samples for Lead Contamination 2

Visual Inspection for Damaged Asbestos-Containing Materials 3

Visual Inspection for Water Damage and Mold Growth 3

Visual Inspection for Housekeeping Concerns 3

Lighting 3

Indoor Air Quality (IAQ) 4

Temperature and Relative Humidity 4

Carbon Dioxide (CO₂) and Carbon Monoxide (CO) 4

7 Conclusions 5

8 Limitations 5

List of Tables and Appendices

Table 1 - Results of Dust Wipe Sampling for the VTARNG Green Mountain Readiness Center on October 19, 2012.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

Appendix A – Building Layout

Appendix B – Certificates of Analysis for Air, Dust Wipe and Bulk Samples

Appendix C – Photo Documentation

Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Green Mountain Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VTARNG) Green Mountain Readiness Center located at 789 Vermont National Guard Road, Colchester, VT 05446 Non-Responsive. CIH, CSP performed the evaluation on October 19, 2012. The point of contact for the facility was LTC Non-Responsive. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Paint Chip and Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. No peeling paint was observed in the facility. Results of dust wipe samples taken throughout the facility were below the recommended maximum criterion for surface contamination of lead (200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$)) in all areas sampled.

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there were any suspect asbestos-containing material and its condition. No damaged suspect asbestos-containing materials were observed.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. Evidence of water intrusion was observed in the form of stained ceiling tiles, moisture fogged windows and water damaged wooden window sills.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping was acceptable. Most areas were clean and tidy.

Lighting: A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in several areas. Light fixtures were installed too far apart so that light was deficient in between fixtures in some rooms and most hallways. The illumination measurements indoors ranged from 5 foot candles (fc) to 200 fc.

Indoor Air Quality: Temperature and relative humidity measurements were mostly within the comfort ranges for the winter season on the day of the survey. The outdoor temperature and relative humidity were 63.3° F and 64.4% on the day of monitoring. CO₂ measurements were below the guideline in all areas monitored except for office B159 (1,112 ppm) where three people were working with no central ventilation and in the newly built Recruiting and Retention offices where concentrations ranged from 1,046 to 1,257 ppm. On average CO₂ concentrations were about 600 ppm in the rest of the building even in areas where there was no mechanical ventilation; therefore, this newly built section may have a problem with ventilation balancing or fresh air exchange. Carbon monoxide concentrations were below the guidelines in all areas sampled. An odor issue was reported in Office Suite A174 due to newly installed carpeting. This office suite has no mechanical ventilation; therefore, odors from new building materials will accumulate over time as they off-gas especially since the windows are closed due to the colder weather.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Green Mountain Readiness Center**

Emergency Eyewash and Shower Maintenance: Plumbed emergency eyewash stations located on sink faucets in the medical department were not being inspected and flushed on a weekly basis in accordance with ANSI Z358.1-2009. Weekly flushing and a general cleaning of the fountains are recommended. Inspection tags were not up to date.

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updated MSDSs are required per OSHA 29 CFR 1910.1200. It is recommended that a copy of the written hazard communication program be placed in every MSDS notebook. This is a large readiness center with several departments with a variety of chemical products including those for maintenance, medical, and kitchen cleaning supplies. MSDSs should be stored near the chemical products and in a central location where they can be accessed at any time.

Overall, the Green Mountain Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Green Mountain Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VTARNG) Green Mountain Readiness Center located at 789 Vermont National Guard Road, Colchester, VT 05446. Non-Responsive, CIH, CSP performed the evaluation on October 19, 2012. The point of contact for the facility was LTC Non-Responsive. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

The 76,800 square foot, Green Mountain Readiness Center was built in 1989. The operations conducted at the facility include supply, administrative and military medical duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the Green Mountain Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the Green Mountain facility consist of supply and administrative duties in addition to military medical exams and some medical laboratory tasks. No maintenance of vehicles or other physical tasks are performed at the facility. Ground maintenance and upkeep of the building are the responsibility of the state employed Armorer and not part of the duties of National Guard personnel.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Green Mountain Readiness Center**

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility.

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for water damage or mold problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were taken in select areas.

Paint Chip and Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. No peeling paint was observed. The former firing range was renovated within the last year and is now a sound proof practice and recording area for the military band. To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected using ghost wipes and 10 centimeter (cm) x 10cm templets. The Environmental Protection Agency (EPA) and the State of Vermont limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. All wipe samples collected from the facility were below the recommended maximum in all areas sampled. Results are given in Table 1 and certificates of analysis are included in Appendix B.

**Table 1 – Results of Dust Wipe Sampling for VTARNG
Green Mountain Readiness Center on October 19, 2012.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
GMA – W01	Drill Hall – center of floor	<110
GMA – W02	Drill Hall – floor near former range	<110
GMA – W03	Drill Hall – dusty blue floor mat	<110
GMA – W04	Drill Hall – serving counter	<110
GMA – W05	Drill Hall – water fountain	<110
GMA – W06	Drill Hall – tray return	<110
GMA – W07	1 st Floor Hallway – floor in recycling area	<110
GMA – W08	1 st Floor Hallway – floor near construction	<110
GMA – W09	1 st Floor Former IFR – Band Practice Room - table	<110
GMA – W10	1 st Floor Former IFR – Band Practice Room – hallway treated concrete floor	<110

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Green Mountain Readiness Center**

**Table 1 – Results of Dust Wipe Sampling for VTARNG
Green Mountain Readiness Center on October 19, 2012.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
GMA – W11	1 st Floor Former IFR – Band Practice Room – B156 – untreated concrete floor	<110
GMA – W12	C115 Band Room – small white table	<110
GMA – W13	C115 Band Room – return grill	<110
GMA – W14	New Recruiting and Retention Area – hallway floor	<110
GMA – W15	New Recruiting and Retention Area – lobby floor	<110
GMA – W16	2 nd Floor E228 Conference Room – window sill	<110
GMA – W17	2 nd Floor E228 Conference Room – table	<110
GMA – W18	2 nd Floor E260 Med Lab – counter	<110
GMA – W19	2 nd Floor E259 Exam Room – counter	<110
GMA – W20	2 nd Floor E256 Dental Office - floor	<110

*The recommended maximum level for adult exposures is 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) lead on surfaces.

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). No damaged suspect asbestos-containing materials were observed.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. Evidence of water intrusion was observed in the form of stained ceiling tiles, moisture fogged windows and water damaged wooden window sills.

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping was acceptable. Most areas were clean and tidy.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on April 16, 2012, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

A lighting survey was performed throughout the readiness center. The evaluation indicated illumination deficiencies in several areas. Light fixtures were installed too far apart so that light was deficient in between fixtures in some rooms and most hallways. The illumination measurements indoors ranged from 5 foot candles (fc) to 200 fc. The complete results of the

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Green Mountain Readiness Center**

evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Model 7565X, factory calibrated in March, 2012. Temperature, relative humidity and carbon dioxide (CO₂) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 2. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30 and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 68.1 to 74.5° F and 43.5 to 69.0% Rh. Temperatures and relative humidity were mostly within the winter comfort ranges in the areas monitored. The outdoor temperature and relative humidity was 63.3° F and 64.4% on the day of monitoring and it was raining.

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1–2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 376 to 1,257 parts per million (ppm) and the outdoor concentration was 355 ppm. CO₂ measurements were below the guideline in all areas monitored except for office B159 (1,112 ppm) where three people were working with no central ventilation and in the newly built Recruiting and Retention offices where concentrations ranged from 1,046 to 1,257 ppm. On average CO₂ concentrations were about 600 ppm in the rest of the building even in areas where there was no mechanical ventilation; therefore, this newly built section may have a problem with ventilation balancing or fresh air exchange.

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Green Mountain Readiness Center**

lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 0.0 to 0.5 ppm; therefore, concentrations are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

Odor Issue

An odor issue was reported in Office Suite A174 due to newly installed carpeting. This office suite has no mechanical ventilation; therefore, odors from new building materials will accumulate over time as they off-gas especially since the windows are closed due to the colder weather.

Additional Information

Emergency Eyewash and Shower Maintenance: Plumbed emergency eyewash stations located on sink faucets in the medical department were not being inspected and flushed on a weekly basis in accordance with ANSI Z358.1-2009. Weekly flushing and a general cleaning of the fountains are recommended. Inspection tags were not up to date.

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updated MSDSs are required per OSHA 29 CFR 1910.1200. It is recommended that a copy of the written hazard communication program be placed in every MSDS notebook. This is a large readiness center with several departments with a variety of chemical products including those for maintenance, medical, and kitchen cleaning supplies. MSDSs should be stored near the chemical products and in a central location where they can be accessed at any time.

7 Conclusions

The results of the evaluation indicated few concerns with the facility. Overall, the Green Mountain Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these


**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Green Mountain Readiness Center**

findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.

9 References

1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.
3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.
4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.
5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2011.
6. Army Regulation (AR) 420-70 Buildings and Structures, 11 November 1997.
7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 13 December 2007.
8. Army Regulation (AR) 420-1 Army Facilities Management, 12 February 2008, RAR 24 August 2012.
9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.
10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.
12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.
13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".
15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.
19. ANSI Z358.1 – 2009, Emergency Eyewash and Shower Equipment.


Appendix A Building Layout



115'5"

First Floor

1" = 30'



78'3"

GMA Second Floor

1" = 20'

Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	GMA	Chain Of Custody:	514367
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Colchester, VT	Date Submitted:	11/2/2012
Attention:	Non-Responsive	Job Number:	J12-685	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/9/2012
				Report Date:	11/12/2012

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
13010616	GMA-W 01	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010617	GMA-W 02	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010618	GMA-W 03	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010619	GMA-W 04	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010620	GMA-W 05	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010621	GMA-W 06	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010622	GMA-W 07	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010623	GMA-W 08	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010624	GMA-W 09	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010625	GMA-W 10	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010626	GMA-W 11	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010627	GMA-W 12	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010628	GMA-W 13	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010629	GMA-W 14	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010630	GMA-W 15	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010631	GMA-W 16	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010632	GMA-W 17	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010633	GMA-W 18	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010634	GMA-W 19	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS



Client: National Guard Bureau	Job Name: GMA	Chain Of Custody: 514367
Address: 301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location: Colchester, VT	Date Submitted: 11/2/2012
	Job Number: J12-685	Person Submitting: Non-Responsive
	P.O. Number: W912K6-09-A-0003	Date Analyzed: 11/9/2012 Report Date: 11/12/2012
Attention: Non-Responsive		

Summary of Atomic Absorption Analysis for Lead

Page 2 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
13010635	GMA-W 20	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm)
 %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb)
 Note: All samples were received in good condition unless otherwise noted.
 Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Air and Wipe results are not corrected for any blank results
 Final results for air and wipe samples are based on client supplied information nor verified by this laboratory.
 All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Analyst: Non-Responsive

Technical Manager: Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



AMA Analytical Services, Inc.
 Focused on Results www.amalab.com
 AIHA (#100470) NVLAP (#101143-0) NY ELAP (10920)
 4475 Forbes Blvd. • Lanham, MD 20706
 (301) 459-2640 • (800) 346-0961 • Fax (301) 459-2643

BEST AVAILABLE COPY

CHAIN OF CUSTODY

(Please Refer To This Number For Inquiries)

514367

Mailing/Billing Information:

- Client Name: National Guard Bureau
- Address 1: 301-IH Old Bay Lane
- Address 2: Attn: NGB-AVN-SI, State Military Reservation
- Address 3: Havre de Grace, Maryland 21078
- Phone #: (410) 942-0273 Fax #: (410) 942-0254

Submittal Information:

- Job Name: GMA
- Job Location: Colchester, VT
- Job #: J12-085 P.O. #: W912K6-09-A-0003
- Contact Person: Non-Responsive @ phone # _____
- Submitted by: Non-Responsive Signature: Non-Responsive

Reporting Info (Results provided as soon as technically feasible). If no TAT/Reporting Info is provided, AMA will assign defaults of 5-Day and email/fax to contacts on file.

AFTER HOURS (must be pre-scheduled) <input type="checkbox"/> Immediate Date Due: _____ <input type="checkbox"/> 24 Hours Time Due: _____ Comments: _____		NORMAL BUSINESS HOURS <input type="checkbox"/> Immediate <input type="checkbox"/> Next Day <input type="checkbox"/> 2 Day <input type="checkbox"/> 3 Day <input checked="" type="checkbox"/> 5 Day + <u>Wait Wait</u> Date Due: _____ <input type="checkbox"/> Results Required By Noon		REPORT TO: <input checked="" type="checkbox"/> Include <u>Non-Responsive</u> with Report <input checked="" type="checkbox"/> Email: <u>@_ariaenviro.com</u> <input type="checkbox"/> Fax: <u>@us.army.mil</u> <input type="checkbox"/> Verbals: <u>@us.army.mil</u>	
--	--	---	--	--	--

Asbestos Analysis

- *PCM Air - Please Indicate Filter Type:
 - NIOSH 7400 (QTY)
 - Fiberglass (QTY)
- TEM Air* - Please Indicate Filter Type:
 - AHERA (QTY)
 - NIOSH 7402 (QTY)
 - Other (specify _____) (QTY)
- PLM Bulk
 - EPA 600 - Visual Estimate (QTY)
 - EPA Point Count (QTY)
 - NY State Friable 198.1 (QTY)
 - Grav. Reduction ELAP 198.6 (QTY)
 - Other (specify _____) (QTY)

TEM Bulk

- ELAP 198.4/Chatfield (QTY)
- NY State PLM/TEM (QTY)
- Residual Ash (QTY)

TEM Dust*

- Qual. (pres/abs) Vacuum/Dust (QTY)
- Quan. (s/area) Vacuum D5755-95 (QTY)
- Quan. (s/area) Dust D6480-99 (QTY)

TEM Water

- Qual. (pres/abs) (QTY)
- ELAP 198.2/EPA 100.2 (QTY)
- EPA 100.1 (QTY)

All samples received in good condition unless otherwise noted.
 (TEM Water samples _____ °C)

Metals Analysis

- Pb Paint Chip (QTY)
- Pb Dust Wipe (wipe type 10x10 cm) 20 (QTY) ghost
- Pb Air (QTY)
- Pb Soil/Solid (QTY)
- Pb TCLP (QTY)
- Drinking Water Pb (QTY) Cu (QTY) As (QTY)
- Waste Water Pb (QTY) Cu (QTY) As (QTY)
- Pb Furnace (Media _____) (QTY)

Fungal Analysis

- Collection Apparatus for Spore Traps/Air Samples: _____
- Collection Media _____
- *Spore-Trap (QTY) Surface Vacuum Dust (QTY)
- *Surface Swab (QTY) Culturable ID Genus (Media _____) (QTY)
- *Surface Tape (QTY) Culturable ID Species (Media _____) (QTY)
- Other (Specify _____) (QTY)

MISC

- Vermiculite
 - Asbestos Soil PLM (Qual) PLM (Quan) PLM/TEM (Qual) PLM/TEM (Quan)
- *It is recommended that blank samples be submitted with all air and surface samples

If field data sheets are submitted, there is no need to complete bottom section.

CLIENT ID #	SAMPLE INFORMATION SAMPLE LOCATION/ID	DATE/TIME	VOL (L)/ Wipe Area	ANALYSIS												CLIENT CONTACT			
				TEM	PCM	PLM	LEAD	MOLD	AIR	BULK	DUST	MATRIX WATER AND OTHER	SPORE TRAP	TAPE	SWAB	(LABORATORY STAFF ONLY)			
	SEE ATTACHED FIELD DATA SHEETS																Date/Time:	Contact:	By:
																	Date/Time:	Contact:	By:
																	Date/Time:	Contact:	By:

LABORATORY STAFF ONLY: (CUSTODY)

1. Date/Time RCVD: 11/2/12 @ 10:15 Via: Foot By (Print): Non-Responsive Sign: Non-Responsive

2. Date/Time Analyzed: _____ @ _____ By (Print): _____ Sign: _____

3. Results Reported To: _____ Via: _____ Date: _____ / _____ / _____ Time: _____ Initials: _____

Posted to NGB FOIA Reading Room May, 2018

Aria Environmental, Inc
SURFACE WIPE AND BULK SAMPLING
SURVEY SHEET

Date Collected: 10-19-12
 Job Site: J12-685
 Project No.: GMA

Inspector:



10 X 10 cm

Sample No.	Sample Type	Sample Location	Dimensions (Area)
GMA-W01	Lead	Drill Hall - floor center	
W02		Drill Hall - floor near former range	
W03		Drill Hall - dusty blue floor mat	
W04		Drill Hall - serving counter	
W05		Drill Hall - water fountain	
W06		Drill Hall - tray return	
W07	1 st Fl	Hallway (recycling + trash area) - floor	(Construction workers egress)
W08	1 st Fl	Hallway near construction containment	
W09	1 st Fl	former IFR - Band Practice Room B166 - table	
W10	"	" - " - Hallway floor treated conc.	
W11	"	" - " - B156 floor untreated conc.	
W12	"	C115 Band Room - small white table	
W13	"	C115 Band Room - return grill	
W14	"	R+R Battalion Area - floor - hallway	
W15	"	R+R Battalion Area - floor - Lobby	
W16	2 nd Fl	E228 Conf Room - window sill	
W17	"	E228 Conf Room - table	
W18	"	E260 Med Lab - Counter	
W19	"	E259 Exam Room - Counter	
W20	"	E256 Dental - floor (VCT)	

Appendix C Photo Documentation

VT Green Mountain Armory (GMA)



Lobby



JFHQ Office Suite



JFHQ Office Suite




Drill Hall

VT GMA



Drill Hall



Janitor's Closet



Drill Hall



Trash and Recycling in Hallway

VT GMA



Containment near area being renovated



Containment does not go to floor to prevent dust from entering hallway



Storage Area near Drill Hall

Posted to NGB FOIA Reading Room
May, 2018



Human Resources Office

VT GMA



Renovated area



Offices near Drill Hall



Offices and storage near Drill Hall



Storage Area

VT GMA



Office



Office



Storage and Office area



Funeral Services Office


VT GMA



Supply Office



Janitor's closet with a coffee station



Janitor's closet

Posted to NGB FOIA Reading Room
May, 2018



Band Office

VT GMA



Band Instrument storage room



Kitchenette in Band Storage Room



Band Room



Stained Ceiling Tiles in Band Room

VT GMA



Band Room



Band Offices



Stained Ceiling tiles in Band offices



Recording area

VT GMA



Stained Ceiling Tiles




Newly Installed Band Practice Room



Newly Installed Band Practice Room

Posted to NGB FOIA Reading Room
May, 2008



Newly Installed Band Practice Room

VT GMA



Newly Installed Band Practice Room



Newly Installed Band Practice Room

VT GMA



Newly Installed Band Practice Room



Lobby in Recruiting Area



Office



Conference Room

VT GMA



Boiler Room



Electrical Closet



Janitor's Closet

Posted to NGB FOIA Reading Room
May, 2018



Hallway

VT GMA



Lobby



Office



Conference Room



Office

VT GMA



Conference Room



Office Suite



Janitor's Closet

Posted to NGB FOIA Reading Room
May, 2018



Electrical Closet with blocked panel

VT GMA



Stained Ceiling Tiles



Stained Ceiling Tiles



Classroom



Stained Ceiling Tiles

VT GMA



Stained Ceiling Tiles



2nd Floor Hallway



Stained Ceiling Tile

VT GMA




Stained Ceiling Tiles



Medical Office



Janitor's Closet with Medical Supplies and Cleaning Products



Dental Office

Posted to NGB FOIA Reading Room
May, 2011

VT GMA



Dental Office Storage



Medical Exam Room



Eyewash Station



Medical Exam Room

VT GMA



Medical Lab



Eyewash Station in Lab



Medical Lab



Window with water intrusion

VT GMA



Office Suite



Office Suite Conference Table



Office

Posted to NGB FOIA Reading Room
May, 2018



Office

VT GMA



Break Room



Human Resources Office



Chapel

Appendix D
IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Colchester	IAQ							Light		
Date	10/19/2012	Inspector	Non-Responsive	Instrument	Q-trak 7565-X						Instrument	Cal-Light 400	
Facility Description	GMA			Serial Number	7565X0839019						Serial Number	K070003	
Weather Conditions				Last Calibration	Mar-12						Last Calibration	16-Apr-12	
Location/Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
Lobby	1	0918	68.8		53.0		480		0.5		11-184		10
A174 Suite	2	0922	70.3		45.0		705		0.2		50-165		30-50
A177 Office	1	0923	70.4		45.4		713		0.2		30-126		30-50
A178 Office	1	0923	70.5		43.5		681		0.2		30-130		30-50
B110 Janitor's Closet	1	0925									18	X	30
Drill Hall	2	0933	71.2		52.3		689		0.2		30-75	X	50
B161 Storage	1	0957									18-55		10
B159 HRO Suite	3	0958	72.0		51.5		1112	X	0.5		50-100		30-50
B154 New Office	1	1002	71.4		49.9		575		0.2		18-56	X	30-50
B148 Vault Storage	1	1005									30-71		30
B149 Office	2	1007	70.5		48.4		516		0.1		17-70	X	30-50
B150 Office Supplies	2	1010									7-128	X	10
B144 Storage Lockers	1	1011									30-50		30
B145 Office	2	1012	71.9		48.0		605		0.0		50-80		30-50
B169 Storage and Office	5	1013	72.3		50.0		558		0.2		18-35	X	30
C101 Janitor's Closet	1	1015									41		30
C103 Office	1	1020									30-80		30-50
C105A Office	5	1021	74.1		50.4		788		0.1		50-150		30-50
C105B	3	1022									30-137		30-50
C108 Office	1	1023									40-180		30-50
C110 Storage	1	1024	73.4		44.5		567		0.0		30-104		30
C115 Band Room	1	1026	69.7		50.6		424		0.1		16-37	X	30-50
C114 Sound Room	1	1028									70-144		30-50

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Colchester	IAQ							Light		
Date	10/19/2012	Inspector	Non-Responsive	Instrument	Q-trak 7565-X							Instrument	Cal-Light 400
Facility Description	GMA			Serial Number	7565X0839019							Serial Number	K070003
Weather Conditions				Last Calibration	Mar-12							Last Calibration	16-Apr-12
Location/Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
C113 Office	1	1032	70.2		50.7		448		0.1		80-175		30-50
B154 Band Practice Suite	1	1035									5-65	X	30-50
B167 Large Practice Area	1	1036	68.1		54.0		382		0.1		30-55		30-50
B166 Sound Room	1	1040	68.1		49.7		406		0.1		100-120		30-50
B165 Small Practice Area	1	1044	68.7		48.0		376		0.0		85-110		30-50
R&R Battery Lobby/Waiting Area	2	1110	71.7		51.9		1140	X	0.1		54-65		10
D191 Office	2	1112	71.7		52.1		1216	X	0.2		40-60		30-50
D195 Office	2	1113	71.8		53.3		1046		0.1		40-70		30-50
D197 ID Office	5	1114	71.6		53.8		1257	X	0.2		60-70		30-50
D196 Office	1	1115	71.3		52.6		1233	X	0.2		30-60		30-50
D194 Office	3	1116	71.7		53.6		1218	X	0.2		40-60		30-50
D192 Office	2	1116	72.2		52.5		1170	X	0.1		35-72		30-50
D189 Office	2	1117	72.1		51.7		1161	X	0.1		50-77		30-50
D190 Office	3	1118	72.1		52.2		1217	X	0.3		48-78		30-50
D188 Office	3	1118	72.0		52.5		1232	X	0.1		33-65		30-50
D183 Print Room	1	1122	72.2		52.2		1171	X	0.1		40-58		30-50
D182 Office	3	1123	72.5		53.1		1227	X	0.2		30-80		30-50
B134 Office	1	1129	72.2		48.5		759		0.2		70-145		30-50
B135 Office	1	1129	72.5		48.0		765		0.1		86-150		30-50
B135 Conference Room	1	1130	71.1		46.9		677		0.2		30-140		30-50
B136 Office	1	1131									30-113		30-50
B137 Office	1	1131									30-70		30-50
B130 Office Suite	1	1132	73.1		45.8		750		0.1		30-117		30-50

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Colchester	IAQ							Light			
Date	10/19/2012	Inspector	Non-Responsive	Instrument	Q-trak 7565-X							Instrument	Cal-Light 400	
Facility Description	GMA			Serial Number	7565X0839019							Serial Number	K070003	
Weather Conditions				Last Calibration	Mar-12							Last Calibration	16-Apr-12	
Location/Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)	
A160 Office	1	1146	70.2		52.0		532		0.0		40-160		30-50	
A159 Office	3	1147	70.6		52.9		697		0.1		40-200		30-50	
A156A Office Suite	5	1148	71.5		51.1		636		0.1		18-108	X	30-50	
A156B Office Suite	2	1150									15-86	X	30-50	
A156C Office Suite	2	1153									50-100		30-50	
A156D Conference Room	1	1155									30-50		30-50	
A156E Office	1	1200	72.7		48.9		665		0.1		30-150		30-50	
A117 Office Suite	2	1212	70.3		52.2		522		0.2		30-130		30-50	
A116 Office	1	1212	70.1		51.2		497		0.2		30-120		30-50	
Break Room Kitchenette	1	1213	70.0		52.8		515		0.1		80-120		15	
A120 Office	1	1214	69.8		51.4		482		0.1		60-120		30-50	
A121 Conference Room	1	1220	68.1		56.6		595		0.1		8-83	X	30-50	
A103 Office	1	1222	68.4		53.4		525		0.1		30-80		30-50	
A110 Office	1	1225	68.9		52.0		549		0.1		40-116		30-50	
A107 Office	4	1226	69.1		54.5		705		0.1		30-119		30-50	
A108 Office	1	1226	69.0		52.3		535		0.1		30-107		30-50	
A134 Suite	2	1228	70.1		53.5		590		0.0		30-150		30-50	
A138 Office	1	1229									30-135		30-50	
A137 Office	2	1230	70.8		52.3		743		0.0		80-130		30-50	
A139 Office	1	1231									125		30-50	
A145 Suite	1	1232	71.0		50.6		541		0.0		50-165		30-50	
A149 Conference Room	1	1233	70.7		50.9		539		0.1		40-112		30-50	
A165 Office Suite	1	1240									80-165		30-50	

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Colchester	IAQ							Light		
Date	10/19/2012	Inspector	Non-Responsive	Instrument	Q-trak 7565-X						Instrument	Cal-Light 400	
Facility Description	GMA			Serial Number	7565X0839019						Serial Number	K070003	
Weather Conditions				Last Calibration	Mar-12						Last Calibration	16-Apr-12	
Location/Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
E227 Electrical Closet	1	1242									60-70		30
E228/E235 Class/Conference Room	1	1242									35-52		30-50
E234 Office	2	1243	72.6		69.0	X	559		0.2		30-99		30-50
E236 Office	2	1256	74.2		50.6		759		0.0		60-125		30-50
E237 Office	0	1257									145		30-50
E238 Office	5	1303	72.8		49.9		583		0.1		50-150		30-50
E249 Office	3	1308	74.4		51.6		736		0.0		80-150		30-50
E250 Office	2	1309	74.5		50.4		713		0.1		60-150		30-50
E251 Office	3	1310	74.2		49.9		695		0.1		30-110		30-50
E251A Break Area	1	1318									130		15
E253 Office	1	1318	73.8		49.8		610		0.1		50-100		30-50
E255 Janitor's & Electrical Closet	1	1319									30		30
E256 Dental	1	1320									105		30-50
E258 Vision	1	1321									150		30-50
E259 EKG & Vitals	1	1322	73.5		50.9		664		0.1		50-115		30-50
E260 Lab	1	1323	73.5		49.9		624		0.0		30-109		30-50
Waiting Room	1	1323	73.5		50.2		631		0.0		10-46		10
E252 Hearing	1	1334	73.8		52.2		676		0.1		50-70		30-50
E203 Office Suite	1	1336	73.5		49.5		438		0.1		70-160		30-50
E213A Office	1	1338	73.3		48.1		478		0.1		90-128		30-50
E213 Office	2	1338	73.7		49.3		530		0.1		80		30-50
E215A Office	1	1340	73.4		46.5		485		0.1		30-50		30-50
E216 Suite	1	1341	73.7		49.5		523		0.1		50		30-50

Shaw Environmental, Inc.

312 Directors Drive
Knoxville, TN 37923
865.690.3211
Fax 865.690.3628



**National Guard Armory
Lyndonville Readiness Center – Lyndonville, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

11 December 2003

**National Guard Armory
Lyndonville Readiness Center – Lyndonville, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

11 December 2003

Prepared by:

Non-Responsive

Industrial Hygienist

Reviewed by:

Non-Responsive

Business Line Manager

Table of Contents

Table of Contents *i*

List of Tables *ii*

List of Appendices *ii*

Executive Summary *E-1*

1.0 Introduction..... *1-1*

2.0 Findings, Discussion, and Interpretation of Results *2-1*

2.1 Sampling for Lead..... *2-1*

2.1.1 Wipe Sampling..... *2-1*

2.1.2 Air Sampling..... *2-2*

2.2 Physical Condition of Facility..... *2-2*

2.2.1 Peeling Paint - Lead..... *2-2*

2.2.2 Visual Inspection - Asbestos..... *2-2*

2.2.3 Visual Inspection - Water Damage and Mold *2-3*

2.2.4 Visual Inspection - Housekeeping *2-3*

2.3 Building Concerns..... *2-3*

2.3.1 Ergonomic Concerns..... *2-3*

2.3.2 Indoor Air Quality..... *2-3*

2.4 Safety and Industrial Hygiene Programs..... *2-3*

2.5 Ventilation *2-4*

2.5.1 Ventilation System Evaluation *2-4*

2.5.2 Contamination of Clean Air Sources *2-4*

2.6 Noise Dosimetry..... *2-4*

2.7 Lighting *2-4*

2.8 Converted Indoor Firing Ranges *2-4*

2.9 HVAC Systems..... *2-5*

2.10 IHMM *2-5*

3.0 Conclusions *3-1*

Tables *Follows Section 3.0*

Appendices *Follows Figures*

List of Tables

Table 1	Wipe Sampling for Lead
Table 2	Air Sampling for Lead
Table 3	Indoor Air Quality Measurements
Table 4	Illumination Readings
Table 5	Indoor Firing Ranges - Wipe Sampling

List of Appendices

Appendix A	IIIM Data Form
Appendix B	Building Layout
Appendix C	Sampling Sheets and Laboratory Analyses
Appendix D	References
Appendix E	Recommendations for Surface Lead Dust in Armories

Executive Summary

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Lyndonville Readiness Center in Lyndonville, Vermont **Non-Responsive**. **Non-Responsive** performed the evaluation on 29 July 2003 and 7 October 2003. The point of contact at the readiness center was SGT **Non-Responsive**.

The following industrial hygiene concerns were evaluated.

- Wipe Sampling for Lead
- Air Sampling for Lead
- Peeling Paint – Lead
- Suspected Asbestos Containing Material
- Water Damage
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Indoor Air Quality
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- Lighting
- Converted Indoor Firing Ranges
- HVAC Systems

The following items were either not applicable to the armory or the evaluation resulted in a conclusion that there were no industrial hygiene concerns.

- Air Sampling for Lead
- Peeling Paint – Lead
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Indoor Air Quality

- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- HVAC Systems

Areas where there were industrial hygiene concerns are as follows:

- Wipe sampling for lead revealed a concentration above the recommended level at one location in the assembly room (the fire alarm control box top surface). It is recommended that the fire alarm control box top surface and the area immediately around the fire alarm control box top surface be cleaned thoroughly to reduce the lead level. In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.
- Wipe sampling for lead revealed concentrations above a level of 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) in the assembly hall and the 1st floor (flammable cabinet top and office heating vent). If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.
- Materials suspected of containing asbestos were observed. An operations and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.
- Water damage was observed at two locations at the armory. The source of the water damage was likely from roof leaks. The source of the water should be confirmed and actions taken to eliminate the source in order to prevent the possibility of mold growth that may lead to indoor air quality problems.
- Lighting measurements were conducted at the armory. The lighting did not meet minimum requirements in many areas; therefore consideration should be given to providing more lighting in these areas. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.
- Wipe sampling for lead in the converted firing range revealed concentrations above the recommended level at all of the locations sampled. These areas must be decontaminated by a thorough cleaning along with re-sampling until surface lead concentrations are reduced to below recommended levels. In addition, employees

should not be allowed to work in these areas without protective clothing until the areas are cleaned and re-sampled.

1.0 Introduction

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Lyndonville Readiness Center in Lyndonville, Vermont. [Non-Responsive] performed the evaluation on 29 July 2003 and 7 October 2003. The point of contact at the readiness center was SGT [Non-Responsive]

The findings, discussion, and interpretation of results are provided in Section 2.0. The conclusions are provided in Section 3.0. The HHIM data form for the facility is provided in Appendix A. The building layout is provided in Appendix B. Sampling sheets and laboratory analyses are provided in Appendix C. References are provided in Appendix D. The *Recommendations for Surface Lead Dust in Armories* document is provided in Appendix E.

The statements, opinions, and conclusions contained in this report are based solely upon the services performed by Shaw as described in the report. In performing these services and preparing the report, Shaw Environmental, Inc. relied upon the work and information provided by others, including public agencies, whose information is not guaranteed by Shaw Environmental, Inc.

2.0 Findings, Discussion, and Interpretation of Results

The results, discussion, and interpretation of results are provided in the following sections.

2.1. Sampling for Lead

2.1.1 Wipe Sampling

Wipe samples were collected for lead from the drill floor/assembly area. Also, wipe samples were collected for lead in rooms, hallways, foyers, etc. The sampling in rooms, hallways, foyers, etc. represented approximately 25% of the building. Approximately half of the samples were collected from surfaces in common areas, such as surfaces of a desk. The remaining samples were collected from uncommon surface areas, such as a supply vent or the top of a file cabinet. The samples were collected and analyzed in accordance with the Instructions for *Completing the Sampling of Army National Guard Armories* procedure.

The only samples initially submitted for analysis were those from the drill floor/assembly hall. If there were any positive results from the drill floor, the other samples would be submitted for analysis.

Results of the wipe sampling are provided in Table 1. The results revealed lead at all locations sampled at concentrations below recommended level of 200 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$) (See Appendix F) except at one location. The assembly hall fire alarm control box top surface had a lead concentration of $830 \mu\text{g}/\text{ft}^2$. It is recommended that fire alarm control box surface and the immediate areas around the fire alarm control box be thoroughly cleaned to reduce the lead level. For guidance on the proper method of cleaning, please refer to NG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.

Wipe sampling for lead revealed concentrations above a level of $40 \mu\text{g}/\text{ft}^2$ in the assembly hall and the 1st floor (flammable cabinet top and office heating vent). Please

note that the *Recommendations for Surface Lead Dust in Armories* (Appendix E) states that all areas should be cleaned that will be accessible to children. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.

2.1.2 Air Sampling

Breathing zone air sampling was conducted on one (1) full-time building occupant. (Please note that no state employees were monitored.) In addition, a general air sample was collected in the converted firing range. The samples were taken and analyzed in accordance with Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods.

The results of the sampling are provided in Table 2. The results revealed non-detectable concentrations of lead in the breathing zone of the employee and in the general area of the converted firing range; therefore, no actions are necessary.

2.2 Physical Condition of Facility

2.2.1 Peeling Paint - Lead

Peeling paint was not observed at the armory, therefore, bulk samples for lead in paint were not taken.

2.2.2 Visual Inspection - Asbestos

A visual inspection was made to determine if there was any suspected asbestos-containing material at the armory. Materials suspected of containing asbestos were observed. The suspected asbestos-containing material was floor tiles in the kitchen and two kitchen storage rooms (approximately 800 square feet) and insulation in the boiler room (approximately 39 linear feet). The condition of the floor tiles materials was considered average since there was some damage to tiles at the doorways. The condition of the boiler room insulation materials was considered good (no rips, tears, or other damage).

An operation and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.

2.2.3 Visual Inspection – Water Damage and Mold

A visual inspection was made to determine if there was any water damage or visible mold at the armory. Visible mold was not observed, however, water damage was observed at the armory. The water damage was observed in the classroom on the second floor in the form of stained ceiling tiles and in the men's latrine on the ceiling above the shower.

The source of the water damage was likely from roof leaks. The source of the water damage should be confirmed and actions taken to eliminate the source in order to prevent the possibility of mold growth that may lead to indoor air quality problems.

2.2.4 Visual Inspection - Housekeeping

The housekeeping was determined to be good.

2.3. Building Concerns

2.3.1 Ergonomic Concerns

Interviews with employees and observation of work activities revealed no ergonomic concerns at the armory.

2.2.4 Indoor Air Quality

Interviews with employees and measurements for carbon dioxide, humidity, and temperature revealed no indoor air quality concerns at the armory. The results of the measurements for carbon dioxide, humidity, and temperature are provided in Table 3.

2.4. Safety and Industrial Hygiene Programs

An evaluation was performed to determine the applicability of the following programs.

- Confined Spaces
- Hearing Conservation
- Respiratory Protection
- Hazard Communication (HAZCOM)
- Personal Protective Equipment (PPE)

It was determined that the HAZCOM program was the only program listed above that was applicable at the facility. HAZCOM program was evaluated and it was determined that the program met minimum requirements.

2.5. Ventilation

2.5.1 Ventilation System Evaluation

There were no local exhaust ventilation systems at this armory, therefore, no ventilation studies were performed.

2.5.2 Contamination of Clean Air Sources

Since there were no local exhaust ventilation systems at the armory, there was no possibility that clean air sources could be contaminated by exhaust air.

2.6. Noise Dosimetry

An evaluation was performed to determine if there were any hazardous noise areas at the armory. It was determined that there were no areas at the armory that would exceed the permissible exposure limit for noise.

2.7 Lighting

Lighting measurements were conducted at the armory. Results of the lighting evaluation are provided in Table 4. As can be seen from the results, the lighting did not meet the minimum requirements in many areas, including the COB DET FSB RNCO Office, supply room office area, and kitchen.

Consideration should be given to providing more lighting to the areas listed above. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

2.8. Converted Indoor Firing Ranges

There was a converted indoor firing range at the facility; therefore, wipe samples were taken for lead at various locations in or near the converted range. The results are provided in Table 5. The results revealed lead, with associated concentrations, at the following locations:

- floor outside the range at 790 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$);
- bullet trap floor at 17000 $\mu\text{g}/\text{ft}^2$;
- light fixture at 3800 $\mu\text{g}/\text{ft}^2$;
- floor at 1000 $\mu\text{g}/\text{ft}^2$;
- stored item -- locker top at 1000 $\mu\text{g}/\text{ft}^2$;
- inside remaining ventilation ductwork at 6400 $\mu\text{g}/\text{ft}^2$; and
- storage room (separate room) at 1300 $\mu\text{g}/\text{ft}^2$.

The lead levels at these locations were above the recommended level of 200 $\mu\text{g}/\text{ft}^2$, a level recommended in the *Guidelines for Converting Indoor Firing Ranges to Other Uses* document (Department of Army). These areas must be decontaminated by a thorough cleaning along with re-sampling until surface lead concentrations are reduced to below recommended levels. For guidance on the proper method of cleaning, please refer to NGB PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, employees should not be allowed to work in these areas without protective clothing until the areas are cleaned and re-sampled.

2.9. HVAC System

There was not a HVAC system at the armory.

2.10. HHIM

A Health Hazard Information Module (HHIM) form was completed for the armory. The completed form is provided in Appendix A.

3.0 Conclusions

It is concluded that there were no industrial hygiene concerns at the armory with regards to atmospheric exposure to lead, peeling lead-based paint, indoor air quality, visible mold, housekeeping, ergonomic conditions, safety and industrial hygiene programs, ventilation systems or contamination of clean air sources, noise exposure, and HVAC systems.

There were industrial hygiene concerns at the armory with regards to lead surface contamination, suspected asbestos-containing material, water damage, surface lead contamination in the converted firing range, and lighting. These concerns are discussed in detail in Section 2.0 of this report.

TABLES

Table 1
Wipe Sampling for Lead
National Guard Armory
Lyndonville, Vermont

Date of Sampling: 29 July 2003 and 7 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTLYN209-1	Drill Floor – On Floor (See Building Layout – Appendix B)	< 110
VTLYN209-2	Drill Floor – On Floor (See Building Layout – Appendix B)	< 110
VTLYN209-3	Drill Floor – On Floor (See Building Layout – Appendix B)	< 110
VTLYN209-4	Drill Floor – On Floor (See Building Layout – Appendix B)	< 110
VTLYN209-5	Drill Floor – On Floor (See Building Layout – Appendix B)	130
VTLYN209-6	Field Blank	<12 μg
VTLYN209-15	1 st Floor Co. D Supply Television Top	14
VTLYN209-16	1 st Floor Kitchen Dough Mixer Top	5.4
VTLYN209-17	1 st Floor Co B Det FSB RNCO Office Desktop	23
VTLYN209-18	Field Blank	<0.3 μg
VTLYN209-19	1 st Floor Flammable Cabinet Top	130
VTLYN209-20	1 st Floor Recruiting Office Desktop	<2.7
VTLYN209-21	1 st Floor Training Office Heating Vent	120
VTLYN209-22	1 st Floor Desktop	6.5
VTLYN209-23	2 nd floor classroom table top	7.9
VTLYN209-24	Field Blank	<0.3 μg
VTLYN281-1	Assembly Hall (Soda Machine Top Surface)	90
VTLYN281-2	Assembly Hall (Locker Top Surface)	78

(Continued)

Table 1 (Continued)
Wipe Sampling for Lead
National Guard Armory
Lyndonville, Vermont

Date of Sampling: 29 July 2003 and 7 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTLYN281-3	Assembly Hall (Flammable Storage Cabinet Top Surface)	110
VTLYN281-4	Assembly Hall (Fire Alarm Control Box)	830
VTLYN281-5	Assembly Hall (Table Top Surface)	43
VTLYN281-6	Field Blank	0.39

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the *Instructions for Completing the Sampling of Army National Guard Armories* procedure.

In armories that do not contain childcare facilities, the NGB Region North Industrial Hygiene Office recommends cleaning the areas with sample results greater than 200 $\mu\text{g}/\text{ft}^2$.

Table 2
Breathing Zone Air Samples for Lead
National Guard Armory
Lyndonville, Vermont
Date of Sampling: 29 July 2003

Sample Number	Employee	Sampling Information			Results (mg/m ³) ^a
		Time Sampled / Minutes	Flow Rate (lpm) ^b	Volume (liters)	
VTLYN209-A1	SSG Non-Responsive [REDACTED]	1131-1246/75	2.489	186.67	<0.005
VTLYN209-A2	General Sample-Converted Firing Range	1215-1330/75	2.494	187.06	<0.005
VTLYN209-A3	Field Blank	-	-	-	None Detected

^a Milligrams lead per cubic meter of air.

^b Liters of air per minute.

Only one employee was sampled because there were no other employees available at the armory on the date of the survey.

Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods was followed for sampling for lead.

Table 3
Indoor Air Quality Measurements for Carbon Dioxide, Humidity, and Temperature
National Guard Armory
Lyndonville, Vermont
Date of Sampling: 29 July 2003

Location	Occupants in Area	Carbon Dioxide, parts per million parts of air (ppm)	Percent (%) Humidity	Temperature (°F)
1 st Floor Copy room	1	526	53.0	77.4
2 nd Floor	1	472	49.3	76.5
Outdoors	-	432	52.4	78.6

Carbon dioxide, humidity, and temperature measurements were taken with a TSI Q Trak Plus, Model 8554, Indoor Air Quality Meter, calibrated in April 2003.

American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommends that indoor carbon dioxide levels be less than 700 ppm above outdoor levels.

ASHRAE recommends that the relative humidity levels be maintained between 30 to 60 percent.

ASHRAE recommends that the acceptable temperature range be 68 degrees Fahrenheit to 74 degrees Fahrenheit in the winter and 73 degrees Fahrenheit to 79 degrees Fahrenheit in the summer.

Table 4
Illumination Readings
National Guard Armory
Lyndonville, Vermont
Date of Sampling: 29 July 2003

Location	Luminance (fc) ^a	Standard (fc) ^a	Standard Met
COB DET FSB RNCO Office	28.2-68.1	70	No
Women's Latrine	15.8-55.1	40	Some Areas
Men's Latrine	33.6-70.1	40	Some Areas
Recruiting Office	19.1-87.3	70	Some Areas
Front Middle Office	34.7-93.5	70	Some Areas
Classroom	45.3-82.7	70	Some Areas
2 nd Floor Office	48.1-92.1	70	Some Areas
Kitchen (Storage)	14.1-60.3	30	Some Areas
Supply Room Office Area	25.1-63.5	70	No
Kitchen	38.2-65.3	70	No

^a fc - Footcandles

The readings were taken with a Cooke Corporation cal-LIGHT 400 Calibrated Precision Lightmeter, calibrated on 19 Aug 2002.

The standards listed above are from Design Guide DG-415-2, Logistics Facilities, published by the National Guard Bureau Installation Division.

Table 5
Wipe Sampling for Lead – Converted Firing Range
National Guard Armory
Lyndonville, Vermont
Date of Sampling: 29 July 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTLYN209-7	Floor Outside the Range	790
VTLYN209-8	Bullet Trap Floor	17000
VTLYN209-9	Light Fixture	3800
VTLYN209-10	Floor	1000
VTLYN209-11	Stored Item - Locker Top	1000
VTLYN209-12	Field Blank	<12 μg
VTLYN209-13	Inside Remaining Ventilation Ductwork	6400
VTLYN209-14	Storage Room (Separate Room)	1300

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the instructions for *Completing the Sampling of Army National Guard Armories* procedure.

Appendix A

HHIM Data Form(s)

HEALTH HAZARD INFORMATION MODULE INDUSTRIAL HYGIENE SURVEY

(For use of this form, see HHIM User's Guide)

SECTION 1. DEMOGRAPHIC DATA

ARLOC		INSTALLATION Lyndonville Armory Vermont ARNG		BLDG/RM NO. Lyndonville	
LOCATION/CODE Administrative Areas / AA			OPERATION/CODE Administrative OP/ADO		
SURVEY DATE 29 July 2003			EVALUATOR (Initials) M.S.		
MACOM/CODE Army National Guard		SUBMACOM/CODE XX		SUPERVISOR Non-Responsive	
TELEPHONE/DSN NO. 802 626 5503		UNIT/ORGANIZATION Company D (1st BN) 172nd Armor (8th BDE) 22nd IUE		RAC 5	FREQUENCY (hrs/day) 8
NO. CIV(S) 1	NO. MIL 6	NO. CONTRACTOR(S) 0	NO. LOC(S) 0	NO. OTHER 0	

SECTION 2. FACILITY DATA

LAB HOODS <input type="radio"/>	VAPOR DEGREASERS <input type="radio"/>		SPRAY BOOTHS <input type="radio"/>	
MAINTENANCE BAYS <input type="radio"/>	OPEN SURFACE TANKS <input type="radio"/>		VENTILATION UNITS <input type="radio"/>	

SECTION 3. SURVEY DATA

CONTROLS PRESENT	EVALUATION	UNIT CODE	CONTROLS REQUIRED	STATUS

PERSONAL PROTECTIVE EQUIPMENT (R = Required; U = Utilized)

GLOVES	R	U	RESPIRATOR	R	U	MOSETC. NO.	MANUFACTURER	R	U
ACID			ABLUNG						
COLD SURFACES			ABRASIVE BLASTING HOOD						
HOT SURFACES			DISPOSABLE						
NBC AGENTS			FULL FACE AIR PURIFYING						
OR			1/2 FACE AIR PURIFYING						
SOLVENTS			POWERED AIR PURIFYING						
SURGICAL GLOVES			1/4 FACE AIR PURIFYING						
			SELF-CONTAINED						

EYES/FACE	R	U	HEARING	R	U	BODY	R	U	HEAD/FIT	R
			CANAL CAPS			APRONS			COLD WEATHER BOOTS/HATS	
			EAR PLUGS			COLD WEATHER CLOTHING			HARD HATS	
			HELMETS			COVERALLS			IMPERMEABLE BOOTS	
			MUFFS			FULL BODY SUIT			SAFETY/CONDUCTIVE SHOES	
			MUFF/EARPLUG COMBO			HEAT REFLECTIVE VEST/SUIT			SAFETY/NON-CONDUCTIVE SHOES	
			MUFF/EARPLUG W/TIME LIMIT			SAFETY BELT/HARNES				

AEHA Form 271-R (Test) 1 Jan 92 (HSHB-MI-1)

SECTION 4. HAZARD INVENTORY DATA

CAS CODE	HAZARD DESCRIPTION	PAC	EPC
FOVDTXXX	Video Display Terminal	3-low	Uncontrolled Physical
332-21-4	Asbestos (Other)	2-moderate	Uncontrolled Respiratory
7439-92-	Lead inorganic dusts & fumes	2-moderate	Uncontrolled Respiratory

SECTION 5. PERSONNEL DATA

LAST NAME	FIRST NAME	MI	SEX	SSN	
Non-Responsive		A	M	Non-Responsive	MIL
		M			
		M			
		K			
		M			CIU MIL

SECTION 6. COMMENTS

No comments. See attached sheet. Survey conducted by Michele Serwan. Building contains 5 full-time military staff members, 1 part-time (3+ days/week) and 1 custodian (part-time 2 days per week). The full-time staff performs mainly administrative functions.


PRIVACY ACT STATEMENT

Title 5 US Code, Section 301; Executive Order 9397 authorizes the use of your Social Security Number as an identification number. The purpose of this information is to identify and monitor data relating each DA civilian and military employee exposed to a hazardous workplace or operation. The use of this information is to provide histories of exposures for any given worker.

Disclosure of your Social Security Number is not mandatory; however, nondisclosures may result in untimely provision of proper medical monitoring.


Appendix B

Building Layout



27 room = 1st floor = 7 samples

29 July 2003
7 October 2005



DRILL HALL

Building Fire Escape Plan

4

MENS ROOM

MENS ROOM

LADIES ROOM


CUSTODIAL ROOM

Co B DET 1
FSB
CDR/ISG
OFFICE

Co B DET 1
FSB
RNLCO OFFICE

Co B DET 3
DET 172 INFANTRY
VAULT

B Det
Sgt
IA Det
upper



Drill Hall

Lobby

FRONT

PLT ROOM

PLT ROOM
you find
HALL

PLT ROOM

(12)

2

Painted Room

poss. Asbestos on boiler.

DEF 172 HIT Storage

[Redacted]

Drill Hall

3

OHID

1

Kitchen


Kitchen Storage

6

Kitchen Storage

FIRE PLAN-OFFICE AREA

DRILL HALL




DO NOT REMOVE

OUTSIDE AREA

2nd floor
4-5 rooms =
1 sample

Spot to be
sampled



STAIRS
TO
DRILL HALL

you are
here

ROOMS

23

Appendix C

Sampling Sheets and Laboratory Analyses

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301 JH Old Bay Lane, Attn: NGB-AVN-SI,
State Military Reservation
Havre de Grace, Maryland 21078
Attention: [REDACTED]

Job Name: VTLYN209
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01

Chain Of Custody: 116193
Date Analyzed: 08/08/2003
Person Submitting: [REDACTED]
Report Date: 08-Aug-03

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0361038	VTLYN209-1	Flame	Wipe	*****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0361039	VTLYN209-2	Flame	Wipe	*****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0361040	VTLYN209-3	Flame	Wipe	*****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0361041	VTLYN209-4	Flame	Wipe	*****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0361042	VTLYN209-5	Flame	Wipe	*****	0.111	108.01 ug/ft ²	130 ug/ft ²	
0361043	VTLYN209-6	Flame	Wipe Blank	*****	N/A	12.00 ug	< 12 ug	
0361044	VTLYN209-7	Flame	Wipe	*****	0.111	108.01 ug/ft ²	790 ug/ft ²	
0361045	VTLYN209-8	Flame	Wipe	*****	0.111	108.01 ug/ft ²	17000 ug/ft ²	
0361046	VTLYN209-9	Flame	Wipe	*****	0.111	108.01 ug/ft ²	3800 ug/ft ²	
0361047	VTLYN209-10	Flame	Wipe	*****	0.111	108.01 ug/ft ²	1000 ug/ft ²	
0361048	VTLYN209-11	Flame	Wipe	*****	0.111	108.01 ug/ft ²	1000 ug/ft ²	
0361049	VTLYN209-12	Flame	Wipe Blank	*****	N/A	12.00 ug	< 12 ug	
0361050	VTLYN209-13	Flame	Wipe	*****	0.111	108.01 ug/ft ²	6400 ug/ft ²	
0361051	VTLYN209-14	Flame	Wipe	*****	0.111	108.01 ug/ft ²	1300 ug/ft ²	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

An AIHA (#8863), NVLAP (# 101143), & New York ELAP (#109920) Accredited Laboratory
4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

All rights reserved. AMA Analytical Services, Inc.

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301-1H Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation
Havre de Grace, Maryland 21078
Job Name: VTLYN209
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 0701
Chain Of Custody: 118890
Date Analyzed: 10/27/2003
Person Submitting: [Redacted]
Report Date: 27-Oct-03

Attention: [Redacted]

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analyst Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0404046	VTLYN209-15	Furnace	Wipe	*****	0.111	2.70 ug/ft ²	14 ug/ft ²	
0404047	VTLYN209-16	Furnace	Wipe	*****	0.111	2.70 ug/ft ²	5.4 ug/ft ²	
0404048	VTLYN209-17	Furnace	Wipe	*****	0.111	2.70 ug/ft ²	23 ug/ft ²	
0404049	VTLYN209-18	Furnace	Wipe Blank	*****	N/A	0.30 ug	0.3 ug	
0404050	VTLYN209-19	Furnace	Wipe	*****	0.111	67.51 ug/ft ²	130 ug/ft ²	
0404051	VTLYN209-20	Furnace	Wipe	*****	0.111	2.70 ug/ft ²	2.7 ug/ft ²	
0404052	VTLYN209-21	Furnace	Wipe	*****	0.111	67.51 ug/ft ²	120 ug/ft ²	
0404053	VTLYN209-22	Furnace	Wipe	*****	0.111	2.70 ug/ft ²	6.5 ug/ft ²	
0404054	VTLYN209-23	Furnace	Wipe	*****	0.111	2.70 ug/ft ²	7.9 ug/ft ²	
0404055	VTLYN209-24	Furnace	Wipe Blank	*****	N/A	0.30 ug	0.3 ug	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 800/R-93/200(M)-7420; Water: SM-3111B
Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids: EPA 800/R-93/200(M)-7421; Water: SM-3113B
N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per billion (ppb)

%Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)
Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted]

Non-Responsive

Technical Manager: [Redacted]

[Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AIHA air samples.

An AIHA (#8863), NVLAP (# 101143), & New York ELAP (#10920) Accredited Laboratory
4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301 JH Old Bay Lane, Attn: NGB-AVN-SL,
State Military Reservation
Havre de Grace, Maryland 21078

Job Name: VTLYN281
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 0701

Chain Of Custody: 118705
Date Analyzed: 10/16/2003
Person Submitting: [Redacted]
Report Date: 16-Oct-03

Attention: [Redacted]

Summary of Atomic Absorption Analysis for Lead

Page 1 of 1

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0402838	VTLYN281 -1	Furnace	Wipe	****	0.111	27.00 ug/ft ²	90 ug/ft ²	
0402839	VTLYN281 -2	Furnace	Wipe	****	0.111	13.50 ug/ft ²	78 ug/ft ²	
0402840	VTLYN281 -3	Furnace	Wipe	****	0.111	27.00 ug/ft ²	110 ug/ft ²	
0402841	VTLYN281 -4	Furnace	Wipe	****	0.111	135.01 ug/ft ²	830 ug/ft ²	
0402842	VTLYN281 -5	Furnace	Wipe	****	0.111	13.50 ug/ft ²	43 ug/ft ²	
0402843	VTLYN281 -6	Furnace	Wipe Blank	****	N/A	0.30 ug	0.39 ug	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B

Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7421; Water: SM-3113B

NA = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)

%Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted]

Non-Responsive


Technical Manager: [Redacted]

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

AN AIHA (#8863), NVLAP (#101143), & New York ELAP (#10920) Accredited Laboratory
4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

CERTIFICATE OF ANALYSIS



Client: National Guard Bureau
Address: 301-1H Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation
Hayre de Grace, Maryland 21078

Job Name: VTLVND209
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01

Chain Of Custody: 116193
Date Analyzed: 08/08/2003
Person Submitting: [Redacted]
Report Date: 08-Aug-03

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B
N/A = Not Applicable mg/kg = parts per million (ppm) by weight mg/L = parts per million (ppm)
%Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)
Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analysis: [Redacted] **Non-Responsive**
Technical Manager: [Redacted] **No n-Responsive**

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

An AIHA (#8863), NVLAP (# 101143), & New York ELAP (#10920) Accredited Laboratory
4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643



Submitted To: **Non-Responsive**
Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTRED210-A2 through VTWIN210-A3
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Filter
Method Reference:	NIOSH 7300
DCL Set ID No.:	03-S-3799
DCL Sample ID No.:	03-23284 through 03-23312
Sample Receipt Date:	8/4/2003
Preparation Date:	08/07/03
Analysis Date:	08/07/03

The samples were prepared and analyzed in accordance with NIOSH method 7300 using a Perkin Elmer 3000XL ICP.

The sample condition upon receipt was acceptable except where noted.

The results are in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive
[Redacted Signature]

Analyst

Non-Responsive
[Redacted Signature]

Reviewer

CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 280-8071, FAX 415 893-9469

Results

Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTRED210-A2	03-23284	0	ND	-
VTNEW209-A1	03-23285	210.24	ND	<0.005
VTNEW209-A2	03-23286	0	ND	-
VTBRA209-A1	03-23288	197.36	ND	<0.005
VTBRA209-A2	03-23289	0	ND	-
VTLYN209-A1	03-23290	186.67	ND	<0.005
VTLYN209-A2	03-23291	187.06	ND	<0.005
VTLYN209-A3	03-23292	0	ND	-
VTNOR213-A1	03-23293	376.81	ND	<0.003
VTNOR213-A2	03-23294	0	ND	-
VTLUD212-A1	03-23297	157.79	ND	<0.006
VTLUD212-A2	03-23298	275.40	ND	<0.004
VTLUD212-A3	03-23299	0	ND	-
VTWIN212-A1	03-23305	173.64	ND	<0.006
VTWIN212-A2	03-23306	0	ND	-
VTVER210-A1	03-23307	259.68	ND	<0.004
VTVER210-A2	03-23308	0	ND	-
VTRED210-A1	03-23309	158.68	ND	<0.006
VTWIN210-A1	03-23310	218.92	ND	<0.005
VTWIN210-A2	03-23311	193.56	ND	<0.005
VTWIN210-A3	03-23312	0	ND	-
	Prep Blank		ND	
% Recovery	LCS		99.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).

LCS = laboratory control sample.

Non-Responsive



Analyst

Non-Responsive



Reviewer

Industrial Hygiene Sampling Calculation Worksheet

National Guard Armory Location: LYN
Date: 7/29/2002

Sample 1

Sample Number: VTLYN209-A1

Pump: 647615

	Pre Flow Rate	Post Flow Rate
	2.509	2.478
	2.502	2.479
	2.497	2.477
	2.497	2.472
Average	2.501	2.477

Average Pre and Post **2.4889**

Time 1 11:31

Time 2 12:46

Total Time Sampled 1:15

Minutes Sampled 75.00

Volume 186.67 Liters

Sample 2

Sample Number: VTLYN209-A2

Pump: 648339

	Pre Flow Rate	Post Flow Rate
	2.533	2.468
	2.524	2.476
	2.516	2.458
	2.506	2.472
Average	2.520	2.469

Average Pre and Post **2.4941**

Time 1 12:15

Time 2 13:30

Total Time Sampled 1:15

Minutes Sampled 75.00

Volume 187.06 Liters

Appendix D

References

References

- Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration (current edition)
- American Society of Heating, Refrigerating and Air-Conditioning Engineers, Inc (ASHRAE) 62-2002, Ventilation for Acceptable Indoor Air Quality
- Instructions for Completing the Sampling of Army National Guard Armories, Lead Wipe Sampling Procedure included with the Request for Proposal
- Air Sampling for Lead - Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods
- Design Guide DG-415-2, Logistics Facilities, National Guard Bureau Installation Division, 14 December 1999
- Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998
- Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, 15 October 1990
- AR 385-10, The Army Safety Program, 29 February 2000
- Department of the Army Pamphlet (DA PAM) 40-501, Medical Services, Hearing Conservation Program, 10 December 1998
- DA PAM 40-503, Medical Services, Industrial Hygiene Program, 30 October 2000
- Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH) (current edition)
- Guidelines for Converting Indoor Firing Ranges to Other Uses, Headquarters, Department of the Army and the Air Force, NG PAM (AR) 385-16/ANGPAM 91-101, 31 January 1994
- 24 CFR, Part 35, Subpart B, Section 35-110, Definition of Lead-Based Paint, Housing and Urban Development, U. S. Department of Housing

Appendix E
Recommendations for
Surface Lead Dust in Armories

Subject: Recommendations for Surface Lead Dust in Armories

1. In armories that do not contain childcare facilities, the National Guard Bureau (NGB) Region North Industrial Hygiene Office recommends cleaning the areas in which sample results are greater than 200 micrograms per square foot ($1 \mu\text{g}/\text{ft}^2$). If a special function will be held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function. This guidance is based on professional judgment, risk assessments, adaptation of Occupational Safety and Health Administration (OSHA) guidance, and feasibility of cleaning to a certain level.

a. Environmental Protection Agency (EPA) standards (40 Code of Federal Regulations (CFR) 745.227(h)(3)) are not directly applicable because they are criteria for dust-lead hazards developed for floors ($40 \mu\text{g}/\text{ft}^2$) and windowsills ($250 \mu\text{g}/\text{ft}^2$) in residential dwellings and child occupied facilities. A child occupied facility is defined as a building, or portion of a building, constructed prior to 1978, visited regularly by the same child, 6 years of age or under, on at least two different days within any week (Sunday through Saturday period), provided that each day's visit lasts at least 3 hours and the combined weekly visit lasts at least 6 hours, and the combined annual visits last at least 60 hours. Most of the wipe samples in armories were collected in undisturbed areas and therefore, results are worst case scenarios and do not correlate to these standards.

b. OSHA has no specific requirement for work area surfaces. The lead standard (29 CFR 1910.1025(h)) states that all surfaces shall be maintained as free as practicable of accumulations of lead dust. In workplaces where lead dust is generated, surface levels may be much higher, but personnel exposures can be controlled by limiting airborne lead levels and following good cleanup and hygienic practices.

c. OSHA used to cite a level of $200 \mu\text{g}/\text{ft}^2$ in their Technical Manual and 29 CFR 1926.62 as guidance to its own inspectors for evaluating the cleanliness of lunchroom and locker room surfaces that are supposed to be kept as clean as possible.

d. In a report titled Derivation of Wipe Surface Screening Levels for Environmental Chemicals, the US Army Center for Health Promotion and Preventive Medicine (USACHPPM) has determined that $200 \mu\text{g}/\text{ft}^2$ is a safe surface contamination level. They have also applied these standards as the decontamination levels for surfaces in administrative offices.

e. It should be noted that levels above these recommendations do not necessarily mean there is a significant hazard to workers who are following good cleaning and hygienic practices since there is no correlation between wipe and air samples. Rather, we recommend these levels as a precautionary measure.

2. The NGB Occupational Health Branch is developing guidance for armories that are used as childcare facilities. All states will receive this guidance when it is completed. In the interim, we recommend the following actions:

- a. Clean all areas that will be accessible to children to the EPA dust-lead standard for children 6 years of age or under ($40 \mu\text{g}/\text{ft}^2$ on floors and $250 \mu\text{g}/\text{ft}^2$ on windowsills).
 - b. Refer to the local authorities' regulations since they can be more stringent than federal regulations.
 - c. Post signs in the area to inform people of the presence of lead dust and its effects.
 - d. If soldiers clean weapons in the facility change the policy so that they cannot clean their weapons in the facility, or if they are allowed to clean their weapons indoors, they must clean the area by wet wiping and mopping the area when they are done.
 - e. If the paint is peeling, contact the state Environmental Office to test for lead content and provide recommendations.
3. Air samples collected on individuals in the armory were well below OSHA's permissible exposure limit for lead (29 CFR 1910.1025(e)) of $0.05 \text{ mg}/\text{m}^3$ averaged over an 8-hour day. Therefore, based on these conditions there is currently no overexposure to personnel from lead dust in this building.

Industrial Hygiene Survey

Vermont Army National Guard (VT ARNG)

Prepared For: NGB ARNG– Region North IH Office

Survey Location:

Lyndonville Readiness Center
73 High Street
Lyndonville, VT 05851

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 26, 2011

AEI Project #: J11-601 4L VT Lyndonville RC

Non- [REDACTED], CIH, CSP
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Lyndonville Readiness Center**

Table of Contents

Executive Summary ii

1 Introduction 1

2 Evaluation Methods 1

3 Operations 1

4 Noise Hazards 1

5 Hazard Controls 2

Ventilation Systems 2

6 Physical Condition of the Facility and Personnel Concerns 2

Paint Chip and Dust Wipe Samples for Lead Contamination 2

Visual Inspection for Damaged Asbestos-Containing Materials 3

Visual Inspection for Water Damage and Mold Growth 3

Visual Inspection for Housekeeping Concerns 3

Lighting 3

Indoor Air Quality (IAQ) 4

Temperature and Relative Humidity 4

Carbon Dioxide (CO₂) and Carbon Monoxide (CO) 4

7 Conclusions 5

8 Limitations 5

List of Tables and Appendices

Table 1 - Results of Dust Wipe Sampling for the VT ARNG Lyndonville Readiness Center on October 26, 2011.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

Appendix A – Building Layout

Appendix B – Certificates of Analysis for Air, Dust Wipe and Bulk Samples

Appendix C – Photo Documentation

Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Lyndonville Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Lyndonville Readiness Center located at 73 High Street, Lyndonville, VT 05851. Non-██████████, CIH, CSP performed the evaluation on October 26, 2011. The point of contact for the facility was SFC Non-██████████. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Paint Chip and Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed in the Boiler Room. A bulk sample of the peeling paint contained 0.19% lead by weight which is less than the EPA and State of Vermont definitions of lead-based paint (0.5% by weight). Results of dust wipe samples collected throughout the facility were below the recommended maximum criterion for surface contamination of lead (200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$)) in all areas sampled except for a sample collected on the heater in the former firing range ($<340 \mu\text{g}/\text{ft}^2$). No lead was detected in this sample, but the limit of detection was above the recommended maximum due to insufficient sample size. Lead was not detected in any of the samples collected in the former firing range.

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there were any suspect asbestos-containing material and its condition. Damaged suspect floor tile and mastic were observed and sampled from the doorway to the Administration Office. The EPA defines an asbestos-containing material as one percent (1%) or more asbestos by visual estimation. The submitted floor tile and mastic samples contained 2% and 5% Chrysotile asbestos, respectively. The broken floor tile also creates a possible tripping hazard.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. Water stains were observed on the ceiling in the kitchen area and on ceiling tiles in several areas throughout the building. These stains are most likely old because the roof was replaced within the past year. No pooling of water, wet areas or mold was observed.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping needed some improvement especially in the janitor's closet and the kitchen. The building was being renovated which may have contributed to storage and housekeeping problems.

Lighting: A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in the janitor's closet and the gym. The illumination measurements indoors ranged from 5 foot candles (fc) to 1,000 fc.

Indoor Air Quality: Temperature and relative humidity measurements were within the comfort ranges for the winter season on the day of the survey. The outdoor temperature and relative humidity were 51.0° F and 37.4% on the day of monitoring. Indoor concentrations of carbon dioxide (CO_2) and carbon monoxide (CO) were below the guidelines in all areas.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Lyndonville Readiness Center**

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and MSDSs for some new custodial products were required per OSHA 29 CFR 1910.1200.

Overall, the Lyndonville Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Lyndonville Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Lyndonville Readiness Center located at 73 High Street, Lyndonville, VT 05851. Non-██████████, CIH, CSP performed the evaluation on October 26, 2011. The point of contact for the facility was SFC Non-██████████. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

The Lyndonville Readiness Center was built in the 1950s and was being renovated at the time of the survey. The readiness center is staffed by 5 administrative personnel. The operations conducted at the facility include supply and administrative duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the Lyndonville Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) evaluations of operations including operation description, sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the Lyndonville facility consist exclusively of supply and administrative duties. Some vehicle stenciling is performed. No other maintenance of vehicles or other physical tasks are performed at the facility. Ground maintenance and upkeep of the building are the responsibility of the state employed Armorer and not part of the duties of National Guard personnel.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Lyndonville Readiness Center**

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility.

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; potential ergonomic problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were collected in select areas.

Paint Chip and Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed in the Boiler Room and a bulk sample was sent to AMA Analytical Services, Inc. (AMA) of Lanham, MD for lead analysis. The sample contained 0.19% lead by weight which would not be considered lead-based by the Environmental Protection Agency (EPA) and the State of Vermont definitions (0.5% by weight). Certificates of analysis are included in Appendix B.

To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected using ghost wipes and 10 centimeter (cm) x 10cm templates. The Environmental Protection Agency (EPA) and the State of Vermont limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. All wipe samples collected from the facility were below the recommended maximum except for the sample collected from a heater in the former firing range ($<340 \mu\text{g}/\text{ft}^2$). No lead was detected in this sample, but the limit of detection was above the recommended maximum due to insufficient sample size. Lead was not detected in any of the other samples collected in the former firing range. Results are given in Table 1 and certificates of analysis are included in Appendix B.

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
Lyndonville Readiness Center on October 26, 2011.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
LYN – 01	Drill Hall – floor	<110
LYN – 02	Drill Hall – electrical box	<110
LYN – 03	Drill Hall – floor	<110
LYN – 04	Drill Hall – vent	<120
LYN – 05	Drill Hall – floor	<110
LYN – 06	Former Firing Range – floor	<110

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Lyndonville Readiness Center**

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
Lyndonville Readiness Center on October 26, 2011.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
LYN – 07	Former Firing Range – treadmill	<110
LYN – 08	Former Firing Range – table	<110
LYN – 09	Former Firing Range – heater	<340
LYN – 10	Former Firing Range – floor	<110
LYN – 11	Kitchen – serving counter	<110
LYN – 12	Supply Office – floor	<110
LYN - 13	2 nd Floor Classroom – floor	<110

*The recommended maximum level for adult exposures is 200 $\mu\text{g}/\text{ft}^2$ lead on surfaces.

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). Damaged suspect floor tile and mastic were observed and sampled from the doorway to the Administration Office. The sample was submitted to AMA Analytical Services, Inc. of Lanham, MD 20706 (NIST-NVLAP Accreditation No. 101143-0) for analysis by Polarized Light Microscopy (PLM) using EPA method 600/R-93/116. The EPA defines an asbestos-containing material as one percent (1%) or more asbestos by visual estimation. The submitted floor tile and mastic samples contained 2% and 5% Chrysotile asbestos, respectively. Certificates of analysis are included in Appendix B. The broken floor tile also creates a possible tripping hazard.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. Water stains were observed on the ceiling in the kitchen area and on ceiling tiles in several areas throughout the building. These stains are most likely old because the roof was replaced within the past year. No pooling of water, wet areas or mold was observed.

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping needed some improvement especially in the janitor's closet and the kitchen. The building was being renovated which may have contributed to storage and housekeeping problems.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on March 9, 2011, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in a few areas: the janitor's closet and the gym. The

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Lyndonville Readiness Center**

illumination measurements indoors ranged from 5 foot candles (fc) to 1,000 fc. The complete results of the evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Plus Model 8554, factory calibrated in February, 2011. Temperature, relative humidity and carbon dioxide (CO₂) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 3. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30 and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

Table 3 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 69.0 to 73.9° F and 35.5 to 39.9% Rh. Temperatures and relative humidity were all within the winter comfort ranges in the areas monitored. The outdoor temperature and relative humidity was 51.0° F and 37.4% on the day of monitoring.

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1–2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 571 to 788 parts per million (ppm). CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange.

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 0.1 to 0.7 ppm; therefore, concentrations

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Lyndonville Readiness Center**

are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

Additional Information

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updating of the MSDS notebook was necessary as per OSHA 29 CFR 1910.1200 requirements.

7 Conclusions

The results of the evaluation indicated no concerns with the following at the facility: contamination of clean air sources, peeling lead-based paints, noise hazards and visible mold. The results of the evaluation indicated industrial hygiene concerns in the following areas: lighting, damaged asbestos-containing floor tile and mastic, and some hazard communication issues. Overall, the Lyndonville Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.

9 References

1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.
3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.
4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Lyndonville Readiness Center**

5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2011.
6. Army Regulation (AR) 420-70 Buildings and Structures, 10 October 1997.
7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 28 March 2009.
8. Army Regulation (AR) 420-1 Army Facilities Management, 28 March 2009.
9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.
10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.
12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.
13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".
15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.

Appendix A Building Layout

LYNDONVILLE ARMORY

VERMONT ARMY NATIONAL GUARD

Lyndonville Army National Guard Armory renovation project includes the addition of a kitchen, storage room, mezzanine, and

new construction with steel framing built in 1955 with a

double

of manufactured metal

added by the renovation

REVIEW

- 087 SF
- 79 SF
- 45 SF
- 505 SF



1 MAIN FLOOR PLAN -- EXISTING CONDITIONS
1/16" = 1'-0"

2 2nd FLOOR PLAN --
1/16" = 1'-0"

Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	Lyndonville RC	Chain Of Custody:	511731
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Lyndonville, VT	Date Submitted:	11/1/2011
Attention:	Non-Responsive	Job Number:	J11-601	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/7/2011
				Report Date:	11/8/2011

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
12010595	Lyn-01	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010596	Lyn-02	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010597	Lyn-03	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010598	Lyn-04	Flame	Wipe	****	0.104	120 ug/ft ²	<12	<120 ug/ft ²	
12010599	Lyn-05	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010600	Lyn-06	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010601	Lyn-07	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010602	Lyn-08	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010603	Lyn-09	Flame	Wipe	****	0.035	340 ug/ft ²	<12	<340 ug/ft ²	
12010604	Lyn-10	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010605	Lyn-11	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010606	Lyn-12	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010607	Lyn-13	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010610	Lyn-Blk-02	Flame	Paint Chip	****	N/A	0.0075 %Pb		0.19 %Pb	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.

AMA Analytical Services, Inc.



A Specialized Environmental Laboratory

CERTIFICATE OF ANALYSIS



Client: National Guard Bureau	Job Name: Lyndonville RC	Chain Of Custody: 511731
Address: 301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location: Lyndonville, VT	Date Submitted: 11/1/2011
	Job Number: J11-601	Person Submitting: Non-Responsive
	P.O. Number: W912K6-09-A-0003	Date Analyzed: 11/7/2011
Attention: Non-Responsive		Report Date: 11/8/2011

Summary of Atomic Absorption Analysis for Lead

Page 2 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	----------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm)
 %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb)

See QC Summary for analytical results of quality control samples associated with these samples.

Note: All samples were received in good condition unless otherwise noted.

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Air and Wipe results are not corrected for any blank results

Final results for air and wipe samples are based on client supplied information nor verified by this laboratory.

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Analyst

Non-Responsive

Technical Manager

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



AMA Analytical Services, Inc.

Focused on Results www.ama-lab.com
AIHA (#100470) NVLAP (#101143-0) NY ELAP (10920)
4475 Forbes Blvd. • Lanham, MD 20706
(301) 459-2640 • (800) 346-0961 • Fax (301) 459-2643

CHAIN OF CUSTODY

(Please Refer To This Number For Inquiries)

511731

P.1/2

Mailing/Billing Information:

1. Client Name: National Guard Bureau
2. Address 1: 301-JH Old Bay Lane
3. Address 2: Attn: NGB-AVN-SI, State Military Reservation
4. Address 3: Havre de Grace, Maryland 21078
5. Phone #: (410) 942-0273 Fax #: (410) 942-0254

Submittal Information:

1. Job Name: Lyndonville PC
2. Job Location: Lyndonville, VT
3. Job #: 17-1001 PO #: W912KG-09-A-0003
4. Contact Person: Non-Responsive
5. Submitted by: Non-Responsive

Reporting Information (Results will be provided as soon as technically feasible):

Form with sections: AFTER HOURS (must be pre-scheduled), NORMAL BUSINESS HOURS, REPORT TO: (ariaenviro.com), and checkboxes for report options.

Asbestos Analysis

PCM Air - Please Indicate Filter Type:
NIOSH 7400 (QTY)
Fiberglass (QTY)
TEM Air - Please Indicate Filter Type:
AHERA (QTY)
NIOSH 7402 (QTY)
Other (specify) (QTY)
PLM Bulk
EPA 600 - Visual Estimate (QTY)
EPA Point Count (QTY)
NY State Friable 198.1 (QTY)
Grav. Reduction ELAP 198.6 (QTY)
Other (specify) (QTY)
MISC
Vermiculite
Asbestos Soil PLM (Qual PLM (QTY) PLM/TEM (Qual PLM/TEM (QTY)

TEM Bulk

ELAP 198.4/Chatfield (QTY)
NY State PLM/TEM (QTY)
Residual Ash (QTY)

TEM Dust

Qual. (pres/abs) Vacuum Dust (QTY)
Quan. (s/area) Vacuum D5755-95 (QTY)
Quan. (s/area) Dust D6480-99 (QTY)

TEM Water

Qual. (pres/abs) (QTY)
ELAP 198.2/EPA 100.2 (QTY)
EPA 100.1 (QTY)

All samples received in good condition unless otherwise noted.
(TEM Water samples °C)

Metals Analysis

Pb Paint Chip (QTY)
Pb Dust Wipe (wipe type 10x10) 12 (QTY) (13 total)
Pb Air (QTY)
Pb Soil/Solid (QTY)
Pb TCLP (QTY)
Drinking Water Pb (QTY) Cu (QTY) As (QTY)
Waste Water Pb (QTY) Cu (QTY) As (QTY)
Pb Furnace (Media) (QTY)

Fungal Analysis

Collection Apparatus for Spore Traps/Air Samples:
Collection Media:
Spore-Trap (QTY) Surface Vacuum Dust (QTY)
Surface Swab (QTY) Culturable ID Genus (Media) (QTY)
Surface Tape (QTY) Culturable ID Species (Media) (QTY)
Other (Specify) (QTY)

Table with columns: CLIENT ID NUMBER, SAMPLE INFORMATION (SAMPLE LOCATION IDENTIFICATION, DATE, VOLUME (LITERS), Cm WIPE AREA), ANALYSIS (TEM, PCM, PLM, LEAD, MOLD, AIR, BULK, DUST, MATRICES), CLIENT CONTACT (LABORATORY STAFF ONLY) with Date/Time, Contact, By fields.

LABORATORY STAFF ONLY: (CUSTODY)

1. Date/Time RCVD: 11/11/11 @ 1015 Via: FedEx By (Print): WMM Sign:
2. Date/Time Analyzed: 1/1/11 @ By (Print): Sign:
3. Results Reported To: Via: Date: 1/1/11



AMA Analytical Services, Inc.

Focused on Results www.amalab.com
AIHA (#100470) NVLAP (#101143-0) NY ELAP (10920)
4475 Forbes Blvd. • Lanham, MD 20706
(301) 459-2640 • (800) 346-0961 • Fax (301) 459-2643

CHAIN OF CUSTODY

(Please Refer To This Number For Inquires)

COCK
S11731
P2/2

Mailing/Billing Information:

- Client Name: National Guard Bureau
- Address 1: 301-JH Old Bay Lane
- Address 2: Attn: NGB-AVN-SI, State Military Reservation
- Address 3: Havre de Grace, Maryland 21078
- Phone #: (410) 942-0273 Fax #: (410) 942-0254

Submittal Information:

- Job Name: Lymdonville RC
- Job Location: Lymdonville, VT
- Job #: J11-601
- Contact Person: Non-Responsive RG #: WB12KG-09-A-0003
- Submitted by: [Redacted] Signature: Non-Responsive

Reporting Information (Results will be provided as soon as technically feasible):

AFTER HOURS (must be pre-scheduled)

Immediate Date Due: _____

24 Hours Time Due: _____

Comments: _____

NORMAL BUSINESS HOURS

Immediate 3 Day

Next Day 5 Day +

2 Day Date Due: _____

Results Required By Noon (Every Attempt Will Be Made to Accommodate)

REPORT TO:

Include COC/ELAP/NIOSH with Report

Email: Non-Responsive

Fax: Non-Responsive

Verbal: Non-Responsive

REPORT TO: anaenviro.com
@us.army.mil
@us.army.mil

Asbestos Analysis

- PCM Air** - Please Indicate Filter Type:
- NIOSH 7400 (QTY)
 - Fiberglass (QTY)
- TEM Air** - Please Indicate Filter Type:
- AHERA (QTY)
 - NIOSH 7402 (QTY)
 - Other (specify) _____ (QTY)
- PLM Bulk**
- EPA 600 - Visual Estimate (QTY)
 - EPA Point Count (QTY)
 - NY State Friable 198.1 (QTY)
 - Grav. Reduction ELAP 198.6 (QTY)
 - Other (specify) _____ (QTY)

TEM Bulk

- ELAP 198.4/Chatfield (QTY)
- NY State PLM/TEM (QTY)
- Residual Ash (QTY)

TEM Dust

- Qual. (pres/abs) Vacuum/Dust (QTY)
- Quan. (s/area) Vacuum D5755-95 (QTY)
- Quan. (s/area) Dust D6480-99 (QTY)

TEM Water

- Qual. (pres/abs) (QTY)
- ELAP 198.2/EPA 100.2 (QTY)
- EPA 100.1 (QTY)

All samples received in good condition unless otherwise noted. (TEM Water samples _____ °C)

Matrix Analysis

- Pb Paint Chip (QTY)
- Pb Dust Wipe (wipe-type) (QTY) 1 (13 total)
- Pb Air (QTY)
- Pb Sol/Solid (QTY)
- Pb TCLP (QTY)
- Drinking Water Pb (QTY) Cu (QTY) As (QTY)
- Waste Water Pb (QTY) Cu (QTY) As (QTY)
- Pb Furnace (Media) (QTY)

Spore Analysis

- Collection Apparatus for Spore Traps/Air Samples:
- Collection Media:
- Spore Trap (QTY)
 - Surface Swab (QTY)
 - Surface Tape (QTY)
 - Other (Specify) _____ (QTY)
 - Surface Vacuum Dust (QTY)
 - Culture ID Gema (Media) (QTY)
 - Culture ID Species (Media) (QTY)

CLIENT ID NUMBER	SAMPLE INFORMATION			VOLUME (GAL)	WIPE AREA	ANALYSIS										CLIENT CONTACT			
	SAMPLE LOCATION IDENTIFICATION	DATE				TEM	PCM	PLM	LEAD	MOLD	AIR	BULK	DUST	MATRIX	SPORE TRAP	TAPE	SWAB	Date/Time:	Contact:
Lyn-13		10/26			10X10														
Lyn-01K-01	ETmasteric																		
Lyn-01K-02	chip																		

LABORATORY STAFF ONLY: (CUSTODY)

- Date/Time RCVD: _____ / _____ / _____ @ _____ Via: _____ By (Date): _____ Sign: _____
- Date/Time Analyzed: _____ / _____ / _____ @ _____ By (Date): _____ Sign: _____
- Results Reported To: _____ Via: _____ Date: _____ / _____ / _____

Non-Responsive



CERTIFICATE OF ANALYSIS

Client:	National Guard Bureau	Job Name:	Lyndonville RC	Chain Of Custody:	511731
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Lyndonville, VT	Date Analyzed:	11/8/2011
		Job Number:	J11-601	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003		

Attention: Non-Responsive

Summary of Polarized Light Microscopy

AMA Sample Number	Client Sample #	Total Asbestos	Chrysotile Percent	Amosite Percent	Crocidolite Percent	Other Asbestos Percent	Mineral Wool Percent	Fiberglass Percent	Organic Percent	Synthetic Percent	Other Percent	Particulate Percent	Sample Type	Sample Color	Homogeneity	Analyst ID	Comments
12010608	Lyn-Blk-01 FT	2	2	--	--	--	--	--	--	--	--	98	FT	Beige	Homogeneous	PC	
12010609	Lyn-Blk-01 M	5	5	--	--	--	--	--	--	--	--	95	MS	Black	Homogeneous	PC	

The following footnotes only apply to those samples which the total asbestos result is flagged with a note number.

- TEM RECOMMENDATION** - Please note, due to resolution limitations with optical microscopy and/or interference from matrix components of this sample, results which are reported via PLM as negative or trace (<1%) for asbestos may contain a significant quantity of asbestos. It is recommended that the additional analytical technique of TEM be used to check for asbestos fibers below the resolution limits of optical microscopy.
- MATRIX REDUCTION RECOMMENDATION** - Please note, due to interference from the matrix components of this sample, results which are reported via PLM as negative or trace (<1%) for asbestos may contain a significant quantity of asbestos which is obscured from view. It is recommended that the additional preparation technique of gravimetric reduction be performed on this sample to minimize the obscuring effects of matrix components, followed by reanalysis by PLM and/or TEM.

Analysis Method - EPA/600/R-93/116 dated July 1993

NAD = "No Asbestos Detected" TR = "Trace equals less than 1% of this component"

Uncertainty: For samples containing asbestos in range of 1-10% the CV is 0.43, 11-35% CV=0.55, >35 CV=0.23

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Technical Director

Non-Responsive

Analyst(s)

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.

Appendix C Photo Documentation

Lyndonville, VT Readiness Center




Lyndonville RC Exterior



Drill Hall



View of Fitness Center from Drill Hall



Fitness Center

Lyndonville, VT Readiness Center



Fitness Center 2



Storage Room



Drill Hall 2




Bunk Room

Lyndonville, VT Readiness Center



Locker Room



Janitor's Closet



Janitor's Closet Storage Cabinet



Janitor's Closet Storage Shelf

Lyndonville, VT Readiness Center



MSDSs in Janitor's Closet



Remodeled Bathroom



Offices

Posted to NGB FOIA Reading Room
May, 2018



Kitchen

Lyndonville, VT Readiness Center



Kitchen 2



Kitchen 3



Water Damage on Ceiling



Water Damage on Ceiling

Lyndonville, VT Readiness Center



[Empty box]



Flammable Storage Cabinet



Flammable Storage Cabinet 2



Supply Room

Lyndonville, VT Readiness Center



2nd Floor Classroom Area



View from Second Floor



Damaged Floor Tile



Office

Lyndonville, VT Readiness Center



Boiler Room



Boiler Room – water incursion



Boiler Room



Vent in Drill Hall

Appendix D
IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Lyndonville	IAQ						Light			
Date	10/26/2011	Inspector	Non-	Instrument	Q-trak 7565-X						Instrument	Cal-Light 400	
Facility Description	Lyndonville RC			Serial Number	7565X0839020						Serial Number	K070003	
Weather Conditions	Cool, Clear			Last Calibration	Feb-11						Last Calibration	9-Mar-11	
Location/Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
Drill Hall	1	10:52	70.7		37.1		571		0.3		50-102		30-50
Bunk Room	1	10:55	69.0		38.6		576		0.1		14-52		5
Women's Bathroom	1	10:55	71.5		36.0		700		0.1		80-100		5
JC	1	10:56									5-8	X	30
Office 4B	1	10:56									55		30-50
R&R Office	2	11:00	73.9		38.4		788		0.4		30-80		30-50
Kitchen	1	10:58	72.8		35.5		619		0.4		60-94		50
Food Storage	1	10:58	73.0		35.8		614		0.4		70-85		30
Kit Storage	1	10:59	73.5		35.9		638		0.5		65-70		30
Supply Room	3	11:01	73.1		36.8		617		0.4		40-80		30
Drill Hall Storage	1	11:02									45-50		30
Gym	1	11:03	73.4		36.5		615		0.7		18-80	X	30
Storage Room	1	11:08	70.7		37.2		614		0.7		30-67		30
Admin Office	2	11:09	70.9		38.6		632		0.4		40-70		30-50
Admin Readiness Office	2	11:10	72.3		38.1		783		0.6		60-155		30-50
NCO Office	1	11:10	73.4		37.3		683		0.3		50-300		30-50
Center office	1	11:13									50-90		30-50
Copier Area	1	11:13									40-95		30-50
Second Floor Computer Room	1	11:50	71.8		39.7		717		0.4		40-103		30-50
Command Office	3	11:52	70.9		39.9		721		0.6		40-100		30-50
Mezzanine Area	1	11:53									80-1,000		30
Outside		12:16	51.0		37.4		413		1.3				

Industrial Hygiene Survey

Vermont Army National Guard (VTARNG)

Prepared For: NGB ARNG– Region North IH Office

Survey Location:

Lyndonville Readiness Center
73 High Street
Lyndonville, VT 05851

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 24, 2012

AEI Project #: J12-686 3m VT Lyndonville RC

Non- [REDACTED], CIH, CSP
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Lyndonville Readiness Center**

Table of Contents

Executive Summary ii

1 Introduction 1

2 Evaluation Methods 1

3 Operations 1

4 Noise Hazards 1

5 Hazard Controls 1

Ventilation Systems 1

6 Physical Condition of the Facility and Personnel Concerns 2

Paint Chip and Dust Wipe Samples for Lead Contamination 2

Visual Inspection for Damaged Asbestos-Containing Materials 3

Visual Inspection for Water Damage and Mold Growth 3

Visual Inspection for Housekeeping Concerns 3

Lighting 3

Indoor Air Quality (IAQ) 3

Temperature and Relative Humidity 4

Carbon Dioxide (CO₂) and Carbon Monoxide (CO) 4

7 Conclusions 4

8 Limitations 5

List of Tables and Appendices

Table 1 - Results of Dust Wipe Sampling for the VTARNG Lyndonville Readiness Center on October 24, 2012.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

Appendix A – Building Layout

Appendix B – Certificates of Analysis for Air, Dust Wipe and Bulk Samples

Appendix C – Photo Documentation

Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Lyndonville Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VTARNG) Lyndonville Readiness Center located at 73 High Street, Lyndonville, VT 05851. Non-██████████, CIH, CSP performed the evaluation on October 24, 2012. The point of contact for the facility was SSG Non-██████████. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Paint Chip and Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed in the Boiler Room. A bulk sample of the peeling paint contained 0.19% lead by weight which is less than the EPA and State of Vermont definitions of lead-based paint (0.5% by weight). Results of dust wipe samples collected throughout the facility were below the recommended maximum criterion for surface contamination of lead (200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$)) in all areas sampled except for a sample collected on the heater in the former firing range ($<340 \mu\text{g}/\text{ft}^2$). No lead was detected in this sample, but the limit of detection was above the recommended maximum due to insufficient sample size. Lead was not detected in any of the samples collected in the former firing range.

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). No damaged suspect material was observed that was not addressed in the 2011 survey.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. Water stains were observed on the ceiling in the kitchen area and on ceiling tiles in several areas throughout the building. These stains are most likely old because the roof was replaced within the last two years. Moisture fogged windows were observed on the 2nd floor. One area of the roof in the Drill Hall was being repaired due to leaks. No pooling of water, wet areas or mold was observed. Leaks should be repaired and damaged or leaky windows should be replaced when possible.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping needed some improvement to reduce accumulated dust, cobwebs and clutter.

Lighting: A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in the janitor's closet and the gym. The illumination measurements indoors ranged from 1 foot candles (fc) to 400 fc.

Indoor Air Quality: Temperature and relative humidity measurements were mostly within the comfort ranges for the winter season on the day of the survey. The outdoor temperature and relative humidity were 49.9° F and 45.0% on the day of monitoring. Indoor concentrations of carbon dioxide (CO_2) and carbon monoxide (CO) were below the guidelines in all areas.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Lyndonville Readiness Center**

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updating of the MSDS notebooks near flammable cabinets and in the janitor's closet was necessary as per OSHA 29 CFR 1910.1200 requirements. MSDSs for products no longer used should be "retired" and put in a separate section of the notebooks.

Overall, the Lyndonville Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Lyndonville Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VTARNG) Lyndonville Readiness Center located at 73 High Street, Lyndonville, VT 05851. Non- [REDACTED], CIH, CSP performed the evaluation on October 24, 2012. The point of contact for the facility was SSG Non- [REDACTED]. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

The Lyndonville Readiness Center was built in the 1950s and was renovated in 2011. The readiness center is staffed by 4 administrative personnel. The operations conducted at the facility include supply and administrative duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the Lyndonville Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) evaluations of operations including operation description, sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the Lyndonville facility consist exclusively of supply and administrative duties. Some vehicle stenciling is performed. No other maintenance of vehicles or other physical tasks are performed at the facility. Ground maintenance and upkeep of the building are the responsibility of the state employed Armorer and not part of the duties of National Guard personnel.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Lyndonville Readiness Center**

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were collected in select areas.

Paint Chip and Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. No peeling paint was observed. To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected using ghost wipes and 10 centimeter (cm) x 10cm templates. The Environmental Protection Agency (EPA) and the State of Vermont limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. All wipe samples collected from the facility were below the recommended maximum. Results are given in Table 1 and certificates of analysis are included in Appendix B.

**Table 1 – Results of Dust Wipe Sampling for VTARNG
Lyndonville Readiness Center on October 24, 2012.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
LYN – 01	Drill Hall – center of floor	<110
LYN – 02	Drill Hall – floor near bay door	<110
LYN – 03	Drill Hall – top of mobile food service island	<110
LYN – 04	Drill Hall – floor under basketball hoop	<110
LYN – 05	Drill Hall – floor near former range	<110
LYN – 06	Former Firing Range – Fintess center – front of treadmill	<110
LYN – 07	Former Firing Range – Classroom - floor covering bullet trap area	<110
LYN – 08	Kitchen – top of microwave	<110
LYN – 09	Mezzanine storage – floor	<110
LYN – 10	2 nd Floor Classroom – painted window sill	<110
LYN – 11	2 nd Floor Classroom – floor	<110

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Lyndonville Readiness Center**

**Table 1 – Results of Dust Wipe Sampling for VTARNG
Lyndonville Readiness Center on October 24, 2012.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
LYN – 12	Kitchen – metal window sill	<110

*The recommended maximum level for adult exposures is 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) lead on surfaces.

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). No damaged suspect material was observed that was not addressed in the 2011 survey.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. Water stains were observed on the ceiling in the kitchen area and on ceiling tiles in several areas throughout the building. These stains are most likely old because the roof was replaced within the last two years. Moisture fogged windows were observed on the 2nd floor. One area of the roof in the Drill Hall was being repaired due to leaks. No pooling of water, wet areas or mold was observed.

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping needed some improvement due to dust accumulation, cobwebs and clutter.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on April 16, 2012, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in several areas. The illumination measurements indoors ranged from 1 foot candles (fc) to 400 fc. The complete results of the evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Model 7656X, factory calibrated in March, 2012. Temperature, relative humidity and carbon dioxide (CO₂) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 3. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Lyndonville Readiness Center**

and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

Table 3 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 69.0 to 73.3° F and 22.9 to 38.7% Rh. Temperatures and relative humidity were mostly within the winter comfort ranges in the areas monitored. The outdoor temperature and relative humidity was 49.9° F and 45.0% on the day of monitoring.

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1–2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 505 to 718 parts per million (ppm), and the outdoor measurement was 373 ppm. CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange.

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 0.1 to 3.0 ppm; therefore, concentrations are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

Additional Information

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updating of the MSDS notebooks near flammable cabinets and in the janitor's closet was necessary as per OSHA 29 CFR 1910.1200 requirements. MSDSs for products no longer used should be "retired" and put in a separate section of the notebooks.

7 Conclusions

The results of the evaluation indicated few concerns at the facility. Overall, the Lyndonville Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Lyndonville Readiness Center**

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.

9 References

1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.
3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.
4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.
5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2011.
6. Army Regulation (AR) 420-70 Buildings and Structures, 11 November 1997.
7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 13 December 2007.
8. Army Regulation (AR) 420-1 Army Facilities Management, 12 February 2008, RAR 24 August 2012.
9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.
10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Lyndonville Readiness Center**

12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.
13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".
15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.

Appendix A Building Layout

LYNDONVILLE ARMORY

VERMONT ARMY NATIONAL GUARD

Lyndonville Army National Guard Armory renovation project includes the addition of a kitchen, storage room, mezzanine, and

new construction with steel framing built in 1955 with a

double

and manufactured metal

added by the renovation

REVIEW

- 087 SF
- 79 SF
- 45 SF
- 505 SF



1 MAIN FLOOR PLAN -- EXISTING CONDITIONS
1/16" = 1'-0"

2 2nd FLOOR PLAN --
1/16" = 1'-0"

Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples



CERTIFICATE OF ANALYSIS



Client: National Guard Bureau	Job Name: Lyndonville RC	Chain Of Custody: 514360
Address: 301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location: Lyndonville, VT	Date Submitted: 11/2/2012
	Job Number: J12-685	Person Submitting: Non-Responsive
	P.O. Number: W912K6-09-A-0003	Date Analyzed: 11/8/2012
Attention: Non-Responsive		Report Date: 11/9/2012

Summary of Atomic Absorption Analysis for Lead

Page 1 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
13010493	LYN-W 01	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010494	LYN-W 02	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010495	LYN-W 03	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010496	LYN-W 04	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010497	LYN-W 05	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010498	LYN-W 06	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010499	LYN-W 07	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010500	LYN-W 08	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010501	LYN-W 09	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010502	LYN-W 10	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010503	LYN-W 11	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010504	LYN-W 12	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS



Client: National Guard Bureau	Job Name: Lyndonville RC	Chain Of Custody: 514360
Address: 301-JH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location: Lyndonville, VT	Date Submitted: 11/2/2012
Attention: Non-Responsive	Job Number: J12-685	Person Submitting: Non-Responsive
	P.O. Number: W912K6-09-A-0003	Date Analyzed: 11/8/2012
		Report Date: 11/9/2012

Summary of Atomic Absorption Analysis for Lead

Page 2 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	----------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm)
 %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb)

See QC Summary for analytical results of quality control samples associated with these samples.

Note: All samples were received in good condition unless otherwise noted.

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Air and Wipe results are not corrected for any blank results

Final results for air and wipe samples are based on client supplied information nor verified by this laboratory.

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Analyst:

Non-Responsive

Technical Manager:

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



AMA Analytical Services, Inc.
 Focused on Results www.amalab.com
 AIHA (#100470) NVLAP (#101143-0) NY ELAP (10920)
 4475 Forbes Blvd. • Lanham, MD 20706
 (301) 459-2640 • (800) 346-0961 • Fax (301) 459-2643

BEST AVAILABLE COPY

(Please Refer To This
 Number For Inquires)

CHAIN OF CUSTODY

514360

Mailing/Billing Information:

- Client Name: National Guard Bureau
- Address 1: 301-IH Old Bay Lane
- Address 2: Attn: NGB-AVN-SI, State Military Reservation
- Address 3: Hayre de Grace, Maryland 21078
- Phone #: (410) 942-0273 Fax #: (410) 942-0254

Submittal Information:

- Job Name: Lyndonville RC
- Job Location: Lyndonville, VT
- Job #: 12-085 PO #: W912K6-09-A-0003
- Contact Person: Non-Responsive
- Submitted by: Non-Responsive Signature: Non-Responsive

Reporting Info (Results provided as soon as technically feasible). If no TAT/Reporting Info is provided, AMA will assign defaults of 5-Day and email mix to contacts on file.

AFTER HOURS (must be pre-scheduled) <input type="checkbox"/> Immediate Date Due: _____ <input type="checkbox"/> 24 Hours Time Due: _____ Comments: _____		NORMAL BUSINESS HOURS <input type="checkbox"/> Immediate <input type="checkbox"/> 3 Day <input type="checkbox"/> Next Day <input checked="" type="checkbox"/> 5 Day + <input type="checkbox"/> Results Required By Noon <input type="checkbox"/> 2 Day Date Due: <u>11/9/12</u>		REPORT TO: <input checked="" type="checkbox"/> Include <u>Non-Responsive</u> with Report <input checked="" type="checkbox"/> Email: <u>ariaenviro.com</u> <input type="checkbox"/> Fax: <u>us.army.mil</u> <input type="checkbox"/> Verbal: <u>us.army.mil</u>	
--	--	--	--	---	--

Asbestos Analysis

- *PCM Air - Please Indicate Filter Type:
 NIOSH 7400 (QTY)
 Fiberglass (QTY)
 TEM Air* - Please Indicate Filter Type:
 AHERA (QTY)
 NIOSH 7402 (QTY)
 Other (specify) _____ (QTY)
 PLM Bulk
 EPA 600 - Visual Estimate (QTY)
 EPA Point Count (QTY)
 NY State Friable 198.1 (QTY)
 Grav. Reduction ELAP 198.6 (QTY)
 Other (specify) _____ (QTY)

TEM Bulk

- ELAP 198.4/Chatfield (QTY)
 NY State PLM/TEM (QTY)
 Residual Ash (QTY)
 TEM Dust*
 Qual. (pres/abs) Vacuum/Dust (QTY)
 Quan. (s/area) Vacuum D5755-95 (QTY)
 Quan. (s/area) Dust D6480-99 (QTY)

TEM Water

- Qual. (pres/abs) (QTY)
 ELAP 198.2/EPA 100.2 (QTY)
 EPA 100.1 (QTY)

All samples received in good condition unless otherwise noted.
 (TEM Water samples _____ °C)

Metals Analysis

- Pb Paint Chip (QTY)
 Pb Dust Wipe (wipe type 10X10) 12 (QTY) *ghost*
 *Pb Air (QTY)
 Pb Soil/Solid (QTY)
 Pb TCLP (QTY)
 Drinking Water Pb (QTY) Cu (QTY) As (QTY)
 Waste Water Pb (QTY) Cu (QTY) As (QTY)
 Pb Furnace (Media _____) (QTY)

Fungal Analysis

- Collection Apparatus for Spore Traps/Air Samples: _____
 Collection Media _____
 *Spore-Trap (QTY) Surface Vacuum Dust (QTY)
 *Surface Swab (QTY) Culturable ID Genus (Media _____) (QTY)
 *Surface Tape (QTY) Culturable ID Species (Media _____) (QTY)
 Other (Specify _____) (QTY)

MISC

- Vermiculite
 Asbestos Soil PLM (Qual) PLM (Quan) PLM/TEM (Qual) PLM/TEM (Quan)
 *It is recommended that blank samples be submitted with all air and surface samples

If field data sheets are submitted, there is no need to complete bottom section.

CLIENT ID #	SAMPLE INFORMATION SAMPLE LOCATION/ID	DATE/ TIME	VOL (L)/ Wipe Area	ANALYSIS										CLIENT CONTACT					
				TEM	PCM	PLM	LEAD	MOLD	AIR	BULK	DUST	MATRIX	WATER AND OTHER	SPORE TRAP	TAPE	SWAB	(LABORATORY STAFF ONLY)		
	SEE ATTACHED FIELD DATA SHEETS																Date/Time:	Contact:	By:
																	Date/Time:	Contact:	By:
																	Date/Time:	Contact:	By:

LABORATORY STAFF ONLY:
 (CUSTODY)
 Posted to NGB FOIA Reading Room
 May, 2018

- Date/Time RCVD: 11/2/12 @ _____ Via: FDIX By (Print): _____ Sign: Non-Responsive
- Date/Time Analyzed: _____ @ _____ By (Print): _____ Sign: _____
- Results Reported To: 7919 2722 092 Via: _____ Date: _____ / _____ / _____ Time: _____ Initials: _____

BEST AVAILABLE COPY

FOIA Requested Record #J-15-0085 (VT)

Released by National Guard Bureau

Appendix C Photo Documentation

VT Lyndonville RC



Exterior



Drill Hall



Bunk Room




Electrical closet in bunk room

VT Lyndonville RC



Locker room



Janitor's closet



Chemicals in janitor's closet



Janitor's closet

VT Lyndonville RC



MSDSs in janitor's closet



Women's latrine



Scaffolding to fix a leak



Kitchen

VT Lyndonville RC



Kitchen



Kitchen storage



Stains on ceiling in Kitchen area



Broken floor tile in kitchen

VT Lyndonville RC



Drill Hall



Drill Hall



Flammable cabinets with MSDSs



Flammable cabinets blocked by equipment

VT Lyndonville RC



Storage room



Fitness Center



Classroom

Posted to NGB FOIA Reading Room
May, 2018



View of offices and classroom
from Drill Hall

VT Lyndonville RC



Lobby



Offices



Mezzanine storage



View from mezzanine of Drill Hall

VT Lyndonville RC



2nd Floor Classroom



2nd Floor Office



2nd Floor Office



Fogged window

VT Lyndonville RC



Fogged window



Drill Hall



Boiler Room



Boiler Room

VT Lyndonville RC



Boiler Room



Building layout

Appendix D
IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Lyndonville	IAQ							Light		
Date	10/24/2012	Inspector	Non-	Instrument	Q-trak 7565-X							Instrument	Cal-Light 400
Facility Description	Lyndonville RC			Serial Number	7565X0839019							Serial Number	K070003
Weather Conditions	Cool and Sunny			Last Calibration	Mar-12							Last Calibration	16-Apr-12
Location/Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
Drill Hall	2	1342	72.1		31.4		599		0.3		30-90	X	50
Foyer	1	1343									35-60		10
Bunk Room	1	1345	70.5		34.4		577		0.2		14-45		5
Locker Room	1	1346	69.6		35.5		543		0.3		5-32	X	7
Janitor's Closet	1	1347									7-10	X	30
Women's Latrine and Locker	1	1348	73.3		31.8		506		0.1		30-90		7
Fitness Center	1	1354	69.8		35.2		598		0.4		13-43	X	30
Classroom and Storage	1	1355	69.0		35.7		548		0.2		10-32	X	30-50
Admissions Office	2	1356	69.6		36.2		699		0.3		30-76		30-50
Storage Room	1	1357	70.4		30.3		652		0.3		30-86		30
Copier Room	1	1358	70.6		32.1		540		0.4		39-95		30
CO Office	1	1359	70.6		32.5		586		0.2		30-74		30-50
Office 4B	1	1401	71.3		35.2		698		0.3		20-62	X	30-50
R&R Office	5	1402	72.5		37.2		718		0.1		30-60		30-50
RNCO Office	3	1405	71.0		22.9	L	532		0.1		20-102	X	30-50
Food Storage	1	1406	69.6		30.1		505		0.2		50-75		10
Kitchen	1	1407	69.5		31.5		515		0.1		40-60	X	50
S4 Office	2	1410	70.0		36.8		547		3.0		30-60		30-50
Supply Room	2	1411	70.3		38.7		525		0.1		30-65		30-50
General Storage	2	1412									5-20	X	10
Mezzanine Storage Sunny Side	1	1417									60-400		30
Mezzanine Storage Shaded Side	1	1418	71.7		34.7		529		0.1		33-106		30
Classrooms A&B	1	1419	71.0		34.9		577		0.2		30-165		30-50
Computer Room	1	1420	70.9		35.6		574		0.2		18-109	X	30-50
2nd Floor Office	1	1421	70.5		36.1		587		0.2		55-102		30-50
Boiler Room	1	1520	70.7		26.6	L	633		0.2		1-25	X	30
Outside		1055	49.9		45.0		373		0.2				

Shaw Environmental, Inc.

312 Directors Drive
Knoxville, TN 37923
865.690.3211
Fax 865.690.3626



Shaw Environmental, Inc.

**National Guard Armory
Campbell Readiness Center – Montpelier, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

19 February 2004

**National Guard Armory
Campbell Readiness Center – Montpelier, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

19 February 2004

Prepared by:

Non-Responsive

Industrial Hygienist

Reviewed by:

Non-Responsive

Business Line Manager

Table of Contents

<i>Table of Contents</i>	<i>i</i>
<i>List of Tables</i>	<i>ii</i>
<i>List of Appendices</i>	<i>ii</i>
<i>Executive Summary</i>	<i>E-1</i>
<i>1.0 Introduction</i>	<i>1-1</i>
<i>2.0 Findings, Discussion, and Interpretation of Results</i>	<i>2-1</i>
<i>2.1 Sampling for Lead</i>	<i>2-1</i>
<i>2.1.1 Wipe Sampling</i>	<i>2-1</i>
<i>2.1.2 Air Sampling for Lead</i>	<i>2-2</i>
<i>2.2 Physical Condition of Facility</i>	<i>2-2</i>
<i>2.2.1 Peeling Paint - Lead</i>	<i>2-2</i>
<i>2.2.2 Visual Inspection - Asbestos</i>	<i>2-2</i>
<i>2.2.3 Visual Inspection - Water Damage and Mold</i>	<i>2-3</i>
<i>2.2.4 Visual Inspection - Housekeeping</i>	<i>2-3</i>
<i>2.3 Building Concerns</i>	<i>2-3</i>
<i>2.3.1 Ergonomic Concerns</i>	<i>2-3</i>
<i>2.3.2 Indoor Air Quality</i>	<i>2-3</i>
<i>2.4 Safety and Industrial Hygiene Programs</i>	<i>2-4</i>
<i>2.5 Ventilation</i>	<i>2-4</i>
<i>2.5.1 Ventilation System Evaluation</i>	<i>2-4</i>
<i>2.5.2 Contamination of Clean Air Sources</i>	<i>2-4</i>
<i>2.6 Noise Exposure</i>	<i>2-4</i>
<i>2.7 Lighting</i>	<i>2-5</i>
<i>2.8 Converted Indoor Firing Ranges</i>	<i>2-5</i>
<i>2.9 HVAC Systems</i>	<i>2-5</i>
<i>2.10 IHIM</i>	<i>2-6</i>
<i>3.0 Conclusions</i>	<i>3-1</i>
<i>Tables</i>	<i>Follows Section 3.0</i>
<i>Appendices</i>	<i>Follows Tables</i>

List of Tables

Table 1	Wipe Sampling for Lead
Table 2	Air Sampling for Lead
Table 3	Peeling Paint Sampling for Lead
Table 4	Indoor Air Quality Measurements
Table 5	Illumination Readings
Table 6	Indoor Firing Ranges – Wipe Sampling

List of Appendices

Appendix A	HHIM Data Form
Appendix B	Building Layout
Appendix C	Sampling Sheets and Laboratory Analyses
Appendix D	References
Appendix E	Recommendations for Surface Lead Dust in Armories

Executive Summary

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Campbell Readiness Center in Montpelier, Vermont. **Non-Responsive** performed the evaluation on 24 July 2003 and 8 October 2003. The point of contact at the readiness center was MAJ **Non-Responsive**

The following industrial hygiene concerns were evaluated.

- Wipe Sampling for Lead
- Air Sampling for Lead
- Peeling Paint -- Lead
- Suspected Asbestos Containing Material
- Water Damage
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Indoor Air Quality
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- Lighting
- Converted Indoor Firing Range
- HVAC Systems

The following items were either not applicable to the armory or the evaluation resulted in a conclusion that there were no industrial hygiene concerns.

- Air Sampling for Lead
- Peeling Paint -- Lead
- Housekeeping
- Ergonomic Concerns
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation

- Contamination of Clean Air Sources
- Noise Exposure
- HVAC Systems

Areas where there were industrial hygiene concerns are as follows:

- Wipe sampling for lead revealed concentrations above the recommended level at three locations in the assembly/drill hall. It is recommended that these surfaces and the areas immediately around these surfaces be thoroughly cleaned to reduce the lead level. In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.
- Wipe sampling for lead revealed concentrations above a level of 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) in the assembly hall, 186 FSB OPS NCO Office, and the windowsill in the basement hallway. Areas with lead concentrations above 40 $\mu\text{g}/\text{ft}^2$ that will be accessible to children should be cleaned. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.
- Materials suspected of containing asbestos were observed. An operations and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.
- Water damage was observed at the armory. The source of the water damage was likely from roof leaks or high water table and foundation leaks around the basement wall. The source of the water should be confirmed and actions taken to eliminate the source in order to prevent the possibility of mold growth that may lead to indoor air quality problems.
- Visual mold was observed in the armory on the firing range room wall. The area where the mold is located should be thoroughly cleaned with 0.5% sodium hypochlorite solution (1 part household bleach to nine parts water) or equivalent in order to eliminate the potential mold/indoor air quality problem. In addition, the source of the mold should be identified and actions taken to eliminate the source of the mold.
- Indoor air quality measurements revealed that the humidity at the armory exceeded the recommended levels. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory.
- Lighting measurements were conducted at the armory. The lighting did not meet minimum requirements in most areas; therefore consideration should be given to

providing more lighting in these areas. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

- Wipe sampling for lead in the converted firing range revealed concentrations above the recommended level at all of the locations sampled. These areas must be decontaminated by a thorough cleaning along with re-sampling until surface lead concentrations are reduced to below recommended levels. In addition, employees should not be allowed to work in these areas without protective clothing until the areas have been cleaned and re-sampled.

1.0 Introduction

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Campbell Readiness Center in Montpelier, Vermont **Non-Responsive** performed the evaluation on 24 July 2003 and 8 October 2003. The point of contact at the readiness center was MAJ **Non-Responsive**

The findings, discussion, and interpretation of results are provided in Section 2.0. The conclusions are provided in Section 3.0. The HHIM data form for the facility is provided in Appendix A. The building layout is provided in Appendix B. Sampling sheets and laboratory analyses are provided in Appendix C. References are provided in Appendix D. The *Recommendations for Surface Lead Dust in Armories* document is provided in Appendix E.

The statements, opinions, and conclusions contained in this report are based solely upon the services performed by Shaw as described in the report. In performing these services and preparing the report, Shaw Environmental, Inc. relied upon the work and information provided by others, including public agencies, whose information is not guaranteed by Shaw Environmental, Inc.

2.0 Findings, Discussion, and Interpretation of Results

The results, discussion, and interpretation of results are provided in the following sections.

2.1. Sampling for Lead

2.1.1 Wipe Sampling

Wipe samples were collected for lead from the drill floor/assembly area. Also, wipe samples were collected for lead in rooms, hallways, foyers, etc. The sampling in rooms, hallways, foyers, etc. represented approximately 25% of the building. Approximately half of the samples were collected from surfaces in common areas, such as surfaces of a desk. The remaining samples were collected from uncommon surface areas, such as a supply vent or the top of a file cabinet. The samples were collected and analyzed in accordance with the Instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

The only samples initially submitted for analysis were those from the drill floor/assembly hall. If there were any positive results from the drill floor, the other samples would be submitted for analysis.

Results of the wipe sampling are provided in Table I. The results revealed lead at all locations sampled at concentrations below recommended level of 200 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$) (See Appendix E) except at three locations. One sample on the assembly/drill hall floor had lead concentrations of $210 \mu\text{g}/\text{ft}^2$. The sample obtained from the top of the soda machine in the assembly/drill hall had a lead concentration of $760 \mu\text{g}/\text{ft}^2$. The sample obtained from the locker top surface in the assembly/drill hall had a lead concentration of $250 \mu\text{g}/\text{ft}^2$. It is recommended that these surfaces and the immediate areas around the surfaces be thoroughly cleaned to reduce the lead level to below $200 \mu\text{g}/\text{ft}^2$. For guidance on the proper method of cleaning, please refer to NG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.

In addition, wipe sampling for lead revealed concentrations above a level of 40 $\mu\text{g}/\text{ft}^2$ in the assembly hall, 186 FSB OPS NCO Office, and the windowsill in the basement hallway. Please note that the *Recommendations for Surface Lead Dust in Armories* (Appendix F) states that all areas with lead concentrations above 40 $\mu\text{g}/\text{ft}^2$ that will be accessible to children should be cleaned. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.

2.1.2 Air Sampling for Lead

Breathing zone air sampling was conducted on two (2) full-time building occupants. (Please note that no state employees were monitored.) The samples were collected and analyzed in accordance with Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods.

The results of the sampling are provided in Table 2. The results revealed non-detectable concentrations of lead in the breathing zone of the employee and in the general area of the converted firing range; therefore, no actions are necessary.

2.2 Physical Condition of Facility

2.2.1 Peeling Paint - Lead

Peeling paint was observed in the armory. The Department of Housing and Urban Development (HUD) defines lead-based paint as paint or other surface coatings that contain lead equal to or exceeding 0.5 percent by weight. Bulk sampling results revealed lead at a concentration of 0.016 percent by weight in the paint sample taken from the firing range room wall. Since HUD does not consider the paint a lead-based paint, no actions are necessary. The results of the sampling are provided in Table 3.

2.2.2 Visual Inspection - Asbestos

A visual inspection was made to determine if there was any suspected asbestos-containing material at the armory. Materials suspected of containing asbestos were observed. The suspected asbestos-containing material were floor tiles in the Service Battery ORD Office, first floor classroom, supply room adjacent to the first floor classroom, copier room, 186 FSB HED CDR TRNG NCO office, 186 FSB S4 office, lobby, 186 FSB OPS NCO S2/3 office (approximately 1182 square feet), and insulation in the boiler room (approximately 24 linear feet and 7 joints/elbows). The

condition of the floor tile materials were considered good since there was no damage to tiles. The condition of the boiler room insulation materials was considered good (no rips, tears, or other damage).

An operation and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.

2.2.3 Visual Inspection – Water Damage and Mold

A visual inspection was made to determine if there was any water damage or visible mold at the armory. Water damage and visible mold were observed on the firing range wall. In addition, a leaky pipe in the men's latrine was noted as water damage due to the precipitate that accumulates on the latrine floor.

The source of the water damage in the firing range room was likely from roof leaks or high water table and foundation leaks. The source of the water damage should be confirmed and actions taken to eliminate the source in order to prevent the possibility of mold growth that may lead to indoor air quality problems.

The area where the mold is located should be thoroughly cleaned with 0.5% sodium hypochlorite solution (1 part household bleach to nine parts water) or equivalent in order to eliminate the potential mold/indoor air quality problem. In addition, the source of the mold should be identified and actions taken to eliminate the source of the mold.

2.2.4 Visual Inspection - Housekeeping

The housekeeping was determined to be good.

2.3. Building Concerns

2.3.1 Ergonomic Concerns

Interviews with employees and observation of work activities revealed no ergonomic concerns at the armory.

2.3.2 Indoor Air Quality

Interviews with employees revealed no indoor air quality concerns at the armory. However, measurements for humidity revealed that levels exceeded the American

Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommended level of 60% in the armory. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed.

The results of the measurements for carbon dioxide, humidity, and temperature are provided in Table 3.

2.4. Safety and Industrial Hygiene Programs

An evaluation was performed to determine the applicability of the following programs.

- Confined Spaces
- Hearing Conservation
- Respiratory Protection
- Hazard Communication (HAZCOM)
- Personal Protective Equipment (PPE)

It was determined that the HAZCOM program was the only program listed above that was applicable at the facility. The HAZCOM program was evaluated and it was determined that the program met minimum requirements.

2.5. Ventilation

2.5.1 Ventilation System Evaluation

There were no local exhaust ventilation systems at this armory; therefore, no ventilation studies were performed.

2.5.2 Contamination of Clean Air Sources

Since there were no local exhaust ventilation systems at the armory, there was no possibility that clean air sources could be contaminated by exhaust air.

2.6. Noise Exposure

An evaluation was performed to determine if there were any hazardous noise areas at the armory. It was determined that there were no areas at the armory that would exceed the permissible exposure limit for noise.

2.7 Lighting

Lighting measurements were conducted at the armory. Results of the lighting evaluation are provided in Table 5. As can be seen from the results, the lighting did not meet the minimum requirements in most areas, including the CDR's Office, Administrative Office, Recreation Room, Classroom, and Maintenance PLT Room.

Consideration should be given to providing more lighting to the areas listed above. This may be accomplished by replacing burnt out luminaires, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

2.8 Converted Indoor Firing Ranges

There was an inactive indoor firing range used as a storage room at the facility; therefore, wipe samples were taken for lead at various locations in or near the converted range. It should be noted that the room is not occupied by personnel and is infrequently utilized. The results are provided in Table 6. The results revealed lead, with associated concentrations, at the following locations:

- bullet trap at 180000 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$);
- light fixture in the office area at 180000 $\mu\text{g}/\text{ft}^2$;
- overhead heaters in the office area at 410000 $\mu\text{g}/\text{ft}^2$;
- stored item, filing cabinet top surface at 640 $\mu\text{g}/\text{ft}^2$;
- floor in the bullet trap area at 1900 $\mu\text{g}/\text{ft}^2$; and
- floor outside the range at 300 $\mu\text{g}/\text{ft}^2$.

The lead levels at these locations were above the recommended level of 200 $\mu\text{g}/\text{ft}^2$, a level recommended in the *Guidelines for Converting Indoor Firing Ranges to Other Uses* document (Department of Army). These areas must be decontaminated by a thorough cleaning until surface lead concentrations are reduced to below recommended levels. For guidance on the proper method of cleaning, please refer to NG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, employees should not be allowed to work in these areas without protective clothing until the areas have been cleaned and re-sampled.

2.9. HVAC System

There was not a HVAC system at the armory.

2.10. HHIM

A Health Hazard Information Module (HHIM) form was completed for the armory. The completed form is provided in Appendix A.

3.0 Conclusions

It is concluded that there were no industrial hygiene concerns at the armory with regards to atmospheric exposure to lead, peeling lead-based paint, housekeeping, ergonomic conditions, safety and industrial hygiene programs, ventilation systems or contamination of clean air sources, noise exposure, and HVAC systems.

There were industrial hygiene concerns at the armory with regards to lead surface contamination, suspected asbestos-containing material, water damage, visible mold, indoor air quality, surface lead contamination in the converted firing range, and lighting. These concerns are discussed in detail in Section 2.0 of this report.

TABLES

Table 1
Wipe Sampling for Lead
National Guard Armory
Montpelier, Vermont
Dates of Sampling: 24 July 2003 and 8 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTCAM205-1	Drill Floor (See Building Layout - Appendix B)	210
VTCAM205-2	Drill Floor (See Building Layout - Appendix B)	< 110
VTCAM205-3	Drill Floor (See Building Layout - Appendix B)	< 110
VTCAM205-4	Drill Floor (See Building Layout - Appendix B)	< 110
VTCAM205-5	Drill Floor (See Building Layout - Appendix B)	< 110
VTCAM205-6	Field Blank	< 12 μg
VTCAM205-14	Basement-Classroom table top	< 110
VTCAM205-15	Basement-Hallway window sill	180
VTCAM205-16	1 st Floor-Kitchen stove shelf	< 110
VTCAM205-17	1 st Floor-SVC BTRY CDR Office-hard drive top	< 110
VTCAM205-18	Field Blank	< 12 μg
VTCAM205-19	1 st Floor-186 FSB XO/AO Office-desk top	< 110
VTCAM205-20	1 st Floor-Classroom-table top	< 110
VTCAM205-21	1 st Floor-186 FSB CSM Office-window sill	< 110
VTCAM205-22	1 st Floor-186 FSB HHD CDR Office-desktop	< 110
VTCAM205-23	1 st Floor-186 FSB OPS NCO Office-desktop	180
VTCAM205-24	Field Blank	< 12 μg
VTCAM205-25	2 nd Floor-desktop	< 110

^aMicrograms lead per square foot

Table 1 Continued
Wipe Sampling for Lead
National Guard Armory
Montpelier, Vermont
Dates of Sampling: 24 July 2003 and 8 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTCAM282-1	Assembly Room - display case table top (See Building Layout - Appendix B)	10
VTCAM282-2	Assembly Room - desktop (See Building Layout - Appendix B)	46
VTCAM282-3	Assembly Room - locker top surface (See Building Layout - Appendix B)	150
VTCAM282-4	Assembly Room - soda machine top surface (See Building Layout - Appendix B)	760
VTCAM282-5	Assembly Room - locker top surface (See Building Layout - Appendix B)	250
VTCAM282-6	Field Blank	< 0.3 μg

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of Army National Guard Armories* procedure.

In armories that do not contain childcare facilities, the NGB Region North Industrial Hygiene Office recommends cleaning the areas with lead concentrations greater than 200 $\mu\text{g}/\text{ft}^2$.

Table 2
 Breathing Zone Air Samples for Lead
 National Guard Armory
 Montpelier, Vermont
 Date of Sampling: 24 July 2003

Sample Number	Employee	Sampling Information			Results (mg/m ³) ^a
		Time Sampled / Minutes	Flow Rate (lpm) ^b	Volume (liters)	
VTCAM205-A1	Non-Responsive	0823 – 1106/163	2.5003	407.54	< 0.002
VTCAM205-A2		0833 – 1106/153	2.4684	377.66	< 0.003
VTCAM205-A3	Field Blank	-	-	-	None Detected

^a Milligrams lead per cubic meter of air.

^b Liters of air per minute.

Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods was followed for sampling for lead.

Table 3
Peeling Paint Sampling for Lead
National Guard Armory
Montpelier, Vermont
Date of Sampling: 24 July 2003

Sample Number	Location	Results, % By Weight
VICAM205-131	Converted Firing Range Wall	0.016

The Department of Housing and Urban Development (HUD) defines lead-based as paint or other surface coatings that contain lead equal to or exceeding 0.5 percent by weight.

Table 4
Indoor Air Quality Measurements for Carbon Dioxide, Humidity, and Temperature
National Guard Armory
Montpelier, Vermont
Date of Sampling: 24 July 2003

Location	Occupants in Area	Carbon Dioxide, parts per million parts of air (ppm)	Percent (%) Humidity	Temperature (°F)
1 st Floor 185 FSB XO/AO Office	1	443	63.0	77.7
2 nd Floor - Classroom/Gym	1	496	71.7	76.1
Basement - Classroom	1	424	71.9	70.3
Outdoors	-	396	69.8	75.3

Carbon dioxide, humidity, and temperature measurements were taken with a TSI Q Trak Plus, Model 8554, Indoor Air Quality Meter, calibrated in April 2003.

American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommends that indoor carbon dioxide levels be less than 700 ppm above outdoor levels.

ASHRAE recommends that the relative humidity levels be maintained between 30 to 60 percent.

ASHRAE recommends that the acceptable temperature range be 68 degrees Fahrenheit to 74 degrees Fahrenheit in the winter and 73 degrees Fahrenheit to 79 degrees Fahrenheit in the summer.

Table 5
Illumination Readings
National Guard Armory
Montpelier, Vermont
Date of Sampling: 24 July 2003

Location	Luminance (fc) ^a	Standard (fc) ^a	Standard Met
1 st Floor - Kitchen	40.3-45.1	70	No
1 st Floor - Service Battery ORD Office	25.2-51.3	70	No
1 st Floor - Classroom	25.3-41.3	70	No
1 st Floor - 186 FSB RRO Office	33.1-57.9	70	No
1 st Floor - 186 FSB XO/AO Office	25.7-104.3	70	Some Areas
1 st Floor - 186 FSB HHB CDR TRNG NCO Office	16.8-56.3	70	No
1 st Floor - 186 FSB S4 Office	20.1-42.3	70	No
1 st Floor - 186 OPS NCO S2/3	30.1-69.3	70	No
Basement - Gym	33.6-42.3	70	No
Basement - Classroom	41.6-130.3	70	Some Areas
Basement - Men's Latrine	16.4-70.1	40	Some Areas

^a fc - Footcandles

The readings were taken with a Cooke Corporation cal-LIGHT 400 Calibrated Precision Lightmeter, calibrated on 19 Aug 2002.

The standards listed above are from ANSI/IES RP-1 and RP-7.

Table 6
Wipe Sampling for Lead – Converted Firing Range
National Guard Armory
Montpelier, Vermont
Date of Sampling: 24 July 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTCAM205-7	Bullet Trap	180000
VTCAM205-8	Light Fixture	180000
VTCAM205-9	Overhead Heaters	410000
VTCAM205-10	Stored Item - Top of filing cabinet	640
VTCAM205-11	Floor	1900
VTCAM205-13	Floor Outside the Range	300
VTCAM205-12	Blank	< 12 μg

^a Micrograms lead per square foot

^b Below Detectable Limits, at a detection level of 23 $\mu\text{g}/\text{ft}^2$

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

Appendix A

HHIM Data Form(s)

HEALTH HAZARD INFORMATION MODULE: INDUSTRIAL HYGIENE SURVEY

(For use of this form, see HHIM User's Guide)

SECTION 1. DEMOGRAPHIC DATA

ARLOC		INSTALLATION Campbell Armory Vermont ARNG		BLDG/RM NO. Montpelier	
LOCATION/CODE Administrative Areas / AA			OPERATION/CODE Administrative OP / ADO		
SURVEY DATE 24 July 2003			EVALUATOR (Initials) Non-Responsive		
MACOM/CODE ARMY NATIONAL GUARD		SUBMACOM/CODE XX		SUPERVISOR Non-Responsive : MAJ	
TELEPHONE/DSN NO. 802-828-2968		UNIT/ORGANIZATION 186 FSB		RAC 4	FREQUENCY (hrs/day) 8
NO. CIV(S) 0	NO. MIL 11	NO. CONTRACTOR(S) 0	NO. LOC(S) 0	NO. OTHER 0	

SECTION 2. FACILITY DATA

LAB HOODS 0	VAPOR DEGREASERS 0	SPRAY BOOTHS 0
MAINTENANCE BAYS 0	OPEN SURFACE TANKS 0	VENTILATION UNITS 0

SECTION 3. SURVEY DATA

CONTROLS PRESENT	EVALUATION	UNIT CODE	CONTROLS REQUIRED	STATUS

PERSONAL PROTECTIVE EQUIPMENT (R = Required; U = Utilized)

GLOVES		R	U	RESPIRATOR		NOSH TC NO.	MANUFACTURER	R	U
ACID				AIRLINE					
COLD SURFACES				ABRASIVE BLASTING HOOD					
HOT SURFACES				DISPOSABLE					
NBC AGENTS				FULL FACE AIR PURIFYING					
OIL				1/2 FACE AIR PURIFYING					
SOLVENTS				POWERED AIR PURIFYING					
SURGICAL GLOVES				1/4 FACE AIR PURIFYING					
				SELF CONTAINED					

EVES/FACE	R	U	HEARING	R	U	BODY	R	U	HEAD/HT	R	U
CHEMICAL SPLASH			CANAL CAPS			APRONS			COLD WEATHER BOOTS/HATS		
FULL FACE SHIELD			EAR PLUGS			COLD WEATHER CLOTHING			FIARD HATS		
CHEMICAL/SAFETY			HELMETS			COVERALLS			IMPERMEABLE BOOTS		
SAFETY/IMPACT			MUFFS			FULL BODY SUIT			SAFETY/CONDUCTIVE SHOES		
WELDING HELMET			MUFF/EARPLUG COMBO			HEAT REFLECTIVE VEST/SUIT			SAFETY/NON-CONDUCTIVE SHOES		
			MUFF/EARPLUG W/TIME LIMIT			SAFETY BELT/HARNES					

SECTION 4. HAZARD INVENTORY DATA

GAS CODE	HAZARD DESCRIPTION	PAC	EPC
POVDT XXXX	Video Display Terminal	3-low	Uncontrolled Physical
7439-92-1	lead, inorganic dusts and fumes, as Pb	2-moderate	Uncontrolled Respiratory
1332-21-4	Asbestos (other)	2-moderate	Uncontrolled Physical

SECTION 5. PERSONNEL DATA

LAST NAME	FIRST NAME	MI	SEX	SSN	CATEGORY
See attached sheet for personnel list					

SECTION 6. COMMENTS

No comments. See attached sheet
 Survey conducted by Michele Senous, Building contains eleven (11) full time military staff. Full time staff performs mainly administrative functions

PRIVACY ACT STATEMENT

Title 5 US Code, Section 301; Executive Order 9397 authorizes the use of your Social Security Number as an identification number. The purpose of this information is to identify and monitor data relating each DA civilian and military employee exposed to a hazardous workplace or operation. The use of this information is to provide histories of exposures for any given worker.

Disclosure of your Social Security Number is not mandatory; however, non-disclosure may result in untimely provision of proper medical monitoring.


186 FSB FTM Roster Campbell Armory, 363 Fisher Road, Montpelier, VT 05602 AS OF: 24 JUL 03			
Rank	Last Name (SEX)	Position / Room	FTS
MAJ	Non-Responsive (MALE)	XO & AO	Yes
CPT	(FEMALE)	RRO/Adjutant	Yes
MSG	(FEMALE)	Bn Ops NCO	Yes
SFC	(FEMALE)	Bn S4 NCO	Yes
SFC	(FEMALE)	Bn PAC NCO	Yes
SSG	(FEMALE)	HHD Supply NCO	Yes
SSG	2334 (MALE)	HHD Tng / UA NCO	Yes
SPC	(FEMALE)	Personnel NCO	Yes
SFC	2 (MALE)	Svc Btry Readiness NCO	Yes
SSG	(FEMALE)	Svc Btry UA	Yes
SSG	(FEMALE)	Svc Btry Supply NCO	Yes

* last 4 digits of social security number
social security numbers not available for other personnel.

Appendix B

Building Layout

NOTE THIS ROOM HAS
2 FLOORS, SAMPLE
INDICATED REPRESENTS
SAMPLE TAKEN ON
SECOND FLOOR.




VERMONT
Army National Guard
CAMPBELL ARMORY / 50A10

Facility Use Drawing
BUILDING A1001
Version: DRAFT
Floor: FIRST
Survey Date: -
Stowers, NC
A1001_1

○ Sample date : 24 July 2003
△ Sample date : 8 October 2003



Gross: 15044 5' 5" Net: 13316 5' 5" N/C Ratio: 0.890444



VERMONT
 Army National Guard
 CAMPBELL ARMORY / 50A10
 Facility Use Drawing
 BUILDING A1001

Sheet: 1 OF 2
 Survey Date: _____
 Floor: BASEMENT
 Version: DRAFT
 Drawing No: A1001_A



Scale: 1/8" = 1'-0"

N/G Ratio: 0.755798

SF: 5320
 SU: 494

Appendix C

Sampling Sheets and Laboratory Analyses

Client: National Guard Bureau Job Name: VTCAM205 Chain Of Custody: 115809
 Address: 301-JE Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation Job Location: Not Provided Date Analyzed: 8/5/2003
 Havre de Grace, Maryland 21078 Job Number: Not Provided Person Submitting: **982070**
 P.O. Number: 07-01 Report Date: 05-Aug-03

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0359478	VTCAM205-1	Flame	Wipe	****	0.111	108.00 ug/ft ²	210 ug/ft ²	
0359479	VTCAM205-2	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359480	VTCAM205-3	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359481	VTCAM205-4	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359482	VTCAM205-5	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359483	VTCAM205-6	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0359484	VTCAM205-7	Flame	Wipe	****	0.111	108.00 ug/ft ²	180000 ug/ft ²	
0359485	VTCAM205-8	Flame	Wipe	****	0.111	108.00 ug/ft ²	180000 ug/ft ²	
0359486	VTCAM205-9	Flame	Wipe	****	0.111	108.00 ug/ft ²	410000 ug/ft ²	
0359487	VTCAM205-10	Flame	Wipe	****	0.111	108.00 ug/ft ²	640 ug/ft ²	
0359488	VTCAM205-11	Flame	Wipe	****	0.111	108.00 ug/ft ²	1900 ug/ft ²	
0359489	VTCAM205-12	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0359490	VTCAM205-13	Flame	Wipe	****	0.111	108.00 ug/ft ²	300 ug/ft ²	
0359491	VTCAM205-15	Flame	Wipe	****	0.111	108.00 ug/ft ²	180 ug/ft ²	

BEST AVAILABLE COPY

BEST AVAILABLE COPY

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

Client: National Guard Bureau
 Address: 301-IH Old Bay Lane, Attn: NGB-AVN-SL
 State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTCAM205
 Job Location: Not Provided
 Job Number: Not Provided
 P.O. Number: 07-01

Chain Of Custody: 113809
 Date Analyzed: 8/5/2003
 Person Submitting: **Non-Responsive**
 Report Date: 05-Aug-03

Attention: **Non-Responsive**

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)
 Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst:

Non-Responsive

Technical Manager:

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

Client: National Guard Bureau
Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SL, State Military Reservation
 Havre de Grace, Maryland 21078
Job Name: VTCAM205
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01
Chain Of Custody: 115917
Date Analyzed: 08/18/2003
Person Submitting: Non Responsive
Report Date: 18-Aug-03

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0362687	VTCAM205-14	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362688	VTCAM205-16	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362689	VTCAM205-17	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362690	VTCAM205-18	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0362691	VTCAM205-19	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362692	VTCAM205-20	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362693	VTCAM205-21	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362694	VTCAM205-22	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362695	VTCAM205-23	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 180 ug/ft ²	
0362696	VTCAM205-24	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0362697	VTCAM205-25	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	

Non-Responsive

Non-Responsive

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B
 N/A = Not Applicable mg/kg = parts per million (ppm) by weight mg/L = parts per million (ppm)
 %Pb = percent lead by weight ug/L = parts per billion (ppb)
 Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: _____
 Technical Manager: _____

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

Client: National Guard Bureau Job Name: VTCAM282 Chain Of Custody: 118709
 Address: 301-1H Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation Job Location: Not Provided Date Analyzed: 10/21/2003
 Havre de Grace, Maryland 21078 Job Number: Not Provided Person Submitting: **95 77 76**
 P.O. Number: 0701 Report Date: 21-Oct-03

Attention: **Non Responsive**

Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0402862	VTCAM282-1	Furnace	Wipe	****	0.111	2.70 ug/ft ²	10 ug/ft ²	
0402863	VTCAM282-2	Furnace	Wipe	****	0.111	13.50 ug/ft ²	46 ug/ft ²	
0402864	VTCAM282-3	Furnace	Wipe	****	0.111	33.75 ug/ft ²	150 ug/ft ²	
0402865	VTCAM282-4	Furnace	Wipe	****	0.111	135.01 ug/ft ²	760 ug/ft ²	
0402866	VTCAM282-5	Furnace	Wipe	****	0.111	67.51 ug/ft ²	250 ug/ft ²	
0402867	VTCAM282-6	Furnace	Wipe Blank	****	N/A	0.30 ug	< 0.3 ug	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per million (ppm)

%Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: **Non-Responsive**
 Technical Manager: **Non-Responsive**

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

AN AIHA (#8863), NVLAP (#101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643



Submitted To: **Non-Responsive**
Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTCAM205-B1 through VTMCR203-B2
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Paint Chip
Method Reference:	3050B/6010B
DCL Set ID No.:	03-S-3621
DCL Sample ID No.:	03-22312 through 03-22339
Sample Receipt Date:	07/28/2003
Preparation Date:	07/29/2003
Analysis Date:	07/31/2003

The samples were prepared in accordance with EPA method 3050B. Sample condition was acceptable upon receipt except where noted. The samples were then analyzed in accordance with EPA method 6010B using a Jarrell Ash Trace ICP.

The results are provided in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive

Analyst

CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5336, FAX 513 733-5347

Non-Responsive

Reviewer

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 260-8071, FAX 415 893-9469

Results Lead

Client #	DCL #	mg/Kg (ppm)	% by weight
VTCAM205-B1	03-22312	160.	0.016
VTWIN202-B1	03-22315	11000.	1.1
VTENO196-B1	03-22318	96000.	9.6
VTSTA197-B1	03-22327	1800.	0.18
VTWAT203-B1	03-22330	40.	0.0040
VTWAT203-B2	03-22331	57.	0.0057
VTMOR203-B1	03-22338	3900.	0.39
VTMOR203-B2	03-22339	11000.	1.1
	Prep Blank	ND	
% Recovery	LCS	87.	
% Recovery	03-22327 MS	* 0.	
% Recovery	03-22327 MSD	* 4.	
RPL		25.	0.0025

ND = not detected at or above the reporting limit (RPL).

LCS = laboratory control sample.

MS/MSD = matrix spike/matrix spike duplicate.

* Low recovery due to non-homogeneous sample matrix.

Non-Responsive

Analyst

Non-Responsive

Reviewer



Submitted To: **Non-Responsive**
Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTCAM205-A1 through VTAAS204-A3
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Filter
Method Reference:	NIOSH 7300
DCL Set ID No.:	03-S-3621
DCL Sample ID No.:	03-22309 through 03-22345
Sample Receipt Date:	7/28/2003
Preparation Date:	07/29/03
Analysis Date:	07/31/03

The samples were prepared and analyzed in accordance with NIOSH method 7300 using a Perkin Elmer 3000XL ICP.

The sample condition upon receipt was acceptable except where noted.

The results are in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive
[Redacted]

Analyst

Non-Responsive
[Redacted]

REVIEWER

CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 280-8071, FAX 415 893-9469

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTCAM205-A1	03-22309	407.54	ND	<0.002
VTCAM205-A2	03-22310	377.66	ND	<0.003
VTCAM205-A3	03-22311	0	ND	-
VTWIN202-A1	03-22313	152.91	ND	<0.007
VTWIN202-A2	03-22314	0	ND	-
VTENO196-A1	03-22316	150.55	ND	<0.007
VTENO196-A2	03-22317	0	ND	-
VTWIL197-A1	03-22319	199.78	ND	<0.005
	Prep Blank 1		ND	
% Recovery	LCS 1		96.	
% Recovery	LCS 2		96.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).
 LCS = laboratory control sample.

Non-Responsive

Analyst

Non-Responsive

Reviewer

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTWIL197-A2	03-22320	149.76	ND	<0.007
VTWIL197-A3	03-22321	0	ND	-
VTSWA196-A1	03-22322	149.24	ND	<0.007
VTSWA196-A2	03-22323	0	ND	-
VTSTA196-A1	03-22324	165.20	ND	<0.006
VTSTA196-A2	03-22325	151.74	ND	<0.007
VTSTA196-A3	03-22326	0	ND	-
VTWAT203-A1	03-22328	194.90	ND	<0.005
VTWAT203-A2	03-22329	0	ND	-
VTGOS202-A1	03-22332	175.30	ND	<0.006
VTGOS202-A2	03-22333	0	ND	-
VTMOR203-A1	03-22335	346.43	ND	<0.003
VTMOR203-A2	03-22336	348.65	ND	<0.003
VTMOR203-A3	03-22337	0	ND	-
VTGRE197-A1	03-22340	240.55	ND	<0.004
VTGRE197-A2	03-22341	250.76	ND	<0.004
VTGRE197-A3	03-22342	0	ND	-
VTAAS209-A1	03-22343	748.92	ND	<0.001
VTAAS209-A2	03-22344	507.55	ND	<0.002
VTAAS209-A3	03-22345	0	ND	-
	Prep Blank 2		ND	
% Recovery	LCS 3		96.	
% Recovery	LCS 4		95.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).
LCS = laboratory control sample.

Non-Responsive



Analyst

Non-Responsive



Industrial Hygiene Sampling Calculation Worksheet

National Guard Armory Location: CAM
 Date: 205

Sample 1

Sample Number: VTCAM205-A1

Pump: 647615

	Pre Flow Rate	Post Flow Rate
	2.55	2.477
	2.55	2.441
	2.542	2.451
	2.54	2.451
Average	2.546	2.455

Average Pre and Post 2.5003

Time 1 8:23

Time 2 11:06

Total Time Sampled 2:43

Minutes Sampled 163.00

Volume 407.54 Liters

Sample 2

Sample Number: VTCAM205-A2

Pump: 648339

	Pre Flow Rate	Post Flow Rate
	2.492	2.448
	2.494	2.445
	2.494	2.445
	2.485	2.444
Average	2.491	2.446

Average Pre and Post 2.4684

Time 1 8:33

Time 2 11:06

Total Time Sampled 2:33

Minutes Sampled 153.00

Volume 377.66 Liters

Appendix D

References

References

Title 29, Code of Federal Regulations CFR), Part 1910, Occupational Safety and Health Administration (current edition)

American Society of Heating, Refrigerating and Air-Conditioning Engineers, Inc (ASHRAE) 62-2002, Ventilation for Acceptable Indoor Air Quality

Instructions for Completing the Sampling of Army National Guard Armories, Lead Wipe Sampling Procedure included with the Request for Proposal

Air Sampling for Lead - Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods

Design Guide DG-415-2, Logistics Facilities, National Guard Bureau Installation Division, 14 December 1999

Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998

Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, 15 October 1990

AR 385-10, The Army Safety Program, 29 February 2000

Department of the Army Pamphlet (DA PAM) 40-501, Medical Services, Hearing Conservation Program, 10 December 1998

DA PAM 40-503, Medical Services, Industrial Hygiene Program, 30 October 2000

Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH) (current edition)

Guidelines for Converting Indoor Firing Ranges to Other Uses, Headquarters, Department of the Army and the Air Force, NG PAM (AR) 385-16/ANGPAM 91-101, 31 January 1994

24 CFR, Part 35, Subpart B, Section 35-110, Definition of Lead-Based Paint, Housing and Urban Development, U. S. Department of Housing

Appendix E
Recommendations for
Surface Lead Dust in Armories

Subject: Recommendations for Surface Lead Dust in Armories

1. In armories that do not contain childcare facilities, the National Guard Bureau (NGB) Region North Industrial Hygiene Office recommends cleaning the areas in which sample results are greater than 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$). If a special function will be held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function. This guidance is based on professional judgment, risk assessments, adaptation of Occupational Safety and Health Administration (OSHA) guidance, and feasibility of cleaning to a certain level.

a. Environmental Protection Agency (EPA) standards (40 Code of Federal Regulations (CFR) 745.227(l)(3)) are not directly applicable because they are criteria for dust-lead hazards developed for floors ($40 \mu\text{g}/\text{ft}^2$) and windowsills ($250 \mu\text{g}/\text{ft}^2$) in residential dwellings and child occupied facilities. A child occupied facility is defined as a building, or portion of a building, constructed prior to 1978, visited regularly by the same child, 6 years of age or under, on at least two different days within any week (Sunday through Saturday period), provided that each day's visit lasts at least 3 hours and the combined weekly visit lasts at least 6 hours, and the combined annual visits last at least 60 hours. Most of the wipe samples in armories were collected in undisturbed areas and therefore, results are worst case scenarios and do not correlate to these standards.

b. OSHA has no specific requirement for work area surfaces. The lead standard (29 CFR 1910.1025(h)) states that all surfaces shall be maintained as free as practicable of accumulations of lead dust. In workplaces where lead dust is generated, surface levels may be much higher, but personnel exposures can be controlled by limiting airborne lead levels and following good cleanup and hygienic practices.

c. OSHA used to cite a level of $200 \mu\text{g}/\text{ft}^2$ in their Technical Manual and 29 CFR 1926.62 as guidance to its own inspectors for evaluating the cleanliness of lunchroom and locker room surfaces that are supposed to be kept as clean as possible.

d. In a report titled Derivation of Wipe Surface Screening Levels for Environmental Chemicals, the US Army Center for Health Promotion and Preventive Medicine (USACHPPM) has determined that $200 \mu\text{g}/\text{ft}^2$ is a safe surface contamination level. They have also applied these standards as the decontamination levels for surfaces in administrative offices.

e. It should be noted that levels above these recommendations do not necessarily mean there is a significant hazard to workers who are following good cleaning and hygienic practices since there is no correlation between wipe and air samples. Rather, we recommend these levels as a precautionary measure.

2. The NGB Occupational Health Branch is developing guidance for armories that are used as childcare facilities. All states will receive this guidance when it is completed. In the interim, we recommend the following actions:

a. Clean all areas that will be accessible to children to the EPA dust-lead standard for children 6 years of age or under ($40 \mu\text{g}/\text{ft}^2$ on floors and $250 \mu\text{g}/\text{ft}^2$ on windowsills).

b. Refer to the local authorities' regulations since they can be more stringent than federal regulations.

c. Post signs in the area to inform people of the presence of lead dust and its effects.

d. If soldiers clean weapons in the facility change the policy so that they cannot clean their weapons in the facility, or if they are allowed to clean their weapons indoors, they must clean the area by wet wiping and mopping the area when they are done.

e. If the paint is peeling, contact the state Environmental Office to test for lead content and provide recommendations.

3. Air samples collected on individuals in the armory were well below OSHA's permissible exposure limit for lead (29 CFR 1910.1025(e)) of $0.05 \text{ mg}/\text{m}^3$ averaged over an 8-hour day. Therefore, based on these conditions there is currently no overexposure to personnel from lead dust in this building.

Industrial Hygiene Survey

Vermont Army National Guard (VT ARNG)

Prepared For: NGB ARNG– Region North IH Office

Survey Location:

Berlin Readiness Center
363 Fisher Road
Montpelier, VT 05602

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 17, 2012

AEI Project #: J12-685 3M VT Berlin RC

Non-Responsive, DrPH, CIH
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Berlin Readiness Center**

Table of Contents

Section	Page
Executive Summary	ii
1 Introduction	1
2 Evaluation Methods.....	1
3 Operations.....	1
4 Noise Hazards	1
5 Hazard Controls	1
Ventilation Systems	1
6 Physical Condition of the Facility and Personnel Concerns	2
Paint Chip and Dust Wipe Samples for Lead Contamination	2
Visual Inspection for Damaged Asbestos-Containing Materials	3
Visual Inspection for Water Damage and Mold Growth.....	3
Visual Inspection for Housekeeping Concerns	3
Lighting	3
Indoor Air Quality (IAQ)	4
Temperature and Relative Humidity.....	4
Carbon Dioxide (CO ₂) and Carbon Monoxide (CO)	4
Additional Information	5
7 Conclusions.....	5
8 Limitations.....	5
9 References	5

List of Tables

- Table 1 – Results of Lead Paint Chip Sampling for VT ARNG Berlin Readiness Center on October 17, 2012
- Table 2 - Results of Dust Wipe Sampling for the VT ARNG Berlin Readiness Center on October 17, 2012.
- Table 3 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

List of Appendices

- Appendix A – Building Layout
- Appendix B – Certificates of Analysis for Dust Wipe and Bulk Samples
- Appendix C – Photographic Documentation
- Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Berlin Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Berlin Readiness Center located at 363 Fisher Road, Montpelier, VT 05602. Non-Responsive, DrPH, CIH performed the evaluation on October 17, 2012. The point of contact for the facility was SFC Non-Responsive. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. No peeling paint was observed. Results of dust wipe samples taken throughout the facility were below the recommended maximum criterion for surface contamination of lead (200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$)) in all areas sampled except for three of the five samples collected from the former indoor firing range. Results from the samples collected in the firing range were between 110 and 2,300 $\mu\text{g}/\text{ft}^2$.

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there were any suspect asbestos-containing material and its condition. No damaged suspect asbestos-containing material was observed. The boiler room was abated and a new boiler was installed prior to the survey. Hard elbows and pipe insulation appeared to be undamaged.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. Water damage was observed in the former firing range on the lower level of the facility from what appeared to be an active water leak. Rust marks were observed on the floor of the former firing range where the lockers were stored. Facility personnel indicated that the leaks had been repaired. There was no visual or odor evidence of mold or fungus growth.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping appeared to be acceptable overall; with the exception of water damage that has created housekeeping problems in the lower level former firing range.

Lighting: The evaluation indicated illumination deficiencies in several areas including the: FSB CSM Office, Upstairs classroom, Janitor's Closet, Assembly Hall, OPS NCO B, HHD Supply Room (area 7), HHD Vault, HHD Supply Room Communications Closet, Office, Stairwells, FSB RRO Office, and the Former Range Storage Area. The illumination measurements indoors ranged from 2.2 foot candles (fc) to 2,900 fc.

Indoor Air Quality: Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 67.3 to 75.0° F and 27.6 to 52.4% Rh. Temperatures and Rh measurements were mostly within the comfort ranges. The outdoor temperature and relative humidity was 59.8° F and 27.7%

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Berlin Readiness Center**

on the day of monitoring. Indoor concentrations of carbon dioxide (CO₂) ranged from 444 to 764 parts per million (ppm). CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange. Indoor concentrations of carbon monoxide (CO) ranged from 3.2 to 4.0 ppm; therefore, concentrations are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was readily available. MSDSs were last updated in on October 17, 2012.

Other: A fiberboard drum holding discarded fluorescent lamps was observed in the lower level area that was formerly the firing range. The bottom 1/3 of the drum had evidence of water or other staining. The stain is most likely water damage related based upon a rust-colored stain of the same size and shape of the drum on the floor in the vicinity of the water leak. There were no labels on the drum indicating the contents.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Berlin Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Berlin Readiness Center located at 363 Fisher Road, Montpelier, VT 05602. **Non-Responsive**, DrPH, CIH performed the evaluation on October 17, 2012. The point of contact for the facility was SFC **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

The Berlin Readiness Center was built in the early 1960's and is staffed by six military administrative personnel and one part time civilian. The operations conducted at the facility include training and administrative duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the Berlin Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) evaluations of operations including operation description, sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the Berlin facility consist exclusively of supply and administrative duties. No maintenance of vehicles or other physical tasks are performed at the facility.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Berlin Readiness Center**

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were collected in select areas.

Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. No peeling paint was observed.

To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected by wiping a Ghost Wipe over a measured area. The Environmental Protection Agency (EPA) and the State of Vermont limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA Analytical for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. All wipe samples collected from the facility were below the recommended maximum except for three of the five samples collected from the former indoor firing range. Results from the samples collected in the firing range were between 110 and 2,300 $\mu\text{g}/\text{ft}^2$. Results are given in Table 1 and certificates of analysis are included in Appendix B.

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
Berlin Readiness Center on October 17, 2012.**

Wipe Sample Number	Sample Location	Wipe Dimensions	Lead ($\mu\text{g}/\text{ft}^2$)*
BRC-1	Floor SVC Battery Vault, 3' South of North Wall, 6' West of East Wall	12" x 12"	14
BRC-2	Floor of Former Firing Range, 6' East of West Wall, 8' South of North Wall	9" x 8.5"	700
BRC-3	Floor of Former Range, Clean Spot Along East Wall, 20' South of North Wall from Where Cabinets Were Moved	7.5" x 8.5"	190
BRC-4	Floor of Former Range, 10' West of East Wall, 30' South of North Wall	9" x 8"	2,300
BRC-5	Top of Cabinet in Former Range	3" x 36"	110
BRC-6	Floor of Former Range, 7' West of East Wall, 6' North of South Wall	8" x 8.5"	1,800

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Berlin Readiness Center**

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
Berlin Readiness Center on October 17, 2012.**

Wipe Sample Number	Sample Location	Wipe Dimensions	Lead ($\mu\text{g}/\text{ft}^2$)*
BRC-7	Kitchen on top of Cabinet with Toaster on North Wall, 8' East of West Wall	15" x 13"	<8.9
BRC-8	Assembly Hall Floor, 18' East of West Wall, 28' South of North Wall	10" x 11"	130
BRC-9	Assembly Hall on Cafeteria Style Table Top After Weapons Inspection and Maintenance	10" x 10"	39
BRC-10	Assembly Hall Floor, 11' West of East Wall, 12' North of South Wall	12" x 12"	15
BRC-11	FSB XO/AO Office Window Sill, East Wall – North Half	13.5" x 17"	<7.5

*The recommended maximum level for adult exposures is 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) lead on surfaces.

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). No damaged, suspect asbestos-containing material was observed. The boiler room was abated and a new boiler was installed prior to the survey. Hard elbows and pipe insulation appeared to be undamaged.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. There was no visual or odor evidence of mold or fungus growth.

Standing water and rust stains were observed in the south end of the former firing range where unused lockers and equipment are currently stored. A fiberboard drum holding discarded fluorescent lamps was observed in the lower level area that was formerly the firing range. The bottom of the drum had evidence of water or other staining on the bottom 1/3 of the drum. The stain is most likely water damage related based upon a rust-colored stain of the same size and shape of the drum on the floor in the vicinity of the water leak. There were no labels on the drum indicating the contents.

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping appeared to be acceptable overall; with the exception of water damage in the lower level former firing range.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on April 16, 2012, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Berlin Readiness Center**

A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in several areas including: FSB Office, CSM Office, Upstairs classroom, Janitor's Closet, Assembly Hall, OPS NCO B, HHD Supply Room (area 7), HHD Vault, HHD Supply Room Communications Closet, Office, Stairwells, FSB RRO Office, and the Former Range Storage Area. The illumination measurements indoors ranged from 2.2 foot candles (fc) to 2,900 fc. The complete results of the evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Model 7565X, factory calibrated in July, 2012. Temperature, relative humidity and carbon dioxide (CO₂) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 2. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30 and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 67.3 to 75.0° F and 27.6 to 52.4% Rh. Temperature and relative humidity measurements were mostly within the winter comfort ranges for thermal comfort except for in the arms vault. The outdoor temperature and relative humidity was 59.8° F and 27.7% on the day of monitoring.

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1–2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 444 to 764 parts per million (ppm). CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Berlin Readiness Center**

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 3.2 to 4.0 ppm; therefore, concentrations are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

Additional Information

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was readily available. MSDS were last updated in on October 17, 2012.

7 Conclusions

The results of the evaluation indicated few concerns at the facility. Overall, the Berlin Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.


9 References

1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Berlin Readiness Center**

3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.
4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.
5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2011.
6. Army Regulation (AR) 420-70 Buildings and Structures, 11 November 1997.
7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 13 December 2007.
8. Army Regulation (AR) 420-1 Army Facilities Management, 12 February 2008, RAR 24 August 2012.
9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.
10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.
12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.
13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".
15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.
19. National Fire Protection Association (NFPA) 70: National Electrical Code (NEC) 2011.
20. National Guard Pamphlet (NG PAM) 420-15, Guidelines and Procedures for Rehabilitation and Conversion of Indoor Firing Ranges, November 3, 2006.

Appendix A Building Layout



Family Support Office

Vermont Army National Guard Campbell Armory

Fire Evacuation Plan


Follow the direction Marked in Red

Industrial Hygiene Survey
Berlin Readiness Center
October 17, 2012



First Floor
*## = Sample Location

FOIA Requested Record #J-15-0085 (VT)
Released by National Guard Bureau
Page 675 of 1352



Industrial Hygiene Survey
Berlin Readiness Center
October 17, 2012

Basement
Not to Scale
*## = Sample Location



Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples



CERTIFICATE OF ANALYSIS



LAB #100470

Client: National Guard Bureau	Job Name: VT ARNG 4M IH Surveys	Chain Of Custody: 514302
Address: 301-JH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location: Berlin RC	Date Submitted: 10/24/2012
	Job Number: 120685	Person Submitting: Non-Responsive
	P.O. Number: W912K6-09-A-0003	Date Analyzed: 11/2/2012 Report Date: 11/2/2012
Attention: Non-Responsive		

Summary of Atomic Absorption Analysis for Lead

Page 1 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
13008812	BRC-1	Flame	Wipe	****	1.000	12 ug/ft ²	14	14 ug/ft ²	
13008813	BRC-2	Flame	Wipe	****	0.531	23 ug/ft ²	370	700 ug/ft ²	
13008814	BRC-3	Flame	Wipe	****	0.443	27 ug/ft ²	86	190 ug/ft ²	
13008815	BRC-4	Flame	Wipe	****	0.500	24 ug/ft ²	1100	2300 ug/ft ²	
13008816	BRC-5	Flame	Wipe	****	0.750	16 ug/ft ²	83	110 ug/ft ²	
13008817	BRC-6	Flame	Wipe	****	0.472	2.5 ug/ft ²	860	1800 ug/ft ²	
13008818	BRC-7	Flame	Wipe	****	1.354	8.9 ug/ft ²	<12	<8.9 ug/ft ²	
13008819	BRC-8	Flame	Wipe	****	0.764	16 ug/ft ²	97	130 ug/ft ²	
13008820	BRC-9	Flame	Wipe	****	0.694	17 ug/ft ²	27	39 ug/ft ²	
13008821	BRC-10	Flame	Wipe	****	1.000	12 ug/ft ²	15	15 ug/ft ²	
13008822	BRC-11	Flame	Wipe	****	1.594	7.5 ug/ft ²	<12	<7.5 ug/ft ²	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	VT ARNG 4M IH Surveys	Chain Of Custody:	514302
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Berlin RC	Date Submitted:	10/24/2012
Attention:	Non-Responsive	Job Number:	120685	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/2/2012
				Report Date:	11/2/2012

Summary of Atomic Absorption Analysis for Lead

Page 2 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	----------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B

See QC Summary for analytical results of quality control samples associated with these samples.

N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm)

%Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb)

Note: All samples were received in good condition unless otherwise noted.

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Air and Wipe results are not corrected for any blank results

Final results for air and wipe samples are based on client supplied information nor verified by this laboratory.

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Non-Responsive
 Analyst:

Non-Responsive
 Technical Manager:

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.

Appendix C Photo Documentation

VT Berlin RC



Photo 1: Entrance to Berlin RC.



Photo 2: Exterior of Berlin RC.



Photo 3: Entrance to the lower level of the Berlin RC.



Photo 4: Interior of Assembly Hall.

VT Berlin RC



Photo 5: Kitchen.



Photo 6: New boilers.



Photo 7: New tankless hot water heaters.



Photo 8: Arms vault.

VT Berlin RC



Photo 9: Supply room.



Photo 10: Interior of flammable materials cabinet.



Photo 11: Interior of flammable materials cabinet.



Photo 12: Maintenance area.

VT Berlin RC



Photo 13: Supply room.



Photo 14: Former indoor firing range on lower level.



Photo 15: Evidence of water damage fluorescent lamp disposal drum.



Photo 16: Interior of flammable materials storage cabinet.

VT Berlin RC



Photo 17: Water damage from active water leak in lower level former range area.



Photo 18: Water damage from active water leak in lower level former range area.



Photo 19: Former indoor firing range.

Appendix D IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Berlin	IAQ								Light		
Date	10/17/2012	Inspector	Non-Responsive	Instrument	Q-trak 7565-X							Instrument	Cal-Light 400L	
Facility Description	Berlin RC			Serial Number	7575x1228004							Serial Number	K040084EL	
Weather Conditions	Sunny			Last Calibration	Jul-12							Last Calibration	16-Apr-12	
Location	Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
Arms Vault (SVC)	Storage	1	1237	67.3	X	52.4		693		3.9		24.6		10
Service Battery - Area 1	Storage/Office	1	1245	69.9		43.2		658		3.8		36.7		30
Service Battery - Area 2	Storage	1	1246	69.9		44.6		694		3.8		23.0		10
Service Battery - Area 3	Storage Corridor	1	1247	70.0		45.1		644		4.0		34.0		10
Service Battery - Area 4	Storage	1	1248	70.0		44.9		618		3.8		23.8		10
Kitchen	Kitchen	1	1249	70.4		43.1		599		3.8		54.1		50
HHD Supply Room - Area 5	Storage	1	1253	69.9		48.6		561		3.8		20.2		10
HHD Supply Room - Area 6	Corridor	1	1254	69.9		49.1		572		3.8		13.1		10
HHD Supply Room - Area 7	Storage/Office	1	1255	69.9		48.2		582		3.8		14.0	X	30-50
HHD Vault	Vault	1	1256	69.9		48.6		581		3.8		2.2	X	10
HHD Supply Room	Communication	1	1256	70.9		44.1		610		3.7		5.7	X	30-50
FSB S4	Office	1	1257	71.3		43.2		615		3.7		32.1		30-50
Command Training NCO	Office	1	1259	71.0		35.3		547		3.5		31.0		30-50
Family Support	Office	1	1300	71.1		38.0		581		3.7		23.8	X	30-50
Conference Room	Conference Room	1	1302	70.6		42.2		589		3.8		76.2		30-50
R&R	Office	1	1304	70.6		43.9		604		3.6		47.3		30-50
Office	Office	1	1305	70.5		44.1		604		3.8		20.4	X	30-50
Stairwell (East)	Corridor	1	1306	70.3		43.8		537		3.6		4.9	X	5
Copier Room	Office	1	1307	70.2		44.3		634		4.0		44.4		30-50
FSB XO/AO	Office	2	1308	70.3		43.6		629		3.7		30.8		30-50
FSB RRO	Office	1	1310	71.2		42.8		632		3.7		19.9	X	30-50

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Berlin	IAQ							Light			
Date	10/17/2012	Inspector	Not-Responsive	Instrument	Q-trak 7565-X						Instrument	Cal-Light 400L		
Facility Description	Berlin RC			Serial Number	7575x1228004						Serial Number	K040084EL		
Weather Conditions	Sunny			Last Calibration	Jul-12						Last Calibration	16-Apr-12		
Location	Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
Office 1	Office	1	1311	71.0		43.6		727		3.8		49.3		30-50
Office 2	Office	1	1312	70.8		43.8		764		3.8		52.2		30-50
Entry Vestibule	Lobby	var	1313	71.1		42.5		606		3.5		12.7		10
FSB CSM	Office	1	1315	71.2		41.9		598		3.7		19.6	X	30-50
Supply	Corridor	1	1316	71.3		42.5		600		3.8		17.4		5
FSB CDR	Office	1	1317	71.8		42.2		591		3.7		31.3		30-50
Classroom	Classroom	var	1318	72.1		41.4		579		3.7		28.1	X	30-50
Female Latrine	Latrine	var	1319	72.2		42.8		577		3.7		30.3		5
Janitor's Closet	Closet	1	1320	71.9		42.7		696		3.7		no light	X	30
Assembly Hall	Hallway	var	1321	71.6		41.6		611		3.8		15.8	X	30-50
Service Battery CDR	Office	1	1323	74.8		44.8		494		3.2		33.1		30-50
Service Battery ORD Room	Office	1	1324	75.0		39.2		617		3.7		39.0		30-50
Boiler Room	Boiler Room	1	1326	71.1		27.6	X	456		3.7		2.9 K		30
Outdoors	Outdoors	1	1327	59.8		27.7		402		3.9		8.4 K		N/A
Ops NCO A	Office	1	1330	70.4		43.5		609		3.3		42.3		30-50
Ops NCO B	Conference Room	var	1330	70.8		43.2		624		3.3		28.4	X	30-50
FAC A	Office	1	1331	71.1		43.1		604		3.3		48.3		30-50
FAC B	Lounge	1	1331	71.2		42.8		610		3.4		64.9		30-50
Gym	Gym	var	1400	68.1		40.8		467		3.3		33.0		30
Classroom	Classroom	var	1405	68.6		41.2		473		3.3		52.2		30-50
East Stairs	Corridor	var	1406	68.5		41.2		480		3.3		29.2		5

Shaw Environmental, Inc.

312 Directors Drive
Knoxville, TN 37923
865.690.3211
Fax 865.690.3626



**National Guard Armory
Morrisville Readiness Center – Morrisville, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

11 December 2003

**National Guard Armory
Morrisville Readiness Center – Morrisville, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

11 December 2003

Prepared by:

Non-Responsive

Industrial Hygienist

Reviewed by:

Non-Responsive

Business Line Manager

Table of Contents

<i>Table of Contents</i>	<i>i</i>
<i>List of Tables</i>	<i>ii</i>
<i>List of Appendices</i>	<i>ii</i>
<i>Executive Summary</i>	<i>ii-1</i>
<i>1.0 Introduction</i>	<i>1-1</i>
<i>2.0 Findings, Discussion, and Interpretation of Results</i>	<i>2-1</i>
<i>2.1 Sampling for Lead</i>	<i>2-1</i>
<i>2.1.1 Wipe Sampling</i>	<i>2-1</i>
<i>2.1.2 Air Sampling for Lead</i>	<i>2-2</i>
<i>2.2 Physical Condition of Facility</i>	<i>2-2</i>
<i>2.2.1 Peeling Paint - Lead</i>	<i>2-2</i>
<i>2.2.2 Visual Inspection - Asbestos</i>	<i>2-2</i>
<i>2.2.3 Visual Inspection - Water Damage and Mold</i>	<i>2-3</i>
<i>2.2.4 Visual Inspection - Housekeeping</i>	<i>2-3</i>
<i>2.3 Building Concerns</i>	<i>2-3</i>
<i>2.3.1 Ergonomic Concerns</i>	<i>2-3</i>
<i>2.3.2 Indoor Air Quality</i>	<i>2-4</i>
<i>2.4 Safety and Industrial Hygiene Programs</i>	<i>2-4</i>
<i>2.5 Ventilation</i>	<i>2-4</i>
<i>2.5.1 Ventilation System Evaluation</i>	<i>2-4</i>
<i>2.5.2 Contamination of Clean Air Sources</i>	<i>2-4</i>
<i>2.6 Noise Exposure</i>	<i>2-5</i>
<i>2.7 Lighting</i>	<i>2-5</i>
<i>2.8 Converted Indoor Firing Ranges</i>	<i>2-5</i>
<i>2.9 HVAC Systems</i>	<i>2-6</i>
<i>2.10 HHIM</i>	<i>2-6</i>
<i>3.0 Conclusions</i>	<i>3-1</i>
<i>Tables</i>	<i>Follows Section 3.0</i>
<i>Appendices</i>	<i>Follows Tables</i>

List of Tables

Table 1	Wipe Sampling for Lead
Table 2	Air Sampling for Lead
Table 3	Peeling Paint Sampling for Lead
Table 4	Indoor Air Quality Measurements
Table 5	Illumination Readings
Table 6	Indoor Firing Ranges – Wipe Sampling

List of Appendices

Appendix A	HHM Data Form
Appendix B	Building Layout
Appendix C	Sampling Sheets and Laboratory Analyses
Appendix D	References
Appendix E	Recommendations for Surface Lead Dust in Armories

Executive Summary

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Morrisville Readiness Center in Morrisville, Vermont. **Non-Responsive** performed the evaluation on 22 July 2003 and 8 October 2003. The point of contact at the readiness center was SSG **Non-Responsive**

The following industrial hygiene concerns were evaluated.

- Wipe Sampling for Lead
- Air Sampling for Lead
- Peeling Paint – Lead
- Suspected Asbestos Containing Material
- Water Damage
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Indoor Air Quality
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- Lighting
- Converted Indoor Firing Range
- HVAC Systems

The following items were either not applicable to the armory or the evaluation resulted in a conclusion that there were no industrial hygiene concerns.

- Air Sampling for Lead
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation

- Contamination of Clean Air Sources
- Noise Exposure
- HVAC Systems

Areas where there were industrial hygiene concerns are as follows:

- Wipe sampling for lead revealed concentrations above the recommended level at four locations in the assembly/drill hall. It is recommended that these surfaces and the areas immediately around these surfaces be thoroughly cleaned to reduce the lead level. In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.
- Wipe sampling for lead revealed concentrations above a level of 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) in the assembly hall. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.
- Peeling paint was observed in the converted firing range room, and bulk sampling results revealed this paint to be a lead-based paint. Anyone who may perform repair and/or maintenance activities on this surface should be made aware of the presence of the lead-based paint so appropriate precautions (control of exposures, personal protective equipment, training, etc.) can be taken.
- Materials suspected of containing asbestos were observed. An operations and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.
- Water damage was observed at several locations at the armory. The source of the water damage was likely from roof leaks. It was indicated that the roof is to be replaced within the year. The source of the water should be confirmed and actions taken to eliminate the source in order to prevent the possibility of mold growth that may lead to indoor air quality problems.
- Indoor air quality measurements revealed that the humidity at the armory exceeded the recommended levels. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory. In addition, interviews with employees revealed ventilation as an indoor air quality concern at the armory, specifically in the supply room where there is a minimal fresh air supply. A fan can be used for cooling purposes and to circulate air in the supply room.
- Lighting measurements were conducted at the armory. The lighting did not meet minimum requirements in most areas; therefore consideration should be given to

providing more lighting in these areas. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

- Wipe sampling for lead in the converted firing range revealed concentrations above the recommended level at all of the locations sampled. These areas must be decontaminated by a thorough cleaning along with re-sampling until surface lead concentrations are reduced to below recommended levels. In addition, employees should not be allowed to work in these areas without protective clothing until the areas are cleaned and re-sampled.

1.0 Introduction

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Morrisville Readiness Center in Bradford, Morrisville. **Non-Responsive** performed the evaluation on 22 July 2003 and 8 October 2003. The point of contact at the readiness center was SSG **Non-Responsive**

The findings, discussion, and interpretation of results are provided in Section 2.0. The conclusions are provided in Section 3.0. The HHIM data form for the facility is provided in Appendix A. The building layout is provided in Appendix B. Sampling sheets and laboratory analyses are provided in Appendix C. References are provided in Appendix D. The *Recommendations for Surface Lead Dust in Armories* document is provided in Appendix E.

The statements, opinions, and conclusions contained in this report are based solely upon the services performed by Shaw as described in the report. In performing these services and preparing the report, Shaw Environmental, Inc. relied upon the work and information provided by others, including public agencies, whose information is not guaranteed by Shaw Environmental, Inc.

2.0 Findings, Discussion, and Interpretation of Results

The results, discussion, and interpretation of results are provided in the following sections.

2.1. Sampling for Lead

2.1.1 Wipe Sampling

Wipe samples were collected for lead from the drill floor/assembly area. Also, wipe samples were collected for lead in rooms, hallways, foyers, etc. The sampling in rooms, hallways, foyers, etc. represented approximately 25% of the building. Approximately half of the samples were collected from surfaces in common areas, such as surfaces of a desk. The remaining samples were collected from uncommon surface areas, such as a supply vent or the top of a file cabinet. The samples were collected and analyzed in accordance with the Instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

The only samples initially submitted for analysis were those from the drill floor/assembly hall. If there were any positive results from the drill floor, the other samples would be submitted for analysis.

Results of the wipe sampling are provided in Table 1. The results revealed lead at all locations sampled at concentrations below recommended level of 200 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$) (See Appendix E) except at four locations. Two samples on the assembly/drill hall floor (sample locations four and five) had lead concentrations of 220 and 260 $\mu\text{g}/\text{ft}^2$, respectively. The sample obtained from the top of the soda machine in the assembly/drill hall had a lead concentration of 270 $\mu\text{g}/\text{ft}^2$. The sample obtained from the fire alarm control box in the assembly/drill hall had a lead concentration of 400 $\mu\text{g}/\text{ft}^2$. It is recommended that these surfaces and the immediate areas around the surfaces be thoroughly cleaned to reduce the lead level to below 200 $\mu\text{g}/\text{ft}^2$. For guidance on the proper method of cleaning, please refer to NG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.

In addition, wipe sampling for lead revealed concentrations above a level of 40 $\mu\text{g}/\text{ft}^2$ in the assembly hall. Please note that the *Recommendations for Surface Lead Dust in Armories* (Appendix E) states that all areas should be cleaned that will be accessible to children. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.

2.1.2 Air Sampling for Lead

Breathing zone air sampling was conducted on one (1) full-time building occupant. (Please note that no state employees were monitored.) In addition, a general air sample was collected in the converted firing range. The samples were collected and analyzed in accordance with Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods.

The results of the sampling are provided in Table 2. The results revealed non-detectable concentrations of lead in the breathing zone of the employee and in the general area of the converted firing range; therefore, no actions are necessary.

2.2 Physical Condition of Facility

2.2.1 Peeling Paint - Lead

Peeling paint was observed in the armory. The Department of Housing and Urban Development (HUD) defines lead-based paint as paint or other surface coatings that contain lead equal to or exceeding 0.5 percent by weight. Bulk sampling results revealed lead at a concentration of 1.1 percent by weight in the paint sample taken from the converted firing range room. The results of the sampling are provided in Table 3.

Anyone who may perform repair and/or maintenance activities on surfaces coated with lead-based paint should be made aware of the presence of the lead-based paint so appropriate precautions (control of exposures, personal protective equipment, training, etc.) can be taken.

It should be noted that the firing range lead wipe sampling results (See Section 2.8) indicate lead concentrations above the recommended level of 200 $\mu\text{g}/\text{ft}^2$, therefore the

possibility exists that the lead concentration indicated by the paint sample taken from the firing range room could be due to deposition rather than lead based paint.

2.2.2 Visual Inspection - Asbestos

A visual inspection was made to determine if there was any suspected asbestos-containing material at the armory. Materials suspected of containing asbestos were observed. The suspected asbestos-containing material were floor tiles in the Administrative Office, R & R Office, ISG Office, Classroom, Maintenance PLT Room, and 2 Kitchen storage rooms (approximately 1641 square feet), and insulation in the boiler room (approximately 33 linear feet). The condition of the floor tiles materials was considered average since there was some damage to tiles at the doorways. The condition of the boiler room insulation materials was considered good (no rips, tears, or other damage).

An operation and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.

2.2.3 Visual Inspection – Water Damage and Mold

A visual inspection was made to determine if there was any water damage or visible mold at the armory. Visible mold was not observed, however, water damage was observed at the armory. The water damage was observed in the Maintenance PLT Room, Women's Latrine, Men's Latrine, Recreation room, and the ISG Office.

The source of the water damage was likely from roof leaks. It was indicated that the roof is to be replaced within the year. The source of the water damage should be confirmed and actions taken to eliminate the source in order to prevent the possibility of mold growth that may lead to indoor air quality problems.

2.2.4 Visual Inspection - Housekeeping

The housekeeping was determined to be good.

2.3. Building Concerns

2.3.1 Ergonomic Concerns

Interviews with employees and observation of work activities revealed no ergonomic concerns at the armory.

2.2.4 Indoor Air Quality

Interviews with employees revealed ventilation as an indoor air quality concern at the armory, specifically in the supply room where there is a minimal fresh air supply. In addition, measurements for humidity revealed that levels exceeded the American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommended level of 60% in the armory. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory. In addition a fan can be used for cooling purposes and to circulate air in the supply room.

The results of the measurements for carbon dioxide, humidity, and temperature are provided in Table 4.

2.4. Safety and Industrial Hygiene Programs

An evaluation was performed to determine the applicability of the following programs.

- Confined Spaces
- Hearing Conservation
- Respiratory Protection
- Hazard Communication (HAZCOM)
- Personal Protective Equipment (PPE)

It was determined that the HAZCOM program was the only program listed above that was applicable at the facility. The HAZCOM program was evaluated and it was determined that the program met minimum requirements.

2.5. Ventilation

2.5.1 Ventilation System Evaluation

There were no local exhaust ventilation systems at this armory; therefore, no ventilation studies were performed.

2.5.2 Contamination of Clean Air Sources

Since there were no local exhaust ventilation systems at the armory, there was no possibility that clean air sources could be contaminated by exhaust air.

2.6. Noise Exposure

An evaluation was performed to determine if there were any hazardous noise areas at the armory. It was determined that there were no areas at the armory that would exceed the permissible exposure limit for noise.

2.7 Lighting

Lighting measurements were conducted at the armory. Results of the lighting evaluation are provided in Table 5. As can be seen from the results, the lighting did not meet the minimum requirements in most areas, including the CDR's Office, Administrative Office, Recreation Room, Classroom, and Maintenance PLT Room.

Consideration should be given to providing more lighting to the areas listed above. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

2.8. Converted Indoor Firing Ranges

There was a converted indoor firing range at the facility; therefore, wipe samples were taken for lead at various locations in or near the converted range. The space was divided into storage and an office area used only on drill weekends. It should be noted that a blue tarp was hung between the bullet trap area and the rest of the room. The results are provided in Table 5. The results revealed lead, with associated concentrations, at the following locations:

- floor outside the range at 250 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$);
- floor in the office area at 250 $\mu\text{g}/\text{ft}^2$;
- light fixture in the office area at 1600 $\mu\text{g}/\text{ft}^2$;
- floor in the bullet trap area at 8800 $\mu\text{g}/\text{ft}^2$;
- light fixture in the bullet trap area at 760 $\mu\text{g}/\text{ft}^2$; and
- inside remaining ventilation ductwork at 5000 $\mu\text{g}/\text{ft}^2$.

The lead levels at these locations were above the recommended level of 200 $\mu\text{g}/\text{ft}^2$, a level recommended in the *Guidelines for Converting Indoor Firing Ranges to Other Uses* document (Department of Army). These areas must be decontaminated by a thorough cleaning along with re-sampling until surface lead concentrations are reduced to below recommended levels. For guidance on the proper method of

cleaning, please refer to NGI PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, employees should not be allowed to work in these areas without protective clothing until the areas have been cleaned and re-sampled.

2.9. HVAC System

There was not a HVAC system at the armory.

2.10. HHIM

A Health Hazard Information Module (HHIM) form was completed for the armory. The completed form is provided in Appendix A.

3.0 Conclusions

It is concluded that there were no industrial hygiene concerns at the armory with regards to atmospheric exposure to lead, visible mold, housekeeping, ergonomic conditions, safety and industrial hygiene programs, ventilation systems or contamination of clean air sources, noise exposure, and HVAC systems.

There were industrial hygiene concerns at the armory with regards to lead surface contamination, peeling lead-based paint, suspected asbestos-containing material, water damage, indoor air quality, surface lead contamination in the converted firing range, and lighting. These concerns are discussed in detail in Section 2.0 of this report.

TABLES

Table 1
Wipe Sampling for Lead
National Guard Armory
Morrisville, Vermont
Dates of Sampling: 22 July 2003 and 8 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTMOR203-1	Drill Floor -- On Floor (See Building Layout -- Appendix B)	< 110
VTMOR203-2	Drill Floor -- On Floor (See Building Layout -- Appendix B)	< 110
VTMOR203-3	Drill Floor -- On Floor (See Building Layout -- Appendix B)	130
VTMOR203-4	Drill Floor -- On Floor (See Building Layout -- Appendix B)	220
VTMOR203-5	Drill Floor -- On Floor (See Building Layout -- Appendix B)	260
VTMOR203-6	Field Blank	< 12 μg
VTMOR203-15	Classroom Table Surface	< 110
VTMOR203-16	Kitchen Top of Cabinet	< 110
VTMOR203-17	Supply Room Office Desktop	< 110
VTMOR203-18	Field Blank	< 12 μg
VTMOR203-19	Administrative Office Desktop	< 110
VTMOR203-20	Office Top of Bookshelf	< 110
VTMOR282-1	Assembly Room -- Top of Soda Machine (See Building Layout -- Appendix B)	270
VTMOR282-2	Assembly Room -- Top of Locker #71 (See Building Layout -- Appendix B)	21
VTMOR282-3	Assembly Room -- Top of Fire Alarm Control Box (See Building Layout -- Appendix B)	400
VTMOR282-4	Assembly Room -- Top of Locker #29 (See Building Layout -- Appendix B)	66
VTMOR282-1	Assembly Room -- Top of Locker #50 (See Building Layout -- Appendix B)	37
VTMOR282-6	Field Blank	0.33 μg

^aMicrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of Army National Guard Armories* procedure.

In armories that do not contain childcare facilities, the NGB Region North Industrial Hygiene Office recommends cleaning the areas with lead concentrations greater than 200 $\mu\text{g}/\text{ft}^2$.

Table 2
Breathing Zone Air Samples for Lead
National Guard Armory
Morrisville, Vermont
Date of Sampling: 22 July 2003

Sample Number	Employee	Sampling Information			Results (mg/m ³) ^a
		Time Sampled / Minutes	Flow Rate (lpm) ^b	Volume (liters)	
VTMOR203-A1	Non-Responsive	0851-1111/140	2.4745	346.43	<0.003
VTMOR203-A2	General sample-firing range office	0853-1113/140	2.4904	348.65	<0.003
VTMOR203-A3	Field Blank	-	-	-	None Detected

^a Milligrams lead per cubic meter of air.

^b Liters of air per minute.

Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods was followed for sampling for lead.

Table 3
Peeling Paint Sampling for Lead
National Guard Armory
Morrisville, Vermont
Date of Sampling: 22 July 2003

Sample Number	Location	Results, % By Weight
VTMOR203-B1	Women's Latrine wall	0.39
VTMOR203-B2	Converted Firing Rang Wall	1.1

The Department of Housing and Urban Development (HUD) defines lead-based as paint or other surface coatings that contain lead equal to or exceeding 0.5 percent by weight.

Table 4
Indoor Air Quality Measurements for Carbon Dioxide, Humidity, and Temperature
National Guard Armory
Morrisville, Vermont
Date of Sampling: 22 July 2003

Location	Occupants in Area	Carbon Dioxide, parts per million parts of air (ppm)	Percent (%) Humidity	Temperature (°F)
1 st Floor -	2	435	74.9	73.4
Outdoors	0	421	78.3	84.6

Carbon dioxide, humidity, and temperature measurements were taken with a TSI Q Trak Plus, Model 8554, Indoor Air Quality Meter, calibrated in April 2003.

American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommends that indoor carbon dioxide levels be less than 700 ppm above outdoor levels.

ASHRAE recommends that the relative humidity levels be maintained between 30 to 60 percent.

ASHRAE recommends that the acceptable temperature range be 68 degrees Fahrenheit to 74 degrees Fahrenheit in the winter and 73 degrees Fahrenheit to 79 degrees Fahrenheit in the summer.

Table 5
Illumination Readings
National Guard Armory
Morrisville, Vermont
Date of Sampling: 22 July 2003

Location	Luminauce (fc) ^a	Standard (fc) ^a	Standard Met
CDR's Office	43.7-28.6	70	No
Administrative Office	51.8-14.6	70	No
Recreation Room	55.3-20.6	70	No
Classroom	54.9-23.1	70	No
Maintenance PLT Room	60.1-26.3	70	No
Kitchen	85.6-20.5	70	Some areas
Supply Room/Office	73.2-32.2	70	Some areas

^a fc - Footcandles

The readings were taken with a Cooke Corporation cal-LIGHT 400 Calibrated Precision Lightmeter, calibrated on 19 Aug 2002.

The standards listed above are from Design Guide DG-415-2, Logistics Facilities, published by the National Guard Bureau Installation Division.

Table 6
Wipe Sampling for Lead – Converted Firing Range
National Guard Armory
Morrisville, Vermont
Date of Sampling: 22 July 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTMOR203-7	Inside Remaining Ventilation Ductwork	5000
VTMOR203-8	Light Fixture - Office Area	1600
VTMOR203-9	Light Fixture - Bullet Trap Area	760
VTMOR203-10	Stored Item - Office Area (Cabinet Top)	<110
VTMOR203-11	Floor - Office Area	250
VTMOR203-12	Field Blank	<12 μg
VTMOR203-13	Floor - Bullet Trap Area	8800
VTMOR203-14	Floor Outside the Range	250

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the instructions for *Completing the Sampling of Army National Guard Armories* procedure.

Appendix A

HHIM Data Form(s)

HEALTH HAZARD INFORMATION MODULE: INDUSTRIAL HYGIENE SURVEY

(For use of this form, see HHIM User's Guide)

SECTION 1. DEMOGRAPHIC DATA

ARLOC: INSTALLATION: Montpelier Armory Vermont ARNG BLDG/RM NO.: Montpelier

LOCATION/CODE: Administrative Areas/AA OPERATION/CODE: Administrative OP/ADO

SURVEY DATE: 22 July 2003 EVALUATOR (Initials): Non-Responsive

MACOM/CODE: Army National Guard SUBMACOM/CODE: XX SUPERVISOR: Non-Responsive

TELEPHONE/DSN NO.: 802-888-4416 UNIT/ORGANIZATION: G11-172 AR.FTS RAC: 5 FREQUENCY (hrs/day): 8

NO. CIV(S): 0 NO. MIL: 4 NO. CONTRACTOR(S): 0 NO. LOC(S): 0 NO. OTHER: 0

SECTION 2. FACILITY DATA

LAB HOODS: VAPOR DEGREASERS: SPRAY BOOTHS:

MAINTENANCE BAYS: OPEN SURFACE TANKS: VENTILATION UNITS:

SECTION 3. SURVEY DATA

CONTROLS PRESENT	EVALUATION	UNIT CODE	CONTROLS REQUIRED	STATUS

PERSONAL PROTECTIVE EQUIPMENT (R = Required; U = Utilized)

GLOVES	R	U	RESPIRATOR	NIOSH TC NO.	MANUFACTURER	R	U
ACID			AIRLINE				
COLD SURFACES			ABRASIVE BLASTING HOOD				
HOT SURFACES			DISPOSABLE				
HBC AGENTS			FULL FACE AIR PURIFYING				
OR			1/2 FACE AIR PURIFYING				
SOLVENTS			POWERED AIR PURIFYING				
SURGICAL GLOVES			1/4 FACE AIR PURIFYING				
			SELF CONTAINED				

EYES/FACE	R	U	HEARING	R	U	BODY	R	U	HEAD/HAT	R	U
CHEMICAL SPLASH			CANAL CAPS			APRONS			COLD WEATHER BOOTS/HATS		
FULL FACE SHIELD			EAR PLUGS			COLD WEATHER CLOTHING			HARD HATS		
CHEMICAL/SAFETY			HELMETS			COVERALLS			IMPERMEABLE BOOTS		
SAFETY/IMPACT			MUFFS			FULL BODY SUIT			SAFETY/CONDUCTIVE SHOES		
WELDING HELMET			MUFF/EARPLUG COMBO			HEAT REFLECTIVE VEST/SUIT			SAFETY/NON-CONDUCTIVE SHOES		
			MUFF/EARPLUG W/TIME LIMIT			SAFETY BELT/HARNES					

AEHA Form 271-R (Test) 1 Jan 92 (HSHB-MI-1)

SECTION 4. HAZARD INVENTORY DATA

CAS CODE	HAZARD DESCRIPTION	PAC	EPC
POVDTXXXX	Video Display Terminal	3-low	Uncontrolled Physical
13825-21-4	Asbestos (Other)	2-moderate	Uncontrolled Respiratory
7439-92-	Lead, inorganic dusts and fumes	2-moderate	Uncontrolled Respiratory

SECTION 5. PERSONNEL DATA

LAST NAME	FIRST NAME	MI	SEX	SSN	CATEGORY
Non-Responsive		T	M	Not available	
		L			
		E			
		W			

SECTION 6. COMMENTS

No comments See attached sheet
 Survey conducted by Tucker Seman contain 4 full time employees.
 Employees perform mainly administrative functions.

PRIVACY ACT STATEMENT

Title 5 US Code, Section 301; Executive Order 9397 authorizes the use of your Social Security Number as an identification number. The purpose of this information is to identify and monitor data relating each DA civilian and military employee exposed to a hazardous workplace or operation. The use of this information is to provide histories of exposures for any given worker.


Disclosure of your Social Security Number is not mandatory; however, nondisclosures may result in untimely provision of proper medical monitoring.

C/1-172 AR FTS Roster

1SG	Non-Responsive	ess NCO
SSG		- Training NCO
SSG		Sergeant
SSG		R NCO

Appendix B

Building Layout



EXTINGUISHER

○ 22 JUNY 2003
 △ 8 OCTOBER 2003

FLOOR PLAN
MORRISVILLE ARMORY
SCALE: 1" = 20' 6 NOV. / 80

FIRE EVACUATION PLAN

Appendix C

Sampling Sheets and Laboratory Analyses

Client: National Guard Bureau
 Address: 301-IE Old Bay Lane, Attn: NGB-AVN-SL
 State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTMOR203
 Job Location: Not Provided
 Job Number: Not Provided
 P.O. Number: 07-01

Chain Of Custody: 115813
 Date Analyzed: 08/05/2003
 Person Submitting: [REDACTED]
 Report Date: 18-Aug-03

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft²)	Reporting Limit	Final Result	Comments
0359523	VTMOR203-1	Flame	Wipe	*****	0.111	108.00 ug/ft²	< 110 ug/ft²	
0359524	VTMOR203-2	Flame	Wipe	*****	0.111	108.00 ug/ft²	< 110 ug/ft²	
0359525	VTMOR203-3	Flame	Wipe	*****	0.111	108.00 ug/ft²	130 ug/ft²	
0359526	VTMOR203-4	Flame	Wipe	*****	0.111	108.00 ug/ft²	220 ug/ft²	
0359527	VTMOR203-5	Flame	Wipe	*****	0.111	108.00 ug/ft²	260 ug/ft²	
0359528	VTMOR203-6	Flame	Wipe Blank	*****	N/A	12.00 ug	< 12 ug	
0359529	VTMOR203-7	Flame	Wipe	*****	0.111	108.00 ug/ft²	5000 ug/ft²	
0359530	VTMOR203-8	Flame	Wipe	*****	0.111	108.00 ug/ft²	1600 ug/ft²	
0359531	VTMOR203-9	Flame	Wipe	*****	0.111	108.00 ug/ft²	760 ug/ft²	
0359532	VTMOR203-10	Flame	Wipe	*****	0.111	108.00 ug/ft²	< 110 ug/ft²	
0359533	VTMOR203-11	Flame	Wipe	*****	0.111	108.00 ug/ft²	250 ug/ft²	
0359534	VTMOR203-12	Flame	Wipe Blank	*****	N/A	12.00 ug	< 12 ug	
0359535	VTMOR203-13	Flame	Wipe	*****	0.111	108.00 ug/ft²	8800 ug/ft²	
0359536	VTMOR203-14	Flame	Wipe	*****	0.111	108.00 ug/ft²	250 ug/ft²	

BEST AVAILABLE COPY

BEST AVAILABLE COPY

FOIA Requested Record #J-15-0085 (1)
 Released by National Guard Bureau

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

All rights reserved. AMA Analytical Services, Inc.

An AIHA (#8863), NVLAP (# 101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

Client: National Guard Bureau
 Address: 301-IH Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTMR0203
 Job Location: Not Provided
 Job Number: Not Provided
 P.O. Number: 07-01

Chain Of Custody: 115813
 Date Analyzed: 08/05/2003
 Person Submitting: [Redacted]
 Report Date: 18-Aug-03

Attention: [Redacted]

Page 2 of 2

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B
 N/A = Not Applicable mg/kg = parts per million (ppm) by weight ug/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)
 Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] Non-Responsive

Technical Manager: [Redacted]

[Redacted] Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

All rights reserved. AMA Analytical Services, Inc.

An AIHA (#8863), NVLAP (# 101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

Client: National Guard Bureau
Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SL
 State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTMOR203
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01

Chain Of Custody: 115919
Date Analyzed: 08/18/2003
Person Submitting: [Redacted]
Report Date: 18-Aug-03

Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0362704	VTMOR203-15	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362705	VTMOR203-16	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362706	VTMOR203-17	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362707	VTMOR203-18	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0362708	VTMOR203-19	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362709	VTMOR203-20	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms mg/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] Technical Manager: [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

An AIHA (#8863), NVLAP (# 101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

CERTIFICATE OF ANALYSIS

AMA Analytical Services, Inc.
A Specialized Environmental Laboratory

Client: National Guard Bureau
Address: 301-JH Old Esy Lane, Attn: NGB-AVN-SI, State Military Reservation, Havre de Grace, Maryland 21078

Job Name: VTMOR203
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01

Chain Of Custody: 115813
Date Analyzed: 8/5/2003
Person Submitting: [Redacted]
Report Date: 05-AUG-03

Page 2 of 2

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per billion (ppb)

%Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)
Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
							Non-Responsive	Technical Manager: [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a medical protection to clients, the public and these Laboratories, no report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of brick samples and transmission electron microscopy of AHRA air samples.

All rights reserved. AMA Analytical Services, Inc.

An AIHA (#8863), NVLAP (#101143), & New York ELAP (#10920) Accredited Laboratory

Client: National Guard Bureau Job Name: VTMOR282 Chain Of Custody: 118707
 Address: 301-H Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation Job Location: Not Provided Date Analyzed: 10/21/2003
 Havre de Grace, Maryland 21078 Job Number: Not Provided Person Submitting: [Redacted]
 P.O. Number: 0701 Report Date: 21-Oct-03

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft²)	Reporting Limit	Final Result	Comments
0402850	VTMOR282-1	Furnace	Wipe	****	0.111	67.51 ug/ft²	270 ug/ft²	
0402851	VTMOR282-2	Furnace	Wipe	****	0.111	2.70 ug/ft²	21 ug/ft²	
0402852	VTMOR282-3	Furnace	Wipe	****	0.111	67.51 ug/ft²	400 ug/ft²	
0402853	VTMOR282-4	Furnace	Wipe	****	0.111	13.50 ug/ft²	66 ug/ft²	
0402854	VTMOR282-5	Furnace	Wipe	****	0.111	5.40 ug/ft²	37 ug/ft²	
0402855	VTMOR282-6	Furnace	Wipe Blank	****	N/A	0.30 ug	0.33 ug	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per million (ppm)

%Pb = percent lead by weight ug = micrograms mg/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] Technical Manager: [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. All rights reserved. AMA Analytical Services, Inc.



Submitted To: **Non-Responsive**
 Shaw Environmental, Inc.
 101 Fieldcrest Ave., 4th Floor
 Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTCAM205-A1 through VTAAS204-A3
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Filter
Method Reference:	NIOSH 7300
DCL Set ID No.:	03-S-3621
DCL Sample ID No.:	03-22309 through 03-22345
Sample Receipt Date:	7/28/2003
Preparation Date:	07/29/03
Analysis Date:	07/31/03

The samples were prepared and analyzed in accordance with NIOSH method 7300 using a Perkin Elmer 3000XL ICP.

The sample condition upon receipt was acceptable except where noted.

The results are in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive



Analyst

Non-Responsive



Reviewer

CINCINNATI OFFICE
 4388 GLENDALE-MILFORD ROAD
 CINCINNATI, OHIO 45242-3706
 513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
 11 SANTA YORMA COURT
 NOVATO, CALIFORNIA 94945
 800 280-8071, FAX 415 893-9469

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTCAM205-A1	03-22309	407.54	ND	<0.002
VTCAM205-A2	03-22310	377.66	ND	<0.003
VTCAM205-A3	03-22311	0	ND	-
VTWIN202-A1	03-22313	152.91	ND	<0.007
VTWIN202-A2	03-22314	0	ND	-
VTENO196-A1	03-22316	150.55	ND	<0.007
VTENO196-A2	03-22317	0	ND	-
VTWIL197-A1	03-22319	199.78	ND	<0.005
	Prep Blank 1		ND	
% Recovery	LCS 1		96.	
% Recovery	LCS 2		96.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).
 LCS = laboratory control sample.

Non-Responsive

Analyst

Non-Responsive

Reviewer

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTWIL197-A2	03-22320	149.76	ND	<0.007
VTWIL197-A3	03-22321	0	ND	-
VTSWA196-A1	03-22322	149.24	ND	<0.007
VTSWA196-A2	03-22323	0	ND	-
VTSTA196-A1	03-22324	165.20	ND	<0.006
VTSTA196-A2	03-22325	151.74	ND	<0.007
VTSTA196-A3	03-22326	0	ND	-
VTWAT203-A1	03-22328	194.90	ND	<0.005
VTWAT203-A2	03-22329	0	ND	-
VTGOS202-A1	03-22332	175.30	ND	<0.006
VTGOS202-A2	03-22333	0	ND	-
VTMOR203-A1	03-22335	346.43	ND	<0.003
VTMOR203-A2	03-22336	348.65	ND	<0.003
VTMOR203-A3	03-22337	0	ND	-
VTGRE197-A1	03-22340	240.55	ND	<0.004
VTGRE197-A2	03-22341	250.76	ND	<0.004
VTGRE197-A3	03-22342	0	ND	-
VTAAS209-A1	03-22343	748.92	ND	<0.001
VTAAS209-A2	03-22344	507.55	ND	<0.002
VTAAS209-A3	03-22345	0	ND	-
	Prep Blank 2		ND	
% Recovery	LCS 3		96.	
% Recovery	LCS 4		95.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).
LCS = laboratory control sample.

Non-Responsive



Analyst

Non-Responsive



REVIEWER

Industrial Hygiene Sampling Calculation Worksheet

National Guard Armory Location: MOR
 Date: 203

Sample 1

Sample Number: VTMOR203-A1

Pump: 648339

	Pre Flow Rate	Post Flow Rate
	2.51	2.442
	2.508	2.445
	2.502	2.441
	2.511	2.437
Average	2.508	2.441
Average Pre and Post	2.4746	
Time 1	8:51	
Time 2	11:11	
Total Time Sampled	2:20	
Minutes Sampled	140.00	
Volume	346.43 Liters	

Sample 2

Sample Number: VTMOR203-A2

Pump: 647615

	Pre Flow Rate	Post Flow Rate
	2.525	2.459
	2.516	2.468
	2.513	2.469
	2.512	2.461
Average	2.517	2.464
Average Pre and Post	2.4904	
Time 1	8:53	
Time 2	11:13	
Total Time Sampled	2:20	
Minutes Sampled	140.00	
Volume	348.65 Liters	



Submitted To: **Non-Responsive**
Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTCAM205-B1 through VTMC203-B2
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Paint Chip
Method Reference:	3050B/6010B
DCL Set ID No.:	03-S-3621
DCL Sample ID No.:	03-22312 through 03-22339
Sample Receipt Date:	07/28/2003
Preparation Date:	07/29/2003
Analysis Date:	07/31/2003

The samples were prepared in accordance with EPA method 3050B. Sample condition was acceptable upon receipt except where noted. The samples were then analyzed in accordance with EPA method 6010B using a Jarrell Ash Trace ICP.

The results are provided in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive

Analyst

Non-Responsive

Reviewer

CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 280-8071, FAX 415 893-9469

Results Lead

Client #	DCL #	mg/Kg (ppm)	% by weight
VTCAM205-B1	03-22312	160.	0.016
VTWIN202-B1	03-22315	11000.	1.1
VTENO196-B1	03-22318	96000.	9.6
VTSTA197-B1	03-22327	1800.	0.18
VTWAT203-B1	03-22330	40.	0.0040
VTWAT203-B2	03-22331	57.	0.0057
VTMOR203-B1	03-22338	3900.	0.39
VTMOR203-B2	03-22339	11000.	1.1
	Prep Blank	ND	
% Recovery	LCS	87.	
% Recovery	03-22327 MS	* 0.	
% Recovery	03-22327 MSD	* 4.	
RPL		25.	0.0025

ND = not detected at or above the reporting limit (RPL).

LCS = laboratory control sample.

MS/MSD = matrix spike/matrix spike duplicate.

* Low recovery due to non-homogeneous sample matrix.

Non-Responsive



Analyst

Non-Responsive



Reviewer

Appendix D

References

References

Title 29, Code of Federal Regulations CFR), Part 1910, Occupational Safety and Health Administration (current edition)

American Society of Heating, Refrigerating and Air-Conditioning Engineers, Inc (ASHRAE) 62-2002, Ventilation for Acceptable Indoor Air Quality

Instructions for Completing the Sampling of Army National Guard Armories, Lead Wipe Sampling Procedure included with the Request for Proposal

Air Sampling for Lead - Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods

Design Guide DG-415-2, Logistics Facilities, National Guard Bureau Installation Division, 14 December 1999

Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998

Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, 15 October 1990

AR 385-10, The Army Safety Program, 29 February 2000

Department of the Army Pamphlet (DA PAM) 40-501, Medical Services, Hearing Conservation Program, 10 December 1998

DA PAM 40-503, Medical Services, Industrial Hygiene Program, 30 October 2000

Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH) (current edition)

Guidelines for Converting Indoor Firing Ranges to Other Uses, Headquarters, Department of the Army and the Air Force, NG PAM (AR) 385-16/ANGPAM 91-101, 31 January 1994

24 CFR, Part 35, Subpart B, Section 35-110, Definition of Lead-Based Paint, Housing and Urban Development, U. S. Department of Housing

Appendix E
Recommendations for
Surface Lead Dust in Armories

Subject: Recommendations for Surface Lead Dust in Armories

1. In armories that do not contain childcare facilities, the National Guard Bureau (NGB) Region North Industrial Hygiene Office recommends cleaning the areas in which sample results are greater than 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$). If a special function will be held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function. This guidance is based on professional judgment, risk assessments, adaptation of Occupational Safety and Health Administration (OSHA) guidance, and feasibility of cleaning to a certain level.

a. Environmental Protection Agency (EPA) standards (40 Code of Federal Regulations (CFR) 745.227(h)(3)) are not directly applicable because they are criteria for dust-lead hazards developed for floors ($40 \mu\text{g}/\text{ft}^2$) and windowsills ($250 \mu\text{g}/\text{ft}^2$) in residential dwellings and child occupied facilities. A child occupied facility is defined as a building, or portion of a building, constructed prior to 1978, visited regularly by the same child, 6 years of age or under, on at least two different days within any week (Sunday through Saturday period), provided that each day's visit lasts at least 3 hours and the combined weekly visit lasts at least 6 hours, and the combined annual visits last at least 60 hours. Most of the wipe samples in armories were collected in undisturbed areas and therefore, results are worst case scenarios and do not correlate to these standards.

b. OSHA has no specific requirement for work area surfaces. The lead standard (29 CFR 1910.1025(h)) states that all surfaces shall be maintained as free as practicable of accumulations of lead dust. In workplaces where lead dust is generated, surface levels may be much higher, but personnel exposures can be controlled by limiting airborne lead levels and following good cleanup and hygienic practices.

c. OSHA used to cite a level of $200 \mu\text{g}/\text{ft}^2$ in their Technical Manual and 29 CFR 1926.62 as guidance to its own inspectors for evaluating the cleanliness of lunchroom and locker room surfaces that are supposed to be kept as clean as possible.

d. In a report titled Derivation of Wipe Surface Screening Levels for Environmental Chemicals, the US Army Center for Health Promotion and Preventive Medicine (USACHPPM) has determined that $200 \mu\text{g}/\text{ft}^2$ is a safe surface contamination level. They have also applied these standards as the decontamination levels for surfaces in administrative offices.

e. It should be noted that levels above these recommendations do not necessarily mean there is a significant hazard to workers who are following good cleaning and hygienic practices since there is no correlation between wipe and air samples. Rather, we recommend these levels as a precautionary measure.

2. The NGB Occupational Health Branch is developing guidance for armories that are used as childcare facilities. All states will receive this guidance when it is completed. In the interim, we recommend the following actions:

a. Clean all areas that will be accessible to children to the EPA dust-lead standard for children 6 years of age or under ($40 \mu\text{g}/\text{ft}^2$ on floors and $250 \mu\text{g}/\text{ft}^2$ on windowsills).

b. Refer to the local authorities' regulations since they can be more stringent than federal regulations.

c. Post signs in the area to inform people of the presence of lead dust and its effects.

d. If soldiers clean weapons in the facility change the policy so that they cannot clean their weapons in the facility, or if they are allowed to clean their weapons indoors, they must clean the area by wet wiping and mopping the area when they are done.

e. If the paint is peeling, contact the state Environmental Office to test for lead content and provide recommendations.

3. Air samples collected on individuals in the armory were well below OSHA's permissible exposure limit for lead (29 CFR 1910.1025(e)) of $0.05 \text{ mg}/\text{m}^3$ averaged over an 8-hour day. Therefore, based on these conditions there is currently no overexposure to personnel from lead dust in this building.

Industrial Hygiene Survey

Vermont Army National Guard (VT ARNG)

Prepared For: NGB ARNG– Region North IH Office

Survey Location:

Morrisville Readiness Center
415 Farr Avenue
Morrisville, VT 05661

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 26, 2011

AEI Project #: J11-601 4L VT Morrisville RC

Non-Responsive, CIH, CSP
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

Table of Contents

Executive Summary ii

1 Introduction 1

2 Evaluation Methods 1

3 Operations 1

4 Noise Hazards 1

5 Hazard Controls 1

Ventilation Systems 1

6 Physical Condition of the Facility and Personnel Concerns 2

Paint Chip and Dust Wipe Samples for Lead Contamination 2

Visual Inspection for Damaged Asbestos-Containing Materials 3

Visual Inspection for Water Damage and Mold Growth 3

Visual Inspection for Housekeeping Concerns 3

Lighting 3

Indoor Air Quality (IAQ) 3

Temperature and Relative Humidity 4

Carbon Dioxide (CO₂) and Carbon Monoxide (CO) 4

7 Conclusions 4

8 Limitations 5

List of Tables and Appendices

Table 1 - Results of Dust Wipe Sampling for the VT ARNG Morrisville Readiness Center on October 26, 2011.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

Appendix A – Building Layout

Appendix B – Certificates of Analysis for Air, Dust Wipe and Bulk Samples

Appendix C – Photo Documentation

Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Morrisville Readiness Center located at 415 Farr Avenue, Morrisville, VT 05661. **Non-Responsive**, CIH, CSP performed the evaluation on October 26, 2011. The point of contact for the facility was SGT **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Paint Chip and Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. No peeling paint was observed in the facility. Results of dust wipe samples taken throughout the facility were below the recommended maximum criterion for surface contamination of lead (200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$)) in all areas sampled except for a sample collected on the bay door in the Drill Hall (270 $\mu\text{g}/\text{ft}^2$).

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there were any suspect asbestos-containing material and its condition. No damaged suspect material was observed.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. A water stain was observed on the Fitness Center ceiling. No evidence of wet areas or mold growth was observed on the day of the survey.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping needed improvement. Floors were dirty, and dust had accumulated on many of the horizontal surfaces. Unlike several other Vermont Readiness Centers that were surveyed, this Readiness Center does not have a custodian.

Lighting: A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in the storage locker, the kitchen, the family readiness room, the supply office and the boiler room. The illumination measurements indoors ranged from 3 foot candles (fc) to 75 fc.

Indoor Air Quality: Temperature and relative humidity measurements were within the comfort ranges for the winter season on the day of the survey. The outdoor temperature and relative humidity were 55.3° F and 36.3% on the day of monitoring. Indoor concentrations of carbon dioxide (CO_2) and carbon monoxide (CO) were below the guidelines in all areas.

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was readily available. MSDSs for some new custodial products were required per OSHA 29 CFR 1910.1200.

Overall, the Morrisville Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Morrisville Readiness Center located at 415 Farr Avenue, Morrisville, VT 05661. **Non-Responsive** CIH, CSP performed the evaluation on October 26, 2011. The point of contact for the facility was SGT **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

The Morrisville Readiness Center was built in the 1950's. The readiness center is staffed by 6 administrative personnel. The operations conducted at the facility include supply and administrative duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the Morrisville Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) evaluations of operations including operation description, sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the Morrisville facility consist exclusively of supply and administrative duties. No maintenance of vehicles or other physical tasks are performed at the facility.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; potential ergonomic problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were collected in select areas.

Paint Chip and Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. No peeling paint was observed. To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected using ghost wipes and 10 centimeter (cm) x 10cm templets. The Environmental Protection Agency (EPA) and the State of Vermont limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. All wipe samples collected from the facility were below the recommended maximum except for the sample collected from the ledge of the bay door in the Drill Hall (270 $\mu\text{g}/\text{ft}^2$). Results are given in Table 1 and certificates of analysis are included in Appendix B.

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
Morrisville Readiness Center on October 26, 2011.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
MOR – 01	Former Firing Range – bullet trap area – floor	<110
MOR – 02	Former Firing Range – metal stand	<110
MOR – 03	Former Firing Range – metal tool case	<110
MOR – 04	Former Firing Range – metal shelf	<110
MOR – 05	Former Firing Range – counter	<110
MOR – 06	Drill Hall – floor	<110
MOR – 07	Drill Hall – table	<110
MOR – 08	Drill Hall – bay door ledge	270
MOR – 09	Drill Hall – chemical storage cabinet	160
MOR – 10	Drill Hall – floor	<110
MOR – 11	Kitchen – serving counter	<110
MOR – 12	Supply Room – floor	<110

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
Morrisville Readiness Center on October 26, 2011.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
MOR – 13	Gym - floor	<110

*The recommended maximum level for adult exposures is 200 $\mu\text{g}/\text{ft}^2$ lead on surfaces.

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). No damaged suspect ACM was observed.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. A water stain was observed in the fitness center. No wet areas or evidence of mold growth was observed on the day of the inspection.

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping needed improvement. Floors were dirty, and dust had accumulated on many of the horizontal surfaces. Unlike several other Vermont Readiness Centers that were surveyed, this Readiness Center does not have a custodian.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on March 9, 2011, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in a few areas: the storage locker, the kitchen, the family readiness room, the supply office and the boiler room. The illumination measurements indoors ranged from 3 foot candles (fc) to 75 fc. The complete results of the evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Plus Model 8554, factory calibrated in February, 2011. Temperature, relative humidity and carbon dioxide (CO_2) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 2. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30 and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 70.1 to 73.5° F and 32.1 to 47.9% Rh. Temperatures and relative humidity were within the summer comfort ranges in the areas monitored. The outdoor temperature and relative humidity was 55.3° F and 36.3% on the day of monitoring.

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1–2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 508 to 862 parts per million (ppm). CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange.

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 0.5 to 1.3 ppm; therefore, concentrations are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

Additional Information

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was readily available. MSDSs for some new custodial products were required per OSHA 29 CFR 1910.1200.

7 Conclusions

The results of the evaluation indicated no concerns with the following at the facility: contamination of clean air sources, peeling potentially lead-based paints, noise hazards, visible mold and the presence of damaged suspect asbestos-containing materials. The results of the evaluation indicated industrial hygiene concerns in the following areas: accumulated lead-containing dust in one area, lighting, MSDS updates and housekeeping. Overall, the Morrisville Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.


9 References

1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.
3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.
4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.
5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2011.
6. Army Regulation (AR) 420-70 Buildings and Structures, 10 October 1997.
7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 28 March 2009.
8. Army Regulation (AR) 420-1 Army Facilities Management, 28 March 2009.
9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.
10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.
12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".
15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.

Appendix A Building Layout



First Floor

Prepared by: AIM Group <i>Environmental Consultants</i> Morrisville, Vermont	Morrisville Armory - Project # 9800307 Asbestos-Containing Material Locations Scale: 1/16"=10" (+/-) December 1, 1997	ACM-1
--	--	--------------

Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	Morrisville RC	Chain Of Custody:	511727
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Morrisville, VT	Date Submitted:	11/1/2011
Attention:	Non-Responsive	Job Number:	J11-601	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/7/2011
				Report Date:	11/8/2011

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
12010513	Mor-01	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010514	Mor-02	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010515	Mor-03	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010516	Mor-04	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010517	Mor-05	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010518	Mor-06	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010519	Mor-07	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010520	Mor-08	Flame	Wipe	****	0.111	110 ug/ft ²	30	270 ug/ft ²	
12010521	Mor-09	Flame	Wipe	****	0.108	110 ug/ft ²	17	160 ug/ft ²	
12010522	Mor-10	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010523	Mor-11	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010524	Mor-12	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010525	Mor-13	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS



Client: National Guard Bureau	Job Name: Morrisville RC	Chain Of Custody: 511727
Address: 301-JH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location: Morrisville, VT	Date Submitted: 11/1/2011
Attention: Non-Responsive	Job Number: J11-601	Person Submitting: Non-Responsive
	P.O. Number: W912K6-09-A-0003	Date Analyzed: 11/7/2011
		Report Date: 11/8/2011

Summary of Atomic Absorption Analysis for Lead

Page 2 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm) %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb) Note: All samples were received in good condition unless otherwise noted. Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result. Air and Wipe results are not corrected for any blank results Final results for air and wipe samples are based on client supplied information nor verified by this laboratory. All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.							See QC Summary for analytical results of quality control samples associated with these samples.		
						Analy Non-Responsive	Technical Manag Non-Responsive		

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



AMA Analytical Services, Inc.
Focused on Results www.amalab.com
AIHA (#100470) NVLAP (#101143-0) NY ELAP (10920)
4475 Forbes Blvd. • Lanham, MD 20706
(301) 459-2640 • (800) 346-0961 • Fax (301) 459-2643

CHAIN OF CUSTODY

(Please Refer To This Number For Inquiries)

Handwritten notes: 511727, p.2/2, (2)

Mailing/Billing Information:

1. Client Name: National Guard Bureau
2. Address 1: 301-IH Old Bay Lane
3. Address 2: Attn: NGB-AVN:SI, State Military Reservation
4. Address 3: Havre de Grace, Maryland 21078
5. Phone #: (410) 942-0273 Fax #: (410) 942-0254

Submittal Information:

1. Job Name: Morrisville PC
2. Job Location: Morrisville, VT
3. Job #: J11-601
4. Contact Person: Non-Responsive
5. Submitted by: Non-Responsive

Reporting Information (Results will be provided as soon as technically feasible):

AFTER HOURS (must be pre-scheduled)
Immediate Date Due:
24 Hours Time Due:
Comments:

NORMAL BUSINESS HOURS
Immediate
Next Day
2 Day
3 Day
3 Day +
Date Due:
Results Required By Noon (Every Attempt Will Be Made to Accommodate)

REPORT TO:
Include:
Email:
Fax:
Verbal:
ar@aeuvis.com
us.army.mil
us.army.mil

Asbestos Analysis

PCM Air - Please Indicate Filter Type:
NIOSH 7400 (QTY)
Fiberglass (QTY)
TEM Air - Please Indicate Filter Type:
AHERA (QTY)
NIOSH 7402 (QTY)
Other (specify) (QTY)
PLM Bulk
EPA 600 - Visual Estimate (QTY)
EPA Point Count (QTY)
NY State Friable 198.1 (QTY)
Grav. Reduction ELAP 198.6 (QTY)
Other (specify) (QTY)

TEM Bulk

ELAP 198.4/Chatfield (QTY)
NY State PLM/TEM (QTY)
Residual Ash (QTY)

TEM Dust

Qual. (pres/nbs) Vacuum/Dust (QTY)
Quan. (s/area) Vacuum D5755-95 (QTY)
Quan. (s/area) Dust D6180-99 (QTY)

TEM Water

Qual. (pres/abs) (QTY)
ELAP 198.2/EPA 100.2 (QTY)
EPA 100.1 (QTY)

All samples received in good condition unless otherwise noted. (TEM Water samples °C)

Metal Analysis

Pb Paint Chip (QTY)
Pb Dust Wipe (wipe type) (QTY)
Pb Air (QTY)
Pb Soil/Solid (QTY)
Pb TCLP (QTY)
Drinking Water Pb (QTY) Cu (QTY) As (QTY)
Waste Water Pb (QTY) Cu (QTY) As (QTY)
Pb Furnace (Media) (QTY)

Fungal Analysis

Collection Apparatus for Spore Traps/Air Samples:
Collection Media:
Spore Trap (QTY)
Surface Vacuum Dust (QTY)
Surface Swap (QTY)
Culturable ID Occas (Media) (QTY)
Surface Tape (QTY)
Culturable ID Species (Media) (QTY)
Other (Specify) (QTY)

Table with columns: CLIENT ID NUMBER, SAMPLE INFORMATION (LOCATION, DATE, VOLUME, WIPER AREA), ANALYSIS (ITEM, PCM, PLM, LEAD, MOLD, AIR, BULK, DUST, MATRI), CLIENT CONTACT (Date/Time, Contact, By). Includes handwritten entry for 'Mor-13' on 10/26.

LABORATORY STAFF ONLY: (CUSTODY)

1. Date/Time RCVD: @ Via: By (Print): Sign:
2. Date/Time Analyzed: @ By (Print): Sign:
3. Results Reported To: Via: Date: Sign:
4. Comments:

Appendix C Photo Documentation

Morrisville, VT Readiness Center



Morrisville RC Exterior



Drill Hall



Storage – Former Firing Rang



Storage – Former Firing Range 2

Morrisville, VT Readiness Center



Bullet Trap Area of Former Firing Range



Improperly stored flammable liquid canisters



Classroom



View of Kitchen

Morrisville, VT Readiness Center



Kitchen



Kitchen 2



Kitchen 3



Family Readiness Room

Morrisville, VT Readiness Center



Janitor's Closet



Janitor's Closet 2



Janitor's Closet 3

Posted to NGB FOIA Reading Room
May, 2018



Fitness Center

Morrisville, VT Readiness Center




Water Damage on Ceiling



Fitness Center



CDR/1SG Office



Recruiting Office

Morrisville, VT Readiness Center



Office



Office



Drill Hall 2

Posted to NGB FOIA Reading Room
May, 2018



Flammable Storage Cabinets

Morrisville, VT Readiness Center



Supply Room



Supply Room



Boiler Room



Boiler Room 2

Morrisville, VT Readiness Center



Boiler Room Pipe Insulation



Boiler Room Pipe Insulation



Flammable Storage Cabinet 2

Posted to NGB FOIA Reading Room
May, 2018



MSDS Notebook

Appendix D
IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Morrisville	IAQ								Light		
Date	10/26/2011	Inspector	Non-Responsive	Instrument	Q-trak 7565-X								Instrument	Cal-Light 400
Facility Description	Morrisville RC			Serial Number	7565X0839020								Serial Number	K070003
Weather Conditions	Cool, Clear			Last Calibration	Feb-11								Last Calibration	9-Mar-11
Location/Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)	
Storage Locker	1	14:40	70.1		47.9		532		1.0		5-40	X	7	
Classroom	1	15:17	71.8		36.1		572		1.3		30-75		30-50	
Kitchen	1	15:18									35-40	X	50	
Kitchen Storage	1	15:18	71.2		32.1		509		0.6		17-25		5	
Family Readiness	1	15:21	70.5		36.9		597		0.7		10-48	X	30-50	
JC	1	15:22									42		30	
Ladies Restroom	1	15:22	71.1		43.5		508		0.6		33		5	
Gym	1	15:23	70.9		38.1		625		1.2		30-55		30-50	
Foyer	1										20		10	
CDR/1SG Office	1	15:25	71.3		39.4		688		1.0		30-40		30-50	
R&R Office	2	15:25	72.3		38.5		668		0.9		30-45		30-50	
Admin Office	2	15:26	73.3		38.1		695		1.0		40-55		30-50	
Readiness NCO Office	2	15:28	73.5		36.8		673		0.7		30-55		30-50	
Supply Office	3	15:29	72.3		41.7		862		1.3		3-55	X	30-50	
Boiler Room	1	15:31	73.5		35.8		620		0.5		6-30	X	30	
Storage Room	1	15:32									30		30	
Drill Hall	1	15:35	71.7		37.4		630		1.0		40-70		30-50	
Outside		16:15	55.3		36.3		419		1.4					

Industrial Hygiene Survey

Vermont Army National Guard (VT ARNG)

Prepared For: NGB ARNG- Region North IH Office

Survey Location:

Morrisville Readiness Center

415 Farr Avenue
Morrisville, VT 05661

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 17, 2012

AEI Project #: J12-685 3M VT Morrisville RC

Non-Responsive, DrPH, CIH
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

Table of Contents

Section	Page
Executive Summary	ii
1 Introduction	1
2 Evaluation Methods.....	1
3 Operations	1
4 Noise Hazards	1
5 Hazard Controls.....	1
Ventilation Systems	1
6 Physical Condition of the Facility and Personnel Concerns.....	2
Paint Chip and Dust Wipe Samples for Lead Contamination	2
Visual Inspection for Damaged Asbestos-Containing Materials.....	3
Visual Inspection for Water Damage and Mold Growth.....	3
Visual Inspection for Housekeeping Concerns	4
Lighting	4
Indoor Air Quality (IAQ).....	4
Temperature and Relative Humidity	5
Carbon Dioxide (CO ₂) and Carbon Monoxide (CO)	5
Additional Information.....	5
7 Conclusions.....	5
8 Limitations.....	5
9 References.....	6

List of Tables

Table 1 – Results of Lead Paint Chip Sampling for VT ARNG Morrisville Readiness Center on October 17, 2012

Table 2 - Results of Dust Wipe Sampling for the VT ARNG Morrisville Readiness Center on October 17, 2012.

Table 3 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

List of Appendices

Appendix A – Building Layout

Appendix B – Certificates of Analysis for Air, Dust Wipe and Bulk Samples

Appendix C – Photographic Documentation

Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Morrisville Readiness Center located at 415 Farr Avenue, Morrisville, VT 05661. **Non-Responsive**, DrPH, CIH performed the evaluation on October 17, 2012. The point of contact for the facility was SGT **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Paint Chip and Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed on the exterior of the facility. Samples were collected from the porch ceiling and an exterior metal door. The peeling, flaking and chipping paint on the porch ceiling is lead-based paint. The paint on the exterior door is not lead-based paint. Results of dust wipe samples taken throughout the facility were below the recommended maximum criterion for surface contamination of lead (200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$)) in all areas sampled except for a sample collected from the floor in the Drill Hall (270 $\mu\text{g}/\text{ft}^2$).

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there were any suspect asbestos-containing material and its condition. The only damaged suspect asbestos-containing material was limited to small areas of broken floor tile in the office area.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No evidence of water intrusion or mold growth was observed on the day of the survey.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping appeared to be acceptable overall. One area of concern was observed in the Drill Hall. Oily rags were stored in plastic bags in the flammable materials storage cabinet that also contained propane cylinders. The POL storage cabinet doors do not close properly. This is a fire and life safety hazard as the cabinets are in the route of egress to the supply room and arms vault.

Lighting: A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in a few areas: the platoon room, Office 1, the gym, the janitor's closet, FSC Office, maintenance, the kitchen and the boiler room. The illumination measurements indoors ranged from 13.7 foot candles (fc) to 82.0 fc.

Indoor Air Quality: Temperature measurements fell just below the comfort range for the winter season in all but five of the locations measured. Relative humidity measurements were within the comfort ranges for the winter season on the day of the survey. The outdoor temperature and relative humidity were 46.5° F and 39.5% on the day of monitoring. Indoor concentrations of carbon dioxide (CO_2) and carbon monoxide (CO) were below the guidelines in all areas. A diesel

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

powered fork lift was parked inside the drill hall on the day of monitoring. The use of diesel powered equipment indoors may contribute to unsafe carbon monoxide concentrations.

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was readily available. MSDS were last updated in July of 2009. MSDSs for some new custodial products were required per OSHA 29 CFR 1910.1200.

Overall, the Morrisville Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Morrisville Readiness Center located at 415 Farr Avenue, Morrisville, VT 05661. **Non-Responsive**, DrPH, CIH performed the evaluation on October 17, 2012. The point of contact for the facility was SGT **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

The Morrisville Readiness Center was built in the 1950's. The readiness center is staffed by 4 administrative personnel. The operations conducted at the facility include supply and administrative duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the Morrisville Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) evaluations of operations including operation description, sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the Morrisville facility consist exclusively of supply and administrative duties. No maintenance of vehicles or other physical tasks are performed at the facility.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; potential ergonomic problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were collected in select areas.

Paint Chip and Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. No peeling paint was observed on the interior of the building. Two areas of peeling, flaking and chipping paint were observed on the exterior of the building. Bulk samples for lead-paint analysis were collected into centrifuge tubes and analyzed by AMA Analytical Laboratory. Paint is defined as lead-based if it contains more than 0.5 percent lead by atomic absorption spectrophotometry (AAS) analysis following the analytical method ASTM D3335-85A. One of the two paint chip samples was above the 0.5% definition of lead-based paint. Table 1 presents the results of paint chip sample analysis. Certificates of Analysis are included in Appendix B.

**Table 1 – Results of Lead Paint Chip Sampling for VT ARNG
Morrisville Readiness Center on October 17, 2012**

Sample Number	Sample Description	Sample Location	Comments	Lead Content (percent)
MRC-20	White metal or transite ceiling	Front Porch ceiling by light fixture closest to Office 3 location	An area approximately 6 ft by 40 ft was peeling, flaking and chipping. Paint chips were falling to the ground.	1.7
MRC-21	White metal exterior door	Boiler Room Door Upper hinge side	Three distinct layers of paint were visible. Not all three layers were equally/representatively sampled. The outermost layer was peeling and flaking.	0.093

To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected by wiping a Ghost Wipe over a measured area. The Environmental Protection Agency (EPA) and the State of Vermont limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. All wipe samples collected from the facility were below the recommended maximum except for the sample collected from the ledge of the bay door in the Drill Hall (270 $\mu\text{g}/\text{ft}^2$). Results are given in Table 2 and certificates of analysis are included in Appendix B.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

Note that limited supplies were provided by the ARNG IH Region North for the group of sites surveyed by the inspector. The number and location of samples was limited and is based upon professional judgment.

**Table 2 – Results of Dust Wipe Sampling for VT ARNG
Morrisville Readiness Center on October 17, 2012.**

Wipe Sample Number	Sample Location	Wipe Dimensions	Lead ($\mu\text{g}/\text{ft}^2$)*
MRC-1	Former Firing Range – End of range, 7' north of south, 12' west of east – floor	11" x 11"	74
MRC-2	Former Firing Range – Middle 7' south of north wall, 24' east of west wall – floor	10" x 11"	41
MRC-3	Former Firing Range – By door, 1' south of north wall, 8' east of west wall - floor	9" x 10.5"	58
MRC-4	Vault – 3' west of east wall, 1.5' south of north wall - Floor	12" x 11"	61
MRC-5	Drill Hall – 18' north of south wall, 15' west of east wall – Floor	14" x 13"	270
MRC-6	Drill Hall – Top of locker #81. 25' west of east wall, 2' south of north wall.	3" x 36"	<16
MRC-7	Drill Hall – Middle of room - Floor	11" x 11.5"	22
MRC-8	Drill Hall – Top of POL Locker	9" x 12.5"	140
MRC-9	Kitchen – Window Sill	(9" x 7") + (2.5" x 2.5")	27
MRC-10	Kitchen – 5' east of west wall, 7' north of south wall – Floor	12" x 12"	<12
MRC-11	Scullery Kitchen – Bottom shelf of pot storage	10" x 10"	<17

*The recommended maximum level for adult exposures is 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) lead on surfaces.

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). A drawing from the Asbestos Survey Report by AIM Group performed on December 1, 1997 identified the floor tile as asbestos-containing material. Three broken floor tiles were noted between Office 1 and Office 2. The tile is not crumbling into small pieces. No other damaged suspect ACM was observed.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or visible mold growth was observed.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping appeared to be acceptable overall. One area of concern was observed in the Drill Hall. Oily rags were stored in plastic bags in the flammable materials storage cabinet that also contained propane cylinders. The POL storage cabinet doors do not close properly. This is a fire and life safety hazard as the cabinets are in the route of egress to the supply room and arms vault.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on April 16, 2012, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in a few areas: the platoon room, Office 1, the gym, the janitor's closet, FSC Office, maintenance, the kitchen and the boiler room. The illumination measurements indoors ranged from 13.7 foot candles (fc) to 82.0 fc. The complete results of the evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Plus Model 8554, factory calibrated in July 2012. Temperature, relative humidity and carbon dioxide (CO₂) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 3. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30 and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

Table 3 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 65.2 to 70.1° F and 34.4 to 52.7% Rh. Temperatures and relative humidity were just below lower end of the winter temperature range for thermal comfort in all but five of the locations monitored. The outdoor temperature and relative humidity was 46.5° F and 39.5% on the day of monitoring.

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1-2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 482 to 600 parts per million (ppm). CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange.

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 03.3 to 4.0 ppm; therefore, concentrations are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

A diesel powered fork lift was parked inside the drill hall on the day of the survey. The use of the equipment indoors may contribute to unsafe carbon monoxide concentrations.

Additional Information

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was readily available. MSDSs were last updated in July of 2009. MSDSs for some new custodial products were required per OSHA 29 CFR 1910.1200.

7 Conclusions

The results of the evaluation indicated a few industrial hygiene concerns in the facility. Overall, the Morrisville Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.

9 References


1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.
3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.
4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.
5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2011.
6. Army Regulation (AR) 420-70 Buildings and Structures, 11 November 1997.
7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 13 December 2007.
8. Army Regulation (AR) 420-1 Army Facilities Management, 12 February 2008, RAR 24 August 2012.
9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.
10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.
12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.
13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Morrisville Readiness Center**

15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.

Appendix A Building Layout

FIRE EVACUATION PLAN



Sample Location Plan
 Industrial Hygiene Survey
 October 17, 2012

FLOOR PLAN

MORRISVILLE ARMORY
 SCALE: 1" = 20' | 6 NOV. / 80

*## - Lead Wipe or Paint Chip Sample Location

● = AREA OCCUPATION AND ARROWS TO FOLLOW

● = LOCATION OF FIRE EXTINGUISHERS

Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	VT ARNG 3M IH Surveys	Chain Of Custody:	514301
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Morrisville RC	Date Submitted:	10/24/2012
Attention:	Non-Responsive	Job Number:	120685	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	10/30/2012
				Report Date:	11/2/2012

Summary of Atomic Absorption Analysis for Lead

Page 1 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
13008799	MCR-1	Flame	Wipe	****	0.840	14 ug/ft ²	62	74 ug/ft ²	
13008800	MCR-2	Flame	Wipe	****	0.764	16 ug/ft ²	31	41 ug/ft ²	
13008801	MCR-3	Flame	Wipe	****	0.656	18 ug/ft ²	38	58 ug/ft ²	
13008802	MCR-4	Flame	Wipe	****	0.917	13 ug/ft ²	56	61 ug/ft ²	
13008803	MCR-5	Flame	Wipe	****	1.264	9.5 ug/ft ²	340	270 ug/ft ²	
13008804	MCR-6	Flame	Wipe	****	0.750	16 ug/ft ²	<12	<16 ug/ft ²	
13008805	MCR-7	Flame	Wipe	****	0.879	14 ug/ft ²	20	22 ug/ft ²	
13008806	MCR-8	Flame	Wipe	****	0.781	15 ug/ft ²	110	140 ug/ft ²	
13008807	MCR-9	Flame	Wipe	****	0.481	25 ug/ft ²	13	27 ug/ft ²	
13008808	MCR-10	Flame	Wipe	****	1.000	12 ug/ft ²	<12	<12 ug/ft ²	
13008809	MCR-11	Flame	Wipe	****	0.694	17 ug/ft ²	<12	<17 ug/ft ²	
13008810	MCR-20	Flame	Paint Chip	****	N/A	0.0085 %Pb		1.7 %Pb	
13008811	MCR-21	Flame	Paint Chip	****	N/A	0.0087 %Pb		0.093 %Pb	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS



Client: National Guard Bureau	Job Name: VT ARNG 3M IH Surveys	Chain Of Custody: 514301
Address: 301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location: Morrisville RC	Date Submitted: 10/24/2012
	Job Number: 120685	Person Submitting: Non-Responsive
	P.O. Number: W912K6-09-A-0003	Date Analyzed: 10/30/2012 Report Date: 11/2/2012
Attention: Non-Responsive		

Summary of Atomic Absorption Analysis for Lead

Page 2 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	----------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm)
 %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb)

See QC Summary for analytical results of quality control samples associated with these samples.

Note: All samples were received in good condition unless otherwise noted.

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Air and Wipe results are not corrected for any blank results
 Final results for air and wipe samples are based on client supplied information nor verified by this laboratory.

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Analyst:

Non-Responsive

Technical Manager:

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.

Aria Environmental, Inc

ASBESTOS BULK AND PAINT CHIP SAMPLING SURVEY SHEET

Inspector: **Non-Responsive**
 License/Accreditation No.: _____
 Witnessed By: _____

Date Collected: 10-17-12
 Job Site: Morrisville RC
 Project No.: J12-685

Sample No.	Type of Material Sampled	Floor	Functional Area	Sample Location	Comments
MRC-20	White ^{metal or transite} ceiling	1	Front Porch	ceiling on by light fixture closest to office 3 location	40'x6' PFC
MRC-21	White metal exterior door	1	Boiler Room Door	on door upper hinge side	PFC - 3 distinct layers

Appendix C Photo Documentation

VT Morrisville RC



Photo 1: Morrisville RC view from Farr Avenue.



Photo 2: Morrisville RC Commemorative Plaque from 1958.



Photo 3: Morrisville RC rear façade.



Photo 4: Morrisville RC rear façade at boiler room.

VT Morrisville RC



Photo 5: Drill Hall.



Photo 6: Diesel powered fork lift in drill hall.



Photo 7: POL and flammable cabinets in Drill Hall. Note doors to POL storage cabinet do not function properly.



Photo 8: View inside POL storage cabinet.

VT Morrisville RC



Photo 9: Oily rags in plastic bag inside flammable materials cabinet.



Photo 10: View inside part of the flammable material storage cabinet.



Photo 11: View inside cold storage.



Photo 12: View of fueling tent.

VT Morrisville RC



Photo 13: View of full fuel cans inside fueling tent.



Photo 14: View of peeling, flaking and chipping lead-based paint on porch ceiling.



Photo 15: View of damaged paint on metal exterior door. The paint was tested and is not lead-based.




Photo 16: View of broken asbestos-containing floor tile typical of damage in the office areas.

Appendix D
IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Morrisville	IAQ								Light		
Date	10/17/2012	Inspector	Non-Responsive	Instrument	Q-trak 7565-X							Instrument	Cal-Light 400L	
Facility Description	Morrisville RC			Serial Number	7575x1228004							Serial Number	K040084EL	
Weather Conditions	Sunny			Last Calibration	Jul-12							Last Calibration	16-Apr-12	
Location	Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
Former Range	Storage	var	0809	65.4	L	52.7		530		3.7		13.7		10
Vault	Weapon Storage	var	0826	66.5	L	48.9		482		3.9		60.6		10
Storage (BR)	Storage	var	0832	65.2	L	35.2		514		3.7		20.0		10
Platoon Room	Platoon Room	var	0837	66.4	L	42.1		538		4.0		24.9	X	30-50
Vestibule	Vestibule	var	0838	66.1	L	41.0		566		3.7		20.8		10
Office 3	Office	1	0839	66.9	L	41.9		563		3.5		39.7		30-50
Office 2	Office	1	0840	67.8	L	42.6		600		3.3		57.3		30-50
Office 1	Office	1	0840	68.3	L	42.0		633		3.3		26.5	X	30-50
Drill Hall	Drill Hall	var	0841	67.5	L	39.1		536		3.7		82.0		30-50
Gym	Gym	var	0842	66.8	L	40.2		566		3.8		24.9	X	30
Women's Latrine	Latrine	var	0843	67.0	L	36.4		509		3.6		36.6		5
Janitor's Closet	Storage	var	0844	68.4	L	43.6		555		3.3		23.1	X	30
Men's Latrine	Latrine	var	0845	68.6		52.1		593		3.5		38.3		5
FSC Office	Office	5	0846	70.1		40.0		492		3.6		24.8	X	30-50
Maintenance	Office	var	0847	69.0		39.5		502		3.8		20.2	X	30-50
Kitchen	Storage	var	0848	68.5		34.4		533		3.6		15.3		5
Kitchen	Kitchen	var	0849	68.7		36.8		543		3.6		36.7	X	50
Boiler Room	Boiler Room	var	0850	68.2	L	35.0		525		3.5		21.5	X	30
Supply	Storage	1	0851	67.8	L	41.5		550		3.4		32.7		30
Outdoors	Outdoors	0	0855	46.5		39.5		466		4.1		3.1 K		N/A

Shaw Environmental, Inc.

312 Directors Drive
Knoxville, TN 37923
865.690.3211
Fax 865.690.3626



**National Guard Armory
Rutland Readiness Center – Rutland, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

13 May 2004

National Guard Armory
Rutland Readiness Center – Rutland, Vermont

Industrial Hygiene Evaluation

Prepared for:

National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078

Prepared by:

Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923

13 May 2004

Prepared by:

Non-Responsive

Industrial Hygienist

Reviewed by:

Non-Responsive

Business Line Manager

Table of Contents

<i>Table of Contents</i>	<i>i</i>
<i>List of Tables</i>	<i>ii</i>
<i>List of Appendices</i>	<i>ii</i>
<i>Executive Summary</i>	<i>E-1</i>
<i>1.0 Introduction</i>	<i>1-1</i>
<i>2.0 Findings, Discussion, and Interpretation of Results</i>	<i>2-1</i>
<i>2.1 Sampling for Lead</i>	<i>2-1</i>
<i>2.1.1 Wipe Sampling</i>	<i>2-1</i>
<i>2.1.2 Air Sampling for Lead</i>	<i>2-2</i>
<i>2.2 Physical Condition of Facility</i>	<i>2-2</i>
<i>2.2.1 Peeling Paint - Lead</i>	<i>2-2</i>
<i>2.2.2 Visual Inspection - Asbestos</i>	<i>2-3</i>
<i>2.2.3 Visual Inspection - Water Damage and Mold</i>	<i>2-3</i>
<i>2.2.4 Visual Inspection - Housekeeping</i>	<i>2-4</i>
<i>2.3 Building Concerns</i>	<i>2-4</i>
<i>2.3.1 Ergonomic Concerns</i>	<i>2-4</i>
<i>2.3.2 Indoor Air Quality</i>	<i>2-4</i>
<i>2.4 Safety and Industrial Hygiene Programs</i>	<i>2-4</i>
<i>2.5 Ventilation</i>	<i>2-5</i>
<i>2.5.1 Ventilation System Evaluation</i>	<i>2-5</i>
<i>2.5.2 Contamination of Clean Air Sources</i>	<i>2-5</i>
<i>2.6 Noise Exposure</i>	<i>2-5</i>
<i>2.7 Lighting</i>	<i>2-5</i>
<i>2.8 Indoor Firing Ranges</i>	<i>2-6</i>
<i>2.9 HVAC Systems</i>	<i>2-6</i>
<i>2.10 HHIM</i>	<i>2-6</i>
<i>3.0 Conclusions</i>	<i>3-1</i>
<i>Tables</i>	<i>Follows Section 3.0</i>
<i>Appendices</i>	<i>Follows Tables</i>

List of Tables

Table 1	Wipe Sampling for Lead
Table 2	Air Sampling for Lead
Table 3	Peeling Paint Sampling for Lead
Table 4	Indoor Air Quality Measurements
Table 5	Illumination Readings
Table 6	Indoor Firing Ranges Wipe Sampling

List of Appendices

Appendix A	HHHM Data Form
Appendix B	Building Layout
Appendix C	Sampling Sheets and Laboratory Analyses
Appendix D	References
Appendix E	Recommendations for Surface Lead Dust in Armories

Executive Summary

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Rutland Readiness Center in Rutland, Vermont **Non-Responsive** performed the evaluation on 5 August 2003 and 10 October 2003. The point of contact at the readiness center was SFC **Non-Responsive**

The following industrial hygiene concerns were evaluated.

- Wipe Sampling for Lead
- Air Sampling for Lead
- Peeling Paint – Lead
- Suspected Asbestos Containing Material
- Water Damage
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Indoor Air Quality
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- Lighting
- Converted Indoor Firing Range
- HVAC Systems

The following items were either not applicable to the armory or the evaluation resulted in a conclusion that there were no industrial hygiene concerns.

- Air Sampling for Lead
- Housekeeping
- Ergonomic Concerns
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources

- Noise Exposure
- HVAC Systems

Areas where there were industrial hygiene concerns are as follows:

- Wipe sampling for lead revealed concentrations above the recommended level at four locations (assembly hall and basement kitchen) in the armory. It is recommended that these surfaces and the areas immediately around these surfaces be thoroughly cleaned to reduce the lead level. In addition, any other dusty/dirty areas in the assembly area/drill floor and basement kitchen should be thoroughly cleaned.
- Wipe sampling for lead revealed concentrations above a level of 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) at several locations in the armory. Areas with lead concentrations above $40 \mu\text{g}/\text{ft}^2$ that will be accessible to children should be cleaned. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function. It should be noted that the Vermont based STARBASE youth program leases a portion of the Rutland armory. This portion is immediately between the armory lobby and the drill hall. Both military personnel and STARBASE personnel/youth program activities utilize the drill hall/assembly room, therefore, thoroughly cleaning these areas is strongly recommended.
- Peeling paint was observed in the basement of the armory, and bulk sampling results at four locations (boiler room walls, man's latrine, and shower room ceiling and wall) revealed this paint to be a lead-based. Anyone who may perform repair and/or maintenance activities on these surfaces should be made aware of the presence of the lead-based paint so appropriate precautions (control of exposures, personal protective equipment, training, etc.) can be taken.
- Materials (floor tiles in the kitchen) suspected of containing asbestos were observed. An operations and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.
- Water damage was observed at several locations at the armory. The source of the water damage was likely from roof leaks, poor ventilation, or building foundation breach/high water table. The source of the water damage should be confirmed and actions taken to eliminate the source in order to prevent the possibility of mold growth that may lead to indoor air quality problems.
- Visible mold was observed on the engineering unit office wall and boiler room walls at the armory. The areas where the mold is located should be thoroughly cleaned with

0.5% sodium hypochlorite solution (1 part household bleach to nine parts water) or equivalent in order to eliminate the potential mold/indoor air quality problem. In addition, the source of the mold should be identified and actions taken to eliminate the source of the mold.

- Indoor air quality measurements revealed that the humidity and temperature measurements at the armory exceeded the recommended levels. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory. In addition, interviews with employees revealed ventilation as an indoor air quality concern at the armory, specifically on the second floor and in the men's shower room where there is a minimal fresh air supply. A fan can be used for both cooling purposes and to circulate air in the men's shower room.
- Lighting measurements were conducted at the armory. The lighting did not meet minimum requirements in most areas; therefore consideration should be given to providing more lighting in these areas. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.
- There was not a converted firing range at the facility; however, there was an inactive indoor firing range. For informational purposes, wipe samples were taken for lead at various locations in or near the range. As expected, the results revealed lead at extremely high concentrations. This inactive firing range should not be used for any purposes, except as a firing range (if approved as a fully operating range), until the lead levels are reduced below the recommended level. In addition, employees should not be allowed to work in these areas without protective clothing until the areas have been cleaned.

1.0 Introduction

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Rutland Readiness Center in Rutland, Vermont. **Non-Responsive** performed the evaluation on 5 August 2003 and 10 October 2003. The point of contact at the readiness center was SFC **Non-Responsive**

The findings, discussion, and interpretation of results are provided in Section 2.0. The conclusions are provided in Section 3.0. The HHIM data form for the facility is provided in Appendix A. The building layout is provided in Appendix B. Sampling sheets and laboratory analyses are provided in Appendix C. References are provided in Appendix D. The *Recommendations for Surface Lead Dust in Armories* document is provided in Appendix E.

The statements, opinions, and conclusions contained in this report are based solely upon the services performed by Shaw as described in the report. In performing these services and preparing the report, Shaw Environmental, Inc. relied upon the work and information provided by others, including public agencies, whose information is not guaranteed by Shaw Environmental, Inc.

2.0 Findings, Discussion, and Interpretation of Results

The results, discussion, and interpretation of results are provided in the following sections.

2.1. Sampling for Lead

2.1.1 Wipe Sampling

Wipe samples were collected for lead from the drill floor/assembly area. Also, wipe samples were collected for lead in rooms, hallways, foyers, etc. The sampling in rooms, hallways, foyers, etc. represented approximately 25% of the building. Approximately half of the samples were collected from surfaces in common areas, such as surfaces of a desk. The remaining samples were collected from uncommon surface areas, such as a supply vent or the top of a file cabinet. The samples were collected and analyzed in accordance with the Instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

The only samples initially submitted for analysis were those from the drill floor/assembly hall. If there were any positive results from the drill floor/assembly hall, the other samples would be submitted for analysis.

Results of the wipe sampling are provided in Table 1. The results revealed lead at all locations sampled at concentrations below recommended level of 200 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$) (See Appendix E) except at three locations. Three samples collected in the assembly hall (soda machine top surface, heater vent surface, and floor outside the firing range) had lead concentrations of 310, 290, and 30,000 $\mu\text{g}/\text{ft}^2$, respectively. The sample collected from the heater unit flap surface in the basement kitchen had a lead concentration of 1100 $\mu\text{g}/\text{ft}^2$. It is recommended that these surfaces and the immediate areas around the surfaces be thoroughly cleaned to reduce the lead level to below 200 $\mu\text{g}/\text{ft}^2$. For guidance on the proper method of cleaning, please refer to NG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.

In addition, wipe sampling for lead revealed concentrations above a level of 40 $\mu\text{g}/\text{ft}^2$ at several locations in the basement, first floor, and the assembly hall. Please note that the *Recommendations for Surface Lead Dust in Armories* (Appendix E) states that all areas with lead concentrations above 40 $\mu\text{g}/\text{ft}^2$ that will be accessible to children should be cleaned. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.

It should be noted that the Vermont based STARBASE youth program leases a portion of the Rutland armory. This portion is immediately between the armory lobby and the drill hall. Both military personnel and STARBASE personnel/youth program activities utilize the drill hall/assembly room, therefore, thoroughly cleaning these areas is strongly recommended.

2.1.2 Air Sampling for Lead

Breathing zone air sampling was conducted on two (2) full-time building occupants. (Please note that no state employees were monitored.) The samples were collected and analyzed in accordance with Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods.

The results of the sampling are provided in Table 2. The results revealed non-detectable concentrations of lead in the breathing zone of the employees; therefore, no actions are necessary.

2.2 Physical Condition of Facility

2.2.1 Peeling Paint - Lead

Peeling paint was observed in the armory in six locations in the basement (hallway outside of Firing Range, engineering unit classroom wall, boiler room walls, men's latrine wall - 1st stall, men's shower room ceiling, and men's shower room wall. The Department of Housing and Urban Development (HUD) defines lead-based paint as paint or other surface coatings that contain lead equal to or 0.5 percent by weight. Bulk sampling results revealed lead at four of the six locations were below 0.5 percent by weight. The samples collected from the boiler room walls (approximately 2600 square feet), men's latrine wall (1st stall) (approximately 12 square feet) and men's shower room ceiling and wall (approximately 120 square feet) revealed lead

concentrations of 0.58, 9.7, 5.3, and 0.97 percent by weight, respectively. The paint was in poor condition. The results of the sampling are provided in Table 3.

Anyone who may perform repair and/or maintenance activities on surfaces coated with lead-based paint should be made aware of the presence of the lead-based paint so appropriate precautions (control of exposures, personal protective equipment, training, etc.) can be taken.

2.2.2 Visual Inspection - Asbestos

A visual inspection was made to determine if there was any suspected asbestos-containing material at the armory. Materials suspected of containing asbestos were observed. The suspected asbestos-containing materials were floor tiles in the kitchen (approximately 1641 square feet). The condition of the floor tiles materials was considered good since there was no damage to tiles.

An operation and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.

2.2.3 Visual Inspection – Water Damage and Mold

A visual inspection was made to determine if there was any water damage or visible mold at the armory. Water damage and visible mold were observed at the armory. Water damage was observed on the ceilings in the drill hall/assembly room, second floor foyer/common area/stairwell, and first floor office adjacent to handicap bathroom. In addition, the water damage observed on the ceiling in the man's latrine, walls in the hallway outside of firing range, engineering unit office, boiler room, men's latrine, and shower room were all accompanied by peeling paint. Visible mold was observed on the engineering unit office wall and boiler room walls.

The source of the water damage was likely from roof leaks concerning the ceiling water damage, poor ventilation in the men's shower room, and building foundation breach/high water table concerning the damage observed in the basement. The source of the water damage should be confirmed and actions taken to eliminate the source in order to prevent the possibility of mold growth that may lead to indoor air quality problems.

The areas where the mold is located should be thoroughly cleaned with 0.5% sodium hypochlorite solution (1 part household bleach to nine parts water) or equivalent in order to eliminate the potential mold/indoor air quality problem. In addition, the source of the mold should be identified and actions taken to eliminate the source of the mold.

2.2.4 Visual Inspection - Housekeeping

The housekeeping was determined to be good.

2.3. Building Concerns

2.3.1 Ergonomic Concerns

Interviews with employees and observation of work activities revealed no ergonomic concerns at the armory.

2.3.2 Indoor Air Quality

Interviews with employees revealed ventilation as an indoor air quality concern at the armory, specifically in the men's shower room, where there is a minimal fresh air supply, and the offices on the second floor. In addition, measurements for humidity revealed that levels exceeded the American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommended level of 60% in the armory. Also, ASHRAE recommends that the acceptable temperature range be 68 degrees Fahrenheit to 74 degrees Fahrenheit in the winter and 73 degrees Fahrenheit to 79 degrees Fahrenheit in the summer. The measurements for temperature on the second floor exceeded the acceptable range. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory. In addition, a fan can be used for cooling purposes and to circulate air in the men's shower room.

The results of the measurements for carbon dioxide, humidity, and temperature are provided in Table 4.

2.4. Safety and Industrial Hygiene Programs

An evaluation was performed to determine the applicability of the following programs.

- Confined Spaces
- Hearing Conservation
- Respiratory Protection
- Hazard Communication (HAZCOM)
- Personal Protective Equipment (PPE)

It was determined that the HAZCOM and personal protective equipment (supply sergeant is required to wear safety boots) programs were applicable at the facility. The programs were evaluated and it was determined that the program met minimum requirements.

2.5. Ventilation

2.5.1 Ventilation System Evaluation

There were no local exhaust ventilation systems at this armory; therefore, no ventilation studies were performed.

2.5.2 Contamination of Clean Air Sources

Since there were no local exhaust ventilation systems at the armory, there was no possibility that clean air sources could be contaminated by exhaust air.

2.6. Noise Exposure

An evaluation was performed to determine if there were any hazardous noise areas at the armory. It was determined that there were no areas at the armory that would exceed the permissible exposure limit for noise.

2.7 Lighting

Lighting measurements were conducted at the armory. Results of the lighting evaluation are provided in Table 5. As can be seen from the results, the lighting did not meet the minimum requirements in most areas, including the gym, men's latrine, basement storage area, first floor office adjoining to SFC Rabtoy's office, first floor office adjacent to handicap bathroom, and six offices on the second floor.

Consideration should be given to providing more lighting to the areas listed above. This may be accomplished by replacing burnt out luminaries, cleaning fixtures,

cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

2.8 Converted Indoor Firing Ranges

There was not a converted firing range at the facility; however, there was an inactive indoor firing range. For informational purposes, wipe samples were taken for lead at various locations in or near the range. The results are provided in Table 6. As expected, the results revealed lead at extremely high concentrations. This inactive firing range should not be used for any purposes, except as a firing range (if approved as a fully operating range), until the lead levels are reduced below the recommended level of 200 $\mu\text{g}/\text{ft}^2$, a level recommended in the *Guidelines for Converting Indoor Firing Ranges to Other Uses* document (Department of Army). For guidance on the proper method of cleaning, please refer to NGB PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, employees should not be allowed to work in these areas without protective clothing until the areas have been cleaned and re-sampled.

2.9. HVAC System

There was a HVAC system located in the computer classroom. The maintenance schedule for the HVAC system was evaluated to verify that maintenance occurs on a regular basis. Also, the condition of the HVAC system was evaluated to determine if the maintenance performed is effective. It was deemed that maintenance occurs on a regular basis, and the maintenance performed is effective.

2.10. HHIM

A Health Hazard Information Module (HHIM) form was completed for the armory. The completed form is provided in Appendix A.

3.0 Conclusions

It is concluded that there were no industrial hygiene concerns at the armory with regards to atmospheric exposure to lead, housekeeping, ergonomic conditions, safety and industrial hygiene programs, ventilation systems or contamination of clean air sources, noise exposure, and HVAC systems.

There were industrial hygiene concerns at the armory with regards to lead surface contamination, peeling lead-based paint, suspected asbestos-containing material, water damage, visible mold, indoor air quality, surface lead contamination in the firing range, and lighting. These concerns are discussed in detail in Section 2.0 of this report.

TABLES

Table 1
Wipe Sampling for Lead
National Guard Armory
Rutland, Vermont
Dates of Sampling: 5 August 2003 and 10 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTRUT217-1	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTRUT217-2	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTRUT217-3	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTRUT217-4	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTRUT217-5	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTRUT217-6	Field Blank	< 12 μg
VTRUT217-14	Basement - Classroom (mess hall) - table top	16
VTRUT217-15	Basement - Classroom (engineering unit office) - cabinet top	100
VTRUT217-16	Basement - Kitchen - heater unit flap surface	1100
VTRUT217-17	Basement - Break room - cabinet top surface	39
VTRUT217-18	Field Blank	< 0.3 μg
VTRUT217-19	Basement - Hallway - windowsill	14
VTRUT217-20	First Floor - Recruiting office - desktop	16
VTRUT217-21	First Floor - Lobby - glass case top surface	22
VTRUT217-22	First Floor - hallway to drill hall (Star base) - counter top surface	54
VTRUT217-23	First Floor - Office adjoining C. Rubtoy's office - desk shelf top surface	6.7
VTRUT217-24	Field Blank	< 0.3 μg
VTRUT217-25	Second Floor - Office - desktop surface	6.5
VTRUT217-26	Second Floor - Office - cabinet top surface	18
VTRUT284-1	Assembly Room - soda machine top surface (See Building Layout - Appendix B)	310
VTRUT284-2	Assembly Room - heater vent top surface (adjacent to stage) (See Building Layout - Appendix B)	290
VTRUT284-3	Assembly Room - heater vent top surface (adjacent to exit door) (See Building Layout - Appendix B)	58

^aMicrograms lead per square foot

Table 1 Continued
Wipe Sampling for Lead
National Guard Armory
Rutland, Vermont
Dates of Sampling: 5 August 2003 and 10 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTRUT284-4	Assembly Room - locker top surface (See Building Layout - Appendix B)	30
VTRUT284-5	Assembly Room - cabinet top surface (See Building Layout - Appendix B)	37
VTRUT284-6	Field Blank	< 0.3 μg
VTRUT284-7	HVAC Unit - Exhaust Ventilation Air Grille	39

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the instructions for *Completing the Sampling of Army National Guard Armories* procedure.

In armories that do not contain childcare facilities, the NGB Region North Industrial Hygiene Office recommends cleaning the areas with lead concentrations greater than 200 $\mu\text{g}/\text{ft}^2$.

Table 2
Breathing Zone Air Samples for Lead
National Guard Armory
Rutland, Vermont
Date of Sampling: 5 August 2003

Sample Number	Employee	Sampling Information			Results (mg/m ³) ^a
		Time Sampled / Minutes	Flow Rate (lpm) ^b	Volume (liters)	
VTRUT217-A1	Non-Responsive	0803-1053/170	2.471	420.05	< 0.002
VTRUT217-A2		0804-1052/168	2.458	412.99	< 0.002
VTRUT217-A3	Field Blank	-	-	-	None Detected

^a Milligrams lead per cubic meter of air.

^b Liters of air per minute.

Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods was followed for sampling for lead.

Table 3
Peeling Paint Sampling for Lead
National Guard Armory
Rutland, Vermont
Date of Sampling: 5 August 2003

Sample Number	Location	Results, % By Weight
VTRUT217-B1	Basement - hallway outside of Firing Range	0.16
VTRUT217-B2	Basement - classroom (engineering unit office) wall	0.044
VTRUT217-B3	Basement - boiler room walls	0.58
VTRUT217-B4	Basement - men's latrine wall (1 st stall)	9.7
VTRUT217-B5	Basement - men's shower room ceiling	5.3
VTRUT217-B6	Basement - men's shower room wall	0.87

The Department of Housing and Urban Development (HUD) defines lead-based as paint or other surface coatings that contain lead equal to or exceeding 0.5 percent by weight.

Table 4
Indoor Air Quality Measurements for Carbon Dioxide, Humidity, and Temperature
National Guard Armory
Rutland, Vermont
Date of Sampling: 5 August 2003

Location	Occupants in Area	Carbon Dioxide, parts per million parts of air (ppm)	Percent (%) Humidity	Temperature (°F)
Outdoors	0	445	78.4	78.5
Basement-Classroom (mess hall)	1	718	67.4	75.6
1 st Floor-foyer	2-3	405	61.9	78.4
2 nd Floor-office (see diagram)	1	450	63.4	84.4

Carbon dioxide, humidity, and temperature measurements were taken with a TSI Q Trak Plus, Model 8554, Indoor Air Quality Meter, calibrated in April 2003.

American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommends that indoor carbon dioxide levels be less than 700 ppm above outdoor levels.

ASHRAE recommends that the relative humidity levels be maintained between 30 to 60 percent.

ASHRAE recommends that the acceptable temperature range be 68 degrees Fahrenheit to 74 degrees Fahrenheit in the winter and 73 degrees Fahrenheit to 79 degrees Fahrenheit in the summer.

Table 5
Illumination Readings
National Guard Armory
Rutland, Vermont
Date of Sampling: 5 August 2003

Location	Luminance (fc) ^a	Standard (fc) ^a	Standard Met
Basement-Classroom Engineering unit	106.4-116.5	70	Yes
Basement-Classroom (mess hall)	31.5-124.6	70	Some areas
Basement-hallway	0.7-75.3	7.5	Some areas
Basement-Gym	3.2-14.3	70	No
Basement-Men's Latrine	1.9-12.3	40	No
Basement-Kitchen	19.7-81.3	70	Some areas
Basement-Storage area	0.5-17.8	30	No
1 st Floor-Office adjoining to SFC Non-Responsive office	27.4-51.3	70	No
1 st Floor-Office adjacent to handicap bathroom	39.4-117.2	70	Some areas
1 st Floor-Office opposite computer classroom	62.1-82.5	70	Some areas
1 st Floor-Office adjacent to handicap bathroom	38.2-55.6	70	No
2 nd Floor-Office	12.7-36.3	70	No
2 nd Floor-Office	11.1-40.1	70	No
2 nd Floor-Office	13.7-46.1	70	No
2 nd Floor-Office	18.0-51.5	70	No
2 nd Floor-Office	7.9-32.9	70	No
2 nd Floor-Office	22.1-47.6	70	No

^a fc - Footcandles

The readings were taken with a Cooke Corporation cal-LIGHT 400 Calibrated Precision Lightmeter, calibrated on 19 Aug 2002.

The standards listed above are from Design Guide DG-415-2, Logistics Facilities, published by the National Guard Bureau Installation Division.

Table 6
Wipe Sampling for Lead – Firing Range
National Guard Armory
Rutland, Vermont
Date of Sampling: 5 August 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTRUT217-7	Floor Outside the Range drill hall	30000
VTRUT217-8	Floor	290000
VTRUT217-9	Stored Item (shelf)	23000
VTRUT217-10	Overhead Heaters	15000
VTRUT217-11	Light Fixture	3600
VTRUT217-12	Blank	< 12 μg
VTRUT217-13	Bullet Trap	1000000

^aMicrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

Appendix A

HHIM Data Form(s)

HEALTH HAZARD INFORMATION MODULE: INDUSTRIAL HYGIENE SURVEY

(For use of this form, see HHIM User's Guide)

SECTION 1. DEMOGRAPHIC DATA

ARLOC	INSTALLATION Rutland Armory Vermont ARNG	BLDG/RM NO. Rutland		
LOCATION/CODE Administrative Areas / AA	OPERATION/CODE Administrative Operations / ADO			
SURVEY DATE 5 August 2003	EVALUATOR (Initials) Non-Responsive			
MACOM/CODE Army National Guard	SUBMACOM/CODE XX	SUPERVISOR Non-Responsive SFC		
TELEPHONE/DSN NO. 802-786-8800	UNIT/ORGANIZATION Headquarters 1st Battalion	RAC # 4	FREQUENCY (hrs/day) 8	
NO. CIV(S) 3	NO. MIL 15	NO. CONTRACTOR(S) 0	NO. LOC(S) 0	NO. OTHER 0

SECTION 2. FACILITY DATA

LAB HOODS 0	VAPOR DEGREASERS 0	SPRAY BOOTHS 0
MAINTENANCE BAYS 0	OPEN SURFACE TANKS 0	VENTILATION UNITS 0

SECTION 3. SURVEY DATA

CONTROLS PRESENT	EVALUATION	UNIT CODE	CONTROLS REQUIRED	STATUS

PERSONAL PROTECTIVE EQUIPMENT (R = Required; U = Utilized)

GLOVES	R	U	RESPIRATOR	NOSH TC NO.	MANUFACTURER	R	U
ACID			AIRLINE				
COLD SURFACES			ABRASIVE BLASTING HOOD				
HOT SURFACES			DISPOSABLE				
NBC AGENTS			FULL FACE AIR PURIFYING				
OIL			1/2 FACE AIR PURIFYING				
SOLVENTS			POWERED AIR PURIFYING				
SURGICAL GLOVES			1/4 FACE AIR PURIFYING				
			SELF CONTAINED				

EYES/FACE	R	U	HEARING	R	U	BODY	R	U	HEAD/FIT	R	U
CHEMICAL SPLASH			CANAL CAPS			APRONS			COLD WEATHER BOOTS/HATS		
FULL FACE SHIELD			EAR PLUGS			COLD WEATHER CLOTHING			HARD HATS		
CHEMICAL/SAFETY			HELMETS			COVERALLS			IMPERMEABLE BOOTS		
SAFETY/IMPACT			MUFFS			FULL BODY SUIT			SAFETY/CONDUCTIVE SHOES		
WELDING HELMET			MUFF/EARPLUG COMBO			HEAT REFLECTIVE VEST/SUIT			SAFETY/NON-CONDUCTIVE SHOES		
			MUFF/EARPLUG W/TIME LIMIT			SAFETY BELT/HARNES					

SECTION 4. HAZARD INVENTORY DATA

CAS CODE	HAZARD DESCRIPTION	PAC	EPC
POVDTXXX	videodisplay terminal	3-low	Uncontrolled Physical
7489-92-1	lead, inorganic dusts and fumes Pb	2 moderate	Uncontrolled Respiratory
1332-21-4	Asbestos (amph)	3-low	Uncontrolled Respiratory

SECTION 5. PERSONNEL DATA

LAST NAME	FIRST NAME	MI	SEX	SSN	CATEGORY
<p>please see attached ^{military} personnel list, have all employees name and social security numbers are not available, in addition 5 members are in Basco during site visit, personnel including Matthew D Cole and Christopher B Sachin present at facility as replacement personnel. The building is also occupied by STABBASE Youth Program, the staff is military and leases and upkeep a section of the building, however both military personnel and STABBASE personnel and Youth programs utilize the ball hall. STABBASE full-time personnel include at least 2 employees as well the building has one civilian caretaker.</p>					

SECTION 6. COMMENTS

No comments. X See attached sheet for staff (personnel) Survey was conducted by Michele Sewan. Building occupants include attached list of military personnel and others (see above). Military staff perform routinely administrative functions.

PRIVACY ACT STATEMENT

Title 5 US Code, Section 301; Executive Order 9397 authorizes the use of your Social Security Number as an identification number. The purpose of this information is to identify and monitor data relating each DA civilian and military employee exposed to a hazardous workplace or operation. The use of this information is to provide histories of exposures for any given worker.

Disclosure of your Social Security Number is not mandatory; however, nondisclosures may result in untimely provision of proper medical monitoring.

Ridgland Armory

AGR Soldiers:

MAJ Non-Responsive
CPT
1LT
MSC
SFC
SFC
SFC
SSG
SSG
SGT


ADSW Soldiers (SFOR) Bosnia:

CPT Non-Responsive
1LT
SFC
SSG
SSG


Appendix B

Building Layout


Rustland Armory
1st. Floor





○ Sample date 5 August 2003
 △ Sample date 10 October 2003



Rutland Armory
2nd Floor





Appendix C

Sampling Sheets and Laboratory Analyses

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301-TH Old Bay Lane, Attn: NGB-AVN-SI,
State Military Reservation
Havre de Grace, Maryland 21078

Job Name: VTRUT217
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01

Chain Of Custody: 115915
Date Analyzed: 8/15/2003

Person Submitting: [REDACTED]
Report Date: 15-Aug-03

Attention: [REDACTED]

Page 1 of 2

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0362265	VTRUT217-1	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362266	VTRUT217-2	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362267	VTRUT217-3	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362268	VTRUT217-4	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362269	VTRUT217-5	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362270	VTRUT217-6	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0362271	VTRUT217-7	Flame	Wipe	****	0.111	108.00 ug/ft ²	30000 ug/ft ²	
0362272	VTRUT217-8	Flame	Wipe	****	0.111	108.00 ug/ft ²	290000 ug/ft ²	
0362273	VTRUT217-9	Flame	Wipe	****	0.111	108.00 ug/ft ²	23000 ug/ft ²	
0362274	VTRUT217-10	Flame	Wipe	****	0.111	108.00 ug/ft ²	15000 ug/ft ²	
0362275	VTRUT217-11	Flame	Wipe	****	0.111	108.00 ug/ft ²	3600 ug/ft ²	
0362276	VTRUT217-12	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0362277	VTRUT217-13	Flame	Wipe	****	0.111	108.00 ug/ft ²	1000000 ug/ft ²	

BEST AVAILABLE COPY

BEST AVAILABLE COPY

FOIA Requested Record #J-15-0085 (VT)
Released by National Guard Bureau

Page 822 of 1352

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

All rights reserved. AMA Analytical Services, Inc.

An AIHA (#8863), NVLAP (# 101143), & New York ELAP (#10920) Accredited Laboratory

4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
 Address: 301-IH Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation
 Havre de Grace, Maryland 21078
 Attention: [Redacted]

Job Name: VTRUT217
 Job Location: Not Provided
 Job Number: Not Provided
 P.O. Number: 07-01

Chain Of Custody: 11S915
 Date Analyzed: 8/15/2003
 Person Submitting: [Redacted]
 Report Date: 15-Aug-03

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms mg/L = parts per billion (ppb)
 Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Technical Manager: [Redacted]

Analyst: [Redacted]

Non-Responsive

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

All rights reserved. AMA Analytical Services, Inc.

An AIHA (#8863), NVLAP (# 101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SL, State Military Reservation
Havre de Grace, Maryland 21078

Job Name: VTRUT217
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: Not Provided

Chain Of Custody: 118929
Date Analyzed: 10/30/2003

Person Submitting: [Redacted]
Report Date: 30-Oct-03

Attention: [Redacted]

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0404814	VTRUT217-14	Furnace	Wipe	****	0.111	2.70 ug/ft ²	16 ug/ft ²	
0404815	VTRUT217-15	Furnace	Wipe	****	0.111	27.00 ug/ft ²	100 ug/ft ²	
0404816	VTRUT217-16	Furnace	Wipe	****	0.111	135.01 ug/ft ²	1100 ug/ft ²	
0404817	VTRUT217-17	Furnace	Wipe	****	0.111	5.40 ug/ft ²	39 ug/ft ²	
0404818	VTRUT217-18	Furnace	Wipe Blank	****	N/A	0.30 ug	< 0.3 ug	
0404819	VTRUT217-19	Furnace	Wipe	****	0.111	2.70 ug/ft ²	14 ug/ft ²	
0404820	VTRUT217-20	Furnace	Wipe	****	0.111	2.70 ug/ft ²	16 ug/ft ²	
0404821	VTRUT217-21	Furnace	Wipe	****	0.111	2.70 ug/ft ²	22 ug/ft ²	
0404822	VTRUT217-22	Furnace	Wipe	****	0.111	6.75 ug/ft ²	54 ug/ft ²	
0404823	VTRUT217-23	Furnace	Wipe	****	0.111	2.70 ug/ft ²	6.7 ug/ft ²	
0404824	VTRUT217-24	Furnace	Wipe Blank	****	N/A	0.30 ug	< 0.3 ug	
0404825	VTRUT217-25	Furnace	Wipe	****	0.111	2.70 ug/ft ²	6.5 ug/ft ²	
0404826	VTRUT217-26	Furnace	Wipe	****	0.111	2.70 ug/ft ²	18 ug/ft ²	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau Job Name: VTRUTZ17 Chain of Custody: 118929
 Address: 301-IH Old Bay Lane, Attn: NGB-AVN-S1, State Military Reservation Job Location: Not Provided Date Analyzed: 10/30/2003
 Havre de Grace, Maryland 21078 Job Number: Not Provided Person Submitting: [Redacted]
 P.O. Number: Not Provided Report Date: 30-Oct-03

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Solids: EPA 600/R-93/200(M)-7421; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)
 Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] Manager: [Redacted]
 Non-Responsive [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

Client: National Guard Bureau Job Name: VTRUT284 Chain Of Custody: 118720
 Address: 301-H Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation Job Location: Not Provided Date Analyzed: 10/21/2003
 Havre de Grace, Maryland 21078 Job Number: Not Provided Person Submitting: [Redacted]
 P.O. Number: 0701 Report Date: 21-Oct-03

Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0402928	VTRUT284-1	Furnace	Wipe	****	0.111	67.51 ug/ft ²	310 ug/ft ²	
0402929	VTRUT284-2	Furnace	Wipe	****	0.111	67.51 ug/ft ²	290 ug/ft ²	
0402930	VTRUT284-3	Furnace	Wipe	****	0.111	13.50 ug/ft ²	58 ug/ft ²	
0402931	VTRUT284-4	Furnace	Wipe	****	0.111	5.40 ug/ft ²	30 ug/ft ²	
0402932	VTRUT284-5	Furnace	Wipe	****	0.111	6.75 ug/ft ²	37 ug/ft ²	
0402933	VTRUT284-6	Furnace	Wipe Blank	****	N/A	0.30 ug	< 0.3 ug	
0402934	VTRUT284-7	Furnace	Wipe	****	0.111	6.75 ug/ft ²	39 ug/ft ²	

Analysis Method for Flame: Air, Wipes, Paints, and Sol/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B

Analysis Method For Furnace: Air, Wipes, Paints, and Sol/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)

%Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] Technical Manager: [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. All rights reserved. AMA Analytical Services, Inc.



Submitted To: **Non-Responsive**
Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTBEN216-A1 through VTRUT217-A3
P.O. No.:	Not Available
Sample Location:	VT
Sample Type:	Filter
Method Reference:	NIOSH 7300
DCL Set ID No.:	03-S-3834
DCL Sample ID No.:	03-23429 through 03-23442
Sample Receipt Date:	8/8/2003
Preparation Date:	08/11/03
Analysis Date:	08/11/03

The samples were prepared and analyzed in accordance with NIOSH method 7300 using a Perkin Elmer 3000XL ICP.

The sample condition upon receipt was acceptable except where noted.

The results are in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive

[Redacted]

Analyst

Non-Responsive

[Redacted]

Reviewer

CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 280-8071, FAX 415 893-9469

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTBEN216-A1	03-23429	402.71	ND	<0.002
VTBEN216-A2	03-23430	404.73	ND	<0.002
VTBEN216-A3	03-23431	0	ND	-
VTWES216-A1	03-23437	294.35	ND	<0.003
VTWES216-A2	03-23438	0	ND	-
VTRUT217-A1	03-23440	420.05	ND	<0.002
VTRUT217-A2	03-23441	412.99	ND	<0.002
VTRUT217-A3	03-23442	0	ND	-
	Prep Blank		ND	
% Recovery	LCS		100.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).
LCS = laboratory control sample.

Non-Responsive



Analyst

Non-Responsive





Submitted To:

Non-Responsive

Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

Reference Data:

	Lead
Client Sample No.:	VTBEN216-B1 through VTRUT217-B6
P.O. No.:	Not Available
Sample Location:	VT
Sample Type:	Paint Chip
Method Reference:	3050B/6010B
DCL Set ID No.:	03-S-3834
DCL Sample ID No.:	03-23432 through 03-23448
Sample Receipt Date:	8/8/2003
Preparation Date:	8/8/2003
Analysis Date:	8/12/2003

The samples were prepared in accordance with EPA method 3050B. Sample condition was acceptable upon receipt except where noted. The samples were then analyzed in accordance with EPA method 6010B using a Jarrell Ash Trace ICP.

The results are provided in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive

Analyst

Non-Responsive

Reviewer

CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 280-8071, FAX 415 893-9469

Results Lead

Client #	DCL #	mg/Kg (ppm)	% by weight
VTBEN216-B1	03-23432	190000.	19.
VTBEN216-B2	03-23433	4000.	0.40
VTBEN216-B3	03-23434	4400.	0.44
VTBEN216-B4	03-23435	36000.	3.6
VTBEN216-B5	03-23436	2400.	0.24
VTWES216-B1	03-23439	35.	0.0035
VTRUT217-B1	03-23443	1600.	0.16
VTRUT217-B2	03-23444	440.	0.044
VTRUT217-B3	03-23445	5800.	0.58
VTRUT217-B4	03-23446	97000.	9.7
VTRUT217-B5	03-23447	53000.	5.3
VTRUT217-B6	03-23448	8700.	0.87
	Prep Blank	ND	
% Recovery	LCS	93.	
% Recovery	23303MS	98.	
% Recovery	23303MSD	96.	
RPL		25.	0.0025

ND = not detected at or above the reporting limit (RPL).

LCS = laboratory control sample.

MS/MSD = matrix spike/matrix spike duplicate.

Non-Responsive



Analyst

Non-Responsive



Reviewer

Industrial Hygiene Sampling Calculation Worksheet

National Guard Armory Location: RUT
Date: 8/5/2002

Sample 1

Sample Number:	<u>VTRUT217-A1</u>	
Pump:	647615	
	Pre Flow Rate	Post Flow Rate
	2.51	2.446
	2.497	2.442
	2.493	2.442
	2.498	2.439
Average	2.500	2.442
Average Pre and Post	2.4709	
Time 1	8:03	
Time 2	10:53	
Total Time Sampled	2:50	
Minutes Sampled	170.00	
Volume	420.05 Liters	

Sample 2

Sample Number:	<u>VTRUT217-A2</u>	
Pump:	648339	
	Pre Flow Rate	Post Flow Rate
	2.494	2.428
	2.509	2.418
	2.485	2.421
	2.483	2.428
Average	2.493	2.424
Average Pre and Post	2.4583	
Time 1	8:04	
Time 2	10:52	
Total Time Sampled	2:48	
Minutes Sampled	168.00	
Volume	412.99 Liters	

Industrial Hygiene Sampling Calculation Worksheet

National Guard Armory

Location: Rutland - VTRUT217

Date: 8/2/03

Sample 1

Sample Number: VTRUT217-A1

Pump: 647615

	Pre Flow Rate	Post Flow Rate
	2.510	2.446
	2.497	2.442
	2.493	2.442
Average	<u>2.498</u>	<u>2.443</u>
	2.500	2.442

Average Pre and Post 2471

Time 1 0803

Time 2 1053

Total Time Sampled 2:50

Minutes Sampled 170

Volume 420.05

Liters

Sample 2

Sample Number: VTRUT217-A2

Pump: 648339

	Pre Flow Rate	Post Flow Rate
	2.494	2.428
	2.507	2.418
	2.485	2.421
Average	<u>2.482</u>	<u>2.428</u>
	2.493	2.424

Average Pre and Post

Time 1 0804

Time 2 1052

Total Time Sampled 1:68 5

Minutes Sampled 2:48

Volume 412.99

Liters

Appendix D

References

References

Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration (current edition)

American Society of Heating, Refrigerating and Air-Conditioning Engineers, Inc (ASHRAE) 62-2002, Ventilation for Acceptable Indoor Air Quality

Instructions for Completing the Sampling of Army National Guard Armories, Lead Wipe Sampling Procedure included with the Request for Proposal

Air Sampling for Lead - Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods

Design Guide DG-415-2, Logistics Facilities, National Guard Bureau Installation Division, 14 December 1999

Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998

Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, 15 October 1990

AR 385-10, The Army Safety Program, 29 February 2000

Department of the Army Pamphlet (DA PAM) 40-501, Medical Services, Hearing Conservation Program, 10 December 1998

DA PAM 40-503, Medical Services, Industrial Hygiene Program, 30 October 2000

Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH) (current edition)

Guidelines for Converting Indoor Firing Ranges to Other Uses, Headquarters, Department of the Army and the Air Force, NG PAM (AR) 385-16/ANGPAM 91-101, 31 January 1994

24 CFR, Part 35, Subpart B, Section 35-110, Definition of Lead-Based Paint, Housing and Urban Development, U. S. Department of Housing

Appendix E
Recommendations for
Surface Lead Dust in Armories

Subject: Recommendations for Surface Lead Dust in Armories

1. In armories that do not contain childcare facilities, the National Guard Bureau (NGB) Region North Industrial Hygiene Office recommends cleaning the areas in which sample results are greater than 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$). If a special function will be held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function. This guidance is based on professional judgment, risk assessments, adaptation of Occupational Safety and Health Administration (OSHA) guidance, and feasibility of cleaning to a certain level.

a. Environmental Protection Agency (EPA) standards (40 Code of Federal Regulations (CFR) 745.227(h)(3)) are not directly applicable because they are criteria for dust-lead hazards developed for floors ($40 \mu\text{g}/\text{ft}^2$) and windowsills ($250 \mu\text{g}/\text{ft}^2$) in residential dwellings and child occupied facilities. A child occupied facility is defined as a building, or portion of a building, constructed prior to 1978, visited regularly by the same child, 6 years of age or under, on at least two different days within any week (Sunday through Saturday period), provided that each day's visit lasts at least 3 hours and the combined weekly visit lasts at least 6 hours, and the combined annual visits last at least 60 hours. Most of the wipe samples in armories were collected in undisturbed areas and therefore, results are worst case scenarios and do not correlate to these standards.

b. OSHA has no specific requirement for work area surfaces. The lead standard (29 CFR 1910.1025(h)) states that all surfaces shall be maintained as free as practicable of accumulations of lead dust. In workplaces where lead dust is generated, surface levels may be much higher, but personnel exposures can be controlled by limiting airborne lead levels and following good cleanup and hygienic practices.

c. OSHA used to cite a level of $200 \mu\text{g}/\text{ft}^2$ in their Technical Manual and 29 CFR 1926.62 as guidance to its own inspectors for evaluating the cleanliness of lunchroom and locker room surfaces that are supposed to be kept as clean as possible.

d. In a report titled Derivation of Wipe Surface Screening Levels for Environmental Chemicals, the US Army Center for Health Promotion and Preventive Medicine (USACHPPM) has determined that $200 \mu\text{g}/\text{ft}^2$ is a safe surface contamination level. They have also applied these standards as the decontamination levels for surfaces in administrative offices.

e. It should be noted that levels above these recommendations do not necessarily mean there is a significant hazard to workers who are following good cleaning and hygienic practices since there is no correlation between wipe and air samples. Rather, we recommend these levels as a precautionary measure.

2. The NGB Occupational Health Branch is developing guidance for armories that are used as childcare facilities. All states will receive this guidance when it is completed. In the interim, we recommend the following actions:

a. Clean all areas that will be accessible to children to the EPA dust-lead standard for children 6 years of age or under ($40 \mu\text{g}/\text{ft}^2$ on floors and $250 \mu\text{g}/\text{ft}^2$ on windowsills).

b. Refer to the local authorities' regulations since they can be more stringent than federal regulations.

c. Post signs in the area to inform people of the presence of lead dust and its effects.

d. If soldiers clean weapons in the facility change the policy so that they cannot clean their weapons in the facility, or if they are allowed to clean their weapons indoors, they must clean the area by wet wiping and mopping the area when they are done.

e. If the paint is peeling, contact the state Environmental Office to test for lead content and provide recommendations.

3. Air samples collected on individuals in the armory were well below OSHA's permissible exposure limit for lead (29 CFR 1910.1025(e)) of $0.05 \text{ mg}/\text{m}^3$ averaged over an 8-hour day. Therefore, based on these conditions there is currently no overexposure to personnel from lead dust in this building.

Shaw Environmental, Inc.

312 Directors Drive
Knoxville, TN 37923
865.690.3211
Fax 865.690.3626



Shaw Environmental, Inc.

**National Guard Armory
St. Albans Readiness Center – St. Albans, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

22 March 2004

National Guard Armory
St. Albans Readiness Center – St. Albans, Vermont

Industrial Hygiene Evaluation

Prepared for:

National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078

Prepared by:
Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923

22 March 2004

Prepared by:

Non-Responsive

Industrial Hygienist

Reviewed by:

Non-Responsive

Business Line Manager

Table of Contents

<i>Table of Contents</i>	<i>i</i>
<i>List of Tables</i>	<i>ii</i>
<i>List of Appendices</i>	<i>ii</i>
<i>Executive Summary</i>	<i>E-1</i>
<i>1.0 Introduction</i>	<i>1-1</i>
<i>2.0 Findings, Discussion, and Interpretation of Results</i>	<i>2-1</i>
<i>2.1 Sampling for Lead</i>	<i>2-1</i>
<i>2.1.1 Wipe Sampling</i>	<i>2-1</i>
<i>2.1.2 Air Sampling for Lead</i>	<i>2-2</i>
<i>2.2 Physical Condition of Facility</i>	<i>2-2</i>
<i>2.2.1 Peeling Paint - Lead</i>	<i>2-2</i>
<i>2.2.2 Visual Inspection - Asbestos</i>	<i>2-2</i>
<i>2.2.3 Visual Inspection – Water Damage and Mold</i>	<i>2-3</i>
<i>2.2.4 Visual Inspection - Housekeeping</i>	<i>2-3</i>
<i>2.3 Building Concerns</i>	<i>2-3</i>
<i>2.3.1 Ergonomic Concerns</i>	<i>2-3</i>
<i>2.3.2 Indoor Air Quality</i>	<i>2-3</i>
<i>2.4 Safety and Industrial Hygiene Programs</i>	<i>2-3</i>
<i>2.5 Ventilation</i>	<i>2-4</i>
<i>2.5.1 Ventilation System Evaluation</i>	<i>2-4</i>
<i>2.5.2 Contamination of Clean Air Sources</i>	<i>2-4</i>
<i>2.6 Noise Exposure</i>	<i>2-4</i>
<i>2.7 Lighting</i>	<i>2-4</i>
<i>2.8 Converted Indoor Firing Ranges</i>	<i>2-5</i>
<i>2.9 HVAC Systems</i>	<i>2-5</i>
<i>2.10 HHM</i>	<i>2-5</i>
<i>3.0 Conclusions</i>	<i>3-1</i>
<i>Tables</i>	<i>Follows Section 3.0</i>
<i>Appendices</i>	<i>Follows Tables</i>

List of Tables

Table 1	Wipe Sampling for Lead
Table 2	Air Sampling for Lead
Table 3	Peeling Paint Sampling for Lead
Table 4	Indoor Air Quality Measurements
Table 5	Illumination Readings
Table 6	Indoor Firing Ranges – Wipe Sampling

List of Appendices

Appendix A	IIIM Data Form
Appendix B	Building Layout
Appendix C	Sampling Sheets and Laboratory Analyses
Appendix D	References
Appendix E	Recommendations for Surface Lead Dust in Armories

Executive Summary

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the St. Albans Readiness Center in St. Albans, Vermont. **Non-Responsive** performed the evaluation on 15 and 16 July 2003 and 9 October 2003. The point of contact at the readiness center was CPT **Non-Responsive**.

The following industrial hygiene concerns were evaluated.

- Wipe Sampling for Lead
- Air Sampling for Lead
- Peeling Paint – Lead
- Suspected Asbestos Containing Material
- Water Damage
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Indoor Air Quality
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- Lighting
- Converted Indoor Firing Range
- HVAC Systems

The following items were either not applicable to the armory or the evaluation resulted in a conclusion that there were no industrial hygiene concerns.

- Air Sampling for Lead
- Peeling Paint – Lead
- Water Damage
- Presence of Mold
- Ergonomic Concerns
- Safety and Industrial Hygiene Programs

- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- HVAC Systems

Areas where there were industrial hygiene concerns are as follows:

- Wipe sampling for lead revealed concentrations above the recommended level at two locations (top of locker #90 and stereo system top surface) in the assembly/drill hall and a shelf top in the kitchen. It is recommended that these surfaces and the areas immediately around these surfaces be thoroughly cleaned to reduce the lead level. In addition, any other dusty/dirty areas in the assembly area/drill floor and kitchen should be thoroughly cleaned.
- Wipe sampling for lead revealed concentrations above a level of 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) in the assembly hall and kitchen. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.
- Materials suspected of containing asbestos were observed. An operations and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.
- The housekeeping in the basement was considered average in the areas that are not used by the staff; these areas were cluttered and dusty. The housekeeping in these areas should be improved.
- Indoor air quality measurements revealed that the temperature at the armory exceeded the recommended levels. A fan could be used for cooling purposes and to circulate air.
- Lighting measurements were conducted at the armory. The lighting did not meet minimum requirements in most areas; therefore consideration should be given to providing more lighting in these areas. This may be accomplished by replacing burnt out luminaires, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.
- Wipe sampling for lead in the converted firing range revealed concentrations above the recommended level at all of the locations sampled. These areas must be decontaminated by a thorough cleaning until surface lead concentrations are reduced to below recommended levels. In addition, employees should not be allowed to work

in these areas without protective clothing until the areas have been cleaned and re-sampled.

1.0 Introduction

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the St. Albans Readiness Center in St. Albans, Vermont. **Non-Responsive** performed the evaluation on 15 and 16 July 2003 and 9 October 2003. The point of contact at the readiness center was CPT **Non-Responsive**

The findings, discussion, and interpretation of results are provided in Section 2.0. The conclusions are provided in Section 3.0. The HHIM data form for the facility is provided in Appendix A. The building layout is provided in Appendix B. Sampling sheets and laboratory analyses are provided in Appendix C. References are provided in Appendix D. The *Recommendations for Surface Lead Dust in Armories* document is provided in Appendix E.

The statements, opinions, and conclusions contained in this report are based solely upon the services performed by Shaw as described in the report. In performing these services and preparing the report, Shaw Environmental, Inc. relied upon the work and information provided by others, including public agencies, whose information is not guaranteed by Shaw Environmental, Inc.

2.0 Findings, Discussion, and Interpretation of Results

The results, discussion, and interpretation of results are provided in the following sections.

2.1. Sampling for Lead

2.1.1 Wipe Sampling

Wipe samples were collected for lead from the drill floor/assembly area. Also, wipe samples were collected for lead in rooms, hallways, foyers, etc. The sampling in rooms, hallways, foyers, etc. represented approximately 25% of the building. Approximately half of the samples were collected from surfaces in common areas, such as surfaces of a desk. The remaining samples were collected from uncommon surface areas, such as a supply vent or the top of a file cabinet. The samples were collected and analyzed in accordance with the instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

The only samples initially submitted for analysis were those from the drill floor/assembly hall. If there were any positive results from the drill floor, the other samples would be submitted for analysis.

Results of the wipe sampling are provided in Table 1. The results revealed lead at all locations sampled at concentrations below recommended level of 200 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$) (See Appendix E) except at three locations. Two samples collected in the assembly/drill hall (top of locker #90 and stereo system top surface) had lead concentrations of 200 and 490 $\mu\text{g}/\text{ft}^2$, respectively. The sample obtained from the shelf top in the kitchen had a lead concentration of 360 $\mu\text{g}/\text{ft}^2$. It is recommended that these surfaces and the immediate areas around the surfaces be thoroughly cleaned to reduce the lead level to below 200 $\mu\text{g}/\text{ft}^2$. For guidance on the proper method of cleaning, please refer to NCG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.

In addition, wipe sampling for lead revealed concentrations above a level of 40 $\mu\text{g}/\text{ft}^2$ in the assembly hall and the kitchen. Please note that the *Recommendations for Surface Lead Dust in Armories* (Appendix E) states that all areas should be cleaned that will be accessible to children. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.

2.1.2 Air Sampling for Lead

Breathing zone air sampling was conducted on two (2) full-time building occupants. (Please note that no state employees were monitored.) The samples were collected and analyzed in accordance with Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods.

The results of the sampling are provided in Table 2. The results revealed non-detectable concentrations of lead in the breathing zone of the employees; therefore, no actions are necessary.

2.2 Physical Condition of Facility

2.2.1 Peeling Paint - Lead

Peeling paint was observed in the armory. The Department of Housing and Urban Development (HUD) defines lead-based paint as paint or other surface coatings that contain lead equal to or exceeding 0.5 percent by weight. Bulk sampling results revealed lead at a concentration of 0.18 percent by weight in the paint sample taken from the kitchen wall. Since HUD does not consider the paint a lead-based paint, no actions are necessary. The results of the sampling are provided in Table 3.

2.2.2 Visual Inspection - Asbestos

A visual inspection was made to determine if there was any suspected asbestos-containing material at the armory. Materials suspected of containing asbestos were observed. The suspected asbestos-containing material was insulation in the boiler room (approximately 13 linear feet and 10 pipe elbows/joints). The condition of the boiler room insulation materials was considered average since there were some areas where previous asbestos samples were collected that were covered by tape.

An operation and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.

2.2.3 Visual Inspection – Water Damage and Mold

A visual inspection was made to determine if there was any water damage or visible mold at the armory. The inspection did not reveal any water damage or visible mold.

2.2.4 Visual Inspection - Housekeeping

The housekeeping was determined to be good on the first and second floors. The housekeeping in the basement was considered average in the areas that are not used by the staff; these areas were cluttered and dusty. The housekeeping in these areas should be improved.

2.3. Building Concerns

2.3.1 Ergonomic Concerns

Interviews with employees and observation of work activities revealed no ergonomic concerns at the armory.

2.3.2 Indoor Air Quality

Interviews with employees and measurements for carbon dioxide, humidity, and temperature revealed no indoor air quality concerns at the armory. However, measurements for temperature revealed that levels exceeded the American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommendations. ASHRAE recommends that the acceptable temperature range be 68 degrees Fahrenheit to 74 degrees Fahrenheit in the winter and 73 degrees Fahrenheit to 79 degrees Fahrenheit in the summer. A fan could be used for cooling purposes and to circulate air.

The results of the measurements for carbon dioxide, humidity, and temperature are provided in Table 4.

2.4. Safety and Industrial Hygiene Programs

An evaluation was performed to determine the applicability of the following programs.

- Confined Spaces
- Hearing Conservation
- Respiratory Protection
- Hazard Communication (HAZCOM)
- Personal Protective Equipment (PPE)

It was determined that the HAZCOM program was the only program listed above that was applicable at the facility. The HAZCOM program was evaluated and it was determined that the program met minimum requirements.

2.5. Ventilation

2.5.1 Ventilation System Evaluation

There were no local exhaust ventilation systems at this armory; therefore, no ventilation studies were performed.

2.5.2 Contamination of Clean Air Sources

Since there were no local exhaust ventilation systems at the armory, there was no possibility that clean air sources could be contaminated by exhaust air.

2.6. Noise Exposure

An evaluation was performed to determine if there were any hazardous noise areas at the armory. It was determined that there were no areas at the armory that would exceed the permissible exposure limit for noise.

2.7 Lighting

Lighting measurements were conducted at the armory. Results of the lighting evaluation are provided in Table 5. As can be seen from the results, the lighting did not meet the minimum requirements in most areas, including the Supply Technician Office, BN Supply SGT Office, IHC Administrative Office, XO Office, Conference Room, second floor bathroom, CSM Office, Medical Office, and Medical Exam Room.

Consideration should be given to providing more lighting to the areas listed above. This may be accomplished by replacing burnt out luminaires, cleaning fixtures,

cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

2.8. Converted Indoor Firing Ranges

There was a converted indoor firing range at the facility; therefore, wipe samples were taken for lead at various locations in or near the converted range. The space was divided into a locker room and classroom (construction of classroom occurring during the survey). The results are provided in Table 6. The results revealed lead, with associated concentrations, at the following locations:

- inside remaining ventilation ductwork at 66000 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$);
- stored item -- locker top surface at 540 $\mu\text{g}/\text{ft}^2$;
- floor in the bullet trap area at 28000 $\mu\text{g}/\text{ft}^2$.

The lead levels at these locations were above the recommended level of 200 $\mu\text{g}/\text{ft}^2$, a level recommended in the *Guidelines for Converting Indoor Firing Ranges to Other Uses* document (Department of Army). These areas must be decontaminated by a thorough cleaning until surface lead concentrations are reduced to below recommended levels. For guidance on the proper method of cleaning, please refer to NG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, employees should not be allowed to work in these areas without protective clothing until the areas have been cleaned and re-sampled.

2.9. HVAC System

There was not a HVAC system at the armory.

2.10. HHIM

A Health Hazard Information Module (HHIM) form was completed for the armory. The completed form is provided in Appendix A.

3.0 Conclusions

It is concluded that there were no industrial hygiene concerns at the armory with regards to atmospheric exposure to lead, peeling lead-based paint, water damage, visible mold, ergonomic conditions, safety and industrial hygiene programs, ventilation systems or contamination of clean air sources, noise exposure, and HVAC systems.

There were industrial hygiene concerns at the armory with regards to lead surface contamination, suspected asbestos-containing material, housekeeping, indoor air quality, surface lead contamination in the converted firing range, and lighting. These concerns are discussed in detail in Section 2.0 of this report.

TABLES

Table 1
Wipe Sampling for Lead
National Guard Armory
St. Albans, Vermont
Dates of Sampling: 15 and 16 July 2003 and 9 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTSTA196-1	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTSTA196-2	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTSTA196-3	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTSTA196-4	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTSTA196-5	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTSTA196-6	Field Blank	< 12 μg
VTSTA196-7	1 st Floor - Recruiting Retention Office - cabinet top	13
VTSTA196-8	1 st Floor - BN Supply Sgt. Office - desktop	4.8
VTSTA196-9	2 nd Floor - Conference Area - table top	3.8
VTSTA196-10	2 nd Floor - XO Office - desktop	< 2.7
VTSTA196-11	2 nd Floor - CSM Office - cabinet top	3.2
VTSTA196-12	Field Blank	6 μg
VTSTA197-13	Basement - Kitchen - shelf top (below radiator)	360
VTSTA197-14	Basement - Medic Exam Room - desktop	10
VTSTA283-1	Assembly Room - top of soda machine (See Building Layout - Appendix B)	160
VTSTA283-2	Assembly Room - top of locker #90 (See Building Layout - Appendix B)	200
VTSTA283-3	Assembly Room - top of locker #81 (See Building Layout - Appendix B)	130

^aMicrograms lead per square foot

**Table 1 Continued
Wipe Sampling for Lead
National Guard Armory
St. Albans, Vermont**

Dates of Sampling: 15 and 16 July 2003 and 9 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTSTA283-4	Assembly Room - top of locker #141 (See Building Layout - Appendix B)	130
VTSTA283-5	Assembly Room - stereo system top surface (See Building Layout - Appendix B)	490
VTSTA283-6	Field Blank	0.37 μg

^aMicrograms lead per square foot

The samples were taken and analyzed in accordance with the instructions for *Completing the Sampling of Army National Guard Armories* procedure.

In armories that do not contain childcare facilities, the NGB Region North Industrial Hygiene Office recommends cleaning the areas with lead concentrations greater than 200 $\mu\text{g}/\text{ft}^2$.

Table 2
Breathing Zone Air Samples for Lead
National Guard Armory
St. Albans, Vermont
Date of Sampling: 15 July 2003

Sample Number	Employee	Sampling Information			Results (mg/m ³) ^a
		Time Sampled / Minutes	Flow Rate (lpm) ^b	Volume (liters)	
VTSTA196-A1	Non-Responsive	1513-1618/65	2.5415	165.20	<0.006
VTSTA196-A2		1519-1619/60	2.5290	151.74	<0.007
VTSTA196-A3	Field Blank	-	-	-	None Detected

^a Milligrams lead per cubic meter of air.

^b Liters of air per minute.

Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods was followed for sampling for lead.

Table 3
Peeling Paint Sampling for Lead
National Guard Armory
St. Albans, Vermont
Date of Sampling: 16 July 2003

Sample Number	Location	Results, % By Weight
VTSTA197-B1	Kitchen wall	0.18

The Department of Housing and Urban Development (HUD) defines lead-based as paint or other surface coatings that contain lead equal to or exceeding 0.5 percent by weight.

Table 4
Indoor Air Quality Measurements for Carbon Dioxide, Humidity, and Temperature
National Guard Armory
St. Albans, Vermont
Date of Sampling: 15 July 2003

Location	Occupants in Area	Carbon Dioxide, parts per million parts of air (ppm)	Percent (%) Humidity	Temperature (°F)
1 st Floor	1	401	49.1	81.5
2 nd Floor	2	495	52.7	82.0
Basement	1	443	51.0	79.9
Outdoors	0	370	75.1	72.3

Carbon dioxide, humidity, and temperature measurements were taken with a TSI Q Trak Plus, Model 8554, Indoor Air Quality Meter, calibrated in April 2003.

American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommends that indoor carbon dioxide levels be less than 700 ppm above outdoor levels.

ASHRAE recommends that the relative humidity levels be maintained between 30 to 60 percent.

ASHRAE recommends that the acceptable temperature range be 68 degrees Fahrenheit to 74 degrees Fahrenheit in the winter and 73 degrees Fahrenheit to 79 degrees Fahrenheit in the summer.

Table 5
Illumination Readings
National Guard Armory
St. Albans, Vermont
Date of Sampling: 15 and 16 July 2003

Location	Luminance (fc) ^a	Standard (fc) ^a	Standard Met
1 st Floor -- foyer	8.1-36.8	7.5	Yes
1 st Floor -- Recruiting Retention Office	19.1-75.4	70	Some Areas
1 st Floor -- Supply Technician Office	19.1-47.7	70	No
1 st Floor -- BN Supply SGT Office	20.1-46.5	70	No
1 st Floor -- HHC Administrative Office	11.1-52.1	70	No
2 nd Floor -- XO Office	8.1-56.8	70	No
2 nd Floor -- Conference Room	19.3-68.3	70	No
2 nd Floor -- S-3 Office	16.2-78.7	70	Some areas
Staircase between 1 st and 2 nd Floor	2.3-57.4	7.5	Some areas
2 nd Floor -- bathroom	20.1-24.0	40	No
2 nd Floor -- BN CDR Office	8.3-78.5	70	Some areas
2 nd Floor -- CSM Office	12.1-45.2	70	No
Basement -- Kitchen	27.6-94.2	70	Some areas
Basement -- Medical Office	9.2-43.2	70	No
Basement -- Medical Exam Room	20.1-50.1	70	No
Basement -- Classroom	51.3-179	70	Some areas

^a fc - Footcandles

The readings were taken with a Cooke Corporation cal-LIGHT 400 Calibrated Precision Lightmeter, calibrated on 19 Aug 2002.

The standards listed above are from Design Guide DG-415-2, Logistics Facilities, published by the National Guard Bureau Installation Division.

Table 6
Wipe Sampling for Lead – Converted Firing Range
National Guard Armory
St. Albans, Vermont
Date of Sampling: 16 July 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTSTA197-15	Inside Remaining Ventilation Ductwork	66000
VTSTA197-16	Stored Item - Locker Top	540
VTSTA197-17	Floor - Bullet Trap Area	28000

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the instructions for *Completing the Sampling of Army National Guard Armories* procedure.

Appendix A

HHIM Data Form(s)

HEALTH HAZARD INFORMATION MODULE: INDUSTRIAL HYGIENE SURVEY

(For use of this form, see HHIM User's Guide)

SECTION 1. DEMOGRAPHIC DATA

RLOC St. Albans Armory Vermont ARNG		INSTALLATION St. Albans Armory Vermont ARNG		BLDG/RM NO. St. Albans	
LOCATION/CODE Administrative Areas/ AA			OPERATION/CODE Administrative OP/ADO		
SURVEY DATE 15 and 16 July 2003			EVALUATOR (Initials) Non-Responsive		
MACOM/CODE Army National Guard		SUBMACOM/CODE XX		SUPERVISOR Non-Responsive : CPT	
TELEPHONE/DSN NO. 802-524-4101		UNIT/ORGANIZATION Headquarters/1-172 AR Battalion		RAC 04	FREQUENCY (hrs/day) 8
NO. CIV(S) 0	NO. MIL 10	NO. CONTRACTOR(S) 2	NO. LOC(S) 0	NO. OTHER 0	

SECTION 2. FACILITY DATA

FAB HOODS 0		VAPOR DEGREASERS 0		SPRAY BOOTHS 0	
MAINTENANCE BAYS 0		OPEN SURFACE TANKS 0		VENTILATION UNITS 0	

SECTION 3. SURVEY DATA

CONTROLS PRESENT	EVALUATION	UNIT CODE	CONTROLS REQUIRED	STATUS

PERSONAL PROTECTIVE EQUIPMENT (R = Required; U = Utilized)

GLOVES	R	U	RESPIRATOR	NOSH TC NO.	MANUFACTURER	R	U
ACID			AIRLINE				
COLD SURFACES			ABRASIVE BLASTING HOOD				
HOT SURFACES			DISPOSABLE				
NBC AGENTS			FULL FACE AIR PURIFYING				
OIL			1/2 FACE AIR PURIFYING				
SOLVENTS			POWERED AIR PURIFYING				
SURGICAL GLOVES			1/4 FACE AIR PURIFYING				
			SELF CONTAINED				

EYES/FACE	R	U	HEARING	R	U	BODY	R	U	HEAD/FIT	R	U
CHEMICAL SPLASH			CANAL CAPS			APRONS			COLD WEATHER BOOTS/HATS		
FULL FACE SHIELD			EAR PLUGS			COLD WEATHER CLOTHING			HARD HATS		
CHEMICAL/SAFETY			HELMETS			COVERALLS			IMPERMEABLE BOOTS		
SAFETY/IMPACT			MUFFS			FULL BODY SUIT			SAFETY/CONDUCTIVE SHOES		
WELDING HELMET			MUFF/EARPLUG COMBO			HEAT REFLECTIVE VEST/SUIT			SAFETY/NON-CONDUCTIVE SHOES		
			MUFF/EARPLUG W/TIME LIMIT			SAFETY BELT/HARNES					

SECTION 4. HAZARD INVENTORY DATA

CAS CODE	HAZARD DESCRIPTION	PAC	EPC
POVDTXXXX	Video Display Terminal	3-low	D Uncontrolled Physical
7439-92-1	Lead, inorganic dust and fumes, as Pb	2-moderate	C Uncontrolled Respiratory
1332-21-4	Asbestos (other)	2-moderate	C Uncontrolled Respiratory

SECTION 5. PERSONNEL DATA

LAST NAME	FIRST NAME	MI	SEX	SSN	CATEGORY
Non-Responsive		C	M	Non-Responsive	MIL
			M		
			M		
			M		
			M		
			M		
			M		
			M		

SECTION 6. COMMENTS

No comments See attached sheet
 Survey was conducted by Michele Senan. Building contains 10 full-time military staff. The employees perform mainly administrative functions. Contractors were on site (2) two, constructing the ventilation system in the classroom in basement. **PRIVACY ACT STATEMENT**


Title 5 US Code, Section 301; Executive Order 9397 authorizes the use of your Social Security Number as an identification number. The purpose of this information is to identify and monitor data relating each DA civilian and military employee exposed to a hazardous workplace or operation. The use of this information is to provide histories of exposures for any given worker.

Disclosure of your Social Security Number is not mandatory; however, nondisclosures may result in untimely provision of proper medical monitoring.

Appendix B


Building Layout

HQs & HHC 1-172d First Floor Fire Escape Plan




○ Sample date: 13 July 2003
 △ Sample date: 9 October 2008

FM 42-10 3 33 10 1 MCT
FM THE ACCIDENTS, LTR, WSPR



Hqs & HHC 1-172d Basement Fire Escape Plan



Appendix C

Sampling Sheets and Laboratory Analyses

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301 JIE Old Bay Lane, Aftn NGB-AVN-SI, State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTSTAI96/097
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01

Chain Of Custody: 115810
Date Analyzed: 8/5/2003

Person Submitting: [Redacted]
Report Date: 05-Aug-03

Attention: [Redacted] Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0359492	VTSTAI96-1	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359493	VTSTAI96-2	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359494	VTSTAI96-3	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359495	VTSTAI96-4	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359496	VTSTAI96-5	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359497	VTSTAI96-6	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0359498	VTSTAI97-15	Flame	Wipe	****	0.111	108.00 ug/ft ²	66000 ug/ft ²	
0359499	VTSTAI97-16	Flame	Wipe	****	0.111	108.00 ug/ft ²	540 ug/ft ²	
0359500	VTSTAI97-17	Flame	Wipe	****	0.111	108.00 ug/ft ²	28000 ug/ft ²	

Analysis Method for Flame: Air, Wipes, Paints, and Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Solids: EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)

%Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] Technical Manager:

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a neutral protection to clients, the public and these Laboratories, no report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. All rights reserved. AMA Analytical Services, Inc.



Client: National Guard Bureau
Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SL, State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTSTA283
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 0701

Chain of Custody: 118717
Date Analyzed: 10/21/2003

Persons Submitting: [Redacted]
Report Date: 21-Oct-03

Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft²)	Reporting Limit	Final Result	Comments
0402910	VTSTA283 -1	Furnace	Wipe	*****	0.111	67.51 ug/ft²	160 ug/ft²	
0402911	VTSTA283 -2	Furnace	Wipe	*****	0.111	67.51 ug/ft²	200 ug/ft²	
0402912	VTSTA283 -3	Furnace	Wipe	*****	0.111	67.51 ug/ft²	130 ug/ft²	
0402913	VTSTA283 -4	Furnace	Wipe	*****	0.111	67.51 ug/ft²	130 ug/ft²	
0402914	VTSTA283 -5	Furnace	Wipe	*****	0.111	67.51 ug/ft²	490 ug/ft²	
0402915	VTSTA283 -6	Furnace	Wipe Blank	*****	N/A	0.30 ug	0.37 ug	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] **Technical Manager:** [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

An AIHA (#8863), NVLAP (# 101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTSTA196/VTSTA197
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: Not Provided

Chain Of Custody: 118931
Date Analyzed: 10/30/2003
Person Submitting: [Redacted]
Report Date: 30-Oct-03

Attention: [Redacted] Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0404833	VTSTA196-7	Furnace	Wipe	****	0.111	2.70 ug/ft ²	13 ug/ft ²	
0404834	VTSTA196-8	Furnace	Wipe	****	0.111	2.70 ug/ft ²	4.8 ug/ft ²	
0404835	VTSTA196-9	Furnace	Wipe	****	0.111	2.70 ug/ft ²	3.8 ug/ft ²	
0404836	VTSTA196-10	Furnace	Wipe	****	0.111	2.70 ug/ft ²	<	
0404837	VTSTA196-11	Furnace	Wipe	****	0.111	2.70 ug/ft ²	3.2 ug/ft ²	
0404838	VTSTA196-12	Furnace	Wipe Blank	****	N/A	1.50 ug	6 ug	
0404839	VTSTA197-13	Furnace	Wipe	****	0.111	67.51 ug/ft ²	360 ug/ft ²	
0404840	VTSTA197-14	Furnace	Wipe	****	0.111	2.70 ug/ft ²	10 ug/ft ²	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7421; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] **Technical Manager:** [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

An AIHA (#8863), NVLAP (#101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643



Submitted To: **Non-Responsive**
Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTCAM205-A1 through VTAAS204-A3
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Filter
Method Reference:	NIOSH 7300
DCL Set ID No.:	03-S-3621
DCL Sample ID No.:	03-22309 through 03-22345
Sample Receipt Date:	7/28/2003
Preparation Date:	07/29/03
Analysis Date:	07/31/03

The samples were prepared and analyzed in accordance with NIOSH method 7300 using a Perkin Elmer 3000XL ICP.

The sample condition upon receipt was acceptable except where noted.

The results are in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive



Analyst

Non-Responsive



REVIEWER

CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 280-8071, FAX 415 893-9469

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTCAM205-A1	03-22309	407.54	ND	<0.002
VTCAM205-A2	03-22310	377.66	ND	<0.003
VTCAM205-A3	03-22311	0	ND	-
VTWIN202-A1	03-22313	152.91	ND	<0.007
VTWIN202-A2	03-22314	0	ND	-
VTENO196-A1	03-22316	150.55	ND	<0.007
VTENO196-A2	03-22317	0	ND	-
VTWIL197-A1	03-22319	199.78	ND	<0.005
	Prep Blank 1		ND	
% Recovery	LCS 1		96.	
% Recovery	LCS 2		96.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).
LCS = laboratory control sample.

Non-Responsive

Analyst

Non-Responsive

REVISOR

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTWIL197-A2	03-22320	149.76	ND	<0.007
VTWIL197-A3	03-22321	0	ND	-
VTSWA196-A1	03-22322	149.24	ND	<0.007
VTSWA196-A2	03-22323	0	ND	-
VTSTA196-A1	03-22324	165.20	ND	<0.006
VTSTA196-A2	03-22325	151.74	ND	<0.007
VTSTA196-A3	03-22326	0	ND	-
VTWAT203-A1	03-22328	194.90	ND	<0.005
VTWAT203-A2	03-22329	0	ND	-
VTGOS202-A1	03-22332	175.30	ND	<0.006
VTGOS202-A2	03-22333	0	ND	-
VTMOR203-A1	03-22335	346.43	ND	<0.003
VTMOR203-A2	03-22336	348.65	ND	<0.003
VTMOR203-A3	03-22337	0	ND	-
VTGRE197-A1	03-22340	240.55	ND	<0.004
VTGRE197-A2	03-22341	250.76	ND	<0.004
VTGRE197-A3	03-22342	0	ND	-
VTAAS209-A1	03-22343	748.92	ND	<0.001
VTAAS209-A2	03-22344	507.55	ND	<0.002
VTAAS209-A3	03-22345	0	ND	-
	Prep Blank 2		ND	
% Recovery	LCS 3		96.	
% Recovery	LCS 4		95.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).
LCS = laboratory control sample.

Non-Responsive

Analyst

Non-Responsive

Reviewer


 Submitted To: **Non-Responsive**

 Shaw Environmental, Inc.
 101 Fieldcrest Ave., 4th Floor
 Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTCAM205-B1 through VTMC203-B2
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Paint Chip
Method Reference:	3050B/6010B
DCL Set ID No.:	03-S-3621
DCL Sample ID No.:	03-22312 through 03-22339
Sample Receipt Date:	07/28/2003
Preparation Date:	07/29/2003
Analysis Date:	07/31/2003

The samples were prepared in accordance with EPA method 3050B. Sample condition was acceptable upon receipt except where noted. The samples were then analyzed in accordance with EPA method 6010B using a Jarrell Ash Trace ICP.

The results are provided in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive

Analyst

 CINCINNATI OFFICE
 4388 GLENDALE-MILFORD ROAD
 CINCINNATI, OHIO 45242-3706
 513 733-5336, FAX 513 733-5347

Non-Responsive

Reviewer

 WEST COAST OFFICE
 11 SANTA YORMA COURT
 NOVATO, CALIFORNIA 94945
 800 280-8071, FAX 415 893-9469

Results Lead

Client #	DCL #	mg/Kg (ppm)	% by weight
VTCAM205-B1	03-22312	160.	0.016
VTWIN202-B1	03-22315	11000.	1.1
VTENO196-B1	03-22318	96000.	9.6
VTSTA197-B1	03-22327	1800.	0.18
VTWAT203-B1	03-22330	40.	0.0040
VTWAT203-B2	03-22331	57.	0.0057
VTMOR203-B1	03-22338	3900.	0.39
VTMOR203-B2	03-22339	11000.	1.1
	Prep Blank	ND	
% Recovery	LCS	87.	
% Recovery	03-22327 MS	* 0.	
% Recovery	03-22327 MSD	* 4.	
RPL		25.	0.0025

ND = not detected at or above the reporting limit (RPL).

LCS = laboratory control sample.

MS/MSD = matrix spike/matrix spike duplicate.

* Low recovery due to non-homogeneous sample matrix.

Non-Responsive



Christopher Gibson
Analyst

Non-Responsive



Reviewer

Industrial Hygiene Sampling Calculation Worksheet

National Guard Armory Location: STA
Date: 198

Sample 1

Sample Number: VTSTA196-A1

Pump: 647615

	Pre Flow Rate	Post Flow Rate
	2.558	2.527
	2.556	2.521
	2.562	2.52
	2.57	2.518
Average	2.562	2.522

Average Pre and Post 2.5415

Time 1 15:13

Time 2 16:18

Total Time Sampled 1:05

Minutes Sampled 65.00

Volume 165.20 Liters

Sample 2

Sample Number: VTSTA196-A2

Pump: 648339

	Pre Flow Rate	Post Flow Rate
	2.542	2.514
	2.539	2.518
	2.535	2.523
	2.537	2.524
Average	2.538	2.520

Average Pre and Post 2.5290

Time 1 15:19

Time 2 16:19

Total Time Sampled 1:00

Minutes Sampled 60.00

Volume 151.74 Liters

STA196

Appendix D

References

References

Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration (current edition)

American Society of Heating, Refrigerating and Air-Conditioning Engineers, Inc (ASHRAE) 62-2002, Ventilation for Acceptable Indoor Air Quality

Instructions for Completing the Sampling of Army National Guard Armories, Lead Wipe Sampling Procedure included with the Request for Proposal

Air Sampling for Lead - Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods

Design Guide DG-415-2, Logistics Facilities, National Guard Bureau Installation Division, 14 December 1999

Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998

Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, 15 October 1990

AR 385-10, The Army Safety Program, 29 February 2000

Department of the Army Pamphlet (DA PAM) 40-501, Medical Services, Hearing Conservation Program, 10 December 1998

DA PAM 40-503, Medical Services, Industrial Hygiene Program, 30 October 2000

Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH) (current edition)

Guidelines for Converting Indoor Firing Ranges to Other Uses, Headquarters, Department of the Army and the Air Force, NG PAM (AR) 385-16/ANGPAM 91-101, 31 January 1994

24 CFR, Part 35, Subpart B, Section 35-110, Definition of Lead-Based Paint, Housing and Urban Development, U. S. Department of Housing

Appendix E
Recommendations for
Surface Lead Dust in Armories

Subject: Recommendations for Surface Lead Dust in Armories

1. In armories that do not contain childcare facilities, the National Guard Bureau (NGB) Region North Industrial Hygiene Office recommends cleaning the areas in which sample results are greater than 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$). If a special function will be held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function. This guidance is based on professional judgment, risk assessments, adaptation of Occupational Safety and Health Administration (OSHA) guidance, and feasibility of cleaning to a certain level.

a. Environmental Protection Agency (EPA) standards (40 Code of Federal Regulations (CFR) 745.227(h)(3)) are not directly applicable because they are criteria for dust-lead hazards developed for floors ($40 \mu\text{g}/\text{ft}^2$) and windowsills ($250 \mu\text{g}/\text{ft}^2$) in residential dwellings and child occupied facilities. A child occupied facility is defined as a building, or portion of a building, constructed prior to 1978, visited regularly by the same child, 6 years of age or under, on at least two different days within any week (Sunday through Saturday period), provided that each day's visit lasts at least 3 hours and the combined weekly visit lasts at least 6 hours, and the combined annual visits last at least 60 hours. Most of the wipe samples in armories were collected in undisturbed areas and therefore, results are worst case scenarios and do not correlate to these standards.

b. OSHA has no specific requirement for work area surfaces. The lead standard (29 CFR 1910.1025(h)) states that all surfaces shall be maintained as free as practicable of accumulations of lead dust. In workplaces where lead dust is generated, surface levels may be much higher, but personnel exposures can be controlled by limiting airborne lead levels and following good cleanup and hygienic practices.

c. OSHA used to cite a level of $200 \mu\text{g}/\text{ft}^2$ in their Technical Manual and 29 CFR 1926.62 as guidance to its own inspectors for evaluating the cleanliness of lunchroom and locker room surfaces that are supposed to be kept as clean as possible.

d. In a report titled Derivation of Wipe Surface Screening Levels for Environmental Chemicals, the US Army Center for Health Promotion and Preventive Medicine (USACHPPM) has determined that $200 \mu\text{g}/\text{ft}^2$ is a safe surface contamination level. They have also applied these standards as the decontamination levels for surfaces in administrative offices.

e. It should be noted that levels above these recommendations do not necessarily mean there is a significant hazard to workers who are following good cleaning and hygienic practices since there is no correlation between wipe and air samples. Rather, we recommend these levels as a precautionary measure.

2. The NGB Occupational Health Branch is developing guidance for armories that are used as childcare facilities. All states will receive this guidance when it is completed. In the interim, we recommend the following actions:

a. Clean all areas that will be accessible to children to the EPA dust-lead standard for children 6 years of age or under ($40 \mu\text{g}/\text{ft}^2$ on floors and $250 \mu\text{g}/\text{ft}^2$ on windowsills).

b. Refer to the local authorities' regulations since they can be more stringent than federal regulations.

c. Post signs in the area to inform people of the presence of lead dust and its effects.

d. If soldiers clean weapons in the facility change the policy so that they cannot clean their weapons in the facility, or if they are allowed to clean their weapons indoors, they must clean the area by wet wiping and mopping the area when they are done.

e. If the paint is peeling, contact the state Environmental Office to test for lead content and provide recommendations.

3. Air samples collected on individuals in the armory were well below OSHA's permissible exposure limit for lead (29 CFR 1910.1025(c)) of $0.05 \text{ mg}/\text{m}^3$ averaged over an 8-hour day. Therefore, based on these conditions there is currently no overexposure to personnel from lead dust in this building.

Industrial Hygiene Survey

Vermont Army National Guard (VT ARNG)

Prepared For: NGB ARNG– Region North IH Office

Survey Location:

St. Albans Readiness Center
18 Fairfield Street
St. Albans, VT 05478

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 24, 2011

AEI Project #: J11-601 4L VT St. Albans RC

Non-Responsive, CIH, CSP
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**

Table of Contents

Executive Summary ii

1 Introduction 1

2 Evaluation Methods 1

3 Operations 1

4 Noise Hazards 1

5 Hazard Controls 2

Ventilation Systems 2

6 Physical Condition of the Facility and Personnel Concerns 2

Paint Chip and Dust Wipe Samples for Lead Contamination 2

Visual Inspection for Damaged Asbestos-Containing Materials 3

Visual Inspection for Water Damage and Mold Growth 3

Visual Inspection for Housekeeping Concerns 3

Lighting 3

Indoor Air Quality (IAQ) 4

Temperature and Relative Humidity 4

Carbon Dioxide (CO₂) and Carbon Monoxide (CO) 4

7 Conclusions 5

8 Limitations 5

List of Tables and Appendices

Table 1 - Results of Dust Wipe Sampling for the VT ARNG St. Albans Readiness Center on October 24, 2011.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

Appendix A – Building Layout

Appendix B – Certificates of Analysis for Air, Dust Wipe and Bulk Samples

Appendix C – Photo Documentation

Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) St. Albans Readiness Center located at 18 Fairfield Street, St. Albans, VT 05478. **Non-Responsive**, CIH, CSP performed the evaluation on October 24, 2011. The point of contact for the facility was **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Paint Chip and Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed in the boiler room and on the 2nd floor in a hallway on a painted plaster patch. Bulk paint chip samples were found to contain 0.28% lead by weight in the Boiler Room and 4.8% lead by weight in the 2nd Floor Hallway. The second floor hallway paint chip sample would be considered lead-based by the Environmental Protection Agency (EPA) and State of Vermont definitions (>0.5% by weight). Results of dust wipe samples taken throughout the facility were below the recommended maximum criterion for surface contamination of lead (200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$)) in all areas sampled except for a sample collected on the gray painted window sill in the Drill Hall (11,000 $\mu\text{g}/\text{ft}^2$).

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there were any suspect asbestos-containing material and its condition. Damaged drywall and joint compound was observed on the boiler room ceiling; a crumbling plaster patch was observed in the 2nd Floor hallway; damaged plaster was observed in two offices on the 1st floor (S-4 and Training NCO offices); and damaged green linoleum with black mastic was observed in the Training NCO office. Samples of each damaged material were submitted for asbestos analysis. The EPA defines an asbestos-containing material as one percent (1%) or more asbestos by visual estimation. The damaged drywall and joint compound in the boiler room and the mastic under the green linoleum in the Training NCO Office contained 2% Chrysotile asbestos. No asbestos was detected in the other samples.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or evidence of mold growth was observed on the day of the survey.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping was good.

Lighting: A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in a few areas. The illumination measurements indoors ranged from 2.5 foot candles (fc) to 138 fc.

Indoor Air Quality: Temperature and relative humidity measurements were mostly within the comfort ranges for the winter season on the day of the survey. The outdoor temperature and relative humidity were 59.0° F and 42.1% on the day of monitoring. Indoor concentrations of carbon dioxide (CO₂) and carbon monoxide (CO) were below the guidelines in all areas.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updated MSDSs are required per OSHA 29 CFR 1910.1200. It is recommended that a copy of the written hazard communication program be placed in every MSDS notebook. MSDSs for some new custodial products are required per OSHA 29 CFR 1910.1200. **RAC 4**

Overall, the St. Albans Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) St. Albans Readiness Center located at 18 Fairfield Street, St. Albans, VT 05478. **Non-Responsive**, CIH, CSP performed the evaluation on October 24, 2011. The point of contact for the facility was **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

Construction of the St. Albans Readiness Center was built in 1914. The readiness center is staffed by 14 administrative personnel. The operations conducted at the facility include supply and administrative duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the St. Albans Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) evaluations of operations including operation description, sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the St. Albans facility consist exclusively of supply and administrative duties. No other maintenance of vehicles or other physical tasks are performed at the facility. A small garage exists in the facility basement but it is only used for storage. Ground maintenance and upkeep of the building are the responsibility of the state employed Armorer and not part of the duties of National Guard personnel.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility.

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; potential ergonomic problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were collected in select areas.

Paint Chip and Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed in the boiler room and on a plaster patch in the 2nd Floor hallway. Paint chip samples were submitted to AMA Analytical Services, Inc. of Lanham, MD for lead analysis. The samples were found to contain 0.28% lead by weight in the Boiler Room and 4.8% lead by weight in the 2nd Floor Hallway. The second floor hallway paint chip sample would be considered lead-based by the Environmental Protection Agency (EPA) and State of Vermont definitions (>0.5% by weight). Certificates of analysis are included in Appendix B

To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected using ghost wipes and 10 centimeter (cm) x 10cm templates. The Environmental Protection Agency (EPA) and the State of Vermont limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. All wipe samples collected from the facility were below the recommended maximum except for the sample collected from the gray painted window sill in the Drill Hall (11,000 $\mu\text{g}/\text{ft}^2$). Results are given in Table 1 and certificates of analysis are included in Appendix B.

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
St. Albans Readiness Center on October 24, 2011.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
StA – 01	Drill Hall – floor	<110
StA – 02	Drill Hall – window sill	11,000
StA – 03	Drill Hall – vending machine	<110
StA – 04	Drill Hall – storage locker	<110
StA – 05	Drill Hall – floor	<110
StA – 06	2 nd Floor Stair Platform – floor	<110

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
St. Albans Readiness Center on October 24, 2011.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
StA – 07	Former Firing Range – bullet trap floor	<110
StA – 08	Former Firing Range – exercise bench	<110
StA – 09	Former Firing Range – floor mat	130
StA – 10	Commo Room - desk	<110
StA – 11	Former Firing Range – floor below doorway	<110
StA – 12	Garage – filing cabinet	<110
StA – 13	2 nd Floor – floor	<110
StA – 14	SQDNCO Office – floor	<110
StA – 15	S-1 Office - floor	<110
StA – 16	Basement Kitchen - counter	<110

*The recommended maximum level for adult exposures is 200 $\mu\text{g}/\text{ft}^2$ lead on surfaces.

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). Damaged drywall and joint compound was observed on the boiler room ceiling; a crumbling plaster patch was observed in the 2nd Floor hallway; damaged plaster was observed in two offices on the 1st floor (S-4 and Training NCO offices); and damaged green linoleum with black mastic was observed in the Training NCO office. Samples of each damaged material were submitted to AMA Analytical Services, Inc. of Lanham, MD 20706 (NIST-NVLAP Accreditation No. 101143-0) for analysis by Polarized Light Microscopy (PLM). The EPA defines an asbestos-containing material as one percent (1%) or more asbestos by visual estimation. The damaged drywall and joint compound in the boiler room and the mastic under the green linoleum in the Training NCO Office contained 2% Chrysotile asbestos. No asbestos was detected in the other samples.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or evidence of mold growth was observed on the day of the inspection.

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping was good. Most areas were clean and tidy.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on March 9, 2011, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**

North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in the Drill Hall, the Stairway to the 2nd Floor, The Commo Room in the Basement, the Fitness Room in the Basement, the Custodian's Office and the Boiler Room. The illumination measurements indoors ranged from 2.5 foot candles (fc) to 138 fc. The complete results of the evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Plus Model 8554, factory calibrated in February, 2011. Temperature, relative humidity and carbon dioxide (CO₂) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 2. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30 and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 67.9 to 78.2° F and 36.7 to 45.3% Rh. Temperatures and relative humidity were mostly within the winter comfort ranges in the areas monitored. The outdoor temperature and relative humidity was 59.0° F and 42.1% on the day of monitoring.

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1–2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 462 to 882 parts per million (ppm). CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 0.2 to 1.2 ppm; therefore, concentrations are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

Additional Information

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updated MSDSs are required per OSHA 29 CFR 1910.1200. It is recommended that a copy of the written hazard communication program be placed in every MSDS notebook. MSDSs for some new custodial products are required per OSHA 29 CFR 1910.1200. **RAC 4**

7 Conclusions

The results of the evaluation indicated no concerns with the following at the facility: contamination of clean air sources, water intrusion, noise hazards, visible mold and housekeeping. The results of the evaluation indicated industrial hygiene concerns in the following areas: peeling lead-based paint, accumulated lead-containing dust in one area, the presence of damaged suspect asbestos-containing materials, and lighting. Overall, the St. Albans Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**


9 References

1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.
3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.
4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.
5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2011.
6. Army Regulation (AR) 420-70 Buildings and Structures, 10 October 1997.
7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 28 March 2009.
8. Army Regulation (AR) 420-1 Army Facilities Management, 28 March 2009.
9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.
10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.
12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.
13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".
15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.


Appendix A Building Layout

FORM NO. 7 (10-1-80)
SEE GSA GEN. REG. TITLE (41 CFR) 101-11.6

Hqs & HHC 1-172d Basement Fire Escape Plan




HQs & HHC 1-72d First Floor Fire Escape Plan



FROM: 10 X 10 TO 1 INCH
5TH LINE ACCENTED, 10TH HEAVY

HQ. 2nd FLOOR FIRE ESCAPE PLAN



Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	St. Albans RC	Chain Of Custody:	511730
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	St. Albans, VT	Date Submitted:	11/1/2011
Attention:	Non-Responsive	Job Number:	J11-601	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/7/2011
				Report Date:	11/8/2011

Summary of Atomic Absorption Analysis for Lead

Page 1 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
12010568	StA-Blk-01	Flame	Paint Chip	****	N/A	0.0082 %Pb		0.28 %Pb	
12010572	StA-Blk-04	Flame	Paint Chip	****	N/A	0.0069 %Pb		4.8 %Pb	
12010579	StA-01	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010580	StA-02	Flame	Wipe	****	0.222	54 ug/ft ²	2400	11000 ug/ft ²	
12010581	StA-03	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010582	StA-04	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010583	StA-05	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010584	StA-06	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010585	StA-07	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010586	StA-08	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010587	StA-09	Flame	Wipe	****	0.108	110 ug/ft ²	13	130 ug/ft ²	
12010588	StA-10	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010589	StA-11	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010590	StA-12	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010591	StA-13	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010592	StA-14	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010593	StA-15	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010594	StA-16	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AIHRA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	St. Albans RC	Chain Of Custody:	511730
Address:	301-III Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	St. Albans, VT	Date Submitted:	11/1/2011
Attention:	Non-Responsive	Job Number:	J11-601	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/7/2011
				Report Date:	11/8/2011

Summary of Atomic Absorption Analysis for Lead

Page 2 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	----------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm)
 %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb)

See QC Summary for analytical results of quality control samples associated with these samples.

Note: All samples were received in good condition unless otherwise noted.
 Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Air and Wipe results are not corrected for any blank results
 Final results for air and wipe samples are based on client supplied information nor verified by this laboratory.
 All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Analyst:

Non-Responsive

Technical Manager:

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS

Client:	National Guard Bureau	Job Name:	St. Albans RC	Chain Of Custody:	511730
Address:	301-III Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	St. Albans, VT	Date Analyzed:	11/7/2011
		Job Number:	J11-601	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003		

Attention: Non-Responsive

Page 1 of 2

Summary of Polarized Light Microscopy

AMA Sample Number	Client Sample #	Total Asbestos	Chrysotile Percent	Amosite Percent	Crocidolite Percent	Other Asbestos Percent	Mineral Wool Percent	Fiberglass Percent	Organic Percent	Synthetic Percent	Other Percent	Particulate Percent	Sample Type	Sample Color	Homogeneity	Analyst ID	Comments
12010569	StA-Blk-02	2	2	--	--	--	--	TR	10	--	--	88	DW	Multi	Layered	SW	
12010570	StA-Blk-02	2	2	--	--	--	--	--	TR	--	--	98	JC	White	Homogeneous	SW	
12010571	StA-Blk-03	NAD	--	--	--	--	--	--	TR	--	--	100	PL	White	Homogeneous	SW	
12010573	StA-Blk-05 PL	NAD	--	--	--	--	--	--	TR	--	--	100	PL	White	Homogeneous	SW	
12010574	StA-Blk-05 BC	NAD	--	--	--	--	--	--	TR	--	--	100	BC	Gray	Homogeneous	SW	
12010575	StA-Blk-06 PL	NAD	--	--	--	--	--	--	TR	--	--	100	PL	White	Homogeneous	SW	
12010576	StA-Blk-06 BC	NAD	--	--	--	--	--	--	TR	--	--	100	BC	Gray	Homogeneous	SW	
12010577	StA-Blk-07 FT	NAD	--	--	--	--	--	--	20	--	--	80	FT	Multi	Layered	SW	
12010578	StA-Blk-07 M	2	2	--	--	--	--	--	TR	--	--	98	MS	Black	Homogeneous	SW	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.

An AIHA (#100470), NVLAP (101143-0), and NY ELAP (#10920) Accredited Laboratory



CERTIFICATE OF ANALYSIS

Client:	National Guard Bureau	Job Name:	St. Albans RC	Chain Of Custody:	511730
Address:	301-JH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	St. Albans, VT	Date Analyzed:	11/7/2011
Attention:	Non-Responsive	Job Number:	J11-601	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003		

Summary of Polarized Light Microscopy

AMA Sample Number	Client Sample #	Total Asbestos	Chrysotile Percent	Amosite Percent	Crocidolite Percent	Other Asbestos Percent	Mineral Wool Percent	Fiberglass Percent	Organic Percent	Synthetic Percent	Other Percent	Particulate Percent	Sample Type	Sample Color	Homogeneity	Analyst ID	Comments
-------------------	-----------------	----------------	--------------------	-----------------	---------------------	------------------------	----------------------	--------------------	-----------------	-------------------	---------------	---------------------	-------------	--------------	-------------	------------	----------

The following footnotes only apply to those samples which the total asbestos result is flagged with a note number.

- 1 TEM RECOMMENDATION - Please note, due to resolution limitations with optical microscopy and/or interference from matrix components of this sample, results which are reported via PLM as negative or trace (<1%) for asbestos may contain a significant quantity of asbestos. It is recommended that the additional analytical technique of TEM be used to check for asbestos fibers below the resolution limits of optical microscopy.
- 2 MATRIX REDUCTION RECOMMENDATION - Please note, due to interference from the matrix components of this sample, results which are reported via PLM as negative or trace (<1%) for asbestos may contain a significant quantity of asbestos which is obscured from view. It is recommended that the additional preparation technique of gravimetric reduction be performed on this sample to minimize the obscuring effects of matrix components, followed by reanalysis by PLM and/or TEM.

Analysis Method - EPA/600/R-93/116 dated July 1993

NAD = "No Asbestos Detected" TR = "Trace equals less than 1% of this component"

Uncertainty: For samples containing asbestos in range of 1-10% the CV is 0.43, 11-35% CV=0.55, >35 CV=0.23

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Technical Director

Non-Responsive

Analyst(s)

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



AMA Analytical Services, Inc.
Focused on Results www.amalab.com
AIHA (#100470) NVLAP (#101143-0) NY ELAP (10920)
4475 Forbes Blvd. • Lanham, MD 20706
(301) 459-2640 • (800) 346-0961 • Fax (301) 459-2643

CHAIN OF CUSTODY

(Please Refer To This Number For Inquires)

511730 (2)
page 2/2

Mailing/Billing Information:

1. Client Name: National Guard Bureau
2. Address 1: 301-JH Old Bay Lane
3. Address 2: Attn: NGB AVN-SI, State Military Reservation
4. Address 3: Havre de Grace, Maryland 21078
5. Phone #: (410) 942-0273 Fax #: (410) 942-0254

Submittal Information:

1. Job Name: St Albans RC
2. Job Location: St Albans, VT
3. Job #: 511-601 PO #: W912KG-09-A-0003
4. Contact Person: [Redacted]
5. Submitted By: [Redacted] Signature: [Redacted]

Reporting Information (Results will be provided as soon as technically feasible):

Form with sections: AFTER HOURS (must be pre-scheduled), NORMAL BUSINESS HOURS, REPORT TO: (aria@enviro.com), and various checkboxes for reporting preferences.

Asbestos Analysis

PCM Air - Please Indicate Filter Type:
NIOSH 7400 (QTY)
Fiberglass (QTY)
TEM Air - Please Indicate Filter Type:
AHERA (QTY)
NIOSH 7402 (QTY)
Other (specify) (QTY)
ELM Bulk
EPA 600 - Visual Estimate (QTY)
EPA Point Count (QTY)
NY State Friable 198.1 (QTY)
Grav. Reduction ELAP 198.6 (QTY)
Other (specify) (QTY)
MISC
Vermiculite
Asbestos Soil PLM (Qual) PLM (Quant) PLM/TEM (Qual) PLM/TEM (Quant)

TEM Bulk

ELAP 198.4/Chatfield (QTY)
NY State PLM/TEM (QTY)
Residual Ash (QTY)

TEM Dust

Qual. (pres/abs) Vacuum/Dust (QTY)
Quan. (State) Vacuum D5755-95 (QTY)
Quan. (State) Dust D6-180-99 (QTY)

TEM Water

Qual. (pres/abs) (QTY)
ELAP 198.2/EPA 100.2 (QTY)
EPA 100.1 (QTY)

All samples received in good condition unless otherwise noted.
(TEM Water samples °C)

* Pb Point Chip (QTY)
Pb Dust Wipe (wipe type 10x10, 11 (QTY) (16 total)
Pb Air (QTY)
Pb Soil/Solid (QTY)
Pb TCLP (QTY)
Drinking Water Pb (QTY) Cu (QTY) As (QTY)
Waste Water Pb (QTY) Cu (QTY) As (QTY)
Pb Furnace (Media) (QTY)

Collection Apparatus for Spore Traps/Air Samples:
Collection Media
Spore Trap (QTY) Surface Vacuum Dust (QTY)
Surface Swab (QTY) Culturable ID Grams (Media) (QTY)
Surface Tape (QTY) Culturable ID Spores (Media) (QTY)
Other (Specify) (QTY)

Table with columns: CLIENT ID NUMBER, SAMPLE INFORMATION (LOCATION, DATE, VOLUME, WIPED AREA), ANALYSIS (TEM, PCM, PLM, ELAP, MOLD, AIR, BULK, DUST, MATRICES), and CLIENT CONTACT (LABORATORY STAFF ONLY).

LABORATORY STAFF ONLY: (CUSTODY)

1. Date/Time RCVD: / / @ Via: By (Print):
2. Date/Time Analyzed: / / @ By (Print):
3. Results Reported To: Date: / / Time: Initials:
4. Comments:

[Redacted Signature]

Appendix C Photo Documentation


St. Albans, VT Readiness Center



Lyndonville RC Exterior



Drill Hall



Drill Hall 2




Drill Hall Gray Painted Windows

St. Albans, VT Readiness Center



Drill Hall Gray Painted Windows



Drill Hall 3



Office

Posted to NGB FOIA Reading Room
May, 2018



Office

St. Albans, VT Readiness Center



S-1 Office



Office



2nd Floor



2nd Floor

St. Albans, VT Readiness Center



1st Floor Foyer



Office



Fitness Center - Former Firing Range



Fitness Center - Converted Firing Range

St. Albans, VT Readiness Center



Ceiling of Converted Firing Range



Heating System for Fitness Center



Basement Hallway



Basement Storage Garage

St. Albans, VT Readiness Center



Flammable Storage Cabinet



Custodian's Office



Commo Room

Posted to NGB FOIA Reading Room
May, 2018



Boiler Room

St. Albans, VT Readiness Center



Boiler Room



Damaged Drywall In Boiler Room



Boiler Room



Kitchen

St. Albans, VT Readiness Center



Supply Room

Appendix D
IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	St. Albans	IAQ						Light			
Date	10/24/2011	Inspector	Non-Responsive	Instrument	Q-trak 7565-X						Instrument	Cal-Light 400	
Facility Description	St Albans RC			Serial Number	7565X0839020						Serial Number	K070003	
Weather Conditions	Clear, Cool			Last Calibration	Feb-11						Last Calibration	9-Mar-11	
Location/Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
Drill Hall	1	9:52	70.2		38.9		462		0.6		8-48	X	30-50
SQDNCO Office	1	10:42	70.0		44.6		790		0.7		30-82		30-50
SQDNXO Office	1	10:44	70.2		44.7		819		0.7		38-42		30-50
S-1 Office	1	10:45	70.6		45.3		829		0.3		26-98		30-50
Office	1	10:50	70.6		44.1		799		1.2		50-70		30-50
Hallway	1	10:50									60-78		5
Women's Bathroom	1	10:51									14-38		5
SQDNCSM Office on Second Floor	1	10:52	70.4		43.8		769		0.6		40-48		30-50
Hallway	1	10:55									35-45		5
Operations SGT Major Office	1	10:56	70.7		44.2		848		0.7		20-22		30-50
Stairs to Second Floor	1	10:58	70.1								2.5-50	X	5
Training NCO Office	2	11:04	78.2		36.7		788		0.5		28-60		30-50
Readiness NCO Office	1	11:04									30-60		30-50
S-2 Office	2	11:06	74.5		39.9		882		1.1		30-45		30-50
S-4 Office	1	11:07	73.6		41.1		840		1.0		27-75		30-50
Commo Room	4	11:10	73.0		39.4		632		0.9		7-138	X	30-50
Fitness Room	2	11:13	69.7		39.2		537		1.0		14-50	X	30
Garage	1	11:17	68.1		42.4		495		0.4		7-70	X	30
Custodian Room	2	11:19	67.9	X	45.1		663		0.5		14-76	X	30
Boiler Room	1	11:25	72.2		43.4		651		0.9		3-70	X	30
Kitchen	1	11:29	72.2		38.6		539		0.2		70-100		50
Supply Room	2	11:38	72.7		43.2		672		0.9		30-72		30
Recruitment Office											30-88		30-50
Foyer	2										11-40		10
Outside		11:40	59.0		42.1		426		1.6				

Industrial Hygiene Survey

Vermont Army National Guard (VTARNG)

Prepared For: NGB ARNG– Region North IH Office

Survey Location:

St. Albans Readiness Center
18 Fairfield Street
St. Albans, VT 05478

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 22, 2012

AEI Project #: J12-685 3m VT St. Albans RC

Non-Responsive, CIH, CSP
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**

Table of Contents

Executive Summary ii

1 Introduction 1

2 Evaluation Methods 1

3 Operations 1

4 Noise Hazards 1

5 Hazard Controls 2

Ventilation Systems 2

6 Physical Condition of the Facility and Personnel Concerns 2

Paint Chip and Dust Wipe Samples for Lead Contamination 2

Visual Inspection for Damaged Asbestos-Containing Materials 3

Visual Inspection for Water Damage and Mold Growth 3

Visual Inspection for Housekeeping Concerns 3

Lighting 3

Indoor Air Quality (IAQ) 3

Temperature and Relative Humidity 4

Carbon Dioxide (CO₂) and Carbon Monoxide (CO) 4

7 Conclusions 4

8 Limitations 5

List of Tables and Appendices

Table 1 - Results of Dust Wipe Sampling for the VTARNG St. Albans Readiness Center on October 22, 2012.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

Appendix A – Building Layout

Appendix B – Certificates of Analysis for Air, Dust Wipe and Bulk Samples

Appendix C – Photo Documentation

Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VTARNG) St. Albans Readiness Center located at 18 Fairfield Street, St. Albans, VT 05478. **Non-Responsive**, CIH, CSP performed the evaluation on October 22, 2012. The point of contact for the facility was **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Paint Chip and Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. No peeling paint was observed. Results of dust wipe samples taken throughout the facility were below the recommended maximum criterion for surface contamination of lead (200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$)) in all areas sampled except for samples collected on a heater and a shredder in the Drill Hall (310 - 620 $\mu\text{g}/\text{ft}^2$).

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there were any suspect asbestos-containing material and its condition. No damaged suspect material was observed that was not addressed in the 2011 survey.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or evidence of mold growth was observed on the day of the survey.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping required attention due to dust accumulation most likely associated with renovations in the building.

Lighting: A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in several areas. The illumination measurements indoors ranged from 4 foot candles (fc) to over 1,000 fc.

Indoor Air Quality: Temperature and relative humidity measurements were within the comfort ranges for the winter season on the day of the survey. The outdoor temperature and relative humidity were 62.5° F and 40.1% on the day of monitoring. Indoor concentrations of carbon dioxide (CO_2) and carbon monoxide (CO) were below the guidelines in all areas.

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updated MSDSs are required per OSHA 29 CFR 1910.1200. It is recommended that a copy of the written hazard communication program be placed in every MSDS notebook. MSDSs for custodial products in the caretaker's storage areas are required per OSHA 29 CFR 1910.1200.

Overall, the St. Albans Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VTARNG) St. Albans Readiness Center located at 18 Fairfield Street, St. Albans, VT 05478. **Non-Responsive**, CIH, CSP performed the evaluation on October 22, 2012. The point of contact for the facility was **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

Construction of the St. Albans Readiness Center was built in 1914. Renovations are currently taking place to replace windows and repaint the front walkway rails. The readiness center is staffed by 13 military administrative personnel and one part time civilian caretaker. The operations conducted at the facility include supply and administrative duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the St. Albans Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) evaluations of operations including operation description, sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the St. Albans facility consist exclusively of supply and administrative duties. No other maintenance of vehicles or other physical tasks are performed at the facility. A small garage exists in the facility basement but it is only used for storage. Ground maintenance and upkeep of the building are the responsibility of the state and not part of the duties of National Guard personnel.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility.

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were collected in select areas.

Paint Chip and Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. No peeling paint was observed that was not addressed in the 2011 survey. To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected using ghost wipes and 10 centimeter (cm) x 10cm templets. The Environmental Protection Agency (EPA) and the State of Vermont limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. All wipe samples collected from the facility were below the recommended maximum except for samples collected from a heater and shredder in the Drill Hall (310 - 620 $\mu\text{g}/\text{ft}^2$). Results are given in Table 1 and certificates of analysis are included in Appendix B.

**Table 1 – Results of Dust Wipe Sampling for VTARNG
St. Albans Readiness Center on October 22, 2012.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
StA – W 01	Drill Hall – center of floor	<110
StA – W02	Drill Hall – top of wall unit heater	<110
StA – W03	Drill Hall – floor at end of entrance mat	<110
StA – W04	Drill Hall – dust on heater under new window in back	620
StA – W05	Drill Hall – top of “Secure” shredder	310
StA – W06	Former Firing Range – Fitness Center – weight bench	<110
StA – W07	Former Firing Range – Fitness Center - floor mat	120
StA – W08	Former Firing Range – Fitness Center - bullet trap side floor	<110
StA – W09	Classroom – floor (painted concrete)	<110

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**

**Table 1 – Results of Dust Wipe Sampling for VTARNG
St. Albans Readiness Center on October 22, 2012.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
StA – W10	Kitchen – counter near microwave	<110
StA – W11	Stairs to 2 nd Floor	110
StA – W12	HHT Office – Floor	<110

*The recommended maximum level for adult exposures is 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) lead on surfaces.

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). No damaged suspect material was observed that wasn't addressed in the 2011 survey.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or evidence of mold growth was observed on the day of the inspection.

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping needed improvement to address accumulated dust most likely from current renovations.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on April 16, 2012, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in several areas. The illumination measurements indoors ranged from 4 foot candles (fc) to over 1,000 fc. The complete results of the evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Model 7656X, factory calibrated in March, 2012. Temperature, relative humidity and carbon dioxide (CO₂) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 2. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30 and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 67.9 to 72.5° F and 39.3 to 46.8% Rh. Temperatures and relative humidity were mostly within the winter comfort ranges in the areas monitored. The outdoor temperature and relative humidity was 62.5° F and 40.1% on the day of monitoring.

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1–2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 529 to 727 parts per million (ppm). CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange.

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 0.2 to 1.6 ppm; therefore, concentrations are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

Additional Information

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updated MSDSs are required per OSHA 29 CFR 1910.1200. It is recommended that a copy of the written hazard communication program be placed in every MSDS notebook. MSDSs for custodial products in the caretaker's storage areas are required per OSHA 29 CFR 1910.1200.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**

7 Conclusions

The results of the evaluation indicated few concerns at the facility. Overall, the St. Albans Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.

9 References

1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.
3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.
4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.
5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2011.
6. Army Regulation (AR) 420-70 Buildings and Structures, 11 November 1997.
7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 13 December 2007.
8. Army Regulation (AR) 420-1 Army Facilities Management, 12 February 2008, RAR 24 August 2012.
9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.


**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
St. Albans Readiness Center**


10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.
12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.
13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".
15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.

Appendix A Building Layout

FORM NO. 10-10-1-1000
MAY 1964 (REVISED) (GPO: 1964 O-272)


Hqs & HHC 1-172d Basement Fire Escape Plan





FROM: 10 X 10 TO 1 INCH
5TH LINE ACCENTED, 10TH HEAVY

HQ. 2nd FLOOR FIRE ESCAPE PLAN



Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	St. Albans RC	Chain Of Custody:	514373
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	St. Albans, VT	Date Submitted:	11/2/2012
Attention:	Non-Responsive	Job Number:	J12-685	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/12/2012
				Report Date:	11/12/2012

Summary of Atomic Absorption Analysis for Lead

Page 1 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
13010745	StA-W 01	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010746	StA-W 02	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010747	StA-W 03	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010748	StA-W 04	Flame	Wipe	****	0.250	48 ug/ft ²	150	620 ug/ft ²	
13010749	StA-W 05	Flame	Wipe	****	0.108	110 ug/ft ²	33	310 ug/ft ²	
13010750	StA-W 06	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010751	StA-W 07	Flame	Wipe	****	0.108	110 ug/ft ²	13	120 ug/ft ²	
13010752	StA-W 08	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010753	StA-W 09	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010754	StA-W 10	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010755	StA-W 11	Flame	Wipe	****	0.108	110 ug/ft ²	12	110 ug/ft ²	
13010756	StA-W 12	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	St. Albans RC	Chain Of Custody:	514373
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	St. Albans, VT	Date Submitted:	11/2/2012
Attention:	Non-Responsive	Job Number:	J12-685	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/12/2012
				Report Date:	11/12/2012

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	----------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm)
 %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb)

See QC Summary for analytical results of quality control samples associated with these samples.

Note: All samples were received in good condition unless otherwise noted.
 Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Air and Wipe results are not corrected for any blank results
 Final results for air and wipe samples are based on client supplied information nor verified by this laboratory.

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Analys

Non-Responsive

Technical Manager:

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



AMA Analytical Services, Inc.

Focused on Results www.amalab.com
AIHA (#100470) NVLAP (#101143-0) NY ELAP (10920)
4475 Forbes Blvd. • Lanham, MD 20706
(301) 459-2640 • (800) 346-0961 • Fax (301) 459-2643

BEST AVAILABLE COPY

CHAIN OF CUSTODY

(Please Refer To This
Number For Inquires)

514373

Mailing/Billing Information:

- Client Name: National Guard Bureau
- Address 1: 301-IH Old Bay Lane
- Address 2: Attn: NGB-AVN-SI, State Military Reservation
- Address 3: Havre de Grace, Maryland 21078
- Phone #: (410) 942-0273 Fax #: (410) 942-0254

Submitter Information:

- Job Name: St Albans RC
- Job Location: St Albans, VT
- Job #: 512-685 P.O. #: W912K6-09-A-0003
- Contact Person: **Non-Responsive** @ **Non-Responsive**
- Submitted by: **Non-Responsive** Signature: **Non-Responsive**

Reporting Info (Results provided as soon as technically feasible). If no TAT/Reporting Info is provided, AMA will assign defaults of 5-Day and email/fax to contacts on file.

AFTER HOURS (must be pre-scheduled)		NORMAL BUSINESS HOURS		REPORT TO:	
<input type="checkbox"/> Immediate Date Due: _____	<input type="checkbox"/> 24 Hours Time Due: _____	<input type="checkbox"/> Immediate	<input type="checkbox"/> 3 Day	<input checked="" type="checkbox"/> Include GOC/ID/ETA with Report	<input checked="" type="checkbox"/> Email: Non-Responsive
Comments: _____		<input type="checkbox"/> Next Day	<input checked="" type="checkbox"/> 5 Day + <u>11/9/12</u>	<input checked="" type="checkbox"/> Fax: Non-Responsive	<input type="checkbox"/> Email: <u>ariaenviro.com</u>
		<input type="checkbox"/> 2 Day	Date Due: _____	<input type="checkbox"/> Verbal: Non-Responsive	<input type="checkbox"/> Fax: <u>us.army.mil</u>
					<input type="checkbox"/> Verbal: <u>us.army.mil</u>

Asbestos Analysis

- *PCM Air - Please Indicate Filter Type:
- NIOSH 7400 (QTY)
 - Fiberglass (QTY)
- TEM Air* - Please Indicate Filter Type:
- AHERA (QTY)
 - NIOSH 7402 (QTY)
 - Other (specify _____) (QTY)
- PLM Bulk
- EPA 600 - Visual Estimate (QTY)
 - EPA Point Count (QTY)
 - NY State Friable 198.1 (QTY)
 - Grav. Reduction ELAP 198.6 (QTY)
 - Other (specify _____) (QTY)
- MISC
- Vermiculite
 - Asbestos Soil PLM (Qual) PLM (Quan) PLM/TEM (Qual) PLM/TEM (Quan)

TEM Bulk

- ELAP 198.4/Chatfield (QTY)
- NY State PLM/TEM (QTY)
- Residual Ash (QTY)

TEM Dust*

- Qual. (pres/abs) Vacuum/Dust (QTY)
- Quan. (s/area) Vacuum D5755-95 (QTY)
- Quan. (s/area) Dust D6480-99 (QTY)

TEM Water

- Qual. (pres/abs) (QTY)
- ELAP 198.2/EPA 100.2 (QTY)
- EPA 100.1 (QTY)

All samples received in good condition unless otherwise noted.
(TEM Water samples _____ °C)

If field data sheets are submitted, there is no need to complete bottom section.

Metals Analysis

- Pb Paint Chip (QTY)
- Pb Dust Wipe (wipe type 10x10 cm) (QTY) ghost
- Pb Air (QTY) 1 = 232.2 cm
- Pb Soil/Solid (QTY)
- Pb TCLP (QTY)
- Drinking Water Pb (QTY) Cu (QTY) As (QTY)
- Waste Water Pb (QTY) Cu (QTY) As (QTY)
- Pb Furnace (Media _____) (QTY)

Fungal Analysis

- Collection Apparatus for Spore Traps/Air Samples: _____
- Collection Media _____
- *Spore-Trap (QTY)
 - *Surface Swab (QTY)
 - *Surface Tape (QTY)
 - Other (Specify _____) (QTY)
 - Surface Vacuum Dust (QTY)
 - Culturable ID Genus (Media _____) (QTY)
 - Culturable ID Species (Media _____) (QTY)

CLIENT ID #	SAMPLE INFORMATION SAMPLE LOCATION/ID	DATE/ TIME	VOL (L)/ Wipe Area	ANALYSIS										CLIENT CONTACT (LABORATORY STAFF ONLY)						
				TEM	PCM	PLM	LEAD	MOLD	AIR	BULK	DUST	MATRIX	WATER AND OTHER	SPORE TRAP	TAPE	SWAB	Date/Time:	Contact:	By:	
	SEE ATTACHED FIELD DATA SHEETS																			

LABORATORY STAFF ONLY: (CUSTODY)

Posted to NGB FOIA Reading Room
May, 2018

- Date/Time RCVD: 11/2/12 @ Tedix Via: **Non-Responsive** By: **Non-Responsive**
- Date/Time Analyzed: _____ @ _____ By (Print): _____ Sign: _____
- Results Reported To: 107 222 092 Via: _____ Date: _____ / _____ / _____ Time: _____ Initials: _____

BEST AVAILABLE COPY

FOIA Requested Record #J-15-0085 (VT)

Released by National Guard Bureau

Appendix C Photo Documentation

VT St Albans RC



Drill Hall



Drill Hall




Drill Hall



Storage Room on Drill Hall floor


VT St Albans RC



Stairs to 2nd Floor




2nd Floor Hallway



Office

Posted to NGB FOIA Reading Room
May, 2018



2nd Floor Hallway

BEST AVAILABLE COPY

FOIA Requested Record #J-15-0085 (VT)
Released by National Guard Bureau
Page 934 of 1352

VT St Albans RC



Supply Office



Office



Office



Hallway with copier

VT St Albans RC



Office



Access to attic



Janitor's closet




Janitor's closet

VT St Albans RC



Office



Office



Office

Posted to NGB FOIA Reading Room
May, 2018




Window replacement in progress

VT St Albans RC




Boiler Room



Boiler Room



Peeling paint in Boiler Room



Basement storage

VT St Albans RC



Basement storage window replacement



Clutter in Basement storage



Basement storage

Posted to NGB FOIA Reading Room
May, 2018



Basement Hallway

VT St Albans RC



Kitchen



Conference room



Fitness Center and former range



Caretaker's office

VT St Albans RC



Basement flammable storage cabinets with MSDSs



Bath and shower room in basement



Lockerroom

Posted to NGB FOIA Reading Room
May, 2018



Office

VT St Albans RC



Office



Office suite

Appendix D
IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	St. Albans	IAQ								Light		
Date	10/22/2012	Inspector	Non-Responsible	Instrument	Q-trak 7565-X								Instrument	Cal-Light 400
Facility Description	St. Albans RC			Serial Number	7565X0839019								Serial Number	K070003
Weather Conditions	Cool and sunny			Last Calibration	Mar-12								Last Calibration	16-Apr-12
Location/Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)	
SQDN CO Office	1	1334	71.8		39.3		580		0.3		15-60		30-50	
2nd Floor Center Office	1	1336	72.1		41.2		682		0.3		48-58		30-50	
S-1 Office	5	1338	72.5		41.5		727		0.3		30-100		30-50	
S-3 Office	1	1340	71.8		41.9		679		0.2		30-48		30-50	
SDQN CSM Office	1	1342	71.9		40.2		597		0.4		10-63	X	30-50	
Operation NCO	2	1345	72.3		40.5		646		0.3		30-75		30-50	
2nd Floor Latrine	1	1346									17		5	
1st Floor Janitor's Closet	1	1349	71.6		40.7		569		0.2		80		30	
S4 Large Office	2	1351	71.5		41.1		571		0.2		20-75	X	30-50	
S4 Back Office	1	1352									22-73	X	30-50	
ISG Commander's Office	1	1353									9-68	X	30-50	
S4 Namco Office	1	1353									30-58		30-50	
Basement Boiler Room	1	1355	71.5		42.1		529		0.8		5-110	X	30	
Basement Storage	2	1358	72.0		42.2		583		0.4		40-50		30	
Medical Unit Room	2	1400	72.0		42.9		667		1.6		27-100	X	30	
Kitchen	2	1401	71.8		41.7		554		0.3		39-120	X	50	
Supply Room	4	1402	71.0		43.4		582		0.6		30-70		30	
Classroom/Conference Room	2	1404	71.1		43.3		563		0.2		4-82	X	30-50	
Fitness Center	2	1404	70.7		45.3		617		0.2		14-36	X	30	
Caretaker Office/Storage	1	1405	69.5		46.8		629		0.4		11-56	X	30	
Storage Area	2	1408	67.9	X	46.0		529		0.3		11-54	X	30	
Locker Room	2	1410									50-90		7	
Latrine	2	1410									50-90		5	
SDQN Recruiter 1	2	1411									13-75	X	30-50	
SDQN Recruiter 2	1	1411									30-75		30-50	
AAT Office	2	1412	69.8		44.8		642		0.2		23-75	X	30-50	
Drill Hall	3	1413									20->1000	X	50	
Outside		1003	62.5		40.1		375		0.9					

Shaw Environmental, Inc.

312 Directors Drive
Knoxville, TN 37923
865.690.3211
Fax 865.690.3626



**National Guard Armory
Swanton Readiness Center – Swanton, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

22 March 2004

**National Guard Armory
Swanton Readiness Center – Swanton, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

22 March 2004

Prepared by:

Non-Responsive

Industrial Hygienist

Reviewed by:

Non-Responsive

Business Line Manager

Table of Contents

<i>Table of Contents</i>	<i>i</i>
<i>List of Tables</i>	<i>ii</i>
<i>List of Appendices</i>	<i>ii</i>
<i>Executive Summary</i>	<i>i-1</i>
<i>1.0 Introduction</i>	<i>1-1</i>
<i>2.0 Findings, Discussion, and Interpretation of Results</i>	<i>2-1</i>
<i>2.1 Sampling for Lead</i>	<i>2-1</i>
<i>2.1.1 Wipe Sampling</i>	<i>2-1</i>
<i>2.1.2 Air Sampling for Lead</i>	<i>2-2</i>
<i>2.2 Physical Condition of Facility</i>	<i>2-2</i>
<i>2.2.1 Peeling Paint - Lead</i>	<i>2-2</i>
<i>2.2.2 Visual Inspection - Asbestos</i>	<i>2-2</i>
<i>2.2.3 Visual Inspection - Water Damage and Mold</i>	<i>2-3</i>
<i>2.2.4 Visual Inspection - Housekeeping</i>	<i>2-3</i>
<i>2.3 Building Concerns</i>	<i>2-3</i>
<i>2.3.1 Ergonomic Concerns</i>	<i>2-3</i>
<i>2.3.2 Indoor Air Quality</i>	<i>2-3</i>
<i>2.4 Safety and Industrial Hygiene Programs</i>	<i>2-3</i>
<i>2.5 Ventilation</i>	<i>2-4</i>
<i>2.5.1 Ventilation System Evaluation</i>	<i>2-4</i>
<i>2.5.2 Contamination of Clean Air Sources</i>	<i>2-4</i>
<i>2.6 Noise Exposure</i>	<i>2-4</i>
<i>2.7 Lighting</i>	<i>2-4</i>
<i>2.8 Converted Indoor Firing Ranges</i>	<i>2-4</i>
<i>2.9 HVAC Systems</i>	<i>2-5</i>
<i>2.10 IHIM</i>	<i>2-5</i>
<i>3.0 Conclusions</i>	<i>3-1</i>
<i>Tables</i>	<i>Follows Section 3.0</i>
<i>Appendices</i>	<i>Follows Tables</i>

List of Tables

Table 1	Wipe Sampling for Lead
Table 2	Air Sampling for Lead
Table 3	Indoor Air Quality Measurements
Table 4	Illumination Readings
Table 5	Indoor Firing Ranges – Wipe Sampling

List of Appendices

Appendix A	IIIM Data Form
Appendix B	Building Layout
Appendix C	Sampling Sheets and Laboratory Analyses
Appendix D	References
Appendix E	Recommendations for Surface Lead Dust in Armories

Executive Summary

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Swanton Readiness Center in Swanton, Vermont. **Non-Responsive** performed the evaluation on 15 July 2003 and 9 October 2003. The point of contact at the readiness center was SSG **Non-Responsive**

The following industrial hygiene concerns were evaluated.

- Wipe Sampling for Lead
- Air Sampling for Lead
- Peeling Paint – Lead
- Suspected Asbestos Containing Material
- Water Damage
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Indoor Air Quality
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- Lighting
- Converted Indoor Firing Range
- HVAC Systems

The following items were either not applicable to the armory or the evaluation resulted in a conclusion that there were no industrial hygiene concerns.

- Air Sampling for Lead
- Peeling Paint – Lead
- Presence of Mold
- Water Damage
- Housekeeping
- Ergonomic Concerns

- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- Converted Indoor Firing Range
- HVAC Systems

Areas where there were industrial hygiene concerns are as follows:

- Wipe sampling for lead revealed concentrations above the recommended level at two locations in the assembly/drill hall. It is recommended that these surfaces and the areas immediately around these surfaces be thoroughly cleaned to reduce the lead level. In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.
- Wipe sampling for lead revealed concentrations above a level of 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) in the assembly hall, the Medic Office, and the storage room in the converted firing range. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.
- Materials suspected of containing asbestos were observed. An operations and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.
- Indoor air quality measurements revealed that the humidity at the armory exceeded the recommended levels. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory.
- Lighting measurements were conducted at the armory. The lighting did not meet minimum requirements in some areas; therefore consideration should be given to providing more lighting in these areas. This may be accomplished by replacing burnt out luminaires, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

1.0 Introduction

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Swanton Readiness Center in Swanton, Vermont. **Non-Responsive** performed the evaluation on 15 July 2003 and 9 October 2003. The point of contact at the readiness center was SSG **Non-Responsive**

The findings, discussion, and interpretation of results are provided in Section 2.0. The conclusions are provided in Section 3.0. The HHIM data form for the facility is provided in Appendix A. The building layout is provided in Appendix B. Sampling sheets and laboratory analyses are provided in Appendix C. References are provided in Appendix D. The *Recommendations for Surface Lead Dust in Armories* document is provided in Appendix E.

The statements, opinions, and conclusions contained in this report are based solely upon the services performed by Shaw as described in the report. In performing these services and preparing the report, Shaw Environmental, Inc. relied upon the work and information provided by others, including public agencies, whose information is not guaranteed by Shaw Environmental, Inc.

2.0 Findings, Discussion, and Interpretation of Results

The results, discussion, and interpretation of results are provided in the following sections.

2.1. Sampling for Lead

2.1.1 Wipe Sampling

Wipe samples were collected for lead from the drill floor/assembly area. Also, wipe samples were collected for lead in rooms, hallways, foyers, etc. The sampling in rooms, hallways, foyers, etc. represented approximately 25% of the building. Approximately half of the samples were collected from surfaces in common areas, such as surfaces of a desk. The remaining samples were collected from uncommon surface areas, such as a supply vent or the top of a file cabinet. The samples were collected and analyzed in accordance with the Instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

The only samples initially submitted for analysis were those from the drill floor/assembly hall. If there were any positive results from the drill floor, the other samples would be submitted for analysis.

Results of the wipe sampling are provided in Table 1. The results revealed lead at all locations sampled at concentrations below recommended level of 200 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$) (See Appendix B) except at two locations. The sample obtained from the top of the heater unit flap surface (adjacent to the classroom) in the assembly/drill hall had a lead concentration of 440 $\mu\text{g}/\text{ft}^2$. The sample obtained from heater unit flap surface (adjacent to the lobby) in the assembly/drill hall had a lead concentration of 290 $\mu\text{g}/\text{ft}^2$. It is recommended that these surfaces and the immediate areas around the surfaces be thoroughly cleaned to reduce the lead level to below 200 $\mu\text{g}/\text{ft}^2$. For guidance on the proper method of cleaning, please refer to NG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.

In addition, wipe sampling for lead revealed concentrations above a level of 40 $\mu\text{g}/\text{ft}^2$ in the assembly hall, the Medic Office, and the storage room in the converted firing range. Please note that the *Recommendations for Surface Lead Dust in Armories* (Appendix E) states that all areas should be cleaned that will be accessible to children. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.

2.1.2 Air Sampling for Lead

Breathing zone air sampling was conducted on one (1) full-time building occupant. (Please note that no state employees were monitored.) The sample was collected and analyzed in accordance with Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods.

The results of the sampling are provided in Table 2. The results revealed non-detectable concentrations of lead in the breathing zone of the employee; therefore, no actions are necessary.

2.2 Physical Condition of Facility

2.2.1 Peeling Paint - Lead

Peeling paint was not observed at the armory; therefore, bulk samples for lead in paint were not taken.

2.2.2 Visual Inspection - Asbestos

A visual inspection was made to determine if there was any suspected asbestos-containing material at the armory. Materials suspected of containing asbestos were observed. The suspected asbestos-containing material were floor tiles in the three front offices adjacent to the lobby (approximately 577 square feet), and insulation in the boiler room (approximately 9 linear feet). The condition of the floor tiles materials was considered good since there was no damage to the tiles. The condition of the boiler room insulation materials was considered good (no rips, tears, or other damage).

An operation and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.

2.2.3 Visual Inspection – Water Damage and Mold

A visual inspection was made to determine if there was any water damage or visible mold at the armory. The inspection did not reveal any water damage or visible mold.

2.2.4 Visual Inspection - Housekeeping

The housekeeping was determined to be good.

2.3. Building Concerns

2.3.1 Ergonomic Concerns

Interviews with employees and observation of work activities revealed no ergonomic concerns at the armory.

2.3.2 Indoor Air Quality

Interviews with employees revealed no indoor air quality concerns at the armory. However, measurements for humidity revealed that levels exceeded the American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommended level of 60% in the armory. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory.

The results of the measurements for carbon dioxide, humidity, and temperature are provided in Table 3.

2.4. Safety and Industrial Hygiene Programs

An evaluation was performed to determine the applicability of the following programs.

- Confined Spaces
- Hearing Conservation
- Respiratory Protection
- Hazard Communication (HAZCOM)
- Personal Protective Equipment (PPE)

It was determined that none of the programs were applicable at the armory.

2.5. Ventilation

2.5.1 Ventilation System Evaluation

There were no local exhaust ventilation systems at this armory; therefore, no ventilation studies were performed.

2.5.2 Contamination of Clean Air Sources

Since there were no local exhaust ventilation systems at the armory, there was no possibility that clean air sources could be contaminated by exhaust air.

2.6. Noise Exposure

An evaluation was performed to determine if there were any hazardous noise areas at the armory. It was determined that there were no areas at the armory that would exceed the permissible exposure limit for noise.

2.7 Lighting

Lighting measurements were conducted at the armory. Results of the lighting evaluation are provided in Table 5. As can be seen from the results, the lighting did not meet the minimum requirements in some areas, including the Women's Latrine, Scout Office, Locker Room, PLT Office, Classroom, and Training Center Office.

Consideration should be given to providing more lighting to the areas listed above. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

2.8. Converted Indoor Firing Ranges

There was a converted indoor firing range at the facility; therefore, wipe samples were taken for lead at various locations in or near the converted range. The only remnant of the former firing range was the bullet trap area. This area was converted into storage rooms. The results are provided in Table 5. The results revealed lead, with associated concentrations, at the following locations:

- floor at 120 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$); and
- stored item (shelf top) at $< 180 \mu\text{g}/\text{ft}^2$.

The lead levels were below the recommended level of 200 $\mu\text{g}/\text{ft}^2$, a level recommended in the *Guidelines for Converting Indoor Firing Ranges to Other Uses* document (Department of Army), therefore, no actions are necessary.

2.9. HVAC System

There was not a HVAC system at the armory.

2.10. HHIM

A Health Hazard Information Module (HHIM) form was completed for the armory. The completed form is provided in Appendix A.

3.0 Conclusions

It is concluded that there were no industrial hygiene concerns at the armory with regards to atmospheric exposure to lead, peeling lead-based paint, visible mold, water damage, housekeeping, ergonomic conditions, safety and industrial hygiene programs, ventilation systems or contamination of clean air sources, noise exposure, surface lead contamination in the converted firing range, and HVAC systems.

There were industrial hygiene concerns at the armory with regards to lead surface contamination, suspected asbestos-containing material, indoor air quality, and lighting. These concerns are discussed in detail in Section 2.0 of this report.

TABLES

Table 1
Wipe Sampling for Lead
National Guard Armory
Swanton, Vermont
Dates of Sampling: 15 July 2003 and 9 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTSWA196-1	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTSWA196-2	Drill Floor - On Floor (See Building Layout - Appendix B)	110
VTSWA196-3	Drill Floor - On Floor (See Building Layout - Appendix B)	110
VTSWA196-4	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTSWA196-5	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTSWA196-6	Field Blank	< 12 μg
VTSWA196-9	Kitchen - cabinet top	8.7
VTSWA196-10	Medic Office - shelf top	68
VTSWA196-11	Administrative Office - desktop	10
VTSWA196-12	Field Blank	< 0.3 μg
VTSWA196-13	Classroom - heater vent top surface	9
VTSWA196-14	Training Center - desktop	2.8
VTSWA283-1	Assembly Room - soda machine top surface (See Building Layout - Appendix B)	36
VTSWA283-2	Assembly Room - fire alarm control box top surface (See Building Layout - Appendix B)	160
VTSWA283-3	Assembly Room - heater unit flap surface (adjacent to classroom) (See Building Layout - Appendix B)	440
VTSWA283-4	Assembly Room - locker top surface (See Building Layout Appendix B)	120
VTSWA283-1	Assembly Room - heater unit flap surface (adjacent to lobby) (See Building Layout - Appendix B)	290
VTSWA283-6	Field Blank	< 0.3 μg

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of Army National Guard Armories* procedure.

In armories that do not contain childcare facilities, the NGB Region North Industrial Hygiene Office recommends cleaning the areas with lead concentrations greater than 200 $\mu\text{g}/\text{ft}^2$.

Table 2
Breathing Zone Air Samples for Lead
National Guard Armory
Swanton, Vermont
Date of Sampling: 15 July 2003

Sample Number	Employee	Sampling Information			Results (mg/m ³) ^a
		Time Sampled / Minutes	Flow Rate (lpm) ^b	Volume (liters)	
VTSWA196-A1	Non-Responsive	0838-0938/60	2.4874	149.24	<0.007
VTSWA196-A2	Field Blank	-	-	-	None Detected

^a Milligrams lead per cubic meter of air.

^b Liters of air per minute.

Only one employee was sampled because there were no other employees at the armory on the date of the survey.

Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods was followed for sampling for lead.

Table 3
Indoor Air Quality Measurements for Carbon Dioxide, Humidity, and Temperature
National Guard Armory
Swanton, Vermont
Date of Sampling: 15 July 2003

Location	Occupants in Area	Carbon Dioxide, parts per million parts of air (ppm)	Percent (%) Humidity	Temperature (°F)
1 st Floor – Training Center Office	3	395	67.0	75.7
Outdoors	0	362	33.7	81.3

Carbon dioxide, humidity, and temperature measurements were taken with a TSI Q Trak Plus, Model 8554, Indoor Air Quality Meter, calibrated in April 2003.

American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommends that indoor carbon dioxide levels be less than 700 ppm above outdoor levels.

ASHRAE recommends that the relative humidity levels be maintained between 30 to 60 percent.

ASHRAE recommends that the acceptable temperature range be 68 degrees Fahrenheit to 74 degrees Fahrenheit in the winter and 73 degrees Fahrenheit to 79 degrees Fahrenheit in the summer.

Table 4
Illumination Readings
National Guard Armory
Swanton, Vermont
Date of Sampling: 15 July 2003

Location	Luminance (fc) ^a	Standard (fc) ^a	Standard Met
Kitchen	42.3-76.8	70	Some areas
Women's Latrine	1.4-20.9	40	No
Scouts Locker Room	26.1-55.3	40	Some areas
Scout Office	18.5-39.1	70	No
Locker Room	12.1-38.5	40	No
PLT Office	29.6-38.9	70	No
Classroom	29.5-58.9	70	No
Locker Room/Mortor	32.1-62.5	40	Some areas
Storage Room 1	26.5-63.4	30	Some areas
Storage Room 2	15.2-46.3	30	Some areas
Training Center Office	27.1-64.3	70	No

^a fc - Footcandles

The readings were taken with a Cooke Corporation cal-LIGHT 400 Calibrated Precision Lightmeter, calibrated on 19 Aug 2002.

The standards listed above are from Design Guide DG-415-2, Logistics Facilities, published by the National Guard Bureau Installation Division.

Table 5
Wipe Sampling for Lead – Converted Firing Range
National Guard Armory
Swanton, Vermont
Date of Sampling: 15 July 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTSWA196-7	Stored Item shelf top	< 180
VTSWA196-8	Floor	120

^aMicrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of Army National Guard Armories* procedure.

Appendix A

HHIM Data Form(s)

HEALTH HAZARD INFORMATION MODULE: INDUSTRIAL HYGIENE SURVEY

(For use of this form, see HHIM User's Guide)

SECTION 1. DEMOGRAPHIC DATA

RLOC		INSTALLATION Swanton Army Vermont ARNG		BLDG/RM NO. Swanton	
LOCATION/CODE Administrative Areas/AA			OPERATION/CODE Administrative OP/ADO		
SURVEY DATE 15 July 2003			EVALUATOR (Initials) Non-Responsive		
MACOM/CODE ARMY NATIONAL GUARD		SUBMACOM/CODE XX		SUPERVISOR Non-Responsive SSG	
TELEPHONE/DSN NO. 802-868-3887		UNIT/ORGANIZATION Company E 1st Battalion		RAC 04	FREQUENCY (hrs/day) 8
NO. CIV(S) 1	NO. MIL 3	NO. CONTRACTOR(S) 0	NO. LOC(S) 0	NO. OTHER 0	

SECTION 2. FACILITY DATA

FAB HOODS 0		VAPOR DEGREASERS 0		SPRAY BOOTHS 0	
MAINTENANCE BAYS 0		OPEN SURFACE TANKS 0		VENTILATION UNITS 0	

SECTION 3. SURVEY DATA

CONTROLS PRESENT	EVALUATION	UNIT CODE	CONTROLS REQUIRED	STATUS

PERSONAL PROTECTIVE EQUIPMENT (R = Required; U = Utilized)

GLOVES	R	U	RESPIRATOR	NOSH TC NO.	MANUFACTURER	R	U
ACID			AIRLINE				
COLD SURFACES			ABRASIVE BLASTING HOOD				
HOT SURFACES			DISPOSABLE				
NBC AGENTS			FULL FACE AIR PURIFYING				
OIL			1/2 FACE AIR PURIFYING				
SOLVENTS			POWERED AIR PURIFYING				
SURGICAL GLOVES			1/4 FACE AIR PURIFYING				
			SELF CONTAINED				

EYES/FACE	R	U	HEARING	R	U	BODY	R	U	HEAD/FIT	R	U
CHEMICAL SPLASH			CANAL CAPS			APRONS			COLD WEATHER BOOTS/HATS		
FULL FACE SHIELD			EAR PLUGS			COLD WEATHER CLOTHING			HARD HATS		
CHEMICAL/SAFETY			HELMETS			COVERALLS			IMPERMEABLE BOOTS		
SAFETY/IMPACT			MUFFS			FULL BODY SUIT			SAFETY/CONDUCTIVE SHOES		
WELDING HELMET			MUFF/EARPLUG COMBO			HEAT REFLECTIVE VEST/SUIT			SAFETY/NON-CONDUCTIVE SHOES		
			HEARING AID/W/ TIME LIMIT			SAFETY BELT/HARNES					

SECTION 4. HAZARD INVENTORY DATA

CAS CODE	HAZARD DESCRIPTION	PAC	EPC
POVDTXXX	Video Display Terminal	3-low	Uncontrolled D Physical
7439-92-1	Lead, Inorganic dusts and fumes, 25 ^{Pb}	2-moderate	Uncontrolled C Respiratory
1332-21-4	Asbestos (other)	2-moderate	Uncontrolled C Respiratory

SECTION 5. PERSONNEL DATA

LAST NAME	FIRST NAME	MI	SEX	SEN	CATEGORY
Non-Responsive				Non-Responsive	ML
				Non-Responsive	ML
				Non-Responsive	ML
				Non-Responsive	CU

SECTION 6. COMMENTS

No comments

See attached sheet

Survey conducted by Nichole Sewan, Pawling, contains 3 military full time staff and 1 civilian employee. Employees perform mainly administrative tasks.

PRIVACY ACT STATEMENT

Title 5 US Code, Section 301; Executive Order 9397 authorizes the use of your Social Security Number as an identification number. The purpose of this information is to identify and monitor data relating each DA civilian and military employee exposed to a hazardous workplace or operation. The use of this information is to provide histories of exposures for any given worker.


Disclosure of your Social Security Number is not mandatory; however, nondisclosures may result in untimely provision of proper medical monitoring.

Appendix B


Building Layout

DRIVEWAY

FERRIS STREET



○ Sample date: 15 July 08
 △ Sample date: 9 October 08



Appendix C

Sampling Sheets and Laboratory Analyses

CERTIFICATE OF ANALYSIS

Posted to NGB FOIA Reading Room
May, 2018

Client: National Guard Bureau
Address: 301-4th Old Bay Lane, Aftt: NGB-AVN-SL
State Military Reservation
Havre de Grace, Maryland 21078

Job Name: VTSWA196
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01

Chain of Custody: 115806
Date Analyzed: 8/5/2003

Person Submitting: [Redacted]
Report Date: 05-Aug-03

Attention: [Redacted]

Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0359456	VTSWA196-1	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359457	VTSWA196-2	Flame	Wipe	****	0.111	108.00 ug/ft ²	110 ug/ft ²	
0359458	VTSWA196-3	Flame	Wipe	****	0.111	108.00 ug/ft ²	110 ug/ft ²	
0359459	VTSWA196-4	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359460	VTSWA196-5	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359461	VTSWA196-6	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0359462	VTSWA196-7	Flame	Wipe	****	0.111	188.00 ug/ft ²	< 180 ug/ft ²	
0359463	VTSWA196-8	Flame	Wipe	****	0.111	108.00 ug/ft ²	120 ug/ft ²	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/IR-93/200(M)-7420; Water: SM-3111B

Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids: EPA 600/IR-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per million (ppm)

ppb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] Non-Responsive

Technical Manager: [Redacted] Non-Responsive

Released by National Guard Bureau
Record #J-15-0085 (VT)

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, no report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the conditions that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the person submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AMERA air samples.

All rights reserved. AMA Analytical Services, Inc.

Client: National Guard Bureau
 Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation
 Havre de Grace, Maryland 21078
 Job Name: VTSWA283
 Job Location: Not Provided
 Job Number: Not Provided
 P.O. Number: 0701

Chain Of Custody: 118719
 Date Analyzed: 10/21/2003
 Person Submitting: [Redacted]
 Report Date: 21-Oct-03

Attention: [Redacted] Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0402922	VTSWA283-1	Furnace	Wipe	****	0.111	13.50 ug/ft ²	36 ug/ft ²	
0402923	VTSWA283-2	Furnace	Wipe	****	0.111	67.51 ug/ft ²	160 ug/ft ²	
0402924	VTSWA283-3	Furnace	Wipe	****	0.111	67.51 ug/ft ²	440 ug/ft ²	
0402925	VTSWA283-4	Furnace	Wipe	****	0.111	67.51 ug/ft ²	120 ug/ft ²	
0402926	VTSWA283-5	Furnace	Wipe	****	0.111	67.51 ug/ft ²	290 ug/ft ²	
0402927	VTSWA283-6	Furnace	Wipe Blank	****	N/A	0.30 ug	< 0.3 ug	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B
 N/A = Not Applicable mg/kg = parts per million (ppm) by weight mg/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] Technical Manager: [Redacted]

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

All rights reserved. AMA Analytical Services, Inc.

An AIHA (#8863), NVLAP (#101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau **Job Name:** VTSWA196 **Chain Of Custody:** 118930
Address: 301-H Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation **Job Location:** Not Provided **Date Analyzed:** 10/30/2003
Attention: Havre de Grace, Maryland 21078 **Job Number:** Not Provided **Person Submitting:** [Redacted]
P.O. Number: Not Provided **Report Date:** 05-Nov-03

Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0404827	VTSWA196-9	Furnace	Wipe	****	0.111	2.70 ug/ft ²	8.7 ug/ft ²	
0404828	VTSWA196-10	Furnace	Wipe	****	0.111	13.50 ug/ft ²	68 ug/ft ²	
0404829	VTSWA196-11	Furnace	Wipe	****	0.111	2.70 ug/ft ²	10 ug/ft ²	
0404830	VTSWA196-12	Furnace	Wipe Blank	****	N/A	0.30 ug	< 0.3 ug	
0404831	VTSWA196-13	Furnace	Wipe	****	0.111	2.70 ug/ft ²	9 ug/ft ²	
0404832	VTSWA196-14	Furnace	Wipe	****	0.111	2.70 ug/ft ²	2.8 ug/ft ²	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst:

Technical Manager:

Non-Responsive

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.



Submitted To: **Non-Responsive**

Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

Reference Data:

Lead

Client Sample No.:	VTCAM205-A1 through VTAAS204-A3
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Filter
Method Reference:	NIOSH 7300
DCL Set ID No.:	03-S-3621
DCL Sample ID No.:	03-22309 through 03-22345
Sample Receipt Date:	7/28/2003
Preparation Date:	07/29/03
Analysis Date:	07/31/03

The samples were prepared and analyzed in accordance with NIOSH method 7300 using a Perkin Elmer 3000XL ICP.

The sample condition upon receipt was acceptable except where noted.

The results are in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive



Analyst

Non-Responsive



CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 280-8071, FAX 415 893-9469

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTCAM205-A1	03-22309	407.54	ND	<0.002
VTCAM205-A2	03-22310	377.66	ND	<0.003
VTCAM205-A3	03-22311	0	ND	-
VTWIN202-A1	03-22313	152.91	ND	<0.007
VTWIN202-A2	03-22314	0	ND	-
VTENO196-A1	03-22316	150.55	ND	<0.007
VTENO196-A2	03-22317	0	ND	-
VTWIL197-A1	03-22319	199.78	ND	<0.005
	Prep Blank 1		ND	
% Recovery	LCS 1		96.	
% Recovery	LCS 2		96.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).
LCS = laboratory control sample.

Non-Responsive



Analyst

Non-Responsive



Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTWIL197-A2	03-22320	149.76	ND	<0.007
VTWIL197-A3	03-22321	0	ND	-
VTSWA196-A1	03-22322	149.24	ND	<0.007
VTSWA196-A2	03-22323	0	ND	-
VTSTA196-A1	03-22324	165.20	ND	<0.006
VTSTA196-A2	03-22325	151.74	ND	<0.007
VTSTA196-A3	03-22326	0	ND	-
VTWAT203-A1	03-22328	194.90	ND	<0.005
VTWAT203-A2	03-22329	0	ND	-
VTGOS202-A1	03-22332	175.30	ND	<0.006
VTGOS202-A2	03-22333	0	ND	-
VTMOR203-A1	03-22335	346.43	ND	<0.003
VTMOR203-A2	03-22336	348.65	ND	<0.003
VTMOR203-A3	03-22337	0	ND	-
VTGRE197-A1	03-22340	240.55	ND	<0.004
VTGRE197-A2	03-22341	250.76	ND	<0.004
VTGRE197-A3	03-22342	0	ND	-
VTAAS209-A1	03-22343	748.92	ND	<0.001
VTAAS209-A2	03-22344	507.55	ND	<0.002
VTAAS209-A3	03-22345	0	ND	-
	Prep Blank 2		ND	
% Recovery	LCS 3		96.	
% Recovery	LCS 4		95.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).
LCS = laboratory control sample.

Non-Responsive



Analyst

Non-Responsive



Industrial Hygiene Sampling Calculation Worksheet

National Guard Armory **Location:** **SWA**
Date: 196

Sample 1

Sample Number: VTSWA196-A1

Pump: 647615

	Pre Flow Rate	Post Flow Rate
	2.526	2.448
	2.52	2.458
	2.523	2.448
	2.518	2.458
Average	2.522	2.453

Average Pre and Post **2.4874**

Time 1 **8:38**

Time 2 **9:38**

Total Time Sampled **1:00**

Minutes Sampled **60.00**

Volume **149.24 Liters**

Sample 2

Sample Number: N/A

Pump: N/A

	Pre Flow Rate	Post Flow Rate
	N/A	N/A
Average	N/A	N/A

Average Pre and Post **N/A**

Time 1 **N/A**

Time 2 **N/A**

Total Time Sampled **N/A**

Minutes Sampled **N/A**

Volume **N/A** **Liters**

Industrial Hygiene Sampling Calculation Worksheet

National Guard Armory

Location: Swanton

Date: 7/15/03

Sample 1

Sample Number: VT SWA196-F1

Pump: 647615

Pre Flow Rate	Post Flow Rate
2526	2448
2520	2458
2523	2448
<u>2518</u>	<u>2458</u>
2522	2453

Average

Average Pre and Post

Time 1 833

Time 2 938

Total Time Sampled

Minutes Sampled

Volume

Liters

Sample 2

Sample Number:

Pump:

Pre Flow Rate

Post Flow Rate

Average

Average Pre and Post

Time 1

Time 2

Total Time Sampled

Minutes Sampled

Volume

Liters

Appendix D

References

References

Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration (current edition)

American Society of Heating, Refrigerating and Air-Conditioning Engineers, Inc (ASHRAE) 62-2002, Ventilation for Acceptable Indoor Air Quality

Instructions for Completing the Sampling of Army National Guard Armories, Lead Wipe Sampling Procedure included with the Request for Proposal

Air Sampling for Lead - Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods

Design Guide DG-415-2, Logistics Facilities, National Guard Bureau Installation Division, 14 December 1999

Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998

Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, 15 October 1990

AR 385-10, The Army Safety Program, 29 February 2000

Department of the Army Pamphlet (DA PAM) 40-501, Medical Services, Hearing Conservation Program, 10 December 1998

DA PAM 40-503, Medical Services, Industrial Hygiene Program, 30 October 2000

Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH) (current edition)

Guidelines for Converting Indoor Firing Ranges to Other Uses, Headquarters, Department of the Army and the Air Force, NG PAM (AR) 385-16/ANGPAM 91-101, 31 January 1994

24 CFR, Part 35, Subpart B, Section 35-110, Definition of Lead-Based Paint, Housing and Urban Development, U. S. Department of Housing

Appendix E
Recommendations for
Surface Lead Dust in Armories

Subject: Recommendations for Surface Lead Dust in Armories

1. In armories that do not contain childcare facilities, the National Guard Bureau (NGB) Region North Industrial Hygiene Office recommends cleaning the areas in which sample results are greater than 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$). If a special function will be held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function. This guidance is based on professional judgment, risk assessments, adaptation of Occupational Safety and Health Administration (OSHA) guidance, and feasibility of cleaning to a certain level.

a. Environmental Protection Agency (EPA) standards (40 Code of Federal Regulations (CFR) 745.227(h)(3)) are not directly applicable because they are criteria for dust-lead hazards developed for floors ($40 \mu\text{g}/\text{ft}^2$) and windowsills ($250 \mu\text{g}/\text{ft}^2$) in residential dwellings and child occupied facilities. A child occupied facility is defined as a building, or portion of a building, constructed prior to 1978, visited regularly by the same child, 6 years of age or under, on at least two different days within any week (Sunday through Saturday period), provided that each day's visit lasts at least 3 hours and the combined weekly visit lasts at least 6 hours, and the combined annual visits last at least 60 hours. Most of the wipe samples in armories were collected in undisturbed areas and therefore, results are worst case scenarios and do not correlate to these standards.

b. OSHA has no specific requirement for work area surfaces. The lead standard (29 CFR 1910.1025(h)) states that all surfaces shall be maintained as free as practicable of accumulations of lead dust. In workplaces where lead dust is generated, surface levels may be much higher, but personnel exposures can be controlled by limiting airborne lead levels and following good cleanup and hygienic practices.

c. OSHA used to cite a level of $200 \mu\text{g}/\text{ft}^2$ in their Technical Manual and 29 CFR 1926.62 as guidance to its own inspectors for evaluating the cleanliness of lunchroom and locker room surfaces that are supposed to be kept as clean as possible.

d. In a report titled Derivation of Wipe Surface Screening Levels for Environmental Chemicals, the US Army Center for Health Promotion and Preventive Medicine (USACIIPPM) has determined that $200 \mu\text{g}/\text{ft}^2$ is a safe surface contamination level. They have also applied these standards as the decontamination levels for surfaces in administrative offices.

e. It should be noted that levels above these recommendations do not necessarily mean there is a significant hazard to workers who are following good cleaning and hygienic practices since there is no correlation between wipe and air samples. Rather, we recommend these levels as a precautionary measure.

2. The NGB Occupational Health Branch is developing guidance for armories that are used as childcare facilities. All states will receive this guidance when it is completed. In the interim, we recommend the following actions:

a. Clean all areas that will be accessible to children to the EPA dust-lead standard for children 6 years of age or under ($40 \mu\text{g}/\text{ft}^2$ on floors and $250 \mu\text{g}/\text{ft}^2$ on windowsills).

b. Refer to the local authorities' regulations since they can be more stringent than federal regulations.

c. Post signs in the area to inform people of the presence of lead dust and its effects.

d. If soldiers clean weapons in the facility change the policy so that they cannot clean their weapons in the facility, or if they are allowed to clean their weapons indoors, they must clean the area by wet wiping and mopping the area when they are done.

e. If the paint is peeling, contact the state Environmental Office to test for lead content and provide recommendations.

3. Air samples collected on individuals in the armory were well below OSHA's permissible exposure limit for lead (29 CFR 1910.1025(e)) of $0.05 \text{ mg}/\text{m}^3$ averaged over an 8-hour day. Therefore, based on these conditions there is currently no overexposure to personnel from lead dust in this building.

Industrial Hygiene Survey

Vermont Army National Guard (VT ARNG)

Prepared For: NGB ARNG– Region North IH Office

Survey Location:

Swanton Readiness Center
13 Ferris Street
Swanton, VT 05488

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 24, 2011

AEI Project #: J11-601 4L VT Swanton RC

Non-Responsive, CIH, CSP
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

Table of Contents

Executive Summary ii

1 Introduction 1

2 Evaluation Methods 1

3 Operations 1

4 Noise Hazards 1

5 Hazard Controls 1

Ventilation Systems 1

6 Physical Condition of the Facility and Personnel Concerns 2

Paint Chip and Dust Wipe Samples for Lead Contamination 2

Visual Inspection for Damaged Asbestos-Containing Materials 3

Visual Inspection for Water Damage and Mold Growth 3

Visual Inspection for Housekeeping Concerns 3

Lighting 3

Indoor Air Quality (IAQ) 3

Temperature and Relative Humidity 4

Carbon Dioxide (CO₂) and Carbon Monoxide (CO) 4

7 Conclusions 4

8 Limitations 5

List of Tables and Appendices

Table 1 - Results of Dust Wipe Sampling for the VT ARNG Swanton Readiness Center on October 24, 2011.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

Appendix A – Building Layout

Appendix B – Certificates of Analysis for Air, Dust Wipe and Bulk Samples

Appendix C – Photo Documentation

Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Swanton Readiness Center located at 13 Ferris Street, Swanton, VT 05488. Non-Responsive CIH, CSP performed the evaluation on October 24, 2011. The point of contact for the facility was Non-Responsive. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Paint Chip and Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed in the boiler room on a vent to the outdoors. A sample of this peeling paint was analyzed and contained 0.14% lead by weight which would not be considered lead-based by the Environmental Protection Agency (EPA) and State of Vermont definitions (0.5%). Results of dust wipe samples taken throughout the facility were below the recommended maximum criterion for surface contamination of lead (200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$)) in all areas sampled except for the sample collected from the floor in the custodial storage room that was part of the former firing range (3,700 $\mu\text{g}/\text{ft}^2$) and from a dusty painted vent in the Drill Hall (920 $\mu\text{g}/\text{ft}^2$).

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there were any suspect asbestos-containing material and its condition. No damaged suspect material was observed.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or evidence of mold growth was observed on the day of the survey.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping needs some improvement to reduce clutter and dust accumulation.

Lighting: A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in a few areas. The illumination measurements indoors ranged from 8 foot candles (fc) to 150 fc.

Indoor Air Quality: Temperature measurements were mostly below the comfort ranges for the winter season, and relative humidity measurements were within the comfort ranges on the day of the survey. The outdoor temperature and relative humidity were 63.1° F and 45.9%, and the heating system was turned on for the first time of the season on the day of monitoring. Indoor concentrations of carbon dioxide (CO_2) were below the guidelines in all areas except for the training center where three people were working. Indoor levels of carbon monoxide (CO) ranged from 0.4 to 10.1 ppm; therefore, concentrations are below occupational exposure limits (25 parts per million (ppm)), but above the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE) and the National Ambient Air Quality Standards (NAAQS) recommended CO concentrations (>9 ppm) in certain areas. The ASHRAE and NAAQS guidelines are based on 8 hour

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

averages. It is not likely that the CO concentrations at this readiness center would be sustained above 9 ppm for 8 hours. The heating system was turned on for the first time of the season on the day of monitoring. The carbon monoxide issue was reported immediately to the caretaker and the point of contact. Windows were opened to reduce concentrations while the heating system was warming up, and household-type CO detectors were recommended. The caretaker reported that there did not appear to be anything wrong with the heating system and that maintenance was up to date.

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updated MSDSs are required per OSHA 29 CFR 1910.1200. It is recommended that a copy of the written hazard communication program be placed in every MSDS notebook. MSDSs for some new products are required per OSHA 29 CFR 1910.1200.

Overall, the Swanton Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Swanton Readiness Center located at 13 Ferris Street, Swanton, VT 05488. Non-Responsive, CIH, CSP performed the evaluation on October 24, 2011. The point of contact for the facility was Non-Responsive. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

The Swanton Readiness Center was built in 1950. The readiness center is staffed by 4 administrative personnel. The operations conducted at the facility include supply and administrative duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the Swanton Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) evaluations of operations including operation description, sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the Swanton facility consist exclusively of supply and administrative duties. Ground maintenance and upkeep of the building are the responsibility of the state employed Armorer and not part of the duties of National Guard personnel.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for water damage or mold problems; potential ergonomic problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were taken in select areas.

Paint Chip and Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed on a vent in the boiler room. A sample of the peeling paint was submitted to AMA Analytical Services, Inc. of Lanham, MD for lead analysis. The sample contained 0.14% lead by weight which would not be considered lead-based by the Environmental Protection Agency (EPA) and State of Vermont definitions (>0.5%). To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected using ghost wipes and 10 centimeter (cm) x 10cm templates. The Environmental Protection Agency (EPA) and the Commonwealth of Pennsylvania limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. All wipe samples collected from the facility were below the recommended maximum except for the sample collected from the floor in the custodial storage room that was part of the former firing range (3,700 $\mu\text{g}/\text{ft}^2$) and from a dusty painted vent in the Drill Hall (920 $\mu\text{g}/\text{ft}^2$). Results are given in Table 1 and certificates of analysis are included in Appendix B.

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
Swanton Readiness Center on October 24, 2011.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
SWA-01	Recovery Room – floor (Former Firing Range)	<110
SWA-02	Recovery Room – painted shelf (Former Firing Range)	<110
SWA-03	Custodial Storage – unpainted concrete floor (Former Firing Range)	3,700
SWA-04	Custodial Storage – metal shelf (Former Firing Range)	<110
SWA-05	Drill Hall – floor near former firing range	<110
SWA-06	Drill Hall – metal storage locker	<110
SWA-07	Drill Hall – painted heater vent	920
SWA-08	Drill Hall – floor	<110
SWA-09	Drill Hall – bay door	<110
SWA-10	Drill Hall – floor	<110

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
Swanton Readiness Center on October 24, 2011.**

Wipe Sample #	Sample Location	Result (µg/ft ²)*
SWA-11	Kitchen – stone window ledge	<110
SWA-12	Family Readiness Room - floor	<110

*The recommended maximum level for adult exposures is 200 µg/ft² lead on surfaces.

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). No damaged suspect ACM was observed.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or evidence of mold growth was observed on the day of the inspection.

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping was good. Most areas were clean and tidy.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on March 9, 2011, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in a few areas: the fitness center, the drill hall, the janitor's closet, the maintenance room and in the boiler room. The illumination measurements indoors ranged from 8 foot candles (fc) to 150 fc. The complete results of the evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Plus Model 8554, factory calibrated in February, 2011. Temperature, relative humidity and carbon dioxide (CO₂) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 2. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30 and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 58.2 to 70.0° F and 43.1 to 59.5% Rh. Temperatures were mostly lower than the winter comfort ranges, and relative humidity measurements were within the comfort ranges on the day of monitoring. The outdoor temperature and relative humidity was 63.1° F and 45.9% on the day of monitoring. This was the first day of the season that the heating system was turned on and the system had not reached the set temperature yet.

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1–2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 428 to 1,665 parts per million (ppm). The outdoor CO₂ concentration was 418 ppm on the day of monitoring. CO₂ measurements were below the guideline in all areas monitored except for the training center office where three people were working (1,665 ppm).

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 0.4 to 10.1 ppm; therefore, concentrations are below occupational exposure limits, but above the ASHRAE and the NAAQS-recommended CO concentrations in certain areas. The ASHRAE and NAAQS guidelines are based on 8 hour averages. It is not likely that the CO concentrations at this readiness center would be sustained above 9 ppm for 8 hours. The heating system was turned on for the first time of the season on the day of monitoring. The carbon monoxide issue was reported immediately to the caretaker and the point of contact. Windows were opened to reduce concentrations while the heating system was warming up, and household-type CO detectors were recommended. The caretaker reported that there did not appear to be anything wrong with the heating system and that maintenance was up to date.

Additional Information

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updated MSDSs are required per OSHA 29 CFR 1910.1200. It is recommended that a copy of the written hazard communication program

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

be placed in every MSDS notebook. MSDSs for some new products are required per OSHA 29 CFR 1910.1200. **RAC 4**

7 Conclusions

The results of the evaluation indicated no concerns with the following at the facility: water intrusion, peeling potentially lead-based paints, noise hazards, visible mold and the presence of damaged suspect asbestos-containing materials. The results of the evaluation indicated industrial hygiene concerns in the following areas: accumulated lead-containing dust in one area, lighting, hazard communication and MSDS updates, carbon monoxide concentrations above 9 ppm in some areas and housekeeping. Overall, the Swanton Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.


9 References

1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.
3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.
4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.
5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2011.
6. Army Regulation (AR) 420-70 Buildings and Structures, 10 October 1997.
7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 28 March 2009.


**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

8. Army Regulation (AR) 420-1 Army Facilities Management, 28 March 2009.
9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.
10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.
12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.
13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".
15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.

Appendix A Building Layout



FERRIS STREET



DRIVEWAY

Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples



CERTIFICATE OF ANALYSIS



Client: National Guard Bureau	Job Name: Swanton RC	Chain Of Custody: 511732
Address: 301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location: Swanton, VT	Date Submitted: 11/1/2011
Attention: Non-Responsive	Job Number: J11-601	Person Submitting: Non-Responsive
	P.O. Number: W912K6-09-A-0003	Date Analyzed: 11/7/2011
		Report Date: 11/8/2011

Summary of Atomic Absorption Analysis for Lead

Page 1 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
12010611	SWA-01	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010612	SWA-02	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010613	SWA-03	Flame	Wipe	****	0.108	110 ug/ft ²	400	3700 ug/ft ²	
12010614	SWA-04	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010615	SWA-05	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010616	SWA-06	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010617	SWA-07	Flame	Wipe	****	0.111	110 ug/ft ²	100	920 ug/ft ²	
12010618	SWA-08	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010619	SWA-09	Flame	Wipe	****	0.111	110 ug/ft ²	<12	<110 ug/ft ²	
12010620	SWA-10	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010621	SWA-11	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010622	SWA-12	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010623	SWA-Blk-01	Flame	Paint Chip	****	N/A	0.01 %Pb		0.14 %Pb	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS



Client: National Guard Bureau	Job Name: Swanton RC	Chain Of Custody: 511732
Address: 301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location: Swanton, VT	Date Submitted: 11/1/2011
	Job Number: J11-601	Person Submitting: Non-Responsive
	P.O. Number: W912K6-09-A-0003	Date Analyzed: 11/7/2011
Attention: Non-Responsive		Report Date: 11/8/2011

Summary of Atomic Absorption Analysis for Lead

Page 2 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
<p>Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm) %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb) Note: All samples were received in good condition unless otherwise noted. Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result. Air and Wipe results are not corrected for any blank results Final results for air and wipe samples are based on client supplied information nor verified by this laboratory. All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.</p>							<p>See QC Summary for analytical results of quality control samples associated with these samples.</p>		
								Non-Responsive	Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



AMA Analytical Services, Inc.
Focused on Results www.amalab.com
AIHA (#100470) NVLAP (#101143-0) NY ELAP (10920)
4475 Forbes Blvd. • Lanham, MD 20706
(301) 459-2640 • (800) 346-0961 • Fax (301) 459-2643

CHAIN OF CUSTODY

(Please Refer To This Number For Inquiries)

511732

pepe1/r

Mailing/Billing Information:

- 1. Client Name: National Guard Bureau
2. Address 1: 301-1H Old Bay Lane
3. Address 2: Attn: NGB-AVN-SI, State Military Reservation
4. Address 3: Havre de Grace, Maryland 21078
5. Phone #: (410) 942-0273 Fax #: (410) 942-0254

Submittal Information:

- 1. Job Name: Swanton RC
2. Job Location: Swanton, VT
3. Job #: J11-601
4. Contact Person: Non-Responsive #: W912K6-09-A-0003
5. Submitted By: Non-Responsive @ phone # (410) 942-0273

Reporting Information (Results will be provided as soon as technically feasible):

AFTER HOURS (must be pre-scheduled)

- Immediate Date Due:
24 Hours Time Due:
Comments:

NORMAL BUSINESS HOURS

- Immediate
Next Day
2 Day
3 Day
5 Day +
Results Required By Noon (Every Attempt Will Be Made to Accomodate)

- Include
Exclude
Fax
Verbal

REPORT TO:

- Non-Responsive with Report
afiaenviro.com
us.army.mil
us.army.mil

Asbestos Analysis

PCMA Air - Please Indicate Filter Type:

- NIOSH 7400 (QTY)
Fiberglass (QTY)

TEM Air - Please Indicate Filter Type:

- ASHERA (QTY)
NIOSH 7402 (QTY)
Other (specify) (QTY)

PLM Bulk

- EPA 600 - Visual Estimate (QTY)
EPA Point Count (QTY)
NY State Friable 198.1 (QTY)
Grav. Reduction ELAP 198.6 (QTY)
Other (specify) (QTY)

MISC

- Vermiculite
Asbestos Soil PLM (Qual) PLM (Quan) PLM/TEM (Qual) PLM/TEM (Quan)

TEM Bulk

- ELAP 198.4/Chatfield (QTY)
NY State PLM/TEM (QTY)
Residual Ash (QTY)

TEM Dust

- Qual. (pres/abs) Vacuum/Dust (QTY)
Quan. (s/area) Vacuum D5755-95 (QTY)
Quan. (s/area) Dust D6480-99 (QTY)

TEM Water

- Qual. (pres/abs) (QTY)
ELAP 198.2/EPA 100.2 (QTY)
EPA 100.1 (QTY)

All samples received in good condition unless otherwise noted. (TEM Water samples °C)

Metals Analysis

- Pb Paint Chip (QTY)
Pb Dust Wipe (wipe type 10x10, 12) (QTY)
Pb Air (QTY)
Pb Soil/Solid (QTY)
Pb TCLP (QTY)
Drinking Water Pb (QTY) Cu (QTY) As (QTY)
Waste Water Pb (QTY) Cu (QTY) As (QTY)
Pb Furnace (Media) (QTY)

Fungal Analysis

- Collection Apparatus for Spore Traps/Air Samples:
Collection Media:
Spore-Trap (QTY) Surface Vacuum Dust (QTY)
Surface Swab (QTY) Culturable ID Genus (Media) (QTY)
Surface Tape (QTY) Culturable ID Species (Media) (QTY)
Other (Specify) (QTY)

SAMPLE INFORMATION

Table with columns: CLIENT ID NUMBER, SAMPLE LOCATION/ IDENTIFICATION, DATE, VOLUME (LITERS), WIPE AREA, TEM, PCMA, PLM, LEAD, MOLD, AIR, BULK, DUST, MATRICE, WATER, OTHER, SPORE TRAP, TAPE, SWAB. Rows include SWA-01 through SWA-12 with handwritten data.

CLIENT CONTACT

(LABORATORY STAFF ONLY)

Date/Time: Contact: By:
Date/Time: Contact: By:
Date/Time: Contact: By:

LABORATORY STAFF ONLY:

- 1. Date/Time RCVD: 11/1/11 @ 1015 Via: Fedex By (Print):
2. Date/Time Analyzed: 1/1/ @ By (Print):
3. Results Reported To:
4. Comments: 7952 7193 2377

Non-Responsive



AMA Analytical Services, Inc. Focused on Results www.amalab.com AIHA (#100470) NVLAP (#101143-0) NY ELAP (10920) 4475 Forbes Blvd. • Lanham, MD 20706 (301) 459-2640 • (800) 346-0961 • Fax (301) 459-2643

CHAIN OF CUSTODY

(Please Refer To This Number For Inquires)

511737 page 2/2

Mailing/Billing Information:

1. Client Name: National Guard Bureau
2. Address 1: 301-JH Old Bay Lane
3. Address 2: Attn: NGB-AVN-SI, State Military Reservation
4. Address 3: Havre de Grace, Maryland 21078
5. Phone #: (410) 942-0273 Fax #: (410) 942-0254

Submittal Information:

1. Job Name: Swanlan RC
2. Job Location: Swanlan, VT
3. Job #: JH-601
4. Contact Person: Non-Responsive
5. Submitted By: Non-Responsive

PO #: W912K6-09-A-0003
Signature: Non-Responsive

Reporting Information (Results will be provided as soon as technically feasible):

Form with checkboxes for 'AFTER HOURS (must be pre-scheduled)', 'NORMAL BUSINESS HOURS', and 'REPORT TO:'. Includes options for 'Immediate', '24 Hours', '3 Day', '5 Day +', 'Next Day', '2 Day', 'Results Required By Noon', and 'With Report'.

Asbestos Analysis

PCM Air - Please Indicate Filter Type:
- NIOSH 7400 (QTY)
- Fiberglass (QTY)
TEM Air - Please Indicate Filter Type:
- AHERA (QTY)
- NIOSH 7402 (QTY)
- Other (specify) (QTY)
PLM Bulk
- EPA 600 - Visual Estimate (QTY)
- EPA Point Count (QTY)
- NY State Friable 198.1 (QTY)
- Grav. Reduction ELAP 198.6 (QTY)
- Other (specify) (QTY)
MISC
- Vermiculite
- Asbestos Soil PLM (Qual) PLM (Quan) PLM/TEM (Qual) PLM/TEM (Quan)

TEM Bulk

ELAP 198.4/Chatfield (QTY)
NY State PLM/TEM (QTY)
Residual Ash (QTY)
TEM Dust
- Qual. (pres/abs) Vacuum/Dust (QTY)
- Quan. (s/area) Vacuum D5755-95 (QTY)
- Quan. (s/area) Dust D6480-99 (QTY)
TEM Water
- Qual. (pres/abs) (QTY)
- ELAP 198.2/EPA 100.2 (QTY)
- EPA 100.1 (QTY)

Metals Analysis

Pb Paint Chip (QTY)
Pb Dust Wipe (wipe type) (QTY)
Pb Air (QTY)
Pb Soil/Solid (QTY)
Pb TCLP (QTY)
Drinking Water Pb (QTY) Cu (QTY) As (QTY)
Waste Water Pb (QTY) Cu (QTY) As (QTY)
Pb Furnace (Media) (QTY)

Fungal Analysis

Collection Apparatus for Spore Traps/Air Samples:
Collection Media:
- Spore-Trap (QTY)
- Surface Vacuum Dust (QTY)
- Surface Swab (QTY)
- Culturable ID Genus (Media) (QTY)
- Surface Tape (QTY)
- Culturable ID Species (Media) (QTY)
- Other (Specify) (QTY)

All samples received in good condition unless otherwise noted. (TEM Water samples °C)

SAMPLE INFORMATION

Table with columns: CLIENT ID NUMBER, SAMPLE LOCATION/ IDENTIFICATION, DATE, VOLUME (LITERS), WIPE AREA, ANALYSIS (TEM, PCM, PLM, LEAD, MOLD, AIR, BULK, DUST, MATRIX), CLIENT CONTACT (LABORATORY STAFF ONLY). Includes handwritten entry 'Swanlan-01' and '5/24'.

LABORATORY STAFF ONLY:

1. Date/Time RCVD: / / @ Via: By (Print): Sign:
2. Date/Time Analyzed: / / @ By (Print): Sign:
3. Results Reported To: Date: / /
4. Comments:

Appendix C Photo Documentation

Swanton, VT Readiness Center



Swanton RC Exterior



Exterior



Drill Hall



Drill Hall

Swanton, VT Readiness Center



Cold Storage – Former Firing Range



Cold Storage – Former Firing Range



Flammable Storage Cabinet



Drill Hall

Swanton, VT Readiness Center



Cold Storage – Former Firing Range



Outdoor Storage Area



Exterior View

Posted to NGB FOIA Reading Room
May, 2018



Outdoor Storage

Swanton, VT Readiness Center



Kitchen



Custodian's Office



Supply Storage Area



Supply Room

Swanton, VT Readiness Center



Supply Room



Flammable Storage Cabinet



Supply Storage Area



Office

Swanton, VT Readiness Center



Classroom



Fitness Center



Boiler Room



Boiler Room

Appendix D
IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Swanton	IAQ						Light			
Date	10/24/2011	Inspector	Non-Responsive	Instrument	Q-trak 7565-X						Instrument	Cal-Light 400	
Facility Description	Swanton RC			Serial Number	7565X0839020						Serial Number	K070003	
Weather Conditions	Clear, Cool			Last Calibration	Feb-11						Last Calibration	9-Mar-11	
Location/Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
Training Room	1	13:59	64.5	X	49.7		524		2.5		48-74		30-50
Fitness Center	1	14:02									15-28	X	30
Family Readiness Center	1	14:05	64.5	X	48.7		495		10.1	X	42-68		30-50
Training Center	3	14:11	70.0		55.9		1665	X	9.5	X	50-75		30-50
Supply Room	2	14:19	66.9	X	43.1		635		8.5		33-85		30
Storage	1	14:20	64.3	X	45.1		611		8.5		40-60		30
Drill Hall	1	14:22	63.1	X	49.1		562		9.6	X	11-32	X	30
Custodian's Office	1	14:25	63.3	X	56.2		533		6.5		30-35		30-50
Kitchen	2	14:30	69.9		48.7		529		2.5		90-150		50
Kitchen Storage	2	14:31	67.0	X	47.7		486		1.6		38		5
JC	2	14:32							9.7	X	27	X	30
Locker Room	2	14:35	61.9	X	51.3		498		4.1		22-63		7
Maintenance Room	2	14:37	60.1	X	52.3		428		0.4		14-48	X	30
Foyer	1	14:39	61.8	X	57.7		537		0.7		35		5
Recruiting	2	14:40	62.6	X	57.5		735		0.6		40-80		30-50
Captain's Office	2	14:41	63.9	X	55.2		655		1.0		38-53		30-50
Recovery Room	1	14:46	59.0	X	54.9		475		6.1		30-40		30
Custodial Storage	1	14:53	58.2	X	59.5		536		7.3		40		30
Boiler Room	3	14:56	66.6	X	56.9		941		6.3		22-38	X	30
Women's Bathroom	1	16:05							6.0		8-30		5
Outside	1	16:13	63.1		45.9		418		0.1				

Industrial Hygiene Survey

Vermont Army National Guard (VTARNG)

Prepared For: NGB ARNG– Region North IH Office

Survey Location:

Swanton Readiness Center
13 Ferris Street
Swanton, VT 05488

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 23, 2012

AEI Project #: J12-685 3m VT Swanton RC

Non-Responsive, CIH, CSP
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

Table of Contents

Executive Summary ii

1 Introduction 1

2 Evaluation Methods 1

3 Operations 1

4 Noise Hazards 1

5 Hazard Controls 1

Ventilation Systems 1

6 Physical Condition of the Facility and Personnel Concerns 2

Paint Chip and Dust Wipe Samples for Lead Contamination 2

Visual Inspection for Damaged Asbestos-Containing Materials 3

Visual Inspection for Water Damage and Mold Growth 3

Visual Inspection for Housekeeping Concerns 3

Lighting 3

Indoor Air Quality (IAQ) 3

Temperature and Relative Humidity 4

Carbon Dioxide (CO₂) and Carbon Monoxide (CO) 4

7 Conclusions 4

8 Limitations 5

List of Tables and Appendices

Table 1 - Results of Dust Wipe Sampling for the VTARNG Swanton Readiness Center on October 23, 2012.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

Appendix A – Building Layout

Appendix B – Certificates of Analysis for Air, Dust Wipe and Bulk Samples

Appendix C – Photo Documentation

Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VTARNG) Swanton Readiness Center located at 13 Ferris Street, Swanton, VT 05488. Non-Responsive, CIH, CSP performed the evaluation on October 23, 2012. The point of contact for the facility was Non-Responsive. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Paint Chip and Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed in the boiler room on a vent to the outdoors. A sample of this peeling paint was sampled and analyzed as part of the 2011 survey and found to contain 0.14% lead by weight which would not be considered lead-based by the Environmental Protection Agency (EPA) and State of Vermont definitions (0.5%). Results of dust wipe samples taken throughout the facility were below the recommended maximum criterion for surface contamination of lead (200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$)) in all areas sampled except for the sample collected from the floor in the cold storage room #2 that was part of the former firing range (270 $\mu\text{g}/\text{ft}^2$).

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material. No damaged suspect material was observed.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or evidence of mold growth was observed on the day of the survey.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping needs some improvement to reduce clutter and dust accumulation.

Lighting: A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in several areas. The illumination measurements indoors ranged from 6 foot candles (fc) to 134 fc.

Indoor Air Quality: Temperature and relative humidity measurements were mostly within the comfort ranges for the winter season on the day of the survey. The outdoor temperature and relative humidity were 58.2° F and 37.9%. Indoor concentrations of carbon dioxide (CO_2) were below the guidelines in all areas except for the training center (1,700 ppm) where four people were working. Indoor levels of carbon monoxide (CO) ranged from 0.0 to 8.7 ppm; therefore, concentrations are below occupational exposure limits (25 parts per million (ppm)), but approaching the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE) and the National Ambient Air Quality Standards (NAAQS) recommended CO concentrations of 9 ppm in the Drill Hall. The ASHRAE and NAAQS guidelines are based on 8 hour averages. It is not likely that the CO concentrations at this readiness center would be sustained

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

above 9 ppm for 8 hours. This problem was also addressed during last year's survey and household-type CO detectors were recommended. The point of contact said that CO detectors were purchased and received but not yet installed.

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updated MSDSs are required per OSHA 29 CFR 1910.1200. It is recommended that a copy of the written hazard communication program be placed in every MSDS notebook. MSDSs for some new products are required per OSHA 29 CFR 1910.1200.

Improper Materials in Flammable Storage Cabinets: Chemical products clearly labeled as non-flammable were stored in flammable storage cabinets. Incompatible products, non-flammable products, personal protective equipment such as dust masks, gloves and safety glasses and excess combustible materials such as paper, cardboard, or other combustible packaging material should not be stored in flammable storage cabinets. Requirements for flammable storage are regulated by OSHA 1910.106.

Improper storage: A cardboard box was stored next to a heater in the storage area, creating a potential fire hazard.

Overall, the Swanton Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VTARNG) Swanton Readiness Center located at 13 Ferris Street, Swanton, VT 05488. Non-Responsive, CIH, CSP performed the evaluation on October 23, 2012. The point of contact for the facility was Non-Responsive. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

The Swanton Readiness Center was built in 1950. The readiness center is staffed by 5 military administrative personnel and one civilian caretaker. The operations conducted at the facility include supply and administrative duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the Swanton Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) evaluations of operations including operation description, sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the Swanton facility consist exclusively of supply and administrative duties. Ground maintenance and upkeep of the building are the responsibility of the state and not part of the duties of National Guard personnel.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for water damage or mold problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were taken in select areas.

Paint Chip and Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed on a vent in the boiler room that had been identified in last year's survey to contain less than 0.5% lead by weight. The sample submitted in 2011 contained 0.14% lead by weight which would not be considered lead-based by the Environmental Protection Agency (EPA) and State of Vermont definitions (>0.5%). To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected using ghost wipes and 10 centimeter (cm) x 10cm templates. The Environmental Protection Agency (EPA) and the Commonwealth of Pennsylvania limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. All wipe samples collected from the facility were below the recommended maximum except for the sample collected from the floor in cold storage room #2 that was part of the former firing range (270 $\mu\text{g}/\text{ft}^2$). Results are given in Table 1 and certificates of analysis are included in Appendix B.

**Table 1 – Results of Dust Wipe Sampling for VTARNG
Swanton Readiness Center on October 23, 2012.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
SW-W01	Drill Hall – center of floor	<110
SW-W02	Drill Hall – top of shipping container	<110
SW-W03	Drill Hall – floor near former range	<110
SW-W04	Drill Hall – serving counter	<110
SW-W05	Drill Hall – outreach table	<110
SW-W06	Kitchen – counter near microwave	<110
SW-W07	Supply room – receiving window	<110
SW-W08	Cold Storage Room #1 – former range – floor	120
SW-W09	Cold Storage Room #2 – former range – floor	270
SW-W10	Classroom – children's table	<110

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

**Table 1 – Results of Dust Wipe Sampling for VTARNG
Swanton Readiness Center on October 23, 2012.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
SW-W11	Fitness Center – front of treadmill	<110

*The recommended maximum level for adult exposures is 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) lead on surfaces.

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). No damaged suspect ACM was observed.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or evidence of mold growth was observed on the day of the inspection.

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping needed some improvement to reduce dust and clutter.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on April 16, 2012, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in several areas. The illumination measurements indoors ranged from 6 foot candles (fc) to 134 fc. The complete results of the evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Model 7656X, factory calibrated in March, 2012. Temperature, relative humidity and carbon dioxide (CO_2) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 2. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30 and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 66.7 to 79.0° F and 36.2 to 52.0% Rh. Temperatures and relative humidity measurements were mostly within the winter comfort ranges on the day of monitoring. The outdoor temperature and relative humidity was 58.2° F and 37.9%.

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1–2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 416 to 1,700 parts per million (ppm). The outdoor CO₂ concentration was 370 ppm on the day of monitoring. CO₂ measurements were below the guideline in all areas monitored except for the training center office where four people were working (1,700 ppm).

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 0.0 to 8.7 ppm; therefore, concentrations are below occupational exposure limits, but approaching the ASHRAE and the NAAQS-recommended CO concentrations in the Drill Hall. The ASHRAE and NAAQS guidelines are based on 8 hour averages. It is not likely that the CO concentrations at this readiness center would be sustained above 9 ppm for 8 hours. The carbon monoxide issue was reported in last year's survey report, and household-type CO detectors were recommended. The point of contact reported that the CO detectors were purchased and received but not yet installed.

Additional Information

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updated MSDSs are required per OSHA 29 CFR 1910.1200. It is recommended that a copy of the written hazard communication program be placed in every MSDS notebook. MSDSs for some new products are required per OSHA 29 CFR 1910.1200.

Improper Materials in Flammable Storage Cabinets: Chemical products clearly labeled as non-flammable were stored in flammable storage cabinets. Incompatible products, non-flammable products, personal protective equipment such as dust masks, gloves and safety glasses and excess combustible materials such as paper, cardboard, or other combustible packaging

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**

material should not be stored in flammable storage cabinets. Requirements for flammable storage are regulated by OSHA 1910.106.

7 Conclusions

The results of the evaluation indicated few concerns with the facility. Overall, the Swanton Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.

9 References


1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.
3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.
4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.
5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2011.
6. Army Regulation (AR) 420-70 Buildings and Structures, 11 November 1997.
7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 13 December 2007.
8. Army Regulation (AR) 420-1 Army Facilities Management, 12 February 2008, RAR 24 August 2012.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Swanton Readiness Center**


9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.
10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.
12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.
13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".
15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.
19. OSHA 29 CFR 1910 Subpart L: Fire Protection
20. National Fire Protection Association (NFPA) 70: National Electrical Code (NEC) 2011.
21. National Guard Pamphlet (NG PAM) 420-15, Guidelines and Procedures for Rehabilitation and Conversion of Indoor Firing Ranges, November 3, 2006.

Appendix A Building Layout

FERRIS STREET



DRIVEWAY



Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	Swanton RC	Chain Of Custody:	514387
Address:	301-JH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Swanton, VT	Date Submitted:	11/2/2012
Attention:	Non-Responsive	Job Number:	J12-285	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/9/2012
				Report Date:	11/9/2012

Summary of Atomic Absorption Analysis for Lead

Page 1 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
13010951	SW-W 01	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010952	SW-W 02	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010953	SW-W 03	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010954	SW-W 04	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010955	SW-W 05	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010956	SW-W 06	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010957	SW-W 07	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010958	SW-W 08	Flame	Wipe	****	0.108	110 ug/ft ²	13	120 ug/ft ²	
13010959	SW-W 09	Flame	Wipe	****	0.108	110 ug/ft ²	29	270 ug/ft ²	
13010960	SW-W 10	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010961	SW-W 11	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS



Client: National Guard Bureau	Job Name: Swanton RC	Chain Of Custody: 514387
Address: 301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location: Swanton, VT	Date Submitted: 11/2/2012
	Job Number: J12-285	Person Submitting: Non-Responsive
	P.O. Number: W912K6-09-A-0003	Date Analyzed: 11/9/2012
Attention: Non-Responsive		Report Date: 11/9/2012

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	----------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm)
 %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb)

See QC Summary for analytical results of quality control samples associated with these samples.

Note: All samples were received in good condition unless otherwise noted.

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Air and Wipe results are not corrected for any blank results
 Final results for air and wipe samples are based on client supplied information nor verified by this laboratory.

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Analyst:

Non-Responsive

Technical Manager:

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



AMA Analytical Services, Inc.
 Focused on Results www.amalab.com
 AIHA (#100470) NVLAP (#101143-0) NY ELAP (10920)
 4475 Forbes Blvd. • Lanham, MD 20706
 (301) 459-2640 • (800) 346-0961 • Fax (301) 459-2643

BEST AVAILABLE COPY

CHAIN OF CUSTODY

(Please Refer To This Number For Inquires)

514387

Mailing/Billing Information:

- Client Name: National Guard Bureau
- Address 1: 301-IH Old Bay Lane
- Address 2: Attn: NGB-AVN-SI, State Military Reservation
- Address 3: Havre de Grace, Maryland 21078
- Phone #: (410) 942-0273 Fax #: (410) 942-0254

Submittal Information:

- Job Name: Swanton RC
- Job Location: Swanton, VT
- Job #: 512, 285 P.O. #: W912K6-09-A-0003
- Contact Person: Non-Responsive @ phone # _____
- Submitted by: Non-Responsive Signature: Non-Responsive

Reporting Info (Results provided as soon as technically feasible). If no TAT/Reporting Info is provided, AMA will assign defaults of 5-Day and chain of custody to contacts on file.

AFTER HOURS (must be pre-scheduled) <input type="checkbox"/> Immediate Date Due: _____ <input type="checkbox"/> 24 Hours Time Due: _____ Comments: _____		NORMAL BUSINESS HOURS <input type="checkbox"/> 3 Day <input checked="" type="checkbox"/> 5 Day + <u>Wk/2</u> Date Due: _____ <input type="checkbox"/> 2 Day <input type="checkbox"/> Results Required By Noon		REPORT TO: <input checked="" type="checkbox"/> Include with Report <input checked="" type="checkbox"/> Email: <u>Non-Responsive</u> @ <u>ariaenviro.com</u> <input type="checkbox"/> Fax: _____ @ <u>us.army.mil</u> <input type="checkbox"/> Verbal: _____ @ <u>us.army.mil</u>
--	--	--	--	---

Asbestos Analysis

- *PCM Air - Please Indicate Filter Type:
 - NIOSH 7400 (QTY)
 - Fiberglass (QTY)
- TEM Air* - Please Indicate Filter Type:
 - AHERA (QTY)
 - NIOSH 7402 (QTY)
 - Other (specify _____) (QTY)
- PLM Bulk
 - EPA 600 - Visual Estimate (QTY)
 - EPA Point Count (QTY)
 - NY State Friable 198.1 (QTY)
 - Grav. Reduction ELAP 198.6 (QTY)
 - Other (specify _____) (QTY)

TEM Bulk

- ELAP 198.4/Chatfield (QTY)
- NY State PLM/TEM (QTY)
- Residual Ash (QTY)
- TEM Dust*
 - Qual. (pres/abs) Vacuum/Dust (QTY)
 - Quan. (s/area) Vacuum D5755-95 (QTY)
 - Quan. (s/area) Dust D6480-99 (QTY)

TEM Water

- Qual. (pres/abs) (QTY)
- ELAP 198.2/EPA 100.2 (QTY)
- EPA 100.1 (QTY)

All samples received in good condition unless otherwise noted.
 (TEM Water samples _____°C)

Metals Analysis

- Pb Paint Chip (QTY)
- *Pb Dust Wipe (wipe type 10X10) (QTY) ghost
- *Pb Air (QTY)
- Pb Soil/Solid (QTY)
- Pb TCLP (QTY)
- Drinking Water Pb (QTY) Cu (QTY) As (QTY)
- Waste Water Pb (QTY) Cu (QTY) As (QTY)
- Pb Furnace (Media _____) (QTY)

Fungal Analysis

- Collection Apparatus for Spore Traps/Air Samples: _____
- Collection Media _____
- *Spore-Trap (QTY)
- *Surface Swab (QTY)
- *Surface Tape (QTY)
- Other (Specify _____) (QTY)
- Surface Vacuum Dust (QTY)
- Culturable ID Genus (Media _____) (QTY)
- Culturable ID Species (Media _____) (QTY)

MISC

- Vermiculite
- Asbestos Soil PLM (Qual) PLM (Quan) PLM/TEM (Qual) PLM/TEM (Quan)

*It is recommended that blank samples be submitted with all air and surface samples

If field data sheets are submitted, there is no need to complete bottom section.

CLIENT ID #	SAMPLE INFORMATION														CLIENT CONTACT				
	SAMPLE LOCATION/ID	DATE/TIME	VOL (L)/Wipe Area	TEM	PCM	PLM	LEAD	MOLD	AIR	BULK	DUST	MATRIX	WATER AND OTHER	SPORE TRAP	TAPE	SWAB	(LABORATORY STAFF ONLY)		
																	Date/Time:	Contact:	By:
	SEE ATTACHED FIELD DATA SHEETS																Date/Time:	Contact:	By:
																	Date/Time:	Contact:	By:

LABORATORY STAFF ONLY: (CUSTODY)

- Date/Time RCVD: 11 / 2 / 12 @ _____ Via: TEK By (Print): Non-Responsive Sign: Non-Responsive
- Date/Time Analyzed: _____ @ _____ By (Print): _____ Sign: _____
- Results Reported To: _____ Via: _____ Date: _____ / _____ / _____ Time: _____ Initials: _____

Posted to NGB FOIA Reading Room
 May, 2018

BEST AVAILABLE COPY

FOIA Requested Record #J-15-0085 (VT)
 Released by National Guard Bureau
 Page 1024 of 1352

Appendix C Photo Documentation

VT Swanton RC



Exterior of Swanton RC



Exterior



Cold Storage – Former Rang

Posted to NGB FOIA Reading Room
May, 2018



Drill Hall

VT Swanton RC



Caretaker's Office



Kitchen



Kitchen



Kitchen Storage

VT Swanton RC




Kitchen



Drill Hall



Janitor's Closet



MSDSs in Janitor's Closet

VT Swanton RC



Drill Hall



Bunk Room in Locker Storage



Storage Area



Storage and Office

VT Swanton RC



Storage



Storage



Storage near heater



Drill Hall

VT Swanton RC



Office



Classroom



Fitness Center

Posted to NGB FOIA Reading Room
May, 2018



Fitness Center

VT Swanton RC



Moisture trapped in windows



Insufficient lighting in telecom closet



Telecom closet



Table for Children

VT Swanton RC



Office



Flammable Cabinet with some non-flammable products



Supply Room



Supply Room

VT Swanton RC



Clutter in Supply Room



Supply Room



Boiler Room



Boiler Room

VT Swanton RC



Boiler Room



Flammable Storage



Cold Storage



Office

Appendix D
IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Swanton	IAQ								Light		
Date	10/23/2012	Inspector	Non-Responsive	Instrument	Q-trak 7565-X								Instrument	Cal-Light 400
Facility Description	Swanton RC			Serial Number	7565X0839019								Serial Number	K070003
Weather Conditions	Cool and Sunny			Last Calibration	Mar-12								Last Calibration	16-Apr-12
Location/Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)	
Drill Hall	10	1203	68.7		44.6		550		8.7		25.0	X	50	
Cold Storage #1	1	1204	66.7	X	44.0		493		5.7		12-15	X	30	
Caretaker Office	1	1206	68.1		45.5		566		0.9		36.0		30-50	
Kitchen	1	1207	72.7		38.5		435		0.3		60-90		50	
Kitchen Storage	1	1208	74.2		36.2		462		0.3		30-60		10	
Women's Latrine	1	1209									8-25		5	
Janitor's Closet	1	1210									6	X	30	
Locker & Bunk Room	1	1211	69.6		47.2		502		3.0		9-18	X	30	
Locker Storage Area Office	1	1215	69.1		48.8		496		2.0		9-18	X	30-50	
Storage Room #1	1	1216	68.8		48.4		466		2.3		21-43	X	30	
Storage Room #2	1	1217	68.7		48.6		468		1.6		38-66		30	
Recruiter's Office	2	1218	70.1		42.9		563		0.0		30-80		30-50	
ISG Office	1	1220	71.1		40.3		428		0.0		19-20	X	30-50	
Classroom	1	1223	70.7		43.6		427		0.2		13-32	X	30-50	
Fitness Center	1	1225	71.7		42.8		416		0.0		10-44	X	30	
Telecom Room	1	1225									15	X	30	
Training Center Office	4	1227	72.7		52.0		1700	X	4.1		38-72		30-50	
Supply Room	1	1230	69.1		48.1		420		2.8		10-44	X	30	
Boiler Room	1	1237	79.0		37.9		495		1.2		35-134		30	
Cold Storage #2	1	1240	69.5		41.4		555		6.8		12-20	X	30	
Office	2	1333	69.5		43.4		453		0.0		10-21	X	30	
Outside	1	1335	58.2		37.9		370		0.1					

Shaw Environmental, Inc.

312 Directors Drive
Knoxville, TN 37923
865.690.3211
Fax 865.690.3626



Shaw Environmental, Inc.

**National Guard Armory
Vergennes Readiness Center – Vergennes, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

01 March 2004

**National Guard Armory
Vergennes Readiness Center – Vergennes, Vermont
Industrial Hygiene Evaluation**

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

04 January 2004

Prepared by:

Non-Responsive

Industrial Hygienist

Reviewed by:

Non-Responsive

Business Line Manager

Table of Contents

<i>Table of Contents</i>	<i>i</i>
<i>List of Tables</i>	<i>ii</i>
<i>List of Appendices</i>	<i>ii</i>
<i>Executive Summary</i>	<i>F-1</i>
<i>1.0 Introduction</i>	<i>1-1</i>
<i>2.0 Findings, Discussion, and Interpretation of Results</i>	<i>2-1</i>
<i>2.1 Sampling for Lead</i>	<i>2-1</i>
<i>2.1.1 Wipe Sampling</i>	<i>2-1</i>
<i>2.1.2 Air Sampling for Lead</i>	<i>2-2</i>
<i>2.2 Physical Condition of Facility</i>	<i>2-2</i>
<i>2.2.1 Peeling Paint - Lead</i>	<i>2-2</i>
<i>2.2.2 Visual Inspection - Asbestos</i>	<i>2-2</i>
<i>2.2.3 Visual Inspection - Water Damage and Mold</i>	<i>2-3</i>
<i>2.2.4 Visual Inspection - Housekeeping</i>	<i>2-3</i>
<i>2.3 Building Concerns</i>	<i>2-3</i>
<i>2.3.1 Ergonomic Concerns</i>	<i>2-3</i>
<i>2.3.2 Indoor Air Quality</i>	<i>2-3</i>
<i>2.4 Safety and Industrial Hygiene Programs</i>	<i>2-4</i>
<i>2.5 Ventilation</i>	<i>2-4</i>
<i>2.5.1 Ventilation System Evaluation</i>	<i>2-4</i>
<i>2.5.2 Contamination of Clean Air Sources</i>	<i>2-4</i>
<i>2.6 Noise Exposure</i>	<i>2-4</i>
<i>2.7 Lighting</i>	<i>2-4</i>
<i>2.8 Converted Indoor Firing Ranges</i>	<i>2-5</i>
<i>2.9 HVAC Systems</i>	<i>2-5</i>
<i>2.10 IHIM</i>	<i>2-5</i>
<i>3.0 Conclusions</i>	<i>3-1</i>
<i>Tables</i>	<i>Follows Section 3.0</i>
<i>Appendices</i>	<i>Follows Tables</i>

List of Tables

Table 1	Wipe Sampling for Lead
Table 2	Air Sampling for Lead
Table 3	Indoor Air Quality Measurements
Table 4	Illumination Readings
Table 5	Indoor Firing Ranges - Wipe Sampling

List of Appendices

Appendix A	HHIM Data Form
Appendix B	Building Layout
Appendix C	Sampling Sheets and Laboratory Analyses
Appendix D	References
Appendix E	Recommendations for Surface Lead Dust in Armories

Executive Summary

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Vergennes Readiness Center in Vergennes, Vermont. **Non-Responsive** performed the evaluation on 30 July 2003 and 9 October 2003. The point of contact at the readiness center was SFC **Non-Responsive**

The following industrial hygiene concerns were evaluated.

- Wipe Sampling for Lead
- Air Sampling for Lead
- Peeling Paint – Lead
- Suspected Asbestos Containing Material
- Water Damage
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Indoor Air Quality
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- Lighting
- Converted Indoor Firing Range
- HVAC Systems

The following items were either not applicable to the armory or the evaluation resulted in a conclusion that there were no industrial hygiene concerns.

- Air Sampling for Lead
- Peeling Paint – Lead
- Housekeeping
- Ergonomic Concerns
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation

- Contamination of Clean Air Sources
- Noise Exposure
- HVAC Systems

Areas where there were industrial hygiene concerns are as follows:

- Wipe sampling for lead revealed concentrations above the recommended level at four locations in the assembly/drill hall. It is recommended that these surfaces and the areas immediately around these surfaces be thoroughly cleaned to reduce the lead level. In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.
- Wipe sampling for lead revealed concentrations above a level of 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) in the assembly hall. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.
- Materials suspected of containing asbestos were observed. An operations and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.
- Water damage was observed at the armory. The source of the water damage was likely from roof leaks, a high water table, and a breach in the building foundation. The sources of the water should be confirmed and actions taken to eliminate the source in order to prevent the possibility of mold growth that may lead to indoor air quality problems.
- Visual mold was observed at the armory. The area where the mold is located should be thoroughly cleaned with 0.5% sodium hypochlorite solution (1 part household bleach to nine parts water) or equivalent in order to eliminate the potential mold/indoor air quality problem. In addition, the source of the mold should be identified and actions taken to eliminate the source of the mold.
- Indoor air quality measurements revealed that the humidity at the armory exceeded the recommended levels. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory.
- Lighting measurements were conducted at the armory. The lighting did not meet minimum requirements in most areas; therefore consideration should be given to providing more lighting in these areas. This may be accomplished by replacing burnt out luminaires, cleaning fixtures, cleaning windows, painting walls with a lighter

color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

- Wipe sampling for lead in the converted firing range revealed a concentration above the recommended level on the floor. The floor must be decontaminated by a thorough cleaning until surface lead concentrations are reduced to below recommended levels. In addition, employees should not be allowed to work in this area without protective clothing until the area has been cleaned and re-sampled.

1.0 Introduction

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Vergennes Readiness Center in Vergennes, Vermont. **Non-Responsive** performed the evaluation on 30 July 2003 and 9 October 2003. The point of contact at the readiness center was SFC **Non-Responsive**

The findings, discussion, and interpretation of results are provided in Section 2.0. The conclusions are provided in Section 3.0. The HHIM data form for the facility is provided in Appendix A. The building layout is provided in Appendix B. Sampling sheets and laboratory analyses are provided in Appendix C. References are provided in Appendix D. The *Recommendations for Surface Lead Dust in Armories* document is provided in Appendix E.

The statements, opinions, and conclusions contained in this report are based solely upon the services performed by Shaw as described in the report. In performing these services and preparing the report, Shaw Environmental, Inc. relied upon the work and information provided by others, including public agencies, whose information is not guaranteed by Shaw Environmental, Inc.

2.0 Findings, Discussion, and Interpretation of Results

The results, discussion, and interpretation of results are provided in the following sections.

2.1. Sampling for Lead

2.1.1 Wipe Sampling

Wipe samples were collected for lead from the drill floor/assembly area. Also, wipe samples were collected for lead in rooms, hallways, foyers, etc. The sampling in rooms, hallways, foyers, etc. represented approximately 25% of the building. Approximately half of the samples were collected from surfaces in common areas, such as surfaces of a desk. The remaining samples were collected from uncommon surface areas, such as a supply vent or the top of a file cabinet. The samples were collected and analyzed in accordance with the Instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

The only samples initially submitted for analysis were those from the drill floor/assembly hall. If there were any positive results from the drill floor, the other samples would be submitted for analysis.

Results of the wipe sampling are provided in Table 1. The results revealed lead at all locations sampled at concentrations below the recommended level of 200 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$) (See Appendix B) except at four locations. Two samples on the assembly/drill hall floor had lead concentrations of 250 and 210 $\mu\text{g}/\text{ft}^2$. The sample obtained from the heater unit flap surface in the assembly/drill hall had a lead concentration of 510 $\mu\text{g}/\text{ft}^2$. The sample obtained from the fire alarm control box in the assembly/drill hall had a lead concentration of 680 $\mu\text{g}/\text{ft}^2$. It is recommended that these surfaces and the immediate areas around the surfaces be thoroughly cleaned to reduce the lead level to below 200 $\mu\text{g}/\text{ft}^2$. For guidance on the proper method of cleaning, please refer to NG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.

In addition, wipe sampling for lead revealed concentrations above a level of 40 $\mu\text{g}/\text{ft}^2$ in the assembly hall. Please note that the *Recommendations for Surface Lead Dust in Armories* (Appendix E) states that all areas should be cleaned that will be accessible to children. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.

2.1.2 Air Sampling for Lead

Breathing zone air sampling was conducted on one (1) full-time building occupant. (Please note that no state employees were monitored.) The sample was collected and analyzed in accordance with Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods.

The results of the sampling are provided in Table 2. The results revealed non-detectable concentrations of lead in the breathing zone of the employee; therefore, no actions are necessary.

2.2 Physical Condition of Facility

2.2.1 Peeling Paint - Lead

Peeling paint was not observed at the armory; therefore, bulk samples for lead in paint were not taken.

2.2.2 Visual Inspection - Asbestos

A visual inspection was made to determine if there was any suspected asbestos-containing material at the armory. Materials suspected of containing asbestos were observed. The suspected asbestos-containing materials were floor tiles in the front three offices, foyer, classroom, and Day Room (Recruiter's Office) (approximately 2503 square feet), and insulation in the boiler room (approximately 21 linear feet). The condition of the floor tiles materials was considered good since there was no damage to tiles. The condition of the boiler room insulation materials was considered good (no rips, tears, or other damage).

An operation and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.

2.2.3 Visual Inspection – Water Damage and Mold

A visual inspection was made to determine if there was any water damage or visible mold at the armory. Both visible mold and water damage was observed at the armory. The water damage was observed in the men's shower room, foyer, kitchen, kitchen storage room, and the boiler room. The visible mold or remnants of mold was observed in the men's shower room. In addition, a green algae-like substance was observed in the boiler room.

The source of the water damage was likely from roof leaks in all of the rooms except the boiler room. It was indicated that the roof has been replaced. However, attention should be given to the water damage in the men's shower room. A high water table and a breach in the building foundation is likely the source of the water damage in the boiler room.

The sources of the water damage should be confirmed and actions taken to eliminate the source in order to prevent mold growth that may lead to indoor air quality problems. The area where the mold is located should be thoroughly cleaned with 0.5% sodium hypochlorite solution (1 part household bleach to nine parts water) or equivalent in order to eliminate the potential mold/indoor air quality problem. In addition, the source of the mold should be identified and actions taken to eliminate it.

2.2.4 Visual Inspection - Housekeeping

The housekeeping was determined to be good.

2.3. Building Concerns

2.3.1 Ergonomic Concerns

Interviews with employees and observation of work activities revealed no ergonomic concerns at the armory.

2.3.2 Indoor Air Quality

Interviews with employees revealed no indoor air quality concerns at the armory. However, measurements for humidity revealed that levels exceeded the American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommended level of 60% in the armory. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory.

The results of the measurements for carbon dioxide, humidity, and temperature are provided in Table 3.

2.4. Safety and Industrial Hygiene Programs

An evaluation was performed to determine the applicability of the following programs.

- Confined Spaces
- Hearing Conservation
- Respiratory Protection
- Hazard Communication (HAZCOM)
- Personal Protective Equipment (PPE)

It was determined that the HAZCOM program was the only program listed above that was applicable at the facility. The HAZCOM program was evaluated and it was determined that the program met minimum requirements.

2.5. Ventilation

2.5.1 Ventilation System Evaluation

There were no local exhaust ventilation systems at this armory; therefore, no ventilation studies were performed.

2.5.2 Contamination of Clean Air Sources

Since there were no local exhaust ventilation systems at the armory, there was no possibility that clean air sources could be contaminated by exhaust air.

2.6. Noise Exposure

An evaluation was performed to determine if there were any hazardous noise areas at the armory. It was determined that there were no areas at the armory that would exceed the permissible exposure limit for noise.

2.7 Lighting

Lighting measurements were conducted at the armory. Results of the lighting evaluation are provided in Table 5. As can be seen from the results, the lighting did

not meet the minimum requirements in most areas, including the Kitchen, Officer's Latrine, Enlisted Men's Shower Room, Enlisted Men's Latrine, Front Office (adjacent to foyer), and Administrative Office.

Consideration should be given to providing more lighting to the areas listed above. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

2.8. Converted Indoor Firing Ranges

There was a converted indoor firing range at the facility; therefore, wipe samples were taken for lead at various locations in or near the converted range. The only remnant of the former firing range was the bullet trap area. This area was converted into a storage room. The results are provided in Table 5. The results revealed lead, with associated concentrations, at the following locations:

- floor at 430 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$);
- stored item (shelf top) at $< 110 \mu\text{g}/\text{ft}^2$.

The lead level on the floor was above the recommended level of $200 \mu\text{g}/\text{ft}^2$, a level recommended in the *Guidelines for Converting Indoor Firing Ranges to Other Uses* document (Department of Army). The floor must be decontaminated by a thorough cleaning until surface lead concentrations are reduced to below recommended levels. For guidance on the proper method of cleaning, please refer to NG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, employees should not be allowed to work in this area without protective clothing until the area has been cleaned and re-sampled.

2.9. HVAC System

There was not a HVAC system at the armory.

2.10. HIIIM

A Health Hazard Information Module (HIIIM) form was completed for the armory. The completed form is provided in Appendix A.

3.0 Conclusions

It is concluded that there were no industrial hygiene concerns at the armory with regards to atmospheric exposure to lead, peeling lead-based paint, housekeeping, ergonomic conditions, safety and industrial hygiene programs, ventilation systems or contamination of clean air sources, noise exposure, and HVAC systems.

There were industrial hygiene concerns at the armory with regards to lead surface contamination, suspected asbestos-containing material, water damage, visible mold, indoor air quality, surface lead contamination in the converted firing range, and lighting. These concerns are discussed in detail in Section 2.0 of this report.

TABLES

Table 1
Wipe Sampling for Lead
National Guard Armory
Vergennes, Vermont
Dates of Sampling: 30 July 2003 and 9 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTVER210-1	Drill Floor (See Building Layout - Appendix B)	250
VTVER210-2	Drill Floor (See Building Layout - Appendix B)	< 110
VTVER210-3	Drill Floor (See Building Layout - Appendix B)	< 110
VTVER210-4	Drill Floor (See Building Layout - Appendix B)	< 110
VTVER210-5	Drill Floor (See Building Layout - Appendix B)	210
VTVER210-6	Field Blank	< 12 μg
VTVER210-9	Classroom - shelf surface	< 110
VTVER210-10	Kitchen - microwave top surface	< 110
VTVER210-11	Administrative Office - desktop	< 110
VTVER210-12	Field Blank	< 12 μg
VTVER210-13	Recruiter's Office - desktop	< 110
VTVER210-14	Supply Room Office - desktop	< 110
VTVER283-1	Assembly Room - heater unit flap surface (See Building Layout - Appendix B)	510
VTVER283-2	Assembly Room - fire alarm control box top surface (See Building Layout - Appendix B)	680
VTVER283-3	Assembly Room - top of soda machine (See Building Layout - Appendix B)	97
VTVER283-4	Assembly Room - shelf top (See Building Layout - Appendix B)	74
VTVER283-5	Assembly Room - table top (See Building Layout - Appendix B)	33
VTVER283-6	Field Blank	0.47 μg

^aMicrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of Army National Guard Armories* procedure.

In armories that do not contain childcare facilities, the NGB Region North Industrial Hygiene Office recommends cleaning the areas with lead concentrations greater than 200 $\mu\text{g}/\text{ft}^2$.

Table 2
Breathing Zone Air Samples for Lead
National Guard Armory
Vergennes, Vermont
Date of Sampling: 30 July 2003

Sample Number	Employee	Sampling Information			Results (mg/m ³) ^a
		Time Sampled / Minutes	Flow Rate (lpm) ^b	Volume (liters)	
VTVER210-A1	Non-Responsive	1447-1631/104	2.497	259.68	<0.004
VTVER210-A2	Field Blank	-	-	-	None Detected

^a Milligrams lead per cubic meter of air.

^b Liters of air per minute.

Only one employee was sampled because there were no other employees at the armory on the date of the survey.

Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods was followed for sampling for lead.

Table 3
Indoor Air Quality Measurements for Carbon Dioxide, Humidity, and Temperature
National Guard Armory
Vergennes, Vermont
Date of Sampling: 30 July 2003

Location	Occupants in Area	Carbon Dioxide, parts per million parts of air (ppm)	Percent (%) Humidity	Temperature (°F)
1 st Floor - Classroom	1	466	60.8	75.9
Outdoors	0	414	61.2	77.6

Carbon dioxide, humidity, and temperature measurements were taken with a TSI Q Trak Plus, Model 8554, Indoor Air Quality Meter, calibrated in April 2003.

American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommends that indoor carbon dioxide levels be less than 700 ppm above outdoor levels.

ASHRAE recommends that the relative humidity levels be maintained between 30 to 60 percent.

ASHRAE recommends that the acceptable temperature range be 68 degrees Fahrenheit to 74 degrees Fahrenheit in the winter and 73 degrees Fahrenheit to 79 degrees Fahrenheit in the summer.

Table 4
Illumination Readings
National Guard Armory
Vergennes, Vermont
Date of Sampling: 30 July 2003

Location	Luminance (fc) ^a	Standard (fc) ^a	Standard Met
Converted Firing Range (Storage Room) 1	18.9-42.3	30	Some Areas
Converted Firing Range (Storage Room) 2	21.1-43.6	30	Some Areas
Kitchen	21.3-55.1	70	No
Officer's Latrine	2.6-10.1	40	No
Enlisted Men's Shower Room	2.6-14.1	20	No
Enlisted Men's Latrine	1.1-10.1	40	No
Locker room area	21.7-44.3	40	Some Areas
Front Office (adjacent to foyer)	21.3-57.7	70	No
Administrative Office	30.0-64.2	70	No
Supply Room	16.2-38.2	30	Some Areas
Recruiter's Office	33.1-76.7	70	Some Areas

^afc - Footcandles

The readings were taken with a Cooke Corporation cal-LIGHT 400 Calibrated Precision Lightmeter, calibrated on 19 Aug 2002.

The standards listed above are from ANSI/IES RP-1 and RP-7.

Table 5
Wipe Sampling for Lead – Converted Firing Range
National Guard Armory
Vergennes, Vermont
Date of Sampling: 30 July 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTVER210-7	Floor	620
VTVER210-8	Stored Item - shelf top	<10

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of Army National Guard Armories* procedure.

Appendix A

HHIM Data Form(s)

HEALTH HAZARD INFORMATION MODULE: INDUSTRIAL HYGIENE SURVEY

(For use of this form, see HHIM User's Guide)

SECTION 1. DEMOGRAPHIC DATA

RLOC Vergennes Vermont		INSTALLATION Vergennes Armory Vermont ARNG		BLDG/RM NO. Vergennes	
LOCATION/CODE Administrative Areas / AA			OPERATION/CODE Administrative OP/ADG		
SURVEY DATE 30 July 2003			EVALUATOR (Initials) Non-Responsive		
MACOM/CODE Army National Guard		SUBMACOM/CODE KK		SUPERVISOR Non-Responsive : SFC	
TELEPHONE/DSN NO. 802-877-2982		UNIT/ORGANIZATION 1 Battalion (155 MM SP) 8th Field Artillery		RAC 4	FREQUENCY (hrs/day) 8
NO. CIV(S) 1	NO. MIL 4	NO. CONTRACTOR(S) 0	NO. LOC(S) 0	NO. OTHER 0	

SECTION 2. FACILITY DATA

LAB HOODS 0	VAPOR DEGREASERS 0	SPRAY BOOTHS 0
MAINTENANCE BAYS 0	OPEN SURFACE TANKS 0	VENTILATION UNITS 0

SECTION 3. SURVEY DATA

CONTROLS PRESENT	EVALUATION	UNIT CODE	CONTROLS REQUIRED	STATUS

PERSONAL PROTECTIVE EQUIPMENT (R = Required; U = Utilized)

GLOVES	R	U	RESPIRATOR	NIOSH TC NO.	MANUFACTURER	R	U
ACID			AIRLINE				
COLD SURFACES			ABRASIVE BLASTING HOOD				
HOT SURFACES			DISPOSABLE				
NBC AGENTS			FULL FACE AIR PURIFYING				
OIL			1/2 FACE AIR PURIFYING				
SOLVENTS			POWERED AIR PURIFYING				
SURGICAL GLOVES			1/4 FACE AIR PURIFYING				
			SELF CONTAINED				

EYES/FACE	R	U	HEARING	R	U	BODY	R	U	HEAD/FIT	R	U
CHEMICAL SPLASH			CANAL CAPS			APRONS			COLD WEATHER BOOTS/HATS		
FULL FACE SHIELD			EAR PLUGS			COLD WEATHER CLOTHING			HARD HATS		
CHEMICAL/SAFETY			HELMETS			COVERALLS			IMPERMEABLE BOOTS		
SAFETY/IMPACT			MUFFS			FULL BODY SUIT			SAFETY/CONDUCTIVE SHOES		
WELDING HELMET			MUFF/EARPLUG COMBO			HEAT REFLECTIVE VEST/SUIT			SAFETY/NON-CONDUCTIVE SHOES		
			MUFF/EARPLUG W/TIME LIMIT			SAFETY BELT/HARNES					

SECTION 4. HAZARD INVENTORY DATA

CAS CODE	HAZARD DESCRIPTION	PAC	EPC
FOVDTXXX	Video Display Terminal	3-low	uncontrolled D Physical
7439-92-1	lead, inorganic dusts & fumes, as Pb	2-moderate	uncontrolled Respiratory
1332-21-4	Asbestos (other)	2-moderate	uncontrolled Respiratory

SECTION 5. PERSONNEL DATA

LAST NAME	FIRST NAME	MI	SEX	SSN	CATEGORY
Non-Responsive				Non-Responsive	MIL
				Non-Responsive	MIL
				Non-Responsive	MIL
				Non-Responsive	MIL
				Non-Responsive	CIV

SECTION 6. COMMENTS

No comments See attached sheet
 Survey was conducted by Michele Serrano. Building contains 4 military employees (full-time) and 1 civilian caretaker (part-time). Employees perform mostly administrative functions.

PRIVACY ACT STATEMENT

Title 5 US Code, Section 301; Executive Order 9397 authorizes the use of your Social Security Number as an identification number. The purpose of this information is to identify and monitor data relating each DA civilian and military employee exposed to a hazardous workplace or operation. The use of this information is to provide histories of exposures for any given worker.

Disclosure of your Social Security Number is not mandatory; however, nondisclosures may result in untimely provision of proper medical monitoring.

Appendix B

Building Layout


BATTERY B
 1 Battalion (155MM SP) 86 Field Artillery
 State Armory, Vergennes, Vermont, 05491

SUBJECT: Fire Plan

1. Four (4) fire extinguishers are located on the drill hall floor:
 - (a) Dry Chemical - Located between kitchen and boiler room
 - (b) Dry Chemical - Located between water fountain and EM latrine
 - (c) Dry Chemical - Located just to right of Day Room door
 - (d) Dry Chemical - Located just to right of Supply Room door

2. The individual who discovers a fire will shout "FIRE" in a loud voice and turn in the alarm to the Vergennes Fire Department by telephone (877-2616). Any and all individuals under the direction of the Fire Marshall will return to the fire and try to extinguish it.

3. The following evacuation plan will be followed when a fire is discovered:



○ Source date: 30 July 2003

△ Source date: 09 October 2003

Appendix C

Sampling Sheets and Laboratory Analyses

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301-H Old Bay Lane, Attn: NGB-AVN-SL, State Military Reservation
 Havre de Grace, Maryland 21078
Job Name: VTVR210
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01
Chain Of Custody: 116190
Date Analyzed: 8/8/2003
Person Submitting: [Redacted]
Report Date: 08-Aug-03

Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0361014	VTVR210-1	Flame	Wipe	****	0.111	108.00 ug/ft ²	250 ug/ft ²	
0361015	VTVR210-2	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0361016	VTVR210-3	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0361017	VTVR210-4	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0361018	VTVR210-5	Flame	Wipe	****	0.111	108.00 ug/ft ²	210 ug/ft ²	
0361019	VTVR210-6	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0361020	VTVR210-7	Flame	Wipe	****	0.111	108.00 ug/ft ²	620 ug/ft ²	
0361021	VTVR210-8	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)

%Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Non-Responsive

Non-Responsive

Analyst:

Technical Manager:

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301-1H Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTVR210
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01

Chain Of Custody: 115943
Date Analyzed: 08/18/2003
Person Submitting: [Redacted]
Report Date: 18-Aug-03

Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft²)	Reporting Limit	Final Result	Comments
0362698	VTVR210-9	Flame	Wipe	****	0.111	108.01 ug/ft²	< 110 ug/ft²	
0362699	VTVR210-10	Flame	Wipe	****	0.111	108.01 ug/ft²	< 110 ug/ft²	
0362700	VTVR210-11	Flame	Wipe	****	0.111	108.01 ug/ft²	< 110 ug/ft²	
0362701	VTVR210-12	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0362702	VTVR210-13	Flame	Wipe	****	0.111	108.01 ug/ft²	< 110 ug/ft²	
0362703	VTVR210-14	Flame	Wipe	****	0.111	108.01 ug/ft²	< 110 ug/ft²	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnaces: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] Technical Manager: [Redacted]

BEST AVAILABLE COPY

BEST AVAILABLE COPY

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples; and transmission electron microscopy of AHERA air samples.

All rights reserved. AMA Analytical Services, Inc.

Client: National Guard Bureau
Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SI,
 State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTGRE283
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 0701

Chain Of Custody: 118714
Date Analyzed: 10/21/2003

Person Submitting: [Redacted]
Report Date: 21-Oct-03

Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0402892	VTGRE283-1	Furnace	Wipe	****	0.111	67.51 ug/ft ²	510 ug/ft ²	
0402893	VTGRE283-2	Furnace	Wipe	****	0.111	135.01 ug/ft ²	680 ug/ft ²	
0402894	VTGRE283-3	Furnace	Wipe	****	0.111	13.50 ug/ft ²	97 ug/ft ²	
0402895	VTGRE283-4	Furnace	Wipe	****	0.111	13.50 ug/ft ²	74 ug/ft ²	
0402896	VTGRE283-5	Furnace	Wipe	****	0.111	5.40 ug/ft ²	33 ug/ft ²	
0402897	VTGRE283-6	Furnace	Wipe Blank	****	N/A	0.30 ug	0.47 ug	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)

%Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] Technical Manager: [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

All rights reserved. AMA Analytical Services, Inc.

An AIHA (#8863), NVLAP (#101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643



Submitted To: **Non-Responsive**
 Shaw Environmental, Inc.
 101 Fieldcrest Ave., 4th Floor
 Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTRED210-A2 through VTWIN210-A3
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Filter
Method Reference:	NIOSH 7300
DCL Set ID No.:	03-S-3799
DCL Sample ID No.:	03-23284 through 03-23312
Sample Receipt Date:	8/4/2003
Preparation Date:	08/07/03
Analysis Date:	08/07/03

The samples were prepared and analyzed in accordance with NIOSH method 7300 using a Perkin Elmer 3000XL ICP.

The sample condition upon receipt was acceptable except where noted.

The results are in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive

Analyst

Non-Responsive

Reviewer

CINCINNATI OFFICE
 4388 GLENDALE-MILFORD ROAD
 CINCINNATI, OHIO 45242-3706
 513 733-5336, FAX 513 733-5347


WEST COAST OFFICE
 11 SANTA YORMA COURT
 NOVATO, CALIFORNIA 94945
 800 280-8071, FAX 415 893-9469

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTRED210-A2	03-23284	0	ND	-
VTNEW209-A1	03-23285	210.24	ND	<0.005
VTNEW209-A2	03-23286	0	ND	-
VTBRA209-A1	03-23288	197.36	ND	<0.005
VTBRA209-A2	03-23289	0	ND	-
VTLYN209-A1	03-23290	186.67	ND	<0.005
VTLYN209-A2	03-23291	187.06	ND	<0.005
VTLYN209-A3	03-23292	0	ND	-
VTNOR213-A1	03-23293	376.81	ND	<0.003
VTNOR213-A2	03-23294	0	ND	-
VTLUD212-A1	03-23297	157.79	ND	<0.006
VTLUD212-A2	03-23298	275.40	ND	<0.004
VTLUD212-A3	03-23299	0	ND	-
VTWIN212-A1	03-23305	173.64	ND	<0.006
VTWIN212-A2	03-23306	0	ND	-
VTVER210-A1	03-23307	259.68	ND	<0.004
VTVER210-A2	03-23308	0	ND	-
VTRED210-A1	03-23309	158.68	ND	<0.006
VTWIN210-A1	03-23310	218.92	ND	<0.005
VTWIN210-A2	03-23311	193.56	ND	<0.005
VTWIN210-A3	03-23312	0	ND	-
	Prep Blank		ND	
% Recovery	LCS		99.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).
LCS = laboratory control sample.

Non-Responsive



Analyst

Non-Responsive



Reviewer

Industrial Hygiene Sampling Calculation Worksheet

National Guard Armory **Location:** **VER**
Date: 7/30/2002

Sample 1

Sample Number: **VTVER210-A1**
Pump: **648339**

	Pre Flow Rate	Post Flow Rate
	2.529	2.47
	2.537	2.475
	2.525	2.472
	2.497	2.47
Average	2.522	2.472

Average Pre and Post **2.4969**

Time 1 **14:47**
Time 2 **16:31**
Total Time Sampled **1:44**
Minutes Sampled **104.00**

Volume **259.68 Liters**

Sample 2

Sample Number: **N/A**
Pump: **N/A**

	Pre Flow Rate	Post Flow Rate
	N/A	N/A
Average	N/A	N/A

Average Pre and Post **N/A**

Time 1 **N/A**
Time 2 **N/A**
Total Time Sampled **N/A**
Minutes Sampled **N/A**

Volume **N/A** **Liters**

Appendix D

References

References

Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration (current edition)

American Society of Heating, Refrigerating and Air-Conditioning Engineers, Inc (ASHRAE) 62-2002, Ventilation for Acceptable Indoor Air Quality

Instructions for Completing the Sampling of Army National Guard Armories, Lead Wipe Sampling Procedure included with the Request for Proposal

Air Sampling for Lead - Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods

Design Guide DG-415-2, Logistics Facilities, National Guard Bureau Installation Division, 14 December 1999

Department of Defense Instruction (DDI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998

Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, 15 October 1990

AR 385-10, The Army Safety Program, 29 February 2000

Department of the Army Pamphlet (DA PAM) 40-501, Medical Services, Hearing Conservation Program, 10 December 1998

DA PAM 40-503, Medical Services, Industrial Hygiene Program, 30 October 2000

Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH) (current edition)

Guidelines for Converting Indoor Firing Ranges to Other Uses, Headquarters, Department of the Army and the Air Force, NG PAM (AR) 385-16/ANGPAM 91-101, 31 January 1994

24 CFR, Part 35, Subpart B, Section 35-110, Definition of Lead-Based Paint, Housing and Urban Development, U. S. Department of Housing

Appendix E
Recommendations for
Surface Lead Dust in Armories

Subject: Recommendations for Surface Lead Dust in Armories

1. In armories that do not contain childcare facilities, the National Guard Bureau (NGB) Region North Industrial Hygiene Office recommends cleaning the areas in which sample results are greater than 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$). If a special function will be held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function. This guidance is based on professional judgment, risk assessments, adaptation of Occupational Safety and Health Administration (OSHA) guidance, and feasibility of cleaning to a certain level.

a. Environmental Protection Agency (EPA) standards (40 Code of Federal Regulations (CFR) 745.227(h)(3)) are not directly applicable because they are criteria for dust-lead hazards developed for floors ($40 \mu\text{g}/\text{ft}^2$) and windowsills ($250 \mu\text{g}/\text{ft}^2$) in residential dwellings and child occupied facilities. A child occupied facility is defined as a building, or portion of a building, constructed prior to 1978, visited regularly by the same child, 6 years of age or under, on at least two different days within any week (Sunday through Saturday period), provided that each day's visit lasts at least 3 hours and the combined weekly visit lasts at least 6 hours, and the combined annual visits last at least 60 hours. Most of the wipe samples in armories were collected in undisturbed areas and therefore, results are worst case scenarios and do not correlate to these standards.

b. OSHA has no specific requirement for work area surfaces. The lead standard (29 CFR 1910.1025(h)) states that all surfaces shall be maintained as free as practicable of accumulations of lead dust. In workplaces where lead dust is generated, surface levels may be much higher, but personnel exposures can be controlled by limiting airborne lead levels and following good cleanup and hygienic practices.

c. OSHA used to cite a level of $200 \mu\text{g}/\text{ft}^2$ in their Technical Manual and 29 CFR 1926.62 as guidance to its own inspectors for evaluating the cleanliness of lunchroom and locker room surfaces that are supposed to be kept as clean as possible.

d. In a report titled Derivation of Wipe Surface Screening Levels for Environmental Chemicals, the US Army Center for Health Promotion and Preventive Medicine (USACHPPM) has determined that $200 \mu\text{g}/\text{ft}^2$ is a safe surface contamination level. They have also applied these standards as the decontamination levels for surfaces in administrative offices.

e. It should be noted that levels above these recommendations do not necessarily mean there is a significant hazard to workers who are following good cleaning and hygienic practices since there is no correlation between wipe and air samples. Rather, we recommend these levels as a precautionary measure.

2. The NGB Occupational Health Branch is developing guidance for armories that are used as childcare facilities. All states will receive this guidance when it is completed. In the interim, we recommend the following actions:

a. Clean all areas that will be accessible to children to the EPA dust-lead standard for children 6 years of age or under ($40 \mu\text{g}/\text{ft}^2$ on floors and $250 \mu\text{g}/\text{ft}^2$ on windowsills).

b. Refer to the local authorities' regulations since they can be more stringent than federal regulations.

c. Post signs in the area to inform people of the presence of lead dust and its effects.

d. If soldiers clean weapons in the facility change the policy so that they cannot clean their weapons in the facility, or if they are allowed to clean their weapons indoors, they must clean the area by wet wiping and mopping the area when they are done.

e. If the paint is peeling, contact the state Environmental Office to test for lead content and provide recommendations.

3. Air samples collected on individuals in the armory were well below OSIA's permissible exposure limit for lead (29 CFR 1910.1025(c)) of $0.05 \text{ mg}/\text{m}^3$ averaged over an 8-hour day. Therefore, based on these conditions there is currently no overexposure to personnel from lead dust in this building.

Industrial Hygiene Survey

Vermont Army National Guard (VT ARNG)

Prepared For: NGB ARNG– Region North IH Office

Survey Location:

Vergennes Readiness Center
37 Monkton Road
Vergennes, VT 05491

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 19, 2012

AEI Project #: J12-685 3M VT Vergennes RC

Non-Responsive, DrPH, CIH
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Vergennes Readiness Center**

Table of Contents

Section	Page
Executive Summary	ii
1 Introduction.....	1
2 Evaluation Methods.....	1
3 Operations.....	1
4 Noise Hazards	1
5 Hazard Controls	1
Ventilation Systems	1
6 Physical Condition of the Facility and Personnel Concerns	2
Paint Chip and Dust Wipe Samples for Lead Contamination	2
Visual Inspection for Damaged Asbestos-Containing Materials	3
Visual Inspection for Water Damage and Mold Growth.....	3
Visual Inspection for Housekeeping Concerns.....	3
Lighting	3
Indoor Air Quality (IAQ)	4
Temperature and Relative Humidity.....	4
Carbon Dioxide (CO2) and Carbon Monoxide (CO)	4
Additional Information	5
7 Conclusions.....	5
8 Limitations.....	5
9 References	5

List of Tables

Table 1 – Results of Lead Paint Chip Sampling for VT ARNG Vergennes Readiness Center on October 19, 2012

Table 2 - Results of Dust Wipe Sampling for the VT ARNG Vergennes Readiness Center on October 19, 2012.

Table 3 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

List of Appendices

Appendix A – Building Layout

Appendix B – Certificates of Analysis for Air, Dust Wipe and Bulk Samples

Appendix C – Photographic Documentation

Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Vergennes Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Vergennes Readiness Center located at 37 Monkton Road, Vergennes, VT 05491. **Non-Responsive**, DrPH, CIH performed the evaluation on October 19, 2012. The point of contact for the facility was SSG **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. No peeling paint was observed. Results of dust wipe samples taken throughout the facility were below the recommended maximum criterion for surface contamination of lead (200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$)) in all areas sampled except for a sample collected from the louver on the Modine Unit located near the former indoor firing range bullet trap in the Drill Hall (3,600 $\mu\text{g}/\text{ft}^2$).

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there were any suspect asbestos-containing material and its condition. No damaged suspect asbestos-containing material was observed. The boiler room was abated and a new boiler was installed in the week prior to the survey. Asbestos signs are still posted on the boiler room door.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No evidence of wet areas or mold growth was observed on the day of the survey. Facility personnel indicated that the boiler room flooded regularly before the site was regraded and new pavement was installed. Mold and fungus removal was performed in the boiler room.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping appeared to be acceptable overall.

Lighting: A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in a few areas including the: platoon room, office 1, gym, cage storage, boiler room, kitchen and drill hall. The light fixtures in the boiler room were not installed after the boiler replacement project. The illumination measurements indoors ranged from 4.5 foot candles (fc) to 84.0 fc.

Indoor Air Quality: Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 66.9 to 69.6° F and 49.2 to 56.8% Rh. Temperatures were just below the lower end of the winter temperature range for thermal comfort in all but ten of the locations monitored. The outdoor temperature and relative humidity was 54° F and 67.8% on the day of monitoring. Indoor levels of CO₂ ranged from 404 to 856 parts per million (ppm). CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange. Indoor levels of CO ranged from 3.3 to 3.8 ppm; therefore, concentrations are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Vergennes Readiness Center**

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was readily available. MSDSs were last updated in April of 2012.

The National Fire Protection Association (NFPA) diamond found on the outdoor hazardous materials/hazardous waste storage cabinet was not complete. No warning numbers or special symbols were placed on the NFPA diamond.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Vergennes Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Vergennes Readiness Center located at 37 Monkton Avenue, Vergennes, VT 05491. **Non-Responsive**, DrPH, CIH performed the evaluation on October 19, 2012. The point of contact for the facility was SSG **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

The Vergennes Readiness Center was built in the 1950's. The readiness center is staffed by 2 administrative personnel and one civilian. The operations conducted at the facility include training and administrative duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the Vergennes Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) evaluations of operations including operation description, sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the Vergennes facility consist exclusively of supply and administrative duties. No maintenance of vehicles or other physical tasks are performed at the facility.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Vergennes Readiness Center**

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were collected in select areas.

Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. No peeling paint was observed.

To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected by wiping a Ghost Wipe over a measured area. The Environmental Protection Agency (EPA) and the State of Vermont limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA Analytical for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. All wipe samples collected from the facility were below the recommended maximum except for the sample collected from the Modine Unit louvers in the drill hall near the former indoor firing range bullet trap (3,600 $\mu\text{g}/\text{ft}^2$). Results are given in Table 1 and certificates of analysis are included in Appendix B.

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
Vergennes Readiness Center on October 19, 2012.**

Wipe Sample Number	Sample Location	Wipe Dimensions	Lead ($\mu\text{g}/\text{ft}^2$)*
VRC-1	Drill Hall – Top of Family Readiness kid's activity table. Along east wall between men's room and AED.	100 cm ²	<110
VRC-2	Drill Hall – one foot northwest of stenciled No. 5 on the floor – Floor	100 cm ²	<110
VRC-3	Drill Hall – Supply Room counter	100 cm ²	<110
VRC-4	Drill Hall – Modine Heater Louver – Northwest corner bottom louver	1.75 inches x 19.5 inches	3,600
VRC-5	Drill Hall – 20 ft south of north wall, 18 ft west of east wall – Floor	100 cm ²	<110
VRC-6	Kitchen – east wall southern window sill	100 cm ²	<110
VRC-7	Vault – 7 ft west of east wall, 4 ft south of north wall – Floor	100 cm ²	<110

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Vergennes Readiness Center**

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
Vergennes Readiness Center on October 19, 2012.**

Wipe Sample Number	Sample Location	Wipe Dimensions	Lead ($\mu\text{g}/\text{ft}^2$)*
VRC-8	Broom Closet Storage (Former Bullet Trap) – Floor	100 cm ²	<110
VRC-9	Hazmat Storage (Former Bullet Trap) Floor	100 cm ²	<110
VRC-10	Hazmat Storage on Storage Cabinet	100 cm ²	120
VRC-11	Drill Hall at entrance to Storage Rooms (Former Range) – 8 ft south of North wall, 25 ft east of west wall – Floor	100 cm ²	<110
VRC-12	Office 1 – Top of Hutch on west wall	100 cm ²	<110
VRC-13	Office 2 – Window sill on south wall	100 cm ²	<110

*The recommended maximum level for adult exposures is 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) lead on surfaces.

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). No damaged, suspect asbestos-containing material was observed. The boiler room was abated and a new boiler was installed in the week prior to the survey. Asbestos signs are still posted on the boiler room door.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or visible mold growth was observed. Facility personnel indicated that the boiler room flooded regularly before the site was regraded and new pavement was installed. Mold and fungus removal was performed in the boiler room.

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping appeared to be acceptable overall.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on April 16, 2012, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in a few areas including the: platoon room, office 1, gym, cage storage, boiler room, kitchen, and drill hall. The light fixtures in the boiler room were not installed after the boiler replacement project. The illumination measurements indoors ranged

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Vergennes Readiness Center**

from 4.5 foot candles (fc) to 84.0 fc. The complete results of the evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Model 7656x, factory calibrated in July, 2012. Temperature, relative humidity and carbon dioxide (CO₂) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 2. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30 and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 66.9 to 69.6° F and 49.2 to 56.8% Rh. Temperatures were just below the lower end of the winter temperature range for thermal comfort in all but ten of the locations monitored. The outdoor temperature and relative humidity was 54° F and 67.8% on the day of monitoring.

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1–2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 404 to 856 parts per million (ppm). CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange.

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 3.3 to 3.8 ppm; therefore, concentrations

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Vergennes Readiness Center**

are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

Additional Information

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was readily available. MSDS were last updated in April of 2012. The National Fire Protection Association (NFPA) diamond found on the outdoor hazardous materials/hazardous waste storage cabinet was not complete. No warning numbers or special symbols were placed on the NFPA diamond.

7 Conclusions

The results of the evaluation indicated few concerns at the facility. Overall, the Vergennes Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.

9 References


1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.
3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.
4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Vergennes Readiness Center**

5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2011.
6. Army Regulation (AR) 420-70 Buildings and Structures, 11 November 1997.
7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 13 December 2007.
8. Army Regulation (AR) 420-1 Army Facilities Management, 12 February 2008, RAR 24 August 2012.
9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.
10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.
12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.
13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".
15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.
19. National Fire Protection Association (NFPA) 70: National Electrical Code (NEC) 2011.
20. National Guard Pamphlet (NG PAM) 420-15, Guidelines and Procedures for Rehabilitation and Conversion of Indoor Firing Ranges, November 3, 2006.

Appendix A Building Layout

BEST AVAILABLE COPY



Key:

- Lead Wipe Sample Location and Sample Number



Vergennes VT Readiness Center
 Industrial Hygiene Survey
 Floor Plan and Sample Location Plan
 October 19, 2012

Aria Environmental, Inc.

BEST AVAILABLE COPY

Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples



CERTIFICATE OF ANALYSIS



Client: National Guard Bureau	Job Name: VT ARNG 3M IH Surveys	Chain Of Custody: 514299
Address: 301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location: Vergennes	Date Submitted: 10/24/2012
	Job Number: J12-685	Person Submitting: Non-Responsive
	P.O. Number: W912K6-09-A-0003	Date Analyzed: 11/2/2012 Report Date: 11/2/2012
Attention: Non-Responsive		

Summary of Atomic Absorption Analysis for Lead

Page 1 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
13008772	VRC-1	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008773	VRC-2	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008774	VRC-3	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008775	VRC-4	Flame	Wipe	****	0.237	51 ug/ft ²	840	3600 ug/ft ²	
13008776	VRC-5	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008777	VRC-6	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008778	VRC-7	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008779	VRC-8	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008780	VRC-9	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008781	VRC-10	Flame	Wipe	****	0.108	110 ug/ft ²	12	120 ug/ft ²	
13008782	VRC-11	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008783	VRC-12	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008784	VRC-13	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS



Client: National Guard Bureau	Job Name: VT ARNG 3M IH Surveys	Chain Of Custody: 514299
Address: 301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location: Vergennes	Date Submitted: 10/24/2012
	Job Number: J12-685	Person Submitting: Non-Responsive
	P.O. Number: W912K6-09-A-0003	Date Analyzed: 11/2/2012 Report Date: 11/2/2012
Attention: Non-Responsive		

Summary of Atomic Absorption Analysis for Lead

Page 2 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	----------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm)
 %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb)

See QC Summary for analytical results of quality control samples associated with these samples.

Note: All samples were received in good condition unless otherwise noted.

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Air and Wipe results are not corrected for any blank results
 Final results for air and wipe samples are based on client supplied information nor verified by this laboratory.

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Analyst: Non-Responsive

Technical Manager: Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.

Appendix C Photo Documentation

VT Vergennes RC



Photo 1: Dedication plaque at Vergennes dated 1962.



Photo 2: Improperly secured compressed gas cylinder.



Photo 3: Fire extinguisher tags did not indicate recent inspection.



Photo 4: Typical cold storage.

VT Vergennes RC



Photo 5: Typical cold storage.



Photo 6: Inside storage unit.



Photo 7: Storage locker located in fenced outdoor storage area. Note: the NFPA signage is missing applicable hazard classifications.



Photo 8: Assembly Hall.

VT Vergennes RC



Photo 9: Storage room.



Photo 10: Arms vault.



Photo 11: Storage room.



Photo 12: Flammable materials storage room.

VT Vergennes RC



Photo 13: Inside flammable materials storage cabinet.



Photo 14: Inside flammable materials storage cabinet.



Photo 15: Kitchen.



Photo 16: Boiler room – post renovation.

VT Vergennes RC



Photo 17: Area of assembly hall formerly used as firing range bullet trap.



Photo 18: Platoon room.

Appendix D IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Vergennes	IAQ							Light			
Date	10/19/2012	Inspector	Non-Responsive	Instrument		Q-trak 7565-X					Instrument	Cal-Light 400L		
Facility Description	Vergennes RC			Serial Number		7565x1228004					Serial Number	K040084EL		
Weather Conditions	Rainy			Last Calibration		Jul-12					Last Calibration	16-Apr-12		
Location	Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
Office 1	Office	1	1015	69.6		51.7		550		3.8		27.7	X	30-50
Entry Vestibule	Corridor	var	1016	68.7		51.9		479		3.8		15.3		10
Classroom	Classroom	var	1017	67.7	L	56.6		422		3.8		63.7		30-50
Family Support	Office	1	1018	68.3	L	55.0		450		3.8		84.0		30-50
Server Room	Server	1	1019	68.9		55.0		438		3.6		78.0		30-50
Cage Storage	Storage	1	1020	67.1	L	52.5		440		3.5		4.5	X	10
Gym	Gym	1	1021	66.9	L	53.1		438		3.8		12.6	X	30-50
Boiler Room	Boiler Room	1	1022	67.6	L	54.0		453		3.3		4.8	X	30
Kitchen	Kitchen	1	1023	67.9	L	53.5		451		3.5		37.9	X	50
Kitchen	Storage	1	1024	68.1	L	53.3		448		3.6		20.9		5
Supply	Storage	1	1025	67.2	L	50.4		452		3.8		30.0		10
Vault	Storage	1	1026	66.9	L	54.2		404		3.6		15.3		10
Recruiter's Office	Office	1	1027	67.3	L	55.5		442		3.4		42.2		30-50
Office 3	Office	1	1028	67.5	L	56.8		445		3.3		33.3		30-50
Office 2	Office	1	1029	67.8	L	56.0		446		3.4		56.6		30-50
Drill Hall	Drill Hall	2	1030	68.5		53.8		806		3.6		20.4	X	50
Men's Latrine	Latrine	1	1031	68.7		52.7		811		3.3		12.1		5
Men's Shower	Shower	1	1032	68.7		53.1		724		3.4		12.8		5
Janitor's Closet	Storage	1	1033	68.9		52.8		750		3.7		13.9	X	30
Women's Latrine	Latrine	1	1034	69.4		52.6		856		3.3		8.0		5
Hazmat Storage	Storage	1	1035	69.1		49.2		491		3.5		31.0		30

**NATIONAL GUARD BUREAU
ARMY NATIONAL GUARD
REGION NORTH INDUSTRIAL HYGIENE OFFICE
ATTN: NGB-AVS-SI
301-IH OLD BAY LANE
HAVRE DE GRACE, MD 21078-4094**

NGB-AVS-SI (40-5f)

29 March 2004

MEMORANDUM FOR VTARNG, Waterbury Readiness, ATTN: SFC [Redacted]
[Redacted] 294 Armory Drive, Waterbury, VT 05676-1308

SUBJECT: Baseline Survey Report

1. I have enclosed the industrial hygiene survey report completed by Shaw Environmental, Incorporated.
2. Please contact me at (410) 942-0273 or 1-800-550-6967 if you have any questions regarding the enclosed report.

Encl

Non-Responsive

Regional Industrial Hygienist

CF: SOHO, MAJ [Redacted]
SHOM, LTC [Redacted]

MEDICAL RECORD – SUPPLEMENTAL MEDICAL DATA
 For use of this form, see AR 40-66; the proponent agency is the Office of The Surgeon General.

REPORT TITLE	OTSG APPROVED (Date)
WORKERS' OCCUPATIONAL WORKSITE SAMPLING DATA RECORD	

DIRECTORATE Waterbury Armory	BLDG/ROOM Waterbury
SPECIAL STUDY/REPORT NUMBER Vermont National Guard Study	
JOB DESCRIPTION/SERIES Military/Administrative Operations	
SAMPLING DATE July 22, 2003	

EXPOSURE MONITORED	TYPE SAMPLE*	PERMISSIBLE EXPOSURE LIMIT	SAMPLING RESULT	CALCULATED TWA	EXPOSURE CATEGORY**
1. Lead	P	0.05 mg/m ³	<0.005	<0.005	1
2.					
3.					
4.					
5.					
6.					
7.					
8.					
9.					
10.					

*TYPE OF SAMPLE: G=General Area Sample
 P=Personal Sample Collected in the Breathing Zone of the Worker.
 R=Personal Sample Collected on another worker, but representative of expected exposure for this worker.

**EXPOSURE CATEGORY
 1. Measured Exposure levels are below permissible exposure limit.
 2. Measured Exposure levels are close to permissible exposure limits: See Comments.
 3. Measured Exposure levels are above permissible exposure limits: See Comments.

COMMENTS:

NOTE: REFER TO THE SPECIAL STUDY OR REPORT REFERENCED FOR DETAILS OF SAMPLING AND RESULTS.

<i>(Continue on reverse)</i>	
PREPARED BY (Signature & Title) Non-Responsive Industrial Hygienist	DEPARTMENT/SERVICE/CLINIC INDUSTRIAL HYGIENE SECTION
DATE 8/14/2003	
PATIENT'S IDENTIFICATION (For typed or written entries give: Name --last, first, Middle; grade; date; hospital or medical facility) NAME: Non-Responsive SFC : 7/22/2003	HISTORY/PHYSICAL
SSN: Non-Responsive	OTHER EXAMINATION OR EVALUATION
UNIT PHONE NO: 802-241-2570	DIAGNOSTIC STUDIES
	FLOW CHART
	OTHER (SPECIFY)
	TREATMENT

DA FORM 4700
 1 MAY 77
 HSXR-APG-Z OP 32 1 Jan 90

Shaw Environmental, Inc.

312 Directors Drive
Knoxville, TN 37923
865.690.3211
Fax 865.690.3626



Shaw Shaw Environmental, Inc.

**National Guard Armory
Waterbury Readiness Center – Waterbury, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

22 March 2004

**National Guard Armory
Waterbury Readiness Center – Waterbury, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

22 March 2004

Prepared by:

Non-Responsive

Industrial Hygienist

Reviewed by:

Non-Responsive

Business Line Manager

Table of Contents

<i>Table of Contents</i>	<i>i</i>
<i>List of Tables</i>	<i>ii</i>
<i>List of Appendices</i>	<i>ii</i>
<i>Executive Summary</i>	<i>F-1</i>
<i>1.0 Introduction</i>	<i>1-1</i>
<i>2.0 Findings, Discussion, and Interpretation of Results</i>	<i>2-1</i>
<i>2.1 Sampling for Lead</i>	<i>2-1</i>
<i>2.1.1 Wipe Sampling</i>	<i>2-1</i>
<i>2.1.2 Air Sampling for Lead</i>	<i>2-2</i>
<i>2.2 Physical Condition of Facility</i>	<i>2-2</i>
<i>2.2.1 Peeling Paint - Lead</i>	<i>2-2</i>
<i>2.2.2 Visual Inspection - Asbestos</i>	<i>2-2</i>
<i>2.2.3 Visual Inspection - Water Damage and Mold</i>	<i>2-3</i>
<i>2.2.4 Visual Inspection - Housekeeping</i>	<i>2-3</i>
<i>2.3 Building Concerns</i>	<i>2-3</i>
<i>2.3.1 Ergonomic Concerns</i>	<i>2-3</i>
<i>2.3.2 Indoor Air Quality</i>	<i>2-4</i>
<i>2.4 Safety and Industrial Hygiene Programs</i>	<i>2-4</i>
<i>2.5 Ventilation</i>	<i>2-4</i>
<i>2.5.1 Ventilation System Evaluation</i>	<i>2-4</i>
<i>2.5.2 Contamination of Clean Air Sources</i>	<i>2-4</i>
<i>2.6 Noise Exposure</i>	<i>2-4</i>
<i>2.7 Lighting</i>	<i>2-4</i>
<i>2.8 Converted Indoor Firing Ranges</i>	<i>2-5</i>
<i>2.9 HVAC Systems</i>	<i>2-5</i>
<i>2.10 IHIM</i>	<i>2-5</i>
<i>3.0 Conclusions</i>	<i>3-1</i>
<i>Tables</i>	<i>Follows Section 3.0</i>
<i>Appendices</i>	<i>Follows Tables</i>

List of Tables

Table 1	Wipe Sampling for Lead
Table 2	Air Sampling for Lead
Table 3	Peeling Paint Sampling for Lead
Table 4	Indoor Air Quality Measurements
Table 5	Illumination Readings
Table 6	Indoor Firing Ranges - Wipe Sampling

List of Appendices

Appendix A	IIHIM Data Form
Appendix B	Building Layout
Appendix C	Sampling Sheets and Laboratory Analyses
Appendix D	References
Appendix E	Recommendations for Surface Lead Dust in Armories

Executive Summary

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Waterbury Readiness Center in Waterbury, Vermont. **Non-Responsive** performed the evaluation on 22 July 2003 and 8 October 2003. The point of contact at the readiness center was SFC **Non-Responsive**

The following industrial hygiene concerns were evaluated.

- Wipe Sampling for Lead
- Air Sampling for Lead
- Peeling Paint – Lead
- Suspected Asbestos Containing Material
- Water Damage
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Indoor Air Quality
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- Lighting
- Converted Indoor Firing Range
- HVAC Systems

The following items were either not applicable to the armory or the evaluation resulted in a conclusion that there were no industrial hygiene concerns.

- Air Sampling for Lead
- Peeling Paint – Lead
- Water Damage
- Housekeeping
- Ergonomic Concerns
- Safety and Industrial Hygiene Programs

- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- HVAC Systems

Areas where there were industrial hygiene concerns are as follows:

- Wipe sampling for lead revealed concentrations above the recommended level at five locations in armory. It is recommended that these surfaces and the areas immediately around these surfaces be thoroughly cleaned to reduce the lead level. In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.
- Wipe sampling for lead revealed concentrations above a level of 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) in the assembly hall. Areas with lead concentrations above 40 $\mu\text{g}/\text{ft}^2$ that will be accessible to children should be cleaned. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.
- Materials suspected of containing asbestos were observed. An operations and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.
- Visual mold was observed in the armory. The area where the mold is located should be thoroughly cleaned with 0.5% sodium hypochlorite solution (1 part household bleach to nine parts water) or equivalent in order to eliminate the potential mold/indoor air quality problem. In addition, the source of the mold should be identified and actions taken to eliminate the source of the mold.
- Indoor air quality measurements revealed that the humidity at the armory exceeded the recommended levels. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory. In addition, interviews with employees revealed ventilation as an indoor air quality concern at the armory, specifically in the supply room, where there is a minimal fresh air supply, and the three front offices. Fans could be used to circulate air in these areas.
- Lighting measurements were conducted at the armory. The lighting did not meet minimum requirements in some areas; therefore consideration should be given to providing more lighting in these areas. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

- Wipe sampling for lead in the converted firing range revealed concentrations above the recommended level. These areas must be decontaminated by a thorough cleaning until surface lead concentrations are reduced to below recommended levels. In addition, employees should not be allowed to work in these areas without protective clothing until the areas have been cleaned and re-sampled.

1.0 Introduction

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Waterbury Readiness Center in Waterbury, Vermont. **Non-Responsive** performed the evaluation on 22 July 2003 and 8 October 2003. The point of contact at the readiness center was SFC **Non-Responsive**

The findings, discussion, and interpretation of results are provided in Section 2.0. The conclusions are provided in Section 3.0. The HHIM data form for the facility is provided in Appendix A. The building layout is provided in Appendix B. Sampling sheets and laboratory analyses are provided in Appendix C. References are provided in Appendix D. The *Recommendations for Surface Lead Dust in Armories* document is provided in Appendix E.

The statements, opinions, and conclusions contained in this report are based solely upon the services performed by Shaw as described in the report. In performing these services and preparing the report, Shaw Environmental, Inc. relied upon the work and information provided by others, including public agencies, whose information is not guaranteed by Shaw Environmental, Inc.

2.0 Findings, Discussion, and Interpretation of Results

The results, discussion, and interpretation of results are provided in the following sections.

2.1. Sampling for Lead

2.1.1 Wipe Sampling

Wipe samples were collected for lead from the drill floor/assembly area. Also, wipe samples were collected for lead in rooms, hallways, foyers, etc. The sampling in rooms, hallways, foyers, etc. represented approximately 25% of the building. Approximately half of the samples were collected from surfaces in common areas, such as surfaces of a desk. The remaining samples were collected from uncommon surface areas, such as a supply vent or the top of a file cabinet. The samples were collected and analyzed in accordance with the Instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

The only samples initially submitted for analysis were those from the drill floor/assembly hall. If there were any positive results from the drill floor/assembly hall, the other samples would be submitted for analysis.

Results of the wipe sampling are provided in Table 1. The results revealed lead at all locations sampled at concentrations below recommended level of 200 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$) (See Appendix E) except at five locations. One sample collected from the drill hall floor had a lead concentration of $300 \mu\text{g}/\text{ft}^2$. Four samples in the assembly/drill hall (soda machine top surface, locker #82 top surface, fire alarm control box top surface, and locker #95 top surface) had lead concentrations of 240, 670, 360 and $410 \mu\text{g}/\text{ft}^2$, respectively. It is recommended that these surfaces and the immediate areas around the surfaces be thoroughly cleaned to reduce the lead level to below $200 \mu\text{g}/\text{ft}^2$. For guidance on the proper method of cleaning, please refer to NGB PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.

In addition, wipe sampling for lead revealed concentrations above a level of 40 $\mu\text{g}/\text{ft}^2$ in the assembly hall and converted firing range. Please note that the *Recommendations for Surface Lead Dust in Armories* (Appendix E) states that all areas with lead concentrations above 40 $\mu\text{g}/\text{ft}^2$ that will be accessible to children should be cleaned. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.

2.1.2 Air Sampling for Lead

Breathing zone air sampling was conducted on one (1) full-time building occupant. (Please note that no state employees were monitored.) The sample was collected and analyzed in accordance with Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods.

The results of the sampling are provided in Table 2. The results revealed non-detectable concentrations of lead in the breathing zone of the employee; therefore, no actions are necessary.

2.2 Physical Condition of Facility

2.2.1 Peeling Paint - Lead

Peeling paint was observed in the armory at two locations; the foyer wall and wall opposite the foyer wall. The Department of Housing and Urban Development (HUD) defines lead-based paint as paint or other surface coatings that contain lead equal to or 0.5 percent by weight. Bulk sampling results revealed lead at levels below 0.5 percent by weight. Since HUD does not consider the paint a lead-based paint, no actions are necessary. The results of the sampling are provided in Table 3.

2.2.2 Visual Inspection - Asbestos

A visual inspection was made to determine if there was any suspected asbestos-containing material at the armory. Materials suspected of containing asbestos were observed. The suspected asbestos-containing material was insulation in the boiler room (approximately 33 linear feet). The condition of the boiler room insulation material was considered good (no rips, tears, or other damage).

An operation and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.

2.2.3 Visual Inspection – Water Damage and Mold

A visual inspection was made to determine if there was any water damage or visible mold at the armory. Water damage and visible mold were observed at the armory during the 22 July 2003 site visit. Water damage and visible mold were observed on the foyer wall and wall opposite of the foyer wall. Please note that the water damage was repaired prior to the 10 October 2003 visit. The source of the water damage was from a pipe leak.

The area where the mold is located should be thoroughly cleaned with 0.5% sodium hypochlorite solution (1 part household bleach to nine parts water) or equivalent in order to eliminate the potential mold/indoor air quality problem. In addition, the source of the mold should be identified and actions taken to eliminate the source of the mold.

2.2.4 Visual Inspection - Housekeeping

The housekeeping was determined to be good.

2.3. Building Concerns

2.3.1 Ergonomic Concerns

Interviews with employees and observation of work activities revealed no ergonomic concerns at the armory.

2.3.2 Indoor Air Quality

Interviews with employees revealed ventilation as an indoor air quality concern at the armory, specifically in the supply room, where there is minimal fresh air, and in the three front offices. In addition, measurements for humidity revealed a level that exceeded the American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommended level of 60% in the armory. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory. In addition, fans could be used to circulate air in the supply room and offices

The results of the measurements for carbon dioxide, humidity, and temperature are provided in Table 4.

2.4. Safety and Industrial Hygiene Programs

An evaluation was performed to determine the applicability of the following programs.

- Confined Spaces
- Hearing Conservation
- Respiratory Protection
- Hazard Communication (HAZCOM)
- Personal Protective Equipment (PPE)

It was determined that the HAZCOM program was the only program listed above that was applicable at the facility. The HAZCOM program was evaluated and it was determined that the program met minimum requirements.

2.5. Ventilation

2.5.1 Ventilation System Evaluation

There were no local exhaust ventilation systems at this armory; therefore, no ventilation studies were performed.

2.5.2 Contamination of Clean Air Sources

Since there were no local exhaust ventilation systems at the armory, there was no possibility that clean air sources could be contaminated by exhaust air.

2.6. Noise Exposure

An evaluation was performed to determine if there were any hazardous noise areas at the armory. It was determined that there were no areas at the armory that would exceed the permissible exposure limit for noise.

2.7 Lighting

Lighting measurements were conducted at the armory. Results of the lighting evaluation are provided in Table 5. As can be seen from the results, the lighting did

not meet the minimum requirements in some areas, including the supply room (office area), kitchen, and men's latrine.

Consideration should be given to providing more lighting to the areas listed above. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

2.8 Converted Indoor Firing Ranges

There was a converted indoor firing range at the facility; therefore, wipe samples were taken for lead at various locations in or near the converted range. The space is used as storage. The results are provided in Table 5. The results revealed lead, with associated concentrations, at the following locations:

- exhaust ventilation system at 3700 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$);
- floor at $< 110 \mu\text{g}/\text{ft}^2$;
- floor outside the range at $< 110 \mu\text{g}/\text{ft}^2$;
- stored item at $930 \mu\text{g}/\text{ft}^2$; and
- light fixture at $250 \mu\text{g}/\text{ft}^2$.

The lead levels at three of the locations were above the recommended level of $200 \mu\text{g}/\text{ft}^2$, a level recommended in the *Guidelines for Converting Indoor Firing Ranges to Other Uses* document (Department of Army). These areas must be decontaminated by a thorough cleaning until surface lead concentrations are reduced to below recommended levels. For guidance on the proper method of cleaning, please refer to NG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, employees should not be allowed to work in these areas without protective clothing until the areas have been cleaned and re-sampled.

2.9. HVAC System

There was not a HVAC system at the armory.

2.10. HHIM

A Health Hazard Information Module (HHIM) form was completed for the armory. The completed form is provided in Appendix A.

3.0 Conclusions

It is concluded that there were no industrial hygiene concerns at the armory with regards to atmospheric exposure to lead, peeling lead-based paint, water damage, housekeeping, ergonomic conditions, safety and industrial hygiene programs, ventilation systems or contamination of clean air sources, noise exposure, and HVAC systems.

There were industrial hygiene concerns at the armory with regards to lead surface contamination, suspected asbestos-containing material, visible mold, indoor air quality, surface lead contamination in the converted firing range, and lighting. These concerns are discussed in detail in Section 2.0 of this report.

TABLES

Table 1
Wipe Sampling for Lead
National Guard Armory
Waterbury, Vermont
Dates of Sampling: 22 July 2003 and 8 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTWAT203-1	Drill Floor - On Floor (See Building Layout - Appendix B)	120
VTWAT203-2	Drill Floor - On Floor (See Building Layout - Appendix B)	300
VTWAT203-3	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTWAT203-4	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTWAT203-5	Drill Floor - On Floor (See Building Layout - Appendix B)	< 110
VTWAT203-6	Field Blank	< 12 μg
VTWAT203-13	Classroom - table top	< 110
VTWAT203-14	Kitchen - refrigerator top surface	< 110
VTWAT203-15	Supply Office - filing cabinet top surface	< 110
VTWAT203-16	Administrative Office - desktop	< 110
VTWAT282-1	Assembly Room - soda machine top surface (See Building Layout - Appendix B)	240
VTWAT282-2	Assembly Room - locker #82 top surface (See Building Layout - Appendix B)	670
VTWAT282-3	Assembly Room - locker #49 top surface (See Building Layout - Appendix B)	130
VTWAT282-4	Assembly Room - fire alarm control box top surface (See Building Layout - Appendix B)	360
VTWAT282-5	Assembly Room - locker #95 top surface (See Building Layout - Appendix B)	410
VTWAT282-6	Field Blank	0.38 μg

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of Army National Guard Armories* procedure.

In armories that do not contain childcare facilities, the NGB Region North Industrial Hygiene Office recommends cleaning the areas with lead concentrations greater than 200 $\mu\text{g}/\text{ft}^2$.

Table 2
Breathing Zone Air Samples for Lead
National Guard Armory
Waterbury, Vermont
Date of Sampling: 22 July 2003

Sample Number	Employee	Sampling Information			Results (mg/m ³) ^a
		Time Sampled / Minutes	Flow Rate (lpm) ^b	Volume (liters)	
VTENO196-A1	Non-Responsive	1301-1420/79	2.4671	194.90	<0.005
VTENO196-A2	Field Blank	-	-	-	None Detected

^a Milligrams lead per cubic meter of air.

^b Liters of air per minute.

Only one employee was sampled because there were no other employees at the armory on the date of the survey.

Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods was followed for sampling for lead.

Table 3
Peeling Paint Sampling for Lead
National Guard Armory
Waterbury, Vermont
Date of Sampling: 22 July 2003

Sample Number	Location	Results, % By Weight
VTWAT203-B1	Foyer wall	0.0040
VTWAT203-B2	Wall opposite of foyer wall	0.0057

The Department of Housing and Urban Development (HUD) defines lead-based as paint or other surface coatings that contain lead equal to or exceeding 0.5 percent by weight.

Table 4
Indoor Air Quality Measurements for Carbon Dioxide, Humidity, and Temperature
National Guard Armory
Waterbury, Vermont
Date of Sampling: 22 July 2003

Location	Occupants in Area	Carbon Dioxide, parts per million parts of air (ppm)	Percent (%) Humidity	Temperature (°F)
1 st Floor	2	514	69.9	74.8
Outdoors	0	419	73.1	85.6

Carbon dioxide, humidity, and temperature measurements were taken with a TSI Q Trak Plus, Model 8554, Indoor Air Quality Meter, calibrated in April 2003.

American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommends that indoor carbon dioxide levels be less than 700 ppm above outdoor levels.

ASHRAE recommends that the relative humidity levels be maintained between 30 to 60 percent.

ASHRAE recommends that the acceptable temperature range be 68 degrees Fahrenheit to 74 degrees Fahrenheit in the winter and 73 degrees Fahrenheit to 79 degrees Fahrenheit in the summer.

Table 5
Illumination Readings
National Guard Armory
Waterbury, Vermont
Date of Sampling: 22 July 2003

Location	Luminance (fc) ^a	Standard (fc) ^a	Standard Met
Supply Room (office area)	24.1-54.3	70	No
Kitchen	14.0-49.9	70	No
Kitchen storage	38.1-85.3	30	Yes
Classroom	10.2-113	70	Some areas
Office	45.7-88.3	70	Some areas
Administrative Office	60.2-120.3	70	Some areas
Men's Latrine	5.3-17.5	40	No

^a fc - Footcandles

The readings were taken with a Cooke Corporation cal-LIGHT 400 Calibrated Precision Lightmeter, calibrated on 19 Aug 2002.

The standards listed above are from Design Guide DG-415-2, Logistics Facilities, published by the National Guard Bureau Installation Division.

Table 6
Wipe Sampling for Lead – Converted Firing Range
National Guard Armory
Waterbury, Vermont
Date of Sampling: 22 July 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTWAT203-7	Exhaust Ventilation System	3700
VTWAT203-8	Floor	< 110
VTWAT203-9	Floor Outside the Range	< 110
VTWAT203-10	Stored Item	930
VTWAT203-11	Light Fixture	250
VTWAT203-12	Blank	< 12 μg

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

Appendix A

HHIM Data Form(s)

HEALTH HAZARD INFORMATION MODULE: INDUSTRIAL HYGIENE SURVEY

(For use of this form, see HHIM User's Guide)

SECTION 1. DEMOGRAPHIC DATA

ARLOC	INSTALLATION Waterbury Armory Vermont ARNG	BLDG/RM NO. Waterbury		
LOCATION/CODE Administrative Areas / AA	OPERATION/CODE Administrative Operations / ADO			
SURVEY DATE 22 July 2003	EVALUATOR (Initials) Non-Responsive			
MACOM/CODE ARMY NATIONAL GUARD	SUBMACOM/CODE XX	SUPERVISOR Non-Responsive		
TELEPHONE/DSN NO. 802 241 2570	UNIT/ORGANIZATION Battery A 1BN (155mm SP) 26 Field Artillery	RAC 4	FREQUENCY (hrs/day) 8	
NO. CIV(S) 0	NO. MIL 4	NO. CONTRACTOR(S) 0	NO. LOC(S) 0	NO. OTHER 0

SECTION 2. FACILITY DATA

LAB HOODS 0	VAPOR DEGREASERS 0	SPRAY BOOTHS 0
MAINTENANCE BAYS 0	OPEN SURFACE TANKS 0	VENTILATION UNITS 0

SECTION 3. SURVEY DATA

CONTROLS PRESENT	EVALUATION	UNIT CODE	CONTROLS REQUIRED	STATUS

PERSONAL PROTECTIVE EQUIPMENT (R = Required; U = Utilized)

GLOVES	R	U	RESPIRATOR	NOSH TC NO.	MANUFACTURER	R	U
ACID			AIRLINE				
COLD SURFACES			ABRASIVE BLASTING HOOD				
HOT SURFACES			DISPOSABLE				
NBC AGENTS			FULL FACE AIR PURIFYING				
OIL			1/2 FACE AIR PURIFYING				
SOLVENTS			POWERED AIR PURIFYING				
SURGICAL GLOVES			1/4 FACE AIR PURIFYING				
			SELF CONTAINED				

EYES/FACE	R	U	HEARING	R	U	BODY	R	U	HEAD/FIT	R	U
CHEMICAL SPLASH			CANAL CAPS			APRONS			COLD WEATHER BOOTS/HATS		
FULL FACE SHIELD			EAR PLUGS			COLD WEATHER CLOTHING			HARD HATS		
CHEMICAL/SAFETY			HELMETS			COVERALLS			IMPERMEABLE BOOTS		
SAFETY/IMPACT			MUFFS			FULL BODY SUIT			SAFETY/CONDUCTIVE SHOES		
WELDING HELMET			MUFF/EARPLUG COMBO			HEAT REFLECTIVE VEST/SUIT			SAFETY/NON-CONDUCTIVE SHOES		

SECTION 4. HAZARD INVENTORY DATA

CAS CODE	HAZARD DESCRIPTION	PAC	EPC
POVDTXXX	Video Display Terminal	3-low	Uncontrolled Physical
1332-21-4	Asbestos (other)	3-low	Uncontrolled Respiratory
7439-92-1	Lead, inorganic dust and fumes, sp	2-moderate	Uncontrolled Respiratory

SECTION 5. PERSONNEL DATA

LAST NAME	FIRST NAME	MI	SEX	SSN	CATEGORY
Non-Responsive		R	M	Non-Responsive	MIL
		W	↓		↓
		J	↓		↓
		E	↓		↓

SECTION 6. COMMENTS

No comments. See attached sheet
 Survey was conducted by Michele Sermon. Building contains 4 (four) full time military employees. Employees perform mainly administrative functions. Please note no lead was observed in the building.

PRIVACY ACT STATEMENT

Title 5 US Code, Section 301; Executive Order 9397 authorizes the use of your Social Security Number as an identification number. The purpose of this information is to identify and monitor data relating each DA civilian and military employee exposed to a hazardous workplace or operation. The use of this information is to provide histories of exposures for any given worker.

Disclosure of your Social Security Number is not mandatory; however, nondisclosures may result in untimely provision of proper medical monitoring.

BATTERY A 1BN(155mmSP) 86 Field Artillery
VERMONT ARMY NATIONAL GUARD
294 Armory Drive
Waterbury, VT 05676-1308

WPXBA0

21JUL2003

MEMORANDUM FOR RECORD

SUBJECT: Full Time Support Personnel

1. The following soldiers are assigned to the above facility as their home station:

SFC **Non-Responsive** Readiness NCO **Non-Responsive**
SFC **Non-Responsive** Recruiter
SSC **Non-Responsive** it Supply NCO
SSC **Non-Responsive** it Training NCO


FOR THE COMMANDER

Non-Responsive

SFC, VTARNG
Readiness NCO

Appendix B

Building Layout



- Sample date 22 July 2003
- △ Sample date 8 October 2003

FLOOR PLAN
 WATERBURY ARMORY
 SCALE: 1" = 20' 28/OCT/03

Appendix C

Sampling Sheets and Laboratory Analyses

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SL, State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTWAT203
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01

Chain Of Custody: 115814
Date Analyzed: 8/5/2003

Person Submitting: [REDACTED]
Report Date: 05-Aug-03

Page 1 of 2

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0359537	VTWAT203-1	Flame	Wipe	****	0.111	108.00 ug/ft ²	120 ug/ft ²	
0359538	VTWAT203-2	Flame	Wipe	****	0.111	108.00 ug/ft ²	500 ug/ft ²	
0359539	VTWAT203-3	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359540	VTWAT203-4	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359541	VTWAT203-5	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359542	VTWAT203-6	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0359543	VTWAT203-7	Flame	Wipe	****	0.111	108.00 ug/ft ²	3700 ug/ft ²	
0359544	VTWAT203-8	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359545	VTWAT203-9	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359546	VTWAT203-10	Flame	Wipe	****	0.111	108.00 ug/ft ²	930 ug/ft ²	
0359547	VTWAT203-11	Flame	Wipe	****	0.111	108.00 ug/ft ²	250 ug/ft ²	
0359548	VTWAT203-12	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

All rights reserved. AMA Analytical Services, Inc.

An AIHA (#8863), NVLAP (# 101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
 Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SI,
 State Military Reservation
 Havre de Grace, Maryland 21078
 Job Name: VTWAT203
 Job Location: Not Provided
 Job Number: Not Provided
 P.O. Number: 07-01
 Chain Of Custody: 115814
 Date Analyzed: 8/5/2003
 Person Submitting: [Redacted]
 Report Date: 05-Aug-03

Page 2 of 2

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
		Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids; EPA 600/R-93/200(M)-7420; Water. SM-3111B						
		Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water. SM-3113B						
		N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per billion (ppb)						
		%Pb = percent lead by weight ug = micrograms						
		Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.						
								Technical Manager: [Redacted]
								Analys: [Redacted]
								Non-Responsive
								Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

All rights reserved. AMA Analytical Services, Inc.
 An AIHA (#8863), NVLAP (# 101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
 Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation
 Hayre de Grace, Maryland 21078
 Job Name: VTWAT203
 Job Location: Not Provided
 Job Number: Not Provided
 P.O. Number: 07-01
 Chain Of Custody: 115918
 Date Analyzed: 08/18/2003
 Person Submitting: [Redacted]
 Report Date: 18-Aug-03

Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0362683	VTWAT203-13	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362684	VTWAT203-14	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362685	VTWAT203-15	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	
0362686	VTWAT203-16	Flame	Wipe	****	0.111	108.01 ug/ft ²	< 110 ug/ft ²	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3113B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B

µg/L = Not Applicable
 mg/Kg = parts per million (ppm) by weight
 mg/L = parts per million (ppm)
 µg/L = parts per billion (ppb)
 %Pb = percent lead by weight
 Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Non-Responsive

Non-Responsive

Analyst:

Technical Manager:

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301-H Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTWA1282
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 0701

Chain Of Custody: 118708
Date Analyzed: 10/21/2003
Person Submitting: [Redacted]
Report Date: 21-Oct-03

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft²)	Reporting Limit	Final Result	Comments
0402856	VTWA1282-1	Furnace	Wipe	****	0.111	67.51 ug/ft²	240 ug/ft²	
0402857	VTWA1282-2	Furnace	Wipe	****	0.111	67.51 ug/ft²	670 ug/ft²	
0402858	VTWA1282-3	Furnace	Wipe	****	0.111	33.75 ug/ft²	130 ug/ft²	
0402859	VTWA1282-4	Furnace	Wipe	****	0.111	67.51 ug/ft²	360 ug/ft²	
0402860	VTWA1282-5	Furnace	Wipe	****	0.111	67.51 ug/ft²	410 ug/ft²	
0402861	VTWA1282-6	Furnace	Wipe Blank	****	N/A	0.30 ug	0.38 ug	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)
 Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] Technical Manager: [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.



Submitted To: **Non-Responsive**
Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTCAM205-A1 through VTAAS204-A3
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Filter
Method Reference:	NIOSH 7300
DCL Set ID No.:	03-S-3621
DCL Sample ID No.:	03-22309 through 03-22345
Sample Receipt Date:	7/28/2003
Preparation Date:	07/29/03
Analysis Date:	07/31/03

The samples were prepared and analyzed in accordance with NIOSH method 7300 using a Perkin Elmer 3000XL ICP.

The sample condition upon receipt was acceptable except where noted.

The results are in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive



Analyst

Non-Responsive



CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 280-8071, FAX 415 893-9469

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTCAM205-A1	03-22309	407.54	ND	<0.002
VTCAM205-A2	03-22310	377.66	ND	<0.003
VTCAM205-A3	03-22311	0	ND	-
VTWIN202-A1	03-22313	152.91	ND	<0.007
VTWIN202-A2	03-22314	0	ND	-
VTENO196-A1	03-22316	150.55	ND	<0.007
VTENO196-A2	03-22317	0	ND	-
VTWIL197-A1	03-22319	199.78	ND	<0.005
	Prep Blank 1		ND	
% Recovery	LCS 1		96.	
% Recovery	LCS 2		96.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).

LCS = laboratory control sample.

Non-Responsive

Analyst

Non-Responsive

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTWIL197-A2	03-22320	149.76	ND	<0.007
VTWIL197-A3	03-22321	0	ND	-
VTSWA196-A1	03-22322	149.24	ND	<0.007
VTSWA196-A2	03-22323	0	ND	-
VTSTA196-A1	03-22324	165.20	ND	<0.006
VTSTA196-A2	03-22325	151.74	ND	<0.007
VTSTA196-A3	03-22326	0	ND	-
VTWAT203-A1	03-22328	194.90	ND	<0.005
VTWAT203-A2	03-22329	0	ND	-
VTGOS202-A1	03-22332	175.30	ND	<0.006
VTGOS202-A2	03-22333	0	ND	-
VTMOR203-A1	03-22335	346.43	ND	<0.003
VTMOR203-A2	03-22336	348.65	ND	<0.003
VTMOR203-A3	03-22337	0	ND	-
VTGRE197-A1	03-22340	240.55	ND	<0.004
VTGRE197-A2	03-22341	250.76	ND	<0.004
VTGRE197-A3	03-22342	0	ND	-
VTAAS209-A1	03-22343	748.92	ND	<0.001
VTAAS209-A2	03-22344	507.55	ND	<0.002
VTAAS209-A3	03-22345	0	ND	-
	Prep Blank 2		ND	
% Recovery	LCS 3		96.	
% Recovery	LCS 4		95.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).

LCS = laboratory control sample.

Non-Responsive



Analyst

Non-Responsive





Submitted To: **Non-Responsive**
 Shaw Environmental, Inc.
 101 Fieldcrest Ave., 4th Floor
 Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTCAM205-B1 through VTMCR203-B2
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Paint Chip
Method Reference:	3050B/6010B
DCL Set ID No.:	03-S-3621
DCL Sample ID No.:	03-22312 through 03-22339
Sample Receipt Date:	07/28/2003
Preparation Date:	07/29/2003
Analysis Date:	07/31/2003

The samples were prepared in accordance with EPA method 3050B. Sample condition was acceptable upon receipt except where noted. The samples were then analyzed in accordance with EPA method 6010B using a Jarrell Ash Trace ICP.

The results are provided in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive

Analyst

CINCINNATI OFFICE
 4388 GLENDALE-MILFORD ROAD
 CINCINNATI, OHIO 45242-3706
 513 733-5336, FAX 513 733-5347

Non-Responsive

Reviewer

WEST COAST OFFICE
 11 SANTA YORMA COURT
 NOVATO, CALIFORNIA 94945
 800 280-8071, FAX 415 893-9469

Results Lead

Client #	DCL #	mg/Kg (ppm)	% by weight
VTCAM205-B1	03-22312	160.	0.016
VTWIN202-B1	03-22315	11000.	1.1
VTENO196-B1	03-22318	96000.	9.6
VTSTA197-B1	03-22327	1800.	0.18
VTWAT203-B1	03-22330	40.	0.0040
VTWAT203-B2	03-22331	57.	0.0057
VTMOR203-B1	03-22338	3900.	0.39
VTMOR203-B2	03-22339	11000.	1.1
	Prep Blank	ND	
% Recovery	LCS	87.	
% Recovery	03-22327 MS	* 0.	
% Recovery	03-22327 MSD	* 4.	
RPL		25.	0.0025

ND = not detected at or above the reporting limit (RPL).

LCS = laboratory control sample.

MS/MSD = matrix spike/matrix spike duplicate.

* Low recovery due to non-homogeneous sample matrix.

Non-Responsive



Analyst

Non-Responsive



Reviewer

Industrial Hygiene Sampling Calculation Worksheet

National Guard Armory Location: WAT
 Date: 203

Sample 1

Sample Number: VTWAT203-A1

Pump: 647615

	Pre Flow Rate	Post Flow Rate
	2.5	2.437
	2.493	2.441
	2.487	2.452
	2.481	2.446
Average	2.490	2.444

Average Pre and Post **2.4671**

Time 1 13:01
 Time 2 14:20
Total Time Sampled **1:19**
Minutes Sampled **79.00**

Volume **194.90 Liters**

Sample 2

Sample Number: N/A

Pump: N/A

	Pre Flow Rate	Post Flow Rate
	N/A	N/A
Average	N/A	N/A

Average Pre and Post **N/A**

Time 1 N/A
 Time 2 N/A
Total Time Sampled **N/A**
Minutes Sampled **N/A**

Volume **N/A** **Liters**

Appendix D

References

References

Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration (current edition)

American Society of Heating, Refrigerating and Air-Conditioning Engineers, Inc (ASHRAE) 62-2002, Ventilation for Acceptable Indoor Air Quality

Instructions for Completing the Sampling of Army National Guard Armories, Lead Wipe Sampling Procedure included with the Request for Proposal

Air Sampling for Lead - Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods

Design Guide DG-415-2, Logistics Facilities, National Guard Bureau Installation Division, 14 December 1999

Department of Defense Instruction (DDI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998

Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, 15 October 1990

AR 385-10, The Army Safety Program, 29 February 2000

Department of the Army Pamphlet (DA PAM) 40-501, Medical Services, Hearing Conservation Program, 10 December 1998

DA PAM 40-503, Medical Services, Industrial Hygiene Program, 30 October 2000

Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH) (current edition)

Guidelines for Converting Indoor Firing Ranges to Other Uses, Headquarters, Department of the Army and the Air Force, NG PAM (AR) 385-16/ANGPAM 91-101, 31 January 1994

24 CFR, Part 35, Subpart B, Section 35-110, Definition of Lead-Based Paint, Housing and Urban Development, U. S. Department of Housing

Appendix E
Recommendations for
Surface Lead Dust in Armories

Subject: Recommendations for Surface Lead Dust in Armories

1. In armories that do not contain childcare facilities, the National Guard Bureau (NGB) Region North Industrial Hygiene Office recommends cleaning the areas in which sample results are greater than 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$). If a special function will be held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function. This guidance is based on professional judgment, risk assessments, adaptation of Occupational Safety and Health Administration (OSHA) guidance, and feasibility of cleaning to a certain level.

a. Environmental Protection Agency (EPA) standards (40 Code of Federal Regulations (CFR) 745.227(h)(3)) are not directly applicable because they are criteria for dust-lead hazards developed for floors ($40 \mu\text{g}/\text{ft}^2$) and windowsills ($250 \mu\text{g}/\text{ft}^2$) in residential dwellings and child occupied facilities. A child occupied facility is defined as a building, or portion of a building, constructed prior to 1978, visited regularly by the same child, 6 years of age or under, on at least two different days within any week (Sunday through Saturday period), provided that each day's visit lasts at least 3 hours and the combined weekly visit lasts at least 6 hours, and the combined annual visits last at least 60 hours. Most of the wipe samples in armories were collected in undisturbed areas and therefore, results are worst case scenarios and do not correlate to these standards.

b. OSHA has no specific requirement for work area surfaces. The lead standard (29 CFR 1910.1025(h)) states that all surfaces shall be maintained as free as practicable of accumulations of lead dust. In workplaces where lead dust is generated, surface levels may be much higher, but personnel exposures can be controlled by limiting airborne lead levels and following good cleanup and hygienic practices.

c. OSHA used to cite a level of $200 \mu\text{g}/\text{ft}^2$ in their Technical Manual and 29 CFR 1926.62 as guidance to its own inspectors for evaluating the cleanliness of lunchroom and locker room surfaces that are supposed to be kept as clean as possible.

d. In a report titled Derivation of Wipe Surface Screening Levels for Environmental Chemicals, the US Army Center for Health Promotion and Preventive Medicine (USACHPPM) has determined that $200 \mu\text{g}/\text{ft}^2$ is a safe surface contamination level. They have also applied these standards as the decontamination levels for surfaces in administrative offices.

e. It should be noted that levels above these recommendations do not necessarily mean there is a significant hazard to workers who are following good cleaning and hygienic practices since there is no correlation between wipe and air samples. Rather, we recommend these levels as a precautionary measure.

2. The NGB Occupational Health Branch is developing guidance for armories that are used as childcare facilities. All states will receive this guidance when it is completed. In the interim, we recommend the following actions:

a. Clean all areas that will be accessible to children to the EPA dust-lead standard for children 6 years of age or under ($40 \mu\text{g}/\text{ft}^2$ on floors and $250 \mu\text{g}/\text{ft}^2$ on windowsills).

b. Refer to the local authorities' regulations since they can be more stringent than federal regulations.

c. Post signs in the area to inform people of the presence of lead dust and its effects.

d. If soldiers clean weapons in the facility change the policy so that they cannot clean their weapons in the facility, or if they are allowed to clean their weapons indoors, they must clean the area by wet wiping and mopping the area when they are done.

e. If the paint is peeling, contact the state Environmental Office to test for lead content and provide recommendations.

3. Air samples collected on individuals in the armory were well below OSHA's permissible exposure limit for lead (29 CFR 1910.1025(c)) of $0.05 \text{ mg}/\text{m}^3$ averaged over an 8-hour day. Therefore, based on these conditions there is currently no overexposure to personnel from lead dust in this building.

Industrial Hygiene Survey

Vermont Army National Guard (VT ARNG)

Prepared For: NGB ARNG– Region North IH Office

Survey Location:

Rex W. Morse Readiness Center
294 Armory Drive
Waterbury, VT 05676

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 19, 2012

AEI Project #: J12-685 3M VT Rex W. Morse RC

Non-Responsive, DrPH, CIH
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Rex W. Morse Readiness Center**

Table of Contents

Section	Page
Executive Summary	ii
1 Introduction	1
2 Evaluation Methods.....	1
3 Operations.....	1
4 Noise Hazards	1
5 Hazard Controls	2
Ventilation Systems	2
6 Physical Condition of the Facility and Personnel Concerns	2
Paint Chip and Dust Wipe Samples for Lead Contamination	2
Visual Inspection for Damaged Asbestos-Containing Materials	3
Visual Inspection for Water Damage and Mold Growth.....	3
Visual Inspection for Housekeeping Concerns.....	4
Lighting	4
Indoor Air Quality (IAQ)	4
Temperature and Relative Humidity.....	4
Carbon Dioxide (CO2) and Carbon Monoxide (CO)	5
Additional Information	5
7 Conclusions.....	5
8 Limitations.....	5
9 References	6

List of Tables

Table 1 – Results of Lead Paint Chip Sampling for VT ARNG Rex W. Morse Readiness Center on October 19, 2012

Table 2 - Results of Dust Wipe Sampling for the VT ARNG Rex W. Morse Readiness Center on October 19, 2012.

Table 3 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

List of Appendices

Appendix A – Building Layout

Appendix B – Certificates of Analysis for Air, Dust Wipe and Bulk Samples

Appendix C – Photographic Documentation

Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Rex W. Morse Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Rex W. Morse Readiness Center located at 294 Armory Drive, Waterbury, VT 05676. **Non-Responsive**, DrPH, CIH performed the evaluation on October 19, 2012. The point of contact for the facility was SFC **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. One small area of peeling paint was observed in the Supply/Storage room on the north concrete masonry unit (CMU) wall between the fire extinguisher and the former bullet trap at about four feet above the finished floor. There was less than one square foot of damaged paint. A paint chip was collected for analysis. The sample contained lead at a concentration of 0.0066% lead and is not considered lead-based paint.

Results of dust wipe samples taken throughout the facility were below the recommended maximum criterion for surface contamination of lead (200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$)) in all areas sampled except for a sample collected from the wall mounted diffuser located in the locker room (280 $\mu\text{g}/\text{ft}^2$).

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there were any suspect asbestos-containing material and its condition. No significantly damaged, suspect asbestos-containing material was observed. Some damaged floor tile with exposed mastic was observed in the kitchen. The area of damage is limited to less than one square foot. The boiler room was abated when a new boiler was installed.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No evidence of wet areas or mold growth was observed on the day of the survey.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping appeared to be acceptable overall.

Lighting: A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in a few areas including the: classroom, women's latrine, janitor's closet, office, gym, kitchen, boiler room, maintenance storage, supply room, locker storage, and entry vestibule. The illumination measurements indoors ranged from 3.3 foot candles (fc) to 52.4 fc.

Indoor Air Quality: Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 64.8 to 68.9° F and 54.4 to 61.3% Rh. Temperatures were just below the lower end of the winter temperature range for thermal comfort in all but four of the locations monitored. Relative humidity exceeded 60% (60.1 to 61.3) in three rooms in the building. The outdoor

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Rex W. Morse Readiness Center**

temperature and relative humidity was 60.3° F and 67.8% on the day of monitoring. Indoor concentrations of carbon dioxide (CO₂) ranged from 522 to 753 parts per million (ppm). CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange. Indoor concentrations of carbon monoxide (CO) ranged from 3.5 to 4.2 ppm; therefore, concentrations are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

The new exhaust fan in the men's latrine does not function and there are odor and indoor air quality complaints during drill weekends when the unit is at capacity.

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was readily available.

The results of the evaluation indicated few concerns at the facility. Overall, the Rex W. Morse Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Rex W. Morse Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Rex W. Morse Readiness Center located at 294 Armory Drive, Waterbury, VT 05676. **Non-Responsive**, DrPH, CIH performed the evaluation on October 19, 2012. The point of contact for the facility was SFC **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

The Rex W. Morse Readiness Center was built in the 1950's. The readiness center is staffed by three administrative personnel. The operations conducted at the facility include training and administrative duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the Rex W. Morse Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) evaluations of operations including operation description, sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the Rex W. Morse Readiness Center consist exclusively of supply and administrative duties. No maintenance of vehicles or other physical tasks are performed at the facility. The unit trains soldiers on the M119 Howitzer.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Rex W. Morse Readiness Center**

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility. The exhaust fan in the men's latrine does not function and there are odor and indoor air quality complaints during drill weekends when the unit is at capacity.

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were collected in select areas.

Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. One small area of peeling paint was observed in the Supply/Storage room on the north concrete masonry unit (CMU) wall between the fire extinguisher and the former bullet trap at about four feet above the finished floor. There was less than one square foot of damaged paint. A paint chip was collected for analysis. The sample contained lead at a concentration of 0.0066% lead and is not considered lead-based paint.

To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected by wiping a Ghost Wipe over a measured area. The Environmental Protection Agency (EPA) and the State of Vermont limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA Analytical for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. All wipe samples collected from the facility were below the recommended maximum except for the sample collected from the wall mounted diffuser located in the locker room (280 $\mu\text{g}/\text{ft}^2$). Results are given in Table 1 and certificates of analysis are included in Appendix B.

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
Rex W. Morse Readiness Center on October 19, 2012.**

Wipe Sample Number	Sample Location	Wipe Dimensions	Lead ($\mu\text{g}/\text{ft}^2$)*
WRC-1	Assembly Room Floor 22' South of North Wall, 5' East of the number 2 stenciled on the floor	100 cm ²	<110
WRC-2	Assembly Room Diffuser on wall to Boiler Room	17.5" x 1.5"	190
WRC-3	Assembly Room Top of Locker South Wall, 15' East of West Wall	3" x 36"	21

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Rex W. Morse Readiness Center**

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
Rex W. Morse Readiness Center on October 19, 2012.**

Wipe Sample Number	Sample Location	Wipe Dimensions	Lead ($\mu\text{g}/\text{ft}^2$)*
WRC-4	Assembly Room Floor 8' North of South at Double Doors to Supply Room	100 cm ²	<110
WRC-5	Assembly Room Top of Drinking Water Fountain	100 cm ²	<110
WRC-6	Supply Room Floor East of Vault Door, 7' North of South Wall	100 cm ²	<110
WRC-7	Kitchen Window Sill West Wall, North Window Sill on South End	100 cm ²	<110
WRC-8	Supply/Locker Room (Former Firing Range) Floor South Wall	100 cm ²	<110
WRC-9	Supply/Locker Room (Former Firing Range) Top of Light Fixture First Fixture East of Caged Supply Storage	9" x 5"	<38
WRC-10	Supply/Locker Room (Former Firing Range) Top of Locker #36	3" x 36"	33
WRC-11	Supply/Locker Room (Former Firing Range) Floor in Corridor Between Assembly Hall Lockers 2' South of North Wall, 12' East of Door to Assembly hall	100 cm ²	<110
WRC-12	Supply/Locker Room (Former Firing Range) Diffuser on North Wall	1" x 15.75"	280
WRC-13	Supply Locker Floor Bullet Trap	100 cm ²	120
WRC-14	Office 3, Window Sill on East Wall	100 cm ²	<110

*The recommended maximum level for adult exposures is
200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) lead on surfaces.

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). No significantly damaged, suspect asbestos-containing material was observed. Some damaged floor tile with exposed mastic was observed in the kitchen. The area of damage is limited to less than one square foot. The boiler room was abated and a new boiler was installed. Floor tile and mastic remains in the building. These asbestos-containing materials were in good condition.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or visible mold growth was observed.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Rex W. Morse Readiness Center**

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping appeared to be acceptable overall.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on April 16, 2012, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in a few areas including the: classroom, women's latrine, janitor's closet, office, gym, kitchen, boiler room, maintenance storage, supply room, locker storage, and entry vestibule. The illumination measurements indoors ranged from 3.3 foot candles (fc) to 52.4 fc. The complete results of the evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Model 7656x, factory calibrated in July, 2012. Temperature, relative humidity and carbon dioxide (CO₂) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 2. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30 and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 64.8 to 68.9° F and 54.4 to 61.3% Rh. Temperatures were just below the winter temperature range for thermal comfort in all but four of the locations monitored. Relative humidity was just above 60% (60.1-61.3%) in three locations. The outdoor temperature and relative humidity was 60.3° F and 67.8% on the day of monitoring.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Rex W. Morse Readiness Center**

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1-2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 522 to 753 parts per million (ppm). CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange.

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 3.5 to 4.2 ppm; therefore, concentrations are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

Additional Information

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was readily available. MSDS were last updated in April of 2012.

7 Conclusions

The results of the evaluation indicated few concerns at the facility. Overall, the Rex W. Morse Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Rex W. Morse Readiness Center**

9 References

1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.
3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.
4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.
5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2011.
6. Army Regulation (AR) 420-70 Buildings and Structures, 11 November 1997.
7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 13 December 2007.
8. Army Regulation (AR) 420-1 Army Facilities Management, 12 February 2008, RAR 24 August 2012.
9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.
10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.
12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.
13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".
15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.


**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Rex W. Morse Readiness Center**

19. National Fire Protection Association (NFPA) 70: National Electrical Code (NEC) 2011.
20. National Guard Pamphlet (NG PAM) 420-15, Guidelines and Procedures for Rehabilitation and Conversion of Indoor Firing Ranges, November 3, 2006.

Appendix A Building Layout

Emergency Evacuation Plan

Waterbury, VT



Legend:

- Fire Extinguisher
- AED Machine
- Main Rout
- Alternet Rout
- Your Location
- Exit Sign

Sample Location Plan and Room Location Plan
 Industrial Hygiene Survey
 October 19, 2012
 Key: *## Lead Sample

Floor Plan
Waterbury Armory
3/30/2010

Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples



CERTIFICATE OF ANALYSIS



Client: National Guard Bureau	Job Name: VT ARNG 3M IH Surveys	Chain Of Custody: 514298
Address: 301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location: Rex W. Morse, Waterbury, VT	Date Submitted: 10/24/2012
	Job Number: J12-685	Person Submitting: Non-Responsive
	P.O. Number: W912K6-09-A-0003	Date Analyzed: 10/30/2012 Report Date: 10/31/2012
Attention: Non-Responsive		

Summary of Atomic Absorption Analysis for Lead

Page 1 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
13008757	WRC-1	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008758	WRC-2	Flame	Wipe	****	0.182	66 ug/ft ²	35	190 ug/ft ²	
13008759	WRC-3	Flame	Wipe	****	0.750	16 ug/ft ²	16	21 ug/ft ²	
13008760	WRC-4	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008761	WRC-5	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008762	WRC-6	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008763	WRC-7	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008764	WRC-8	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008765	WRC-9	Flame	Wipe	****	0.313	38 ug/ft ²	<12	<38 ug/ft ²	
13008766	WRC-10	Flame	Wipe	****	0.750	16 ug/ft ²	25	33 ug/ft ²	
13008767	WRC-11	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008768	WRC-12	Flame	Wipe	****	0.109	110 ug/ft ²	31	280 ug/ft ²	
13008769	WRC-13	Flame	Wipe	****	0.108	110 ug/ft ²	13	120 ug/ft ²	
13008770	WRC-14	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13008771	WRC-20	Flame	Paint Chip	****	N/A	0.0066 %Pb		0.019 %Pb	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS



Client: National Guard Bureau	Job Name: VT ARNG 3M IH Surveys	Chain Of Custody: 514298
Address: 301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location: Rex W. Morse, Waterbury, VT	Date Submitted: 10/24/2012
	Job Number: J12-685	Person Submitting: Non-Responsive
Attention: Non-Responsive	P.O. Number: W912K6-09-A-0003	Date Analyzed: 10/30/2012 Report Date: 10/31/2012

Summary of Atomic Absorption Analysis for Lead

Page 2 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	----------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm)
 %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb)

Note: All samples were received in good condition unless otherwise noted.

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Air and Wipe results are not corrected for any blank results

Final results for air and wipe samples are based on client supplied information nor verified by this laboratory.

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

See QC Summary for analytical results of quality control samples associated with these samples.

Analyst: **Non-Responsive** Technical Manager: **Non-Responsive**

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.

Aria Environmental, Inc
SURFACE WIPE AND BULK SAMPLING
SURVEY SHEET

Date Collected: 10-19-12

Inspector: Non-Responsive

Job Site: Rex W. Morse, Waterbury, VT

Project No.: J12-685

Sample No.	Sample Type	Sample Location	Dimensions (Area)
WRC-1	Pb Wipe	Assembly Floor 22' S of N wall, 5' E of number 2' sketched on floor	100 cm ²
WRC-2	Pb Wipe	Assembly Room Diffuse (not functioning) on wall to Boiler Room	17.5" x 1.5"
WRC-3		Assembly Room to Top of Locker S wall 15' E of W wall	3" x 36"
WRC-4		Assembly Room Floor 8' N of S at double doors to Supply Room	100 cm ²
WRC-5		Assembly Room top of drinking water fountain	100 cm ²
WRC-6		Supply Room Floor 1.5' E of vault door, 7' N of S	100 cm ²
WRC-7		Kitchen window sill west wall N window sill, S end	100 cm ²
WRC-8		Supply/Locker Floor S wall	100 cm ²
WRC-9		Supply/Locker Top of light fixture 1st fixture E of Caged Supply Stg	9" x 5"
WRC-10		Supply/Locker Top of locker #36	3" x 36"
WRC-11		Supply/Locker Floor in Corridor btw Assembly Hall & Locker 2' S of N 12' E of door to Ass. Hall	100 cm ²
WRC-12		Supply/Locker Floor register on N wall	1" x 15.75"
WRC-13		Supply/Locker Floor Bullet trap pit	100 cm ²
WRC-14	✓	Supply/Locker window sill on E wall Office 3	100 cm ²

Aria Environmental, Inc

ASBESTOS BULK AND PAINT CHIP SAMPLING SURVEY SHEET

Inspector: **Non-Responsive**
 License/Accreditation No.: [REDACTED]
 Witnessed By: _____

Date Collected: 10-19-12
 Job Site: Waterbury, VT
 Project No.: J12-685

Sample No.	Type of Material Sampled	Floor	Functional Area	Sample Location	Comments
WRC-20	Paint White emul wall	1	Supply/Storage	North wall Between fire extinguisher & former bullet trap ~ 4' AFF	> 1 ft. Damage

Appendix C Photo Documentation

VT Rex W. Morse RC



Photo 1: Main entrance to Rex W. Morse Readiness Center.



Photo 2: Main entrance to Rex W. Morse Readiness Center.



Photo 3: Assembly Hall with M119 Howitzers.



Photo 4: Supply/Locker Room.

VT Rex W. Morse RC



Photo 5: Kitchen.



Photo 6: Damaged floor tile with exposed mastic in kitchen.



Photo 7: Kitchen.



Photo 8: View of Assembly Hall from loading dock.

VT Rex W. Morse RC



Photo 9: Renovated boiler room.



Photo 10: Maintenance Storage.



Photo 11: Flammable materials storage cabinets with MSDS book.



Photo 12: View inside flammable materials storage cabinet.

Appendix D IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Rex Morse	IAQ							Light			
Date	10/19/2012	Inspector	Non-Responsive	Instrument		Q-trak 7565-X					Instrument		Cal-Light 400L	
Facility Description	Rex W. Morse RC			Serial Number		7575x1228004					Serial Number		K040084EL	
Weather Conditions	Rainy			Last Calibration		Jul-12					Last Calibration		16-Apr-12	
Location	Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
Classroom	Classroom	var	1433	67.4	X	57.4		731		4.0		17.8	X	30-50
Men's Latrine	Latrine	var	1439	67.1	X	59.5		643		4.2		9.5		5
Women's Latrine	Latrine	var	1440	66.8	X	61.3	X	621		4.0		3.3	X	5
Janitor's Closet	Storage	var	1441	67.0	X	60.1	X	633		3.8		15.0	X	30
Assembly Hall	Assembly Hall	var	1442	67.2	X	58.5		635		3.8		45.4		30-50
Office	Office	1	1443	67.4	X	58.1		630		3.8		21.3	X	30-50
Gym	Gym	var	1444	67.7	X	57.5		614		4.0		12.5	X	30
Table Storage	Storage	var	1445	67.4	X	57.0		611		3.8		29.9		10
Maintenance Office	Office	1	1446	67.2	X	56.6		603		3.8		41.1		30-50
Kitchen	Storage	1	1447	67.1	X	57.8		600		3.8		37.6		5
Kitchen	Kitchen	var	1448	67.1	X	59.0		594		3.8		44.0	X	50
Boiler Room	Boiler Room	1	1449	64.9	X	59.1		522		3.7		4.9	X	30
Maintenance Storage	Storage	1	1450	64.8	X	60.1	X	527		3.8		7.0	X	30
Vault	Storage	1	1451	65.1	X	54.4		665		3.6		26.1		10
Supply	Office/Storage	2	1452	66.1	X	56.6		650		3.5		27.6	X	30
Locker Storage	Storage	var	1453	66.6	X	57.7		590		3.7		7.4	X	10
Office 3	Office	1	1454	67.3	X	59.1		633		3.6		47.1		30-50
Office 2	Office	1	1455	68.1		58.6		647		3.7		52.4		30-50
Office 1	Office	1	1456	68.1		58.2		645		3.6		48.0		30-50
Entry Vestibule	Corridor	1	1457	67.8	X	57.4		658		3.8		5.8	X	10
Office 4	Office	1	1457	68.6		56.9		753		3.8		49.6		30-50

Shaw Environmental, Inc.

312 Directors Drive
Knoxville, TN 37923
865.690.3211
Fax 865.690.3626



Shaw Environmental, Inc.

**National Guard Armory
Westminster Readiness Center – Westminster, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

01 March 2004

**National Guard Armory
Westminster Readiness Center – Westminster, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

01 March 2004

Prepared by:

Non-Responsive

Industrial Hygienist

Reviewed by:

Non-Responsive

Business Line Manager

Table of Contents

<i>Table of Contents</i>	<i>i</i>
<i>List of Tables</i>	<i>ii</i>
<i>List of Appendices</i>	<i>ii</i>
<i>Executive Summary</i>	<i>E-1</i>
<i>1.0 Introduction</i>	<i>1-1</i>
<i>2.0 Findings, Discussion, and Interpretation of Results</i>	<i>2-1</i>
<i>2.1 Sampling for Lead</i>	<i>2-1</i>
<i>2.1.1 Wipe Sampling</i>	<i>2-1</i>
<i>2.1.2 Air Sampling for Lead</i>	<i>2-2</i>
<i>2.2 Physical Condition of Facility</i>	<i>2-2</i>
<i>2.2.1 Peeling Paint - Lead</i>	<i>2-2</i>
<i>2.2.2 Visual Inspection - Asbestos</i>	<i>2-2</i>
<i>2.2.3 Visual Inspection - Water Damage and Mold</i>	<i>2-3</i>
<i>2.2.4 Visual Inspection - Housekeeping</i>	<i>2-3</i>
<i>2.3 Building Concerns</i>	<i>2-3</i>
<i>2.3.1 Ergonomic Concerns</i>	<i>2-3</i>
<i>2.3.2 Indoor Air Quality</i>	<i>2-3</i>
<i>2.4 Safety and Industrial Hygiene Programs</i>	<i>2-4</i>
<i>2.5 Ventilation</i>	<i>2-4</i>
<i>2.5.1 Ventilation System Evaluation</i>	<i>2-4</i>
<i>2.5.2 Contamination of Clean Air Sources</i>	<i>2-4</i>
<i>2.6 Noise Exposure</i>	<i>2-4</i>
<i>2.7 Lighting</i>	<i>2-4</i>
<i>2.8 Indoor Firing Range</i>	<i>2-5</i>
<i>2.9 HVAC Systems</i>	<i>2-5</i>
<i>2.10 IHIM</i>	<i>2-5</i>
<i>3.0 Conclusions</i>	<i>3-1</i>
<i>Tables</i>	<i>Follows Section 3.0</i>
<i>Appendices</i>	<i>Follows Tables</i>

List of Tables

Table 1	Wipe Sampling for Lead
Table 2	Air Sampling for Lead
Table 3	Peeling Paint Sampling for Lead
Table 4	Indoor Air Quality Measurements
Table 5	Illumination Readings
Table 6	Indoor Firing Ranges – Wipe Sampling

List of Appendices

Appendix A	HHM Data Form
Appendix B	Building Layout
Appendix C	Sampling Sheets and Laboratory Analyses
Appendix D	References
Appendix E	Recommendations for Surface Lead Dust in Armories

Executive Summary

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Westminster Readiness Center in Westminster, Vermont. [Non-Responsive] [Non-Responsive] performed the evaluation on 4 August 2003 and 7 October 2003. The point of contact at the readiness center was [Non-Responsive].

The following industrial hygiene concerns were evaluated.

- Wipe Sampling for Lead
- Air Sampling for Lead
- Peeling Paint – Lead
- Suspected Asbestos Containing Material
- Water Damage
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Indoor Air Quality
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- Lighting
- Converted Indoor Firing Range
- HVAC Systems

The following items were either not applicable to the armory or the evaluation resulted in a conclusion that there were no industrial hygiene concerns.

- Air Sampling for Lead
- Peeling Paint – Lead
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Safety and Industrial Hygiene Programs

- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- HVAC Systems

Areas where there were industrial hygiene concerns are as follows:

- Wipe sampling for lead revealed concentrations above the recommended level at one location in armory. It is recommended that this surface and the area immediately around this surface be thoroughly cleaned to reduce the lead level. In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.
- Wipe sampling for lead revealed concentrations above a level of 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) in the assembly hall. Areas with lead concentrations above 40 $\mu\text{g}/\text{ft}^2$ that will be accessible to children should be cleaned. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.
- Materials suspected of containing asbestos were observed. An operations and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.
- Water damage was observed at two locations at the armory. The sources of the water damage were likely from a roof leak on the first floor and building foundation breach/high water table concerning the basement wall. The sources of the water damage should be confirmed and actions taken to eliminate the sources in order to prevent the possibility of mold growth that may lead to indoor air quality problems.
- Indoor air quality measurements revealed that the humidity and temperature on the first floor at the armory exceeded the recommended levels. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory to control the humidity. Window air-conditioning units and/or fans can be used for cooling purposes and to circulate air.
- Lighting measurements were conducted at the armory. The lighting did not meet minimum requirements in some areas; therefore consideration should be given to providing more lighting in these areas. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

- Wipe sampling for lead in the converted firing range revealed concentrations above the recommended level at all of the locations sampled. These areas must be decontaminated by a thorough cleaning until surface lead concentrations are reduced to below recommended levels. In addition, employees should not be allowed to work in these areas without protective clothing until the areas have been cleaned and re-sampled.

1.0 Introduction

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Westminster Readiness Center in Westminster, Vermont. [Non-Responsive] [Non-Responsive] performed the evaluation on 4 August 2003 and 7 October 2003. The point of contact at the readiness center was [Non-Responsive]

The findings, discussion, and interpretation of results are provided in Section 2.0. The conclusions are provided in Section 3.0. The HHIM data form for the facility is provided in Appendix A. The building layout is provided in Appendix B. Sampling sheets and laboratory analyses are provided in Appendix C. References are provided in Appendix D. The *Recommendations for Surface Lead Dust in Armories* document is provided in Appendix E.

The statements, opinions, and conclusions contained in this report are based solely upon the services performed by Shaw as described in the report. In performing these services and preparing the report, Shaw Environmental, Inc. relied upon the work and information provided by others, including public agencies, whose information is not guaranteed by Shaw Environmental, Inc.

2.0 Findings, Discussion, and Interpretation of Results

The results, discussion, and interpretation of results are provided in the following sections.

2.1. Sampling for Lead

2.1.1 Wipe Sampling

Wipe samples were collected for lead from the drill floor/assembly area. Also, wipe samples were collected for lead in rooms, hallways, foyers, etc. The sampling in rooms, hallways, foyers, etc. represented approximately 25% of the building. Approximately half of the samples were collected from surfaces in common areas, such as surfaces of a desk. The remaining samples were collected from uncommon surface areas, such as a supply vent or the top of a file cabinet. The samples were collected and analyzed in accordance with the *Instructions for Completing the Sampling of ARMY National Guard Armories* procedure.

The only samples initially submitted for analysis were those from the drill floor/assembly hall. If there were any positive results from the drill floor/assembly hall, the other samples would be submitted for analysis.

Results of the wipe sampling are provided in Table 1. The results revealed lead at all locations sampled at concentrations below recommended level of 200 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$) (See Appendix E) except at one location. One sample collected from the assembly hall (heater unit flap surface) had a lead concentration of $1000 \mu\text{g}/\text{ft}^2$. It is recommended that this surface and the immediate area around the surface be thoroughly cleaned to reduce the lead level to below $200 \mu\text{g}/\text{ft}^2$. For guidance on the proper method of cleaning, please refer to NG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.

In addition, wipe sampling for lead revealed concentrations above a level of $40 \mu\text{g}/\text{ft}^2$ in the assembly hall. Please note that the *Recommendations for Surface Lead Dust in*

Armories (Appendix B) states that all areas with lead concentrations above $40 \mu\text{g}/\Omega^2$ that will be accessible to children should be cleaned. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.

2.1.2 Air Sampling for Lead

Breathing zone air sampling was conducted on one (1) full-time building occupant. (Please note that no state employees were monitored.) The sample was collected and analyzed in accordance with Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods.

The results of the sampling are provided in Table 2. The results revealed non-detectable concentrations of lead in the breathing zone of the employee; therefore, no actions are necessary.

2.2 Physical Condition of Facility

2.2.1 Peeling Paint - Lead

Peeling paint was observed in the armory at one location; the converted firing range/storage room wall. The Department of Housing and Urban Development (HUD) defines lead-based paint as paint or other surface coatings that contain lead equal to or 0.5 percent by weight. Bulk sampling results revealed lead at that location was below 0.5 percent by weight. Since HUD does not consider the paint a lead-based paint, no actions are necessary. The results of the sampling are provided in Table 3.

2.2.2 Visual Inspection - Asbestos

A visual inspection was made to determine if there was any suspected asbestos-containing material at the armory. Materials suspected of containing asbestos were observed. The suspected asbestos-containing material was insulation in the boiler room (approximately 7.5 linear feet). The condition of the boiler room insulation material was considered good (no rips, tears, or other damage).

An operation and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.

2.2.3 Visual Inspection – Water Damage and Mold

A visual inspection was made to determine if there was any water damage or visible mold at the armory. Mold was not observed, however water damage was observed at the armory. Water damage was observed as a stained ceiling tile in the CDR office and stained walls and ceiling in the range room.

The source of the water damage was likely from a roof leak concerning the CDR office stained tile, and a building foundation breach/high water table concerning the Range room damage. The source of the water damage should be confirmed and actions taken to eliminate the source in order to prevent the possibility of mold growth that may lead to indoor air quality problems.

2.2.4 Visual Inspection - Housekeeping

The housekeeping was determined to be good.

2.3. Building Concerns

2.3.1 Ergonomic Concerns

Interviews with employees and observation of work activities revealed no ergonomic concerns at the armory.

2.3.2 Indoor Air Quality

Interviews with employees revealed ventilation as an indoor air quality concern at the armory. In addition, measurements for humidity and temperature revealed levels that exceeded the American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommendations of 60% humidity and 79 degrees Fahrenheit in the summer. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory to control the humidity. Window air-conditioning units and/or fans can be used for cooling purposes and to circulate air.

The results of the measurements for carbon dioxide, humidity, and temperature are provided in Table 4.

2.4. Safety and Industrial Hygiene Programs

An evaluation was performed to determine the applicability of the following programs.

- Confined Spaces
- Hearing Conservation
- Respiratory Protection
- Hazard Communication (HAZCOM)
- Personal Protective Equipment (PPE)

It was determined that the HAZCOM program was the only program listed above that was applicable at the facility. The HAZCOM program was evaluated and it was determined that the program met minimum requirements.

2.5. Ventilation

2.5.1 Ventilation System Evaluation

There were no local exhaust ventilation systems at this armory; therefore, no ventilation studies were performed.

2.5.2 Contamination of Clean Air Sources

Since there were no local exhaust ventilation systems at the armory, there was no possibility that clean air sources could be contaminated by exhaust air.

2.6. Noise Exposure

An evaluation was performed to determine if there were any hazardous noise areas at the armory. It was determined that there were no areas at the armory that would exceed the permissible exposure limit for noise.

2.7 Lighting

Lighting measurements were conducted at the armory. Results of the lighting evaluation are provided in Table 5. As can be seen from the results, the lighting did not meet the minimum requirements in some areas, including the NBC/supply room (office area), locker room, kitchen storage room, storage room and women's latrine.

Consideration should be given to providing more lighting to the areas listed above. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

2.8 Indoor Firing Range

There is an inactive indoor firing range used as a storage room at the facility; therefore, wipe samples were taken for lead at various locations in or near the range. It should be noted that the room is not occupied by personnel and is infrequently utilized. The results are provided in Table 5. The results revealed lead, with associated concentrations, at the following locations:

- floor outside the range at 1100 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$);
- floor at 1900 $\mu\text{g}/\text{ft}^2$;
- stored item (desktop) at 1300 $\mu\text{g}/\text{ft}^2$; and
- overhead heater at 3200 $\mu\text{g}/\text{ft}^2$.

The lead levels at all of these locations were above the recommended level of 200 $\mu\text{g}/\text{ft}^2$, a level recommended in the *Guidelines for Converting Indoor Firing Ranges to Other Uses* document (Department of Army). These areas must be decontaminated by a thorough cleaning until surface lead concentrations are reduced to below recommended levels. For guidance on the proper method of cleaning, please refer to NG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, employees should not be allowed to work in these areas without protective clothing until the areas have been cleaned and re-sampled.

2.9. HVAC System

There was not a HVAC system at the armory.

2.10. HHIM

A Health Hazard Information Module (HHIM) form was completed for the armory. The completed form is provided in Appendix A.

3.0 Conclusions

It is concluded that there were no industrial hygiene concerns at the armory with regards to atmospheric exposure to lead, peeling lead-based paint, visible mold, housekeeping, ergonomic conditions, safety and industrial hygiene programs, ventilation systems or contamination of clean air sources, noise exposure, and HVAC systems.

There were industrial hygiene concerns at the armory with regards to lead surface contamination, suspected asbestos-containing material, water damage, indoor air quality, surface lead contamination in the converted firing range, and lighting. These concerns are discussed in detail in Section 2.0 of this report.

TABLES

Table 1
Wipe Sampling for Lead
National Guard Armory
Westminster, Vermont
Dates of Sampling: 04 August 2003 and 7 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTWES216-1	Drill Floor (See Building Layout – Appendix B)	< 110
VTWES216-2	Drill Floor (See Building Layout – Appendix B)	< 110
VTWES216-3	Drill Floor (See Building Layout – Appendix B)	< 110
VTWES216-4	Drill Floor (See Building Layout – Appendix B)	< 110
VTWES216-5	Drill Floor (See Building Layout – Appendix B)	< 110
VTWES216-6	Field Blank	< 12 μg
VTWES216-11	Classroom – table top	13
VTWES216-12	Field Blank	0.3 μg
VTWES216-13	Kitchen – refrigerator top surface	< 2.7
VTWES216-14	Supply Room – printer top surface	18
VTWES216-15	RNCO Office – desktop	11
VTWES216-16	CDR Office – desktop	15
VTWES216-17	Weight Room – book shelf	32
VTWES216-18	Field Blank	< 0.3 μg
VTWES281-1	Assembly Room – windowsill (See Building Layout – Appendix B)	7.5
VTWES281-2	Assembly Room – table top (See Building Layout – Appendix B)	13
VTWES281-3	Assembly Room – heater unit flap surface (See Building Layout – Appendix B)	1000
VTWES281-4	Assembly Room – soda machine top surface (See Building Layout – Appendix B)	150

^aMicrograms lead per square foot

Table 1 Continued
Wipe Sampling for Lead
National Guard Armory
Westminster, Vermont
Dates of Sampling: 08 August 2003 and 7 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTWES281-5	Assembly Room mail slot top surface (See Building Layout - Appendix B)	65
VTWES281-6	Field Blank	< 0.3 μg

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the instructions for *Completing the Sampling of Army National Guard Armories* procedure.

In armories that do not contain childcare facilities, the NGB Region North Industrial Hygiene Office recommends cleaning the areas with lead concentrations greater than 200 $\mu\text{g}/\text{ft}^2$.

Table 2
Breathing Zone Air Samples for Lead
National Guard Armory
Westminster, Vermont
Date of Sampling: 04 August 2003

Sample Number	Employee	Sampling Information			Results (mg/m ³) ^a
		Time Sampled / Minutes	Flow Rate (lpm) ^b	Volume (liters)	
VTWES216-A1	Non-Responsive	1344-1532/118	2.4945	294.35	<0.003
VTWES216-A2	Field Blank	-	-	-	None Detected

^a Milligrams lead per cubic meter of air.

^b Liters of air per minute.

Only one employee was sampled because there were no other employees at the armory on the date of the survey.

Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods was followed for sampling for lead.

Table 3
Peeling Paint Sampling for Lead
National Guard Armory
Westminster, Vermont
Date of Sampling: 04 August 2003

Sample Number	Location	Results, % By Weight
VTWES216-B1	Converted Firing Range (Storage Room)	0.0035

The Department of Housing and Urban Development (HUD) defines lead-based as paint or other surface coatings that contain lead equal to or exceeding 0.5 percent by weight.

Table 4
Indoor Air Quality Measurements for Carbon Dioxide, Humidity, and Temperature
National Guard Armory
Westminster, Vermont
Date of Sampling: 04 August 2003

Location	Occupants in Area	Carbon Dioxide, parts per million parts of air (ppm)	Percent (%) Humidity	Temperature (°F)
1 st Floor – Classroom	1	501	73.6	79.9
Basement	1	521	79.6	72.0
Outdoors	0	431	74.0	85.1

Carbon dioxide, humidity, and temperature measurements were taken with a TSI Q Trak Plus, Model 8554, Indoor Air Quality Meter, calibrated in April 2003.

American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommends that indoor carbon dioxide levels be less than 700 ppm above outdoor levels.

ASHRAE recommends that the relative humidity levels be maintained between 30 to 60 percent.

ASHRAE recommends that the acceptable temperature range be 68 degrees Fahrenheit to 74 degrees Fahrenheit in the winter and 73 degrees Fahrenheit to 79 degrees Fahrenheit in the summer.

Table 5
Illumination Readings
National Guard Armory
Westminster, Vermont
Date of Sampling: 04 August 2003

Location	Luminance (fc) ^a	Standard (fc) ^a	Standard Met
Kitchen	51.3-125.3	70	Some Areas
Locker Room	2.1-7.4	40	No
NBC Room/Supply Room (office area)	11.1-67.8	70	No
Weight Room	37-140	70	Some Areas
Classroom	24.3-108	70	Some Areas
Storage room	13.1-23.5	30	No
ISG Office	37.6-132.3	70	Some Areas
Administrative Office	72.1-135.6	70	Yes
Kitchen -- storage room	9.8-23.2	30	No
Women's Latrine	11.1-23.2	40	No

^a fc - Footcandles

The readings were taken with a Cooke Corporation cal-LIGHT 400 Calibrated Precision Lightmeter, calibrated on 19 Aug 2002.

The standards listed above are from ANSI/IES RP-1 and RP-7.

Table 6
Wipe Sampling for Lead – Converted Firing Range
National Guard Armory
Westminster, Vermont
Date of Sampling: 04 August 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTWES216-7	Floor Outside the Range	1100
VTWES216-8	Floor	1900
VTWES216-9	Stored Item – stored desk	1300
VTWES216-10	Overhead heaters	3200

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

Appendix A

HHIM Data Form(s)

HEALTH HAZARD INFORMATION MODULE: INDUSTRIAL HYGIENE SURVEY

(For use of this form, see HHIM User's Guide)

SECTION 1. DEMOGRAPHIC DATA

ARLOC	INSTALLATION Westminster Armory Vermont ARNG	BLDG/RM NO. Westminster		
LOCATION/CODE Administrative Areas / AA	OPERATION/CODE Administrative Operations / ADO			
SURVEY DATE 04 August 2003	EVALUATOR (Initials) Non-Responsive			
MACOM/CODE Army National Guard	SUBMACOM/CODE XX	SUPERVISOR Non-Responsive		
TELEPHONE/DSN NO. 802-722-4259	UNIT/ORGANIZATION Company B, 2nd Battalion	RAC 4	FREQUENCY (hrs/day) 8	
NO. CIV(S) 2	NO. MIL 2	NO. CONTRACTOR(S) 0	NO. LOC(S) 0	NO. OTHER 0

SECTION 2. FACILITY DATA

LAB HOODS 0	VAPOR DEGREASERS 0	SPRAY BOOTHS 0
MAINTENANCE BAYS 0	OPEN SURFACE TANKS 0	VENTILATION UNITS 0

SECTION 3. SURVEY DATA

CONTROLS PRESENT	EVALUATION	UNIT CODE	CONTROLS REQUIRED	STATUS

PERSONAL PROTECTIVE EQUIPMENT (R = Required; U = Utilized)

GLOVES	R	U	RESPIRATOR	NOSH TC NO.	MANUFACTURER	R	U
ACID			AIRLINE				
COLD SURFACES			ABRASIVE BLASTING HOOD				
HOT SURFACES			DISPOSABLE				
NBC AGENTS			FULL FACE AIR PURIFYING				
OIL			1/2 FACE AIR PURIFYING				
SOLVENTS			POWERED AIR PURIFYING				
SURGICAL GLOVES			1/4 FACE AIR PURIFYING				
			SELF CONTAINED				

EYES/FACE	R	U	HEARING	R	U	BODY	R	U	HEAD/FIT	R	U
CHEMICAL SPLASH			CANAL CAPS			APRONS			COLD WEATHER BOOTS/HATS		
FULL FACE SHIELD			EAR PLUGS			COLD WEATHER CLOTHING			HARD HATS		
CHEMICAL/SAFETY			HELMETS			COVERALLS			IMPERMEABLE BOOTS		
SAFETY/IMPACT			MUFFS			FULL BODY SUIT			SAFETY/CONDUCTIVE SHOES		
WELDING HELMETS			MUFF/EARPLUG COMBO			HEAT REFLECTIVE VEST/SUIT			SAFETY/NON-CONDUCTIVE SHOES		
			MUFF/EARPLUG W/TIME LIMIT			SAFETY BELT/HARNES					

SECTION 4. HAZARD INVENTORY DATA

CAS CODE	HAZARD DESCRIPTION	PAC	EPC
POVDTXXX	Video Display Terminal	3-low	Uncontrolled D Physical
1382-21-4	Asbestos other	2 moderate	Uncontrolled Respiratory
7439-92-1	Lead, Inorganic dusts and fumes, as Pb	2 moderate	Uncontrolled Respiratory

SECTION 5. PERSONNEL DATA

LAST NAME	FIRST NAME	MI	SEX	SSN	CATEGORY
Non-Responsive				Non-Responsive	MIL
					↓
					CIV
					↓

SECTION 6. COMMENTS

No comments. See attached sheet
 Survey conducted by Michele Seman. Building contains 2 full-time military employees and 2 state employees. Full-time military employees perform mainly administrative functions.


PRIVACY ACT STATEMENT

Title 5 US Code, Section 301; Executive Order 9397 authorizes the use of your Social Security Number as an identification number. The purpose of this information is to identify and monitor data relating each DA civilian and military employee exposed to a hazardous workplace or operation. The use of this information is to provide histories of exposures for any given worker.

Disclosure of your Social Security Number is not mandatory; however, nondisclosures may result in untimely provision of proper medical monitoring.

Appendix B

Building Layout




○ - Sample date 04 August 2003
 △ - Sample date 07 October 2003

FIRST FLOOR PLAN
 WESTMINSTER ARMOURY
 SCALE: 1" = 20' 23/NOV/83

FIRE ESCAPE PLAN

7-330



Note: Basement only consists of Range Room

Basement	PLAN
WESTMINSTER ARMORY	
SCALE: 1" = 20' 23/NOV/81	

7-330

Appendix C

Sampling Sheets and Laboratory Analyses

Client: National Guard Bureau
Address: 301-TH Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation
 Havre de Grace, Maryland 21078
Job Name: VTWES216
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 07-01
Chain Of Custody: 115914
Date Analyzed: 08/15/2003
Person Submitting: [Redacted]
Report Date: 15-Aug-03

Attention: [Redacted] Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0362255	VTWES216-1	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362256	VTWES216-2	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362257	VTWES216-3	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362258	VTWES216-4	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362259	VTWES216-5	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0362260	VTWES216-6	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0362261	VTWES216-7	Flame	Wipe	****	0.111	108.00 ug/ft ²	1100 ug/ft ²	
0362262	VTWES216-8	Flame	Wipe	****	0.111	108.00 ug/ft ²	1900 ug/ft ²	
0362263	VTWES216-9	Flame	Wipe	****	0.111	108.00 ug/ft ²	1300 ug/ft ²	
0362264	VTWES216-10	Flame	Wipe	****	0.111	108.00 ug/ft ²	3200 ug/ft ²	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)
 Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Non-Responsive

Non-Responsive

Technical Manager:

Analyst:

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

An AIHA (#38663), NVLAP (# 101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

Client: National Guard Bureau
Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SI,
 State Military Reservation
 Havre de Grace, Maryland 21078

Job Name: VTWES281
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 0701

Chain Of Custody: I18701
Date Analyzed: 10/16/2003

Person Submitting: [Redacted]
Report Date: 16-Oct-03

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0402814	VTWES281 -1	Furnace	Wipe	****	0.111	2.70 ug/ft ²	7.5 ug/ft ²	
0402815	VTWES281 -2	Furnace	Wipe	****	0.111	2.70 ug/ft ²	13 ug/ft ²	
0402816	VTWES281 -3	Furnace	Wipe	****	0.111	202.52 ug/ft ²	1000 ug/ft ²	
0402817	VTWES281 -4	Furnace	Wipe	****	0.111	67.51 ug/ft ²	150 ug/ft ²	
0402818	VTWES281 -5	Furnace	Wipe	****	0.111	13.50 ug/ft ²	65 ug/ft ²	
0402819	VTWES281 -6	Furnace	Wipe Blank	****	N/A	0.30 ug	< 0.3 ug	

Analysis Method for Flame: Air, Wipes, Paints, and Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
Analysis Method For Furnace: Air, Wipes, Paints, and Solids: EPA 600/R-93/200(M)-7421; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] **Technical Manager:** [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

All rights reserved. AMA Analytical Services, Inc.

AIHA (#8863), NVLAP (#101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643

Client: National Guard Bureau
Address: 301-4H Old Bay Lane, Atrn: NGB-AVN-SI, State Military Reservation
 Havre de Grace, Maryland 21078
Job Name: VTWES216
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 0701
Chain of Custody: 118889
Date Analyzed: 10/27/2003
Person Submitting: [Redacted]
Report Date: 27-Oct-03

Attention: [Redacted]

Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0404038	VTEWS216-11	Furnace	Wipe	****	0.111	2.70 ug/ft ²	13 ug/ft ²	
0404039	VTEWS216-12	Furnace	Wipe Blank	****	N/A	0.30 ug	0.3 ug	
0404040	VTEWS216-13	Furnace	Wipe	****	0.111	2.70 ug/ft ²	< 2.7 ug/ft ²	
0404041	VTEWS216-14	Furnace	Wipe	****	0.111	2.70 ug/ft ²	18 ug/ft ²	
0404042	VTEWS216-15	Furnace	Wipe	****	0.111	2.70 ug/ft ²	11 ug/ft ²	
0404043	VTEWS216-16	Furnace	Wipe	****	0.111	2.70 ug/ft ²	15 ug/ft ²	
0404044	VTEWS216-17	Furnace	Wipe	****	0.111	5.40 ug/ft ²	32 ug/ft ²	
0404045	VTEWS216-18	Furnace	Wipe Blank	****	N/A	0.30 ug	< 0.3 ug	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnaces: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7421; Water: SM-3113B

N/A = Not Applicable mg/Kg = parts per million (ppm) by weight mg/L = parts per million (ppm)

%Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted]

Technical Manager: [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, support is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

All rights reserved. AMA Analytical Services, Inc.



Submitted To: **Non-Responsive**
 Shaw Environmental, Inc.
 101 Fieldcrest Ave., 4th Floor
 Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTBEN216-A1 through VTRUT217-A3
P.O. No.:	Not Available
Sample Location:	VT
Sample Type:	Filter
Method Reference:	NIOSH 7300
DCL Set ID No.:	03-S-3834
DCL Sample ID No.:	03-23429 through 03-23442
Sample Receipt Date:	8/8/2003
Preparation Date:	08/11/03
Analysis Date:	08/11/03

The samples were prepared and analyzed in accordance with NIOSH method 7300 using a Perkin Elmer 3000XL ICP.

The sample condition upon receipt was acceptable except where noted.

The results are in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive

Analyst

Non-Responsive

CINCINNATI OFFICE
 4388 GLENDALE-MILFORD ROAD
 CINCINNATI, OHIO 45242-3706
 513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
 11 SANTA YORMA COURT
 NOVATO, CALIFORNIA 94945
 800 280-8071, FAX 415 893-9469

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTBEN216-A1	03-23429	402.71	ND	<0.002
VTBEN216-A2	03-23430	404.73	ND	<0.002
VTBEN216-A3	03-23431	0	ND	-
VTWES216-A1	03-23437	294.35	ND	<0.003
VTWES216-A2	03-23438	0	ND	-
VTRUT217-A1	03-23440	420.05	ND	<0.002
VTRUT217-A2	03-23441	412.99	ND	<0.002
VTRUT217-A3	03-23442	0	ND	-
	Prep Blank		ND	
% Recovery	LCS		100.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).
LCS = laboratory control sample.

Non-Responsive

Analyst

Non-Responsive



Submitted To: **Non-Responsive**
Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTBEN216-B1 through VTRUT217-B6
P.O. No.:	Not Available
Sample Location:	VT
Sample Type:	Paint Chip
Method Reference:	3050B/6010B
DCL Set ID No.:	03-S-3834
DCL Sample ID No.:	03-23432 through 03-23448
Sample Receipt Date:	8/8/2003
Preparation Date:	8/8/2003
Analysis Date:	8/12/2003

The samples were prepared in accordance with EPA method 3050B. Sample condition was acceptable upon receipt except where noted. The samples were then analyzed in accordance with EPA method 6010B using a Jarrell Ash Trace ICP.

The results are provided in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive

Analyst

Non-Responsive

Reviewer

CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 280-6071, FAX 415 893-9469

Results
Lead

Client #	DCL #	mg/Kg (ppm)	% by weight
VTBEN216-B1	03-23432	190000.	19.
VTBEN216-B2	03-23433	4000.	0.40
VTBEN216-B3	03-23434	4400.	0.44
VTBEN216-B4	03-23435	36000.	3.6
VTBEN216-B5	03-23436	2400.	0.24
VTWES216-B1	03-23439	35.	0.0035
VTRUT217-B1	03-23443	1600.	0.16
VTRUT217-B2	03-23444	440.	0.044
VTRUT217-B3	03-23445	5800.	0.58
VTRUT217-B4	03-23446	97000.	9.7
VTRUT217-B5	03-23447	53000.	5.3
VTRUT217-B6	03-23448	8700.	0.87
	Prep Blank	ND	
% Recovery	LCS	93.	
% Recovery	23303MS	98.	
% Recovery	23303MSD	96.	
RPL		25.	0.0025

ND = not detected at or above the reporting limit (RPL).

LCS = laboratory control sample.

MS/MSD = matrix spike/matrix spike duplicate.

Non-Responsive



Analyst

Non-Responsive



Reviewer

Industrial Hygiene Sampling Calculation Worksheet

National Guard Armory **Location:** **WES**
8/4/2003

Sample 1

Sample Number: **VTWES216-A1**
Pump: **648399**

	Pre Flow Rate	Post Flow Rate
	2.498	2.466
	2.503	2.488
	2.501	2.49
	2.503	2.507
Average	2.501	2.488

Average Pre and Post **2.4945**

Time 1 **13:34**
Time 2 **15:32**
Total Time Sampled **1:58**
Minutes Sampled **118.00**

Volume **294.35 Liters**

Sample 2

Sample Number: **N/A**
Pump: **N/A**

	Pre Flow Rate	Post Flow Rate
	N/A	N/A
Average	N/A	N/A

Average Pre and Post **N/A**

Time 1 **N/A**
Time 2 **N/A**
Total Time Sampled **N/A**
Minutes Sampled **N/A**

Volume **N/A** **Liters**

Appendix D

References

References

Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration (current edition)

American Society of Heating, Refrigerating and Air-Conditioning Engineers, Inc (ASHRAE) 62-2002, Ventilation for Acceptable Indoor Air Quality

Instructions for Completing the Sampling of Army National Guard Armories, Lead Wipe Sampling Procedure included with the Request for Proposal

Air Sampling for Lead - Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods

Design Guide DG-415-2, Logistics Facilities, National Guard Bureau Installation Division, 14 December 1999

Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998

Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, 15 October 1990

AR 385-10, The Army Safety Program, 29 February 2000

Department of the Army Pamphlet (DA PAM) 40-501, Medical Services, Hearing Conservation Program, 10 December 1998

DA PAM 40-503, Medical Services, Industrial Hygiene Program, 30 October 2000

Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH) (current edition)

Guidelines for Converting Indoor Firing Ranges to Other Uses, Headquarters, Department of the Army and the Air Force, NG PAM (AR) 385-16/ANGPAM 91-101, 31 January 1994

24 CFR, Part 35, Subpart B, Section 35-110, Definition of Lead-Based Paint, Housing and Urban Development, U. S. Department of Housing

Appendix E
Recommendations for
Surface Lead Dust in Armories

Subject: Recommendations for Surface Lead Dust in Armories

1. In armories that do not contain childcare facilities, the National Guard Bureau (NGB) Region North Industrial Hygiene Office recommends cleaning the areas in which sample results are greater than 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$). If a special function will be held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function. This guidance is based on professional judgment, risk assessments, adaptation of Occupational Safety and Health Administration (OSHA) guidance, and feasibility of cleaning to a certain level.

a. Environmental Protection Agency (EPA) standards (40 Code of Federal Regulations (CFR) 745.227(h)(3)) are not directly applicable because they are criteria for dust-lead hazards developed for floors ($40 \mu\text{g}/\text{ft}^2$) and windowsills ($250 \mu\text{g}/\text{ft}^2$) in residential dwellings and child occupied facilities. A child occupied facility is defined as a building, or portion of a building, constructed prior to 1978, visited regularly by the same child, 6 years of age or under, on at least two different days within any week (Sunday through Saturday period), provided that each day's visit lasts at least 3 hours and the combined weekly visit lasts at least 6 hours, and the combined annual visits last at least 60 hours. Most of the wipe samples in armories were collected in undisturbed areas and therefore, results are worst case scenarios and do not correlate to these standards.

b. OSHA has no specific requirement for work area surfaces. The lead standard (29 CFR 1910.1025(b)) states that all surfaces shall be maintained as free as practicable of accumulations of lead dust. In workplaces where lead dust is generated, surface levels may be much higher, but personnel exposures can be controlled by limiting airborne lead levels and following good cleanup and hygienic practices.

c. OSHA used to cite a level of $200 \mu\text{g}/\text{ft}^2$ in their Technical Manual and 29 CFR 1926.62 as guidance to its own inspectors for evaluating the cleanliness of lunchroom and locker room surfaces that are supposed to be kept as clean as possible.

d. In a report titled Derivation of Wipe Surface Screening Levels for Environmental Chemicals, the US Army Center for Health Promotion and Preventive Medicine (USACHPPM) has determined that $200 \mu\text{g}/\text{ft}^2$ is a safe surface contamination level. They have also applied these standards as the decontamination levels for surfaces in administrative offices.

e. It should be noted that levels above these recommendations do not necessarily mean there is a significant hazard to workers who are following good cleaning and hygienic practices since there is no correlation between wipe and air samples. Rather, we recommend these levels as a precautionary measure.

2. The NGB Occupational Health Branch is developing guidance for armories that are used as childcare facilities. All states will receive this guidance when it is completed. In the interim, we recommend the following actions:

a. Clean all areas that will be accessible to children to the EPA dust-lead standard for children 6 years of age or under ($40 \mu\text{g}/\text{ft}^2$ on floors and $250 \mu\text{g}/\text{ft}^2$ on windowsills).

b. Refer to the local authorities' regulations since they can be more stringent than federal regulations.

c. Post signs in the area to inform people of the presence of lead dust and its effects.

d. If soldiers clean weapons in the facility change the policy so that they cannot clean their weapons in the facility, or if they are allowed to clean their weapons indoors, they must clean the area by wet wiping and mopping the area when they are done.

e. If the paint is peeling, contact the state Environmental Office to test for lead content and provide recommendations.

3. Air samples collected on individuals in the armory were well below OSHA's permissible exposure limit for lead (29 CFR 1910.1025(c)) of $0.05 \text{ mg}/\text{m}^3$ averaged over an 8-hour day. Therefore, based on these conditions there is currently no overexposure to personnel from lead dust in this building.

Industrial Hygiene Survey

Vermont Army National Guard (VT ARNG)

Prepared For: NGB ARNG– Region North IH Office

Survey Location:

Westminster Readiness Center
23 Armory Lane
Westminster, VT 05158

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 24, 2012

AEI Project #: 12685 3m VT Westminster RC

Non-Responsive
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Westminster Readiness Center**

Table of Contents

Executive Summary ii

1 Introduction 1

2 Evaluation Methods 1

3 Operations 1

4 Noise Hazards 1

5 Hazard Controls 1

Ventilation Systems 1

6 Physical Condition of the Facility and Personnel Concerns 2

Paint Chip and Dust Wipe Samples for Lead Contamination 2

Visual Inspection for Damaged Asbestos-Containing Materials 3

Visual Inspection for Water Damage and Mold Growth 3

Visual Inspection for Housekeeping Concerns 3

Lighting 3

Indoor Air Quality (IAQ) 3

Temperature and Relative Humidity 4

Carbon Dioxide (CO₂) and Carbon Monoxide (CO) 4

7 Conclusions 4

8 Limitations 5

List of Tables and Appendices

Table 1 - Results of Dust Wipe Sampling for the VT ARNG Westminster Readiness Center on October 24, 2012.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

Appendix A – Building Layout

Appendix B – Certificates of Analysis for Air, Dust Wipe and Bulk Samples

Appendix C – Photo Documentation

Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Westminster Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Westminster Readiness Center located at 23 Armory Lane, Westminster VT 05158. **Non-Responsive** performed the evaluation on October 24, 2012. The point of contact for the facility was Sergeant **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Paint Chip and Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed on the roof drain located in the drill hall. Due to the height of the peeling paint, a sample was not collected. A Evidence of peeling paint that had been repaired was observed in the women's latrine. Results of dust wipe samples taken throughout the facility were below the recommended maximum criterion for surface contamination of lead (200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$)) in all areas sampled.

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there were any suspect asbestos-containing material and its condition A damaged fitting was observed on a roof drain at the roof line of the drill hall. Due to the height of the peeling paint, a sample was not collected.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or evidence of mold growth was observed on the day of the survey.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping was good.

Lighting: A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in the Drill Hall and Kitchen. The illumination measurements indoors ranged from 10.7 foot candles (fc) to 124.4 fc.

Indoor Air Quality: Temperature and relative humidity measurements were mostly within the comfort ranges for the winter season on the day of the survey. The outdoor temperature and relative humidity were 68.1° F and 29.0% on the day of monitoring. Indoor concentrations of carbon dioxide (CO_2) and carbon monoxide (CO) were below the guidelines in all areas.

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updated MSDSs are required per OSHA 29 CFR 1910.1200. It is recommended that a copy of the written hazard communication program be placed in every MSDS notebook. MSDSs for some new custodial products are required per OSHA 29 CFR 1910.1200.

Overall, the Westminster Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Westminster Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Westminster Readiness Center located at 23 Armory Lane, Westminster VT 05158. Non-Responsive performed the evaluation on October 24, 2012. The point of contact for the facility was Sergeant Non-Responsive. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

The Westminster Readiness Center was built in 1976. The readiness center is staffed by 7 administrative personnel. The operations conducted at the facility include supply and administrative duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the Westminster Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) evaluations of operations including operation description, sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the Westminster facility consist exclusively of supply and administrative duties. No other maintenance of vehicles or other physical tasks are performed at the facility. A small garage exists in the facility basement but it is only used for storage.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Westminster Readiness Center**

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were collected in select areas.

Paint Chip and Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed on the roof drain located in the drill hall. Due to the height of the peeling paint, a sample was not collected. Evidence of peeling paint that had been repaired was observed in the women's latrine.

To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected using ghost wipes and 10 centimeter (cm) x 10cm templates. The Environmental Protection Agency (EPA) and the State of Vermont limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. All wipe samples collected from the facility were below the recommended maximum levels for adult exposures. Results are given in Table 1 and certificates of analysis are included in Appendix B.

**Table 1 –Dust Wipe Sampling Data Sheet for VT ARNG
Westminster Readiness Center on October 24, 2012.**

Wipe Sample #	Wipe Sample Location	Lead by Weight ($\mu\text{g}/\text{ft}^2$)
WRC-01	Kitchen, Prep Table	<110
WRC-02	Drill Hall, Middle of floor	<110
WRC-03	Drill Hall, on stored desks	<110
WRC-04	Drill Hall, Wall climbing mats	<110
WRC-05	Room 12, Supply grill	<110
WRC-06	Room 19, Top of refrigerator	<110
WRC-07	Room 14, Work station	<110
WRC-08	Room 8, Window sill	<110
WRC-09	Classroom, From table	<110
WRC-10	Stairs outside former firing range, Floor	<110
WRC-11	Garage/Former Indoor Firing Range, Former bullet trap	<110

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Westminster Readiness Center**

**Table 1 –Dust Wipe Sampling Data Sheet for VT ARNG
Westminster Readiness Center on October 24, 2012.**

Wipe Sample #	Wipe Sample Location	Lead by Weight ($\mu\text{g}/\text{ft}^2$)
WRC-12	Garage/Former Indoor Firing Range, Light fixture	<110
WRC-13	Garage/Former Indoor Firing Range, Overhead heater	<110
WRC-14	Garage/Former Indoor Firing Range, Stored lockers	<110
WRC-15	Garage/Former Indoor Firing Range, Floor	<110

*The recommended maximum level for adult exposures is 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) lead on surfaces.

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). A damaged fitting was observed on a roof drain at the roof line of the drill hall. Due to the height of the peeling paint, a sample was not collected.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or evidence of mold growth was observed on the day of the inspection.

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping was good. Most areas were clean and tidy.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on April 16, 2012, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in the Drill Hall and Kitchen. The illumination measurements indoors ranged from 10.7 foot candles (fc) to 124.4 fc. The complete results of the evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Model 7575, factory calibrated in July, 2012. Temperature, relative humidity and carbon dioxide (CO_2) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Westminster Readiness Center**

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 2. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30 and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 62.7 to 74.4° F and 31.4 to 44.1% Rh. Temperatures and relative humidity were mostly within the winter comfort ranges in the areas monitored. The outdoor temperature and relative humidity was 68.1° F and 29.0% on the day of monitoring.

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1–2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 406 to 664 parts per million (ppm). CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange.

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 0.5 to 0.8 ppm; therefore, concentrations are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

Additional Information

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was not readily available, and updated MSDSs are required per OSHA 29 CFR 1910.1200. It is recommended that a copy of the written hazard communication program be placed in every MSDS notebook. MSDSs for some new custodial products are required per OSHA 29 CFR 1910.1200.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Westminster Readiness Center**

7 Conclusions

The results of the evaluation indicated few concerns at the facility. Overall, the Westminster Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.

9 References

1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.
3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.
4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.
5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2012.
6. Army Regulation (AR) 420-70 Buildings and Structures, 11 November 1997.
7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 13 December 2007.
8. Army Regulation (AR) 420-1 Army Facilities Management, 12 February 2008, RAR 24 August 2012.
9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.


**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Westminster Readiness Center**

10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.
12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.
13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".
15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.

Appendix A Building Layout

50B10 Westminster Armory Floor Plan

BEST AVAILABLE COPY



* Assume all elbows (MJPI's) are positive for asbestos

Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	Westminster, RC	Chain Of Custody:	514369
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Westminster, VT	Date Submitted:	11/2/2012
Attention:	Non-Responsive	Job Number:	Not Provided	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/9/2012
				Report Date:	11/9/2012

Summary of Atomic Absorption Analysis for Lead

Page 1 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
13010676	WRC-01	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010677	WRC-02	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010678	WRC-03	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010679	WRC-04	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010680	WRC-05	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010681	WRC-06	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010682	WRC-07	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010683	WRC-08	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010684	WRC-09	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010685	WRC-10	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010686	WRC-11	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010687	WRC-12	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010688	WRC-13	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010689	WRC-14	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010690	WRC-15	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	Westminster, RC	Chain Of Custody:	514369
Address:	301-JH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Westminster, VT	Date Submitted:	11/2/2012
		Job Number:	Not Provided	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/9/2012
				Report Date:	11/9/2012

Attention: Non-Responsive

Summary of Atomic Absorption Analysis for Lead

Page 2 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	----------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm)
 %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb)

See QC Summary for analytical results of quality control samples associated with these samples.

Note: All samples were received in good condition unless otherwise noted.

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Air and Wipe results are not corrected for any blank results

Final results for air and wipe samples are based on client supplied information nor verified by this laboratory.

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Analyst: Non-Responsive

Technical Manager: Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.

Date Collected: October 24, 2012
Location: Westminster Readiness Center
Project No: J120685
Inspector: **Non-Responsive**

**Table 1 –Dust Wipe Sampling Data Sheet for VT ARNG
Westminster Readiness Center on October 24, 2012.**

Wipe Sample #	Sample Location	Area
WRC-01	Kitchen, Prep Table	10 cm x 10 cm
WRC-02	Drill Hall, Middle of floor	10 cm x 10 cm
WRC-03	Drill Hall, on stored desks	10 cm x 10 cm
WRC-04	Drill Hall, Wall climbing mats	10 cm x 10 cm
WRC-05	Room 12, Supply grill	10 cm x 10 cm
WRC-06	Room 19, Top of refrigerator	10 cm x 10 cm
WRC-07	Room 14, Work station	10 cm x 10 cm
WRC-08	Room 8, Window sill	10 cm x 10 cm
WRC-09	Classroom, From table	10 cm x 10 cm
WRC-10	Stairs outside former firing range, Floor	10 cm x 10 cm
WRC-11	Garage/Formal Indoor Firing Range, Former bullet trap	10 cm x 10 cm
WRC-12	Garage/Formal Indoor Firing Range, Light fixture	10 cm x 10 cm
WRC-13	Garage/Formal Indoor Firing Range, Overhead heater	10 cm x 10 cm
WRC-14	Garage/Formal Indoor Firing Range, Stored lockers	10 cm x 10 cm
WRC-15	Garage/Formal Indoor Firing Range, Floor	10 cm x 10 cm

Appendix C Photo Documentation

Westminster RC



Photo 1: Westminster Readiness Center



Photo 2: Westminster Readiness Center



Photo 3: Office



Photo 4: Office

Westminster RC



Photo 5: Former Firing Range



Photo 6: Former Firing Range




Photo 7: Stairwell with Exit



Photo 8: Fitness Room

Westminster RC



Photo 9: Restroom



Photo 10: Drill Hall



Photo 11: Classroom



Photo 12: Rear of Classroom

Westminster RC



Photo 13: Office



Photo 14: Janitor's Closet



Photo 15: Mechanical Room



Photo 16: Mechanical Room

Westminster RC



Photo 17: Kitchen



Photo 18: Rear of Readiness Center



Photo 19: Drill Hall



Photo 20: Damaged Roof Drain Fitting at Roof Deck of Drill Hall

Westminster RC



Photo 21: Peeling Paint on Roof Drain in Drill Hall



Photo 22: Entryway

Appendix D IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Westminster	IAQ								Light		
Date	10/24/2012	Inspector	Non-Responsive	Instrument	Q-trak 7565-X						Instrument	Cal-Light 400L		
Facility Description	Westminster RC			Serial Number	7575x1228011						Serial Number	4980243		
Weather Conditions				Last Calibration	Jul-12						Last Calibration	16-Apr-12		
Location	Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
1	Storage			69.8		34.0		458		0.7		22.3		30
2	Kitchen			69.8		34.1		406		0.7		40.6	X	50
3	Mechanical Room			74.2		31.6		590		0.5		62.4		30
4	Janitor's Closet			74.7		36.7		664		0.5		40.3		30
5	Women's Latrine			73.3		31.4		540		0.5		10.7		5
6	Hallway			73.0		33.2		544		0.8		45.5		5
7	Men's Latrine			72.3		37.6		553		0.7		57.8		5
8	Weight Room			71.1		37.7		555		0.5		36.7		30
9	Attached Garage/Storage			64.4	X	39.2	X	441		0.8		35.4		30
10	Stairwell			62.7	X	40.9	X	465		0.7		29.8		5
11	Classroom			67.0	X	44.1	X	529		0.5		106.4		30-50
12	Commander's Office			68.1	X	40.5	X	474		0.5		72.5		30-50
13	1st SGT Office			69.8		40.1		516		0.5		33.7		30-50
14	Office			70.1		39.5		516		0.5		124.4		30-50
15	Recruiter's Office			70.7		39.7		590		0.6		105.2		30-50
16	Entry Vestibule			70.5		37.7		480		0.7		30.2		10
17	Office			70.5		37.7		480		0.7		83.0		30-50
18	Office			71.2		39.6		507		0.5		58.5		30-50
19	Office			71.5		38.1		556		0.6		51.5		30-50
20	Drill Hall			71.5		36.3		527		0.5		35.9	X	50

NATIONAL GUARD BUREAU
ARMY NATIONAL GUARD
REGION NORTH INDUSTRIAL HYGIENE OFFICE
ATTN: NGB-AVS-SI
301-IH OLD BAY LANE
HAVRE DE GRACE, MD 21078-4094

NGB-AVS-SI (40-5f)

21 January 2004

MEMORANDUM FOR VTARNG, Winooski, RC, ATTN: SSG [Redacted] Non-Responsive
255 Lafountan Street, Winooski, VT 05404

SUBJECT: Annual Survey Report

1. I have enclosed the industrial hygiene survey report completed by Shaw Environmental, Inc.
2. Please contact me at (410) 942-0273 or 1-800-550-6967 if you have any questions regarding the enclosed report.

Encl

[Redacted] Non-Responsive
Regional Industrial Hygienist

CF: SOHM, LTC [Redacted] Non-Responsive

Shaw Environmental, Inc.

312 Directors Drive
Knoxville, TN 37923
865.690.3211
Fax 865.690.3626



Shaw Environmental, Inc.

**National Guard Armory
Winooski Readiness Center – Winooski, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

04 January 2004

**National Guard Armory
Winooski Readiness Center – Winooski, Vermont**

Industrial Hygiene Evaluation

Prepared for:

**National Guard Region North Industrial Hygiene Office
Havre De Grace, Maryland 21078**

Prepared by:

**Shaw Environmental, Inc.
312 Directors Drive
Knoxville, Tennessee 37923**

04 January 2004

Prepared by:

Non-Responsive

Industrial Hygienist

Reviewed by:

Non-Responsive

Business Line Manager

Table of Contents

<i>Table of Contents</i>	<i>i</i>
<i>List of Tables</i>	<i>ii</i>
<i>List of Appendices</i>	<i>ii</i>
<i>Executive Summary</i>	<i>E-1</i>
<i>1.0 Introduction</i>	<i>1-1</i>
<i>2.0 Findings, Discussion, and Interpretation of Results</i>	<i>2-1</i>
<i>2.1 Sampling for Lead</i>	<i>2-1</i>
<i>2.1.1 Wipe Sampling</i>	<i>2-1</i>
<i>2.1.2 Air Sampling</i>	<i>2-2</i>
<i>2.2 Physical Condition of Facility</i>	<i>2-2</i>
<i>2.2.1 Peeling Paint - Lead</i>	<i>2-2</i>
<i>2.2.2 Visual Inspection - Asbestos</i>	<i>2-3</i>
<i>2.2.3 Visual Inspection - Water Damage and Mold</i>	<i>2-3</i>
<i>2.2.4 Visual Inspection - Housekeeping</i>	<i>2-3</i>
<i>2.3 Building Concerns</i>	<i>2-3</i>
<i>2.3.1 Ergonomic Concerns</i>	<i>2-3</i>
<i>2.3.2 Indoor Air Quality</i>	<i>2-3</i>
<i>2.4 Safety and Industrial Hygiene Programs</i>	<i>2-4</i>
<i>2.5 Ventilation</i>	<i>2-4</i>
<i>2.5.1 Ventilation System Evaluation</i>	<i>2-4</i>
<i>2.5.2 Contamination of Clean Air Sources</i>	<i>2-4</i>
<i>2.6 Noise Exposure</i>	<i>2-4</i>
<i>2.7 Lighting</i>	<i>2-5</i>
<i>2.8 Converted Indoor Firing Ranges</i>	<i>2-5</i>
<i>2.9 HVAC Systems</i>	<i>2-5</i>
<i>2.10 IHUM</i>	<i>2-6</i>
<i>3.0 Conclusions</i>	<i>3-1</i>
<i>Tables</i>	<i>Follows Section 3.0</i>
<i>Appendices</i>	<i>Follows Tables</i>

List of Tables

Table 1	Wipe Sampling for Lead
Table 2	Air Sampling for Lead
Table 3	Peeling Paint Sampling for Lead
Table 4	Indoor Air Quality Measurements
Table 5	Illumination Readings
Table 6	Indoor Firing Ranges - Wipe Sampling

List of Appendices

Appendix A	IHIM Data Form
Appendix B	Building Layout
Appendix C	Sampling Sheets and Laboratory Analyses
Appendix D	References
Appendix E	Recommendations for Surface Lead Dust in Armories

Executive Summary

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Winooski Readiness Center in Winooski, Vermont. **Non-Responsive** performed the evaluation on 21 July 2003 and 9 October 2003. The point of contact at the readiness center was SSG **Non-Responsive**.

The following industrial hygiene concerns were evaluated.

- Wipe Sampling for Lead
- Air Sampling for Lead
- Peeling Paint – Lead
- Suspected Asbestos Containing Material
- Water Damage
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Indoor Air Quality
- Safety and Industrial Hygiene Programs
- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- Lighting
- Converted Indoor Firing Range
- HVAC Systems

The following items were either not applicable to the armory or the evaluation resulted in a conclusion that there were no industrial hygiene concerns.

- Air Sampling for Lead
- Water Damage
- Presence of Mold
- Housekeeping
- Ergonomic Concerns
- Safety and Industrial Hygiene Programs

- Ventilation System Evaluation
- Contamination of Clean Air Sources
- Noise Exposure
- HVAC Systems

Areas where there were industrial hygiene concerns are as follows:

- Wipe sampling for lead revealed concentrations above the recommended level at four locations in the assembly/drill hall. It is recommended that these surfaces and the areas immediately around these surfaces be thoroughly cleaned to reduce the lead level. In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.
- Wipe sampling for lead revealed concentrations above a level of 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) in the Company B Administrative Office. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.
- Peeling paint was observed in the supply room (former bullet trap room of firing range) and bulk sampling results revealed this paint to be a lead-based paint. Anyone who may perform repair and/or maintenance activities on this surface should be made aware of the presence of the lead-based paint so appropriate precautions (control of exposures, personal protective equipment, training, etc.) can be taken.
- Materials suspected of containing asbestos were observed. An operations and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.
- Indoor air quality measurements revealed that the humidity at the armory exceeded the recommended levels. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory.
- Lighting measurements were conducted at the armory. The lighting did not meet minimum requirements in most areas; therefore consideration should be given to providing more lighting in these areas. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.
- Wipe sampling for lead in the converted firing range revealed concentrations above the recommended level at all of the locations sampled. These areas must be decontaminated by a thorough cleaning along with re-sampling until surface lead

concentrations are reduced to below recommended levels. In addition, employees should not be allowed to work in these areas without protective clothing until the areas have been cleaned and re-sampled.

1.0 Introduction

Shaw Environmental, Inc. (Shaw) was contracted to perform an industrial hygiene evaluation for the Winooski Readiness Center in Winooski, Vermont. **Non-Responsive** performed the evaluation on 21 July 2003 and 9 October 2003. The point of contact at the readiness center was SSG **Non-Responsive**

The findings, discussion, and interpretation of results are provided in Section 2.0. The conclusions are provided in Section 3.0. The HHIM data form for the facility is provided in Appendix A. The building layout is provided in Appendix B. Sampling sheets and laboratory analyses are provided in Appendix C. References are provided in Appendix D. The *Recommendations for Surface Lead Dust in Armories* document is provided in Appendix E.

The statements, opinions, and conclusions contained in this report are based solely upon the services performed by Shaw as described in the report. In performing these services and preparing the report, Shaw Environmental, Inc. relied upon the work and information provided by others, including public agencies, whose information is not guaranteed by Shaw Environmental, Inc.

2.0 Findings, Discussion, and Interpretation of Results

The results, discussion, and interpretation of results are provided in the following sections.

2.1. Sampling for Lead

2.1.1 Wipe Sampling

Wipe samples were collected for lead from the drill floor/assembly area. Also, wipe samples were collected for lead in rooms, hallways, foyers, etc. The sampling in rooms, hallways, foyers, etc. represented approximately 25% of the building. Approximately half of the samples were collected from surfaces in common areas, such as surfaces of a desk. The remaining samples were collected from uncommon surface areas, such as a supply vent or the top of a file cabinet. The samples were collected and analyzed in accordance with the Instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

The only samples initially submitted for analysis were those from the drill floor/assembly hall. If there were any positive results from the drill floor, the other samples would be submitted for analysis.

Results of the wipe sampling are provided in Table I. The results revealed lead at all locations sampled at concentrations below recommended level of 200 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$) (See Appendix E) except at four locations. The samples obtained from the heater unit flap surface, locker (AYDINYAN) top surface, locker (BOYLE) top surface, and soda machine top surface in the assembly room had lead concentrations of 3,300, 43,000, 2,100, and 1,900 $\mu\text{g}/\text{ft}^2$, respectively. It is recommended that these surfaces and the immediate areas around the surfaces be thoroughly cleaned to reduce the lead level to below 200 $\mu\text{g}/\text{ft}^2$. For guidance on the proper method of cleaning, please refer to NG PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, any other dusty/dirty areas in the assembly area/drill floor should be thoroughly cleaned.

In addition, wipe sampling for lead revealed concentrations above a level of 40 $\mu\text{g}/\text{ft}^2$ in the Company B Administrative Office on the stereo system top surface. Please note that the *Recommendations for Surface Lead Dust in Armories* (Appendix B) states that all areas should be cleaned that will be accessible to children. If a special function is held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function.

2.1.2 Air Sampling

Breathing zone air sampling was conducted on one (1) full-time building occupant. (Please note that no state employees were monitored.) The sample was collected and analyzed in accordance with Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods.

The results of the sampling are provided in Table 2. The results revealed non-detectable concentrations of lead in the breathing zone of the employee; therefore, no actions are necessary.

2.2 Physical Condition of Facility

2.2.1 Peeling Paint - Lead

Peeling paint was observed in the armory. The Department of Housing and Urban Development (HUD) defines lead-based paint as paint or other surface coatings that contain lead equal to or exceeding 0.5 percent by weight. Bulk sampling results revealed lead at a concentration of 1.1 percent by weight in the paint sample taken from the supply room (former bullet trap room of firing range). The results of the sampling are provided in Table 3.

Anyone who may perform repair and/or maintenance activities on surfaces coated with lead-based paint should be made aware of the presence of the lead-based paint so appropriate precautions (control of exposures, personal protective equipment, training, etc.) can be taken.

It should be noted that the firing range lead wipe sampling results (See Section 2.8) indicate lead concentrations above the recommended level of 200 $\mu\text{g}/\text{ft}^2$, therefore the possibility exists that the lead concentration indicated by the paint sample taken from the firing range room could be due to deposition rather than lead based paint.

2.2.2 Visual Inspection - Asbestos

A visual inspection was made to determine if there was any suspected asbestos-containing material at the armory. Floor tiles suspected of containing asbestos were observed. The suspected asbestos-containing materials were floor tiles in the Company B RNCO Office (Room 8), Company B ADMIN Office (Room 9), and Company C ADMIN Office (Room 2) (approximately 895 square feet), and insulation in the boiler room (approximately 15-16 linear feet and 14-16 pipe joints/elbows). The condition of the floor tiles materials was considered average since there was some damage to tiles at the doorways. The condition of the boiler room insulation materials was considered good (no rips, tears, or other damage).

An operation and maintenance plan should be followed when performing any activities that may disturb the suspected asbestos-containing materials.

2.2.3 Visual Inspection – Water Damage and Mold

A visual inspection was made to determine if there was any water damage or visible mold at the armory. Visible mold was not observed, however, water damage was observed at the armory. The water damage was observed on the Company B ADMIN Office (Room 9) ceiling.

The source of the water damage was likely from a roof leak. John MacFarland stated that the roof membrane was replaced in the past year and a half. The source of the water damage is not longer present; therefore, no additional actions are necessary.

2.2.4 Visual Inspection - Housekeeping

The housekeeping was determined to be good.

2.3. Building Concerns

2.3.1 Ergonomic Concerns

Interviews with employees and observation of work activities revealed no ergonomic concerns at the armory.

2.3.2 Indoor Air Quality

Interviews with employees revealed no indoor air quality concerns at the armory. However, measurements for humidity revealed that levels exceeded the American

Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommended level of 60% in the armory. Since there is no HVAC system at the armory, it is recommended that a dehumidification system be installed at the armory.

The results of the measurements for carbon dioxide, humidity, and temperature are provided in Table 4.

2.4. Safety and Industrial Hygiene Programs

An evaluation was performed to determine the applicability of the following programs.

- Confined Spaces
- Hearing Conservation
- Respiratory Protection
- Hazard Communication (HAZCOM)
- Personal Protective Equipment (PPE)

It was determined that the HAZCOM program was the only program listed above that was applicable at the facility. The HAZCOM program was evaluated and it was determined that the program met minimum requirements.

2.5. Ventilation

2.5.1 Ventilation System Evaluation

There were no local exhaust ventilation systems at this armory; therefore, no ventilation studies were performed.

2.5.2 Contamination of Clean Air Sources

Since there were no local exhaust ventilation systems at the armory, there was no possibility that clean air sources could be contaminated by exhaust air.

2.6. Noise Exposure

An evaluation was performed to determine if there were any hazardous noise areas at the armory. It was determined that there were no areas at the armory that would exceed the permissible exposure limit for noise.

2.7 Lighting

Lighting measurements were conducted at the armory. The lighting did not meet the minimum requirements in the Company C ADMIN office, Company C CDR/IAG Office, Kitchen, Company B ADMIN Office, and the Company B RNCO Office. Some areas in the classroom meet minimum lighting requirements. Results of the lighting evaluation are provided in Table 5.

Consideration should be given to providing more lighting to the areas listed above. This may be accomplished by replacing burnt out luminaries, cleaning fixtures, cleaning windows, painting walls with a lighter color, repositioning detailed work to higher illuminated areas, and using supplemental lighting.

2.8. Converted Indoor Firing Ranges

There was a converted indoor firing range at the facility; therefore, wipe samples were collected for lead at various locations in or near the range. The results are provided in Table 6. The results revealed lead, with concentrations, at the following locations:

- Light fixture, at 240,000 micrograms lead per square foot ($\mu\text{g}/\text{ft}^2$); and
- stored item (outside caged storage area), at 180 $\mu\text{g}/\text{ft}^2$;
- floor, at 980 $\mu\text{g}/\text{ft}^2$; and
- stored item (youth group storage area), at 4,500 $\mu\text{g}/\text{ft}^2$.

The lead levels at three of these locations were above the recommended level of 200 $\mu\text{g}/\text{ft}^2$, a level recommended in the *Guidelines for Converting Indoor Firing Ranges to Other Uses* document (Department of Army). These areas must be decontaminated by a thorough cleaning along with re-sampling until surface lead concentrations are reduced to below recommended levels. For guidance on the proper method of cleaning, please refer to NGB PAM 385-16 (*Guidelines for Converting Indoor Firing Ranges to Other Uses*). In addition, employees should not be allowed to work in these areas without protective clothing until the areas have been cleaned and re-sampled.

2.9. HVAC System

There was not a HVAC system at the armory.

2.10. HHIM

A Health Hazard Information Module (HHIM) form was completed for the armory. The completed form is provided in Appendix A.

f

3.0 Conclusions

It is concluded that there were no industrial hygiene concerns at the armory with regards to atmospheric exposure to lead, water damage, visible mold, housekeeping, ergonomic conditions, safety and industrial hygiene programs, ventilation systems or contamination of clean air sources, noise exposure, and HVAC systems.

There were industrial hygiene concerns at the armory with regards to lead surface contamination, peeling lead-based paint, suspected asbestos-containing material, indoor air quality, surface lead contamination in the converted firing range, and lighting. These concerns are discussed in detail in Section 2.0 of this report.

TABLES

Table 1
Wipe Sampling for Lead
National Guard Armory
Winooski, Vermont
Dates of Sampling: 21 July 2003 and 9 October 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTWIN202-1	Drill Floor – On Floor (See Building Layout – Appendix B)	< 110
VTWIN202-2	Drill Floor – On Floor (See Building Layout – Appendix B)	< 110
VTWIN202-3	Drill Floor – On Floor (See Building Layout – Appendix B)	< 110
VTWIN202-4	Drill Floor – On Floor (See Building Layout – Appendix B)	< 110
VTWIN202-5	Drill Floor – On Floor (See Building Layout – Appendix B)	< 110
VTWIN202-6	Field Blank	< 12 μg
VTWIN202-11	Kitchen – counter top	< 2.7
VTWIN202-12	Field Blank	< 0.3 μg
VTWIN202-13	Classroom – table top	4.1
VTWIN202-14	Company B RNCO Office – desktop	6.6
VTWIN202-15	Company B Administrative Office – stereo system top surface	110
VTWIN202-16	Company C CDR/ISG Office – shelf top	14
VTWIN283-1	Assembly Room – heater unit flap surface (See Building Layout – Appendix B)	3300
VTWIN283-2	Assembly Room – locker (AYDINYAN) top surface (See Building Layout – Appendix B)	43000
VTWIN283-3	Assembly Room – locker (BOYLE) top surface (See Building Layout – Appendix B)	2100
VTWIN283-4	Assembly Room – soda machine top surface (See Building Layout – Appendix B)	1900
VTWIN283-1	Assembly Room – fire alarm control box top surface (See Building Layout – Appendix B)	36
VTWIN283-6	Field Blank	< 0.3 μg

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of Army National Guard Armories* procedure.

In armories that do not contain childcare facilities, the NGB Region North Industrial Hygiene Office recommends cleaning the areas with lead concentrations greater than 200 $\mu\text{g}/\text{ft}^2$.

Table 2
Breathing Zone Air Samples for Lead
National Guard Armory
Winooski, Vermont
Date of Sampling: 21 July 2003

Sample Number	Employee	Sampling Information			Results (mg/m ³) ^a
		Time Sampled / Minutes	Flow Rate (lpm) ^b	Volume (liters)	
VTWIN202-A1	Non-Responsive	0958-1059/61	2.507	152.91	<0.007
VTWIN202-A2	Field Blank	-	-	-	None Detected

^a Milligrams lead per cubic meter of air.

^b Liters of air per minute.

Only one employee was sampled because there were no other employees at the armory on the date of the survey.

Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods was followed for sampling for lead.

Table 3
Peeling Paint Sampling for Lead
National Guard Armory
Winooski, Vermont
Date of Sampling: 21 July 2003

Sample Number	Location	Results, % By Weight
VTWIN202-B1	Storage room (former bullet trap room of firing range) wall	1.1

The Department of Housing and Urban Development (HUD) defines lead-based as paint or other surface coatings that contain lead equal to or exceeding 0.5 percent by weight.

Table 4
Indoor Air Quality Measurements for Carbon Dioxide, Humidity, and Temperature
National Guard Armory
Winooski, Vermont
Date of Sampling: 21 July 2003

Location	Occupants in Area	Carbon Dioxide, parts per million parts of air (ppm)	Percent (%) Humidity	Temperature (°F)
1 st Floor Classroom	1	405	61.9	78.4
Outdoors	0	379	68.6	74.3

Carbon dioxide, humidity, and temperature measurements were taken with a TSI Q Trak Plus, Model 8554, Indoor Air Quality Meter, calibrated in April 2003.

American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) recommends that indoor carbon dioxide levels be less than 700 ppm above outdoor levels.

ASHRAE recommends that the relative humidity levels be maintained between 30 to 60 percent.

ASHRAE recommends that the acceptable temperature range be 68 degrees Fahrenheit to 74 degrees Fahrenheit in the winter and 73 degrees Fahrenheit to 79 degrees Fahrenheit in the summer.

Table 5
Illumination Readings
National Guard Armory
Winooski, Vermont
Date of Sampling: 21 July 2003

Location	Luminance (fc)^a	Standard (fc)^a	Standard Met
Company C ADMIN Office	19.3-58.3	70	No
Company C CDR/ISG Office	40.1-79.3	70	Some Areas
Kitchen	20.1-65.5	70	No
Company B ADMIN Office	23.5-58.3	70	No
Company B RNCO Office	20.1-59.6	70	No
Classroom	39.1-96.5	70	Some Areas

^a fc - Footcandles

The readings were taken with a Cooke Corporation cal-LIGHT 400 Calibrated Precision Lightmeter, calibrated on 19 Aug 2002.

The standards listed above are from Design Guide DG-415-2, Logistics Facilities, published by the National Guard Bureau Installation Division.

Table 6
Wipe Sampling for Lead – Converted Firing Range
National Guard Armory
Winooski, Vermont
Date of Sampling: 21 July 2003

Sample Number	Location	Results, $\mu\text{g}/\text{ft}^2$ ^a
VTWIN202-6	Blank	< 12 μg
VTWIN202-7	Light Fixture	240,000
VTWIN202-8	Stored Item (caged area)	180
VTWIN202-9	Floor	980
VTWIN202-10	Stored Item (youth group storage area)	4500

^a Micrograms lead per square foot

The samples were taken and analyzed in accordance with the Instructions for *Completing the Sampling of ARMY National Guard Armories* procedure.

Appendix A

HHIM Data Form(s)

HEALTH HAZARD INFORMATION MODULE: INDUSTRIAL HYGIENE SURVEY

(For use of this form, see HHIM User's Guide)

SECTION 1. DEMOGRAPHIC DATA

RLOC		INSTALLATION Winooski Armory Vermont ARNG		BLDG/RM NO. Winooski	
LOCATION/CODE Administrative Areas/AA			OPERATION/CODE Administrative OP/ADO		
SURVEY DATE 21 July 2003			EVALUATOR (Initials) Non-Responsive		
MACOM/CODE Army National Guard		SUBMACOM/CODE XX		SUPERVISOR Non-Responsive SSG	
TELEPHONE/DSN NO. 802-655-1288		UNIT/ORGANIZATION		RAC 5	FREQUENCY (hrs/day) 8
NO. CIV(S) 0	NO. MIL 6	NO. CONTRACTOR(S) 0	NO. LOC(S) 0	NO. OTHER 0	

SECTION 2. FACILITY DATA

FAB HOODS 0	VAPOR DEGREASERS 0		SPRAY BOOTHS 0	
MAINTENANCE BAYS 0	OPEN SURFACE TANKS 0		VENTILATION UNITS 0	

SECTION 3. SURVEY DATA

CONTROLS PRESENT	EVALUATION	UNIT CODE	CONTROLS REQUIRED	STATUS

PERSONAL PROTECTIVE EQUIPMENT (R = Required; U = Utilized)

GLOVES	R	U	RESPIRATOR	NOSH TC NO.	MANUFACTURER	R	U
ACID			AIRLINE				
COLD SURFACES			ABRASIVE BLASTING HOOD				
HOT SURFACES			DISPOSABLE				
NBC AGENTS			FULL FACE AIR PURIFYING				
OIL			1/2 FACE AIR PURIFYING				
SOLVENTS			POWERED AIR PURIFYING				
SURGICAL GLOVES			1/4 FACE AIR PURIFYING				
			SELF CONTAINED				

EYES/FACE	R	U	HEARING	R	U	BODY	R	U	HEAD/FT	R	U
CHEMICAL SPLASH			CANAL CAPS			APRONS			COLD WEATHER BOOTS/HATS		
FULL FACE SHIELD			EAR PLUGS			COLD WEATHER CLOTHING			HARD HATS		
CHEMICAL/SAFETY			HELMETS			COVERALLS			IMPERMEABLE BOOTS		
SAFETY/IMPACT			MUFFS			FULL BODY SUIT			SAFETY/CONDUCTIVE SHOES		
WELDING HELMET			MUFF/EARPLUG COMBO			HEAT REFLECTIVE VEST/SUIT			SAFETY/NON-CONDUCTIVE SHOES		
			MUFF/EARPLUG W/TIME LIMIT			SAFETY BELT/HARNES					

SECTION 4. HAZARD INVENTORY DATA

CAS CODE	HAZARD DESCRIPTION	PAC	EPC
POVDT XXXX	Video Display Terminal	3-low	Uncontrolled D Physical
7439-92-1	Lead, inorganic dusts and fumes, as Pb	2-moderate	Uncontrolled C Respiratory
1332-21-4	Asbestos (other)	2-moderate	Uncontrolled C Respiratory

SECTION 5. PERSONNEL DATA

LAST NAME	FIRST NAME	MI	SEX	SSN	CATEGORY
Non-Responsive			M	Non-Responsive	MIL
		A.	F		
			M		
			M		
			M		
			M		

SECTION 6. COMMENTS

No comments See attached sheet
 Survey conducted by Michele Semon, building contains 6 military full-time employees. Employees perform mainly administrative functions.

PRIVACY ACT STATEMENT

Title 5 US Code, Section 301; Executive Order 9397 authorizes the use of your Social Security Number as an identification number. The purpose of this information is to identify and monitor data relating each DA civilian and military employee exposed to a hazardous workplace or operation. The use of this information is to provide histories of exposures for any given worker.

Disclosure of your Social Security Number is not mandatory; however, nondisclosures may result in untimely provision of proper medical monitoring.

Appendix B

Building Layout

CLASSROOM

(16)

REC OFF

FOYER

CO C ADMIN Room 2

CO C CDR/1SG

CO C SUPPLY AREA

(B1) Print Out

MALE LATRINE

FEMALE LATRINE

JANITOR

KITCHEN

CO B ADMIN OFF

CO B RNCO OFF

CO B SUPPLY ROOM

CO B VAULT

BOILER ROOM

CO B SUPPLY

CO C SUPPLY ROOM

CO C VAULT

(4)

(5)

(3)

(15)

(14)

(2)

(1)

(7)

(10)

(8)

(9)

CO B SUPPLY AREA/ LOCKER ROOM

CO B SUPPLY AREA



Appendix C

Sampling Sheets and Laboratory Analyses

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau
Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SL
 State Military Reservation
 Haver de Grace, Maryland 21078

Job Name: VTWIN202
Job Location: Not Provided
Job Number: Not Provided
P.O. Number: 0701

Chain Of Custody: 115804
Date Analyzed: 8/5/2003
Person Submitting: [Redacted]
Report Date: 05-Aug-03

Page 1 of 1

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0359434	VTWIN202-1	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359435	VTWIN202-2	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359436	VTWIN202-3	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359437	VTWIN202-4	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359438	VTWIN202-5	Flame	Wipe	****	0.111	108.00 ug/ft ²	< 110 ug/ft ²	
0359439	VTWIN202-6	Flame	Wipe Blank	****	N/A	12.00 ug	< 12 ug	
0359440	VTWIN202-7	Flame	Wipe	****	0.111	108.00 ug/ft ²	240000 ug/ft ²	
0359441	VTWIN202-8	Flame	Wipe	****	0.111	108.00 ug/ft ²	180 ug/ft ²	
0359442	VTWIN202-9	Flame	Wipe	****	0.111	108.00 ug/ft ²	980 ug/ft ²	
0359443	VTWIN202-10	Flame	Wipe	****	0.111	108.00 ug/ft ²	4500 ug/ft ²	

Analysis Method for Flames: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200 (M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200 (M)-7421; Water: SM-3111B
 N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)
 Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted]
 Technical Manager: [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a national protection to clients, the public and these Laboratories, we report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection practices are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air-samples.

All rights reserved. AMA Analytical Services, Inc.

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau Job Name: VTWIN283 Chain Of Custody: 118715
Address: 301-IH Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation Job Location: Not Provided Date Analyzed: 10/21/2003
 Havre de Grace, Maryland 21078 Job Number: Not Provided Person Submitting: [Redacted]
Attention: [Redacted] P.O. Number: 0701 Report Date: 21-Oct-03

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Final Result	Comments
0402898	VTWIN283 -1	Furnace	Wipe	****	0.111	675.07 ug/ft ²	3300 ug/ft ²	
0402899	VTWIN283 -2	Furnace	Wipe	****	0.111	13501.35 ug/ft ²	43000 ug/ft ²	
0402900	VTWIN283 -3	Furnace	Wipe	****	0.111	675.07 ug/ft ²	2100 ug/ft ²	
0402901	VTWIN283 -4	Furnace	Wipe	****	0.111	675.07 ug/ft ²	1900 ug/ft ²	
0402902	VTWIN283 -5	Furnace	Wipe	****	0.111	5.40 ug/ft ²	36 ug/ft ²	
0402903	VTWIN283 -6	Furnace	Wipe Blank	****	N/A	0.30 ug	< 0.3 ug	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7421; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) by weight ug/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analysis: [Redacted] Technical Manager: [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

CERTIFICATE OF ANALYSIS

Client: National Guard Bureau **Job Name:** VTWIN202 **Chain Of Custody:** 118932
Address: 301-JH Old Bay Lane, Attn: NGB-AVN-SI, State Military Reservation **Job Location:** Not Provided **Date Analyzed:** 10/30/2003
 Havre de Grace, Maryland 21078 **Job Number:** Not Provided **Person Submitting:** [Redacted]
Attention: [Redacted] **P.O. Number:** Not Provided **Report Date:** 30-Oct-03

Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft²)	Reporting Limit	Final Result	Comments
0404841	VTWIN202-11	Furnace	Wipe	****	0.111	2.70 ug/ft²	< 2.7 ug/ft²	
0404842	VTWIN202-12	Furnace	Wipe Blank	****	N/A	0.30 ug	< 0.3 ug	
0404843	VTWIN202-13	Furnace	Wipe	****	0.111	2.70 ug/ft²	4.1 ug/ft²	
0404844	VTWIN202-14	Furnace	Wipe	****	0.111	2.70 ug/ft²	6.6 ug/ft²	
0404845	VTWIN202-15	Furnace	Wipe	****	0.111	67.51 ug/ft²	110 ug/ft²	
0404846	VTWIN202-16	Furnace	Wipe	****	0.111	2.70 ug/ft²	14 ug/ft²	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7420; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7421; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) mg/L = parts per million (ppm)
 %Pb = percent lead by weight ug = micrograms ug/L = parts per billion (ppb)

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Analyst: [Redacted] **Technical Manager:** [Redacted]

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a neutral protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP Accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples.

An AIHA (#8863), NVLAP (# 101143), & New York ELAP (#10920) Accredited Laboratory
 4475 Forbes Blvd. • Lanham, MD 20706 • (301) 459-2640 • Toll Free (800) 346-0961 • Fax (301) 459-2643
 All rights reserved. AMA Analytical Services, Inc.



TEST REPORT
Page 1 of 3
8/1/03

Submitted To: **Non-Responsive**
Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTCAM205-A1 through VTAAS204-A3
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Filter
Method Reference:	NIOSH 7300
DCL Set ID No.:	03-S-3621
DCL Sample ID No.:	03-22309 through 03-22345
Sample Receipt Date:	7/28/2003
Preparation Date:	07/29/03
Analysis Date:	07/31/03

The samples were prepared and analyzed in accordance with NIOSH method 7300 using a Perkin Elmer 3000XL ICP.

The sample condition upon receipt was acceptable except where noted.

The results are in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive



Analyst

Non-Responsive



CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 260-8071, FAX 415 893-8469

TEST REPORT
Page 2 of 3
03-S-3621

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTCAM205-A1	03-22309	407.54	ND	<0.002
VTCAM205-A2	03-22310	377.66	ND	<0.003
VTCAM205-A3	03-22311	0	ND	-
VTWIN202-A1	03-22313	152.91	ND	<0.007
VTWIN202-A2	03-22314	0	ND	-
VTENO196-A1	03-22316	150.55	ND	<0.007
VTENO196-A2	03-22317	0	ND	-
VTWIL197-A1	03-22319	199.78	ND	<0.005
	Prep Blank 1		ND	
% Recovery	LCS 1		96.	
% Recovery	LCS 2		96.	
RPL			1.	


ND = not detected at or above the reporting limit (RPL).
LCS = laboratory control sample.

Non-Responsive



Analyst

Non-Responsive





Submitted To: **Non-Responsive**
 Shaw Environmental, Inc.
 101 Fieldcrest Ave., 4th Floor
 Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTRED210-A2 through VTWIN210-A3
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Filter
Method Reference:	NIOSH 7300
DCL Set ID No.:	03-S-3799
DCL Sample ID No.:	03-23284 through 03-23312
Sample Receipt Date:	8/4/2003
Preparation Date:	08/07/03
Analysis Date:	08/07/03

The samples were prepared and analyzed in accordance with NIOSH method 7300 using a Perkin Elmer 3000XL ICP.

The sample condition upon receipt was acceptable except where noted.

The results are in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive

Analyst

Non-Responsive

Reviewer

CINCINNATI OFFICE
 4388 GLENDALE-MILFORD ROAD
 CINCINNATI, OHIO 45242-3706
 513 733-5336, FAX 513 733-5347

WEST COAST OFFICE
 11 SANTA YORMA COURT
 NOVATO, CALIFORNIA 94945
 800 280-8071, FAX 415 893-9469

Results Lead

Client #	DCL #	Sample Volume (L)	µg/sample	mg/m ³
VTRED210-A2	03-23284	0	ND	-
VTNEW209-A1	03-23285	210.24	ND	<0.005
VTNEW209-A2	03-23286	0	ND	-
VTBRA209-A1	03-23288	197.36	ND	<0.005
VTBRA209-A2	03-23289	0	ND	-
VTLYN209-A1	03-23290	186.67	ND	<0.005
VTLYN209-A2	03-23291	187.06	ND	<0.005
VTLYN209-A3	03-23292	0	ND	-
VTNOR213-A1	03-23293	376.81	ND	<0.003
VTNOR213-A2	03-23294	0	ND	-
VPLUD212-A1	03-23297	157.79	ND	<0.006
VPLUD212-A2	03-23298	275.40	ND	<0.004
VPLUD212-A3	03-23299	0	ND	-
VTWIN212-A1	03-23305	173.64	ND	<0.006
VTWIN212-A2	03-23306	0	ND	-
VTVER210-A1	03-23307	259.68	ND	<0.004
VTVER210-A2	03-23308	0	ND	-
VTRED210-A1	03-23309	158.68	ND	<0.006
VTWIN210-A1	03-23310	218.92	ND	<0.005
VTWIN210-A2	03-23311	193.56	ND	<0.005
VTWIN210-A3	03-23312	0	ND	-
	Prep Blank		ND	
% Recovery	LCS		99.	
RPL			1.	

ND = not detected at or above the reporting limit (RPL).
LCS = laboratory control sample.

Non-Responsive

Analyst

Non-Responsive

Reviewer



Submitted To: **Non-Responsive**
Shaw Environmental, Inc.
101 Fieldcrest Ave., 4th Floor
Edison, NJ 08837

Reference Data:	Lead
Client Sample No.:	VTCAM205-B1 through VTMCR203-B2
P.O. No.:	07-02
Sample Location:	VT
Sample Type:	Paint Chip
Method Reference:	3050B/6010B
DCL Set ID No.:	03-S-3621
DCL Sample ID No.:	03-22312 through 03-22339
Sample Receipt Date:	07/28/2003
Preparation Date:	07/29/2003
Analysis Date:	07/31/2003

The samples were prepared in accordance with EPA method 3050B. Sample condition was acceptable upon receipt except where noted. The samples were then analyzed in accordance with EPA method 6010B using a Jarrell Ash Trace ICP.

The results are provided in the enclosed data table. Results relate only to the items tested and are not blank corrected unless indicated in the data table.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Non-Responsive

Analyst

Non-Responsive

Reviewer

CINCINNATI OFFICE
4388 GLENDALE-MILFORD ROAD
CINCINNATI, OHIO 45242-3706
513 733-5338, FAX 513 733-5347

WEST COAST OFFICE
11 SANTA YORMA COURT
NOVATO, CALIFORNIA 94945
800 280-8071, FAX 415 893-9469

Results
Lead

Client #	DCL #	mg/Kg (ppm)	% by weight
VTCAM205-B1	03-22312	160.	0.016
VTWIN202-B1	03-22315	11000.	1.1
VPENO196-B1	03-22318	96000.	9.6
VTSTA197-B1	03-22327	1800.	0.18
VTWAT203-B1	03-22330	40.	0.0040
VTWAT203-B2	03-22331	57.	0.0057
VTMOR203-B1	03-22338	3900.	0.39
VTMOR203-B2	03-22339	11000.	1.1
	Prep Blank	ND	
% Recovery	LCS	87.	
% Recovery	03-22327 MS	* 0.	
% Recovery	03-22327 MSD	* 4.	
RPL		25.	0.0025

ND = not detected at or above the reporting limit (RPL).

LCS = laboratory control sample.

MS/MSD = matrix spike/matrix spike duplicate.

* Low recovery due to non-homogeneous sample matrix.

Non-Responsive



Analyst

Non-Responsive



Reviewer

Industrial Hygiene Sampling Calculation Worksheet

National Guard Armory
Date: JULY 21, 2003

Location: WINOOSKI

Sample 1

Sample Number: VTWIN202-A1

Pump: 648339

	Pre Flow Rate	Post Flow Rate
	2.542	2.475
	2.542	2.483
	2.534	2.477
	2.524	2.477
Average	2.536	2.478

Average Pre and Post **2.5068**

Time 1 9:58

Time 2 10:59

Total Time Sampled **1:01**

Minutes Sampled **61.00**

Volume **152.91 Liters**

Sample 2

Sample Number: N/A

Pump: N/A

	Pre Flow Rate	Post Flow Rate
	N/A	N/A
Average	N/A	N/A

Average Pre and Post **N/A**

Time 1 N/A

Time 2 N/A

Total Time Sampled **N/A**

Minutes Sampled **N/A**

Volume **N/A Liters**

Appendix D

References

References

Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration (current edition)

American Society of Heating, Refrigerating and Air-Conditioning Engineers, Inc (ASHRAE) 62-2002, Ventilation for Acceptable Indoor Air Quality

Instructions for Completing the Sampling of Army National Guard Armories, Lead Wipe Sampling Procedure included with the Request for Proposal

Air Sampling for Lead - Method 7082 of the National Institute of Occupational Safety and Health (NIOSH) Manual of Analytical Methods

Design Guide DG-415-2, Logistics Facilities, National Guard Bureau Installation Division, 14 December 1999

Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998

Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, 15 October 1990

AR 385-10, The Army Safety Program, 29 February 2000

Department of the Army Pamphlet (DA PAM) 40-501, Medical Services, Hearing Conservation Program, 10 December 1998

DA PAM 40-503, Medical Services, Industrial Hygiene Program, 30 October 2000

Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH) (current edition)

Guidelines for Converting Indoor Firing Ranges to Other Uses, Headquarters, Department of the Army and the Air Force, NG PAM (AR) 385-16/ANGPAM 91-101, 31 January 1994

24 CFR, Part 35, Subpart B, Section 35-110, Definition of Lead-Based Paint, Housing and Urban Development, U. S. Department of Housing

Appendix E
Recommendations for
Surface Lead Dust in Armories

Subject: Recommendations for Surface Lead Dust in Armories

1. In armories that do not contain childcare facilities, the National Guard Bureau (NGB) Region North Industrial Hygiene Office recommends cleaning the areas in which sample results are greater than 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$). If a special function will be held in which children will be present in this facility, consider thoroughly cleaning the areas that will be accessible to children prior to the function. This guidance is based on professional judgment, risk assessments, adaptation of Occupational Safety and Health Administration (OSHA) guidance, and feasibility of cleaning to a certain level.

a. Environmental Protection Agency (EPA) standards (40 Code of Federal Regulations (CFR) 745.227(h)(3)) are not directly applicable because they are criteria for dust-lead hazards developed for floors ($40 \mu\text{g}/\text{ft}^2$) and windowsills ($250 \mu\text{g}/\text{ft}^2$) in residential dwellings and child occupied facilities. A child occupied facility is defined as a building, or portion of a building, constructed prior to 1978, visited regularly by the same child, 6 years of age or under, on at least two different days within any week (Sunday through Saturday period), provided that each day's visit lasts at least 3 hours and the combined weekly visit lasts at least 6 hours, and the combined annual visits last at least 60 hours. Most of the wipe samples in armories were collected in undisturbed areas and therefore, results are worst case scenarios and do not correlate to these standards.

b. OSHA has no specific requirement for work area surfaces. The lead standard (29 CFR 1910.1025(h)) states that all surfaces shall be maintained as free as practicable of accumulations of lead dust. In workplaces where lead dust is generated, surface levels may be much higher, but personnel exposures can be controlled by limiting airborne lead levels and following good cleanup and hygienic practices.

c. OSHA used to cite a level of $200 \mu\text{g}/\text{ft}^2$ in their Technical Manual and 29 CFR 1926.62 as guidance to its own inspectors for evaluating the cleanliness of lunchroom and locker room surfaces that are supposed to be kept as clean as possible.

d. In a report titled Derivation of Wipe Surface Screening Levels for Environmental Chemicals, the US Army Center for Health Promotion and Preventive Medicine (USACHPPM) has determined that $200 \mu\text{g}/\text{ft}^2$ is a safe surface contamination level. They have also applied these standards as the decontamination levels for surfaces in administrative offices.

e. It should be noted that levels above these recommendations do not necessarily mean there is a significant hazard to workers who are following good cleaning and hygienic practices since there is no correlation between wipe and air samples. Rather, we recommend these levels as a precautionary measure.

2. The NGB Occupational Health Branch is developing guidance for armories that are used as childcare facilities. All states will receive this guidance when it is completed. In the interim, we recommend the following actions:

a. Clean all areas that will be accessible to children to the EPA dust-lead standard for children 6 years of age or under ($40 \mu\text{g}/\text{ft}^2$ on floors and $250 \mu\text{g}/\text{ft}^2$ on windowsills).

b. Refer to the local authorities' regulations since they can be more stringent than federal regulations.

c. Post signs in the area to inform people of the presence of lead dust and its effects.

d. If soldiers clean weapons in the facility change the policy so that they cannot clean their weapons in the facility, or if they are allowed to clean their weapons indoors, they must clean the area by wet wiping and mopping the area when they are done.

e. If the paint is peeling, contact the state Environmental Office to test for lead content and provide recommendations.

3. Air samples collected on individuals in the armory were well below OSHA's permissible exposure limit for lead (29 CFR 1910.1025(e)) of $0.05 \text{ mg}/\text{m}^3$ averaged over an 8-hour day. Therefore, based on these conditions there is currently no overexposure to personnel from lead dust in this building.

Field Notes and Checklist

State: Vermont Location: Winooski Date: 7/21/03
Contact: SS Non-Responsive

1.0 Sampling for Lead

1.1 Wipe Sampling

VTWIN 202-	Sample #: <u>1</u>	Picture #: <u> </u>	Location: <u>drill hall floor (see diagram)</u>
	Sample #: <u>2</u>	Picture #: <u> </u>	Location: <u>↓</u>
	Sample #: <u>3</u>	Picture #: <u> </u>	Location: <u>↓</u>
	Sample #: <u>4</u>	Picture #: <u> </u>	Location: <u>↓</u>
	Sample #: <u>5</u>	Picture #: <u> </u>	Location: <u>↓</u>
	Sample #: <u>6/12</u>	Picture #: <u> </u>	Location: <u>blanks</u>
	Sample #: <u>7</u>	Picture #: <u> </u>	Location: <u>firing range</u>
	Sample #: <u>8</u>	Picture #: <u> </u>	Location: <u>↓</u>
	Sample #: <u>9</u>	Picture #: <u> </u>	Location: <u>↓</u>
	Sample #: <u>10</u>	Picture #: <u> </u>	Location: <u>↓</u>
	Sample #: <u>11</u>	Picture #: <u> </u>	Location: <u>Kitchen - counter top</u>
	Sample #: <u>13</u>	Picture #: <u> </u>	Location: <u>Classroom - table surface</u>
	Sample #: <u>14</u>	Picture #: <u> </u>	Location: <u>Co B RUCG office - top of desk</u>
	Sample #: <u>15</u>	Picture #: <u> </u>	Location: <u>Co B ADMIN office - top of stereo</u>
	Sample #: <u>16</u>	Picture #: <u> </u>	Location: <u>Co C CDR/ISSG office - top of shelf</u>
	Sample #: <u> </u>	Picture #: <u> </u>	Location: <u> </u>
	Sample #: <u> </u>	Picture #: <u> </u>	Location: <u> </u>
	Sample #: <u> </u>	Picture #: <u> </u>	Location: <u> </u>
	Sample #: <u> </u>	Picture #: <u> </u>	Location: <u> </u>

(Also, please see the sketch of sampling locations.)

1.2 Breathing Zone Air Sampling

Sample #: A1 Employee Sampled
Sample #: --- Employee Sampled

Non-Responsive

2.0 Physical Condition of Facility

2.1 Peeling Paint - Lead

Peeling paint observed (Yes or No): Yes

If peeling paint observed, samples were taken as follows:

Sample #: B1 Picture #: Location: Co C Supply Area
 Condition (Good, Average, Poor): Poor Quantity: 51 ft²
 Sample #: Picture #: Location:
 Condition (Good, Average, Poor): Quantity: ft²
 Sample #: Picture #: Location:
 Condition (Good, Average, Poor): Quantity: ft²
 Sample #: Picture #: Location:
 Condition (Good, Average, Poor): Quantity: ft²
 Sample #: Picture #: Location:
 Condition (Good, Average, Poor): Quantity: ft²

2.2 Visual Inspection - Asbestos

Suspected asbestos-containing material observed (Yes or No): Yes Possible

If suspected asbestos-containing material observed, samples were taken as follows:

Location 1: Room #8 (Co B BUO OFF) Porch Picture #:
 Condition: good/average Approximate (Square or Linear Feet): 19.5 x 10 = 195 ft²
 Location 2: Room #9 (Co B ADMIN OFF) Porch Picture #:
 Condition: good/average Approximate (Square or Linear Feet): 19.5 x 20.5 = 400 ft²
 Location 3: Room #2 (Co C ADMIN OFF) Porch Picture #:
 Condition: good/average Approximate (Square or Linear Feet): 15 x 20 = 300 ft²
 Location 4: Boiler room pipes and joints Picture #:
 Condition: Approximate (Square or Linear Feet): 15-16 linear feet
 Location 5: Picture #:
 Condition: Approximate (Square or Linear Feet): and 14-16 joints/elbows

2.3 Visual Inspection – Water Damage and Mold

Water damage observed (Yes or No): Yes - as per John MacFarland
No new damage, roof membrane replaced within 1 1/2 years, evidence of water damage repaired

If yes, water damage was observed at the following locations:

- Location 1: _____ Picture #: _____
- Location 2: _____ Picture #: _____
- Location 3: _____ Picture #: _____
- Location 4: _____ Picture #: _____
- Location 5: _____ Picture #: _____

Mold observed (Yes or No): NO - bathroom (base) from toilet will
moldy; backs of frequently

If yes, mold was observed at the following locations:

- Location 1: _____ Picture #: _____
- Location 2: _____ Picture #: _____
- Location 3: _____ Picture #: _____
- Location 4: _____ Picture #: _____
- Location 5: _____ Picture #: _____

2.4 Visual Inspection - Housekeeping

Housekeeping (good, average, poor): good

Comments (such as no dirt or trash was visible on the floors or the housekeeping was poor in that there was trash and debris on the floors that could lead to a tripping hazard, or there was dust in the vents.):

no trash, dirt etc.

3.0 Building Concerns

3.1 Ergonomic Concerns

Ergonomic concerns (Yes or No): NO

If there are ergonomic concerns at the armory, describe the extent of the problem, such as three employees stated that they perform repetitive motion at the XYZ machine for 6 hours per day, and they stated that they are suffering from symptoms of musculoskeletal disorders (MSDs).

N/A

3.2 Indoor Air Quality

IAQ concerns (based on employee interviews)(Yes or No): NO

If yes, what were concerns:
N/A

Measurements for carbon dioxide, humidity, and temperature:

Location	CO ₂ (ppm)	Humidity (%)	Temperature (°F)	Occupancy (People in Room)
Outdoors - <u>outside garage door</u>	<u>379</u>	<u>68.6</u>	<u>74.3</u>	<u>—</u>
1 st Floor - <u>classroom</u>	<u>403</u>	<u>61.9</u>	<u>78.4</u>	<u>1</u>
2 nd Floor - <u>—</u>				
3 rd Floor - <u>—</u>				
Basement - <u>—</u>				

4.0 Safety and Industrial Hygiene Programs

4.1 Confined Spaces

Are confined spaces applicable (Yes or No): NO

If yes, does the program meet minimum standards (Yes or No): N/A

If no, explain the deficiencies:
N/A

4.2 Hearing Conservation

Is hearing conservation applicable (Yes or No): NO - vehicle operation requires hearing protection for selected vehicles during drill weekends

If yes, does the program meet minimum standards (Yes or No): NSA

If no, explain the deficiencies:

NSA

4.3 Respiratory Protection

Is respiratory protection applicable (Yes or No): NSD

If yes, does the program meet minimum standards (Yes or No): NSA

If no, explain the deficiencies:

NSA

4.4 Hazard Communication

Is hazard communication applicable (Yes or No): Yes

If yes, does the program meet minimum standards (Yes or No): Yes - flammable cabinet on premise w/ MSDS

If no, explain the deficiencies:

NSA

4.5 Personal Protective Equipment

Is personal protective equipment applicable (Yes or No): ISA ^{Yes - supply not required}
^{to wire, steel}
^{tools, etc.}

If yes, does the program meet minimum standards (Yes or No): ~~ISA~~ Yes

If no, explain the deficiencies:

ISA

5.0 Ventilation

5.1 Ventilation System Evaluation

Local exhaust ventilation systems at this armory (Yes or No): ISA

If yes, results of airflow patterns:

Location 1: _____

Airflow Pattern (acceptable or unacceptable, with reason):

Location 2: _____

Airflow Pattern (acceptable or unacceptable, with reason):

Location 3: _____

Airflow Pattern (acceptable or unacceptable, with reason):

5.2 Contamination of Clean Air Sources

Clean air sources contaminated by contaminated exhaust air (Yes or No): ISA

If yes, describe:

ISA

6.0 Noise Dosimetry

Potential hazardous noise areas (Yes or No): ND

If yes, results of noise dosimetry sampling:

Employee sampled: _____
 Results: _____ % Actual _____ % Projected 8-hour TWA _____ Equivalent dBA
 Activity: _____
 Employee sampled: _____
 Results: _____ % Actual _____ % Projected 8-hour TWA _____ Equivalent dBA
 Activity: _____
 Employee sampled: _____
 Results: _____ % Actual _____ % Projected 8-hour TWA _____ Equivalent dBA
 Activity: _____

7.0 Lighting Evaluation

Location	Luminance Range (fc)
CoC Admin office	58.3-19.3
CoC CDR/ISG office	79.3-40.1
Kitchen (light out)	65.5-29.1
CoB Admin office	58.3-23.5
CoB RUCC office	59.1-20.1
Classroom	96.5-39.1

8.0 Converted Indoor Firing Ranges

Converted indoor firing range (Yes or No): Yes - CoC Supply Area (caged)
+ part of room
lockers divide room

If yes, locations sampled:

- Sample #: — Picture #: — Location: Inside any remaining ventilation ductwork * youth group storage in this section NOT APP
- Sample #: — Picture #: — Location: Exhaust ventilation system NOT APP
- Sample #: — Picture #: — Location: Bullet trap NOT APP (CAGED AREA ONLY)
- Sample #: 7 Picture #: — Location: Light fixtures
- Sample #: — Picture #: — Location: Overhead heaters NOT APPLICABLE
- Sample #: 8/10 Picture #: — Location: Stored items 5 - CoC Supply Area
- Sample #: 9 Picture #: — Location: Floor 10 - CoB Supply Area - chicken's youth center area (storage)
- Sample #: — Picture #: — Location: Outside the range - drill hall floor

9.0 HVAC System

Does the HVAC system have maintenance performed on a regular basis (Yes or No):
NO

In yes, is the maintenance effective (Yes or No): N/A

If no, describe:

N/A

10.0 IHIM

Complete IHIM form for facility (Initial as completed): _____

Reproduction Room IHIM Necessary (Yes or No) (Initial if Yes): _____

Film Developing Room IHIM Necessary (Yes or No) (Initial if Yes): _____

Maintenance Area IHIM Necessary (Yes or No) (Initial if Yes): _____

11.0 Additional Items

- Table 1 (wipe sampling) completed (initial when completed): U.S.
- Table 2 (air sampling) completed (initial when completed): U.S.
- Table 3 (peeling paint), if necessary, completed (initial when completed): U.S.
- Table 3 or 4 (IAQ) completed (initial when completed): U.S.
- Table 4 or 5 (noise), if necessary, completed (initial when completed): N/A
- Table 5 or 6 (firing ranges), if necessary, completed (initial when completed): U.S.
- Airflow pattern diagram(s) completed (initial when completed): N/A
- Building layout included (initial when completed): U.S.
- Photographs (initial when completed): U.S.
- Sampling Sheets and Laboratory Analyses (initial when completed): U.S.
- Sampling tracking form completed and faxed to NGB ARNG Region North III office
within 5 days of date of this survey (initial when completed): U.S.
(Fax to Ken Forsythe at 410-942-0254)
- State Lead Wipes Spreadsheet completed (initial when completed): _____
- Three copies of noise exposure notification letter, if necessary (initial when
completed): N/A
- Three copies of contaminant exposure forms for each employee that participated in air
sampling (initial when completed): U.S.

N/A = not applicable.

Field Notes and Checklist

State: Vermont Location: Wincooki Date: 8/1/03
Contact: Non-Responsive

1.0 Sampling for Lead

1.1 Wipe Sampling

VTWIN283

- Sample #: 1 Picture #: Location: Assembly Room - heat exchanger surface
- Sample #: 2 Picture #: Location: below (AYDIN/AYW) adj to c. fr
- Sample #: 3 Picture #: Location: locker (Boyle)
- Sample #: 4 Picture #: Location: soda machine top
- Sample #: 5 Picture #: Location: fire alarm control box stop
- Sample #: 6 Picture #: Location: bank
- Sample #: Picture #: Location:

Industrial Hygiene Survey

Vermont Army National Guard (VT ARNG)

Prepared For: NGB ARNG– Region North IH Office

Survey Location:

Winooski Readiness Center
255 LaFountain Street
Winooski, VT 05404

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 28, 2011

AEI Project #: J11-601 4L VT Winooski RC

Non-Responsive, CIH, CSP
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Winooski Readiness Center**

Table of Contents

Executive Summary ii

1 Introduction 1

2 Evaluation Methods 1

3 Operations 1

4 Noise Hazards 1

5 Hazard Controls 1

Ventilation Systems 1

6 Physical Condition of the Facility and Personnel Concerns 2

Paint Chip and Dust Wipe Samples for Lead Contamination 2

Visual Inspection for Damaged Asbestos-Containing Materials 3

Visual Inspection for Water Damage and Mold Growth 3

Visual Inspection for Housekeeping Concerns 3

Lighting 3

Indoor Air Quality (IAQ) 3

Temperature and Relative Humidity 4

Carbon Dioxide (CO₂) and Carbon Monoxide (CO) 4

7 Conclusions 4

8 Limitations 5

List of Tables and Appendices

Table 1 - Results of Dust Wipe Sampling for the VT ARNG Winooski Readiness Center on October 28, 2011.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

Appendix A – Building Layout

Appendix B – Certificates of Analysis for Air, Dust Wipe and Bulk Samples

Appendix C – Photo Documentation

Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Winooski Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Winooski Readiness Center located at 255 LaFountain Street, Winooski, VT 05404. ~~Non-Responsive~~, CIH, CSP performed the evaluation on October 28, 2011. The point of contact for the facility was SSG ~~Non-Responsive~~. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Paint Chip and Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed on the kitchen ceiling and on in the boiler room ceiling. Bulk paint chip samples were analyzed and found to contain 0.035% lead by weight in the kitchen and <0.0079% lead by weight in the boiler room. These concentrations of lead would not be considered lead-based paint by the Environmental Protection Agency (EPA) and the State of Vermont definitions. Results of dust wipe samples taken throughout the facility were below the recommended maximum criterion for surface contamination of lead (200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$)) in all areas sampled except for samples collected from a metal cabinet and a vent in the Drill Hall (260 and 470 $\mu\text{g}/\text{ft}^2$) and for samples collected in the former firing range (530 – 24,000 $\mu\text{g}/\text{ft}^2$).

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there were any suspect asbestos-containing material and its condition. Damaged plaster and joint compound were observed in the boiler room. No asbestos was detected in either sample sent for analysis.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or evidence of mold growth was observed on the day of the survey.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping needs some improvement to reduce accumulated dust.

Lighting: A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in the janitor's closet only. The illumination measurements indoors ranged from 20 foot candles (fc) to 1,000 fc.

Indoor Air Quality: Temperature and relative humidity measurements were mostly within the comfort ranges for the winter season on the day of the survey. The outdoor temperature and relative humidity were 50.3° F and 22.6% on the day of monitoring. Indoor concentrations of carbon dioxide (CO_2) and carbon monoxide (CO) were below the guidelines in all areas.

Emergency Eyewash and Shower Maintenance: Personal eyewash saline bottles were installed in the drill hall. There did not appear to be a reason such as risk of corrosive splashing for the saline bottles except for general first aid purposes. According to the latest guidance, ANSI Z358.1-2009,

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Winooski Readiness Center**

eyewash saline will not provide enough fluid to meet flushing requirements of 15 minutes at 0.4 gallons per minute. The saline bottles have expiration dates that were not visible because the bottles were taped in place. The bottles should be readily accessible and the expiration dates should be clearly visible.

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was readily available, and the MSDSs were up to date as required by OSHA 29 CFR 1910.1200. Flammable storage cabinets were well organized.

Overall, the Winooski Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Winooski Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VT ARNG) Winooski Readiness Center located at 255 LaFountain Street, Winooski, VT 05404. **Non-Responsive**, CIH, CSP performed the evaluation on October 28, 2011. The point of contact for the facility was **Non-Responsive** | SSG **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

The Winooski Readiness Center was built in the 1950s. The readiness center is staffed by 7 administrative personnel. The operations conducted at the facility include supply and administrative duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the Winooski Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) evaluations of operations including operation description, sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the Winooski facility consist exclusively of supply and administrative duties. No maintenance of vehicles or other physical tasks are performed at the facility.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Winooski Readiness Center**

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; potential ergonomic problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were collected in select areas.

Paint Chip and Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed on the ceilings of the kitchen and boiler room. Bulk paint chip samples were submitted to AMA Analytical Services, Inc. of Lanham, MD for lead analysis. The samples contained 0.035% lead by weight in the kitchen and <0.0079% lead by weight in the boiler room. These concentrations of lead would not be considered lead-based paint by the Environmental Protection Agency (EPA) and State of Vermont definitions (>0.5%). To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected using ghost wipes and 10 centimeter (cm) x 10cm templets. The Environmental Protection Agency (EPA) and the Commonwealth of Pennsylvania limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. All wipe samples collected from the facility were below the recommended maximum except for samples collected from a metal cabinet and a vent in the Drill Hall (260 and 470 $\mu\text{g}/\text{ft}^2$) and for samples collected in the former firing range (530 – 24,000 $\mu\text{g}/\text{ft}^2$). Results are given in Table 1 and certificates of analysis are included in Appendix B.

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
Winooski Readiness Center on October 28, 2011.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
WIN-01	Drill Hall – vending machine	<110
WIN-02	Drill Hall – dusty metal cabinet	260
WIN-03	Drill Hall – dusty wall vent	470
WIN-04	Drill Hall – floor near bay door	<110
WIN-05	Drill Hall – floor near former firing range	130
WIN-06	Former Firing Range – floor near door	<110
WIN-07	Former Firing Range – floor in bullet trap	560
WIN-08	Former Firing Range – painted baseboard heater	24,000
WIN-09	Former Firing Range – dusty metal cabinet	530

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Winooski Readiness Center**

**Table 1 – Results of Dust Wipe Sampling for VT ARNG
Winooski Readiness Center on October 28, 2011.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
WIN-10	Kitchen – counter near microwave	<110
WIN-11	Exercise Equipment Room – weight bench	<110
WIN-12	Classroom – floor	<110
WIN-13	Classroom - desktop	<110

*The recommended maximum level for adult exposures is 200 $\mu\text{g}/\text{ft}^2$ lead on surfaces.

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). Damaged plaster and joint compound was observed in the boiler room. Samples of each damaged material were submitted to AMA Analytical Services, Inc. of Lanham, MD 20706 (NIST-NVLAP Accreditation No. 101143-0) for analysis by Polarized Light Microscopy (PLM). No asbestos was detected in either sample.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or evidence of mold growth was observed on the day of the inspection.

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping needed some improvement to reduce accumulated dust on surfaces.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on March 9, 2011, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in the janitor's closet only. The illumination measurements indoors ranged from 20 foot candles (fc) to 100 fc. The complete results of the evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Plus Model 8554, factory calibrated in February, 2011. Temperature, relative humidity and carbon dioxide (CO_2) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Winooski Readiness Center**

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 2. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30 and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 65.2 to 69.6° F and 31.9 to 44.8% Rh. Temperatures and relative humidity were mostly within the winter comfort ranges in the areas monitored. The outdoor temperature and relative humidity was 50.3° F and 22.6% on the day of monitoring.

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1–2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 498 to 852 parts per million (ppm). CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange.

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 0.0 to 0.2 ppm; therefore, concentrations are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

Additional Information

Emergency Eyewash and Shower Maintenance: Personal eyewash saline bottles were installed in the drill hall. There did not appear to be a reason such as risk of corrosive splashing for the saline bottles except for general first aid purposes. According to the latest guidance, ANSI Z358.1-2009, eyewash saline will not provide enough fluid to meet flushing requirements of 15 minutes at 0.4 gallons per minute. The saline bottles have expiration dates that were not visible because the bottles were taped in place. The bottles should be readily accessible and the expiration dates should be clearly visible.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Winooski Readiness Center**

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was readily available, and the MSDSs were up to date as required by OSHA 29 CFR 1910.1200. Flammable storage cabinets were well organized.

7 Conclusions

The results of the evaluation indicated no concerns with the following at the facility: contamination of clean air sources, water intrusion, peeling potentially lead-based paints, noise hazards, visible mold and the presence of damaged asbestos-containing materials. The results of the evaluation indicated industrial hygiene concerns in the following areas: accumulated lead-containing dust in one area, lighting, and housekeeping. Overall, the Winooski Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.


9 References

1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.
3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.
4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.
5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2011.
6. Army Regulation (AR) 420-70 Buildings and Structures, 10 October 1997.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VT ARNG)
Winooski Readiness Center**

7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 28 March 2009.
8. Army Regulation (AR) 420-1 Army Facilities Management, 28 March 2009.
9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.
10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.
12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.
13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".
15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.

Appendix A Building Layout



50B25 Winooski Armory Floor Plan

First Floor

Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples

AMA Analytical Services, Inc.



A Specialized Environmental Laboratory

CERTIFICATE OF ANALYSIS



Client: National Guard Bureau	Job Name: Winooski RC	Chain Of Custody: 511728
Address: 301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location: Winooski, VT	Date Submitted: 11/1/2011
Attention: Non-Responsive	Job Number: J11-601	Person Submitting: Non-Responsive
	P.O. Number: W912K6-09-A-0003	Date Analyzed: 11/7/2011 Report Date: 11/8/2011

Summary of Atomic Absorption Analysis for Lead

Page 1 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
12010526	Win-Blk-01	Flame	Paint Chip	****	N/A	0.0093 %Pb		0.035 %Pb	
12010527	Win-Blk-02	Flame	Paint Chip	****	N/A	0.0079 %Pb		<0.0079 %Pb	
12010530	Win-01	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010531	Win-02	Flame	Wipe	****	0.108	110 ug/ft ²	28	260 ug/ft ²	
12010532	Win-03	Flame	Wipe	****	0.056	220 ug/ft ²	26	470 ug/ft ²	
12010533	Win-04	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010534	Win-05	Flame	Wipe	****	0.108	110 ug/ft ²	14	130 ug/ft ²	
12010535	Win-06	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010536	Win-07	Flame	Wipe	****	0.108	110 ug/ft ²	60	560 ug/ft ²	
12010537	Win-08	Flame	Wipe	****	0.104	120 ug/ft ²	2500	24000 ug/ft ²	
12010538	Win-09	Flame	Wipe	****	0.108	110 ug/ft ²	57	530 ug/ft ²	
12010539	Win-10	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010540	Win-11	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010541	Win-12	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
12010542	Win-13	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.

AMA Analytical Services, Inc.



A Specialized Environmental Laboratory

CERTIFICATE OF ANALYSIS



Client: National Guard Bureau **Job Name:** Winooski RC **Chain Of Custody:** 511728
Address: 301-JH Old Bay Lane, Attn: ARNG-CJG-P, **Job Location:** Winooski, VT **Date Submitted:** 11/1/2011
 State Military Reservation
 Havre de Grace, Maryland 21078 **Job Number:** J11-601 **Person Submitting:** Non-Responsive
Attention: Non-Responsive **P.O. Number:** W912K6-09-A-0003 **Date Analyzed:** 11/7/2011 **Report Date:** 11/8/2011

Summary of Atomic Absorption Analysis for Lead

Page 2 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	----------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm)
 %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb)
 Note: All samples were received in good condition unless otherwise noted.
 Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

See QC Summary for analytical results of quality control samples associated with these samples.

Air and Wipe results are not corrected for any blank results
 Final results for air and wipe samples are based on client supplied information nor verified by this laboratory.
 All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Analyst: Non-Responsive

Technical Manager: Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS

Client:	National Guard Bureau	Job Name:	Winooski RC	Chain Of Custody:	511728
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Winooski, VT	Date Analyzed:	11/8/2011
		Job Number:	J11-601	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003		

Attention: **Non-Responsive**

Page 1 of 1

Summary of Polarized Light Microscopy

AMA Sample Number	Client Sample #	Total Asbestos	Chrysotile Percent	Amosite Percent	Crocidolite Percent	Other Asbestos Percent	Mineral Wool Percent	Fiberglass Percent	Organic Percent	Synthetic Percent	Other Percent	Particulate Percent	Sample Type	Sample Color	Homogeneity	Analyst ID	Comments
12010528	Win-Blk-03	NAD	--	--	--	--	--	--	TR	--	--	100	PL	Brown	Homogeneous	PC	
12010529	Win-Blk-04	NAD	--	--	--	--	--	--	--	--	--	100	JC	White	Homogeneous	PC	

The following footnotes only apply to those samples which the total asbestos result is flagged with a note number.

- TEM RECOMMENDATION** - Please note, due to resolution limitations with optical microscopy and/or interference from matrix components of this sample, results which are reported via PLM as negative or trace (<1%) for asbestos may contain a significant quantity of asbestos. It is recommended that the additional analytical technique of TEM be used to check for asbestos fibers below the resolution limits of optical microscopy.
- MATRIX REDUCTION RECOMMENDATION** - Please note, due to interference from the matrix components of this sample, results which are reported via PLM as negative or trace (<1%) for asbestos may contain a significant quantity of asbestos which is obscured from view. It is recommended that the additional preparation technique of gravimetric reduction be performed on this sample to minimize the obscuring effects of matrix components, followed by reanalysis by PLM and/or TEM.

Analysis Method - EPA/600/R-93/116 dated July 1993

NAD = "No Asbestos Detected" TR = "Trace equals less than 1% of this component"

Uncertainty: For samples containing asbestos in range of 1-10% the CV is 0.43, 11-35% CV=0.55, >35 CV=0.23

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Technical Director

Non-Responsive

Analyst(s)

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, NVLAP, NIST, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



AMA Analytical Services, Inc.

Focused on Results www.amalab.com
AIHA (#100470) NVLAP (#101143-0) NY ELAP (10920)
4475 Forbes Blvd. • Lanham, MD 20706
(301) 459-2640 • (800) 346-0961 • Fax (301) 459-2643

CHAIN OF CUSTODY

(Please Refer To This Number For Inquiries)

511728

page 1/2

Mailing/Billing Information:

- 1. Client Name: National Guard Bureau
2. Address 1: 301-JH Old Bay Lane
3. Address 2: Attn: NGB-AVNL-SI, State Military Reservation
4. Address 3: Havre de Grace, Maryland 21078
5. Phone #: (410) 942-0273 Fax #: (410) 942-0254

Submission Information:

- 1. Job Name: Winowski, RC
2. Job Location: Winowski, VT
3. Job #: J11-1001
4. Contact Person: [Redacted]
5. Submitted: [Redacted]

Reporting Information (Results will be provided)

Form with sections: AFTER HOURS (must be pre-scheduled), NORMAL BUSINESS HOURS, Results Required By Noon, and Report To: aria@enviro.com

Asbestos Analysis

- PCM Air - Please Indicate Filter Type:
- NIOSH 7400 (QTY)
- Fiberglass (QTY)
TEM Air - Please Indicate Filter Type:
- AHRA (QTY)
- NIOSH 7402 (QTY)
- Other (specify) (QTY)
PLM Bulk
- EPA 600 - Visual Estimate (QTY)
- EPA Point Count (QTY)
- NY State Friable 198.1 (QTY)
- Grav. Reduction ELAP 198.6 (QTY)
- Other (specify) (QTY)
MISC
- Vermiculite
- Asbestos Soil PLM (Qual) PLM (Quan) PLM/TEM (Qual) PLM/TEM (Quan)

TEM Bulk

- ELAP 198.4/Chatfield (QTY)
NY State PLM/TEM (QTY)
Residual Ash (QTY)

TEM Dust

- Qual. (pres/abs) Vacuum/Dust (QTY)
Quan. (S/area) Vacuum D5755-95 (QTY)
Quan. (S/area) Dust D6480-99 (QTY)

TEM Water

- Qual. (pres/abs) (QTY)
ELAP 198.2/EPA 100.2 (QTY)
EPA 100.1 (QTY)

All samples received in good condition unless otherwise noted. (TEM Water samples °C)

- Paint Chip (2)
Dust Wipe (wipe type 10x10) (8) (13 total)
Pb Air (QTY)
Pb Soil/Solid (QTY)
Pb TCLP (QTY)
Drinking Water Pb (QTY) Cd (QTY) As (QTY)
Waste Water Pb (QTY) Cu (QTY) As (QTY)
Pb Furnace (Media) (QTY)

- Collection Apparatus for Spore Traps/Air Samples:
Collection Media
Spore Trap (QTY) Surface Vacuum Dust (QTY)
Surface Swab (QTY) Calibrated ID Gens (Media) (QTY)
Surface Tape (QTY) Calibrated ID Spores (Media) (QTY)
Other (Specify) (QTY)

SAMPLE INFORMATION

Table with columns: CLIENT ID NUMBER, SAMPLE LOCATION IDENTIFICATION, DATE, VOLUME (LITERS), WIPE AREA, TEM, PCM, PLM, LEAD, MOLD, AIR, BULK, DUST, PAINT AND SURF, SPW, TAPE, SWAB. Rows include Win-bk-01 to Win-bk-08 and Win-01 to Win-08.

CLIENT CONTACT

Form for CLIENT CONTACT (LABORATORY STAFF ONLY) with fields for Date/Time, Contact, and By.

LABORATORY STAFF ONLY: (CUSTODY)

- 1. Date/Time RCVD: 11/11/15 @ 015 Via: Fedex By (Print):
2. Date/Time Analyzed: 1/1/16 @ By (Print):
3. Results Reported To:
4. Comments: 1952 87173 2377

Non-Responsive



AMA Analytical Services, Inc.
Focused on Results www.amalab.com
AIHA (#100470) NVLAP (#101143-0) NY ELAP (10920)
4475 Forbes Blvd. • Lanham, MD 20706
(301) 459-2640 • (800) 346-0961 • Fax (301) 459-2643

CHAIN OF CUSTODY

(Please Refer To This Number For Inquiries)

Handwritten notes: 51728, page 2/2, page 2/2

Mailing/Billing Information:

- 1. Client Name: National Guard Bureau
2. Address 1: 301-JH Old Bay Lane
3. Address 2: Attn: NGB-AVN-SI, State Military Reservation
4. Address 3: Havre de Grace, Maryland 21078
5. Phone #: (410) 942-0273 Fax #: (410) 942-0254

Submittal Information:

- 1. Job Name: Winouski RC
2. Job Location: Winouski, VT
3. Job #: J11-60
4. Contact Person: [Redacted]
5. Submitted: [Redacted]

Non-Responsive (Redacted)

Reporting Information (Results will be provided by...)

Reporting Information form with sections for AFTER HOURS, NORMAL BUSINESS HOURS, and REPORT TO: (includes checkboxes for immediate, 24 hours, 3 day, etc.)

Asbestos Analysis

- PCM Air - Please Indicate Filter Type:
- NIOSH 7400 (QTY)
- Fiberglass (QTY)
TEM Air - Please Indicate Filter Type:
- AHERA (QTY)
- NIOSH 7402 (QTY)
- Other (specify) (QTY)

ELM Bulk

- EPA 600 - Visual Estimate (QTY)
EPA Point Count (QTY)
NY State Friable 198.1 (QTY)
Grav. Reduction ELAP 198.6 (QTY)
Other (specify) (QTY)

MISC

- Vermiculite
Asbestos Soil: PLM (Qual) PLM (Quan) PLM/TEM (Qual) PLM/TEM (Quan)

TEM Bulk

- ELAP 198.4/Chatfield (QTY)
NY State PLM/TEM (QTY)
Residual Ash (QTY)

TEM Dust

- Qual. (pres/abs) Vacuum/Dust (QTY)
Quan. (%area) Vacuum D5755-95 (QTY)
Quan. (%area) Dust D6480-99 (QTY)

TEM Water

- Qual. (pres/abs) (QTY)
ELAP 198.2/EPA 100.2 (QTY)
EPA 100.1 (QTY)

All samples received in good condition unless otherwise noted. (TEM Water samples: °C)

- Pb Paint Chip (QTY)
Pb Dust Wipe (wipo type) (QTY)
Pb Air (QTY)
Pb Soil/Solid (QTY)
Pb TCLP (QTY)
Drinking Water (QTY)
Waste Water (QTY)
Pb Pipes (Media) (QTY)

- Collection Apparatus for Spore Traps/Air Samples:
Collection Media:
Spore-Trap (QTY)
Surface Vacuum Dust (QTY)
Surface Swab (QTY)
Culturable ID Gens (Media) (QTY)
Surface Tape (QTY)
Culturable ID Species (Media) (QTY)
Other (specify) (QTY)

Table with columns: CLIENT ID NUMBER, SAMPLE INFORMATION (LOCATION, DATE, VOLUME, WIPE AREA), ANALYSIS (TEM, PCM, PLM, LEAD, MOLD, AIR, SOIL, DUST, etc.), and CLIENT CONTACT (LABORATORY STAFF ONLY).

LABORATORY STAFF ONLY: (CUSTODY)

- 1. Date/Time RCVD: @ Via: By (Print): Sign:
2. Date/Time Analyzed: @ By (Print): Sign:
3. Results Reported To: Via: Date: Sign:
4. Comments:

Non-Responsive (Redacted)

Appendix C Photo Documentation

Winooski, VT Readiness Center



Winooski RC Exterior



Drill Hall



Drill Hall



Classroom

Winooski, VT Readiness Center



Safety Equipment in Drill Hall



Fitness Area



Storage Area – former firing range



Storage Area – former firing range

Winooski, VT Readiness Center



Storage Area – former firing range



Ceiling of former firing range



Flammable storage cabinets



Storage Area

Winooski, VT Readiness Center



This room was locked.



Boiler Room



Boiler Room




Boiler Room


Winooski, VT Readiness Center



Boiler Room



Flammable Storage Cabinets



Peeling Paint on Ceiling in Boiler Room



MSDS Station

Winooski, VT Readiness Center



Office



Kitchen



Peeling Paint in Kitchen



Kitchen

Winooski, VT Readiness Center



Women's Bathroom



Janitor's Closet Storage



MSDs in Janitor's closet



AED and Eyewash Station

Appendix D
IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Winooski	IAQ						Light				
Date	10/28/2011	Inspector	Non-Responsive	Instrument	Q-trak 7565-X						Instrument	Cal-Light 400		
Facility Description	RC			Serial Number	7565X0839020						Serial Number	K070003		
Weather Conditions	Cool, Clear			Last Calibration	Feb-11						Last Calibration	9-Mar-11		
Location/Function		No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
Room 14	Classroom	1	14:54	69.6		32.7		498		0.1		40-1000		30-50
Room 1	Office	1	15:31	68.7		31.9		574		0.2		35-52		30-50
Room 2	Office	1										40-70		30-50
Room 3	Storage	1	15:33	66.6	X	32.1		501		0.1		30-65		30
Drill Hall		1	15:34	65.2	X	32.6		507		0.0		30-1000		30-50
Room 4	Supply Storage	1	15:36									30		30
Room 5	Med Supply Office	2	15:37	69.4		44.8		852		0.1		30-50		30-50
Room 6	Boiler Room	1	15:38									30-70		30
Room 9	Office	2	15:39	69.1		33.5		577		0.0		30-60		30-50
Room 8	Office	1	15:39									30-60		30-50
Kitchen		1	15:40									50-100		50
Women's Bathroom		1	15:42									30-55		5
Janitor's Closet		1										20	X	30
Outside			12:02	50.3		22.6		429		1.2				

Industrial Hygiene Survey

Vermont Army National Guard (VTARNG)

Prepared For: NGB ARNG– Region North IH Office

Survey Location:

Winooski Readiness Center
255 LaFountain Street
Winooski, VT 05404

Prepared By: Aria Environmental, Inc. (AEI)
PO Box 286
Woodbine, MD 21797

Survey Date: October 26, 2012

AEI Project #: J12-685 3m VT Winooski RC

Non-Responsive, CIH, CSP
Industrial Hygienist



**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Winooski Readiness Center**

Table of Contents

Executive Summary ii

1 Introduction 1

2 Evaluation Methods 1

3 Operations 1

4 Noise Hazards 1

5 Hazard Controls 1

Ventilation Systems 1

6 Physical Condition of the Facility and Personnel Concerns 2

Paint Chip and Dust Wipe Samples for Lead Contamination 2

Visual Inspection for Damaged Asbestos-Containing Materials 3

Visual Inspection for Water Damage and Mold Growth 3

Visual Inspection for Housekeeping Concerns 3

Lighting 3

Indoor Air Quality (IAQ) 3

Temperature and Relative Humidity 4

Carbon Dioxide (CO₂) and Carbon Monoxide (CO) 4

7 Conclusions 4

8 Limitations 5

List of Tables and Appendices

Table 1 - Results of Dust Wipe Sampling for the VTARNG Winooski Readiness Center on October 26, 2012.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter

Appendix A – Building Layout

Appendix B – Certificates of Analysis for Air, Dust Wipe and Bulk Samples

Appendix C – Photo Documentation

Appendix D – IAQ and Lighting Survey Log Sheets

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Winooski Readiness Center**

Executive Summary

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VTARNG) Winooski Readiness Center located at 255 LaFountain Street, Winooski, VT 05404. **Non-Responsive**, CIH, CSP performed the evaluation on October 26, 2012. The point of contact for the facility was SSG **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities. The survey included: (1) ventilation system evaluations, noise dosimetry if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) photographs of the exterior and interior of the readiness center. The results of the evaluation indicated the following:

Paint Chip and Wipe Samples for Lead Contamination: A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed on the ceiling of the men's latrine, the wall in the boiler room and the older style window frames in Room 7. The samples contained from <0.006 to 0.27% lead by weight and would not be considered lead-based paint. Results of dust wipe samples taken throughout the facility were below the recommended maximum criterion for surface contamination of lead (200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$)) in all areas sampled except for samples collected from three areas in the former firing range where concentrations approached or exceeded the maximum (190 – 1,200 $\mu\text{g}/\text{ft}^2$) and for one sample collected in the fitness area of the Drill Hall that approached the maximum (190 $\mu\text{g}/\text{ft}^2$).

Visual Inspection for Damaged Asbestos-Containing Materials: A visual inspection was performed to determine if there were any suspect asbestos-containing material and its condition. Damaged window caulk was observed in Room 7. No asbestos was detected in the sample sent for analysis.

Visual Inspection for Water Damage and Mold Growth: A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or evidence of mold growth was observed on the day of the survey. Moisture was observed around the older windows in Rooms 5 and 7.

Visual Inspection for Housekeeping Concerns: A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping needs some improvement to reduce accumulated dust.

Lighting: A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in several areas. The illumination measurements indoors ranged from 5 foot candles (fc) to 80 fc.

Indoor Air Quality: Temperature and relative humidity measurements were all within the comfort ranges for the winter season on the day of the survey. The outdoor temperature and relative humidity were 64.2° F and 62.6% on the day of monitoring. Indoor concentrations of carbon dioxide (CO_2) and carbon monoxide (CO) were below the guidelines in all areas.

Emergency Eyewash and Shower Maintenance: Personal eyewash saline bottles were installed in the drill hall. There did not appear to be a reason such as risk of corrosive splashing for the saline bottles except for general first aid purposes. According to the latest guidance, ANSI Z358.1-2009,

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Winooski Readiness Center**

eyewash saline will not provide enough fluid to meet flushing requirements of 15 minutes at 0.4 gallons per minute. The saline bottles expire in 2013 and should be replaced when they expire.

Personal Protective Equipment (PPE) Storage: The MSDS station on the back wall of the Drill Hall had dust masks available for staff. This station and the dust masks had an accumulation of dust on it. PPE such as dust masks, respirators and gloves should be stored in clean dry places and sealed in plastic bags to prevent contamination from dirt and dust per OSHA 29 CFR 1910.133 and 134.

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was readily available as required by OSHA 29 CFR 1910.1200. MSDSs require updating due to the Bravo Unit moving out.

Overall, the Winooski Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Winooski Readiness Center**

1 Introduction

Aria Environmental, Inc. (AEI) was contracted to perform an industrial hygiene evaluation for the Vermont Army National Guard (VTARNG) Winooski Readiness Center located at 255 LaFountain Street, Winooski, VT 05404. **Non-Responsive**, CIH, CSP performed the evaluation on October 26, 2012. The point of contact for the facility was **Non-Responsive** SSG **Non-Responsive**. The purpose of the evaluation was to identify and measure the existence and extent of potentially hazardous operations or conditions at Army National Guard (ARNG) facilities.

The Winooski Readiness Center was built in the 1950s. The readiness center is staffed by 7 administrative personnel; however, the Bravo Unit was in the process of moving to another location and the staff will be reduced to 4 at that point. The operations conducted at the facility include supply and administrative duties. A diagram of the building layout is provided in Appendix A. All sampling sheets and laboratory certificates of analysis are provided in Appendix B. Selected photographs taken during the evaluation are provided in Appendix C. Indoor air quality and lighting survey measurement log sheets are provided in Appendix D. Lists of all references used during the evaluation are included in the main body of the report.

2 Evaluation Methods

The industrial hygiene survey of the Winooski Readiness Center consisted of visual inspections, interviews with employees, and sampling plan development in order to achieve the following: (1) evaluations of operations including operation description, sampling for lead in air or on surfaces if appropriate, ventilation system evaluations, noise measurements if appropriate, lighting surveys, hazard control evaluations and any additional information pertinent to the operations; (2) an evaluation of the physical condition of the facility and personnel concerns including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; indoor air quality concerns; and housekeeping practices; and (3) a building layout and photographic documentation of the interior of the facility.

The National Guard Bureau (NGB) Region North IH Office provided all industrial hygiene equipment for air sampling (equipment and media), ventilation, lighting, noise and indoor air quality (IAQ) survey instruments and paid for laboratory analytical fees. Laboratories were chosen or approved by the NGB IH office.

3 Operations

Operations conducted at the Winooski facility consist exclusively of supply and administrative duties. No maintenance of vehicles or other physical tasks are performed at the facility.

4 Noise Hazards

No noise-generating activities were taking place on the day of the survey. Due to the nature of the tasks performed onsite, no activities requiring noise monitoring are anticipated to occur at the RC.

5 Hazard Controls

Ventilation Systems

No local exhaust ventilation systems were present in the facility.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Winooski Readiness Center**

6 Physical Condition of the Facility and Personnel Concerns

An evaluation of the physical condition of the facility and personnel concerns was performed including visual inspections for peeling potentially lead-based paint, damaged suspect asbestos-containing materials, water damage or mold problems; and housekeeping practices. Lighting measurements were taken in all areas of the facility, and indoor air quality measurements were collected in select areas.

Paint Chip and Dust Wipe Samples for Lead Contamination

A visual inspection was performed to determine if there were any areas of peeling paint at the facility that could pose a lead exposure hazard. Peeling paint was observed on the ceiling of the men's latrine, the wall in the boiler room and the older style window frames in Room 7. Bulk paint chip samples were submitted to AMA Analytical Services, Inc. of Lanham, MD for lead analysis. The samples contained from <0.006 to 0.27% lead by weight and would not be considered lead-based paint by the Environmental Protection Agency (EPA) and State of Vermont definitions (>0.5%). To determine if any cross contamination of lead from any source into areas of the facility existed, wipe samples were collected using ghost wipes and 10 centimeter (cm) x 10cm templets. The Environmental Protection Agency (EPA) and the State of Vermont limits for lead in dust are 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) on floors, 250 $\mu\text{g}/\text{ft}^2$ on window sills, and 400 $\mu\text{g}/\text{ft}^2$ in window troughs. These limits apply to pre-1978 Army facilities only if children under 6 years of age occupy them for 60 or more hours per year. The NGB Region North Industrial Hygiene Office concurs with the US Army Public Health Command recommended maximum level for adult exposures of 200 $\mu\text{g}/\text{ft}^2$ on floors and frequently contacted surfaces, which is more stringent for window sills than the EPA/State standards. Dust wipe samples were submitted to AMA for atomic absorption spectrophotometry (AAS) following the analytical method ASTM D3335-85A. All wipe samples collected from the facility were below the recommended maximum except for samples collected from three areas in the former firing range where concentrations approached or exceeded the maximum (190 – 1,200 $\mu\text{g}/\text{ft}^2$) and for one sample collected in the fitness area of the Drill Hall that approached the maximum (190 $\mu\text{g}/\text{ft}^2$). Results are given in Table 1 and certificates of analysis are included in Appendix B.

**Table 1 – Results of Dust Wipe Sampling for VTARNG
Winooski Readiness Center on October 26, 2012.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
WNSK-01	Former Firing Range – floor in bullet trap area	190
WNSK-02	Former Firing Range – dusty metal shelf panels on floor	<110
WNSK-03	Former Firing Range – floor at firing end	1,200
WNSK-04	Former Firing Range – center of floor	250
WNSK-05	Drill Hall – floor near former firing range	<110
WNSK-06	Drill Hall – fitness area – floor mat	190
WNSK-07	Drill Hall – fitness area – lifting bench	<110
WNSK-08	Drill Hall – center of floor	<110
WNSK-09	Drill Hall – top of shipping container	<110

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Winooski Readiness Center**

**Table 1 – Results of Dust Wipe Sampling for VTARNG
Winooski Readiness Center on October 26, 2012.**

Wipe Sample #	Sample Location	Result ($\mu\text{g}/\text{ft}^2$)*
WNSK-10	Kitchen – counter near sink	<110

*The recommended maximum level for adult exposures is 200 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) lead on surfaces.

Visual Inspection for Damaged Asbestos-Containing Materials

A visual inspection was performed to determine if there was any damaged suspect asbestos-containing material (ACM). Damaged window caulk was observed on older style windows in Room 7. A sample was submitted to AMA Analytical Services, Inc. of Lanham, MD 20706 (NIST-NVLAP Accreditation No. 101143-0) for analysis by Polarized Light Microscopy (PLM). No asbestos was detected in the sample.

Visual Inspection for Water Damage and Mold Growth

A visual inspection was performed to determine if there was any water damage or visible mold growth at the facility. No water damage or evidence of mold growth was observed on the day of the inspection. Some moisture was observed around older style windows in Rooms 5 and 7.

Visual Inspection for Housekeeping Concerns

A visual inspection was performed to assess the state of housekeeping in the facility. The housekeeping needed some improvement to reduce accumulated dust on surfaces.

Lighting

Illumination levels were measured using a Cal-Light 400L, calibrated on April 16, 2012, and compared to minimum lighting requirements for various facilities and functions based on the following references: American National Standards Institute/Illumination Engineering Society of North America (ANSI/IESNA) Standard RP-1-04 (Office Lighting) and ANSI/IESNA Standard RP-7-01 (Lighting Industrial Facilities).

A lighting survey was performed in all areas within the readiness center. The evaluation indicated illumination deficiencies in the janitor's closet only. The illumination measurements indoors ranged from 5 foot candles (fc) to 80 fc. The complete results of the evaluation are presented in Appendix D, including whether the results met minimum requirements for illumination.

Indoor Air Quality (IAQ)

Indoor air quality measurements (i.e., temperature, relative humidity, carbon dioxide and carbon monoxide) were taken using a TSI Q-Trak Model 7656X, factory calibrated in March, 2012. Temperature, relative humidity and carbon dioxide (CO_2) measurements were compared to the recommended levels established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE). Carbon monoxide (CO) concentrations were compared to the ACGIH Threshold Limit Value (TLV) for CO and the Environmental Protection Agency's (EPA's) National Ambient Air Quality Standard (NAAQS) for CO.

Industry guidelines or standards for seasonal temperature and humidity ranges for thermal comfort are established by ASHRAE standard 55-2010. These ranges are presented in Table 2. The U.S. EPA also recommends maintaining relative humidity below 60% and ideally between 30

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Winooski Readiness Center**

and 50% to prevent mold growth. Complete results are provided in Appendix D with the lighting survey measurements.

Table 2 - Acceptable Ranges of Temperature and Relative Humidity in Summer and Winter^a

Relative Humidity	Winter Temperature	Summer Temperature
30%	68.5°F – 76.0°F	74.0°F – 80°F
40%	68.5°F – 75.5°F	73.5°F – 79.5°F
50%	68.5°F – 74.5°F	73.0°F – 79.0°F
60%	68.0°F – 74.0°F	72.5°F – 78.0°F

^aadapted from ASHRAE Standard 55-2010

Temperature and Relative Humidity

Indoor temperature and relative humidity (Rh) measurements in the facility ranged from 68.3 to 72.0° F and 49.8 to 58.8% Rh. Temperatures and relative humidity were all within the winter comfort ranges in the areas monitored. The outdoor temperature and relative humidity was 64.2° F and 62.6% on the day of monitoring.

Carbon Dioxide (CO₂) and Carbon Monoxide (CO)

Carbon dioxide and carbon monoxide measurements are used to assess ventilation system performance. The exhaled breath of building occupants is the main indoor source of carbon dioxide; therefore, the build up of CO₂ indicates inadequate ventilation. The concentration of concern for carbon dioxide is set by ASHRAE standard 62.1–2010 as 700 ppm above outdoor concentrations. Indoor levels of CO₂ ranged from 402 to 565 parts per million (ppm), and the outdoor measurement was 385 ppm. CO₂ measurements were below the guideline in all areas monitored, indicating adequate fresh air exchange.

Carbon monoxide is a byproduct of incomplete combustion. Indoor concentrations indicate contamination caused by improperly vented or malfunctioning boilers, furnaces or stoves or from vehicle exhaust entering the building from garages, loading docks, nearby roads or parking lots. The concentration of interest set by ASHRAE standard 62.1-2010 and the National Ambient Air Quality Standards (NAAQS) for carbon monoxide is an 8 hour average of 9 ppm. The ACGIH TLV for CO is 25 ppm. Indoor levels of CO ranged from 0.1 to 0.6 ppm; therefore, concentrations are below occupational exposure limits, ASHRAE and the NAAQS-recommended CO concentrations.

Additional Information

Emergency Eyewash and Shower Maintenance: Personal eyewash saline bottles were installed in the drill hall. There did not appear to be a reason such as risk of corrosive splashing for the saline bottles except for general first aid purposes. According to the latest guidance, ANSI Z358.1-2009, eyewash saline will not provide enough fluid to meet flushing requirements of 15 minutes at 0.4 gallons per minute. The saline bottles expire in 2013 and should be replaced when they expire.

Hazard Communication Program and Material Safety Data Sheets (MSDSs): A written hazard communication program was readily available as required by OSHA 29 CFR 1910.1200; however, MSDSs need updating due to the Bravo Unit moving out.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Winooski Readiness Center**

Personal Protective Equipment (PPE) Storage

The MSDS station on the back wall of the Drill Hall had dust masks available for staff. This station and the dust masks had an accumulation of dust on it. PPE such as dust masks, respirators and gloves should be stored in clean dry places and sealed in plastic bags to prevent contamination from dirt and dust per OSHA 29 CFR 1910.133 and 134.

7 Conclusions

The results of the evaluation indicated few concerns at the facility. Overall, the Winooski Readiness Center has few industrial hygiene issues, and programs are in place to protect, inform and train employees and maintain the facility.

8 Limitations

This report has been prepared for the exclusive use of the U.S. Army National Guard (USARNG) and/or their agents. This service has been performed in accordance with generally accepted industrial hygiene and environmental practices. No other warranty, expressed or implied, is made. Our conclusions and recommendations are based, in part, upon information provided to us by others and our site observations. We have not verified the completeness or accuracy of the information provided to us by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards.

By virtue of providing the services described in this report, the preparer does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. It is the Client's responsibility to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. Under this scope of services, the preparer assumes no responsibility regarding response actions initiated as a result of these findings. Response actions are the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, and should be performed by appropriately licensed personnel as warranted.


9 References

1. Title 29, Code of Federal Regulations (CFR), Part 1910, Occupational Safety and Health Administration, current edition.
2. Title 24, Code of Federal Regulations (CFR), Part 35, Subpart B, Sections 35.110, Definitions of Lead-Based Paint, Housing and Urban Development, U.S. Department of Housing.
3. Department of Defense Instruction (DODI) 6055.1, Department of Defense Occupational Safety and Health (OSH) Program, August 19, 1998.
4. Army Regulation (AR) 40-5, Medical Service, Preventive Medicine, May 25, 2007.
5. Army Regulation (AR) 385-10, The Army Safety Program, 4 October 2011.
6. Army Regulation (AR) 420-70 Buildings and Structures, 11 November 1997.
7. Army Regulation (AR) 200-1 Environmental Protection and Enhancement, 13 December 2007.

**Industrial Hygiene Survey Report
Vermont Army National Guard (VTARNG)
Winooski Readiness Center**

8. Army Regulation (AR) 420-1 Army Facilities Management, 12 February 2008, RAR 24 August 2012.
9. Department of the Army Pamphlet (DA PAM) 40-501, Medical Service, Hearing Conservation Program, December 10, 1998.
10. Department of the Army Pamphlet (DA PAM) 40-503, Medical Service, Industrial Hygiene Program, October 30, 2000.
11. Technical Manual (TM) 5-810-1, Mechanical Design, Heating, Ventilation, and Air Conditioning, June 1991.
12. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs), American Conference of Governmental Industrial Hygienists (ACGIH), current edition.
13. RP-1-2004 (Office Lighting) and RP-7-2001 (Industrial Lighting), Illuminating Engineering Society of North America (IESNA)/ANSI.
14. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE), Standard 62.1-2010, "Ventilation for Acceptable Indoor Air Quality" and Standard 55-2010, "Thermal Environmental Conditions for Human Occupancy".
15. NIOSH website: <http://www.cdc.gov/niosh/>.
16. OSHA website: <http://www.osha.gov/>.
17. Army Public Health Command website: <http://phc.amedd.army.mil/Pages/default.aspx>.
18. EPA website: <http://www.epa.gov>.
19. ANSI Z358.1 – 2009, Emergency Eyewash and Shower Equipment.

Appendix A Building Layout



50B25 Winooski Armory Floor Plan

First Floor

Appendix B
Certificates of Analysis for Dust Wipe and Bulk Samples



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	Winooski RC	Chain Of Custody:	514384
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Winooski, VT	Date Submitted:	11/2/2012
Attention:	Non-Responsive	Job Number:	J12-685	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/12/2012
				Report Date:	11/12/2012

Summary of Atomic Absorption Analysis for Lead

Page 1 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
13010917	WNSK-W 01	Flame	Wipe	****	0.108	110 ug/ft ²	21	190 ug/ft ²	
13010918	WNSK-W 02	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010919	WNSK-W 03	Flame	Wipe	****	0.108	110 ug/ft ²	130	1200 ug/ft ²	
13010920	WNSK-W 04	Flame	Wipe	****	0.108	110 ug/ft ²	27	250 ug/ft ²	
13010921	WNSK-W 05	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010922	WNSK-W 06	Flame	Wipe	****	0.108	110 ug/ft ²	21	190 ug/ft ²	
13010923	WNSK-W 07	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010924	WNSK-W 08	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010925	WNSK-W 09	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010926	WNSK-W 10	Flame	Wipe	****	0.108	110 ug/ft ²	<12	<110 ug/ft ²	
13010927	WNSK-Bulk 01	Flame	Paint Chip	****	N/A	0.006 %Pb		<0.006 %Pb	
13010928	WNSK-Bulk 02	Flame	Paint Chip	****	N/A	0.0066 %Pb		0.27 %Pb	
13010929	WNSK-Bulk 03	Flame	Paint Chip	****	N/A	0.0072 %Pb		0.18 %Pb	

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS



Client:	National Guard Bureau	Job Name:	Winooski RC	Chain Of Custody:	514384
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Winooski, VT	Date Submitted:	11/2/2012
Attention:	Non-Responsive	Job Number:	J12-685	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003	Date Analyzed:	11/12/2012
				Report Date:	11/12/2012

Summary of Atomic Absorption Analysis for Lead

Page 2 of 2

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Air Volume (L)	Area Wiped (ft ²)	Reporting Limit	Total ug	Final Result	Comments
-------------------	----------------------	---------------	-------------	----------------	-------------------------------	-----------------	----------	--------------	----------

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B
 Analysis Method For Furnace: Air, Wipes, Paints, and Soil/Solids : EPA 600/R-93/200(M)-7010; Water: SM-3113B
 N/A = Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm)
 %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb)

See QC Summary for analytical results of quality control samples associated with these samples.

Note: All samples were received in good condition unless otherwise noted.

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the result.

Air and Wipe results are not corrected for any blank results

Final results for air and wipe samples are based on client supplied information nor verified by this laboratory.

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Non-Responsive

Non-Responsive

Analys

Technical Manager:

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AIHA, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



CERTIFICATE OF ANALYSIS

Client:	National Guard Bureau	Job Name:	Winooski RC	Chain Of Custody:	514384
Address:	301-IH Old Bay Lane, Attn: ARNG-CJG-P, State Military Reservation Havre de Grace, Maryland 21078	Job Location:	Winooski, VT	Date Analyzed:	11/8/2012
		Job Number:	J12-685	Person Submitting:	Non-Responsive
		P.O. Number:	W912K6-09-A-0003		

Attention: **Non-Responsive**

Page 1 of 1

Summary of Polarized Light Microscopy

AMA Sample Number	Client Sample #	Total Asbestos	Chrysotile Percent	Amosite Percent	Crocidolite Percent	Other Asbestos Percent	Mineral Wool Percent	Fiberglass Percent	Organic Percent	Synthetic Percent	Other Percent	Particulate Percent	Sample Type	Sample Color	Homogeneity	Analyst ID	Comments
13010930	WNSK-Bulk 04	NAD	--	--	--	--	--	--	--	--	TR	100	CK	White	Homogeneous	SW	

The following footnotes only apply to those samples which the total asbestos result is flagged with a note number.

- 1 TEM RECOMMENDATION - Please note, due to resolution limitations with optical microscopy and/or interference from matrix components of this sample, results which are reported via PLM as negative or trace (<1%) for asbestos may contain a significant quantity of asbestos. It is recommended that the additional analytical technique of TEM be used to check for asbestos fibers below the resolution limits of optical microscopy.
- 2 MATRIX REDUCTION RECOMMENDATION - Please note, due to interference from the matrix components of this sample, results which are reported via PLM as negative or trace (<1%) for asbestos may contain a significant quantity of asbestos which is obscured from view. It is recommended that the additional preparation technique of gravimetric reduction be performed on this sample to minimize the obscuring effects of matrix components, followed by reanalysis by PLM and/or TEM.

Analysis Method - EPA/600/R-93/116 dated July 1993

NAD = "No Asbestos Detected" TR = "Trace equals less than 1% of this component"

Uncertainty: For samples containing asbestos in range of 1-10% the CV is 0.43, 11-35% CV=0.55, >35 CV=0.23

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Technical Director

Non-Responsive

Analyst(s)

Non-Responsive

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NVLAP or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



AMA Analytical Services, Inc.
 Focused on Results www.amalab.com
 ATHA (#100470) NVLAP (#101143-0) NY ELAP (10920)
 4475 Forbes Blvd. • Lanham, MD 20706
 (301) 459-2640 • (800) 346-0961 • Fax (301) 459-2643

BEST AVAILABLE COPY

CHAIN OF CUSTODY

(Please Refer To This Number For Inquires)

514384

Mailing/Billing Information:

- Client Name: National Guard Bureau
- Address 1: 301-IH Old Bay Lane
- Address 2: Attn: NGB-AVN-SI, State Military Reservation
- Address 3: Havre de Grace, Maryland 21078
- Phone #: (410) 942-0273 Fax #: (410) 942-0254

Submittal Information:

- Job Name: Winooski RC
- Job Location: Winooski, VT
- Job #: 312-685 PO #: W912K6-09-A-0003
- Contact Person: **Non-Responsive**
- Submitted by: **Non-Responsive**

Reporting Info (Results provided as soon as technically feasible). If no TAT/Reporting Info is provided, AMA will assign defaults of 5-Day and email/fax to contacts on file.

AFTER HOURS (must be pre-scheduled)		NORMAL BUSINESS HOURS		REPORT TO:	
<input type="checkbox"/> Immediate	Date Due: _____	<input type="checkbox"/> 3 Day	<input type="checkbox"/> Results Required By Noon	<input checked="" type="checkbox"/> Include _____ with Report	<input checked="" type="checkbox"/> Email Non-Responsive
<input type="checkbox"/> 24 Hours	Time Due: _____	<input type="checkbox"/> Next Day	<input checked="" type="checkbox"/> 5 Day + <u>W/W</u>	<input checked="" type="checkbox"/> Email <u>ariaenviro.com</u>	<input type="checkbox"/> Fax: _____
Comments: _____		<input type="checkbox"/> 2 Day	Date Due: <u>11/2</u>	<input type="checkbox"/> Fax: _____	<input type="checkbox"/> Verbal _____

Asbestos Analysis

- *PCM Air - Please Indicate Filter Type:
- NIOSH 7400 (QTY)
 - Fiberglass (QTY)
- TEM Air* - Please Indicate Filter Type:
- AHERA (QTY)
 - NIOSH 7402 (QTY)
 - Other (specify _____) (QTY)
- PLM Bulk
- EPA 600 - Visual Estimate 1 (QTY)
 - EPA Point Count (QTY)
 - NY State Friable 198.1 (QTY)
 - Grav. Reduction ELAP 198.6 (QTY)
 - Other (specify _____) (QTY)

TEM Bulk

- ELAP 198.4/Chatfield (QTY)
- NY State PLM/TEM (QTY)
- Residual Ash (QTY)

TEM Dust*

- Qual. (pres/abs) Vacuum/Dust (QTY)
- Quan. (s/area) Vacuum D5755-95 (QTY)
- Quan. (s/area) Dust D6480-99 (QTY)

TEM Water

- Qual. (pres/abs) (QTY)
- ELAP 198.2/EPA 100.2 (QTY)
- EPA 100.1 (QTY)

All samples received in good condition unless otherwise noted.
 (TEM Water samples _____ °C)

Metals Analysis

- Pb Paint Chip (QTY)
- Pb Dust Wipe (wipe type 10x10) (QTY) ghost
- Pb Air (QTY)
- Pb Soil/Solid (QTY)
- Pb TCLP (QTY)
- Drinking Water Pb (QTY) Cu (QTY) As (QTY)
- Waste Water Pb (QTY) Cu (QTY) As (QTY)
- Pb Furnace (Media _____) (QTY)

Fungal Analysis

- Collection Apparatus for Spore Traps/Air Samples: _____
- Collection Media _____
- *Spore-Trap (QTY)
 - *Surface Swab (QTY)
 - *Surface Tape (QTY)
 - Other (Specify _____) (QTY)
 - Surface Vacuum Dust (QTY)
 - Culturable ID Genus (Media _____) (QTY)
 - Culturable ID Species (Media _____) (QTY)

MISC:

- Vermiculite
 - Asbestos Soil PLM (Qual) PLM (Quan) PLM/TEM (Qual) PLM/TEM (Quan) If field data sheets are submitted, there is no need to complete bottom section.
- *It is recommended that blank samples be submitted with all air and surface samples

CLIENT ID #	SAMPLE INFORMATION SAMPLE LOCATION/ID	DATE/ TIME	VOL (L)/ Wipe Area	ANALYSIS											CLIENT CONTACT					
				TEM	PCM	PLM	LEAD	MOLD	AIR	BULK	DUST MATRIX	WATER AND OTHER	SPORE TRAP	TAPE	SWAB	(LABORATORY STAFF ONLY)				
	SEE ATTACHED FIELD DATA SHEETS																	Date/Time:	Contact:	By:
																		Date/Time:	Contact:	By:
																		Date/Time:	Contact:	By:

Non-Responsive

LABORATORY STAFF ONLY:
 (CUSTODY)

- Date/Time RCVD: 11/2/12 @ _____ Via: ELAP By (Print): _____
- Date/Time Analyzed: _____ @ _____ By (Print): _____
- Results Reported To: _____ Via: _____ Date: _____ Time: _____ Initials: _____

Posted to NGB FOIA Reading Room
 May, 2018

BEST AVAILABLE COPY

FOIA Requested Record #J 15 0085 (VT)
 Released by National Guard Bureau
 Page 1338 of 1352

Appendix C Photo Documentation

VT Winooski RC



Front exterior



Side exterior



Drill Hall



Drill Hall

VT Winooski RC



Drill Hall



MSDS and PPE Station



Boiler Room



Boiler Room

VT Winooski RC



Same peeling paint and broken plaster as 2011 Survey



New peeling paint



Office

Posted to NGB FOIA Reading Room
May, 2018



Drill Hall view into offices

VT Winooski RC



Kitchen



Same peeling paint as 2011 survey



Women's latrine and shower room



Janitor's closet

VT Winooski RC



Janitor's closet



Janitor's closet



Classroom



Shower

VT Winooski RC



Men's latrine



Peeling paint in men's latrine



Office



Office

VT Winooski RC



Medical practice victims



Storage and former range



Storage and former range



Storage and former range

VT Winooski RC



Storage and former range



Storage and former range



Supply room



Office

VT Winooski RC



Deteriorating glaze and paint on windows



Deteriorating glaze and paint on windows



Office



Office

VT Winooski RC



Only a couple rooms had these older style windows



Personal saline eyewash station

Appendix D
IAQ and Lighting Survey Log Sheets

National Guard Industrial Hygiene Survey For Indoor Air Quality and Light Level

State	Vermont	City	Winooski	IAQ						Light			
Date	10/26/2012	Inspector	Non-Responsive	Instrument	Q-trak 7565-X						Instrument	Cal-Light 400	
Facility Description	Winooski RC			Serial Number	7565X0839019						Serial Number	K070003	
Weather Conditions	Cool and Cloudy			Last Calibration	Mar-12						Last Calibration	16-Apr-12	
Location/Function	No. Occupants	Time	Temp. (°F)	Exceeded	RH (%)	Exceeded	CO ₂ (ppm)	Exceeded	CO (ppm)	Exceeded	Illuminance (fc)	Insufficient	Illuminance Reference (fc)
Drill Hall	1	1108	69.2		52.8		429		0.6		30-40	X	50
Boiler Room 6	1	1110	71.1		51.5		415		0.2		8-33	X	30
Room 8 Offices	1	1114	70.7		51.3		482		0.5		46-70		30-50
Room 9 Offices	4	1116	71.4		50.9		565		0.5		30-80		30-50
Kitchen 10	1	1117	70.9		50.6		457		0.2		50-70		50
Women's Latrine and Shower 11	1	1118	72.0		58.8		440		0.1		20-40		7
Janitor's Closet 12	1	1120									10-15	X	30
Classroom 14	2	1125	70.7		49.8		450		0.2		16-38	X	30-50
Men's Latrine and Shower 13	1	1126	70.4		55.9		438		0.2		18-75		7
Room 1 Offices	2	1132	69.7		51.1		451		0.2		15-45	X	30-50
Room 2 Offices	1	1133	69.9		50.3		446		0.3		20-40	X	30-50
Room 3 Storage	1	1135	68.3		50.6		438		0.2		30-80		30
Room 4 Supply Storage	1	1138	68.6		50.3		402		0.1		5-70	X	30
Room 5 Supply Storage	3	1140	69.3		54.3		474		0.2		16-42	X	30
Room 7 unit Supply Room	2	1144	68.9		52.9		502		0.1		30-40		30
Outside	1	1233	64.2		62.6		385		0.4				