FINAL
Preliminary Assessment Report
Army Aviation Support Facility #2
Salina, Kansas

Perfluorooctane-Sulfonic Acid (PFOS) and Perfluorooctanoic Acid (PFOA) Impacted Sites
ARNG Installations, Nationwide

January 2020

Prepared for:

Army National Guard Headquarters
111 S. George Mason Drive
Arlington, VA 22204

U.S. Army Corps of Engineers, Baltimore District
2 Hopkins Plaza
Baltimore, MD 21201

Prepared by:

AECOM
12420 Milestone Center Drive, Suite 150
Germantown, MD 20876
aecom.com

Contract Number: W912DR-12-D-0014
Delivery Order: W912DR17F0192

Table of Contents

Executive Summary 1
1. Introduction 3
   1.1 Authority and Purpose 3
   1.2 Preliminary Assessment Methods 3
   1.3 Report Organization 4
   1.4 Facility Location and Description 4
   1.5 Facility Environmental Setting 4
      1.5.1 Geology 5
      1.5.2 Hydrogeology 5
      1.5.3 Hydrology 6
      1.5.4 Climate 6
      1.5.5 Current and Future Land Use 6
2. Fire Training Areas 10
3. Non-Fire Training Areas 11
   3.1 AFFF Fire Extinguisher Storage 11
4. Emergency Response Areas 13
5. Adjacent Off-Facility Sources 14
   5.1 Salina Airport Authority Fire Department 14
6. Preliminary Conceptual Site Model 16
7. Conclusions 17
   7.1 Findings 17
   7.2 Uncertainties 17
   7.3 Potential Future Actions 18
8. References 20

Tables

Table 7-1: Uncertainties

Figures

Figure ES-1 Summary of Findings
Figure 1-1 Facility Location
Figure 1-2 Groundwater Features
Figure 1-3 Surface Water Features
Figure 5-1 Adjacent Sources
Figure 7-1 Summary of Findings

Appendices

Appendix A Data Resources
Appendix B Preliminary Assessment Documentation
B.1 Interview Records
B.2 Visual Site Inspection Checklists
B.3 Conceptual Site Model Information
Appendix C Photographic Log

Acronyms and Abbreviations

AASF	Army Aviation Support Facility
AECOM	AECOM Technical Services, Inc.
AFFF	aqueous film forming foam
AOI	Area of Interest
ARNG	Army National Guard
bgs	below ground surface
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act
CSM	conceptual site model
DLA	Defense Logistics Agency
°F	degrees Fahrenheit
FTA	fire training area
KSARNG	Kansas Army National Guard
NOAA	National Oceanic and Atmospheric Administration
PA	Preliminary Assessment
PFAS	per- and poly-fluoroalkyl substances
PFOA	perfluorooctanoic acid
PFOS	perfluorooctanesulfonic acid
QRP	Quality Recycling Program
SI	Site Inspection
US	United States
USACE	United States Army Corps of Engineers
USEPA	United States Environmental Protection Agency
USGS	United States Geological Survey
USP&FO	United States Property and Fiscal Office


Executive Summary

The United States Army Corps of Engineers Baltimore District on behalf of the Army National Guard (ARNG)-Installations & Environment Division, Cleanup Branch contracted AECOM Technical Services, Inc. (AECOM) to perform *Preliminary Assessments (PAs) and Site Inspections (SIs) for Perfluorooctanesulfonic acid (PFOS) and Perfluorooctanoic acid (PFOA) Impacted Sites at ARNG Facilities Nationwide*. The ARNG is assessing potential effects on human health related to processes at facilities that used per- and poly-fluoroalkyl substances (PFAS), primarily in the form of aqueous film forming foam released as part of firefighting activities, although other PFAS sources are possible.

AECOM completed a PA for PFAS at the Salina Army Aviation Support Facility (AASF) #2 in Salina, Kansas to assess potential PFAS release areas and exposure pathways to receptors. The performance of this PA included the following tasks:

- Reviewed data resources to obtain information relevant to suspected PFAS releases
- Conducted a site visit on 28 August 2019
- Interviewed current Kansas ARNG personnel during the site visit as well as environmental managers and operations staff
- Completed visual survey inspections to confirm absence of PFAS-related activities and documented with photographs

No Area(s) of Interest related to potential PFAS use, release, or storage were identified at AASF #2 during the PA; however, one potential PFAS source is located adjacent to the facility. (**Figure ES-1**). Based on facility history and interviews with various personnel, there is no potential for exposure to PFAS contamination in surface soil, subsurface soil, groundwater, surface water, and sediment. The City of Salina is the main source for the water at the facility. Based on the USEPA Unregulated Contaminant Monitoring Rule 3 data, it was indicated that no PFAS were detected in a public water system above the United States Environmental Protection Agency Lifetime Health Advisory level within 20 miles of the facility.



CLIENT	ARNG			
NOTES	Preliminary Assessment for PFAS at Salina AASF 2, KS			
REVISED	11/25/2019	GIS BY	MS	11/25/2019
SCALE	1:9,600	CHK BY	SI	11/25/2019
Base Map: Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS,		PM	RG	11/25/2019

N

Summary of Findings

AECOM
12420 Milestone Center Drive
Germantown, MD 20876

Figure ES-1

Q:\Projects\ENV\GEARS\GEO\ARNG PFAS\900-CAD-GIS\920-GIS or Graphics\MXD\KS\Salina_AASF2_Figures\Fig_ES-1_Salina_AASF2_Summary.mxd

1. Introduction

1.1 Authority and Purpose

The United States (US) Army Corps of Engineers (USACE) Baltimore District on behalf of the Army National Guard (ARNG)-Installations & Environment Division, Cleanup Branch contracted AECOM Technical Services, Inc. (AECOM) to perform *Preliminary Assessments (PAs) and Site Inspections (SIs) for Perfluorooctanesulfonic acid (PFOS) and Perfluorooctanoic acid (PFOA) Impacted Sites at ARNG Facilities Nationwide* under Contract Number W912DR-12-D-0014, Task Order W912DR17F0192, issued 11 August 2017, and Modification 01 issued 30 September 2017. The ARNG is assessing potential effects on human health related to processes at facilities that used per- and poly-fluoroalkyl substances (PFAS), primarily in the form of aqueous film forming foam (AFFF) released as part of firefighting activities, although other PFAS sources are possible. In addition, the ARNG is assessing businesses or operations adjacent to the ARNG facility (not under the control of ARNG) that could potentially be responsible for a PFAS release.

PFAS are classified as emerging environmental contaminants that are garnering increasing regulatory interest due to their potential risks to human health and the environment. PFAS formulations contain highly diverse mixtures of compounds. Thus, the fate of PFAS compounds in the environment varies. The regulatory framework at both federal and state levels continues to evolve. The US Environmental Protection Agency (USEPA) issued Drinking Water Health Advisories for PFOA and PFOS in May 2016, but there are currently no promulgated national standards regulating PFAS in drinking water. In the absence of federal maximum contaminant levels, some states have adopted their own drinking water standards for PFAS. The State of Kansas does not currently have drinking water standards for PFAS.

This report presents findings of a PA for PFAS at the Salina Army Aviation Support Facility (AASF) #2 (also referred to as the “facility”) in Salina, Kansas, in accordance with the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), as amended, the National Oil and Hazardous Substances Pollution Contingency Plan (40 Code of Federal Regulations Part 300), and USACE requirements and guidance.

This PA documents potential locations where PFAS may have been used, stored, or released into the environment at AASF #2. The term PFAS will be used throughout this report to encompass all PFAS chemicals being evaluated, including PFOS and PFOA, which are key components of AFFF.

1.2 Preliminary Assessment Methods

The performance of this PA included the following tasks:

- Reviewed data resources to obtain information relevant to suspected PFAS releases
- Conducted a site visit on 28 August 2019
- Interviewed current Kansas ARNG (KSARNG) personnel during the site visit as well as KSARNG environmental managers and operations staff
- Completed visual survey inspections to confirm absence of PFAS-related activities and documented with photographs

1.3 Report Organization

This report has been prepared in accordance with the USEPA *Guidance for Performing Preliminary Assessments under CERCLA* (USEPA, 1991). The report sections and descriptions of each are:

- **Section 1** – **Introduction:** identifies the project purpose and authority and describes the facility location, environmental setting, and methods used to complete the PA
- **Section 2** – **Fire Training Areas:** describes the fire training areas (FTAs) at the facility identified during the site visit
- **Section 3** – **Non-Fire Training Areas:** describes other locations of PFAS releases at the facility identified during the site visit
- **Section 4** – **Emergency Response Areas:** describes areas of AFFF release at the facility, specifically in response to emergency situations
- **Section 5** – **Adjacent Sources:** describes sources of PFAS release adjacent to the facility that are not under the control of ARNG
- **Section 6** – **Preliminary Conceptual Site Model:** describes the pathways of PFAS transport and receptors for the Areas of Interest (AOIs) and the facility
- **Section 7** –**Conclusions:** summarizes the data findings and presents the conclusions of the PA
- **Section 8** – **References:** provides the references used to develop this document
- **Appendix A** – Data Resources
- **Appendix B** – Preliminary Assessment Documentation
- **Appendix C** – Photographic Log

1.4 Facility Location and Description

AASF #2 is in the eastern portion of the Salina Municipal Airport, in Salina, Kansas (**Figure 1-1**). The facility is on the southwestern city limits of Salina and is adjacent to Dry Creek to the east. The cities of Hedville, Bavaria, Smolan, New Cambria, and Mentor lie within 10 miles of AASF #2.

AASF #2 was constructed in 1942 on an approximately 12-acre parcel of land that is owned by the Salina Airport Authority and leased to the KSARNG. The current lease agreement began in 1988 and expires in 2087. See **Appendix A** for real estate documents. The AASF #2 facilities include a hangar for the operation, maintenance, and repair of KSARNG rotary-winged aircraft, administrative offices, and classrooms.

1.5 Facility Environmental Setting

Environmental information found in **Section 1.5** for this PA was adapted in part from the Operational Range Phase II Assessment at the Kansas Regional Training Center (URS and Arcadis/Malcolm Pirnie, 2011).

AASF #2 is located in the Smoky Hill River Valley. The Smoky Hill River flows from higher elevation in the west, from mountains in Colorado, down through Kansas in a general east-southeast trend. Regionally in Kansas, the Smoky Hill River cuts into the surrounding Permian bedrock, resulting in deep valleys partially filled with Quaternary alluvium. AASF #2 overlies this

alluvium, which covers a large portion of central and northeast Saline County (National Oceanic and Atmospheric Administration [NOAA], 2019).

1.5.1 Geology

The Quaternary alluvium deposit consists of sand and gravel interfingered with clay and silt lenses. The entire deposit ranges from 40 to 120 feet thick, averaging 60 feet thick, with the bottom two-thirds exhibiting coarser grains, and the top third exhibiting finer grains. The thickness of the alluvium directly underlying AASF #2 is unknown (US Geological Survey [USGS], 1986).

The Cretaceous deposits underlying the Quaternary alluvium are up to 400 feet thick and are in places undifferentiated. Where differentiation is apparent, the upper 300 feet are known as the Dakota Formation, which comprises mudstones and channel sandstones; elongate lens-like deposits of sandstone that indicate presence of paleo-river beds (Hattin & Siemers, 1987*)*. Underlying the Dakota Formation is 30 to 100 feet of the Kiowa Formation, consisting of sandstones, siltstones, and shale. The thickness of the formation directly underlying the site is unknown (KGS, 1988). Cretaceous deposits, namely the Dakota Formation, can be seen outcropping to the west of AASF #2.

The Permian Wellington Formation unconformably underlies the Cretaceous deposits. The almost 500-foot thick formation is primarily composed of gray to greenish-gray shale, comprising illite and chlorite clay minerals, and traces of reddish hematite. Lenticular beds of limestone, dolomites, and gypsum are present; the beds are thick enough in places to have member names such as the Carlton Limestone and the Hutchinson Salt Member (Swineford, 1955*)*. The Hutchinson Salt Member, the most important economic member of the Wellington, is predominately halite with anhydrite and shale. Outcrops of the Wellington Formation do occur in Saline county, but the Hutchinson Salt is usually absent, as it weathers readily.

1.5.2 Hydrogeology

The unconsolidated Smoky Hill River-valley alluvium and the Wellington Formation are the two primary aquifers utilized in the area near AASF #2 (**Figure 1-2**). No information was readily available for the Dakota Formation, which, while an important aquifer in other parts of Kansas, is not utilized as an aquifer in the areas surrounding AASF #2.

The Smoky Hill aquifer is generally composed of sand and gravel deposits interlayered with silt and clay. The aquifer encompasses areas recharged on facility by meteoric water and is generally unconfined due to its unconsolidated nature and the limited lateral extent of clay layers within the alluvium. Therefore, surface water and groundwater flow are hydrologically connected in areas within and downgradient from the facility. According to previous reports, more than a dozen downgradient domestic wells are screened within this aquifer. The total thickness of this aquifer below the facility is unknown.

The Wellington aquifer is utilized as an aquifer for a few domestic and agricultural wells in the AASF #2 area. Discontinuous beds of evaporites (halite, gypsum, and anhydrite), limestones, channel sandstones, and mudstones (shales and clays) exist within the formation, giving various hydraulic conductivities, confining units, and water chemistry; dissolution of evaporites and limestone can lead to the presence of cavities within the aquifer and the increase of calcium, sodium, chlorine, and sulfate within the groundwater. Potable water quality is therefore highly variable within the Wellington aquifer.

Groundwater depth within the Smoky Hill aquifer, measured from five existing wells on the facility in 2011, was between 22 and 60 feet below ground surface (bgs). Groundwater flow is generally northeast, following surface topography. The Smoky Hill aquifer is recharged mainly by meteoric water and occasionally by floodwaters of the Smoky Hill River that overflows its banks and

inundates the fluvial plain. The Wellington aquifer is recharged by the Smoky Hill aquifer by infiltration of groundwater and discharges approximately 20 miles northeast of the facility.

No potable water wells are located within the boundary of AASF #2; however, four domestic well types exist within 1 mile of the facility (**Figure 1-2**). These wells are side gradient and down gradient of AASF #2. There are US Geological Survey (USGS) wells in addition to geothermal wells that exist in the area surrounding AASF #2, and several domestic water wells to the east and north of the AASF #2. Drinking water for AASF #2 is supplied by the City of Salina, which obtains water from 17 groundwater wells within the City of Salina, and from the surface water of the Smoky Hill River as their water source (City of Salina, 2019). Based on the USEPA Unregulated Contaminant Monitoring Rule 3 data, it was indicated that no PFAS were detected in the City of Salina public water system above the United States Environmental Protection Agency Lifetime Health Advisory level within 20 miles of the facility.

1.5.3 Hydrology


Located within the Lower Saline River watershed, surface water flow is generally north-northeast (**Figure 1-3**), where tributaries of the Saline River, such as Dry Creek, run into the Solomon River, approximately 16 miles northeast. Intermittent stream channels are present near the facility, indicated by dry but well-formed channels. According to the site Spill Prevention, Control, and Countermeasure (SPCC) Plan, it is into these unnamed, intermittent tributaries of the Saline River that surface flow from the facility eventually drains.

1.5.4 Climate

Climate data for AASF #2 was available at a weather station located at the Saline Municipal Airport, less than 2,000 yards to the northwest of the facility. Kansas has a temperate continental climate. Precipitation in the form of rainfall was recorded at an annual average of 30.6 inches per year. Summer temperatures reach an average of 79.8 degrees Fahrenheit (°F) and an average maximum of 91.7°F, with July being the hottest month. Winter months reach an average temperature of 34.7°F. Winter minimum temperatures reach an average low of 23.3°F, with January being the coldest (NOAA, 2019).

1.5.5 Current and Future Land Use

AASF #2 is a controlled access facility with public roads and is adjacent to the Salina Municipal Airport; it is under lease until 2087. Reasonably anticipated future land use is not expected to change from the current land use; however, future infrastructure improvements, land acquisitions, and land use controls at the Salina Municipal Airport and surrounding areas are unknown.



CLIENT	ARNG			
NOTES	Preliminary Assessment for PFAS at Salina AASF 2, KS			
REVISED	11/25/2019	GIS BY	MS	11/25/2019
SCALE	1:63,360	CHK BY	SI	11/25/2019
Base Map: Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI,		PM	RG	11/25/2019


N

Facility Location

AECOM
12420 Milestone Center Drive
Germantown, MD 20876

Figure 1-1

Q:\Projects\ENV\GEARS\GEO\ARNG PFAS\900-CAD-GIS\920-GIS or Graphics\MXD\KS\Salina_AASF2_Figures\Fig_1-1_Salina_AASF2_Location.mxd



CLIENT	ARNG			
NOTES	Preliminary Assessment for PFAS at Salina AASF 2, KS			
REVISED	11/25/2019	GIS BY	MS	11/25/2019
SCALE	1:31,680	CHK BY	SI	11/25/2019
Base Map: Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS,		PM	RG	11/25/2019

Groundwater Features

AECOM
12420 Milestone Center Drive
Germantown, MD 20876

Figure 1-2

Q:\Projects\ENV\GEARS\GEO\ARNG PFAS\900-CAD-GIS\920-GIS or Graphics\MXD\KS\Salina_AASF2_Figures\Fig_1-2_Salina_AASF2_Groundwater_Features.mxd



CLIENT	ARNG			
NOTES	Preliminary Assessment for PFAS at Salina AASF 2, KS			
REVISED	11/25/2019	GIS BY	MS	11/25/2019
SCALE	1:31,680	CHK BY	SI	11/25/2019
Base Map: Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS,		PM	RG	11/25/2019

N

Surface Water Features

AECOM
12420 Milestone Center Drive
Germantown, MD 20876

Figure 1-3

Q:\Projects\ENV\GEARS\GEO\ARNG PFAS\900-CAD-GIS\920-GIS or Graphics\MXD\KS\Salina_AASF2_Figures\Fig_1-3_Salina_AASF2_Surface_Water_Features.mxd

2. Fire Training Areas

No FTAs were identified at AASF #2 during the PA through interviews (**Appendix B**), historical document review, or the Environmental Data Resource Report.

3. Non-Fire Training Areas

One non-FTA where AFFF was stored and/or potentially released was identified during the PA. A description of the non-FTA is presented below and shown on **Figure 3-1**. Interview records and photographs are included in **Appendix B** and **Appendix C**, respectively.

3.1 AFFF Fire Extinguisher Storage

The AASF #2 facility housed seven 33-gallon Ansul™ Alcohol-Resistant AFFF (Ansul™ AR-33-D) mobile fire extinguishers with 15 percent AFFF and one water-based fire extinguisher in various locations on the ramp area from approximately 2001 to 2015. In 2015, Purple K fire extinguishers were placed on the ramp areas, and the Ansul™ AR-33-D fire extinguishers were stored outside on the northwest perimeter of the main hangar. The Ansul™ AR-33-D fire extinguishers were never dispensed on the ramp area and there were no reports of spills or leaks from the fire extinguishers.

The seven Ansul™ AR-33-D fire extinguishers and one water-based fire extinguisher were stored outside the main hangar until August 2019. The AFFF solution in the seven fire extinguishers and one water-based extinguisher were containerized into 55-gallon drums and properly disposed of through the Defense Logistics Agency (DLA) contract. The empty fire extinguishers were shipped to the US Property and Fiscal Office (USP&FO)/Quality Recycling Program (QRP) in Topeka, Kansas for recycling as scrap metal. There were no reported spills or leaks when the AFFF solution was containerized.



CLIENT	ARNG			
NOTES	Preliminary Assessment for PFAS at Salina AASF 2, KS			
REVISED	11/25/2019	GIS BY	MS	11/25/2019
SCALE	1:1,800	CHK BY	SI	11/25/2019
Base Map: Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS,		PM	RG	11/25/2019

N

Non-Fire Training Area

AECOM
12420 Milestone Center Drive
Germantown, MD 20876

Figure 3-1

Q:\Projects\ENV\GEARS\GEO\ARNG PFAS\900-CAD-GIS\920-GIS or Graphics\MXD\KS\Salina_AASF2_Figures\Fig_3-1_Salina_AASF2_Non-Fire_Training_Areas.mxd

4. Emergency Response Areas


No emergency response areas or incidents were identified within the AASF #2 boundary during the PA through interviews (**Appendix B**), historical document review, or the Environmental Data Resource Report. The Salina Airport Authority Fire Department responds to all emergency incidents at AASF #2.

5. Adjacent Off-Facility Sources

One potential off-facility source of PFAS adjacent to AASF #2, not under the control of the ARNG, was identified during the PA. Based on interviews with KSARNG personnel (**Appendix B**) and historical document review, the identified adjacent area with potential AFFF releases are outside the AASF #2 boundaries. A description of the adjacent source is presented below, and the adjacent source is shown on **Figure 5-1**.

5.1 Salina Airport Authority Fire Department

The Salina Airport Authority Fire Department responds to emergencies at AASF #2. During interviews with the KSARNG, it was reported that the Salina Airport Authority Fire Department has AFFF and Purple K firefighting capabilities; however, there are no accounts or reports of any emergency response or training at the Salina Regional Airport or at AASF #2.



CLIENT	ARNG			
NOTES	Preliminary Assessment for PFAS at Salina AASF 2, KS			
REVISED	11/25/2019	GIS BY	MS	11/25/2019
SCALE	1:9,600	CHK BY	SI	11/25/2019
Base Map: Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS,		PM	RG	11/25/2019

N

Adjacent Source

AECOM
12420 Milestone Center Drive
Germantown, MD 20876

Figure 5-1

Q:\Projects\ENV\GEARS\GEO\ARNG PFAS\900-CAD-GIS\920-GIS or Graphics\MXD\KS\Salina_AASF2_Figures\Fig_5-1_Salina_AASF2_Adjacent_Sources.mxd

6. Preliminary Conceptual Site Model

Based on the PA findings from interviews with facility personnel, on-facility observations, review of the Environmental Data Resource Report, and online research, no release areas were identified as AOIs at AASF #2. A conceptual site model (CSM) identifies three components necessary for potentially complete exposure pathways related to a site: (1) source, (2) pathway, and (3) receptor. If any of these elements are missing, the pathway is considered incomplete. However, since no PFAS sources were identified to originate at AASF #2 or from activities associated with the facility, preliminary CSMs were not developed.

7. Conclusions

This report presents a summary of available information gathered during the PA on the potential use, storage, or release of AFFF and other PFAS-related activities at AASF #2. The PA findings are based on the information presented in **Appendix A** and **Appendix B**.

7.1 Findings

Based on information obtained during interviews conducted with facility personnel, facility observations, and reviewed documentation, it is confirmed that AFFF has never been used or released at AASF #2; therefore, no AOIs related to PFAS releases were identified.

Interviewee knowledge from KSARNG personnel at AASF #2 dates to at least 1987. Evidence obtained during the PA supports that current or former ARNG facility activities have not contributed to any potential PFAS contamination in soil, groundwater, surface water, or sediment. No potential areas of PFAS use or release were identified at AASF #2.

Based on the documented absence of the use or release of PFAS-containing materials at AASF #2, evidence does not support current or former ARNG activities at AASF #2 having contributed to PFAS contamination in soil, groundwater, surface water, or sediment at the facility or adjacent areas. No AOIs related to PFAS release were identified at AASF #2 based on PA data.

7.2 Uncertainties

A number of information sources were investigated during this PA to determine the potential for PFAS-containing materials to have been stored, used, or released at the facility. Historically, documentation of PFAS use was not required because PFAS were considered benign. Therefore, records were not typically kept by the facility or available during the PA on the disposition and use of PFAS in training, firefighting, or other non-traditional activities.

The conclusions of this PA are predominantly based on the information provided during interviews with personnel who had direct knowledge of PFAS use at the facility. Sometimes, the provided information was vague or conflicted with other sources. Gathered information has a degree of uncertainty due to the absence of written documentation, the limited number of personnel with direct knowledge due to staffing changes, the time passed since PFAS were first used (1987 to present), and a reliance on personal recollection. Inaccuracies may arise in potential PFAS release locations, dates of release, volume of releases, and the concentration of AFFF used. There is also a possibility the PA has missed a source of PFAS, as the science of how PFAS may enter the environment continually evolves.


In order to minimize the level of uncertainty, readily available data regarding the use and storage of PFAS were reviewed, current personnel were interviewed, multiple persons were interviewed for the same potential source area, and potential source areas were visually inspected. The uncertainties associated with the PA are summarized in **Table 7-1**.

Table 7-1: Uncertainties

Area	Source of Uncertainty
AASF #2	Direct interviewee knowledge is not available before 1987. Whether potential use, storage, or release of PFAS-containing materials occurred at this facility prior to 1987 is unknown.

7.3 Potential Future Actions

Based on the documented absence (1987-present) of the use or release of PFAS-containing materials at AASF #2, no AOIs were identified during the PA. Evidence does not indicate that current or former ARNG activities contributed PFAS contamination to soil, groundwater, surface water, or sediment at the facility or adjacent areas. AASF #2 will not move forward in the CERCLA process.



CLIENT	ARNG			
NOTES	Preliminary Assessment for PFAS at Salina AASF 2, KS			
REVISED	11/25/2019	GIS BY	MS	11/25/2019
SCALE	1:9,600	CHK BY	SI	11/25/2019
Base Map: Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS,		PM	RG	11/25/2019

Summary of Findings

AECOM
12420 Milestone Center Drive
Germantown, MD 20876

Figure 7-1

Q:\Projects\ENV\GEARS\GEO\ARNG PFAS\900-CAD-GIS\920-GIS or Graphics\MXD\KS\Salina_AASF2_Figures\Fig_7-1_Salina_AASF2_Summary.mxd

8. References

City of Salina, 2019. *Consumer Confidence Report – Covering Calendar Year 2018.* January.

Hattin, D.E; Siemers, C.T. 1987. *Upper Cretaceous Stratigraphy and Depositional Environments of Western Kansas*. Kansas Geological Survey, Guidebook, 39th Field Conference, 1987, Pages 1-30.

KGS, 1988. *Hydrogeology and Water Chemistry of the Great Plains (Dakota, Kiowa, and Cheyenne) and Cedar Hills Aquifers in Central Kansas.*

National Oceanic and Atmospheric Administration (NOAA). 2019. Climate Data Online. https://www.ncdc.noaa.gov/cdo-web/. Accessed September 2019.

Swineford, Ada. 1955. *Composition and Texture of Upper Permian Sediments in South-Central Kansas.* State Geological Survey of Kansas.

URS and Arcadis/Malcolm Pirnie, 2011. *Final Work Plan Operational Range Phase II Assessment Kansas RTC, Kansas.* October.

United States Environmental Protection Agency (USEPA). 1991. *Guidance for Performing Preliminary Assessments under CERCLA.* September.

USGS, 1986. *Geohydrology of the Wellington-Alluvial Aquifer and Evaluation of Possible Locations of Relief Wells to Decrease Saline Ground-Water Discharge to the Smoky Hill and Solomon Rivers, Central Kansas.*

Appendix A
Data Resources

Data Resources will be provided separately on CD. Data Resources for Salina AASF #2.

Salina AASF #2 Leases, Licenses, and Permits

- 1988 Lease Agreement

Salina AASF #2 Documentation

- 2001 KSARNG Cultural Resources Survey
- 2014 Notice of Intent for Stormwater Runoff
- 2019 Schilling AFB Site Background
- 2019 Fire Extinguisher Manifest
- 2019 Signed and Approved AFFF Turn In Manifest

EDR Report

- 2019 Salina AASF #2 EDR Report

STATE OF KANSAS
DEPARTMENT OF ADMINISTRATION
DIVISION OF PURCHASES
DA-46 * (Rev. 5/81)

AGENCY COPY
REAL ESTATE LEASE AGREEMENT

Agency Contract No. 034-20 Enc. No. 886143

( ) For obligation of previously approved lease only

Previous Year's Enc. No. _____

ENCUMBRANCE CLASS [1]	Agency	Sub-Agency	Fund	FY	Sub-Acct	Prog	Act	Obj	Amount	Agency Use
1. Payment must not exceed enc.	034	00	1000	8	1600	9611		234	1.00	
2. Must liquidate w/in $100 or 10%										
3. No liquidation limit										
FIRM/CONTINGENT [1] 1—Firm 2—Contingent										

9. Termination for Fiscal Necessity: Notwithstanding any other provision of this lease, if funds anticipated for the continued fulfillment of this lease agreement are at any time not forthcoming, either through failure of the legislature to appropriate funds or the discontinuance or material alteration of the program under which funds were provided, than second party shall have the right to terminate this lease by giving first party a reasonable notice specifying the reasons for such necessary termination. The termination of the lease pursuant to this paragraph shall not cause any penalty to be charged to the state agency.

10. Automatic Termination; Holding Over: This lease agreement, if not previously terminated, shall automatically expire at the end of the term specified unless second party shall have renewed the lease pursuant to lease special provision (2); however if second party shall hold over the end of the term without the benefit of renewal, he shall be a tenant from month to month at the same terms and conditions as contained herein.

11. Removal of Personal Property: All personal property, or installed personal property, placed upon the premises by second party during occupancy, which may be removed upon vacation by second party at the end of the term without substantial damage to the real estate, shall be and remain the sole property of second party and may be removed; or if substantial damage would occur, second party may elect to remove the property and restore the premises.

12. Agreement with Kansas Law: All lease agreements shall be subject to, governed by, and construed according to the laws of the State of Kansas.

13. Equal Opportunity: First party agrees: (a) to comply with the Kansas Act against discrimination (K.S.A. 1980 Supp. 44-1001 *et seq.*) and to not discriminate against any person who performs work hereunder, because of race, religion, color, sex, national origin or ancestry; (b) to include in all solicitations or advertisements for employees, the phrase "equal opportunity employer"; (c) that he or she will comply with the reporting requirements in K.S.A. 1980 Supp. 44-1031; (d) to include these provisions in every subcontract or purchase order so that they are binding upon such subcontract or vendor; (e) that failure to file any report required in (c) above or if found guilty of any violation of such act by the Kansas Commission on Civil Rights shall constitute a breach of this contract and it may be cancelled, terminated or suspended, in whole or in part by the second party.

14. Binding Effect: The terms and conditions of this lease shall be binding upon the parties, their heirs, agents, administrators, executors or legal successors.

15. Responsibility for Taxes and Liability for Damages: The State of Kansas shall not be responsible for, nor indemnify, a contractor for, any federal, state or local taxes which may be imposed or levied upon the subject matter of the lease. Notwithstanding any language to the contrary, the state shall not be responsible for any damages caused by the public or its employees except as provided in the Kansas Tort Claims Act, K.S.A. 1980 Supp. 75-6101 *et seq.*

16. Special Provisions: The following paragraphs indicated by X and numbered as listed hereafter or on an attachment in numerical sequence are made a part hereof and included by reference, *e.g.* 1, etc.: (1) Terms and conditions of Quitclaim deed from the United States of America to the Salina Airport Authority, dated 9 September (see attached). (2) All provisions of exhibit "A" (attached).

(Check if applicable)

Spec. Prov. 1. (X) Termination Prior to Expiration of Term: Notwithstanding the length of the term, second party may terminate this lease at any time prior to the expiration of the term upon the giving of a sixty (60) days notice in writing to first party.

Spec. Prov. 2. (X) Renewal: By the giving of a notice at least sixty (60) days prior to the end of the term specified, second party may renew this lease for an additional term of ninety-nine (99) years under the same rent, conditions, and terms set out herein.

Spec. Prov. 3. ( ) Parking: First party shall furnish to second party off-street parking for _____ motor vehicles upon land adjacent to the leased building.


Spec. Prov. 4. ( ) Storage: Second party shall have the unrestricted right to store materials or equipment of any kind whatsoever upon the premises and the right to remove said material at any time during the term of this lease or any renewal thereof.

Spec. Prov. 5. ( ) Improvements: Second party may install or construct upon the land, buildings and improvements of a temporary or permanent nature, and such buildings and improvements shall remain the sole property of second party and may be removed at any time.

Additional Special Provisions, if any, should be set out on a separate sheet to begin with number six. If there *are* special provisions they all must be listed in numerical order to be considered effective to bind the parties; the parties to this agreement must sign their names immediately following the last listed special provision. This lease agreement should be completed well in advance of the proposed effective date of the lease and submitted for the approval of the Department of Administration so that if approval is not forthcoming, the parties will not have changed their positions. No lease is effective nor may expenditure be made without all required approvals.

Signed First Party	March 22, 1988 (Date)	Thomas J Kennedy (Name)	Chairman (Title)
Signed Approvals Second Party	Agency Officers Approved: THOMAS A. BECHER Comptroller - AG Dept.	Agency Attorney: *I certify that I have examined this lease agreement and find it is within the authority of the named agency to enter into including the special provisions, if any.* Name Maj John R. Mettner, Jr., Legal Advisor to Adjutant General's Dept Title The Adjutant General	
	Agency Head: *I certify that this lease agreement is entered into within the authority of law, is with my approval, and that the person signing the same for the state is authorized to do so.*	Name PHILIP B. FINLEY, BG, KSARNG Title The Adjutant General	
	Director of Purchases: N/A	Approved as to form and execution: (~~Attorney General~~) (~~Asst. Attorney General~~) (Chief Attorney, Dept. of Admin.) By Daniel J. Carroll ( ) Not Applicable	
	Director of Accounts and Reports: James R. Cobb		
	Department of Administration Space Management Officer: Loren A. Steel	X	

SECRETARY OF ADMINISTRATION



LEGAL DESCRIPTION

COMMENCING AT THE POINT OF INTERSECTION OF SCHILLING ROAD AND ARNOLD AVENUE; THENCE N 00°06'24" W A DISTANCE OF 689.68 FEET ALONG THE CENTERLINE OF ARNOLD ROAD; THENCE S 89°33'36" W A DISTANCE OF 296.47 FEET TO POINT OF BEGINNING; THENCE S 89°33'36" W A DISTANCE OF 358.57 FEET; THENCE N 00°05'39" W A DISTANCE OF 194.64 FEET; THENCE S 89°54'34" W A DISTANCE OF 215.38 FEET; THENCE S 00°06'24" E A DISTANCE OF 941.18 FEET; THENCE N 89°53'43" E A DISTANCE OF 290.31 FEET; THENCE N 00°06'24" W A DISTANCE OF 293.36 FEET; THENCE N 89°54'05" E A DISTANCE OF 75.56 FEET; THENCE N 00°10'29" W A DISTANCE OF 124.64 FEET; THENCE N 89°37'19" E A DISTANCE OF 209.12 FEET; THENCE N 00°16'06" W A DISTANCE OF 329.59 FEET TO POINT OF BEGINNING. SAID TRACT CONTAINS 361,623 SQUARE FEET (8.3 ACRES).

SURVEYOR'S CERTIFICATION

I, RALPH MEAGHER HEREBY CERTIFY THAT I AM A LICENSED LAND SURVEYOR OF THE STATE OF KANSAS; THAT THE SURVEY WAS PERFORMED BY ME OR UNDER MY DIRECTION AND THAT THE SURVEY IS TRUE AND CORRECT AS SHOWN.

Ralph Meagher


RALPH "PETE" MEAGHER
L.S. #512 KANSAS
P.E. #8023 KANSAS

RALPH MEAGHER
L.S. 512
KANSAS

WILSON & COMPANY
ENGINEERS
ARCHITECTS

SALINA, KANSAS
SALINA AIRPORT AUTHORITY
NATIONAL GUARD HANGAR AREA

DSGN. RM	DR. RET	CK. RM
FILE 83-086	DATE JAN. 86	SHEET 1 OF 2



LEGAL DESCRIPTION - TRACT 1

COMMENCING AT THE POINT OF INTERSECTION OF SCHILLING ROAD AND ARNOLD AVENUE; THENCE N 00°06'24" W, A DISTANCE OF 689.68 FEET ALONG THE CENTERLINE OF ARNOLD AVE.; THENCE S 89°33'36" W, A DISTANCE OF 40.00 FEET TO POINT OF BEGINNING; THENCE S 89°33'36" W, A DISTANCE OF 256.47 FEET; THENCE S 00°16'06" E, A DISTANCE OF 271.92 FEET; THENCE N 89°53'41" E, A DISTANCE OF 255.71 FEET; THENCE N 00°06'24" W, A DISTANCE OF 273.42 FEET TO POINT OF BEGINNING. SAID TRACT CONTAINS 69,829 SQUARE FEET (1.60 ACRES).

LEGAL DESCRIPTION - TRACT 2

COMMENCING AT THE POINT OF INTERSECTION OF SCHILLING ROAD AND ARNOLD AVENUE; THENCE N 00°06'24" W, A DISTANCE OF 689.68 FEET ALONG THE CENTERLINE OF ARNOLD AVENUE; THENCE S 89°33'36" W, A DISTANCE OF 296.47 FEET TO POINT OF BEGINNING; THENCE S 89°33'86" W, A DISTANCE OF 187.22 FEET; THENCE N 00°11'23" W, A DISTANCE OF 309.19 FEET; THENCE N 89°49'06" E, A DISTANCE OF 169.18 FEET; THENCE S 10°31'38" E, A DISTANCE OF 100.43 FEET; THENCE S 00°11'38" E, A DISTANCE OF 209.54 FEET TO POINT OF BEGINNING. SAID TRACT CONTAINS 56,911 SQUARE FEET (1.307 ACRES).

LEGAL DESCRIPTION - TRACT 3

COMMENCING AT THE POINT OF INTERSECTION OF SCHILLING ROAD AND ARNOLD AVENUE; THENCE N 00°06'24" W, A DISTANCE OF 749.68 FEET ALONG THE CENTERLINE OF ARNOLD AVENUE; THENCE S 89°33'36" W, A DISTANCE OF 40.00 FEET TO POINT OF BEGINNING; THENCE N 00°06'24" W, A DISTANCE OF 135.00 FEET, THENCE S 89°33'36" W, A DISTANCE OF 216.71 FEET; THENCE S 00°11'38" E, A DISTANCE OF 80.00 FEET; THENCE S 40°29'54" E, A DISTANCE OF 71.85 FEET; THENCE N 89°33'36" E, A DISTANCE OF 170.03 FEET TO THE POINT OF BEGINNING. SAID TRACT CONTAINS 27,962 SQUARE FEET (.642 ACRES).

SURVEYOR'S CERTIFICATION

I, RALPH MEAGHER HEREBY CERTIFY THAT I AM A LICENSED LAND SURVEYOR OF THE STATE OF KANSAS; THAT THE SURVEY WAS PERFORMED BY ME OR UNDER MY DIRECTION AND THAT THE SURVEY IS TRUE AND CORRECT AS SHOWN.

Ralph Meagher

RALPH "PETE" MEAGHER
L.S. #512 KANSAS
P.E. #8023 KANSAS

SUMMARY

TRACT NO.	ACRES	SQ. FT.
1	1.60	69,829
2	1.307	56,911
3	.642	27,962

EXHIBIT "A"

(1). Lease is subject to certain restrictions and limitations contained in "Application for Airport Property" dated September 3, 1964, and the deed of conveyance of the property from the General Services Administration dated September 9, 1966, which appears of record in Deed Book 267, pages 454-467, in the office of the Register of Deeds of Saline County, Kansas.

(2). Agency agrees that it will not use the property in any manner which will interfere with or adversely affect the use, operation, maintenance or development of the airport facilities.

(3). Parties agree to enter into a Joint Use Agreement which shall be mutually acceptable to both parties hereto and the FAA.

(4). Agency agrees that it will comply with all applicable laws, ordinances and regulations of any governmental agency which has jurisdiction over the premises.

(5). The lease is contingent upon its approval by the FAA.

AGREEMENT FOR SALE OF HANGAR

This Agreement, made and entered into this 15th day of September, 1988, by and between the SALINA AIRPORT AUTHORITY of Salina, Saline County, Kansas, herein "Authority," and KANSAS MILITARY BOARD, herein "KMB," WITNESSETH:

Authority agrees to sell to KMB and KMB agrees to purchase from the Authority the aircraft hangar known as Building #309 located at 2917 Hein Avenue (the "Hangar") located on real estate in the Schilling Subdivision to the City of Salina, Saline County, Kansas, described as follows:

> Commencing at the point of intersection of Schilling Road and Arnold Avenue; thence N00°06'24"W a distance of 689.68 feet along the centerline of Arnold Road; thence S89°33'36"W a distance of 296.47 feet to point of beginning; thence S89°33'36"W a distance of 358.57 feet; thence N00°05'39"W a distance of 194.64 feet; thence S89°54'34" a distance of 215.38 feet; thence S00°06'24"E a distance of 941.18 feet; thence N89°53'43"E a distance of 290.31 feet; thence N00°06'24"W a distance of 293.36 feet; thence N89°54'05" a distance of 75.56 feet; thence N00°10'29"W a distance of 124.64 feet; thence N89°37'19"E a distance of 209.12 feet; thence N00°16'06"W a distance of 329.59 feet to point of beginning. Said tract contains 361,623 square feet [8.3 acres] (a copy of the survey is attached hereto as Exhibit "A",

upon the following terms and subject to the conditions and requirements herein set forth:

(1). Purchase Price. The purchase price for the Hangar shall be Three Hundred Ninety Two Thousand Dollars ($392,000), payable from Federal Funds pursuant to NGB #14-88-c-5027, at the following times:

(a) Three Hundred Fifty-Seven Thousand Dollars ($357,000) on Closing Date;

(b) Thirty-Five Thousand Dollars ($35,000) upon completion of the hangar improvements specified in paragraph (6) of the Agreement.

(2). Closing Date. The Closing Date for this transaction shall be the 30th day of September, 1988;

provided, however, that in the event that the Authority is unable to provide KMB with satisfactory evidence of title by said date, then the Closing Date shall be the day following the date on which the Authority does furnish KMB satisfactory evidence of title.

(3). Bill of Sale. Authority shall execute, acknowledge, and deliver to KMB on Closing Date a Bill of Sale transferring the ownership of the Hangar to KMB, free and clear of all liens and encumbrances.

(4). Evidence of Title. Authority shall provide KMB with an Owner's Leasehold Policy of Title Insurance in the amount of the contract price showing good and marketable title in and to the Hangar, free and clear of all liens and encumbrances.

(5). Taxes. The Hangar is at the present time not subject to taxes; provided, however, should it be determined that the Hangar is subject to any ad valorem taxes or assessments, Authority agrees that it will pay any taxes which might be assessed for the year 1988 and all prior years.

(6). Improvements to Hangar. Authority agrees that it will at its own expense make the following improvements to the hangar:

(a). Install overhead crane beam

(b). Install aircraft wash area with oil and/or water separator

(c). Install 12 x 16 foot overhead metal door

(d). Install shower (male)

(e). Seal and paint hangar floor

The above improvements shall be made and installed in accordance with plans and specifications mutually acceptable to Authority and KMB.

(7). Rental. KMB is currently leasing the Hangar from the Authority under an agreement which provides for monthly rentals. Rental shall cease on Hangar on Closing Date. Rental for month of closing shall be prorated as of Closing Date and any unearned rentals shall be refunded to KMB. Any accrued and unpaid rental shall be paid to Authority.

(8). Destruction of Hangar Prior to Closing. If the Hangar is destroyed or substantially damaged by fire, lightning or other cause prior to Closing Date, then either party shall have the option of terminating this agreement by written notice within ten (10) days thereafter. If not cancelled, Authority shall pay over to KMB all insurance proceeds relating to the Hangar it may receive by virtue of said loss.

(9). Extent of Agreement. This agreement shall be binding upon and inure to the benefit of the parties hereto and their respective successors and assigns.

IN WITNESS WHEREOF, the parties have hereunto set their hands the day and year first above written.

SALINA AIRPORT AUTHORITY

By _____
Executive Director

KANSAS MILITARY BOARD

By _____

B 4057

KANSAS ARMY NATIONAL GUARD CULTURAL RESOURCES SURVEY

A report submitted to
the National Guard of Kansas,
Adjutant General's Department,
Director of Facilities Engineering

by
Randall M. Thies
Archeology Office, Cultural Resources Division
Kansas State Historical Society
January 1, 2001

ABSTRACT

Beginning in 1997 and extending into 2000, the Kansas State Historical Society undertook a cultural resources survey of the Kansas Army National Guard installation, which consists of all properties owned, operated, or impacted by the Guard. The purpose of the survey was to identify historic properties (defined according to criteria for listing on the National Register of Historic Places or the Register of Historic Kansas Places) and to document other cultural resources such as archeological sites, buildings, monuments, cannons, artifacts, and works of art.Ten historic properties were identified.

Seven of these properties are buildings. At Fort Leavenworth, three buildings are listed on the National Register as "contributing buildings" in the Fort Leavenworth National Historic Landmark District. Similarly, another building at Fort Riley was determined several years ago to be eligible for the Register as part of the proposed Marshall Army Airfield Historic District. Three more buildings (the armories at Hiawatha, Kingman, and St. Marys) were identified in the current survey as being potentially eligible for listing on the National Register or the Register of Historic Kansas Places. Arrangements are being made to accrue more extensive documentation on the three armories, to serve for Register nominations if so desired by the Guard. No other buildings were found to fit the criteria for National Register listing, generally because of recency of construction but also because most of the buildings are regarded as lacking in architectural or historic significance. However, forty-six armories dating from the Cold War era will soon become old enough to qualify for consideration, and these may be viable candidates for a thematic nomination to the National Register. The SHPO has recommended a research effort designed to result in a context statement that would address the significance of the Cold War armories and also aid in evaluating the Hiawatha, Kingman, and St. Marys armories. Arrangements are thereby underway for such research to be conducted as part of the documentation effort carried out for the three older armories.

The list of historic properties also includes three archeological sites at Fort Leavenworth. The sites were recommended for further testing by earlier investigators and therefore must be considered as potentially eligible for the National Register until the recommended testing resolves their status. One other site at Fort Leavenworth was tested and determined to be lacking in significance and therefore ineligible for the National Register. Other archelogical resources include twenty-one sites at the Guard's Regional Training Area (RTA) in Saline County. All of the RTA sites were found to be lacking in significance and therefore ineligible for the National Register.

In addition, the survey documented numerous artworks (mostly portraits of past commanders) and several weapons that serve as monuments or symbols of the Guard's role in past conflicts. The most notable include two Civil War cannons, a three-inch field gun of 1905 vintage, a World War II self-propelled gun known as a "Priest," a late-model Sherman tank, and perhaps most remarkable of all, a Japanese 75 mm cannon known as a Meiji 41.

ACKNOWLEDGEMENTS

It is seldom that any researcher can accomplish his work without the help of others, and that has certainly been the case with this study. One of the greatest pleasures of my survey of the Kansas Army National Guard installation is the opportunity I have had to meet Guard personnel--at least one individual (usually the local full-timer) in virtually every National Guard facility from one end of the state to the other. They have been unfailingly courteous and helpful, although often a bit puzzled about the nature of my research and amused at the idea that there might be archeological resources on their property. Putting that aside, it soon became clear to me that the men and women of the Kansas Army National Guard are a breed apart from the norm: these are people who know the meaning of dedication and service, honor and courage. These are people who face the real challenges of life by dealing with floods, tornados, and other unexpected disasters in their local communities. At the same time, they stand ready to march off to war. Meeting them has been an honor and I am glad for this opportunity to acknowlege that fact, even though space does not permit me to single them all out in this document.

Two names certainly should be mentioned: Colonel John Andrew and Patti Haines-Lieber from the Facilities Engineering office in Topeka, who served as my main points of contact in negotiating this contract and carrying out the research. Along with Captain Tony Randall who replaced Colonel Andrew in 1999, they have always been helpful, and I thank them for their courtesy and assistance.

Mark Suddock, better known as Barney, who served as Range Supervisor for the Guard's Regional Training Area in rural Saline County, also deserves special mention. Although most of the Guard facilities required only a relatively brief visit, the RTA took several days of on-the-ground survey due to the large size of the property and the presence of numerous archeological sites. Barney gave me a warm welcome which included a complete tour of the training area, and on one occasion he provided much-needed assistance in traversing muddy roads too treacherous for my two-wheel-drive vehicle. Barney's knowledge of the RTA greatly facilitated my search for farmsteads obscured by half a century of abandonment, and I thank him for his assistance.

One last individual deserves mention here as well, although he is no longer among the living. The late John Reynolds was State Archeologist at the time we began negotiating this contract, and he thought the study would be a good idea for several reasons, primarily in that it enabled the Society to aid another state agency and at the same time carry out some relatively unique archeological and historical research. As I had some army experience (albeit from thirty years ago), he thought it would be right up my alley and therefore a logical and beneficial experience for me, the Society, and the Guard. John was always so right about things, and I'm sending him my thanks.

Randall M. Thies
1 January 2001

TABLE OF CONTENTS

Abstract

Acknowledgements

List of Figures

Chapter 1. Introduction: Research Background and Objectives

Chapter 2. Research Methodology

Chapter 3. The Cultural Historical Setting

Chapter 4. Research Results

- Archeological Sites
- The Built Environment
- Traditional Cultural Properties and Sacred Sites
- Armories and OMS Shops
- Fort Riley Properties
- Fort Leavenworth Properties
- Topeka Headquarters Properties
- Forbes Airport Properties
- Salina Airport Properties
- Regional Training Area Properties

Chapter 5. Summary and Conclusions

Chapter 6. Management Considerations

References Cited

Figures 1-23

Table I. List of "Nickell's Armories" and Independent OMS Shops with Dates of Construction

Appendix I. National Register Criteria and SHPO Correspondence
Appendix II. Native American Points of Contact List and Correspondence
Appendix III. Armories and OMS Shops: Basic Data
Appendix IV. Cannons, Monuments, and other Cultural Resources

LIST OF FIGURES

Figure 1. USGS map showing the location of Bldg 741, Marshall Field Hanger, at Fort Riley.

Figure 2. Map showing the location of Bldg 741 within the proposed Marshall Army Airfield Historic District.

Figure 3. USGS map showing general location of KSARNG properties (i.e., areas surveyed) at Fort Riley.

Figure 4. Fort Riley map showing west section of Camp Funston.

Figure 5. Fort Riley map showing east section of Camp Funston.

Figure 6. USGS map showing the general location and boundaries of the KSARNG motor pool area (i.e., area surveyed) at Fort Leavenworth, including Bldgs 109, 113 (north half) and 114.

Figure 7. USGS map showing general location and boundaries of KSARNG property (i.e, areas surveyed) at the Leader Development Center on the Fort Leavenworth military reservation.

Figure 8. USGS map showing general location and limits of archeological sites on KSARNG property at the Leader Development Center on the Fort Leavenworth military reservation.

Figure 9. Map showing the location of archeological site 14LV104.

Figure 10. Map showing the interpreted location of archeological site 14lV105.

Figure 11. Map showing the location of archeological site 14LV106.

Figure 12. Map showing the location of archeological site 14LV107.

Figure 13. Map showing the former location of archeological site 14LV108.

Figure 14. Map showing the interpreted location of archeological site 14LV109.

Figure 15. USGS map showing the location of KSARNG property at the Topeka headquarters complex on 27th Street and Topeka Boulevard in Topeka.

Figure 16. KSARNG map showing KSARNG properties in the northwest section of the Topeka headquarters complex.

Figure 17. KSARNG map showing KSARNG properties in the southeast section of the Topeka headquarters complex.

Figure 18. USGS map showing the location of KSARNG properties at Forbes Field.

Figure 19. USGS map showing the location of KSARNG properties at the Salina Airport.

Figure 20. KSARNG map modified to show the location of KSARNG properties at the Salina airport.

Figure 21. USGS map showing the boundaries of the Regional Training Area in rural Saline County.

Figure 22. USGS map showing the locations and general extent of areas investigated by pedestrian survey at the Regional Training Area in rural Saline County.

Figure 23. USGS map showing the locations and general extent of archeological sites documented at the Regional Training Area in rural Saline County.

INTRODUCTION:
RESEARCH BACKGROUND AND OBJECTIVES

In September 1996 the National Guard of Kansas contracted with the Kansas State Historical Society ("the Society," or KSHS) for a cultural resources survey of the Kansas Army National Guard ("the Guard," or KSARNG) installation consisting of various properties owned, operated, or used by KSARNG. The primary purpose of the study, described as a "Determination of Cultural Resources (Phase I Investigation)" in the Scope of Work (SOW), was to survey, identify, and record all significant cultural resources owned, used, or impacted by KSARNG. Cultural resources were defined in the SOW as including historic structures, prehistoric and historic archeological sites, and sacred places or traditional cultural properties. The study was intended to fulfill the Guard's obligations as required under Sections 106 and 110 of the National Historic Preservation Act (NHPA), EO 11593, Army Regulation 200-4, and other pertinent laws. The SOW noted that the NHPA requires federal entities to identify, evaluate, and to take into account all undertakings on cultural resources under their jurisdiction, and to evaluate any impact to cultural resources that may occur by that entity's actions even though such resources are not owned by that entity. Further, all federal divisions or federally funded divisions are required to exercise caution in assuring that any resource able to qualify for inclusion on the National Register for Historic Places is not inadvertantly transferred, sold, demolished, substantially altered, or allowed to deteriorate significantly.

The KSARNG installation was described as comprising various combinations of armories, maintenance shops, administrative complexes, and training centers in some 70 locations across the state. Also to be considered was the Guard's Regional Training Area consisting of some 3,536 acres of grassland and target ranges in rural Saline County, where remnants of old farmsteads were known to be present. Later additions to the list included several LTAs (Local Training Areas) which are locally-arranged training areas for individual units, usually on land which has been leased or "borrowed" on short-term arrangements with local landowners or governments. The SOW stated that no KSARNG properties were listed on the National Register, that no cultural resource survey had been conducted on the KSARNG installation, that no Historical Preservation Plan (HPP) been completed, and that no consistent effort had been made to maintain unit or armory histories. Research soon revealed, however, that two major studies had been done at Fort Riley and Fort Leavenworth, resulting in written reports describing the cultural resources of those areas (USACERL 1993 for Fort Riley; McNerney *et al.* 1989 for Fort Leavenworth).

The objectives of the survey were explicitly noted in the SOW as follows: 1) to determine the legal descriptions of each property; 2) develop a photo log of all the different structures; 3) account for each unit's history; 4) identify significant military and non-military historical events or structures; and 5) determine which cultural resources are historically significant and requiring further evaluation. The Society was to complete several specified tasks including A) develop a work schedule; B) develop an inventory of all properties owned or used by KSARNG; C) conduct

a background and records search; D) carry out an on-site survey of each property to evaluate its significance and determine what further studies might be required; E) identify any Native American tribes that may have an interest in cultural resources located on the installation, along with names of phone numbers of individuals identified as cultural resource Point-Of-Contact (POC) for those tribes; and F) complete and submit a draft and final report on the findings of the study.

Further details pertaining to these tasks were specified in the contract. As part of the properties inventory, the legal description was to be identified along with a site location as indicated on U.S.G.S. quadrangle maps. Photography was to include color slides along with black and white photos.

For the background and records search, the contractor was to identify all of the military organizations (i.e., units) that had been stationed in each facility; determine whether any historically significant events occurred within that organization; establish where the unit was mustered prior to the construction of the present-day facility; carry out research to identify any records pertaining to previous cultural resource surveys and sites that may have been designated, as well as areas of potential cultural sensitivity as indicated in regional archeological and historical overviews; supply copies of any pertinent documents, maps and/or photographs relating to the sites; identify relevant information concerning state and local cultural resource regulations and requirements; and discuss any additional information that might be pertinent.

With this information in hand, each KSARNG facility was to be evaluated for historical significance using the four criteria for inclusion in the National Register of Historic Places (Appendix I). The results, including recommendations for further research, were to be forwarded to the Guard and the State Historic Preservation Officer (SHPO) for review.

At the recommendation of the SHPO after his review of the draft report, the Society was also to consult directly with pertinent Native American tribes concerning their knowledge of sacred places or traditional cultural properties that might be present on the Kansas Army Guard installation. This consultation involved the same tribes that had been listed as possibly having an interest in cultural resources (Appendix II).

Not specifically stated in the SOW, but agreed upon in various meetings between the representatives of the contractor and KSARNG, were several other points. The research was intended to stretch over nearly three years' time, with a draft report to be submitted in February 1999. The historical research was to be generated from local sources, to augment whatever data already existed in the KSARNG archives. Further, the KSARNG Military History Detachment (the 102d MHD, headquartered in Topeka) was to be contacted to determine their interest in the historical documentation (pertaining to the armories especially) and to get their advice on the amount of effort to be put into such research.

Representatives of both KSARNG and KSHS also expressed an interest in accumulating

information on cultural resources that are extraneous to the National Register criteria. Included in this interest were monuments, cannon, and other equipment serving as "gate guards" and/or war memorials; wartime artifacts (such as Nazi memorabilia) serving as exhibits; artwork such as portraits of past commanders; "time capsules,"and other such items.

As called for in the SOW, a draft report was submitted to the KSARNG and the SHPO, with the Guard receiving their copy on 2 March 1999 (Thies 1999). Comments and suggestions for revision were then received from both parties and incorporated into a second report known as an "Interim Report" (Thies 2000). The Interim Report was deemed advisable to bring matters up to date, as events did not allow for completion of the final report at that time. The primary purpose for the delay centered around the need to obtain specialized services from a separate contractor to obtain National Register documentation for the armories in Hiawatha, Kingman, and St. Marys along with a context statement for the Guard's Cold War armories. The Guard eventually decided to authorize this work but not to have the nominations submitted at this time, as stated in a letter to Dick Pankratz, Dirctor of the KSHS Cultural Resources Division, from Colonel Stewart, Construction and Facilities Manager, dated 31 August 2000. In the same letter, the Guard requested that the Society complete the Survey Report without the armory nominations and address those properties as eligible for listing on the National Register. This report is the end result of these various negotiations and decisions.

RESEARCH DESIGN AND METHODOLOGY

The Society's research involved a combination of office research and field investigations. The work was directed by the author of this report, Society archeologist Randall M. Thies. Most of the basic data gathering associated with the office research was carried out by Office Specialist E.William Wren. All other other research efforts, including all field investigations, were conducted by the author. Assessments of significance were made by the author in consultation with staff of the Kansas State Historic Preservation Office.

Office Research

The office research began with ascertaining the current addresses or legal descriptions of all of the KSARNG facilities, then locating those facilities on USGS topographic quadrangles and county Soil Survey maps. These were examined in an attempt to determine the likelihood of buried archeological remains and the topographic potential for archeological sites, especially prehistoric sites which are linked to the local topography and natural resources in a way much different than historic sites whose locations are usually determined by section lines and road access.

During this level of the investigation the Local Training Areas (or LTAs) were interpreted as being of minimal concern and it was decided that they could safely be ignored by further research. Of the list of LTAs we were provided (along with a few maps), phone calls revealed that none were currently in use, and the ones that had been used and might potentially be used again mostly involved old city dumps and land fill areas obviously needing no further attention from the standpoint of cultural resources. The few areas that were not old city dumps were located in upland areas with no potential for significant prehistoric sites. It was also discovered that the Guard's use of these areas had little or no physical impact on them. Judging from the responses we received, LTAs are a very transitory commodity, usually involving the short-term and sporadic use, often no more than once or twice, of old land fill areas or a friendly farmer's land for training in vehicular use or infantry tactics, with no substantive disturbance of the landscape. Considering especially the lack of disturbance, and more importantly the fact that none of the LTAs were currently in use, it was decided that any further research was unnecessary at this time, and therefore no field investigations were carried out.

The main element of the records review consisted of evaluating the entire KSARNG installation (including the LTAs) for known or potential sites and historic properties using maps and reports on file with the SHPO's office. The SHPO's maps were consulted to determine whether any recorded archeological sites, National Register properties, historic trails or other cultural features (as indicated on the original Land Office surveys and similar sources) were in the locale. The same source was consulted with regard to any previous archeological surveys that may have been conducted in the area. On the few occasions when earlier surveys and recorded

sites were identified, those site files (kept at KSHS as part of the State Master Site File) were examined, as were the original survey reports. Copies of maps and other documents and bibliographic references were gathered when relevant. Early-day county atlases were consulted to determine whether historic buildings were once present in the locations under consideration.

As part of the overall records review and (as noted earlier in this report) to provide proper direction and emphasis to the field work, staff of the KSARNG 102d Military History Detachment was contacted regarding the 102d's view of what the research might contribute. SSGT Bryce Benedict indicated that unless any particularly notable information was developed, his office had very little interest in the armories and other facilities, regarding them as essentially utilitarian structures. The practical impact of this viewpoint was subsequently reinforced by the finding that extensive historical research would be necessary to procure such arcane data as the locations of facilities used as armories (or in most cases, simply rented for drill meetings) prior to the construction of the modern armory. Such research seemed unwarranted, and after discussion between Patti Haines-Lieber and the contractor it was decided that no major efforts were to be exerted in pursuit of this information.

The Society's research also involved consultation of several basic historical sources pertaining to the Guard. The two main sources were Jim Dan Hill's *The Minute Man in Peace and War: A History of the National Guard* (Hill 1964) and Brian Dexter Fowles' *A Guard in Peace and War: the History of the Kansas National Guard, 1854-1987* (Fowles 1989). Two major cultural resource survey reports reflecting the results of intensive archeological survey and historic building evaluations at Fort Riley and Fort Leavenworth were also consulted--these include a report by the U.S. Army Construction Engineering Research Laboratory, known as USACERL, dealing with Fort Riley (USACERL 1993), and a report by a private archeological contractor, American Resources Group, detailing the results of archeological survey on various portions of the Fort Leavenworth Military Reservation, including the lands now occupied by the Guard's Leadership Development Center (McNerney *et al.* 1989).

For determining the Native American tribes that should be contacted by the Guard or consulted with regard to sacred sites and traditional cultural properties, documents provided by the National Park Service's NAGPRA office (the acronym refers to the federal Native American Graves Protection and Repatriation Act of 1990) were consulted along with the Native American Consultation Database webpage created by the National Park Service's National Center for Cultural Resources (http://web.cast.uark.edu/other/mps/nacd/). A list was thereby accrued of tribes having legally adjudicated claims on lands within Kansas and all other tribes which have expressed a desire to be consulted with regard to cultural resources within the state (see Appendix II). These tribes' designated points of contact (POC) were contacted by mail and often by telephone, many of them on several different occasions. A combination of state, county, and local (USGS topographic) maps showing the location of each of the KSARNG facilities were provided to most of the tribes, asking them to indicate whether any sacred sites or traditional cultural properties would be affected by Guard activities in those locations. For some tribes that had only expressed interest in certain specific counties within the state, only the maps pertaining to

KSARNG facilities in those counties were sent. The cover letters that accompanied these mailings stated that if we did not hear from the tribe within sixty days, it would be assumed that the tribe considered none of the Guard properties to be sacred sites or traditional cultural properties (see sample letter, Appendix II). However, in all cases where written responses were not received within this time frame, tribal representatives were then contacted by phone.

Field Investigations

After the office research had been completed, field work began. The field investigations varied according to the kind of facility being investigated, but as an overview it is appropriate to note that all KSARNG facilities were visited and all were afforded a systematic pedestrian survey which focused on determining the archeological character of the facility as well as historic and architectural values of the built environment. Photographs (black and white photos and color slides) were taken usually showing several views of the facility or site.

When armories and office complexes were inspected, standardized written observations were made concerning their physical characteristics, and attempts were made to elicit historical data from local sources. The latter included consultations with on-duty personnel at the armory and often with retired Guardsmen having special knowledge or long-time association with the facility. Attempts were made to record names of especially knowledgable local contacts (again, these were usually retired Guardsmen associated with particular armories) that could be contacted if further research was thought necessary. When available, local armory archives were examined to determine what they might have to contribute with regard to the history of the facility, and the exhibit cases were examined with regard to historical data offered by trophies and certificates. Time was also spent in checking the archives of the local historical society or library, but the results were quite variable. For many armories, "clippings files' were not available from any of these sources, and for some armories there was simply nobody available, whether on-duty personnel or retired, that knew anything of the history of the armory or the local National Guard unit(s) prior to construction of the armory.

Three facilities with larger land areas, namely the Regional Training Area (RTA) in Saline County, the Leader Development Center (LDC) at Fort Leavenworth, and the Guard's maintenance facilities at Fort Riley, were examined not only with regard to their buildings (which were inspected in much the same manner as the armories) but rather to the archeological potential afforded by the relatively large land areas associated with these facilities. County atlases indicated that nearly two dozen historic farmsteads once occupied various locations within the RTA prior to 1942 and the establishment of various army facilities, while at the LDC six archeological sites had been reported as the result of a 1988 survey. At Fort Riley, the various Guard facilities stand on the grounds of old Camp Funston, a World War I training center. Research devoted to these areas was therefore more extensive than that given to armories, and involved consultations with the RTA Range Supervisor, cultural resource specialists at Fort Riley and Fort Leavenworth, and archeologists with the US Army Corps of Engineers, followed by pedestrian surveys to investigate and document known or suspected sites. A number of previously unrecorded archeological sites

were documented in this process. Site survey forms for those sites were provided to the Guard separately from this report.

THE CULTURAL HISTORICAL SETTING

The Kansas Army National Guard installation is located on a landscape that has a rich archeological heritage. Archeological research in Kansas has yielded evidence of prehistoric human occupation dating from around 11,000 years ago and extending up to the modern era, and certainly has the potential for yielding more such evidence. Prehistoric sites usually represent habitation areas or small workshops and more rarely occur as villages or burials. While the full extent of the state's archeological resources has yet to be determined, it is clear that the region contains materials deriving from all of the major cultural periods thus far identified in the Central Plains, which can be outlined as follows:

Paleo-Indian	circa 9,000 B.C. to 7,000 B.C.
Archaic	circa 7,000 B.C. to A.D. 1
Early Ceramic	circa A.D. 1 to A.D. 1000
Middle Ceramic	circa A.D. 1000 to A.D. 1500
Late Ceramic	circa A.D. 1500 to A.D. 1800
Historic	A.D. 1541 to present

The list consists of broad and somewhat artificial categories, and there is some temporal overlap between periods. As might be expected, more is known about the most recent inhabitants than is known about the earliest (Lees 1989; Brown and Simmons 1987; Thies 1987; Wedel 1959). The situation becomes more complicated with the institution of the reservation era and the arrival of various eastern tribes into Kansas after 1825. The National Park Service, working to facilitate the provisions of the federal Native American Graves Protections and Repatriation Act (NAGPRA), has provided maps of the various states showing those tribes with a claim to lands based on judicial decisions. In addition, there are other tribes such as the Kaw who have an extensive historical connection to Kansas even though they have no judicially established claims to the state. A list of such tribes, and their current addresses, is provided in Appendix II.

Moving beyond prehistory into the historic era, Kansas has a rich and varied record of events (Richmond 1999). In 1541, prehistory ended and the historic period began with the arrival of Coronado and his band of Spanish explorers. Journals kept by members of the expedition provide the earliest written accounts of Kansas tribes and their lifestyles, and later expeditions such as the one led by Onate in 1601 added significantly to this unique historical view of the past. The Spanish expeditions are particularly notable for their documentation of central Kansas villagers believed to be ancestral to the modern-day Wichita tribe.

The early 1700s saw French traders entering the area from the northeast, seeking to expand the fur trade. French political authority was established with the building of Fort Cavagnolle along the Missouri River, and an alliance was formed with the Kansa, or Kaw, Indians.

In 1803 the Louisiana Purchase transferred political authority to the United States. Americans began arriving soon thereafter, with the records of the Lewis and Clark Expedition

providing the first archeological observations made in the state, of Kansa village ruins along the Missouri River. In 1821 and for some 80 years thereafter, the Santa Fe Trail facilitated commercial traffic across Kansas, with the Oregon-California Trail providing the same service for Mormons, "Forty-Niners," and Oregon settlers a generation later. Beginning in 1825, the reservation era was established and Kansas became "Indian Territory." Various eastern Indian tribes--the Potowatomi, Kickapoo, and others--immigrated to Kansas reservations established as a result of the Indian removal policy, and forts such as Fort Leavenworth and Fort Scott were established to patrol the border between Euroamericans in the east and Native Americans in the west.

In 1854 Kansas became a territory, and portions of the state were opened to Euroamerican settlement. Conflict over whether Kansas would become a free state or a slave state resulted in the territory becoming known as "Bleeding Kansas." Kansas became a state in 1861, but was almost immediately embroiled in the Civil War and a bitter conflict along the border with Missouri.

Euroamerican settlement increased dramatically with the end of the Civil War, with many of the settlers being Union veterans and their families. Pressure for land resulted in an end to most of the Indian reservations, and nearly all of the tribes moved to Oklahoma after the Civil War. The postwar period saw the construction of military forts such as Fort Hays, as military authorities sought to contain Indian resistence to railroad construction and white settlement in central and western Kansas. During the 1870s the cattle business boomed and the "cowboy" era arrived as railroads were built into the state. Homesteaders arrived throughout the 1880s, taking advantage of a moister-than-usual climate to establish farms and ranches throughout the central and western parts of the state. By the 1880s, certainly by the 1890s, Kansas passed beyond the frontier stage and became a settled and "civilized" part of the United States.

The Kansas Army National Guard of today had its beginnings with the territorial militia of the pre-Civil War "Bleeding Kansas" era (Benedict 2000). Although the earliest units were made up of pro-slavery men, free-state forces soon gained control, and the state militia served with valor on the Union side during the Civil War, most notably during the battles associated with Price's Raid in 1864 (Castel 1958). Particularly important were the heroic actions of the Second Kansas Militia, known as the Shawnee County Militia, citizen-soldiers who performed a central role at the Battle of the Blue by holding back the Confederate advance at a critical moment in the battle (Rogers 1996).

After the Civil War, the state militia continued on in a somewhat unorganized fashion as authorities attempted to deal with Indian depredations and county seat "wars" (Fowles 1989). During the Spanish American War four volunteer infantry regiments were organized, with one of them, the Twentieth Kansas, seeing action in the Philippines and another, the all-black Twenty-Third Kansas, serving garrison duty in Cuba after the ending of hostilities there. In 1903 the Dick Act created the basis for the modern National Guard, formalizing state militia units by creating a National Guard of the various states as the primary reserve of the US Army. The act placed state

units under the supervision of federal authorities and established standards of training which led to the creation, in many Kansas communities, of regularly used facilities for drill and equipment storage. Although most of these were rented or "borrowed" facilities, they were the forerunners of the modern-day KSARNG physical installation.

Kansas Guardsmen served in Mexico during the Mexican Border Crisis of 1916, and then fought in France during World War One as part of the 35th Infantry Division. After the war, the Guard survived the anti-war (and therefore anti-military) atmosphere of the Twenties and Thirties mainly because it attracted enlistments by offering financial remuneration to Guardsmen (particularly important during the depression) and because the federal government helped finance the Guard. By the end of the Thirties and beginnings of the Forties, it was apparent that America might soon be embroiled in conflict, and a general strengthening of the US military began. One tangible result of this was the construction of armories in Kingman, Hiawatha, and St. Marys.

In 1940 the Kansas National Guard was federalized and subsequently saw combat in World War II. Most Kansas Guard units went to Europe, many of them as part of the 35th Infantry Division. One Kansas Guard unit, the 127th Liaison Squadron, took its observation planes to India and Burma.

After the war, a general demobilization occurred which affected the Guard every bit as much as it did the regular military establishment. Although the military perceived a need for more armories, little could be done about it due to the high costs of construction and the public's postwar disinterest in the military. As the Cold War developed and the Korean War flared, the situation changed as the military and the public began to realize the benefits and need for an expanded military, including an enhanced National Guard. After 1953, the story of the American military and the Kansas Guard was one of "continuous adaptation and growth," propelled in large part by the "superior persuasive qualities and political 'savvy'" of the Kansas Guard's best spokesman, Brigadier General Joe Nickell, who served as Adjutant General of Kansas from 1951-1972 (Fowles 1989: 136). The primary result, at least from the perspective of this report, was the construction between 1951 and 1962 of 57 armories in 54 Kansas cities, with one additional armory constructed in 1972. For obvious reasons, "Nickell's armories" is an apt term to describe these facilities. The armories were funded by state funding from local bond issues, matched by federal dollars. In many cases, the city donated the land on which the local armory was built.

In addition to the obvious patriotic impetus, cities envisioned tangible advantages from establishment of local armories. As was pointed out in speeches given by Nickell and other Guard spokesmen, cities would benefit from the Guard payroll and from use of the armory as a community center. Armories in essence become local civic centers, a situation which took on a more formal status in 1964 when the Military Board formally adopted a policy of leasing armories to various community organizations (Fowles 1989:158). Many different uses were made of the armories as the result of that policy, and they became important focal points of community life. Parenthetically, one amusing aspect of the KSHS survey involved questioning people about what "important" events may have taken place at their local armory. While most uses of the armories

were of a somewhat ordinary nature (boy scout meetings, 4-H shows, and the like), dances in particular were social events of utmost importance, and several informants smiled in remembering "important events" of that nature.

Armories also took on new importance in the 1950s as centers for Civil Defense and disaster relief, which were new roles for the Guard. The importance of the Guard in dealing with natural disasters was particularly realized in the 1951 flood, one of the most disastrous floods in Kansas history. With these factors in mind, along with the general expansion of the American military during the Cold War, the Kansas Army Guard and the Guard's physical installation grew enormously.

Various units of the Kansas Army Guard later served in Vietnam and during Operation Desert Storm. As local conditions and the Guard's needs changed, various Guard properties were relinquished and new ones built. In recent years, armories built in the 1950s in Beloit, Eureka, Fredonia, Pleasanton, and Yates Center were turned over to local governments, while new armories were built in Goodland, Olathe, Paola, and Lenexa. Undoubtedly the KSARNG installation will continue to change, as new conditions dictate adaptations in equipment, training, and personnel needs.

RESEARCH RESULTS

As an overview, it seems worthwhile to reiterate that the survey focused on three different kinds of cultural resources: archeological sites, the built environment (buildings, etc.), and Native American traditional cultural properties and sacred sites. The following discussion is divided to reflect those three major considerations before examining the KSARNG installation in greater detail according to topical and geographic groupings.

Archeological Sites

The KSHS survey resulted in the finding or relocating of twenty-five archeological sites on KSARNG lands. These are at two locations: four sites at the Leader Development Center (LDC) at Fort Leavenworth and twenty-one at the Regional Training Area (RTA) near Salina. One of the LDC sites is a prehistoric habitation site; all of the others, at both the LDC and the RTA, are historic sites associated with Euroamerican military and civilian settlement. At the LDC these sites are small "dump" sites containing trash and debris, while the RTA sites include the remains of a schoolhouse along with a number of farmsteads and wells. No archeological sites were discovered at Fort Riley, nor on the grounds of any of the armories and other such facilities. Some slight potential for the finding of historic artifacts associated with the U.S. Army's use of Fort Hays during the Indian Wars is possible on the grounds of the Hays armory, but no other such potential was interpreted for any of the other locations. A few armories located on alluvial terraces along major streamcourses have slight potential (simply due to their topographic setting) for the finding of buried prehistoric sites, but there are no known sites at those facilities and, in this researcher's opinion, little likelihood of any being found.

It should be noted, throughout this document, that determination of "archeological potential" is an assessment of possibility and probability, not a guarantee. One cannot predict the presence of unpatterned archeological (or historical) remains such as an arrowhead lost in hunting, an unplanned campsite in an unlikely location, or isolated graves. The vagaries of human behavior can confound the reasoned assessments of archeologists and historians, and excepting for such obvious situations of site destruction as quarries and landfills where extensive earthmoving has occurred, even the best archeologist cannot guarantee a lack of archeological remains in even the most unlikely of locations. At best, the archeologist can only speak of what was observed in his survey or reported in the past, and present his assessment of potential based on the archeological and historical context of the area. Fortunately, the generally patterned nature of human activities does provide the archeologist with a relatively high degree of confidence in making such assessments, despite the occasional surprize and the corresponding need for archeological caveats in cultural resource survey reports.

The Built Environment

The survey revealed that the Guard installation includes three buildings already listed on the National Register as "contributing buildings" within the Fort Leavenworth National Historic

Landmark District. The buildings were only recently acquired during the course of this survey, for use as a motor pool facility by the staff of the Leadership Development Center (LDC) located elsewhere on the Fort Leavenworth military reservation. The buildings are referred to as Bldgs 109, 113, and 114. (The Guard has only the north half of Bldg 113.) These buildings are not owned by the Guard but are leased from Fort Leavenworth authorities, who retain decision-making responsibility for cultural resources at Fort Leavenworth and should be consulted if any alterations are contemplated for these three historic properties.

The Guard installation includes one other building determined in a 1992 survey to be eligible for listing on the National Register as a contributing building within the proposed Marshall Army Airfield Historic District at Fort Riley (USACERL 1993:43-44). Generally referred to as a single building designated as Bldg 741, also known as Marshall Field Hanger, the structure is actually a building complex consisting of two aircraft hangers joined together by a small office complex. The building is not owned by the Guard but is leased from Fort Riley authorities, who retain decision-making responsibility for cultural resources at Fort Riley and should be consulted if any alterations are contemplated for the property.

The current survey identified three other buildings which appear to be potentially eligible for listing on the National Register of Historic Places and/or the Register of Historic Kansas Places--these are the Hiawatha, Kingman, and St. Marys armories which were built in the late 1930s and early 1940s. The staff of the Kansas Historic Preservation Office has provided a formal statement of concurrence with that assessment, encouraging the Guard to pursue nominations for those three historic properties (see Appendix I).

Most of the other Guard facilities are too new to qualify for the National Register--to be considered, properties must be at least fifty years old. Further, an informal enquiry of the Kansas Deputy SHPO Richard Pankratz on 12 December 1998 revealed that none of the newer armories, taken individually, are considered to have the sort of connection to Cold War history that might qualify them for exemption to the fifty-year rule. In a letter dated 14 December 1999, the SHPO formally reiterated that point, stating that none of the "Cold War" armories are considered eligible for the National Register at the present time (see Appendix I).

Despite their current lack of eligibility, however, the Deputy SHPO has provided informal opinion that as a group, the armories built in the 1950s and 1960s--essentially all of the "Nickell's armories"--might qualify for the National Register as a thematic nomination when they become fifty years old. This point gained formal expression in the SHPO's letter of 14 December 1999, in which it is recommended that a "context statement" or Multiple Property Documentation Form be completed to serve as basis for evaluation of the Cold War armories when they meet the age criteria (see Appendix I). There are forty-six of these buildings (Table I). As a group, these armories were found to have several notable characteristics that prompt their consideration for a thematic nomination to the National Register. They have standardized physical features that make them stand out as distinctive elements of our built environment, they are physical manifestations of America's Cold War effort and are directly associated with General Nickell, and they had

important roles as local civic centers. Although the Cold War armories are not eligible for the National Register at the present time, they can be regarded as viable candidates for a thematic nomination in the future. By way of explanation, it is appropriate to point out here the likely effect of such a nomination would be the awarding of National Register status to the least altered and most "typically representative" of these structures. Since several of the armories have been significantly altered, not all them may be specifically deserving of National Register status, and perhaps only a dozen or more selected examples may actually be nominated to the Register by means of a thematic nomination.

Traditional Cultural Properties and Sacred Sites

Consultation with Native American tribes produced no reports of traditional cultural properties and sacred sites located on or associated with any of the various elements of the KSARNG installation. All of the tribes listed in Appendix II were contacted by mail and telephone, many of them on several occasions. None of the tribes indicated any specific concerns about any of the KSARNG properties, although several (see correspondence, Appendix II) noted a generalized possibility of burial sites in selected portions of the state and requested to be consulted under certain conditions (these requests are described in more detail below, and in the "Management Recommendations" section of this report). Most tribes did not provide a written response, although one of that group, the Northern Cheyenne, by means of a telephone call from Mark Wandering Medicine to the author on 29 September 1999, stated that it was their desire to defer to the Southern Cheyenne whose letter of response can be found in Appendix II. Similarly, the Arapaho (of the combined Cheyenne and Arapaho Tribes of Oklahoma) sent a letter stating that due to the loss of their representative, the Guard request would be forwarded to the Southern Cheyenne representative. Several tribes, including the Sac and Fox of Missouri, the Sac and Fox of Oklahoma, the Sac and Fox of the Mississippi in Iowa, responded verbally through phone calls, stating that they did not have any sacred sites or traditional cultural properties associated with the Guard properties. Several other tribes, such as the Osage and the Wichita, were provided with follow-up letters, a second mailing of maps, and were contacted by phone on several other occasions, but have not produced a response.

As noted, several tribes stated that they wished to be contacted under certain conditions. These are detailed below.

> The Kaw Nation wants to be notified immediately if any artifacts or culturally affiliated materials are uncovered in Morris, Geary, Riley, Pottawatomie or Doniphan counties and if any finds are made in the north half of Kansas.
>
> The Kickapoo Tribe of Kansas wish to be notified if any inadvertant discoveries are made in Atchison, Brown, Doniphan, or Leavenworth counties.
>
> The Iowa Tribe of Oklahoma requests that they be considered an interested party and be notified of any proposed construction projects or ground disturbance in Doniphan,

Wyandotte, Atchison, or Leavenworth counties.

The Cheyenne and Arapho Tribes of Oklahoma wish to be contacted if any human remains, burial goods, or burial grounds are discovered anywhere in Kansas.

The Prairie Band Potawatomi Nation wants to be contacted if any inadvertant discoveries are made anywhere in the state.

Armories and OMS Shops

There are 54 "regular" armories in the KSARNG installation, not including the Aviation Armory at Salina which serves a different and more specialized function than the other armories. Many of the armories also serve as the location for Organizational Maintenance Shops (known as "OMS shops") which are simply maintenance shops often of oversize garage-style construction. One OMS shop (OMS#3, in Wichita) is larger than the other shops and stands alone as an independent facility. Appendix III contains individual descriptions of each of these facilities except for the Aviation Armory which is discussed in the section of this report dealing with the Salina Airport Facilities.

Historical information about the armories varied greatly. A few armories have maintained clippings files and photo albums, but many have no archives of any sort, and the extant archives are often unorganized and lack identifying labels or dates. It was not uncommon to find the archives lanquishing in the backs of lowermost filing cabinet drawers, or on a back shelf in the supply room. Moreover, most extant archives have not been added to in recent years. Several Guard personnel attributed this situation to a directive received a few years ago to deemphasize the time spent on maintenance of such histories. Adding to this problem is the fact that many local libraries and historical societies do not maintain "clippings files" on the local armory. Because of these factors, historical data was often totally lacking with regard to armory construction dates, previous armory locations, previous unit designations, and the like. One saving grace for this situation proved to be the trophies and certificates residing in foyer trophy cases--in more than one case these items provided all that could be learned locally about the history of the armory and the units associated with it. In some cases, however, even this data was lacking.

No archeological remains were found at any of the armory grounds. Examination of the topography and historical context suggests that there is only minimal potential (at best) for any archeological remains to be found at any of the armories. Most of the armories occupy upland locations, areas of fill dirt and/or old dumps, or have been heavily altered by earthmoving and/or graveling, and therefore have no potential, or little or no potential, for the finding of archeological remains. There is some potential for the finding of isolated historic artifacts just below the ground surface at the Hays armory, as detailed below, and there is a remote possibility of deeply buried archeological remains at seven armories including Hays along with Abilene, Clay Center, Junction City, Manhattan, Salina, and Winfield, all of which are located on recent (Holocene-aged) alluvium. This potential for buried prehistoric remains holds true for most situations involving

recent alluvium, however, and should not be taken as proof of any great likelihood of remains being present at those seven armories. No archeological remains of any sort were found on any of the armory grounds during the KSHS survey, nor have any such remains been reported from them earlier. Judging from the evidence at hand, the armory grounds contain no sites and have only minimal archeological potential at best, and therefore do not possess any demonstrable archeological significance.

For those armories which do have some slight potential, another factor which must be taken into account is the relatively small amount of undisturbed soil on the armory grounds. Most armory grounds are taken up by the armory building (and occasionally other buildings as well), parking lots, and vehicle storage areas which have been graded and graveled. In most cases there is very little undisturbed soil, and if any significant archeological sites had been present they would have been noticed (if not destroyed) during construction. Based on these considerations, it is highly unlikely that any of the armories have any archeological potential at all. Appendix III lists the archeological potential of each armory according to the following levels: none, little to none, and low to moderate. If the armory occupies a thoroughly disturbed upland soil setting or sandy alluvium subject to alluvial reworking, or has been built on substantial amounts of fill, the archeological potential is listed as "none." If the armory occupies an otherwise undisturbed upland setting for which no deeply buried archeological deposits can be expected, but within which isolated artifacts or archeological features could conceivably be present even though the topographic setting is not promising with regard to prehistoric settlement, the archeological potential is listed as "little or none." If the armory occupies Holocene-aged silty or loamy alluvium in which deeply buried prehistoric materials are possible (even if the topographic situation is not particularly promising), the archeological potential is listed as "low to moderate." No higher-level archeological potential was interpreted for the armories.

As noted above, there is one possible exception to this apparent dearth of archeological potential, and that is at Hays. The Hays armory is located just north of Big Creek, where artifacts such as pistols and "swords" are reported to have been found by visitors to the local park. Unfortunately, the evidence for these finds is largely anecdotal, but the various accounts do have a certain degree of credibility because of the town's history. The Big Creek area was reportedly used as a sort of early-day park by Fort Hays soldiers seeking respite from the saloons of Hays City which were located only a quarter mile or so to the north, and apparently the soldiers' conditions were such as to result in the occasional loss of equipment. It is therefore possible that someday such artifacts may be found on the grounds of the Hays armory. These would be isolated finds, however, lacking in any other archeological context, and they would be unpredictable in their location.

Cultural resources of another kind can be found at several armories in the form of monuments and/or cannon or other weapons which serve as quasi-monumental "gate guards." Several armories also have artwork in the form of portraits depicting former commanders, and at least two (Kingman and Newton) have a "time capsule" incorporated into the walls of the structure. These sorts of cultural resources are described in the reports on the individual armories contained

in Appendix III, and are summarized in Appendix IV, which also contains a list of the nine "memorial armories" named to honor specific individuals.

With regard to architectural resources and the "built environment," three armories--at Hiawatha, Kingman, and St. Marys--are over fifty years old and potentially eligible for inclusion on the National Register under Criterion C which refers to architectural significance (see Appendix I). As directed by KSARNG staff, a Preliminary Site Information Questionaire (PSIQ) was submitted to the Kansas Historic Preservation Office for each of these three armories, asking that these properties be evaluated for their eligibility to the National Register. In letters dated 10 November 1999 and 27 January 2000 (see correspondence, Appendix I), Martha Hagedorn-Krass of the Historic Preservation Office indicated that all three buildings appear to be significant cultural resources that should be preserved. Further, the Guard was encouraged to pursue a National Register nomination for the Hiawatha and St. Marys armories. (Permission for nomination should be sought from the City of St. Marys, however, as they are the actual owners of the St. Marys armory.) With regard to the Kingman armory, a nomination to the Register of Historic Kansas Places was encouraged. The next step in the nomination process is for nomination forms and supporting documentation to be submitted to the Kansas Historic Sites Board of Review. If the nominations are approved by the Board, the Kingman armory will be listed on the Register of Historic Kansas Places and the Board's recommendation for the awarding of National Register status to the Hiawatha and St. Marys armories will be sent to the National Park Service for final approval by the Secretary of the Interior and the Keeper of the National Register.

Upon being informed of these facts, the Guard directed the Society to proceed with obtaining the documentation necessary for these nominations (personal communication from Patti Haines-Lieber to the author, 12 January 2000). Because the documentation research can be quite extensive and requires expertise not readily available with current Society staff, the Society is proceeding to have that work done by means of a subcontract with funding to be supplied by moneys available under the current contract.

The remainder of the armories can be divided into two groups. First, there are five armories of quite recent construction, at Goodland (constructed 1988-89), Lenexa (1990), Olathe (1991), Paola (1991), and Great Bend (1994-95). Second, there are the Cold War armories constructed under the direction of General Nickell in the 1950s and early 1960s with one late construction in 1972-73. In addition to the independent OMS#3, there are forty-six Cold War armories in the KSARNG installation (Table I). None of these facilities are of sufficient age to be considered eligible for listing on the National Register, and as noted above, none of them are considered to have Cold War significance that would constitute an exception to the fifty-year rule for listing on the National Register.

When they meet the age criteria, however, the Cold War armories might qualify for listing. The Kansas Deputy SHPO has suggested (personal communication to author, 12 December 1999) that collectively the Cold War armories might be regarded as significant and thus eligible for the National Register by means of a thematic nomination. Research resulting in a "context statement"

dealing with Kansas armories in general, and Nickell's armories specifically, was suggested (see Appendix I, letter of 14 December 1999) so that this topic can be evaluated by the Historic Preservation Office. At the direction of the Guard (personal communication from Patti-Haines Lieber to the author, 12 January 2000), the Society is proceeding to have a context statement (more formally known as a National Register "Multiple Property Documentation Form") written as part of the same subcontract designed to provide nominations for the Hiawatha, Kingman, and St. Marys armories.

Fort Riley Properties

The KSARNG installation at Fort Riley consists of several buildings and storage yards that serve mainly for equipment storage and maintenance, retrofitting of tanks and similar military vehicles, and for the housing of Guard personnel performing those or other duties. One of these buildings, Bldg 741, also known as Marshall Field Hanger, is located at Marshall Airfield (see Figures 1 and 2) and has been determined eligible for listing on the National Register as a "contributing building" within the proposed "Marshall Army Airfield Historic District" (USACERL 1993:38-47). All the other Guard facilities are located in the old Camp Funston section of the Fort Riley military reservation (see Figures 3, 4, and 5). Whether at Marshall Airfield or old Camp Funston, all of these buildings are leased from Fort Riley. The responsibility for dealing with cultural resources on the reservation is vested in the Cultural Resources Division, Directorate of Environment and Safety, currently in Building 407 at 407 Pershing Court, Fort Riley KS 66442, and any decisions pertaining to cultural resources at Fort Riley should be made by the staff of that division. Richard Shields is the current director of the Cultural Resources Divison.

According to Shields, and as became apparent during our tour of the KSARNG installation at Fort Riley, there is no evidence of any significant cultural resources and virtually no likelihood of any significant buried archeological remains associated with the KSARNG installation. Archeological resources in particular have received careful consideration by the staff of the Cultural Resources Divison. Marshall Airfield was extensively graded for use as an airfield, and the Camp Funston area was greatly impacted by the development and later destruction of Camp Funston which served as a U.S. Army training base in World War I. It is considered highly unlikely that any prehistoric remains would have survived the earthmoving that occurred at either of these locations. With regard to archeological remains deriving from Camp Funston itself, after World War I all of those structures including foundations, waterlines, and other subsurface constructions were systematically razed and/or removed by excavation and earthmoving, and nothing from that era is believed to be present today.

Some of the KSARNG buildings that were present at the time this study began have since been demolished--this includes one classroom building (Bldg 1985) and the former Retrograde Europe (RETROEUR) headquarters building (Bldg 1918). Of the remaining structures, the Mobilization and Training Equipment Site (MATES) building (Bldg 1460) is of quite recent construction. Other buildings in the former RETROEUR (now the General Support or GS

Maintenance Site) complex (Bldgs 1693, 1633, and XXX) are not only recent but are of a temporary nature. None of these buildings fit the criteria for National Register significance.

The remaining buildings are older two-story wooden buildings built during World War II, but they have been so extensively rehabilitated and reclad with vinyl or metal siding and asphalt shingles that they cannot be considered as eligible for listing on the National Register. These include the KSARNG headquarters building (Bldg 1970) and the MATES billets (Bldg 1987). In addition to these observations, information received from Shields (personal communication of 20 November 1998) indicates that by virtue of a Nationwide Memorandum of Agreement (NMOA) between the National Council of State Historic Preservation Officers (NCSHPO), the Advisory Council for Historic Preservation (ACHP) and others, World War II buildings are not considered eligible for the National Register unless they are associated with specific historic events or individuals.

In summary, the KSARNG installation at Fort Riley includes one building--Bldg 741 at old Marshall Airfield--which has been determined eligible for listing on the National Register and is therefore considered to be a historic property. Survey of the remainder of the KSARNG installation at Fort Riley revealed no evidence of any significant cultural resources of either an archeological or historical nature, and virtually no potential for the finding of such remains. With the exception of Bldg 741, there are no buildings or archeological sites that fit the criteria for listing on the National Register.

Fort Leavenworth Properties

The KSARNG installation at Fort Leavenworth consists of two separate areas housing the Leadership Training Area (LDC) and its motor pool. Both properties are located on the Fort Leavenworth military reservation and are leased from Fort Leavenworth. Responsibilities for cultural resources on the reservation are vested in the Directorate of Public Works, currently at 820 McClellan Avenue, Fort Leavenworth 66027-1360 (913-684-8940), and decisions pertaining to cultural resources management should be directed to the staff of that organization. Tim Hanna is the Directorate's present point of contact for cultural resources, although the Kansas City District U.S. Army Corps of Engineers (USACE) is usually consulted on matters pertaining to archeology.

The Guard's motor pool property at Fort Leavenworth (see Figure 6) is a relatively small area of land located towards the north end of the main post area. The property includes three buildings, designated as Bldgs 109, 113 (only the north half is used by the Guard) and 114. They are wood frame structures surrounded by parking lots or storage yards paved with asphalt or gravel. These buildings are within the bounds of an area designated as the Fort Leavenworth National Historic Landmark District. They are, in other words, historic properties, listed as "contributing buildings" on the National Register. Any alterations to these buildings or their grounds must be cleared through the Fort Leavenworth Directorate of Public Works.

The Guard's LDC complex occupies some forty acres of land located on the southeastern corner of the Fort Leavenworth military reservation (see Figure 7). The LDC consists of two large and interconnected office buildings. The north building is known as the Leader Development Center, while the south building houses the 35th Division Headquarters. Both buildings are used for training, however, and generally the entire property is referred to as the LDC. The buildings are flanked by parking lots and, to the east, storage yards and several small outbuildings. A sizable amount of unused land lies to the west and north. Fences currently demarcate the eastern and most of the western and southwestern boundaries of the Guard property, while Corral Creek serves as the northern boundary. The buildings that make up the LDC complex are of relatively new construction and therefore can not be considered eligible for the National Register at this time. The 35th Division Headquarters building was constructed in the 1980s for use as the 35th Division training center, and the Leadership Development Center building was completed in 1998, at which time many if not all of the subsidiary buildings and parking lots were constructed or expanded. Unfortunately, due to the recency of the construction there is no single map that accurately shows the full extent of the installation with all the modern constructions and topography.

In 1988 the LDC was the subject of a professional archeological investigation specifically aimed at determining the presence or absence of prehistoric and historic archeological sites on this and adjacent portions of the Fort Leavenworth reservation. The investigation was carried out in 1988 by American Resources Group, Inc., working under a contract with the Kansas City District, U.S. Army Corps of Engineers (USACE). The work resulted in a report (McNerney et al. 1989) which described the finding of six archeological sites (14LV104 through 109) on land leased by the Guard. The sites' locations were indicated on a USGS map which contained no indication of the modern built environment (see Figure 8). One goal of the KSHS survey was to compile better maps of the six sites, but unfortunately, as noted above, there still is no single map that shows the modern environment with complete accuracy. It was therefore necessary to use several different maps, some of them being outdated maps showing proposed rather than as-finally-constructed buildings and roads. As one result of the KSHS investigation, copies of these maps have been presented to the Guard and placed in appropriate site files contained within the Master Site File maintained by the Historical Society. Sections of these maps, showing individual site locations, are presented within this report in site-numerical order (Figures 9 through 14).

To summarize, the six sites found in the 1988 survey include one prehistoric site (14LV109) and five historic sites (14LV104 through 14LV108). Site 14LV109 was described as a "limited activity site" evidenced by a small amount of lithic debris exposed by bulldozing in a small area on a "ridge spur" adjacent to the floodplain of the creek. An Archaic cultural affiliation was interpreted. Subsurface testing--eleven shovel tests were excavated--produced no artifacts or archeological features, leading the investigators to conclude that the site was "largely destroyed by construction activity." (McNerney et al. 1989:99). According to their report the site did not appear to be eligible for the National Register, and clearance was recommended for projects located in its vicinity (McNerney et al. 1989: 322). No evidence of the site was found when the site was inspected on two separate occasions in 1998 and 1999, and its location as shown in

Figure 14 is not certain.

Similar conclusions were offered by the 1988 investigators for 14LV105. The site was described as being the remains of a collapsed cement water trough on an earlier limestone foundation or cistern; functionally, it probably served as a water trough for horses and other livestock. The investigators felt that the site did not appear to be eligible for the National Register, and clearance was recommended for projects located in its vicinity (McNerney et al 1989: 86-87, 322). No evidence of this site was found when the area was resurveyed in 1998, and much of the apparent site locale had been graded flat by previous construction activities. The site has apparently been destroyed, and its interpreted former location as shown in Figure 10 is not certain.

The 1988 investigation resulted in further work--specifically test excavations--being recommended for 14LV104, 14LV106, 14LV107, and 14LV108. Each of these sites was described as a "dump/discard location" consisting of historic debris dumped or discarded from military and/or civilian sources associated with the nineteenth and early twentieth century period (McNerney et al 1989:315, 317). All four sites were defined as being potentially National Register eligible (McNerney et al 1989:320). In addition to these specific recommendations, no further investigations were recommended for other areas of the KSARNG property which had not yielded sites, and it was recommended that Army projects proposed for those areas be given clearance to proceed as planned.

Site 14LV104 is located in and along the sides of a swale and/or ravine located to the west and north of the LDC (see Figure 9). During the 1988 investigation the site yielded artifacts thought to date as early as the late 1840s, and it is therefore potentially the most important of the LDC sites due to its apparent antiquity. Artifacts of later date were also found, suggesting long-time use as a dump area. Since the site was located close to the then-proposed LDC construction area, it was recommended that the site be flagged prior to construction so that it might be avoided (McNerney et al 1989:320). The 1998/1999 surveys of this area revealed that upslope of the site, several posts had been set in place and linked by pierced steel planking and similar materials, forming a barrier or short fence. It is thought likely that this construction constitutes a tangible response to the recommendation for flagging of the site. Unfortunately, no records seem to be available to explain the purpose of the barrier, according to Dr. Robert Ziegler, an archeologist with the Kansas City District USACE, and Tim Hanna of the Fort Leavenworth Directorate of Public Works (personal communications of 24 September 1998).

Site 14LV106 is not marked by any such barrier but its location is easily found due to landmarks described in the report and other notes derived from the 1988 investigation. The site is located at the southwestern portion of the Guard property, just north of a fenceline where the state port-of-entry once stood, and west of the new entry road (see Figure 11). The site occupies the crest of a ridge currently covered with grass and small shrubby vegetation. The site does not appear to have been disturbed by the construction of the LDC and attendant facilities.

Site 14LV107 was easily relocated during the 1998/1999 surveys, as the site was partially damaged by storage yard construction which exposed archeological materials by cutting a vertical cutbank into the ridge on which the site is located. The site is just east of the southeast section of the storage yard which lies east of the 35th Division Headquarters building (see Figure 12). A small pathway lies along the outside of the storage yard, and the site lies just east of it on a forested ridge. As of this writing, entry into the site area from the south (i.e., from the parking lot) will soon be restricted by a chainlink fence and appropriate signage scheduled for construction in the near future. Archeologically, the site consists of a deposit of debris and dark mottled soil extending from the surface down to a depth of 1.5 m below surface. The deposit was 14-15 m long and contained fragments of brick, stoneware, glass, coal "clinkers," and metal. The results of the 1998 investigation indicate that the site has good potential for further archeological investigation, and it should be considered potentially eligible for listing on the National Register. We recommend that the site be avoided by any future ground disturbing activities. If this is not possible, test excavations should be carried out to determine National Register eligibility and mitigation needs, much as was stated in the 1989 report.

Site 14LV108 could not be found in the 1998/1999 surveys, as it appears to have been destroyed by construction of the new entry road and/or the adjacent parking lot at the south end of the KSARNG property (see Figure 13). As noted above, testing had been recommended for this site as a result of the 1988 investigation. No record of any such work is known to Fort Leavenworth or Corps of Engineers authorities, according to Tim Hanna and Dr. Robert Ziegler (personal communications of 24 September 1998).

In summary, the results of the 1988 and 1998/1999 investigations indicate that the KSARNG installation at Fort Leavenworth contains three National Register buildings (Bldgs 109, 113, and 114), and three known archeological sites (14LV104, 106, and 107) that previous investigators have described as being potentially eligible for listing on the National Register of Historic Places. Three other sites were documented on the LDC grounds, but two of them have been destroyed and the other has been described (in the 1989 report on the LDC area) as not being eligible for the National Register. Although it is a moot point with regard to the two sites that were destroyed, the 1989 report recommended that any projects planned for these areas be cleared to proceed. Similarly, it was recommended in that report that all other areas of the LDC [where sites were not found] be considered to have been adequately investigated and determined to be lacking in archeological resources, and that any projects planned for those areas be cleared to proceed. The 1998/1999 investigations encountered no evidence that would prompt disagreement with these interpretations and recommendations. Further, it should be noted that the conclusions and recommendations of the 1988 investigation of the LDC area, as spelled out in the draft version of the report, were approved by the SHPO in a letter dated 21 December 1988 (see Appendix I). The SHPO's concurrence effectively clears the bulk of the LDC grounds for development, while formally emphasizing the need for further testing (and thus, the potential for National Register eligibility) at 14LV104, 14LV106, and 14LV107.

Topeka Headquarters Properties

The KSARNG headquarters installation in Topeka consists of a complex of buildings located on state-owned land on the southeast corner of 27th Street and Topeka Avenue, extending east to Kansas Avenue (Figures 15, 16, and 17). Survey revealed that virtually all of this land has been modified in some manner by construction that has created office and maintenance facilities, roads and parking lots, ball fields, and various berms and drainageways to facilitate movement of rain water downslope to the east. Limestone bedrock is close to the surface especially on the western edge of the property. Due to the amount of disturbance and the lack of soil, as well as the upland nature of the property, it is extremely unlikely that prehistoric sites are (or ever were) present.

None of the buildings are old enough to qualify for the National Register, and none are remarkable in terms of architecture or history with the possible exception of Nickell Memorial Armory, which is one of the largest of the state's Cold War armories. Immediately south of the armory, on Topeka Boulevard, is the relatively new State Defense Building. To its south is an older building, OMS#9. Another such building, OMS#6, located northeast of Nickell Armory, now serves simply as a storage annex. Other notable buildings include the recently constructed U.S. Property and Fiscal Office (USP&FO, Bldg 103) located on the southeast corner of the complex. Several older office, maintenance, and warehouse facilities are located to the north including the USP&FO warehouse (Bldg 202), the Combined Support Maintenance Shop (CSMS, Bldg 300), the Facilities Engineering office building (Bldg 101), and many smaller buildings and conex containers used as workshops and storage sheds. Many of the "named" buildings are cinder block with brick veneer, while most of the others are metal buildings.

In summary, survey revealed no significant cultural resources at the KSARNG Topeka Headquarters. There are no known archeological sites and virtually no likelihood of any sites being present. None of the buildings are currently old enough to be considered for listing on the National Register; and none of them (with the possible exception of Nickell Armory, as part of a thematic nomination) appear to have the kind of architectural or cultural significance that would qualify them for listing on the National Register.

Forbes Field Properties

The KSARNG installation at Forbes Field at the south edge of Topeka (Figure 18) occupies land originally developed as Topeka Army Airfield for use by the U.S. Army Air Corps in heavy bombardment training during World War II. That development and later uses of the airfield were the subject of a recent Topeka newspaper article (Smith 1999). After the war the base went through a series of deactivations and reactivations until being returned to operation in 1951 as an Air Force base. During a brief reactivation in 1948-49 the base was named Forbes Air Force base in honor of Major Daniel H. Forbes, Jr., a native of the Topeka area who was killed (in June 1948) while testing the XB-49 "flying wing."(Mechem 1959a:142-145). In 1974 the base was deactivated for apparently the final time, although the Department of Defense (DOD) maintains ownership of several facilities including some that are used by the Kansas Army National Guard.

Now known as Forbes Field, the former air force base is currrently operated by the city of

Topeka through the Metropolitan Topeka Airport Authority (MTAA). According to MTAA Director Dale Stremming (personal communication of 22 February 1999), the MTAA has a joint use agreement with DOD for maintenance of facilities used by the Kansas Air Guard and Army Guard. The Army Guard leases one of its buildings (Bldg 605) from the MTAA, and because of this arrangement the MTAA has ultimate responsibility for cultural resources on that property. The MTAA director, whose offices are located at Forbes Field in Bldg 620, should be contacted with regard to cultural resources concerns. All of the Army Guard's other facilities (Bldgs 636, 680, 681, 682, and 684) are owned by DOD, and cultural resources concerns should be directed to the appropriate DOD office.

The KSARNG installation at Forbes Field consists of three office or administrative buildings and three aircraft hangers, located towards the south end of the airfield (see Figure 18). These facilities house three Guard units. The 1st Battalion of the 108th Aviation Regiment occupies Bldg 605, which is a two-story cinder-block building leased from the MTAA. The Army Aviation Support Facility No. 1 (AASF#1) occupied a several-segmented cinder-block office building (Bldg 636) and uses three nearby metal hangers (Bldgs 680, 681, and 682) for housing and maintaining their aircraft. At the very south end of Forbes Field, the Guard's Counter Drug Operations unit occupies a two-story cinder-block building (Bldg 684). All of these buildings belong to DOD and were constructed beginning in the late 1950s for use by the U.S. Air Force and/or the Kansas Air National Guard. The Army Guard moved to Forbes in the late 1970s. None of the buildings exhibit any notable architectural characteristics and no important events or individuals are known to be associated with them.

With regard to archeological considerations, there are no recorded sites at Forbes Field, and no evidence of any sites was encountered in the survey. Prehistoric occupation of this area is unlikely due to the unpromising upland topographic setting. Any sites once present, whether prehistoric or historic, are almost certain to have been destroyed by construction and operation of the airfield.

In summary, survey of the KSARNG installation at Forbes Field revealed no evidence of any properties that fit the criteria for listing on the National Register.

Salina Airport Properties

The KSARNG installation at the Salina Airport at the southwestern edge of Salina (Figures 19 and 20) occupies land originally developed as Smoky Hill Army Airfield and used primarily as a B-29 training base by the U.S. Army Air Corps in World War II. After a change in command structure in 1946 the base became Smoky Hill Air Force Base, and in 1957 it was renamed Schilling Air Force Base in honor of David Schilling, a famous World War II fighter pilot born and raised in Kansas (Mechem 1959b:347-349). The base was deactivated in 1965. Now known as the Salina Municipal Airport, the airfield and its adjacent facilities--referred to as the Airport Industrial Park--are operated by the City of Salina through the Salina Airport Authority (SAA). The KSARNG leases its facilities from the SAA, and because of this arrangement the SAA has

ultimate responsibility for cultural resources. The SAA director, whose office is located at 3237 Arnold Avenue in Salina, should be contacted with regard to cultural resources concerns.

The KSARNG installation at the Salina Airport is collectively referred to as the Regional Training Center, or RTC, a designation which also includes the Regional Training Area which is located some distance away in rural Saline County and is discussed separately in this report. The airport facilities fall into two main categories: the Army Aviation Support Facility No. 2 (AASF#2) consisting of an armory and adjacent hanger, and various buildings used for training activities as part of the Kansas Regional Training Institute (RTI) and related functions. Several vehicle storage yards are also present, as are some unused buildings.

The AASF#2 is located at 2910 Arnold Road (see Figures 19 and 20) and houses elements of the 108th Aviation and the 114th Aviation Regiments. The KSARNG aviation involvement began in 1985 with their use of a modern hanger facility constructed a few years earlier for use by a private firm. In 1990, a new armory capable of housing small aircraft was built to the east of the hanger, on Arnold Road. The armory is not used as a community center in the same manner as the state's other armories due to its specialized nature and the obvious danger afforded by the presence of aircraft. Neither the armory nor the hanger can be considered eligible for the National Register due to the recency of their construction.

The RTC consists of a variety of buildings, most of recent construction. The main headquarters facility is Nickell Hall, a large several-storied building complex completed in 1996 and located at 2930 Scanlon Avenue. Other new buildings include Eckert Hall at 2850 Scanlon Avenue, which houses the 235th regimental headquarters and the Regional Training Institute (RTI); the troop billets or open-bay barracks (Bldg 465) at 1903 Sutherland Road; and Bldg 460 at 1901 Sutherland Road, which is used as a training center and battalion headquarters. All of these buildings were constructed in 1997. Only slightly older is the Regional Training Site Maintenance (RTSM) building at 2750 Scanlon Avenue, constructed in 1992. None of these buildings can be considered eligible for the National Register due to the recency of their construction.

Several older buildings are also present. These include the former home of the Kansas Military Academy (Bldg 219), which is a two-story cinder-block building located at 3010 Arnold Avenue; the Markeley Building, a large metal building located at 2931 Arnold Avenue; and the Learning Center (Bldg 265), a one-story wood frame building located across Scanlon Avenue to the east of Nickell Hall. Information on the dates of construction for these buildings was obtained from SAA Operations Director Don Kneubuhle (personal communication of 19 February 1999). According to Kneubuhle the former Kansas Military Academy building was constructed in 1955 and the Markeley Building some time in the 1970s. Portions of the Learning Center were constructed in 1942 but the building was greatly altered in a 1955 expansion and has been further altered more recently. None of these buildings can be considered to fit the criteria for inclusion on the National Register, in part because of the recency of their construction or their high degree of alteration, but also because they are lacking in architectural and historical significance.

With regard to archeological considerations, there are no recorded sites at the Salina Airport, and no archeological evidence of any kind was encountered in the survey. There is some slight possibility of prehistoric occupation due to the fact that the airport sits on Holocene-aged alluvium (part of the Dry Creek drainage), but the topographic setting is not promising, and any near-surface sites (whether prehistoric or historic) that may have once been present are almost certain to have been destroyed by the construction and operation of the airfield. Deeply buried sites are possible, however, due to the alluvial setting.

In summary, survey of the KSARNG installation at the Salina Airport produced no evidence of any properties that fit the criteria for listing on the National Register.

Regional Training Area Properties

The Guard's Regional Training Area, or RTA, is located southwest of Salina in rural Saline County (Figure 21). Administratively, it is part of the Regional Training Center (RTC) headquartered at Nickell Hall at the Salina Airport. The RTA lies within and along the eastern edge of the Smoky Hill Air-to Ground Gunnery Range (commonly referred to as the Smoky Hill Bombing Range) which is operated by the Kansas Air National Guard. The RTA is leased from the Air Guard which retains all operational and maintenance authority, including ultimate responsibility for cultural resources. According to KSARNG staff at the Regional Training Center in Salina, the Smoky Hill Gunnery Range is federal property, ultimately controlled by the United States Air Force with active control vested in the Kansas Air National Guard.

Prior to World War II, the RTA was used for farming and ranching, but with the onset of war it became part of a much larger area of land taken by the government and transformed into an Army base known as Camp Phillips. The camp served mainly as a training area for the U.S. Army, with one section set aside for use as an internment camp for German and Italian prisoners of war. Along with Camp Concordia (near Concordia, Kansas), Camp Phillips was one of the largest POW compounds in America when it was created in 1943, although Camp Phillips was smaller and shorter lived than Camp Corcordia (O'Brien, Isern, and Lumley 1984:183-184). Many of the prisoners worked as farm labor in the farms around Camp Phillips; however, none are known to have had any direct involvement with the land now part of the RTA. Maps viewed by the Range Supervisor indicated that the RTA was used mainly as a gunnery range during the war (personal communication from Mark Suddock, 3 February 1999).

Currently the Army Guard has several firing ranges and service buildings in the northeastern portion of the property, and a small area in the southwestern corner has several old armored personnel carriers which serve as the focus of vehicle recovery training. The remainder of the RTA is used as a Land Navigation Course. Native grass covers most of the area, with woody vegetation clustered around former farmsteads and lining the few drainageways which are nothing more than upland draws. There are no named creeks, and alluvium is confined to narrow and presumably thin flood plains along upland drainageways, according the the Saline County soil survey report (Palmer et al.:1992). It is decidedly an upland environment, at some distance from

an active streamcourse and lacking any notable springs.

During the Phase I office review, it became apparent that the RTA had little or no likelihood of prehistoric occupation, as the area consists of uplands far from any dependable water sources or prominent landmarks. Further examination of the soils and topography indicated no likelihood for prehistoric quarries or burial mound areas. However, our records indicated that there were several historic farmsteads and one school that had been abandoned when the area was taken over by the federal government in World War II.

Based on these considerations, a pedestrian survey of selected locations was deemed necessary to document the archeological characteristics and National Register significance of the historic farmsteads and school indicated on the earliest-available county atlases of 1884, 1903, and 1920. At the same time, the occasion was taken to search for prehistoric evidence exposed in ares of "open" ground--vehicle trails, plowed fire breaks, etc. A set of aerial photographs dating from 1938 was obtained from the Kansas Department of Transportation and used to pinpoint the farmstead locations. Armed with this information, a pedestrian survey was then carried out on 10 December and 17 December 1998, and again on 3 February 1999. Range Supervisor Mark Suddock was present on the initial tour and provided information on what he knew of each location. In all but two cases, Suddock had long been aware of the old farmsteads because of his need to flag wells, cellars, and such features that might have endangered participants in Land Navigation Course classes. All of these areas have been walked over many times by Guard personnel during summer camps and classes, and during the spring when the pasture is burned.

Suddock provided information on one "new" location (14SA308, a depression believed to be a capped well) that had not been indicated on the atlases. Perhaps not surprisingly, he knew nothing of four farmsteads that had once been present (according to the atlases) in locations which revealed no archeological remains in the survey. Suddock also corrected the map (of the RTA boundaries) that had been provided by the Topeka KSARNG office, by noting that the northwest quarter of Section 16 was not part of the RTA.

During the survey, 25 different locations were specifically targeted and visited (Figure 22). Nineteen of these locations had some form of archeological evidence, resulting in their designation as archeological sites numbered 14SA307 through 14SA325 (Figure 23). Copies of site survey recordation forms for these sites have been presented to the Guard separately from this report. One site--14SA320--marks the location of a schoolhouse, while all the other sites represent farmsteads or wells associated with farm/ranch operations. No prehistoric remains were found during the course of the survey.

Most of the farmsteads were easily spotted due to their association with trees, as the natural vegetation for this region is pasture except along the bottoms of streamcourses. Cedars and elms were one obvious indicator of historic occupation, as were lilacs. Locust trees and Hedge, or Osage Orange, were also common especially along old fencelines.

Surprisingly, no archeological evidence was found of four historically documented farmsteads. One of them had obviously been obliterated by construction of the M-16 firing range; the remainder may have been very minor occupations leaving no discernible archeological remains, or the remains may have been removed to facilitate farming or ranching activities. These locations are indicated by the following numbers in Figure 22: 2, 9, 16, and 18. The following observations were made at those locations:

2: Pasture; no sign of any disturbance. This area is burned off each year and according to Suddock nothing of an archeological nature has ever been noticed.
9: (Same)
16: (Same) This location seems like a somewhat unlikely spot for a farmstead: although it is on a slight rise, it is in an otherwise lowlying area between two shallow drainages and would have been more likely for a farm building rather than a residence.
18: Obliterated by firing range.

In addition to the KSHS survey, another survey of the RTA was conducted in 1999 by archeologists from DuVall and Associates, Inc., a private archeological contractor hired as part of a similar archeological study carried out for the Kansas Air National Guard. According to information provided by the crew leader, Chris Hazel (personal communication with the author, 5 January 2000), the DuVall survey was not directed at the documentation of historic sites but was meant to be a "ten percent survey" designed to cover ten percent of the Smoky Hill Bombing Range. According to the instructions given them, the investigators were to include the land leased by the Army Guard as part of their survey area. Their survey was opportunistic in that it was generally focused on areas of open ground, specifically burned pastureland and firebreaks. Since no burned areas were present within the RTA, their survey of the RTA involved the strips of land that had been plowed to serve as firebreaks.The DuVall survey resulted in a draft report (Peer *et al* 1999) documenting their finding of three historic archeological sites on RTA land. One of those sites (14SA622) had already been designated by the KSHS survey as 14SA320. The other two sites, 14SA621 and 623 (see Figure 23) consist of small scatters of historic debris lacking any apparent association with habitation areas. Site survey recordation forms for the two sites present recommendations of "No further work," and according to the abstract of the draft report, "None of these [historic sites] retains structural integrity or architectural significance to warrant their consideration for placement on the National Register of Historic Places."

These conclusions appear valid for all of the archeological sites documented at the RTA. For historic sites such as these, the rarity (or redundancy) of the resource is one important consideration with regard to determination of archeological significance, and the "time capsule" effect (or site clarity) is another, as short-term occupations may provide artifact collections useful for comparative purposes (Lees 1989:100). With regard to site rarity, historic Euroamerican farmsteads of the post-Civil War period are one of the most ubiquitous historic site types in Kansas, and schools cannot be far behind; rarity cannot be considered a factor for any of these sites. With regard to clarity and the time capsule effect, none of the RTA sites can be considered significant as they were all occupied for more than a few years, in fact, most of them were

occupied continuously up to WWII. Some of the sites, such as 14SA310, were apparently not occupied at all, and consist of nothing more than a well for livestock.

With regard to National Register criterion pertaining to important historic events or associations with important historical figures, none of the RTA sites appear to have any particular significance, and there are no sites deriving from the Camp Phillips experience. With regard to architectural considerations of historic standing structures, only one such structure was documented, that being a smokehouse at 14SA314. All of the other sites lack standing structures and consist of wells and/or "footprint" features (i.e., cellars and building foundations lacking superstructures). In some cases, these features have been totally destroyed by bulldozing. The remaining features are deteriorated to one degree or another, often with cellar walls crumbling in and trees and other vegetation growing within them.

Bearing all these facts in mind, a letter was submitted to the Kansas SHPO on 6 January 2000, asking for a determination of significance with regard to the RTA sites. The SHPO responded with a letter dated January 18, 2000, concurring with the finding that the RTA sites are not eligible for inclusion on the National Register (see correspondence, Appendix I).

The modern RTA buildings were given cursory inspection during the KSHS survey, with somewhat more attention being provided to them by the DuVall surveyors. Some 33 buildings are present, ranging from latrines, sheds, and observation towers to a few more substantial concrete block structures and metal buildings used for storage and as classrooms. The earliest of these structures (Bldg 6050) was built in 1953 but was modified in a 1960s refurbishing. A few of the other buildings "may date to the 1960s" but most of the datable structures were built in the 1990s (PEER *et al* 1999:90, and Table 8.3). Several are open frame structures designed to be covered with canvas when in use. None of the buildings have architectural or historical characteristics that would qualify them for nomination to the National Register, a conclusion echoed by the DuVall researchers who refer to them (along with other Smoky Hill Gunnery Range buildings) as being "utilitarian structures of no architectural significance," lacking in exceptional historical significance (PEER *et al* 1999:99).

In summary, the KSHS and DuVall surveys resulted in the documentation of 21 previously unrecorded archeological sites on the grounds of the Regional Training Area. The sites were found to be lacking in archeological and historical significance, and for this reason the Kansas SHPO has determined them to be ineligible for listing on the National Register. No further archeological investigations are therefore deemed to be necessary. Likewise, the various RTA buildings are interpreted as lacking in the architectural and historical characteristics that would enable their listing on the National Register. Currently none of these buildings are fifty years old, and therefore they are not eligible for listing on the National Register.

SUMMARY AND CONCLUSIONS

Beginning in late 1997 and extending into 2000, the Kansas State Historical Society carried out a systematic survey of the Kansas Army National Guard installation in an attempt to locate and document, through records research and pedestrian survey, all significant cultural resources that might be affected by Guard activities. As a secondary goal, the survey attempted to document historical information about these properties and to list all monuments, artworks, and other sorts of material culture belonging to the Guard or currently under their control. Counting multiple-building properties (such as the Salina Airport) as one location, the research involved visits to over 60 different locations in the state.

The survey also included consultation with Native American tribes concerning the possibility of sacred sites or traditional cultural properties being affected by Guard activities. None of the tribes identified any such sites or properties.

In terms of the survey's main goal of locating properties of National Register significance, our research identified three buildings that are currently on the National Register--these are Bldgs 109, 113, and 114 at Fort Leavenworth, which are part of the Fort Leavenworth National Historic Landmark District. One other structure--Bldg 741 at Fort Riley--was found to have been determined eligible for listing on the Register as part of the proposed Marshall Army Airfield Historic District. In addition, the research resulted in documenting three buildings deemed eligible for nomination to the National Register and/or the Register of Historic Kansas Places--these are the Hiawatha, Kingman, and Hiawatha armories. It is also possible that in the future the forty-six surviving "Nickell's armories" constructed mainly in the 1950s and early 1960s could be successfully nominated to the National Register as a thematic nomination. After consultation with the Guard and the Kansas Historic Preservation Office, the Society is proceeding with plans to use current funding as part of a separate contract to obtain a qualified researcher to produce a Multiple Property Documentation Form (a "context statement") for the Cold War armories in conjunction with associated research designed to accrue National Register nomination documentation for the Hiawatha, Kingman, and St. Marys armories.

All of the other buildings that make up the Guard installation are of such recent construction or have been so modified as to preclude their consideration for listing on the National Register or the Kansas Register. However, several of the buildings within this group will soon become old enough for consideration, and a preliminary examination of their National Register significance seems worthwhile at this time. In our opinion, none of these buildings are of exceptional historical or architectural importance. They are utilitarian structures, lacking in the historic or architectural characteristics that would qualify them for listing on the National Register.

To reiterate, with the exception of the Nickell's armories, none of the Guard's buildings constructed in the 1950s, 1960s, or 1970s appear, at this time, to have historic or architectural

significance that merit their nomination to the National Register. This conclusion does not apply, however, to the more substantial buildings constructed in the 1980s and 1990s such as the Regional Training Center's Nickell Hall. These buildings should be evaluated according to the standards of their times, when they become old enough to qualify for National Register consideration.

In terms of archeological resources, twenty-five archeological sites have been documented on lands controlled by the Guard, but their National Register status is either nil or problematical. At the Fort Leavenworth Leadership Development Center (LDC), office research revealed that six archeological sites had been documented in 1988. Two of those sites now appear to have been destroyed and one other is regarded as lacking in significance and thus ineligible for the National Register, with no further investigations being recommended. In summary, the LDC grounds contain three sites (14LV104, 14LV106, and 14LV107) that must be considered potentially eligible for the National Register. These three sites therefore need to be protected from damage and given due consideration with regard to any future ground disturbing activities. If any of these three sites is to be disturbed in any way, the recommended testing should be carried out first, so that the site's National Register significance can be determined and appropriate decisions made with regard to their need for preservation and/or mitigation. Any such work should be approved by and coordinated through the Fort Leavenworth Directorate of Public Works.

At the Regional Training Area (RTA) in rural Saline County, twenty-one archeological sites were found, representing the remains of historic farmsteads and small trash dumps along with one schoolhouse. All of these sites are derived from the late 19th and early 20th century occupation of the area prior to the establishment of Camp Phillips in 1942. These sites were found to be lacking in the characteristics of site rarity and site clarity that serve to determine significance of historic sites.The Kansas SHPO has formally concurred with this conclusion, providing a letter stating that the RTA sites are not considered eligible for listing on the National Register of Historic Places. We therefore recommend no further investigations or preservation measures for those sites.

Although the main thrust of this survey was to document the presence of properties that might be considered eligible for the National Register, a number of monuments, cannons, artworks, and artifacts were also documented, and these should be considered cultural resources by the Guard even though they do not fit the National Register criteria for significant cultural resources. They constitute a unique body of material culture, a cultural legacy for all Kansans as well as the Guard. Perhaps foremost among that body of material is the World War II Japanese cannon at the Great Bend armory--it is one of only four such Japanese "trophy weapons" known to be serving as an outdoor monument in Kansas. A cleaning and repainting of this cannon, in an historically accurate color, is certainly recommended.

MANAGEMENT CONSIDERATIONS

As a governmental entity receiving federal funds, the Kansas Army National Guard is required to comply with state and federal legislation pertaining to cultural resources. In practice, this means managing resources primarily with reference to their National Register significance, although as a state agency the Guard must also take into account the Register of Historic Kansas Places.

Section 106 of the National Historic Preservation Act of 1966 directs federal agencies to take into account the effects of projects on historic or archeological properties that are listed in or eligible for listing in the National Register. To elaborate, using language from the Scope of Work that brought about this report, federal agencies are required to exercise caution in assuring that any resource able to qualify for inclusion on the National Register is not inadvertantly transferred, sold, demolished, substantially altered, or allowed to deteriorate significantly. If, on the other hand, a resource has been investigated and deemed ineligible for listing on the National Register and is not listed on the Kansas Register, the Guard is under no obligation to preserve that resource, and the property may be altered or even destroyed in accordance with the agency's needs.

If it has been established that a resource will require further work (such as archeological testing) before its Register significance can be determined, or if a resource has been determined by the agency or the State Historic Preservation Officer to be eligible for listing on the National Register, the Guard should manage that resource in accordance with the provisions of 36 CFR 800, Protection of Historic Properties. The appropriate treatments for cultural resources are described in the Secretary of the Interior's **Standards for Rehabilitation and Guidelines for Rehabilitating Historic Buildings** and the **Treatment of Archeological Properties: A Handbook** issued by the Advisory Council on Historic Preservation. If a property has been listed on the National Register, then the Secretary of the Interior's **Standards** or the Advisory Council's **Handbook** must be followed in dealing with that property. The grounds, not just buildings, must be considered as well, following the guidelines offered by the Secretary of the Interior's **Guidelines for the Treatment of Historic Landscapes**. With regard to buildings, attention should also be given to Appendix E in DA PAM 200-4, "Army Historic Building Management Standards." With these considerations in mind, several observations and recommendations can be made with regard to the Kansas Army National Guard and cultural resource management.

First, the Guard installation currently includes seven historic properties, defined as cultural resources listed on or considered eligible for listing on the National Register of Historic Places and/or the Register of Historic Kansas Places. Three buildings are currently listed on the National Register--these are Bldgs 109, 113, and 114, at Fort Leavenworth. Three other buildings--the armories at Hiawatha and St. Marys, and Bldg 741 at Fort Riley--have been determined eligible

for listing on the National Register. Similarly, the armory at Kingman has been determined eligible for listing on the Kansas Register, although not the National Register. Regulations require that these "eligible" properties be treated as if they were indeed listed on the Register. Undertakings involving any of these seven historic properties should be cleared through the SHPO and, in the case of the properties at Fort Riley and Fort Leavenworth, through the appropriate post authorities.

Second, the Guard installation includes three archeological sites--14LV104, 14LV106, and 14LV107--for which additional investigations have been recommended before their National Register status can be determined. All of these sites are part of the Fort Leavenworth military reservation and therefore the Fort authorities bear the primary responsibility for cultural resource management. At present, these sites must be regarded as potentially eligible for listing on the National Register, but as they are in no imminent danger the Guard's responsibilities are simply to preserve them *in situ*. We recommend that no ground disturbing activities be allowed in these site areas. While light vehicular traffic is acceptable on an occasional basis, we recommend that heavier vehicles such as tanks and bulldozers be prohibited from driving across these site areas. If future development plans call for any ground disturbing activities to be carried out in these areas, archelogical investigations should first be carried out in accordance with recommendations from the earlier investigators, so that the National Register status of these sites can be determined along with any subsequent need for site mitigation. Such actions will require the approval and direction of the Fort Leavenworth authorities.

Third, the Guard installation contains forty-six Cold War armories--the "Nickell's armories"--which might qualify for a thematic nomination to the National Register in the future, when these buildings become fifty years old. The earliest were built in the early 1950s and most of the others were completed by the early 1960s, with one late construction in 1972-73. Within the next decade, the bulk of these buildings will become old enough to be considered for listing on the Register. At present, these buildings do not qualify for the National Register (due to the fifty-year rule) and the Guard is therefore free to deal with these buildings in any way that seems appropriate. However, if the Guard wishes to pursue a thematic nomination in the future, a suitable number of these buildings should be preserved without major modifications. A National Register "Multiple Property Nomination Form" typically calls at least fifteen properties to be included in a thematic nomination. We therefore recommend that at least fifteen of the Cold War armories be preserved for this purpose, without significant modification. A context statement which can serve as a thematic nomination is currently being prepared. Depending on the conclusions obtained through that research, reevaluation of the management of these properties will then be necessary.

Fourth, the Guard should consider the possibility of inadvertant discoveries made during the course of development or use of its various facilities, including the LTAs. Due to the possibility of deeply buried archeological sites in areas of deep alluvium, archeological monitoring should be conducted in conjunction with excavations at Fort Riley, the KSRTC facility at the Salina Airport, and at the armories in Abilene, Clay Center, Hays, Junction City, Salina, St. Marys, Wichita West

(Douglas Avenue), and Winfield. Proposed LTAs should be inspected by a professional archeologist, initially by means of office reseach coordinated with the SHPO to determine the potential for archeological remains, and then by a field survey if deemed appropriate.

With regard to the rest of the Guard installation, no further investigations or preservation efforts are recommended at this time. More specific management recommendations are envisioned for the future through creation of an Integrated Cultural Resources Management Plan, or ICRMP. At this time, however, two generalized recommendations seem appropriate. If, in the future, presently unknown artifacts or archeological features are discovered on the Guard installation, a qualified archeologist should be contacted so that the find can be evaluated and appropriate mitigative efforts carried out. Similarly, as buildings become fifty years old and qualify for inclusion on the National Register, they should be appropriately preserved (i.e., treated as if they were listed on the Register) until their National Register status can be formally determined.

One last set of recommendations derives from consultation with Native American tribes. Several of these tribes requested to be contacted under certain conditions. Following the spirit and intent of the White House Memorandum dated 29 April 1994 establishing Government-to-Government Relations with Native American Tribal Governments, and the Executive Order dated 6 November 2000 dealing with Consultation and Coordination With Indian Tribal Governments, the Guard is enjoined to comply with these requests to the full extent possible. Based on the responses received from the various tribes that were contacted, the Guard should do the following with regard to finds made on the Guard installation:

> Immediately notify the Kaw Nation if any artifacts or culturally affiliated materials are uncovered in Morris, Geary, Riley, Pottawatomie, or Doniphan counties and if any finds are made in the north half of the state.
>
> Contact the Kickapoo Tribe of Kansas if any inadvertant discoveries are made in Atchison, Brown, Doniphan, or Leavenworth counties.
>
> Contact the Cheyenne and Arapaho Tribes of Oklahoma if any human remains, burial goods, or burial grounds are discovered anywhere in the state.
>
> Contact the Prairie Band Potawatomi Nation if any inadvertant discoveries are made anywhere in the state.

In addition, the Guard should do the following with regard to planned projects and undertakings:

> Consider the Iowa Tribe of Oklahoma an interested party and notify them of any proposed construction projects or ground disturbance in Doniphan, Wyandotte, Atchison, or Leavenworth counties.

REFERENCES CITED

Benedict, Bryce
2000 "First Adjutant General Kept the Peace in Antebellum Kansas." Plains Guardian 44(5):10 (August 2000).

Brown, Kenneth L. and Alan H. Simmons, editors
1987 Kansas prehistoric archeological preservation plan. Unpublished report prepared for the Historic Preservation Department, Kansas State Historical Society, by the Office of Archeological Research, Museum of Anthropology, University of Kansas, Lawrence. Ms. on file, Kansas State Historical Society, Topeka.

Castel, Albert
1958 War and Politics: The Price Raid of 1864. Kansas Historical Quarterly 24(2):129-143.

Fowles, Brian Dexter
1989 A Guard in Peace and War: The History of the Kansas National Guard, 1854-1987. Manhattan, Kansas: Sunflower University Press.

Hill, Jim Dan
1964 The Minuteman in Peace and War: A History of the National Guard. Harrisburg, Pennsylvania: Stackpole Company.

Kuchler, A.W.
1974 A new vegetation map of Kansas. Ecology 55(3):586-604.

Lees, William B.
1989 Kansas preservation plan, section on Historical Archeology. Unpublished report prepared for the Historic Preservation Department, Kansas State Historical Society, by the Archeology Department, Kansas State Historical Society. Ms. on file, Kansas State Historical Society, Topeka.

McNerney, Michael J., Mark J. Wagner, Mary R. McCorvie, Brad Koldehoff, Terrance J. Martin, and Kathryn E. Parker
1989 Phase I, II, and III Archeological Investigations at Fort Leavenworth, Kansas. (Also known as Cultural Resources Management Report No. 132.) Unpublished report prepared for Kansas City District Corps of Engineers (Contract No. DACA41-86-D-0064) by American Resources Group, Ltd. of Carbondale, Illinois.

Mechem, Kirke, ed.
1959a U.S. Army and Air Force Wings over Kansas. Kansas Historical Quarterly 25(2):129-157.

1959b U.S. Army and Air Force Wings over Kansas--*Concluded.* Kansas Historical Quarterly 25(3):334-360.

O'Brien, Patrick G., Thomas D. Isern, and R. Daniel Lumley
1984 Stalag Sunflower: German Prisoners of War in Kansas. Kansas History 7(3):182-198.

Palmer, Cecil D., Vernon L. Hamilton, Bruce R. Hoffman, Peter B. Fahnestock, and Wesley L. Barker
1992 Soil Survey of Saline County, Kansas. Washington, DC: National Cooperative Soil Survey.

PEER Consultants, P.C., DuVall and Associates, Inc., and Brad Logan
1999 Cultural Resources Evaluation for Smoky Hill Air-To-Ground Gunnery Range, Salina, Kansas. Draft report prepared for Air National Guard\CEVP under National Bureau contract DAHA90-94-D-0011. Ms. on file at the Kansas State Historical Society, Topeka.

Richmond, Robert W.
1999 Kansas, a Land of Contrasts. Wheeling, Illinois: Harlan Davidson.

Rogers, Richard D.
1996 A Story of Brave Kansans. Kansas History: A Journal of the Central Plains 18(4):258-269.

Schoewe, W.E.
1949 The geography of Kansas, part II, physical geography. Transactions of the Kansas Academy of Science 52(3): 261-333.

Smith, Gene
1999 "Cleared for Takeoff," in Topeka Capital-Journal newspaper, Sunday, May 30, 1999, Section B, pages 1-4.

Thies, Randall M.

2000 Kansas Army National Guard Cultural Resources Survey Interim Report. Report submitted to the National Guard of Kansas, Adjutant General's Department, Director of Facilities Engineering. Ms. on file, Kansas State Historical Society, Topeka.

1999 Kansas Army National Guard Cultural Resources Survey. Draft report submitted to the National Guard of Kansas, Adjutant General's Department, Director of Facilities Engineering. Ms on file, Kansas State Historical Society, Topeka.

1987 Kansas Culture History. In Amateur Archeological handbook for Kansas, Kansas Anthropological Association Journal 7(1-9):35-51.

USACERL (U.S. Army Construction Engineering Research Laboratory)
1993 Historical and Architectural Documentation Reports for Fort Riley, Kansas. (Final report, October 1993). Ms. on file at the State Historic Preservation Office, Kansas State Historical Society, Topeka.

Wedel, Waldo R.
1959 An introduction to Kansas archeology. Smithsonian Institution, Bureau of American Ethnology, Bulletin 174.




Figure 1. USGS map showing the location of Bldg 741, Marshall Field Hanger, at Fort Riley.




Figure 2. Map showing the location of Bldg 741 within the proposed Marshall Army Airfield Historic District (from map provided in USACERL 1993).




Figure 3. USGS map showing general location of KSARNG properties (i.e., areas surveyed) at Fort Riley in the Camp Funston area.




Figure 4. Fort Riley map showing west section of Camp Funston.




Figure 5. Fort Riley map showing east section of Camp Funston.




Figure 6. USGS map showing the general location and boundaries of the KSARNG motor pool area (i.e., area surveyed) at Fort Leavenworth, with insert identifying Bldgs 109, 113, and 114.




Figure 7. USGS map showing general location and boundaries of KSARNG property (i.e, areas surveyed) at the Leader Development Center on the Fort Leavenworth military reservation.




Figure 8. USGS map showing general location and limits of archeological sites on KSARNG property at the Leader Development Center on the Fort Leavenworth military reservation.




Figure 9. Map showing the location of archeological site 14LV104.




Figure 10. Map showing the interpreted location of archeological site 14LV105.




Figure 11. Map showing the location of archeological site 14LV106.




Figure 12. Map showing the location of archeological site 14LV107.




Figure 13. Map showing the former location of archeological site 14LV108.




Figure 14. Map showing the location of archeological site 14LV109.




Figure 15. USGS map showing the location of KSARNG property (i.e., areas surveyed) at the Topeka Headquarters, on 27th Street and Topeka Boulevard in Topeka.




Figure 16. KSARNG map showing KSARNG properties in the northwest section of the Topeka headquarters area.




Figure 17. KSARNG map showing KSARNG properties in the southeast section of the Topeka headquarters area.




Figure 18. USGS map showing the location of KSARNG properties (i.e., areas surveyed) at Forbes Field.




Figure 19. USGS map showing the location of KSARNG properties (i.e., areas surveyed) at the Salina Airport.




Figure 20. KSARNG map modified to show the location of KSARNG properties at the Salina airport.




Figure 21. USGS map showing the boundaries of the Regional Training Area in rural Saline County.

FIGURES 22 and 23

have been deleted due to the presence of locationally specific archeological data.

TABLE I.

LIST OF "NICKELL'S ARMORIES"
AND INDEPENDENT OMS SHOPS
WITH DATES OF COMPLETION

Abilene	1953
Atchison	1963
Augusta	1958
Belleville	1956
Burlington	1954
Chanute	1957
Cherryvale	1956
Clay Center	1955
Coffeyville	1956
Colby	1960
Concordia	1953
Council Grove	1954
Dodge City	1959
Emporia	1955
Fort Scott	1955
Garden City	1958
Garnett	1955
Hays	1956
Holton	1973
Horton	1954
Hutchinson	1958
Iola	1954
Junction City	1958
Kansas City	1956
Larned	1961
Lawrence	1961
Liberal	1958
Manhattan	1955
Mankato	1958
Marysville	1954
Newton	1955
Norton	1957
Ottawa	1954
Phillipsburg	1963
Pittsburg	1956
Pratt	1955
Russell	1956
Sabetha	1953
Salina	1956
Smith Center	1960
Topeka	1956
Troy	1953
Wichita-West	1955
Wichita-East	1955
Wichita-South	1958
Winfield	1953
Wichita OMS#3	1959

APPENDIX I.

NATIONAL REGISTER CRITERIA
AND
SHPO CORRESPONDENCE

KANSAS HISTORIC PRESERVATION OFFICE PROGRAMS: THE NATIONAL REGISTER OF HISTORIC PLACES AND THE REGISTER OF HISTORIC KANSAS PLACES

Properties eligible for the National Register of Historic Places and the Register of Historic Kansas Places retain their original interior and exterior appearance to a fairly high degree, are fifty years or older, and have potential to be documented as historically significant at either the local, state, or national level. Many different property types are listed on each register, including but not limited to barns, banks, courthouses, libraries, houses, ranches, battlefields, hospitals, roads, bridges, rail depots, and archeological sites. In most cases, if a property meets the criteria of age, integrity, and potential significance, the nomination process takes between eight to twelve months. Our office provides direction for the research necessary to complete the nomination, relying heavily on the time and efforts of the nomination sponsor to accomplish that research.

Interested parties may begin the register process by completing the Preliminary Site Information Questionnaire, and returning the application to the Kansas Historic Preservation Office (KHPO). If a property appears eligible for either the National Register of Historic Places or the Register of Historic Kansas Places, the sponsor is sent a research guide, an example nomination, and a nomination form to assist in the development of the nomination. The example nomination shows how different types of information can be combined to tell the history of the property.

Many properties can be documented quite successfully using public records such as census reports, deeds, tax records, and newspapers in addition to secondary source histories, architectural drawings and photographs. These records can be found at local libraries, university research libraries, county courthouses, and local and state historical societies, as well as under private ownership. Many of the Kansas State Historical Society records are available on microfilm through interlibrary loan.

Once the sponsor has completed the research on the property and compiled it into a working draft, it is sent to KHPO for review and evaluation. Often, the sponsor will be asked to provide additional information regarding the history of the property. KHPO staff will work with the sponsor to ensure that all aspects of the nomination forms are accurately completed, so that the final product will be ready to present to the Kansas State Historic Sites Board of Review for nomination consideration. When the property has been thoroughly documented and a site visit to the property has been made by KHPO staff, it is considered for nomination to either the National Register of Historic Places or the Register of Historic Kansas Places by the Kansas Historic Sites Board of Review.

For more information about the National Register of Historic Places and the Register of Historic Kansas Places programs, please contact the Kansas Historic Preservation Office at (785) 272-8681 ext. 240.

THE NATIONAL REGISTER CRITERIA

The quality of significance in American history, architecture, archeology, and culture is present in districts, sites, buildings, structures, and objects that possess integrity of location, design, setting, materials, workmanship, feeling, and association, and:

a. that are associated with events that have made a significant contribution to broad patterns of our history; or

b. that are associated with the lives of persons significant in our past; or

c. That embody the distinctive characteristics of a type, period, or method of construction or that represent the work of a master, or that possess high artistic values, or that represent a significant and distinguishable entity whose components may lack individual distinction; or

d. That have yielded, or may be likely to yield, information important in prehistory or history..

Criteria Considerations (exceptions): Ordinarily cemeteries, birthplaces, or graves of historical figures, properties owned by religious institutions or used for religious purposes, structures that have been moved from their original locations, reconstructed historic buildings, properties primarily commemorative in nature, and properties that have achieved significance within the past 50 years shall not be considered eligible for the National Register. However, such properties will qualify if they are integral parts of districts that do meet the criteria or if they fall within the following categories:

a. a religious property deriving primary significance from architectural or artistic distinction or historical importance; or

b. a building or structure removed from its original location but which is significant primarily for architectural value, or which is the surviving structure most importantly associated with a historic person or event; or

c. a birthplace or grave of a historical figure of outstanding importance if there is no other appropriate site or building directly associated with his or her productive life; or

d. a cemetery which derives its primary significance from graves of persons of transcendent importance, from distinctive design features, or from association with historic events; or

e. a reconstructed building when accurately executed in a suitable environment and presented in a dignified manner as part of a restoration master plan, and when no other building or structure with the same association has survived; or

f. a property primarily commemorative in intent if design, age, tradition, or symbolic value has invested it with its own historical significance; or

g. a property achieving significance within the past 50 years if it is of exceptional importance.

KANSAS

STATE

HISTORICAL

SOCIETY

◆

Cultural Resources
Historic Preservation
Office (ext. 240)

◆

6425 S.W. 6th Avenue
Topeka, Kansas
66615-1099
PHONE# (785) 272-8681
FAX# (785) 272-8682
TTY# (785) 272-8683

◆

KANSAS HISTORY CENTER

Administration
Center for Historical Research
Cultural Resources
Education / Outreach
Historic Sites
Kansas Museum of History
Library & Archives

HISTORIC SITES

Adair Cabin
Constitution Hall
Cottonwood Ranch
First Territorial Capitol
Fort Hays
Goodnow House
Grinter Place
Hollenberg Station
Kaw Mission
Marais des Cygnes Massacre
Mine Creek Battlefield
..ative American Heritage Museum
Pawnee Indian Village
Pawnee Rock
Shawnee Mission

November 10, 1999

Mr. Randy Theis
Kansas State Historical Society
6425 S. W. 6th Street
Topeka, Kansas 66615

Dear Randy:

Our staff has reviewed the Preliminary Site Information Questionnaire submitted for the National Guard Armory in Hiawatha, Kansas. The building appears to be a significant cultural resource that should be preserved. Our staff encourages you to pursue a nomination to the National Register of Historic Places for the property.

Properties eligible for the National Register of Historic Places and the Register of Historic Kansas Places are those which retain their original interior and exterior appearance to a fairly high degree, retain their original location, are fifty years or older, and have the potential to be documented as historically significant at either the local, state, or national level. Many different property types are listed on each register, including but not limited to barns, banks, courthouses, churches, libraries, houses, schools, theaters, ranches, battle fields, hospitals, roads, bridges, railroad depots, and archeological sites.

In most cases, if a property meets the criteria of age, integrity, and potential significance the nomination process takes between eight to twelve months. Our office provides direction for the research necessary to complete the nomination, relying heavily on the time and efforts of the nomination sponsor to accomplish that research.

I have enclosed information to assist you with the development of a nomination for your property. The information includes National Register Bulletin 16A: How to Complete the National Register Registration Form, a research guide, an example nomination, and a nomination form. This information applies to both state and national register nominations. The example nomination shows how different types of information can be combined into a history of the built and sometimes natural environment, however we may not always be able to send a nomination for a similar property type.

Many properties can be documented quite successfully using public records such as census reports, deeds, tax records, newspapers, and maps in addition to secondary source histories, architectural drawings and photographs. Historic photographs are a very important source of information. These records can be found at local libraries, university research libraries, county courthouses, and local, state and national historical societies and archives, as well as under private ownership.

Many of the Kansas State Historical Society records are available on microfilm through interlibrary loan. Careful research is important. Exact citations with the name of the record, the location, the date, and the page are essential. Copies should be made of the research information and sent in with the nomination draft.

Please pay careful attention to the historical association that the property has with the history of the area from its construction date to fifty years from the present date. The period of significance for the property begins with its construction and ends at a fifty year point from present day. Relevant history that precedes the date of the property's construction and history that follows the fifty year cut-off date still needs to be developed.

Once you have completed research on the property and compiled the information into a working draft, send the draft and research information to me. The information is evaluated for its content. Often you will be asked to provide additional information regarding the history of the property.

Our staff will work with you to ensure that all aspects of the nomination forms are accurately completed, so that the final product that you submit will be ready to present to the Kansas Historic Sites Board of Review for nomination consideration. When the property has been thoroughly documented and a site visit by staff has been made to the property, it is considered for nomination.

Our office offers two incentive programs for register listed properties. The first, the Heritage Trust Fund, provides matching grants for the preservation of State and National Register properties. The second is a twenty-percent Investment Tax Credit which is available for the certified rehabilitation of income-producing properties that are listed on the National Register. The ITC projects may begin before the property is actually listed. A ten-percent Income Tax Credit is available for income-producing properties that are at least thirty-six years old and not listed on the National Register.

I trust this letter and the enclosed information will be useful. I look forward to working with you. Please feel free to contact me regarding the nomination process and other preservation related matters at 785-272-8681, ex. 213.

Sincerely yours,

Martha Hagedorn-Krass

Martha Hagedorn-Krass, Architectural Historian

enc.

KANSAS

STATE

HISTORICAL

SOCIETY

◆

Cultural Resources
Historic Preservation
Office (ext. 240)

◆

6425 S.W. 6th Avenue
Topeka, Kansas
66615-1099
PHONE# (785) 272-8681
FAX# (785) 272-8682
TTY# (785) 272-8683

◆

KANSAS HISTORY CENTER

Administration
Center for Historical Research
Cultural Resources
Education / Outreach
Historic Sites
Kansas Museum of History
Library & Archives

HISTORIC SITES

Adair Cabin
Constitution Hall
Cottonwood Ranch
First Territorial Capitol
Fort Hays
Goodnow House
Grinter Place
Hollenberg Station
Kaw Mission
Marais des Cygnes Massacre
Mine Creek Battlefield
...ive American Heritage Museum
Pawnee Indian Village
Pawnee Rock
Shawnee Mission

November 10, 1999

Mr. Randy Theis
Kansas State Historical Society
6425 S. W. 6th Street
Topeka, Kansas 66615

Dear Randy:

Our staff has reviewed the Preliminary Site Information Questionnaire submitted for the National Guard Armory in Kingman, Kansas. The building appears to be a significant cultural resource that should be preserved. Our staff encourages you to pursue a nomination to the Register of Historic Kansas Places for the property.

Properties eligible for the National Register of Historic Places and the Register of Historic Kansas Places are those which retain their original interior and exterior appearance to a fairly high degree, retain their original location, are fifty years or older, and have the potential to be documented as historically significant at either the local, state, or national level. Many different property types are listed on each register, including but not limited to barns, banks, courthouses, churches, libraries, houses, schools, theaters, ranches, battle fields, hospitals, roads, bridges, railroad depots, and archeological sites.

In most cases, if a property meets the criteria of age, integrity, and potential significance the nomination process takes between eight to twelve months. Our office provides direction for the research necessary to complete the nomination, relying heavily on the time and efforts of the nomination sponsor to accomplish that research.

I have enclosed information to assist you with the development of a nomination for your property. The information includes National Register Bulletin 16A: How to Complete the National Register Registration Form, a research guide, an example nomination, and a nomination form. This information applies to both state and national register nominations. The example nomination shows how different types of information can be combined into a history of the built and sometimes natural environment, however we may not always be able to send a nomination for a similar property type.

Many properties can be documented quite successfully using public records such as census reports, deeds, tax records, newspapers, and maps in addition to secondary source histories, architectural drawings and photographs. Historic photographs are a very important source of information. These records can be found at local libraries, university research libraries, county courthouses, and local, state and national historical societies and archives, as well as under private ownership.

Many of the Kansas State Historical Society records are available on microfilm through interlibrary loan. Careful research is important. Exact citations with the name of the record, the location, the date, and the page are essential. Copies should be made of the research information and sent in with the nomination draft.

Please pay careful attention to the historical association that the property has with the history of the area from its construction date to fifty years from the present date. The period of significance for the property begins with its construction and ends at a fifty year point from present day. Relevant history that precedes the date of the property's construction and history that follows the fifty year cut-off date still needs to be developed.

Once you have completed research on the property and compiled the information into a working draft, send the draft and research information to me. The information is evaluated for its content. Often you will be asked to provide additional information regarding the history of the property.

Our staff will work with you to ensure that all aspects of the nomination forms are accurately completed, so that the final product that you submit will be ready to present to the Kansas Historic Sites Board of Review for nomination consideration. When the property has been thoroughly documented and a site visit by staff has been made to the property, it is considered for nomination.

Our office offers two incentive programs for register listed properties. The first, the Heritage Trust Fund, provides matching grants for the preservation of State and National Register properties. The second is a twenty-percent Investment Tax Credit which is available for the certified rehabilitation of income-producing properties that are listed on the National Register. The ITC projects may begin before the property is actually listed. A ten-percent Income Tax Credit is available for income-producing properties that are at least thirty-six years old and not listed on the National Register.

I trust this letter and the enclosed information will be useful. I look forward to working with you. Please feel free to contact me regarding the nomination process and other preservation related matters at 785-272-8681, ex. 213.

Sincerely yours,

Martha Hagedorn-Krass

Martha Hagedorn-Krass, Architectural Historian

enc.

KANSAS

STATE

HISTORICAL

SOCIETY

◆

Cultural Resources
Historic Preservation
Office (ext. 240)

◆

6425 S.W. 6th Avenue
Topeka, Kansas
66615-1099
PHONE# (785) 272-8681
FAX# (785) 272-8682
TTY# (785) 272-8683

◆

KANSAS HISTORY CENTER

Administration
Center for Historical Research
Cultural Resources
Education / Outreach
Historic Sites
Kansas Museum of History
Library & Archives

HISTORIC SITES

Adair Cabin
Constitution Hall
Cottonwood Ranch
First Territorial Capitol
Fort Hays
Goodnow House
Grinter Place
Hollenberg Station
Kaw Mission
Marais des Cygnes Massacre
Mine Creek Battlefield
Native American Heritage Museum
Pawnee Indian Village
Pawnee Rock
Shawnee Mission

January 27, 2000

Mr. Randall Thies
Kansas State Historical Society
6425 SW Sixth Avenue
Topeka, Kansas 66615-1099

Dear Randy:

Our staff has reviewed the Preliminary Site Information Questionnaire submitted for the St. Mary's National Guard Armory in St. Mary's, Kansas. The building appears to be a significant cultural resource that should be preserved. Our staff encourages you to pursue a nomination to the National Register of Historic Places for the property.

Properties eligible for the National Register of Historic Places and the Register of Historic Kansas Places are those which retain their original interior and exterior appearance to a fairly high degree, retain their original location, are fifty years or older, and have the potential to be documented as historically significant at either the local, state, or national level. Many different property types are listed on each register, including but not limited to barns, banks, courthouses, churches, libraries, houses, schools, theaters, ranches, battle fields, hospitals, roads, bridges, railroad depots, and archeological sites.

In most cases, if a property meets the criteria of age, integrity, and potential significance the nomination process takes between eight to twelve months. Our office provides direction for the research necessary to complete the nomination, relying heavily on the time and efforts of the nomination sponsor to accomplish that research.

I have enclosed information to assist you with the development of a nomination for your property. The information includes National Register Bulletin 16A: How to Complete the National Register Registration Form, a research guide, an example nomination, and a nomination form. This information applies to both state and national register nominations. The example nomination shows how different types of information can be combined into a history of the built and sometimes natural environment, however we may not always be able to send a nomination for a similar property type.

Many properties can be documented quite successfully using public records such as census reports, deeds, tax records, newspapers, and maps in addition to secondary source histories, architectural drawings and photographs. Historic photographs are a very important source of information. These records can be found at local libraries, university research libraries, county courthouses, and local, state and national historical societies and archives, as well as under private ownership.

Many of the Kansas State Historical Society records are available on microfilm through interlibrary loan. Careful research is important. Exact citations with the name of the record, the location, the date, and the page are essential. Copies should be made of the research information and sent in with the nomination draft.

Please pay careful attention to the historical association that the property has with the history of the area from its construction date to fifty years from the present date. The period of significance for the property begins with its construction and ends at a fifty year point from present day. Relevant history that precedes the date of the property's construction and history that follows the fifty year cut-off date still needs to be developed.

Once you have completed research on the property and compiled the information into a working draft, send the draft and research information to me. The information is evaluated for its content. Often you will be asked to provide additional information regarding the history of the property.

Our staff will work with you to ensure that all aspects of the nomination forms are accurately completed, so that the final product that you submit will be ready to present to the Kansas Historic Sites Board of Review for nomination consideration. When the property has been thoroughly documented and a site visit by staff has been made to the property, it is considered for nomination.

Our office offers two incentive programs for register listed properties. The first, the Heritage Trust Fund, provides matching grants for the preservation of State and National Register properties. The second is a twenty-percent Investment Tax Credit which is available for the certified rehabilitation of income-producing properties that are listed on the National Register. The ITC projects may begin before the property is actually listed. A ten-percent Income Tax Credit is available for income-producing properties that are at least thirty-six years old and not listed on the National Register.

I trust this letter and the enclosed information will be useful. I look forward to working with you. Please feel free to contact me regarding the nomination process and other preservation related matters at 785-272-8681, ex. 213.

Sincerely yours,

Martha Hagedorn-Krass

Martha Hagedorn-Krass, Architectural Historian

enc.

KANSAS

STATE

HISTORICAL

SOCIETY

◆

Richard Pankratz
Director
Cultural Resources
Division
tel. ext. 217

◆

6425 S.W. 6th Avenue
Topeka, Kansas
66615-1099
PHONE# (913) 272-8681
FAX# (913) 272-8682
TTY# (913) 272-8683

◆

KANSAS HISTORY CENTER

Administration
Center for Historical Research
Cultural Resources
Education / Outreach
Historic Sites
Kansas Museum of History
Library & Archives

HISTORIC SITES

Adair Cabin
Constitution Hall
Cottonwood Ranch
First Territorial Capitol
Fort Hays
Goodnow House
Grinter Place
Hollenberg Station
Kaw Mission
Marais des Cygnes Massacre
Mine Creek Battlefield

December 14, 1999

Mr. Randall M. Thies
Archeology Office
Kansas State Historical Society
6425 S.W. Sixth Avenue
Topeka, KS 66615-1099

RE: Kansas Army National Guard Buildings

Dear Mr. Thies:

In response to your query, we are advising you that the state historic preservation officer does not consider the "Cold War" armories to be eligible for the National Register of Historic Places at the present time.

We recommend that one element of your study of the state's armories could be a Multiple Property Documentation Form, i.e., a context statement that could be used both at the present to serve as the umbrella for the nominations of the three properties that have already been determined eligible for the National Register, and then later as the basis for evaluation of the remaining armories when they meet the age criteria.

If you have any questions, please let us know.

Sincerely yours,

Ramon Powers
State Historic Preservation Officer

Richard Pankratz

Richard Pankratz
Director, Cultural Resources Division

KANSAS

STATE

HISTORICAL

SOCIETY

◆

◆

6425 S.W. 6th Avenue
Topeka, Kansas
66615-1099
PHONE# (785) 272-8681
FAX# (785) 272-8682
TTY# (785) 272-8683

◆

KANSAS HISTORY CENTER

Administration
Center for Historical Research
Cultural Resources
Education / Outreach
Historic Sites
Kansas Museum of History
Library & Archives

HISTORIC SITES

Adair Cabin
Constitution Hall
Cottonwood Ranch
First Territorial Capitol
Fort Hays
Goodnow House
Grinter Place
Hollenberg Station
Kaw Mission
Marais des Cygnes Massacre
Mine Creek Battlefield
Native American Heritage Museum
Pawnee Indian Village
Pawnee Rock
Shawnee Mission

January 18, 2000

Major John Andrew, Environmental Protection Specialist
Kansas National Guard
Adjutant General's Department
Director of Facilities Engineering
131 SW 27th Street
Topeka KS 66611-1159

Re: Kansas Army National Guard Cultural Resources Survey
Regional Training Area

Dear Major Andrew:

Our office has reviewed the materials submitted to us by Randall Thies concerning the archeological sites located at the Kansas Army National Guard's Regional Training Area (RTA) near Salina. We concur with the finding that sites 14SA307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 621, and 623 are not eligible for inclusion on the National Register of Historic Places because they do not exhibit site clarity and are redundant with regard to site type.

If you have any questions or need additional information about these comments, please contact William Banks at (785) 272-8681 ext. 214.

Sincerely,

Ramon Powers
State Historic Preservation Officer

Richard Pankratz, Director
Historic Preservation Office

PD-R

KANSAS STATE HISTORICAL SOCIETY

CENTER FOR HISTORICAL RESEARCH
120 West Tenth • Topeka, Kansas 66612-1291 • 913/296-3251

KANSAS MUSEUM OF HISTORY
6425 South West Sixth • Topeka, Kansas 66615-1099 • 913/272-8681

December 21, 1988

Paul D. Barber
Chief, Engineering Division
Corps of Engineers, Kansas City District
700 Federal Building
Kansas City, Missouri 64106-2896

Dear Mr. Barber:

Staff review of the draft report "Phase I, II and III Archeological Investigations at Fort Leavenworth, Kansas," by Michael J. McNerney and others, has been completed. The report was well written; however, it contains numerous typographical errors. For instance, site number 14LV356 is identified as site "14KV356" on page 233. This error and others should be corrected. We agree with the report's statements and conclusions except in two instances. On page 52 the statement is made that military posts in Colorado and Utah were supplied by train in 1866, but a transcontinental rail line was not completed until a later date. A hypothesis is made on page 416 that the prehistoric inhabitants at site 14LV357 may have traded stone tools manufactured from igneous/metamorphic rocks found in the glaciated area of northeastern Kansas for chert tools or bladelets made by contemporaneous people living in the Blue River valley to the west. The hypothesis should also take into account the fact that the Blue River valley marks the western limit of glaciation in the state and that igneous/metamorphic rocks are plentiful in that locality also.

RAMON POWERS, Executive Director
RUTH A. SHERRER, Associate Executive Director
TERRY MARMET, Director of Facilities Planning
MARK A. HUNT, Director of Museums and Historic Properties
PATRICIA A. MICHAELIS, Curator of Manuscripts
RICHARD D. PANKRATZ, Director Historic Preservation Dept

PORTIA ALLBERT, Library Director
EUGENE D. DECKER, State Archivist
THOMAS A. WITTY, State Archeologist
MARILYN HOLT, Director of Publications
LARRY JOCHIMS, Research Historian
JENNIE CHINN, Folklorist
RON PARKS, Public Relations Director

We agree with the report's recommendations for further evaluation of the historic and prehistoric archeological sites found during the survey and with its conclusion that sites 14LV357 and 14LV358 are eligible for listing on the National Register of Historic Places.

Sincerely yours,

Ramon Powers
State Historic Preservation Officer

Martin Stein for

Richard Pankratz, Director
Historic Preservation Department

MS/djw

APPENDIX II.
NATIVE AMERICAN POINTS OF CONTACT LIST AND CORRESPONDENCE

As noted in the chapter on Prehistoric and Historic Contexts, a variety of Indian tribes have lived in Kansas, and four tribes still reside in the state. Not all of these groups can be considered as being associated with any of the properties that make up the KSARNG installation. In recent years, in response to requests associated with attempts to comply with the federal Native American Graves Protection and Repatriation Act (NAGPRA), the NAGPRA office of the National Park Service prepared a map of Kansas showing the judicially established Indian land areas. A copy of the Kansas section of that map is presented within this appendix, as photocopied from a map provided in a loose-leaf notebook supplied to participants in "NAGPRA's Evolving Legacy," a Heritage Resources Management Program sponsored by the National Park Service at the University of Nevada in Reno on June 19-21, 1998.

As indicated in the map legend, the map portrays the results of cases before the U.S. Indian Claims Commission or U.S. Court of Claims in which an American Indian tribe proved its original tribal occupancy of a tract within the continental United States. The map shows five tribes, including the Osage in southeastern Kansas and the Pawnee in north central Kansas. For western Kansas north of the Arkansas River, three tribes are listed: the Northern Cheyenne, the Northern Arapaho, and the combined Cheyenne and Arapaho (the Cheyenne component of which is often referred to as the Southern Cheyenne). Points of Contact for these tribes, and their addresses, are shown below.

Evertt Waller, NAGPRA Coordinator
Osage Tribe
813 Grandview
Pawhuska OK 74056
918-287-4622

Francis Morris, NAGPRA Coordinator
Pawnee Tribe of Oklahoma
PO Box 470
Pawnee OK 74058
918-762-3621

Gordon Yellowman, Cheyenne NAGPRA Representative
Virgil Franklin, Sr., Arapaho NAGPRA Representative
Cheyenne-Arapaho Tribe of Oklahoma
PO Box 38
Concho OK 73022
405-262-0345

Mark Elkshoulder, NAGPRA Representative
Northern Cheyenne Tribal Council
PO Box 128
Lame Deer MT 59043
406-477-6284

Nelson White
Northern Arapaho Tribe
533 Ethete Rd
Fort Washakie WY 82514
307-332-6120

The Kaw Tribe and the Wichita Tribe have a long history of occupation in Kansas and should also be contacted with regard to cultural resources in Kansas; in terms of their general interests, the Kaw have expressed a concern for the northern half of Kansas and the Wichita for the southern half. Their addresses are as follows:

NAGPRA Representative
Kaw Nation
Drawer 50
Kaw City OK 74641

Virgil Swift
Wichita and Affiliated Tribes
PO Box 729
Anadarko OK 73005

A number of other tribes came to Kansas in the mid-1800s from their original historic homelands in the Eastern Woodlands, mostly from the Great Lakes area, to live on reservations within eastern Kansas. Of these, four tribes still live in Kansas: the Prairie Band Potawatomi, the Kickapoo of Kansas, the Sac and Fox of Missouri, and the Iowa of Kansas and Nebraska. Related tribes, also descendants of those who lived in Kansas, now live elsewhere but still have interests in Kansas; these include the Citizen Potawatomi Nation, the Sac and Fox of Oklahoma, the Sac and Fox of the Mississippi in Iowa, and the Iowa of Oklahoma. All of these tribes were consulted to determine whether any of their traditional cultural properties or sacred sites might be present on lands controlled by the Guard. Their addresses are as follows:

Sandra Massey
Sac and Fox Nation of Oklahoma
Rt 2 Box 246
Stroud OK 74079
918-352-3226

Deanne Bahr
Sac and Fox Nation of Missouri

RR1 Box 60
Reserve KS 66434-9723
785-742-7471

Johnathan Buffalo
Sac and Fox Tribe of the Mississippi in Iowa
349 Mesqwaki Road
Tama IA 52339-9629
515-484-4678

Rey Kitchkumee
Prairie Band Potawatomi of Kansas
14880 K Road
Mayetta KS 66509
785-966-2255

Suzanne Battese
Citizen Potawatomi Nation
1901 S. Gordon Cooper Drive
Shawnee OK 74081
405-275-3121

Joan Comer
Iowa Tribe of Kansas and Nebraska
Rt 1 Box 58a
White Cloud KS 66094
785-595-3438

Richard Black
Iowa Tribe of Oklahoma
Rt 1 Box 721
Perkins OK 74059
405-547-5294

Curtis Simon
Kickapoo of Kansas
PO Box 271
Horton KS 66439
785-486-2131

As part of effort that went into making this report, all of the tribes listed above were given maps of all the facilities associated with the KSARNG installation and asked to indicate whether they had any concerns for sacred sites and traditional cultural properties on lands within that installation. However, none of these tribes have claims or concerns that cover all of Kansas; rather, each tribe has its own interests in specific areas of the state. If discoveries are made that

require notification of Native American tribes, we recommend that the National Park Service's Native American Consultation Database webpage be consulted, at http://web.cast.uark.edu/other/nps/nacd/. The Database lists a tribe's interests by county. In addition to the tribes listed above which received maps of the entire KSARNG installation, five other tribes were found listed on the Database for Kansas. Copies of maps pertaining to KSARNG facilities located within the counties in which these tribes expressed an interest were sent to those tribes. They are as follows:

Henry Kostzuta
Apache Tribe of Oklahoma
PO Box 1220
Anadarko OK 73005
405-247-9493
(For Finney, Ford, and Seward counties, containing the Garden City, Dodge City, and Liberal armories.)


Johnny C. Wauqua
Comanche Tribe
PO Box 908
Lawton OK 73502
520-492-4988
(Finney, Ford, and Seward counties)

Dewey Tsonetokoy, Sr
Kiowa Tribe of Oklahoma, Cultural Resources Managment
PO Box 369
Carnegie OK 73015
405-654-1975
(Finney, Ford, and Seward counties)

Elmer Blackbird
Omaha Tribal Council
PO Box 368
Macy NE 68039
402-837-5391
(Atchison, Doniphan, Leavenworth, and Wyandotte counties, containing the Atchison, Troy, and Kansas City armories, and the LDC at Fort Leavenworth)

James Grant
Otoe-Missouria Tribe
Rt 1 Box 62
Red Rock OK 74651
580-723-4434
(Atchison, Doniphan, Leavenworth, and Wyandotte counties)

As noted in the "Research Results" chapter of this report, numerous attempts were made to contact all of the tribes listed above to ask them about sacred sites and traditional cultural properties that might be affected by Guard activities. The latter part of this appendix contains copies of the written responses received by the Society, along with a copy of the letter of request sent to the Pawnee, which is included to serve as an example of the letters sent to all the tribes listed above.


YANKTON
76
PONCA
66
Fort Robinson
Fort Laramie
OMAHA
65
OTOE & MISSOURIA
IOWA
OMAHA
SAC & FOX
64
IOWA
65
S A C
58
57
P A W N E E
68
CHEYENNE & ARAPAHO
NORTHERN CHEYENNE
NORTHERN ARAPAHO
112
Denver
OTOE &
MISSOURIA
67
Fort
Leavenworth
Fort Osage
Bent's Old Fort
Fort Dodge
OSAGE
70
OSAGE
69
O S A G E
Fort Union

KANSAS

STATE

HISTORICAL

SOCIETY

◆

Randall M. Thies
Ext. 267

E-mail:rthies
@hspo.
wpo.state.ks.us

◆

6425 S.W. 6th Avenue
Topeka, Kansas
66615-1099
PHONE# (913) 272-8681
FAX# (913) 272-8682
TTY# (913) 272-8683

◆

KANSAS HISTORY CENTER

Administration
Center for Historical Research
Cultural Resources
Education / Outreach
Historic Sites
Kansas Museum of History
Library & Archives

HISTORIC SITES

Adair Cabin
Constitution Hall
Cottonwood Ranch
First Territorial Capitol
Fort Hays
Goodnow House
Grinter Place
Hollenberg Station
Kaw Mission
Marais des Cygnes Massacre
Mine Creek Battlefield
Native American Heritage Museum
Pawnee Indian Village
Pawnee Rock
Shawnee Mission

25 May 1999

Francis Morris, Cultural Resources Director
Pawnee Tribe of Oklahoma
PO Box 470
Pawnee OK 74058

Dear Sir:

This letter is written to solicit your tribe's response with regard to identifying any sacred places or traditional cultural properties that might be located on lands owned, used, or impacted by the Kansas Army National Guard (KSARNG). Attached, you will find maps indicating those lands.

By way of explanation, the Guard contracted with the Kansas State Historical Society (KSHS) to carry out a cultural resources investigation of the KSARNG installation, which consists of numerous facilities scattered across the state. Most of these facilities consist of armories built in urban centers in the 1950s and 60s, although one larger area--the Regional Training Area (RTA) in rural Saline County is also included. Two other multiple-building facilities are located at Forts Leavenworth and Riley.

Naturally, the Guard does not want to inadvertantly impact or disturb any sacred places or traditional cultural properties important to Native Americans. We therefore ask that you inspect the accompanying maps and determine whether any of the indicated locations are regarded by your tribe as being sacred places or traditional cultural properties. If so, please contact me. If we have not heard from you in sixty days, we will assume that your tribe considers none of these locations to be sacred places or traditional cultural properties. I will also attempt to contact you by phone within that time to see if you have any comments. Thank you for your attention to this matter.

Sincerely,

Randall M. Thies

Pawnee Nation of Oklahoma

P.O. Box 470
Pawnee, Oklahoma 74058
PHONE: 918-762-2541
FAX: 918-762-4043

June 10, 1999

Mr. Randall Thies
Kansas State Historical Society
6425 S.W. 6th Avenue
Topeka, Kansas 66615-1099

Dear Sir:

In regards to your request for input Re: KSARNG Construction: 25 May 1999 I have gone over what Pawnee sacred sites, or burial grounds information I have, and I see no problems with the locations given on your maps.

As far as the Pawnee are concerned, there seems to be no problems with these locations.

Sincerely,

Francis Morris

Mr. Francis Morris, Coordinator
Pawnee Nation Repatriation Project

Xc: Repatriation Project
Repatriation Committee

KAW NATION

Drawer 50 • Kaw City, Oklahoma 74641 • (580) 269-2552

December 10, 1999

Randall M. Thies
6425 S. W. 6th Avenue
Topeka, Kansas 66615-1099

Dear Mr. Thes:

The Kaw Nation of Oklahoma would like to thank you for your patience in our response to your request. With the large number of sights you provided for review, it was in both our interests to be thorough. I would like to report that the maps you provided were very clear and easy to read and I have been able to make a determination regarding the Kaw Nations interest in your project. I am listing the county maps that are of interest to the Nation, Morris, Geary, Riley, Pottawatomie, and Doniphan Countys these are areas closely related to the Kaw People before removal to their home in Oklahoma. In regard to the listed reference, the small areas that are being considered within the county's do not seem to interfere in ceremonial or religious sites related to the Kaw Nation. However, if any artifacts or culturally affiliated material is uncovered we expect notification immediately. The Kaw Nation would like to add that though the areas listed are very important to them they also held territorial hunting lands that covered the northern half of the State of Kansas. They would like notification of any finds that may turn up. Thank you for your understanding and please call the Kaw Nation at 580-269-2552 and ask for Crystal Douglas NAGPRA representative or Wanda Stone CEO for the Kaw Nation.

Sincerely,

Crystal Douglas
NAGPRA Representative:
cc: Wanda Stone

EMPLOYMENT
AND TRAINING
ADMINISTRATION

CHEYENNE AND ARAPAHO TRIBES OF OKLAHOMA
MANPOWER PROGRAM

Post Office Box 67
Concho, Oklahoma 73022

Phone: 405/262-0345

September 29, 1999

Mr. Randall M. Thies
Kansas State Historical Society
6425 S.W. 6th Avenue
Topeka, KS 66615-1099

Dear Mr. Thies:

Your letter of September 28, 1999, has been received in our office (copy enclosed).

We appreciate your concern, however, please be advised that after a long illness, Virgil Franklin, Sr. passed away in January, 1998. We have continued to received correspondence addressed to Mr. Franklin, and we are making every effort to return a short letter informing offices and organizations of his passing. We regret that your office was undoubtedly overlooked.


Also, please be informed that our office has been forwarding NAGPRA correspondence to Gordon Yellowman, who has also been involved with NAGPRA. Mr. Yellowman serves as Home Improvement Program Director with the Cheyenne & Arapaho Tribes of Oklahoma and his address is P. O. Box 38, Concho, OK 73022.

Should you have any questions, please do not hesitate to contact our office. Thank you.

Sincerely,

Ella N. SpottedBird
JTPA Director

cc: Gordon Yellowman
File



ADMINISTRATION
&
MANAGEMENT

CHEYENNE AND ARAPAHO TRIBES OF OKLAHOMA

P.O. Box 38
Concho, Oklahoma 73022
(405) 262-0345

February 8, 2000

Randall M. Thies
Kansas State Historical Society
6425 S.W. 6Th Avenue
Topeka, Kansas 66615-1099

Dear Mr. Thies:

As per our telephone conversation, please consider this letter as a response to your letter dated May 25, 1999. With the information provided site location maps, it is extremely difficult to positively identify and indicate site locations, as regarded by our tribe, as sacred sites or traditional cultural properties. A more intensive review will have to be conducted, for the purpose of positively identifying sites.

However, for the purpose of granting a "notice to proceed" on conducting a cultural resources investigation of the KSARNG installations, please consider the following comments:

> The Cheyenne and the Arapaho tribes, both have historical sites within the State of Kansas. Such sites include camping sites, traditional hunting grounds, buffalo migration trails, battle grounds, and some ceremonial sites. Cheyenne and Arapaho "Dog Soldiers" were very active in the 1800's in regards to protecting territorial lands and maintaining freedom to roam their lands. Confinement to reservations was not considered by the Dog Soldiers, as a result they became known as renegades by military forces, and others. Dog Soldier camp sites, are scattered across the Kansas plains, evidence of stone tipi rings, indicated long period camping settlements. They always camped along rivers and creeks. Walnut Creek, is a sacred place, because, it is known that the Dog Soldiers, held numerous Sundance ceremonies along Walnut Creek. Medicine Lodge Kansas, is another sacred area/place of the Cheyenne and Arapaho, annual

sundance ceremonies, were held along this area. The Missouri River, is also an area of special interest to the Cheyenne and Arapaho. U. S. Army Forts, served as trading places, and receiving places of annuities goods granted to the Cheyenne and Arapaho.

With so many Cheyenne and Arapaho historic sites located within the state of Kansas, a potential of inadvertently discovering human remains, burial goods and burial grounds exists. Should this occur we, request that your office contact the Cheyenne and Arapaho Tribes of Oklahoma immediately.

I enjoyed talking with you and hope that this letter meets your needs, and I look forward towards working with you in future projects. Should you have any questions or should need further information, please feel to contact my office at (405) 262-0345 extension 111.

Respectfully,

Gordon Yellowman, Representative
Cheyenne and Arapaho Tribes of Oklahoma

cc: file

Iowa Tribe of Oklahoma

R.R. 1, Box 721
Perkins, Oklahoma 74059
(405) 547-2402
Fax: (405) 547-5294

Kansas State Historical Society.

RE:Kansas Army National Guard Letter of August 31 2000

Mr.Randall M. Thies.

The Iowa Tribe of Oklahoma is in receipt of your letter regarding the KSARNG lands.The counties that the Iowa Tribe of Oklahoma are interested in are Doniphan,Wyandotte,Atchison and Leavenworth.Any proposed, construction projects or any ground disturbance by the KSARNG we would like to be considered an interested party.

The only sacred sites we know about are on Fort Leavenworth but there might be sites on the other land that we are not aware of.

Thank you for this information.

Richard Black

Richard Black

Repatriation Representative

10-9-00

cc Marianne Long

KANSAS

STATE

HISTORICAL

SOCIETY

◆

Randall M. Thies
Ext. 267

E-mail:rthies
@hspo.
wpo.state.ks.us

◆

6425 S.W. 6th Avenue
Topeka, Kansas
66615-1099
PHONE# (913) 272-8681
FAX# (913) 272-8682
TTY# (913) 272-8683

◆

KANSAS HISTORY CENTER

Administration
Center for Historical Research
Cultural Resources
Education / Outreach
Historic Sites
Kansas Museum of History
Library & Archives

HISTORIC SITES

Adair Cabin
Constitution Hall
Cottonwood Ranch
First Territorial Capitol
Fort Hays
Goodnow House
Grinter Place
Hollenberg Station
Kaw Mission
Marais des Cygnes Massacre
Mine Creek Battlefield
Native American Heritage Museum
Pawnee Indian Village
Pawnee Rock
Shawnee Mission

11 October 2000

Richard Black, Repatriation Representative
Iowa Tribe of Oklahoma
RR 1 Box 721
Perkins OK 74059

Dear Mr. Black:

Thank you for your letter of 10-9-00. We certainly will consider the Iowa of Oklahoma an interested party with regard to Kansas Army National Guard (KSARNG) undertakings in Doniphan, Wyandotte, Atchison, and Leavenworth couties, as requested in your letter.

I do have one question concerning your statement about sacred sites at Fort Leavenworth. Do you mean that your tribe has a sacred site on the grounds of the KSARNG area at Fort Leavenworth, or is the site located somewhere else on the Fort Leavenworth military reservation? If there is a sacred site on KSARNG property, we naturally would like to know for sure, and would like to know its location if at all possible, so that the site can be protected.

Sincerely,

Randall M. Thies

enc: map of KSARNG Fort Leavenworth property

Iowa Tribe of Oklahoma

R.R. 1, Box 721
Perkins, Oklahoma 74059
(405) 547-2402
Fax: (405) 547-5294

Kansas State Historical Society
6425 S.W. 6th Avenue
Topeka,Kansas 66615-1099

RE:Letter of October 11 2000
KSARNG

Mr. Randall M. Theis
The Iowa Tribe does not know of any sites on KSARNG land at Fort Leavenworth .The concern we have with the lands at Fort Leavenworth is there might be unmarked graves on that land. A few months ago some unmarked graves were found belonging to the Deleware or one of their branchs .When constuction or earth moving is planed on a site like Fort Leavenworth there is a chance that graves might be found.

Thank you

Richard Black
Richard Black
Repatriation Representative
October 25 2000

CC Marianne Long.

Prairie Band Potawatomi Nation

GOVERNMENT CENTER
16281 Q Road • Mayetta, Kansas 66509
Ph. (785) 966-2255

November 2, 2000

Mr. Randall M. Thies
KANSAS STATE HISTORICAL SOCIETY
6425 SW 6th Avenue
Topeka, KS 66615-1099

Dear Mr. Thies:

I am writing to inform you that I am in receipt of your recent National Historic Preservation Act (NHPA), Section 106 and Section 110, related correspondence dated August 31, 2000.

After reviewing the contents or your recent mailing we would like to in from you that we have no objections to **KSARNG's Project Sites as listed in above dated correspondence.** At this time we are unaware of any historical cultural resources in the proposed development area. Although, we do request to be immediately contacted if any inadvertent discoveries are uncovered at anytime throughout the various phases of the project.

Also, please feel free to contact me at (785) 966-4019 or additional information can be faxed to (785) 966-4021. We look forward to working with you.

Respectfully,

Rey Kitchkumme
Historic Preservation Officer
Tribal Council Member
Prairie Band Potawatomi Nation

APPENDIX III.

ARMORIES AND OMS SHOPS: BASIC DATA

This appendix contains basic data about the 54 armories and one independent OMS shop in the KSARNG installation.

Dates given for construction of these facilities are derived from newspaper clippings or other such evidence, and/or from data provided from the Guard.

The exact designations of the various units that once used the facility were not always well documented. Uncertainties such as these are indicated by hypenations if the informant was relatively certain of the general identity of a unit (as in, for example, the -- Engrs), while a question mark was provided if the informant had some doubts about his memory of the unit identity.

Archeological potential is specified according to the following categories. If the armory occupies a thoroughly disturbed upland soil setting or sandy alluvium subject to alluvial reworking, or has been built on a significant amount of fill, the archeological potential is listed as "none." If the armory occupies an otherwise undisturbed upland setting for which no deeply buried archeological deposits can be expected, but within which isolated artifacts or archeological features could conceivably be present even though the topographic setting is not promising with regard to prehistoric settlement, the archeological potential is listed as "little or none." If the armory occupies Holocene-aged silty or loamy alluvium in which deeply buried prehistoric materials are possible (even if the topographic situation is not particularly promising), the archeological potential is listed as "low" or "low to moderate." No higher-level archeological potential was interpreted for the armories.

ABILENE ARMORY

Street address: 1009 NW 8th St, Abilene (Dickinson County) Kansas

Legal description: NE4 of NW4 of SE4 of Section 17, T13S, R2E

Date of completion: 1953

Construction materials: Limestone veneer over cinder block. Recently a new metal roof was installed over all but the drill floor.

Topographic/soil setting: Muir silt loam (a Holocene-aged alluvial soil on low terraces) bordering Mud Creek.

Archeological potential: low to moderate for buried prehistoric sites simply due to alluvial soil and proximity to creek

Current unit: Det. 1, 2nd Bn, 130 Field Artillery

Previous units:1960s: --Engrs; 1970s: Co A, 1/635 Armor; 1980s and early 1990s: Co A, 2/635 Armor

Location of previous armory: unknown

Recommended source for more detailed information: Earl Dean (former Bn administrator in 1950s; lives in Abilene); and Albert "Mac" McCulley of Hope KS.


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: During the cattle drives of the late 1800s, this area was reportedly the location of holding pens for cattle, with cowboys camping in this area as well.


ABILENE ARMORY
T13S R2E
USGS ABILENE 1964
T13S R1E
ABILENE
Abilene Field
ABILENE MUNICIPAL AIRPORT
Wright Airpark
Abilene Country Club
St Joseph Cemetery
Fairground
Trailer Park
Trailer Parks
Eisenhower Center
Sewage Disposal
SANTA FE
PACIFIC
UNION
CHICAGO
BM 1170
BM 1166
BM 1154
BM 1161
BM 1148
BM 1147
BM 1146
Well
Hospital
Quarry
GRANT
15
16
17
20
21

ATCHISON ARMORY

Street address: 405 N 17th St, Atchison (Atchison County) Kansas

Legal description: NE4 of SE4 of SW4 of Section 35, T5S, R20E

Date of completion: 1963

Construction materials: Brick veneer over cinder blocks

Topographic/soil setting:Sharpsburg silty clay loam and Armster clay loam (upland residual soils formed in loess; Sharpsburg on ridgetops and Armster on sideslopes)

Archeological potential: little or none

Current unit: Det. 2, B Batt., 2nd Bn, 130 Field Artillery

Previous units: Co D, 1/137 Inf in 1961;
became Co D, 2/137 Inf on 1 Oct 1964 (activated for Vietnam as part of 69th Bde 1968-69);
became Co B, 2/137 Inf on 1 Jan 1975;
became Det 1, Co D, 2/137 FA onl Sep 1985;
became Det 1, Co D, 2/137 Inf on 1 Mar 91;
became Det 1, Batt B, 1/130 FA on 1 Sep 92;
became (present unit) on 1 Oct 96.

Location of previous armory: unknown

Recommended source for more detailed information: Ron Bahr of Atchison (was in unit in 1961)


Notable artifacts: an M115 Artillery telescope pan (from a howitzer) in foyer; also an older artillery sighting device of unknown nomenclature

Monuments: none

Cannon or other weapons display: none

Artworks: Large wall mural (ca. 12 ft high and 34 ft long) on north wall of drill floor, created in 1964 or 1965 by unit member (signed V. Celano), with a Buffalo Soldier added in 1970s or 80s.

Other: Complex consists of six acres; a wooded area to the west of the armory has been used occasionally for ambush training.


USGS ATCHISON, WEST 1959
ATCHISON Armory
T. 5 S.
T. 6 S.
ATCHISON
Water Tank
Trailer Park
Amelia Earhart Stadium
Oak Hill Cem
Swimming Pool
Franklin Sch
Reisner Park
Tank
Sew Disp
Fairground Sch
Tanks
Maur Hill High Sch
Creek
Brewery
SANTA FE
TOPEKA
KANSAS AVE
MAIN ST
DIVISION ST
(ATCHISON EAST) 6963 II SE
ST. JOSEPH 20 MI. (VIA U.S. 59)
WINTHROP 1 MI.
4384
4383
4382
4379
32'30"

AUGUSTA ARMORY

Street address: 2115 Moyle, Augusta (Butler County) Kansas

Legal description: SE4 of NE4 of SE4 of Section 15, T27S, R4E

Date of completion: 1958

Construction materials: brick veneer over cinder blocks; new metal roof

Topographic/soil setting:Labette-Dwight complex, an upland residual soil complex formed in weathered clay, limestone, and shale

Archeological potential: little or none

Current unit: 226 Engr Co(H) attached to 891st Engr Bn

Previous units:unknown

Location of previous armory: unknown

Recommended source for more detailed information: Paul Tuttle of Augusta


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none


AUGUSTA
Drive-In Theatre
AUGUSTA ARMORY
Calvary Cem
Trailer Park
Cemetery
Radio Tower
Waterworks
OIL REFINERY
Sewage Disposal
WHITEWATER
AUGUSTA
WALNUT
RIVER
Lake
ST L - S F
2 LANE
WICHITA (COURTHOUSE) 19 MI.
KINGMAN 62 MI.
(SANTA FE LAKE)
1965 AUGUSTA 1979

BELLEVILLE ARMORY

Street address: 2003 E Frontage Rd, Belleville (Republic County) Kansas

Legal description: SE4 of SW4 of NE4 of Section 3, T3S, R3W

Date of completion: 1956; dedicated 15 March 1957

Construction materials: brick veneer over cinder blocks; new metal roof over all but central drill floor; all lower windows in building were recently replaced.

Topographic/soil setting: Hastings silty clay loam, an upland residual soil formed in loess.

Archeological potential: little or none

Current unit: Det 2, 995th Maintenance Company

Previous units:
In 1957: Batt B, 135 AAA Automatic Weapons Bn (SP);
Beginning 1 May 1959: 1st & 2nd Magazine Platoons, 170th Ordnance Company;
Also (dates uncertain):
170th Maint. Co.;
4th Combat Support Bn (MSB) in 1986;
735th Spt Bn; 169th Spt Bn (of 69th Inf Bde--called up for Viet Nam 1968-1969)

Location of previous armory: A statement in the armory archives indicates that "The unit meeting place [when organized as Batt B, 135 AAA AW Bn in 1950] was the building which is now the bowling alley [in Belleville].

Recommended source for more detailed information: former Captain (now retired General) Rueger; the armory also has a small folder of archival documents including historical supplement reports, a few newspaper clippings, and photographs most of which are not labeled.


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none


Creek
Radio Tower
BM 1563
Drive-In Theater
Trailer Park
Park
Belleville Armory
Belleville Cemetery
Harkness Cem
PACIFIC
West Sch
Belleville
Radio Tower
Hosp
Belleville Airport
BM 1591
Belleville Country Club
Cem
Riley
USGS Belleville 1966

BURLINGTON (FERGUSON MEMORIAL) ARMORY

Street address: 605 Garrison, Burlington (Coffey County) Kansas

Legal description: NW4 & SW4 of SE4 of SE4 of Section 22, T21S, R15E

Date of completion: 1954

Construction materials: brick veneer over cinder blocks. Small metal building located to northwest of armory.

Topographic/soil setting: Woodson silt loam, an upland residual soil formed in old alluvial sediment

Archeological potential: little or none

Current unit: Det 2, Batt A, 1st Bn, 127th Field Artillery Regiment

Previous units: 1951-1956: Batt B, 127 FA
also (uncertain dates): Batt C, 127 FA; and -- Military Police.
original organization: 114 Horse Artillery Regiment

Location of previous armory: Apparently a building at 3rd and Neosho in Burlington. According to retired Guardsman Leroy Brungardt, they met in a downtown building on Neosho Street (the local main street), south of the hardware building, in a building wherein Coffey County Insurance occupied the second floor.

Recommended source for more detailed information: Leroy Brungardt of Burlington. The armory files also contain a collection of a few old photographs and records pertaining to Guard activities in the early 1900s, and also some photos and records from the 1980s.

Notable artifacts: none

Monuments: Bronze plaque adjacent to portrait in foyer. Plaque relates life and importance of Arthur M. Ferguson (11 Dec 1877-20 Feb 1923) for whom the armory is dedicated. Ferguson, a Coffey County native, enlisted in the 20th KS Vol Inf in 1898, and over time rose in rank from private to colonel. As a First Lieutenant with the 36th USV Inf he received the Congressional Medal of Honor for action at Porac, Luzon, Philippines, although that is not clearly spelled out on the plaque (see attached sheet for plaque text).

Cannon or other weapons display: none

Artworks: In foyer, a portrait of Arthur Ferguson, signed "Domini"(no date is discernible)

Other: none


Addendum: the Burlington Armory plaque text reads as follows, with line breaks and capitalizations as depicted:

ARTHUR M. FERGUSON
11 Dec 1877--20 Feb 1923

To The Honored Memory of Colonel Arthur M. Ferguson For His Outstanding Service to the Community, State and Nation, Exemplifying the Highest Tradition of the National Guard.

He Enlisted in Company E, 20th Kansas Volunteer Infantry On 2 May 1898, At Leroy, Coffey County, Kansas, and Rose Steadily through The Ranks from Private to Colonel, Performing His Duties in a Manner Equaled by Few Men.

Colonel Ferguson Served in Combat Overseas With the 20th Kansas Volunteer Infantry During the Philippine Insurrection, Where He Was Cited For Gallantry in Action as a Corporal. Later Colonel Ferguson, Then a First Lieutenant, Performed a Deed of Daring Described as "Conspicuous as can be found in the Annals of War," and For Which He Received the Congressional Medal of Honor The Nation's Highest Decoration.


BURLINGTON
Burlington
Rock Cr
NEOSHO
RIVER
Gravel Pit
Gravel Pits
Gravel Pit
Gravel Pit
BURLINGTON ARMORY
Park
Park
Pk
Gaging Station
BM 1037
BM 1016
Fairground
Sewage Disposal
Mt Hope Cem
Graceland Cemetery
RAILROAD
OLD
Mathias Lake
Pit
RAILROAD
OLD
KANS. 57 & 99
(JOHN REDMOND DAM)
15
14
13
22
23
24
25
26
27
34
35
36
USGS BURLINGTON 1971
T 21S
T 22S

CHANUTE ARMORY

Street address: 3031 S Santa Fe, Chanute (Neosho County) Kansas

Legal description: SE4 of NE4 of SE4 of Section 32, T27S, R18E

Date of completion: 1957 (dedicated 25 February 1958)

Construction materials: brick veneer over cinder blocks; new metal roof over entire building; unattached metal shed located to west and north of armory.

Topographic/soil setting: Kenoma silt loam, an upland residual soil formed in old alluvial sediments

Archeological potential: little or none

Current unit: Det 1, Co C, 891st Engr Bn

Previous units: In 1954: 297th FA Bn;
beginning 13 May 1957: Batt B, 195th FA Bn
beginning 1 May 1959: Co B (-1 Plat)174th MP Bn;
beginning 1 Apr 1963: Co A(-), 174th QM BN (DS);
beginning 15 Dec 1967: Co C(-), 3d Bn, 137th Inf, 69th Inf Bde

Location of previous armory: unknown

Recommended source for more detailed information: David Fehr


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none


CHANUTE
Radio Tower (KKOY)
Quarry
Highland Park
Alcott Sch
Lincoln Sch
Jr High Sch
PO
Library
City Hall
Central Park
Murray Hill Sch
Katy Park
High Sch
Hutton Sch
Trailer Park
State Hospital
Hosp
Sewage Disposal
Martin Johnson Airport
County Community Junior College
Elmwood Cem
Westview Ch
Roosevelt Sch
Cem
ATCHISON TOPEKA AND SANTA FE
Greenlawn Cem
USGS CHANUTE 1973
Picnic Area
Picnic Areas
Santa Fe Lake
Little
OIL
CHANUTE ARMORY
Trailer Park
Sewage Disposal Pond
PIPELINE
T I O G
C A N V I L L E

CHERRYVALE ARMORY

Street address: 731 S Liberty, Cherryvale (Montgomery County) Kansas

Legal description: NE4 of SE4 of NE4 of Section 17, T32S, R17E

Date of completion: 1956

Construction materials: brick veneer over cinder blocks; unattached metal building located west of armory

Topographic/soil setting: Dennis silt loam, an upland residual soil formed in material weathered from shale

Archeological potential: little or none

Current unit: Det. 1, Co B, 891st Engr Bn

Previous units: 1953-1958?: Co A, 297th FA;
beginning 1958?: 74th QM;
in 1961-1962: Co A, 174th MP;
in 1968: Co B, 3rd Bn, 137th Inf Reg
beginning 1975?: 891st Engr Bn

Location of previous armory: "a mule barn downtown"

Recommended source for more detailed information: Retired Guardsman Joe Shepard of Cherryvale. Armory archives were reportedly moved to Coffeyville and then to Topeka.


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none


USGS CHERRYVALE 1962
CHERRYVALE ARMORY
Cherryvale
Oil Wells
Oil Wells
Sewage Disposal
West Sch
City Hall
High Sch
Fairview Cemetery
Logan Park
St Francis Xavier Cem
Water Tank
TREATY BOUNDARY
INDIAN
OLD
MAIN ST
4TH ST
PARK ST
5TH ST
6TH ST
7TH ST
9TH ST
10TH ST
ST LOUIS - SAN FR
A T & S F
CREEK
2.4 MI. TO JUNC. U.S. 169 & 160 (LIBERTY)
COFFEYVILLE (VIA U.S. 169) 17 MI.
6858 II NE
SCALE 1:24 000
1 MILE
32'30"

CLAY CENTER (RAHN MEMORIAL) ARMORY

Street address: 208 S 12th, Clay Center (Clay County) Kansas
Legal description: NW4 of SE4 (and NE4 of SW4) of SE4 of Section 8, T8S, R3E

Date of completion: 1955

Construction materials: brick veneer over cinder block; unattached metal building located to south of armory.

Topographic/soil setting: Muir silt loam, a Holocene-aged alluvial terrace soil

Archeological potential: low to moderate due to alluvial setting

Current unit: Det 1, HHC, 1st Bn, 635th Armor Regiment

Previous units: organized in 1947 as Co D, 137th Infantry Regiment;
beginning 30 Apr 1959: Earth Moving Platoon, Co A (891st Engr Bn?);
beginning 15 Apr 1961: Co B, 891st Engr Bn;
beginning 15 Dec 1967: Co B (-2 platoons),
beginning in early 1976?: 635th Armor*
*armory was closed "for a while, four or five years ago" [around 1994-95] according to current armory full-timer Sgt Sylvester.

Location of previous armory: unknown

Recommended source for more detailed information:former Guardsmen Oren Erickson (former officer in unit and administrator at armory). A typewritten five-page manuscript entitled "History of the Clay Center National Guard" was written by the current armory full-timer, Sgt Sylvester, and provided to KSHS on 25 March 1998.


Notable artifacts: none

Monuments: none other than the armory itself, named in honor of Brigadier General Roy M. Rahn.

Cannon or other weapons display: none

Artworks: Portrait (signed "Domini," no date) with small brass plate reading: "BG Roy M. Rahn, KNG, The Adj Gen of KS, 1923-1925." Rahn was a First Lieutenant when the first Clay Center National Guard unit was formed in 1908 as Co A, 1st Regiment, Kansas National Guard. The current armory is known as the Rahn Memorial Armory, as indicated by signage above the entrance.

Other: none


USGS CLAY CENTER SE 1964
CLAY CENTER ARMORY
CLAY CENTER
Greenwood Cem
Hospital
High Sch
Fairground
Sewage Disposal
Gaging Station
Drive-in Theater
Well
ABANDONED
PACIFIC
CHICAGO
REPUBLICAN
RIVER

COFFEYVILLE (WARK MEMORIAL) ARMORY

Street address: 3002 W 8th St, Coffeyville (Montgomery County) Kansas

Legal description: SW4 of SE4 of SE4 of Section 33, T34S, R16E

Date of completion: 1956; with significant modifications and additions at different times in the 1970s.

Construction materials: brick veneer over cinder block; new metal roof over all but the drill floor; large wood-frame foyer extension on front (south) end of armory; brick-clad cinder-block office addition in rear central portion of armory; and two-level wood-frame semi-permanent office complex built inside the armory on the northeast corner of drill floor. (The current foyer extension is reportedly a recent modification of the original foyer extension which had a "Mexican" stylistic motif.) Outside the armory, there is an unattached small metal building located at the northwest (rear) corner of armory; and an unattached brick-clad cinder-block two-bay story-and-a-half garage-style building located to north of west end of the armory.

Topographic/soil setting: Kenoma silt loam, an upland soil formed in old alluvium

Archeological potential: little or none

Current unit: Co B(-), 891st Engr Bn

Previous units:unknown date: 174th Supt Svc Bn;
from.1985- 1991 or 1992: Det ?, Co ?, 891st Engr Bn

Location of previous armory: unknown

Recommended source for more detailed information: none known; archives consist only of a few photos from the 1960s or 1970s.


Notable artifacts: none

Monuments: none except for the armory itself, named in honor of -- Wark, however it is of note that there is no plaque or display relating to the individual (Wark) for whom the armory is nominally dedicated according to signage above the entrance.

Cannon or other weapons display: none

Artworks: none

Other: none


RESTLAWN CEMETERY
COFFEYVILLE
Armory
Drive-In Theatre
Edgewood Sch
Hospital
COFFEYVILLE
Garfield Sch
Holy Name Sch
Whittier Sch
Jr High Sch
High Sch
McKinley Sch
Coffeyville College
Elmwood Cemetery
PACIFIC
MISSOURI
OVERLOCK
WARWICK RD
PINE
BUCKEYE
WALNUT
MAPLE
WILLOW
UNION
4TH
6TH
8TH
10TH
13TH
USGS COFFEYVILLE WEST 1979

COLBY ARMORY

Street address: 470 S Range, Colby (Thomas County) Kansas

Legal description: SE4 of NE4 of NE4 of Section 1, T8S, R34W

Date of completion: 1960

Construction materials: brick veneer over cinder blocks; unattached metal building located to west of north end of armory.

Topographic/soil setting: Keith silt loam, an upland soil formed in loess.

Archeological potential: little or none

Current unit: Det 2, 170th Maintenance Company

Previous units: Organized in 1949 as Batt C, 135th AAA AW Bn (SP), 35th Inf Div;
beginning 1 May 1959: 323rd Ord Co (DAS) attached to 110th Ord Bn (Ammo);
beginning 15 Dec 1967: 2nd Mag Plt, 169th Ord Co;
beginning 1976?: 995th Maint Co, later reorganized as current unit.

Location of previous armory: A building known as "the Old Opera House" at 285 W 4th in Colby was used when the unit was originally organized in 1949. Another local building known as "the Harrison Building" was used as a temporary replacement in the year prior to construction of the present armory.

Recommended source for more detailed information: Kenneth Messamore and Don Davis of Colby--Messamore was first full-timer and Davis was the second (from 1968-91). The armory archives has a complete set of unit history annual supplements, including an excellent summary history covering the period 15 Dec 49 through 31 Dec 67, prepared 9 Nov 69 by SFC Barnes and CW2 Linville. Information on the current armory is very minimal, however, referring mainly to the bond issue of 1956.


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none


MORGAN
Well
BM 3167
Prairie Dog Creek
Sewage Disposal CHICAGO
Young Park
Sacred Heart Cem
MURRAY AIRPORT
BM 3141
BM 3153
Drive-In Theatre
Sandpit
Kansas State University Experiment Station
St Thomas Hospital
Radio Towers
Fairground
BM 3133
Beaver Creek
COLBY ARMORY
Villa High Park
Colby Junior College
UNION PACIFIC
USGS COLBY 1967
R. 34 W.
(COLBY SE) 5762 I SE
0.7 MI. TO INTERSTATE 70
RUSSELL SPRINGS 38 MI.
12'30" R. 33 W.
SCALE 1:24000
1 MILE
7000 FEET
1 KILOMETER
CONTOUR INTERVAL 10 FEET
DOTTED LINES REPRESENT 5-FOOT CONTOURS
DATUM IS MEAN SEA LEVEL

CONCORDIA ARMORY

Street address: 2115 Airport Rd, Concordia (Cloud County) Kansas
Legal description: SE4 of NW4 of NE4 of Section 9, T6S, R3W
Date of completion: 1953 with major addition in 1955 (dedicated 30 May 55)
Construction materials: brick veneer over cinder blocks; metal roof over most of building; large long rectangular one-story office/storage/maintance section (with garage doors on east wall) was added to south of original structure; new windows were later added to offices on west wall of south addition.

Topographic/soil setting: Hastings silt loam, an upland residual soil formed in loess

Archeological potential: little or none

Current unit: Det 1, Batt A, 130th Field Artillery

Previous units: Organized in 1954 as Co A, 891st Aviation Engineer Battalion;
beginning 15 Jan 1957: reorganized as 891st Engr Bn (Const);
beginning 1 Feb 1972: reorganized as 891st Engr Bn;
beginning 1 Feb 1976: became Co A, 1st Bn, 635th Armor;
beginning 1 Jan 1977?: became Det 1, HHC, 1/635th;
beginning 1 Oct 1977: Det 1, Support Company, 1/635th;
beginning Oct 1985: Det 2, HHC, 2nd Bn, 635th Armor;
"recently" reorganized into current unit.


Location of previous armory: unknown

Recommended source for more detailed information:former CW2 Jim Cory of Concordia, who served as unit adminstrator and full-timer from 1961-1985. A several-paragraph account of the "National Guard in Cloud County," written by SSG Larry S. Eubanks is available in the 1993 Cloud County History Book compiled by the Cloud County Historical Society on file in Concordia at the Cloud County Historical Society museum and archives facility and at the Kansas State Historical Society in Topeka.

Notable artifacts: none
Monuments: In foyer, a marble plaque with laser photo and inscription as follows: IN LOVING MEMORY OF/SSG ROBERT RAY/"BOBBY"/ALDRIDGE/FEB. 16, 1963-JUNE 27, 1998/*He was a hometown boy who loved people and life./He worked for law and order, and democracy./He was a good soldier./*

Cannon or other weapons display: M60 tank, and an M110 self-propelled gun with eight-inch howitzer, located at some distance to west of armory, on east side of entrance road.

Artworks: none
Other: none.


CONCORDIA
BURLINGTON
ATCHISON, TOPEKA AND SANTA FE
MISSOURI PA
BM 1344
Notre Dame High Sch
Lincoln Sch
Fairground
Water Tank
Radio Tower (KNCK)
St Joseph Hospital
Park
Country Club
Nazareth Convent
Cem
Trailer Park
Hook Park
Cem
CONCORDIA ARMORY
BLOSSER MUNICIPAL AIRPORT
Radio Tower
Gravel Pit
Gravel Pit
USGS CONCORDIA 1980

SABETHA ARMORY AND OMS #5

Street address: 16th and Main, Sabetha (Nemaha County) Kansas

Legal description: SE4 of NE4 of SE4 of Section 1, T2S, R14E

Date of completion: 1953 for armory; detached OMS shop was reportedly constructed right after than armory

Construction materials: brick veneer over cinder blocks for both armory and OMS shop

Topographic/soil setting: mapped as Wymore silty clay loam (an upland soil formed in loess) but area has been landscaped and partially covered with fill and/or gravel

Archeological potential: none

Current unit: Det 1, HQ Batt, 2nd Bn, 130th Field Artillery

Previous units: in 1954: 154th FA Bn

Location of previous armory: unknown

Recommended source for more detailed information: former Guardsmen Larry Grossfield of Topeka (unit administrator for many years), and Bernard Wiltz of Sabetha (fomer Battery CO).


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none


SABETHA ARMORY
USGS SABETHA 1960
Albany Sch
Drive-In Theater
Pacific
Union
Roosevelt
High Sch
Sabetha
Hospital
Sewage Disposal
CEM
Sabetha M
Landing Fi
26
35
6
10

SALINA ARMORY AND OMS #10

Street address: 1127 Armory Rd, Salina (Saline County) Kansas

Legal description: SE4 of NE4 of SW4 of Section 14, T14S, R3W

Date of completion: 1956 (dedication in April 1957)

Construction materials: brick veneer over cinder blocks

Topographic/soil setting: Detroit silty clay loam, an alluvial soil that occurs along streamcourses on terraces subject to rare flooding

Archeological potential: low due to minimal nature of streamcourse (Dry Creek, which lies a quarter of a mile to the west)

Current unit: Batt F, 161st Field Artillery (since 1996?)

Previous units: at time armory was constructed: Co B, 891st Aviation Engr Bn; converted in 1959 to Co B, 891st Engr Bn; converted in 1963 to 891st Engr Co; converted in 1972 to Co D, 891st Engr Bn; converted in 1976 to Co B, 1st Bn, 635th Armor; converted in 1995 to Co B, 2nd Bn, 635th Armor

Location of previous armory: in 1951, at 134 S. 4th in Salina.

Recommended source for more detailed information:Larry Farmer (former CO, ret. Colonel); armory archives include one file of unit historical supplements and miscellaneous materials including list of WWII members of local Guard unit (HQ Batt, 130th FA).


Notable artifacts: none

Monuments: In foyer: framed typed text depicting life and military accomplishments of Brigadier General Herman F. Schuster; and a memorial plaque reading: Maj. Robert E. Turner/KIA 8 May 1969/.

Cannon or other weapons display: none

Artworks: in foyer: a portrait by Domini of Brigadier General Herman F. Schuster.

Other: This is a relatively large armory with more offices and storage space than most small town armories. And unlike the situation in most other such cases, the OMS shop is contained within (or as an integral part of) the Salina armory rather than being housed in a separate building.


SALINA ARMORY 40MSAHD
1965 SALINA 1978
SALINA
SALINA
SMOKY HILL
Dunbar Sch
Sandpit
Oil Tanks
PACIFIC
UNION
Whittier Sch
Washington Sch
Glenn Hill Sch
Oakdale Sch
City Hall
Hospital
South Park Sch
Crawford Avenue Sch
High Sch
Old Wells
Franklin Sch
Lowell Sch
Sunset Sch
Sunset Park
Heusner Sch
Kansas Wesleyan University
Wesleyan
Hageman Sch
St Mary Sch
Trailer Park
Drive-in Theater
Water works
Oakdale Park
Kenwood Park
MISSOURI
SANTA FE
OHIO
FRONT
IRON
WALNUT
ASH
ELM
PRESCOTT AVE
CRAWFORD AVE
FRANKLIN
REPUBLIC AVE
JEWELL
CLOUD
GYPSUM
PENN
BM 1229
BM 1237
1228
1227
1229
1230
1231
1232
1233
1235
1239
1240
1242
1244
Drive-In Theater

SMITH CENTER ARMORY

Street address: 101 Armory, Smith Center (Smith County) Kansas

Legal description: NE4 of NE4 of SW4 of Section 21, T3S, R13W

Date of completion: 1960; date of unattached metal building to north is uncertain but probably recent

Construction materials: brick veneer over cinder blocks; assembly hall has carpet on walls to enhance school basketball games which were emphasis of Leo Tuxhorn, longtime CO; armory also has unattached metal building which stands to north of armory building.

Topographic/soil setting: Harney silt loam, an upland soil formed in loess

Archeological potential: little or none

Current unit: HHC, 995th Maint Company

Previous units: at time armory was constructed: possibly 728th FA Bn; by 1961 through at least 1967, 169th Ordnance Co (Ammo); by 1980, 170th Maint Co; by 1985, Co D, 735th Ord Bn

Location of previous armory: unknown

Recommended source for more detailed information: Leo Tuxhorn of Smith Center


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: This armory is unique in that (it is said) it was designed to face east, but was built facing south because of decision by contractor who ignored previously placed survey stakes and "turned" the building during initial construction which took place when unit was away on annual training.



1565 SMITH CENTER 1973

ST. MARYS ARMORY

Street address: 100 S 5th St, St. Marys (Pottawatomie County) Kansas

Legal description: SE4 of NW4 of SW4 of Section 10, T10S, R12E

Date of completion: 1943 (dedicated 8 May 1943); however, cornerstones on both west corner walls read: Erected /1941/.

Construction materials: limestone blocks and concrete, with some glass block windows, and a metal marque over entrance; drill floor is hardwood over concrete; one (northernmost) office walls were covered with wood paneling in 1970s

Topographic/soil setting: Mapped as Chase silty clay loam, an alluvial soil that occurs along streamcourses on terraces made of silty or clayey Holocene aged alluvium, but the armory grounds have been so extensively landscaped or constructed on that no natural soil surfaces remain.

Archeological potential: none

Current unit: Det 1, 137th Transportation Company

Previous units: at time armory was constructed: HQ Batt, 161st Field Artillery; subsequently (when activated for Korean War in 1951) 174th Military Police; from 1954-1957: HHC, 174th MP Bn; in 1959: Co C, 137th Infantry


Location of previous armory: unknown

Recommended source for more detailed information: former Guardsman George Perry of Wamego (ret. Sgt Major and longtime member of St Marys unit)

Notable artifacts: none

Monuments: in foyer is a memorial consisting of a large wood plaque with small brass plates displaying names of St Marys servicemen, and a heading that reads: Roll of Honor/St Marys Pays Tribute to the Residents of/this Community Who Ansered the Call/ in World War II/; and on exterior of entrance, on one of the pillars flanked by entry doors, is a bronze plaque that reads: Members/City Commission/St. Marys Kansas/Grover C. Ulrbansky Mayor/H.F. Higgins/Paul H. Clark/M.E. Coleman City Manager:Clerk/--/W.E. Glover Architect/1942/.

Cannon or other weapons display: on grounds in front of armory is an M60 tank.
Artworks: none
Other: This armory is owned by the City of St Marys, which uses the basement for a city motor pool and maintenance shop. The armory no longer serves as a community center because it does not comply with ADA requirements.


ST. MARYS ARMORY
USGS ST. MARYS 1978
St Marys
Water Tank
Valley View Cem
Mt Calvary Cem
St Marys Seminary
Golf Course
Trailer Park
BM 960
BM 961
BM 944
BM 1156
BM 955
Pit
Miller Creek
College
Ronsse Landing Strip
LEVEE
PACIFIC
KANSAS
POTT CO

TOPEKA (NICKELL MEMORIAL) ARMORY

Street address: 2722 S. Topeka Blvd, Topeka (Shawnee County) Kansas

Legal description: NE and NW4 of NW4 of SW4 of Section7, T12, R16E

Date of completion: 1956

Construction materials: brick veneer over cinder blocks; new metal roof over entire(?) complex

Topographic/soil setting: mapped as Sogn-Vinland complex, an upland soil complex formed in shale and limestone, but area has been so affected by landscaping that no natural soil surfaces remain

Archeological potential: none

Current unit: HHB, 130th Field Artillery Bde; 714th Maint.

Previous units: unknown

Location of previous armory: prior to World War II, horse cavalry stables were west of current fairgrounds (now Expocentre).

Recommended source for more detailed information: no particular individual


Notable artifacts: none

Monuments: the armory itself, which in 1977 was dedicated in honor of General Nickell.

Cannon or other weapons display: none

Artworks: none

Other: This is one of the largest and most physically complex of the "Nickell armories," apparently eclipsed only by the Kansas City armory. Among other things, the Topeka armory boasts a firing range, located in the basement section of the building north of the drill floor.


USGS TOPEKA 1973
TOPEKA ARMORY
1 MILE
Childrens Park
Medford Park
St Francis Hospital
Stormont-Vail Hospital
Public Library
Washburn Park
Lowman Hall Sch
Methodist Home
Topeka High Sch
STATE CAPITOL
City Hall
County Ctr
Funeral Bldg
Plaza Park
Collins Parkway
Central Park
Shimer Park
WASHBURN UNIVERSITY
KANSAS NEUROLOGICAL INSTITUTE
Stout Sch
Quinton Hts Sch
Shunganunga Park
Shunga Parkway Cem
Topeka Country Club
Big Shunga Park
Oak Parkway
Yardley Jr High School
Avondale West Sch
Shaner Sch
Croix Park
Drive-In Theater
Woodall Park
Austin Park
Highland Park
Bentley Park
Shawnee Country Club
Avondale East
Adams Park
Highland Crest Park
PO
Armory
Park
Pk
BM 888
BM 895
BM 914
BM 920
BM 939
BM 951
BM 999
SANTA FE
WESTERN AVE
WASHBURN
BUCHANAN
FAIRGROUND
OAKLEY
VALLEY
GLEN
HUNTOOR
17TH ST
21ST ST
25TH ST
29TH ST
10TH
VAN BUREN
TOPEKA
PACIFIC
MISSOURI
INDIANA
KANSAS
Shunganunga Creek
South Branch
BR 917
(WAKARUSA)
PAULINE
42'30"
40'

TROY ARMORY

Street address: 530 W Jones, Troy (Doniphan County) Kansas

Legal description: SW4 of NW4 of NW4 of Section 20, T3S, R21E

Date of completion: 1953

Construction materials: brick veneer over cinder blocks; new metal roof over all but drill floor

Topographic/soil setting: Monona silt loam, an upland soil formed in loess

Archeological potential: little or none

Current unit: Det 1, Batt B, 2nd Bn, 130th Field Artillery

Previous units:at time armory was constructed, probably Svc Batt of 154th FA Bn; by 1964 converted to Batt C of 130th FA; at one time was Co B (AC) of 135th Trans Bn.

Location of previous armory: unknown

Recommended source for more detailed information: Mark Wiedmer or rural Troy; armory has relatively extensive scrapbook collection of old photos from WWI and WWII eras.


Notable artifacts: none

Monuments: On exterior wall flanking entrance is a granite panel or slab inset into the wall and reading: AD 1953/AL 5953/[Masonic emblem]/Grand Lodge/of Kansas/Bruce Newton G.M./.

Cannon or other weapons display: located on armory grounds to southwest of building is an M7 "Priest" self-propelled gun of World War II vintage. Stenciling indicates unit identity of "SVC BTRY/2D BGN 130TH.FA" while hand lettered text indicates "C BATTERY/2nd How.Battalion/130th Artillery." Markings on the upper surface of the gun breech read: Howitzer 105 mm M2A1 No. 16874/ORD. DEPT. U.S.A./HAINBELT Co. 1944/1060 LBS INSP.ALR/. A nearly illegible plate in the driver's compartment reads: 105 MM Howitzer Motor Carrier/ORD DEPT US ARMY/SERIAL NO. 1282/. A plate on the gun carriage reads: NO. 4967/MOUNT. HOW. 105 MM/M4/PARISH PRESSED STEEL CO/1945/CJI/.

Artworks: in foyer: portrait by Dahlberg of Col Clarence Blake; plate on frame reads: Colonel Clarence E. Blake, KNG/State Maintenance Officer/1964-/.

Other: none


C E N T E R
Troy
(BM 1099)
BM
1064
Park
Water
UNION
PACIFIC
Mosquito
Creek
St Charles Cem
Mount Olive Cem
R2E T3S
TROY ARMORY
USGS TROY 1972

WICHITA WEST ARMORY

Street address: 3535 W Douglas, Wichita (Sedgwick County) Kansas

Legal description: NE4 of SE4 of SW4 of Section 24, T27S, R1W

Date of completion: 1955

Construction materials: brick veneer over cinder blocks; new metal roof over entire building

Topographic/soil setting: Urban land-Canadian complex, an alluvial soil complex formed in loamy sediments on low terraces and floodplains

Archeological potential: little or none

Current unit: HQ & HQ Batt(-), 1st Bn, 161st Field Artillery

Previous units:635th Armor; 1st Bn of 137th Infantry

Location of previous armory: unknown

Recommended source for more detailed information: none known


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none


WICHITA
Wichita Douglas Ave Removal
Sandpit
Radio Towers (KLEO)
Trailer Park
Hadley Jr High Sch
Bryan Sch
Black Sch
BM 1317
BM 1310
Townhall
Radio Towers (KSIR)
Field Sch
Oil Well
Dodge Sch No 2
Mt Carmel Academy
West Douglas Park
Starkey Sch
Mayberry Jr High Sch
Lawrence Sch
Christ the King Sch
Drive-in Theater
Eureka Sch
Sacred Heart College
Beacon
Trailer Park
Sandpit
AIRPORT
SANTA FE
DOUGLAS
MAPLE
UNIVERSITY
HARRY
MURDOCK
CENTRAL
WICHITA (CH.) 3.1 MI.
EL DORADO 39 MI.
(WICHITA EAST) 6559 III NE

WICHITA EAST ARMORY

Street address: 620 N Edgemoor Drive, Wichita (Sedgwick County) Kansas

Legal description: SW4 of SW4 of SE4 of Section 13, T27S, R1E

Date of completion: 1955

Construction materials: brick veneer over cinder blocks; new metal roof over entire(?) building

Topographic/soil setting: Urban land-Farnum complex, an upland soil formed in ancient alluvium

Archeological potential: little or none

Current unit: HQ Troop Command; Det -, 242nd Engr Co (Dump Truck) of 226th Engr Bn (since early 1970s)

Previous units: at time armory was constructed: Troop Command, and 161st Field Artillery

Location of previous armory: unknown

Recommended source for more detailed information: no one known


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: This is a relatively large armory, although not rivaling Topeka or Kansas City.


USGS WICHITA EAST 1975
WICHITA (EDGEMOOR DRIVE) ARMORY
WICHITA
Wichita Park Cem
Old Mission Cem
WICHITA STATE UNIVERSITY
Crestview Country Club
WHITE CHAPEL CEMETERY
Substation
Fairmount Park
Carter Sch
Independent Sch
St Thomas Aquinas Sch
Price Sch
Maple Grove Cemetery
Highland Cemetery
MC DONALD PARK
Adams Sch
Harris Sch
Children's Home
Alcott Sch
Murdock Sch
Armory
Kapaun Sch
Wesley Hospital
Robinson Jr High
College Hill Sch
Hyde Sch
Eastborough
MINNEHA
WICHITA TWP
Blessed Sacrament Sch
College Hill Park
Redeemer Sch
Magdalen Sch
Sunnyside Sch
Calvary Cem
Water
BM
Tower
1396 STREET
121ST
FEET
(ANDOVER) 6559 II NW
10 ACRES 2.6 MI.
1 KOMADO 2.2 MI.

WICHITA SOUTH ARMORY

Street address: 3617 S Seneca St, Wichita (Sedgwick County) Kansas

Legal description: NE4 of NE4 of SE4 of Section 7, T28S, R1E

Date of completion: 1958, although 1957 is shown on cornerstone located along exterior wall in entry area; a two-bay garage-style maintenance shop located to northwest of armory is undoubtedly more recent.

Construction materials: brick veneer over cinder blocks for both armory and nearby maintance shop, with new metal roof over entire armory. Auxiliary building has similar roof.

Topographic/soil setting: Waldeck sandy loam, an alluvial soil formed in coarse textured alluvium found along streamcourses on low terraces or floodplains

Archeological potential: none due to alluvial reworking of soils in this area

Current unit: Co C and Co D, 2nd Bn, 137th Infantry; and Det 2, Co B, 169th Spt Bn work out of the armory, while the auxiliary building is used by Det 1, HHC, 2/137th.

Previous units: 1st Bn, 137th Infantry

Location of previous armory: unknown

Recommended source for more detailed information: no particular individual; armory apparently has no archives other than a few old photographs from 1931 in hallway exhibit case.


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none



edited, and published by the Geological Survey
ation with State of Kansas agencies
USGS and USC&GS

1000 0 1000 2000

WINFIELD ARMORY

Street address: 407 Harter St, Winfield (Cowley County) Kansas

Legal description: SE4 of SE4 of SE4 of Section 21, T32S, R4E

Date of completion: 1953

Construction materials: brick veneer over cinder blocks; new metal roof over entire building

Topographic/soil setting: Brewer silty clay loam, an alluvial soil formed in clayey alluvium along streamcourses on low terraces and floodplains

Archeological potential: low to moderate

Current unit: Det 1, 226th Engr Company

Previous units: 891st Engr Bn; 137th Infantry

Location of previous armory: unknown

Recommended source for more detailed information: no particular individual


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: This armory was used temporarily as a school in the 1950s or 60s while Irving Elementary was being completed (Irving is located across the street to the north).


WINFIELD
Courthouse
Trinity Sch
Webster Sch
St Johns College
Radio Tower
St Mary's Cem
Whittier Sch
Lowell Sch
Albright Park
Sewage Disposal
WINFIELD Armory
Gaging Station
Highland Cem
Picnic Area
Cowley Cem
Cup and Saucer Hills
WALNUT
Black
MISSOURI PACIFIC
Well
USGS WINFIELD 1979
RIVER

WICHITA OMS #3

Street address: 1201 S McLean Blvd, Wichita (Sedgwick County) Kansas

Legal description: NE4 of NE4 of SW4 of Section 29, T27S, R1E

Date of completion: 1959

Construction materials: brick veneer over cinder blocks.

Topographic/soil setting: Mapped as Urban land-Canadian complex, an alluvial soil complex formed in loamy alluvial sediments on low terraces and floodplains, but area was used for several decades as a city dump area.

Archeological potential: none

Current unit: [maintenance personnel]

Previous units: (same)

Location of previous armory: not applicable

Recommended source for more detailed information: no particular person


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: This is a long one-story gabled building with a flat-roofed office at one end, not an armory but rather a relatively extensive maintenance shop unassociated with any particular armory.


WICHITA
OMS#3
USGS WICHITA EAST 1975
ARKANSAS RIVER
Riverside Park
Central Riverside Park
Cow Town
Museum
Waterworks
Oak Park
Riverside Sch
Horace Mann Sch
Park Sch
St Francis Hospital
Wheatley Sch
Dunbar Sch
Douglas Sch
Emerson Sch
Central Sch
St Anthony Sch
Washington Sch
Athletic Field
Marrinson Sch
St Joseph Sch
Allison Hgh Sch
Franklin Sch
Seneca Park
Lawrence Field
Hospital
Masonic Home
Friends University
City Hall
Auditorium
Union Sta
Gagnon Sta
Hyde Park
Roosevelt Jr Hi
Willard Sch
McCormick Sch
West High Sch
Armory
Lincoln Sch
Lincoln Park
Linwood Sch
Henry Park
Stanley Sch
Alley Park
Barr Street Sch
Orville Wright Boys Sch
Longfellow Sch
Home for the Aged
Beulah Park
Gardiner Sch
Levy Sch
Woodman
Herrmann Park
Missouri Pacific
Santa Fe
Topeka
Broadway
St Francis
Pacific
Lincoln
Harry
Kinkaid
Funston
Zimmerly
Mt Vernon
Lydia
Pawnee
Maple
Brockway
Waterman
Cleveland
Central
Murdock
Washington
Cool Lodge
Meridian
Lang
Hillside
Seneca
Park
Blvd
Ave
St
1303
1305
1301
1296
1290
1291
1288
BM 1301
BM 1303
BM 1296
BM 1288
17
18
19
20
21
16
28
29
30
32
33
3
4

APPENDIX IV.

CANNONS, MONUMENTS, AND OTHER CULTURAL RESOURCES

Artifacts:

Atchison armory: an M115 artillery telescope pan from a howitzer, and an older artillery sighting device of unknown nomenclature.
Goodland: two Iraqi army helmets, a gas mask, an AK-47 rifle, and several Saudi coins and "dollars" from Operation Desert Storm.
Hiawatha:American flags and unit guidons flown by unit members in Korea and Vietnam, presentation sword given to BG Tritsch, and saber worn by Colonel Henry J. Weltmer
Horton: military hat belonging to father of one of unit members; book describing role of local Guard unit in WWI.
Hutchinson: (on semi-permanent loan) Japanese "knee mortar" shell from Saipan, 37 mm German shell from WWII, and German army dress hat with Nazi insignia
Iola: burial flag of local Guard member
Kansas City: flags and standards of different units associated with the armory
Kingman: WWII guidon of Company L, 137th Infantry Regiment, 35th Infantry Division.
Lawrence: framed charter for US Spanish War Veterans Camp 17; and framed American Legion "memorial" to Wilder Metcalf.
Mankato: briefcase, medals, and presentation saber of Brigadier General Wint Smith.
McPherson: American flag flown of date of activation (probably of 114th Cav, for Vietnam); and standard for CSC 1-137th Inf Mortar Section 1983-85.
Newton: books dated 1907, 1911, and 1917 detailing Infantry drill regulations and Guard duty requirements for NCOs and Privates.
Ottawa: WWI German helmet; WWI American helmet and uniform; a bugle awarded by American Legion; ammunition including 50-caliber and 30-caliber machine gun rounds, 37 mm and 20 mm antitank rounds, and 45-caliber pistol rounds.
Paola: 105 mm howitzer round, and an old mortar round.
Phillipsburg: 155 mm howitzer shell, and 90 mm howitzer shell.
Russell: Iraqui army AK-47 assault rifle from Operation Desert Storm

Monuments:

Burlington: bronze plaque for Colonel Arthur M. Ferguson, CMH
Fort Scott: bronze plaque for Charles Irving Martin, CMH
Garnett: wooden plaque for PFC Dean L. Gretencord, Vietnam KIA
Hays: granite panel honoring local Guard veterans of Vietnam and Operation Desert Storm
Hiawatha:bronze dedication plaque dated 1938, listing architect and city commisioners
Holton: bronze plaque on concrete block, honoring three unit members killed in Vietnam; and six trees with small bronze plaques honoring six individualVietnam MIAs and all other MIAs and POWs.

Horton: granite panel dedicating armory to Brigadier General Charles Brown, with additional Masonic notations; and limestone block with bronze plaque honoring J.C. Strube, Vietnam KIA.
Iola: bronze plaque detailing life and accomplishments of Major General Frederick Funston.
Kansas City: bronze plaque on Breidenthal Hall addition, paying tribute to [General] John W. Breidenthal.
Kingman: granite panel (containing time capsule) dedicated in 1937 to Company L, 137th Infantry, KNG.
Lawrence: bronze plaque detailing life and accomplishments of Brigadier General Wilder Metcalf.
Marysville: limestone slab indicating support for troops in Operation Desert Storm, flanked by 16-inch Navy artillery shell.
McPherson: wood plaque with photograph labeled SP4 Ronnie L. Herriman/KIA 1969; wood plaque with brass plates bearing individual names and larger plate dated 1988 dedicated to Members of Troop E/114th Cavalry mobilized in 1968; large bronze plaque dated 1938 memorializing Staff Sergeant Claude M. Nash.
Newton: large bronze plaque detailing life and accomplishments of Colonel Perry Milo Hoisington; wooden plaque memorializing Major Clifton K. Dalbons; three wooden plaques with brass plates honoring the local unit's Vietnam KIAs Captain Jose S. Llamas, SP4 George F. Martinez, and PFC Robert L. Boese.
Ottawa: wooden plaque placed in tribute to Captain Loren L. Leikam.
Salina: framed typed text detailing life and military accomplishments of Brigadier General Herman F. Schuster; and plaque memorializing Major Robert E. Turner, Vietnam KIA.
St. Marys: large "Roll of Honor" wooden plaque with brass plates listing names of those who served in WWII from St. Marys area; and bronze plaque dated 1942 listing architect and city commission members.

Cannon, Tanks, and Other Large Weapons:

Concordia: M60 tank, and an M110 self-propelled gun with eight-inch howitzer
Emporia: M60 tank
Garden City: 155 mm howitzer, Model 1918, modified 1941
Great Bend: Meiji 41 Japanese 75 mm cannon
Hutchinson: two fake cannons made of steel tubes on concrete bases with wooden wheels
Junction City: M60A3 tank
Kingman: M4A1 Sherman tank of Korean War vintage; and two Naval 32-pounder Civil War cannons
Liberal: three-inch field gun, Model of 1905, manufactured in 1907
Marysville: M110A2 self-propelled gun with eight-inch howitzer.
McPherson: M60 tank (said to belong to city)
St. Marys: M60 tank
Troy: M7 "Priest" self-propelled gun of WWII vintage

Artworks:

Atchison: large wall mural created 1964-65 by unit member V. Celano, with Buffalo Soldier added in 1970s or 80s.

Burlington: portrait by Domini of Colonel Arthur M. Ferguson
Clay Center: portrait by Domini of Brigadier General Roy M. Rahn
Fort Scott: portrait of Major General Charles Irving Martin
Hays: portrait by Dahlberg of General Edgar L. Degraw
Hiawatha: portrait by Dahlberg of Brigadier General W. Keith Weltmer, and portrait by Domini of Colonel Henry John Weltmer.
Holton: several murals of unit emblems, painted by unit members.
Horton: portrait by Domini of Major General Charles H. Browne; portrait by Wm Dickerson of Brigadier General Charles H. Browne, Sr; and portrait by Dennis McCarthy of First Sergeant Marvin J. Elkins.
Hutchinson: portraits by Dahlberg of Colonel Mortimer M. Hilleary, Colonel John W. Bennett, Colonel Guy C. Rexroad, Colonel Elmer L. Lentz, and Colonel Albert S. Bigelow; also six-foot-diameter hand-painted Seal of Kansas on wall of drill floor.
Iola: portraits by Dahlberg of Colonel Paul H. Cannady, Brigadier General Frederick Funston, and Brigadier General Johas D. Conderman; one-foot-diameter bronze Seal of Kansas
Kansas City: large wall mural by Colonel Vernassie; portrait by Rick Grimes of General Breidenthal; portrait by Jerry Bond of General Donn Starry; portraits by Dahlberg of General Breidenthal and Major General Wm. K. Herndon; portraits by Domini of Brigadier General Mahlon S. Weed, Major Paul A. Fall, Pvt. William B. Trembley, and Edward White; portrait by Bettes of Colonel Michael P. Sarras.
Mankato: portrait by Domini of Brigadier General Wint Smith.
McPherson: portrait by Wright of Major Robert E. Turner.
Salina: portrait by Domini of Brigadier General Herman F. Schuster.
Troy: portrait by Dahlberg of Colonel Clarence Blake.

List of Memorial Armories:

Burlington: Ferguson Memorial Armory (for Colonel Arthur M. Ferguson)
Clay Center: Rahn Memorial Armory (for Brigadier General Roy M. Rahn)
Coffeyville: Wark Memorial Armory (for -- Wark)
Fort Scott: Martin Memorial Armory (for Major General Charles Irving Martin)
Horton: Browne Memorial Armory (for Brigadier General Charles H. Browne, Sr.)
Iola: Funston Memorial Armory (for Major General Frederick Funston)
Lawrence: Metcalf Memorial Armory (for Brigadier General Wilder Metcalf)
Mankato: Wint Smith Memorial Armory (for Brigadier General Wint Smith)
Topeka: Nickell Memorial Armory (for Brigadier General Joe Nickell)

COUNCIL GROVE ARMORY

Street address: 1020 E Main St, Council Grove (Morris County) Kansas

Legal description: SW4 of NW4 of NE4 of Section 13, T16S, R8E

Date of completion: 1954 (dedicated 10 May 54)

Construction materials: brick veneer over cinder blocks

Topographic/soil setting: The location is mapped as Tully silty clay loam, an upland soil formed in colluvium or similar sediments, but the armory site has been cut into the steep slope of the upland ridge, destroying the natural soil situation.

Archeological potential: none

Current unit: Det 3, 731st Medium Truck Company

Previous units: At time of dedication, Service Batt, 127th Field Artillery;
recently: Det 2, 137th Transportation Co (PLS), 174th Corps Support Bn

Location of previous armory: unknown

Recommended source for more detailed information: none; reportedly no local archives


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none


T. 16 S.
COUNCIL GROVE LAKE
6661 II NE
(COUNCIL GROVE LAKE)
ELEVATION 1270
Boat Ramp
Dam Site Recreation Area
Council Grove Dam
Quarry
Quarry
Radio Tower
COUNCIL GROVE ARMORY
Drive-in Theater
Fairground
Gaging Site
Hospital
Council Grove
(BM 1233)
BM 1233
Sewage Disposal Ponds
Elm Creek
NEOSHO
RIVER
MISSOURI
OLD
Substation
BM 1230
Big John Creek
HERINGTON 24 MI.
WILSEY 11 MI.
120 000 FEET
USGS COUNCIL GROVE 1971

DODGE CITY ARMORY and OMS #13

Street address: 2120 First Street, Dodge City (Ford County) Kansas

Legal description: NW4 and NE4 of NE4 of SE4 of Section 23, T26S, R25W

Date of completion: 1959 (dedicated 14 Nov 59); the detached OMS shop was built at a slightly later date than the armory and in 1993 a new addition was constructed on the north part of that building.

Construction materials: brick veneer over cinder blocks (both armory and OMS shop); unattached metal building located east of armory and south of OMS shop.

Topographic/soil setting: Harney silt loam, an upland residual soil formed in loess

Archeological potential: little or none

Current unit: Batt B, 1st Bn, 161st Field Artillery

Previous units: when dedicated, HQ section of 130th Artillery Grp; and HQ Batt and Medical Detachment, First Howitzer Bn, 161st Artillery, according to newspaper article.

Location of previous armory: unknown

Recommended source for more detailed information: unknown


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none


Dodge City Armory
A265
R25W
USGS Dodge City 1978
DODGE CITY
BOUNDARY
Radio Towers (KEDO)
Radio Towers (KGNO)
Substation
Radio Tower
BM 2593
Northwest Sch
Jr High Sch
St Mary of the Plains College
Golf Course
Hospital
Greencrest Memorial Garden
Drive-in Theater
Trailer Park
Wright Park
Post Office
Courthouse
BM 2830
Lincoln Sch
Miller Sch
Sacred Heart Sch
Santa Fe
Canal
Chiller
1.1 MI. TO JUNC. U.S. 283 & 56
SUBLETTE (VIA U.S. 56) 52 MI.
FORT DODGE 3.8 MI.
MULLINVILLE (U.S. 54) 36 MI.
INTERIOR—GEOLOGICAL SURVEY, RESTON, VIRGINIA—1978
1 MILE
5000 6000 7000 FEET
1 KILOMETER
ROAD CLASSIFICATION
Heavy-duty
Light-duty

EMPORIA ARMORY

Street address: 1809 Merchant, Emporia (Lyon County) Kansas

Legal description: SE4 and SW4 of SE4 of SW4 of Section 3, T19S, R11E

Date of completion: 1955

Construction materials: brick veneer over cinder blocks; unattached metal building located across parking lot to south of armory

Topographic/soil setting: Clime-Sogn complex, a upland soil complex formed in material weathered from limestone and calcareous shale and found on ridgetops and sideslopes

Archeological potential: little or none

Current unit: A Co, 1st Bn, 635th Armor

Previous units: 169th Engr Co, which reportedly "marched from armory to railroad station and on to fly to Viet Nam" [in 1968].

Location of previous armory: unknown

Recommended source for more detailed information: unknown


Notable artifacts: none

Monuments: none

Cannon or other weapons display: M60 tank located in front of and to east of armory

Artworks: none

Other: none


USGS EMPORIA 1957
EMPORIA
Lyndon Valley Sch
Memorial Lawn Cem
St Marys Hospital
College of Emporia
Kansas State Teachers College
Walnut Sch
White Sch
Whitti Sch
County Fairgrounds
Herbert Sch
High Sch
J. High Sch
Civic Center
Hunson Park
Trenton Park
Sacred Heart Sch
Maynard Sch
St Catherine Sch
Kansas Ave Sch
Logan Ave Sch
Soden Dam
Radio Tower (KVOE)
Soden Park
Sewage Disposal
Emporia Junctio
BM 1124
BM 1144
BR 1117
BR 1101
EMPORIA
NEOSHO
COTTONWOOD
PRAIRIE
SUNNYSLOPE
CHESTNUT
WEST
ELM
SOUTH
MERRIMAC
OXFORD
DRIVE
MAPLEWOOD
CONSTITUTION
MARKET
EXCHANGE
SYLVAN
PEYTON
COMMERCIAL
RANDOLPH
LOGAN
POWIN
TA FE

FORT SCOTT (MARTIN MEMORIAL) ARMORY and OMS #12

Street address: 2301 Horton, Fort Scott (Bourbon County) Kansas

Legal description: SW4 of SW4 of NE4 of Section 6, T26S, R25E

Date of completion: 1955 (apparently the same date for both armory and OMS shop); metal building constructed in 1987

Construction materials: brick veneer over cinder blocks (both armory and OMS shop); unattached metal building located immediately north of northwest corner of armory

Topographic/soil setting: Catoosa silt loam, an upland residual soil weathered from limestone

Archeological potential: little or none

Current unit: Co C(-), 891st Engr Bn

Previous units: trophies and certificates in foyer case belong to several units:
HQ, 135th Trans Bn in 1949, 1959, and 1961;
195th FA Bn from 1949 through 1958;
894th Engr Co in 1963;
772 Engr Co, 226 Engr Bn from 1965 through 1972;
Det ?, Spt Co, 3rd Bn, 137th Inf, 69th Inf Bde in 1972
891st Engr Bn in 1979 and 1981.

Location of previous armory: unknown

Recommended source for more detailed information: unknown


Notable artifacts: none

Monuments: the armory itself, dedicated as Martin Memorial Armory; and a bronze plaque in the foyer, describing the life and and military accomplishments of Major General Charles Irving Martin (1871-1953). Martin reportedly served as a Major in the 20th Kansas Volunteer Infantry in the Spanish American War; as Brigadier General, 70th Bde, 35th Infantry Division in World War I; as Commanding General of 35th Infantry Division from 1932-1935; as Superintendent of the Kansas Soldiers Home in Leavenworth in 1923; and as Kansas Adjutant General from 1909-1917 and 1919-1923.

Cannon or other weapons display: none

Artworks: Portrait in foyer of Major General Charles Irving Martin.

Other: none


FORT SCOTT
ARMORY
USGS FORT SCOTT 1978
Bridal Veil Park
Courthouse
High Sch
Mercy Hospital
Fort Scott Jr College
Scott Sch
Gunn Park
Gravel Pit
Quarry
National Cemetery
Fort Scott Country Club
Radio Tower (KMDO)
York Sch
Reservoir
Sewage Disposal
Tank
RAILROAD
TEXAS
RIVER
KANSAS
MARMATON
Creek
SAN FRANCISCO
MILITARY
Road
Scott to

GARDEN CITY ARMORY

Street address: 405 S Main, Garden City (Finney County) Kansas

Legal description: SE4 of SE4 of SW4 of Section 18, T24S, R34W

Date of completion: 1958

Construction materials: brick veneer over cinder blocks; unattached metal building is located to west of north end of armory.

Topographic/soil setting: The location is mapped as Las-Las Animas complex, an alluvial soil complex formed in clay loam and sandy loam on the Arkansas River floodplain, but the armory itself is believed built on fill.

Archeological potential: none

Current unit: Batt A, 161st Field Artillery

Previous units: unknown

Location of previous armory: unknown

Recommended source for more detailed information: none known


Notable artifacts: none

Monuments: none

Cannon or other weapons display: Standing in front (to east) of armory along the highway is a 155 mm howitzer, model 1918, made by Schneider. A plate on the carriage indicates it to be a 155 mm howitzer carriage, M1917A4, derived from Rock Island Arsenal, 1941. An oval plate below reads: LSN/1522.

Artworks: none

Other: none


GARDEN CITY ARMORY
USGS GARDEN CITY WEST
GARDEN CITY
Finnup Park
FINNUP PARK
Fairground
Drive-in Theater
Swimming Pool
Gaging Sta
Radio Tower (KIUL)
Jr College
Hospital
Brown Sch
Hutchinson Sch
Matthew Sch
High Sch
Trailer Park
Valley View Cemetery
Sandpits
Sandpit
Gas Well
Wells
Well
Water
Tower
Sub Sta
ATCHISON TOPEKA AND SANTA FE
SANTA FE
FARMERS DITCH
EMERSON ST
MAIN ST
FAIR ST
OLIVE ST
JONES ST
KANSAS AVE
LAURA ST
FULTON ST
SHERMAN ST
CENTER ST
CEDAR ST
ELM ST
11TH ST
13TH ST
ST JOHN
MARIE ST
CAMPBELL ST
R 33 W
R 32 W
12
13
17
18
19
20
24
25
29
N C I T Y
REFUGE

GARNETT ARMORY

Street address: 510 N Lake Rd, Garnett (Anderson County) Kansas

Legal description: SW4 of SW4 of SE4 of Section 19, T20S, R20E

Date of completion: 1955 (dedicated 3 Dec 55)

Construction materials: brick veneer over cinder blocks; new metal roof over all but drill floor; unattached metal building located to north of armory

Topographic/soil setting: Catoosa silt loam, an upland residual soil formed in material weathered from limestone

Archeological potential: little or none

Current unit: Service Battery (-), 1st Bn, 127th Field Artillery

Previous units: In 1960-61: Co C, 135th Transportation Bn;
current unit designation by at least 1981

Location of previous armory: unknown

Recommended source for more detailed information: retired Guardsman Albert Herman of Garnett


Notable artifacts: none

Monuments: In foyer: wooden plaque with color photograph of, and smaller brass plaque indicating the whole to be a tribute to, PFC Dean L. Gretencord, USA, a member of the unit who died 26 September 1967 in Viet Nam.

Cannon or other weapons display: In foyer: one 155 howitzer dummy round and two powder cans

Artworks: none

Other: none


MONROE
Lake Garnett
LAKE
GARNETT
PARK
GARNETT CEMETERY
GARNETT ARMORY
Gravel Pit
Sewage Disposal
BM
High Sch
WT
PACIFIC
MISSOURI
GARNETT MUNICIPAL AIRPORT
Garnett
(BM 1049)
Sewage Disposal
BM 1032
OLD
RAILROAD
GRADE
OIL FIELD
Crystal Lake Park
Pottawatomie
Fork
South
BM 975
BM 982
WASHINGTON
WAVERLY 25 MI.
HARRIS 12 MI.
R20E
R19E
20 S.
21 S.
0000 FEET
USGS GARNETT EAST 1966

GOODLAND ARMORY

Street address: 720 E. Fairgrounds Rd, Goodland (Sherman County) Kansas

Legal description: SW4 of SE4 of SW4 of Section 8, T8S, R39W

Date of completion: 1989

Construction materials: brick (and some stucco) veneer over cinder blocks

Topographic/soil setting: Keith silt loam, an upland soil formed in loess

Archeological potential: little or none

Current unit: Det 1, 170th Maintenance Company

Previous units: none

Location of previous armory: In Goodland, the upper floor of the Coop building was rented for drill, and the city motor pool was used for vehicle and equipment storage

Recommended source for more detailed information: none


Notable artifacts: in office exhibit case: two Iraqi Army helmets, a gas mask, an AK-47 assault rifle, and several Saudi coins and "dollars" (all were acquired by the 24th Infantry Division during Operation Desert Storm and provided to the unit, which served in Saudi Arabia in 1990)

Monuments: none

Cannon or other weapons display: none other than the AK-47 listed above

Artworks: none

Other: none


Sappa
Fork
Goodland Cemetery
Fairgrounds
GOODLAND ARMORY
Well
Park
Sch
Courthouse
City Hall
Post Office
Goodland
Hospital
Gulick Park
Pk
Radio Tower KLOE
Powerplant
WT
Steever Park
Northwest Kansas Technical Sch
CHICAGO
BM 3692
BM 3696
BM 3704
Roadside Park
USGS GOODLAND 1974
2 LANE
2 LANE
Trailer Park
13
24
25
30
29
20
36
32
27
24

GREAT BEND ARMORY

Street address: 9571 D29 Way, Westport Industrial Park, Great Bend (Barton County) Kansas

Legal description: NW4 of SE4 of NW4 of Section 34, 19S, R14W

Date of completion: 1995 (dedicated Dec 95)

Construction materials: brick veneer over cinder blocks

Topographic/soil setting: Naron fine sandy loam, an upland soil formed in loamy eolian deposits

Archeological potential: little or none

Current unit: Det 1, Batt E (TA), 161st Field Artillery

Previous units: none

Location of previous armory: shared quarters with US Army Reserve at 19th and Williams in Great Bend

Recommended source for more detailed information: none

Notable artifacts: none

Monuments: none

Cannon or other weapons display: Located outside north door entrance: a World War II "trophy weapon" display; a Japanese 75 mm cannon known as a "regimental gun"and more specifically as a Meiji 41, serial number 1330, apparently made in June 1940 at the Osaka army artillery factory. More details on the cannon, efforts to identify it, and its original paint scheme can be found in two letters (see attached). Ownership of the cannon is a bit uncertain--it was reportedly found in recent years out behind the American Legion post at Redwing and retrieved from there by members of the Hoisington American Legion, and then given to the Great Bend National Guard as a sort of a permanent loan, with the American Legion reserving the right to use it in parades and other such functions.

Artworks: none

Other: This armory is located near the old Great Bend Drag Strip, which is listed on the Kansas Register of Historic Places. The drag strip is part of the old airport runway and is located to the northwest of the armory. Normal armory activities should have no effect on the drag strip.

KANSAS

STATE

HISTORICAL

SOCIETY

◆

Randall M. Thies
Ext. 267

E-mail:rthies
@hspo.
wpo.state.ks.us

◆

6425 S.W. 6th Avenue
Topeka, Kansas
66615-1099
PHONE# (913) 272-8681
FAX# (913) 272-8682
TTY# (913) 272-8683

◆

KANSAS HISTORY CENTER

Administration
Center for Historical Research
Cultural Resources
Education / Outreach
Historic Sites
Kansas Museum of History
Library & Archives

HISTORIC SITES

Adair Cabin
Constitution Hall
Cottonwood Ranch
First Territorial Capitol
Fort Hays
Goodnow House
Grinter Place
Hollenberg Station
Kaw Mission
Marais des Cygnes Massacre
Mine Creek Battlefield
Native American Heritage Museum
Pawnee Indian Village
Pawnee Rock
Shawnee Mission

30 November 1998

COPY
FOR YOUR INFORMATION

SFC Derek Slack
Kansas Army National Guard
9571 D 29 Way
Great Bend KS 67530

Dear Sergeant Slack:

My greetings to you and Gary Bainbridge and all the others out there who share an interest in the Japanese cannon currently on display outside the Great Bend armory. I am sure you will be pleased to learn that the cannon's markings have now been translated by University of Kansas graduate student Risa Ueda, for whom Japanese is her native language.

Risa's study confirms that the cannon is of Japanese origin. According to her translations the cannon is a Model (or in her words, "edition") 41 mountain artillery piece, made in June 1940 at the Osaka [army artillery] factory.

Further information is provided by the *Japanese Army Handbook 1939-1945*, by A.J. Barker (NY: Hippocrene Books, 1979). My understanding of this book is that the Great Bend cannon is a Meiji 41 (M1908). One main key to the cannon's identification, other than the model number, is what the book describes as the "peculiar" tubular construction of its single trail. This is certainly a distinguishing characteristic of the Great Bend cannon. Another characteristic of the Great Bend cannon which enables its identification as a Meiji 41 is its bore length of just over 50 inches, which correlates with the listed bore length of 17 caliber, or 50.15 inches.

To quickly summarize, the Meiji 41 was a 75 mm cannon that could be broken down into six pack animal transport loads. It was a "regimental" gun, with four issued to each infantry regiment. Along with the slightly smaller (70 mm) "battalion" gun, the Meiji 41 was deployed in the most forward areas.

I am enclosing a copy of Ms. Ueda's letter, pertinent excerpts from the *Japanese Army Handbook*, and copies of articles written about the other Japanese "trophy weapons" in the *Wamego Times*. It would be useful at this point to better document the sequence of events and people involved in the "rediscovery" of this cannon, beginning, as I understand it, with its retrieval from out behind the American Legion post at Redwing. With a little digging, we might be able to find out when it came to that location and possibly other information pertaining to its history. I suggest that you take all this information to your local newspaper--it should make an interesting article, one that might result in reminiscences about the cannon's origin while at the same time making the public aware of its significance.

In closing, let me reiterate some comments I made for the Wamego newspaper. War trophy weapons are a special kind of monument. They are not meant to glorify war or to commemorate the enemy who once used these weapons, but rather to commemorate the courage and sacrifice that it took to take them from that enemy. Monuments such as these honor the American efforts on the home front and in the field that resulted in the capture of these weapons and the vanquishing of the enemy. They are a monument to American valor and the American spirit. Individually and collectively, they are a unique element of our cultural landscape. There are only four Japanese trophy weapons known in Kansas; they are unique relics and deserve our attention and reflection.

As a postscript, most of these weapons also need restoration in the form of a new paint job using historically accurate colors. Fortunately, the Fort Sill Artillery Museum has provided just such color information, specifically for the Meiji 41. Enclosed is a copy of their letter.

My compliments to all the soldiers of your battery. The 161st Field Artillery is part of a proud long tradition of American artillerymen, and it is entirely appropriate that this unique artillery piece serve its final duty with you.

Sincerely,

Randall M. Thies

COPY
FOR YOUR INFORMATION

DEPARTMENT OF THE ARMY
HEADQUARTERS, U.S. ARMY FIELD ARTILLERY CENTER AND FORT SILL
FORT SILL, OKLAHOMA 73503-5100

REPLY TO
ATTENTION OF:

April 15, 1997

Fort Sill Museum
437 Quanah Road
Fort Sill, Oklahoma 73503-5100

Randy Thies
Kansas State Historical Society
6425 SW 6th
Topeka, Kansas 66615-1099

COPY

Dear Randy:

Concerning your inquiry about paint colors on the Type 38 Japanese Field Gun. Our only point of reference was for the Type 41 Field Gun which used three different colors in one third camouflage pattern or individually.


FS 30372	Khaki (basecoat)
FS 30219	Brown
FS 34151	Green

While the combination of all three colors has been used on the Type 41, we feel the colors may have been used individually on the Type 38. The data is very sparse on this weapon.

Hope this helps.

Sincerely,

Towana D. Spivey
Director, Fort Sill
Museum


BUFFALO
GREAT BEND MEMORY
GREAT BEND AIRPORT
BM 1882
Shady Grove Sch
County Home
LEVEE
TOPEKA
ATCHISON
Santa Fe Road
ARKANSAS
BM 1876
BM
USGS GREAT BEND 1974

HAYS ARMORY and OMS #1

Street address: 200 S Main, Hays (Ellis County) Kansas

Legal description: NE4 of SW4 of NW4 of Section 4, T14S, R18W

Date of completion: 1956

Construction materials: brick veneer over cinder blocks

Topographic/soil setting: Roxbury silt loam, an alluvial soil located on natural terraces along major streamcourses

Archeological potential: low to moderate for buried prehistoric remains due to the soils and topographic setting adjacent to Big Creek; and moderate potential for the finding of isolated historical artifacts resulting from use of this area by soldiers associated with Fort Hays during the Indian Wars era. The limited archeological potential of this site for containing historic artifacts derives from the armory's location between Big Creek and the old downtown area which once offered saloon entertainment to soldiers from nearby Fort Hays. Soldiers are thought to have used the wooded Big Creek area as a sort of early-day park, retiring there after a hard evening in the saloons. On occasion, these visits apparently resulted in lost equipment. Although the evidence appears to be mostly anecdotal, a "sword" (quite possibly a mis-identified bayonet) and a pistol have reportedly been found in recent years in unspecified locations within the city park, known more formally as Frontier Historical Park, which now occupies the creek area. The armory, due to its relatively close proximity to this area, could conceivably have a few of these items buried beneath the surface of its grounds.

Current unit: HHD(-), 174th Combat Spt Bn; 995th Maint Co; 174th Ord Maint Bn; and 731st Trans Co.

Previous units: When first opened, the armory is said to have housed HQ Co, 135th AAA AW Bn; later an artillery unit may have been there; and later the 995th Maintenance Company (DS) in the years 1969, 1974-75, and 1983 according to newspaper clippings at the Ellis County Historical Society. A monument at the armory also lists the 995th as a local unit (serving then in Vietnam) in May 1968.

Location of previous armory: basement of the then-incomplete Hays City auditorium just prior to construction of the present armory, according to undated newspaper clipping at Ellis County Historical Society.

Recommended source for more detailed information: former Guardsman (and local unit administrator for 25 years) Delbert Leiker of Hays.There are no archives at the armory. There was apparently a hiatus of Guard use of the building, and when the present unit(s) moved here from elsewhere in 1991 they found, with regard to local archives, that "it was like nothing was ever here."

Notable artifacts: none


Monuments: Inset into exterior north-facing wall at enrance to armory is a rectangular granite panel reading (all upper case letters): To Honor/Those Who Served/Vietnam/995th Maint. Co./13 May 1968/Operation Desert Storm/170th Maint. Co./29 November 1990/.

Cannon or other weapons display: none

Artworks: in the foyer: a portrait by Dahlberg of General Edgar L. DeGraw, former Kansas Adjutant General, who was commanding officer of Hays National Guard in 1950.

Other: none

E INTERIOR
RVEY



HIAWATHA ARMORY

Street address: 108 N First, Hiawatha (Brown County) Kansas

Legal description: SE4 of NE4 of NE4 of Section 29, T2S, R17E

Date of completion: 1940

Construction materials: cast concrete with some interior brick veneer; two story building with basement, and interior garage bays along north wall; some interior wood paneling on walls of upstairs "museum" room; flat concrete roof over all but drill floor which has metal trusses supporting recently redone roof which also created insulated dropped ceiling

Topographic/soil setting: Mapped as Grundy silty clay loam, an upland soil formed in loess, but in reality there are no undisturbed soils on the property due to the effects of construction and filling.

Archeological potential: none

Current unit: HHB(-), 2nd Bn, 130th Field Artillery

Previous units: Initially a Naval Reserve unit was reportedly housed here, and the Boy Scouts are said to have had a room. Newspaper clippings from 1938 refer to the 130th FA, and local informants believe the 154th FA also was associated with the armory in later years.

Location of previous armory: unknown


Recommended source for more detailed information: no specific individual; however, a number of Guardsmen have been associated with the armory. Apparently the armory has minimal archives other than recent photos.

Notable artifacts: several American flags and unit guidons flown by unit members in Korea and Vietnam; presentation sword given to Brigadier General Leo D.Tritsch; saber worn by Colonel Henry J. Weltmer.

Monuments: Rectangular bronze plate or plaque inset into exterior wall outside entry at head of stairs reads: Hiawatha Armory/1938/Constructed by the City of Hiawatha/and the/Works Progress/Administration/ Newton Reynolds/Mayor/John McKnight/Commissioner/Mart Banum/Commissioner/Robert Reynolds/Architect/Paulette & Wilson/Engineers/.

Cannon or other weapons display: none

Artworks: In "museum" room: a portrait by Dahlberg of Brigadier General W. Keith Weltmer, Asst Chief of Staff, KNG 1967-1979; and a portrait by Domini of Colonel Henry John Weltmer, Commanding Officer, 2nd Bn, 130 FA, 1925-1940.
Other: none


HIAWATHA ARMORY
USGS HIAWATHA 1969
HIAWATHA
Sewage Disposal
Cemetery
Courthouse
Hospital
High Sch
Armory
Water
Drive-In Theater
Hiawatha Country Club
Lake Hiawatha
Wells
BM 1048
BM 1436
UNION PACIFIC
MISSOURI
KANSAS AVE
OKLAHOMA
IOWA
SHAWNEE ST

HOLTON ARMORY

Street address: 1008 W 4th St, Holton (Jackson County) Kansas
Legal description: NE4 of NE4 of NE4 of Section 9, T7S, R15E
Date of completion: 1973
Construction materials: brick veneer over cinder blocks
Topographic/soil setting: Pawnee clay loam, an upland soil formed in glacial till
Archeological potential: little or none

Current unit: Batt C(-), 1st Bn, 127th Field Artillery, 130th Field Artillery Brigade

Previous units: At time of construction, Det 1, Co B, 2nd Bn, 137th Infantry;
in 1980: Det 2, Co B, 2/137th;
in January 1985: Det 1, Co B, 2/137th;
in September 1985: Co D, 2/137th;
in 1991: Co D(-), 2/137th;
in 1992 (to 1996): Batt A(-), 2nd Bn, 130th Field Artillery.

Location of previous armory:Skating rink on second floor of building in downtown area a block west of courthouse square.

Recommended source for more detailed information: former Guardsman Don Hamlin and current Guardsman Brad Stoeffer (former full timer at armory)


Notable artifacts: none

Monuments: Just outside entrance on north side of building: bronze plaque placed on sloping upper surface of concrete block, reads (all upper case): In Memory Of/Dale L. Milbradt/Kansas/1st Lt Co B 16 Inf 1 Inf Div/Vietnam BSM-PH/Aug 21 1943 April 11 1969/Kerry Hess/Kansas/1LT Co A 5 Cav 1 Air Cav Div/Vietnam SS-BSM-AM-PH/June 7 1945 Jun 5 1969/Floy Charles Nevins/Kansas/Sgt Co B 596 Inf 101 Abn Div/Vietnam BSM-PH/Nov 10 1947 May 15 1969/Remembered by/2nd RWP Co b 2/137th Inf 69 Bde/.
"Living monuments" are also found in the form of six trees planted in various locations to the front and sides of the armory, with small bronze plaques on concrete pads on the ground in front of them. The trees are dedicated to Sgt Larry Welsh, Capt Dennis Pugh, T/Sgt John Q. Adam, Capt Glenn McCubbin, Capt Michael Donovon, and Capt Patrick Harrold, whose names are found on the plaques which read as follows (all upper case): The Freedom Tree/With the Vision of Universal Freedom/For All Mankind/This Tree is Dedicated to/[name]/and All/Prisoners of War/and/Missing in Action/1973/.

Cannon or other weapons display: none

Artworks: several murals (of unit emblems) on wall of drill floor, painted by unit members

Other: none


HOLTON
Elk
Creek
Banner
Creek
Trailer Park
Golf Course
ROCK ISLAND
CHICAGO
AND
BM 1035
BM 1020
BM 1091
F R A N K L I N
HOLTON KANSAS
USGS HOLTON 1978

HORTON (BROWNE MEMORIAL) ARMORY

Street address: 444 E 15th Street, Horton (Brown County) Kansas

Legal description: SW4 of SE4 of SW4 of Section 28, T4S, R17E

Date of completion:1954

Construction materials: brick veneer over cinder blocks; new metal roof over drill floor

Topographic/soil setting: Shelby clay loam, an upland soil formed on glacial till and thin loess deposits, but armory sits on slight elevation composed of fill dirt

Archeological potential: none

Current unit: Batt B, 2nd Bn, 130th Field Artillery

Previous units: at time armory was built: Batt C, 1/154th FA;
reorganization produced current unit in 1963;
in 1970 the Battery headquarters was located here.


Location of previous armory: unknown

Recommended source for more detailed information: former Guardsman Marvin Elkins of Horton. Local archives are believed to have been destroyed.

Notable artifacts: in foyer exhibit case: military hat belonging to father of one of unit members; and book (published by company operated by MG Browne) entitled "Our Part in the Great War" portraying the part played in WWI by the local National Guard unit.

Monuments: the armory itself, dedicated to General Charles Browne, Sr., as evidenced by signage above entrance and by rectangular granite panel inset on the exterior wall flanking the entrance to the armory and incised as follows (all upper case): Browne Memorial Armory/Dedicated To/Brigadier General Charles H. Browne/July 6, 1881 [Masonic Symbol] June 13, 1951/This Corner Stone Laid By/M[three dots in triangular arrangement] W [same dots] Grand Lodge A F and A M of Kansas/A D 1953 A L 5953/.
Also, in front of the armory with a tree nearby to the south is a dressed limestone block with rectangular bronze plaque reading (all upper case): This Tree In/Memory of/J.C. Strube/K-I-A Viet Nam/6-11-69/American Legion V.F.W/Post #7 Post #3021/Post #373/.

Cannon or other weapons display: none
Artworks: in foyer, portrait by Domini of Major General Chas H. Browne; portrait by Wm Dickerson (1954) of BG Chas. H. Browne Sr, 1881-1951; and portrait (unsigned, but verified as being done by a Benedictine College art professor, Dennis McCarthy) of 1SG Marvin J. Elkins.
Other: none


Mission Lake Camp
Lakeview Country Club
Mission
Horton Municipal Airport
HORTON AIRWAY
SPILLWAY 1048
Municipal Reservoir
Water
Horton
High
Hospital
CEM
Water
Sewage Disposal
BROWN CO
ATCHISON CO
INDIAN BOUNDARY
Otter Creek
Grasshopper Creek
USGS HORTON 1961
GRASSHOPPER

HUTCHINSON ARMORY AND OMS #4

Street address: 1111 N Severance, Hutchinson (Reno County) Kansas
Legal description:SE4 of SE4 of NW4 of Section 7, T23S, R5W

Date of completion:1958 for armory, with 1957 indicated by cornerstone located on exterior wall near entrance. The OMS shop is thought to have been built a couple years after the armory, probably around 1959 or 1960.

Construction materials: brick veneer over cinder blocks for both armory and OMS shop. The armory has a new metal roof over apparently the whole complex.
Topographic/soil setting: Naron fine sandy loam, an upland soil formed in wind-modified sandy outwash and eolian deposits; and Carwile-Farnum fine sandy loam, an upland soil complex formed in outwash sediments of Pleistocene age.

Archeological potential: little or none

Current unit: HQ and HQ Batt, 35th Division Artillery; and Service Batt, 1st Bn, 161st Artillery

Previous units: 130th FA Group

Location of previous armory: unknown

Recommended source for more detailed information:none known


Notable artifacts: in foyer exhibit case, but on loan: a Japanese "knee mortar" shell from Battle of Saipan in WWII; a 37 mm German shell from WWII; and a German Army dress hat with Nazi insignia from WWII.

Monuments: none

Cannon or other weapons display: none, although two rather obviously fake cannons stand outside entrance to armory. They were made locally with steel "tubes" placed on concrete bases with fake wooden wheels.

Artworks: along the south wall of office corridor at south end of building: five portraits by Dahlberg with labels (brass plates) reading as follows: Col. Mortimer M. Hilleary/KNG/Commander 1965-1974/130th FA GP/; Col. John W. Bennett/Commander 1947-1961/1st Bn, 130th FA/; Col. Guy C. Rexroad/Commanding Officer 1928-1940/130th FA Reg/; Col. Elmer L. Lentz/Commander 1947-1951/130 FA GRP/; Col. Albert S. Bigelow/Asst Adj Gen/KNG/. The armory also has a hand-painted Seal of Kansas (six foot diameter) on the west wall of the drill floor, above the stage.

Other: This armory is somewhat unique in having a small arms range, and in having a small dais or stage at the west end of the drill floor.


HUTCHINSON
STATE FAIRGROUND
Morgan Sch
St. Elizabeth Hospital
Roosevelt Sch
Johnson Park
Liberty Sch
Graber Sch
Jr College
Jr High Sch
Grace Hospital
Allen Sch
Northside Sch
Central Sch
McCandless Sch
Central High Sch
Grandview Park
Grandview Sch
Sherman Sch
Sylvan Park
Ave A Sch
Water
City Hall
Wilson Sch
Eastside Cemetery
Reformatory
Elmdale Park
Salt Wells
Sandpits
HUTCHINSON
TOPEKA
SANTA FE
ROCK ISLAND
BM 1536
BM 1538
BM 1529
BM 1526
BM 1524
USGS HUTCHINSON, 1978
HUTCHINSON Armory Photo #4

IOLA (FUNSTON MEMORIAL) ARMORY AND OMS #2

Street address: 1021 N State, Iola (Allen County) Kansas

Legal description: NW4 of SW4 of NW4 of Section 26, T24S, R18E

Date of completion: 1954 for original armory; major alteration and addition begun in 1998 and completed in 2000

Construction materials: original construction of armory and OMS building was brick veneer over cinder blocks; new armory addition is roughfaced cinder block

Topographic/soil setting: Zaar silty clay, an upland residual soil formed in material weathered from shale.

Archeological potential: little or none

Current unit: HQ and HHC(-), 891st Engineer Bn

Previous units: At time of construction: believed to be HHB, 195th FA Bn;
in 1959: HHC, 195th Engr Grp:
in 1967 (to 1976): HHC?, 3rd Bn, 137th Infantry.

Location of previous armory: unknown

Recommended source for more detailed information: former Guardsmen Alfred Link of Chanute and Carl Harder of Yates Center


Notable artifacts: in foyer case, burial flag of Thomas Wells, given to local Guard unit at time of his death and funeral on 26 June 1975 in Iola (Wells was a former Guard member who was 97 years old at time of death--funeral involved full military honors by local guard unit)

Monuments: rectangular bronze plaque describing life and accomplishments of Brigadier General Frederick Funston

Cannon or other weapons display: none

Artworks: in office area: portrait by Dahlberg of Col Paul H. Cannady, Commanding Officer, 1035-1940, 127 FA Reg; in foyer: two portraits by Dahlberg of Brigadier General Frederick Funston and Brigadier General Jonas D. Conderman (KSARNG, 1933-1974), and on exterior entrance wall is a cast bronze Seal of Kansas (ca. one foot diameter).

Other: The new addition will nearly triple the size of the armory by creating new classrooms, restrooms, storage areas, administrative offices, and break area in addition to upgrading and remodeling the existing kitchen, restroom, classroom, office, and supply space.


IOLA ARMORY & AMS #2
Oil Well
Radio Tower
Horville Sch
Womack Landing Strip
HIGHLAND CEMETERY
Gravel Pit
Lincoln Sch
Waterworks
Courthouse
High Sch
Jr High Sch
Hospital
IOLA
Gravel Pit
Fairgrounds
RIVERSIDE PARK
McKinley Sch
Oil Wells
Oil Wells
Sewage Disposal
Elm Creek
Lake Bassola
QUARRY
Park
Sewage Disposal Ponds
Bassett
Iola Cem
Radio Towers (KALN)
Gas Well
SANTA FE
22
23
24
25
26
27
34
35
36

JUNCTION CITY ARMORY

Street address: 500 Airport Road, Junction City (Geary County), Kansas (east edge of Freeman Field, Junction City Municipal Airport).

Legal description: SW4 of NE4 of NE4 of Section 2, T12S, R5E

Date of completion: 1958; dedicated 7 May 1959. A new one-story addition was added in 1985, consisting of offices and supply rooms attached to the south wall of the original armory and wrapping around a portion of the west wall.

Construction materials: brick veneer over cinder blocks; unattached metal storage building located northwest of armory. New metal roof was placed on original armory building in 1999.

Topographic/soil setting: Muir silty clay loam, an alluvial soil found on second bottoms of major rivers. Armory was built on one foot of fill dirt.

Archeological potential: low to moderate

Current unit: D Company, 1/635th Armor

Previous units: The modern-day Guard unit was organized in June 1955 as C Company, 226th Engineer Aviation Battalion. By 1958 it had been redesignated as C Company, 891st Engineers. In 1972 it became Headquarters and E Troop, 114th Cavalry, 69th Infantry Brigade. In 1985 it attained its present unit designation.

Location of previous armory: Beginning in 1955, prior to the construction of the present armory, the local Guard unit used a building located nearby at 339 W 18th. Currently serving as the Junction City Little Theater, the building was originally built by the WPA in 1943 as a USO hall for African-American servicemen in training at Fort Riley. The building burned in 1948, was rebuilt in 1949, and then served again as a USO hall for an uncertain amount of time.

Junction City had earlier Guard units, but most of the earlier armory locations are unknown. Information on perhaps the first local armory was obtained from Gaylynn Childs, Director of the Geary County Historical Society (personal communcation with author, 10 February 2000). In 1917, the local Guard unit (C Company, 3rd Kansas Infantry Regiment) used the upstairs room of a building at 216 W 7th in Junction City. The location is probably just west of the current Municipal Building. Although the old armory building no longer exists, a photograph in the archives of the County Historical Society and the State Historical Society shows the local unit lined up in front of the building just prior to marching off to participate in World War I. The photograph (see Figure 15) is believed to be the oldest photograph of an armory in Kansas.

Recommended source for more detailed information: Former First Sergeant Jim Bolen of Junction City. The unit also has archives consisting of four loose-leaf notebooks containing a few newspaper clippings and numerous unlabelled photographs of unit activities.


Notable artifacts: none

Monuments: none

Cannon or other weapons display: An M-60A3 tank located on a concrete pad immediately southeast of the armory.

Artworks: none

Other: none


JUNCTION CITY ARMORY
Republican Flats
JUNCTION CITY MUNICIPAL AIRPORT
Trailer Park
Beacon
Ravine
Price
Municipal Athletic Field
JUNCTION CITY
Washington Grade School
Oil Tank
Gas Tank
City Waterworks
Water Intake
Sewage Disp
Drive-in theater
Trailer Parks
Union Pacific Station
Courthouse
Radio Tower
Municipal Building
Post Office
Country club
Municipal Swimming Pool
Lincoln School
SMOKY HILL
Franklin School
Junction City Reservoir
Spuhl Park
City Hospital
Highland Cem
JUNCTION CITY
St Mary's Cem
Pit
USGS JUNCTION CITY 1978
SMOKY HILL
LYON
SMOKY RIVER
MISSOURI
PACIFIC
UNION
2 330 000 FEET
50'
R 5 E
(WAKEFORD) 6661 IV NE
SCALE 1:24000
Map Service

KANSAS CITY ARMORY AND OMS #7

Street address: 100 S 20th St, Kansas City (Wyandotte County) Kansas

Legal description: NE4 and NW4 of NE4 of NE4 of Section 17, T11S, 25E

Date of completion: 1956 (dedicated 5 May 1956); with major (Breidenthal Hall) addition in 1972.

Construction materials: brick veneer over cinder blocks for both armory and OMS shop

Topographic/soil setting: Entire complex sits on a heavily altered landscape: lower-lying portions were built on fill from the 1951 flood and earlier fill from road widening placed in lowlying area, and on higher ground the former soil surface has been obliterated by roadwork and construction.

Archeological potential: none

Current unit: HHC(-), 2nd Bn, 137th Infantry; Batt B, 127th Field Artillery; and Det 1, 35th Military Police Company

Previous units: Apparently always the HHC, 2/137th, but with various smaller units assigned for various lengths of time--the 1956 dedication brochure lists nine other units.

Location of previous armory: Reportedly the [Soldiers and Sailors] Memorial Building in downtown Kansas City, Kansas; however the present armory location once had horse stables located reportedly in the current OMS shop area.

Recommended source for more detailed information:Terry Bush, current full timer (since 1977); also see unpublished undated manuscript signed by [retired Brigadier General] Mahlon S. Weed and entitled "History of the Kansas City Station." The armory also has a remarkably complete set of archival materials including newspaper clippings, photographs, dedication and other program brochures, etc, going back as far as the 1920s.

Notable artifacts: various flags, mostly located in old officers' club room, including the standard of the 2nd Battle Group, 35th Infantry Division; a Harbor Master flag presented to the 197th Trans Bn in 1957 by General Nickell; the standard of the 197th Trans Bn (retired in 1959); the standard of the 135th Trans Bn (retired in 1964); a General Officer's boat flag provided by BG Weed; and the WWII standard of the 137th Infantry Regiment (retired 1955).


Monuments: Rectangular bronze plaque attached to west wall of Breidenthal Hall addition reads (all upper case): John W. Breidenthal/Hall/Erected 1972/.

Cannon or other weapons display: none

Artworks: On the west wall of assembly hall: a large (ca. 100 ft long, 12 ft high) painted mural

(multiple topics) by Col Vernassie; also in assembly hall: portrait by Rick Grimes of General Breidenthal; in the main floor office hallway, eight portraits: of General Donn Starry by Jerry Bond (1978); of General Breidenthal by Dahlberg; of BG Mahlon S. Weed (Asst Division Commander 1957-59, 35th Infantry Division) by Domini; of Major Paul A. Fall (137th Inf, awarded DSC as Sgt 137th Inf in ETO, WWII and battlefield promotion) by Domini; of Major General Wm K. Herndon (Commanding General 1936-40, 24th Cavalry Division) by Dahlberg; of Pvt Wm B. Trembley by Domini, of Edward White by Domini, and of Col. Michael P. Sarras (1938-1978) by Bettes. Trembley and White were Medal of Honor winners with the 20th Kansas Infantry in the Philippines.

Other: This appears to be the largest and most complex of "Nickell's armories," with four floors, a large drill floor with hardwood floor and stage, two transient quarters (small single bedrooms), and formerly an Officers' Club room and an NCO lounge. The armory is well known for two "important" events of an anecdotal nature. One is somewhat minor: during the 1960 presidential campaign, Senator John F. Kennedy reportedly used one of the two transient quarters for a nap, in part because his back had been bothering him. The other event has a more humorous aspect despite some serious effects: sometime during the 1950s or 60s, parties at the "O Club" sometimes got a little out of hand, and at one such party someone allegedly shot a flare out of the window (towards the east); the flare supposedly landed on a nearby house and resulted in a fire.


KANSAS CITY
KANSAS CITY MISSOURI
USGS SHAWNEE 1975
Argentine
KANSAS CITY SOUTHERN
RIVER
Big Eleven Lake
Westlawn Park
Kensington Park
Westheight Park
Mt Calvary Cem
St Michael Monastery
Roosevelt Sch
St Johns Cem
Mark Twain Sch
Central Seminary
Wyandotte High Sch
Ward High Sch
McKinley Sch
Waterway Park
Courthouse
Central Sch
Northrup Park
Providence Hospital
St Peters Sch
Donnelly College
Lowell Sch
Willard Sch
Park Sch
Clifton Park
Armory
Home for the Aged
Bethany Hospital
Riverview Sch
St Benedict Sch
Whittier Sch
Central Jr High Sch
Hospital
Fiske Sch
Park
St Thomas Sch
Morse Sch
St Johns Sch
Emerson Park
Stanley Sch
Argentine High Sch
Franklin Sch
Childrens Home
Reservoirs
Summer High Sch
Douglass Sch
School for the Blind
Metropolitan Jr College
PO
Eastern Terminal
Union Pacific
Kansas Turnpike
Southern
Kansas City
Minnesota
Ohio
Orville
Central
Kansas
Argentine
Miami
Mill
Levee
Expressway
Bridge
Pit
BM 764
BM 812
BM 888
BM 798

KINGMAN ARMORY

Street address: 111 S Main St, Kingman (Kingman County) Kansas

Legal description: SE4 of NE4 of NE4 of Section 6, T28S, R7W

Date of completion: 1938; an unattached storage building was built west of the armory at an unknown date, probably in 1950s or 60s.

Construction materials: armory has buttressed brick walls with wooden roof recently recovered with insulated metal roof. Buttresses have limestone caps. Original wooden doors on garage bay entrance on south wall have been replaced with new doors. Original armory construction reportedly included dirt floor in drill room; this was replaced by a hardwood floor "around 30 years ago," possibly 1954. Original construction also included wooden stage with basement at west end of building; this was replaced (uncertain date; probably in 1950s when drill floor was built) by offices (drywall over stud partitions) after the basement was filled with sand and covered with a concrete slab. Asbestos ceiling tiles were added to the building at some time (they are not thought to have been original construction) but these were removed "early on." Adjacent storage building is constructed of cinder blocks with wood roof.

Topographic/soil setting: Mapped as Waldeck fine sandy loam, an alluvial soil formed in coarse textured allluvium on low terraces or high flood plains, but area has been extensively modified by earlier building construction, levee construction, and roadwork and no natural soil surface is believed to be present.

Archeological potential: none

Current unit: Det 1, Batt C, 1st Bn, 161st Field Artillery

Previous units: At time of construction: Co L, 137th Infantry Regiment;
beginning 1947?: -- Tank Company
beginning around 1955?: Co B, 161st FA

Location of previous armory: unknown, but they were described in 1938 newspaper account as "the poorest accomodations of any company in the state."

Recommended source for more detailed information:

Notable artifacts: in exhibit case: Company L's guidon from World War II


Monuments: Inset in exterior east (front) wall of armory is a granite panel or slab with tooled margins, incised as follows (all upper case): Kingman Memorial/Armory/Co. L. 137 Infantry/K.N.G./1937/.

Cannon or other weapons display: located to north of northeast corner of armory is an M4A1

Sherman tank with a small plate attached the hull containing markings as follows: No. 68146/TANK/MED.M4A1/76 MM GUN, WET/(OVERHAULED)/WATERTOWN ARSENAL/1950/C.H.D/. The tank is believed to have been placed there around 1954, in tribute to the tank company once associated at the armory. Located to the east of the east (front) end of the armory are two Civil War cannons; both are 32-pounder shell guns and both have anchor insignia indicating them to be naval guns. Both have right trunnions marked: 32 Pdr./1865/; and left trunnions marked: P./T.A.H./. The northernmost cannon has markings on the top surface of the breech reading: C.A.&CO. No. 161 4500 lbs/. The top surface of the knob reads: 388/. The top surface of a bolt on the top surface of the knob indicates the foundry number as follows: 1914/. The southernmost cannon has markings on the top surface of the breech reading: C.A.&CO. No. 158 4480 lbs/. The top surface of the knob reads: 382/. The top surface of a bolt on the top surface of the knob indicates the foundry number as follows: 1851/. A Kingman newspaper account indicates that the two cannon were placed at the armory in time for a May 30, 1938 dedication. They came to Kingman in 1897 and stood for a while at the cemetery, a city park, and the courthouse before being moved to the armory grounds.

Artworks: none

Other: This armory is notable for being apparently the first armory to be constructed in Kansas by a municipality.



Mapped, edited, and published by the Geological Survey

Control by USGS and USC&GS

Topography by photogrammetric methods from aerial photographs taken 1965. Field checked 1967

Polyconic projection. 1927 North American datum

(CLEVELAND) 6359 II SW

LARNED ARMORY

Street address: 330 E 14th St, Larned (Pawnee County) Kansas

Legal description: SW4 of SW4 of SW4 of Section 28, and NW4 of NW4 of NW4 of Section 33, T21S, R16W

Date of completion: 1961 (dedicated December 1961)

Construction materials: brick veneer over cinder blocks

Topographic/soil setting: mapped as Holdredge silt loam and Uly silt loam (upland soils formed in loess) but said to be constructed on four (or more) feet of fill due to springs in vicinity

Archeological potential: none

Current unit: Batt E(-) TA, 161st Field Artillery

Previous units: at time of construction: SVC Batt, 161st FA Bn, 130th FA Grp

Location of previous armory: City auditorium beginning with lease agreement of 5 Apr 1948

Recommended source for more detailed information: none


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none


6
c 1871
12'30"
327
30 T21 R16W
364
T21 R16W
LARNED-PAWNEE COUNTY AIRPORT
LARNED ARMORY
Ash Valley Grange Hall
BM 1993
OLD RAILROAD GRADE
Drive-In Theater
Golf Course
Park
Nortside Sch
Sacred Heart Sch
Phinney
BM 1997
High Sch
LARNED
Hillside Sch
BM 2004
Well
Park Sch
PAWNEE
T. 21 S.
T. 22 S.
USGS LARNED 1970
Sewage Disposal
SANTA FE
BM 2002
Radio Tower (KANS)
Sandpits
Substation
ATCHISON TOPEKA
JETMORE 10 MI. TO U.S. 183
6160 II NW (FORT LARNED)
2.6 MI.
8 MI.

LAWRENCE (METCALF MEMORIAL)ARMORY

Street address: 200 N Iowa, Lawrence (Douglas County) Kansas

Legal description: SW4 of SW4 of NW4 of Section 25, T12S, R19E

Date of completion:1961; garage bay along entire north wall was converted into offices in 1990

Construction materials: brick veneer over cinder block; drywall over wood studs used for 1990 remodeling

Topographic/soil setting: Woodson silt loam, an upland soil formed in loess

Archeological potential: little or none

Current unit: E Co and B Co, 2nd Bn, 137th Inf, 69th Inf Bde

Previous units: at time of construction, reportedly H Co, 137th Inf;
in 1961?: Combat Support Company, 2nd Bn, 137th Inf

Location of previous armory: unknown

Recommended source for more detailed information: former First Sgt (ret.) Gwin of Lawrence; armory has no known archives except for assorted old photos in "museum" room


Notable artifacts: in "museum" room: framed charter for US Spanish American War Veterans Camp 17; and a framed American Legion "memorial" to Wilder Metcalf.

Monuments: the armory itself, as dedicated to Brigadier Wilder Metcalf (1855-1935), former major then colonel of 20th Kansas Infantry during Spanish American War; and in foyer: a rectangular bronze plaque detailing accomplishments of Metcalf.

Cannon or other weapons display: none

Artworks: none

Other: none


LAWRENCE WEST QUADRANGLE
KANSAS-DOUGLAS CO.
7.5 MINUTE SERIES (TOPOGRAPHIC)
17' 30"
635 000 METERS
95°15' 00"
TURNPIKE
Creek
USGS LAWRENCE WEST 1991
LAWRENCE ARMORY
WEST LAWRENCE INTERCHANGE
WAKARUSA
Tollgate
LAWRENCE
University of Kansas (West Campus)
4318
4317
4316
4315
4314

LENEXA ARMORY

Street address: 18200 W 87TH St Parkway, Lenexa (Johnson County) Kansas

Legal description: SW4 of SW4 of SW4 of Section 30, T12S, R24E

Date of completion: 1990

Construction materials: brick veneer over cinder block

Topographic/soil setting: Polo silt loam, an upland soil formed in loess and weathered limestone and shale

Archeological potential: little or none

Current unit: Det 5, HHC STARC; Co C, 169th Spt Bn; Det 1, Batt C, 1/127th FA

Previous units: none

Location of previous armory: unknown

Recommended source for more detailed information: none


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none


342
(EDWARDSVILLE)
344
R. 23 E.
R. 24 E.
47'30"
345
346
Ford
Golf Course
Little
SHAWNEE
MISSION
PARK
Shawnee Mission Lake
Creek
TOPEKA
BM
826
Pit
WT
LEAVEXA
ATCHISON
Creek
KANSAS
MAIL
PIPELINE
USGS OLATHE 1956
23
24
19
30
25
26
35
36
31
1
2
6
5

LIBERAL ARMORY

Street address: 730 Armory Road, Liberal (Seward County) Kansas

Legal description: NW4 of NE4 of SE4 of Section 31, T34S, R33W

Date of completion: 1958

Construction materials: brick veneer over cinder blocks; unattached metal building located to southwest of armory

Topographic/soil setting: Richfield silt loam, an upland soil formed in loess

Archeological potential: little or none

Current unit: Det 1, Batt A, 1st Bn, 161st Field Artillery

Previous units: possibly C Batt, 1/161 FA

Location of previous armory: unknown

Recommended source for more detailed information: former commander Ron Martin


Notable artifacts: none

Monuments: none

Cannon or other weapons display: in front of armory entrance is a cannon, M1905, on metal-rimmed wooden wheels. Markings on the cannon read: 3 Inch Field Model of 1905/MID. STEEL/. Markings on the muzzle and barrel read: Vandervliet Arsenal 1907/784 Pounds No. 129 CMA/. The wheels are badly rotted due to not having been turned.

Artworks: none

Other: none


L I B E R A L
USGS LIBERAL 1971
LIBERAL
Gas Well
BM 2857
Vocational Sch
MacArthur Sch
Golf Course
Water Tank
Radio Tower
Sewage Disposal Ponds
Cemetery
First United Ch
St Anthonys Sch
Southwest Medical Center
Sewage Disposal
Light Park
Fairground
Lincoln Sch
Armory
Park
McKinley Sch
Jr High Sch
High Sch
Jr College
PO
Courthouse
City Hall
BM 2836
Washington Sch
Trailer Park
Garfield Sch
McDermott Sch
Drive-in Theater
Park
Boothlawn Sch
South Jr High Sch
Wells
CHICAGO
PACIFIC
AND
PANCAKE
WALNUT
SPRUCE
PINE
BLVD
KANSAS
PENNSYLVANIA
CALHOUN AVE
WESTHAVEN DR
EDWARDS AVE
OKLAHOMA
CALVERT
PERSHING
CLAY
CAIN
WESTERN
OHIO
GRANT
KANSAS
SEWARD
YORK
NEW
WT

MANHATTAN ARMORY AND OMS #11

Street address: 1809 S Airport Rd, Manhattan (Riley County) Kansas

Legal description: SE4 of NE4 of NE4 of Section 32, T10S, R7E

Date of completion: 1955 (dedicated 21 May 1955) with OMS shop possibly being built after armory; an addition was constructed on OMS shop in 1970.

Construction materials: brick veneer over cinder blocks for both armory and OMS shop

Topographic/soil setting: Chase silty clay loam and Muir silt loam, alluvial soils that occur along streamcourses on natural terraces

Archeological potential: low to moderate due to alluvial setting

Current unit: HQ and HHC, 1st Bn, 635th Armor; Det 1, 714 Maint Co

Previous units: at time armory was constructed: HHC, 891st Aviation Engr Bn;
reorganized as 891st Engr Bn in 1957.
beginning 1 Feb 1976: 1/635th Armor, 69th Inf Bde.
Also housed at armory:: 110th Ordnance Company (DS) from 1958-60, and 169th Spt Bn in 1976.

Location of previous armory: unknown

Recommended source for more detailed information: no particular individual; relatively extensive archives (newspaper clippings, ephermera, etc) pertaining to 1/635th and several deactivated 2/635th units (Salina, Abilene, etc).


Notable artifacts: none

Monuments: none

Cannon or other weapons display: An M60 tank had been on display out near K-18 highway but has been removed and placed in storage in the armory's vehicle storage area.

Artworks: none

Other: This is a relatively large armory, with a sizable one-story office/storage section extending to north from west section of building.


MANHATTAN ARMORY
USGS KEATS 1982
352 LANDING STRIP
Well
Eureka Valley
Rebekah Cem
BR 317
BR 319
Radio Facility
Armory
MANHATTAN MUNICIPAL AIRPORT
Beacon
BM 317.8
UNION PACIFIC
Radio Towers
Creek
Manhattan Raceway
Seventmile
(OGDEN) 6662 II SW
10 KM TO INTERSTATE 70 & U.S. 40
JUNCTION CITY 18 KM
R 7 E
SCALE 1:24 000
KILOMETERS
METERS
MILES

MANKATO (WINT SMITH MEMORIAL) ARMORY

Street address: 217 High, Mankato (Jewell County) Kansas

Legal description: NW4 of NW4 of NW4 of Section 22, T3S, R8W

Date of completion: 1958 (dedicated 18 Apr 59; rededicated as Wint Smith Memorial Armory on 8 May 77); small single story room added in SW corner of drill floor in late 1970s

Construction materials: brick veneer over cinder blocks; later interior room addition is drywall over wood stud walls

Topographic/soil setting: Geary silt loam and Harney silt loam, upland soils formed in loess

Archeological potential: little or none

Current unit: Det 1, 995th Maintenance Company (since 1 Jan 90)

Previous units: at time armory was constructed: Batt B, 728th FA Bn;
later: Co B, 287th Inf; 778th QM; 12th Ordnance; 170th Ord (1961-62); Det 1, Co A, 891 Engr Bn; beginning 1 Feb 76: Det 1, 891st Engr Co; beginning 1 Jun 79: Det 1, 170th Maint Co; beginning 1 Jun 87: Det 1, Co D, 735th Combat Support Bn.

Location of previous armory: unknown

Recommended source for more detailed information: no particular individual; armory has relatively good archival collection of annual historical supplements, various orders, newspaper clippings from time of various dedications, and other ephemera.


Notable artifacts: in foyer exhibit case are items belonging to Wint Smith and donated by his widow, including his briefcase, medals, and presentation saber.

Monuments: none

Cannon or other weapons display: none

Artworks: in foyer: portrait by Domini of BG Wint Smith with brass plate describing him as Commanding General of 35th Inf Div Artillery 26 Jun 1947 to 31 Oct 1952.

Other: none


MANKATO ARMORY
USGS MANKATO 1969
Mankato Airport
Quarry
Waste Disposal Ponds
Res
CHICAGO ROCK ISLAND AND PACIFIC
CENTER
St Theresa Cem
Mankato
(BM 1776)
Hope
BM 1721
Lutheran Cem
MISSOURI
Sewage Disposal
BUFFALO
PACIFIC
BR 1665
BR 1648
9
10
11
14
15
16
21
22
23
26
27
28

MARYSVILLE ARMORY

Street address: 306 N 19th St, Marysville (Marshall County) Kansas

Legal description: SE4 of SW4 of SW4 of Section 27, T2S, R7E

Date of completion: 1954 (dedicated 12 April 1954)

Construction materials: brick veneer over cinder blocks; new metal roof over entire building

Topographic/soil setting: Wymore silty clay loam, an upland soil formed in loess

Archeological potential: little or no

Current unit: Batt A(-), 2nd Bn, 130th Field Artillery

Previous units: at time armory was constructed: Batt B, 154th FA Bn;
later 250th Ord Co, and various other Maintenance or Ordnance companies

Location of previous armory: unknown

Recommended source for more detailed information: no partiuclar individual; armory has no old archives


Notable artifacts: none

Monuments: by flagpole in front of armory is a limestone slab marked as follows (all upper case): This Country/Supports/Our Troops/In/Desert Storm/.

Cannon or other weapons display: Adjacent to the Desert Storm monument is a 16-inch Navy artillery shell. Located on grounds at some distance to the east of the armory is a self-propelled gun, an SP M110A2 with 8" howitzer.

Artworks: none

Other: none


MARYSVILLE
Quarry
Radio Tower (KNDY)
MARYSVILLE MUNICIPAL AIRPORT
Cemetery
Gaging Station
Sewage Disposal
Park
Hospital
Country Club
Substation
Creek
MARYSVILLE ARMORY
USGS MARYSVILLE 1983
560 000 FEET
4414
4413
4412
4410
50'
T. 2 S.
T. 3 S.
HOME 6 MI.
SENECA 31 MI.
(HOME) 6663 I SE

NEWTON ARMORY

Street address: 400 N Grandview, Newton (Harvey County) Kansas
Legal description: SW4 of SE4 of SE4 of Section 18, T23S, R1E
Date of completion: 1955
Construction materials: brick veneer over cinder blocks
Topographic/soil setting: Farnum loam, an upland soil formed in old (Pleistocene aged or older) alluvium

Archeological potential: little or none

Current unit: Det 2, HHB, 1st Bn, 161st Field Artillery (since 1996)

Previous units: at time armory was constructed, apparently Co C, 137th Infantry;
the armory was used by a US Army Reserve unit while guard unit was in Vietnam, 1968-69;
in 1992 the local unit was reorganized as a unit of the 635th Armor.

Location of previous armory: unknown

Recommended source for more detailed information: former guardsman Wally Bacon of Newton; the unit has no archives (lost during Vietnam mobilization) but does have a few old (early 1900s) photographs of the Newton Guard unit.

Notable artifacts: in foyer exhibit case: books dated 1907, 1911, and 1917 detailing Infantry drill regulations and Guard duty requirements for NCOs and privates.

Monuments: in foyer: large bronze plaque describing life and accomplishments of local unit commander and Colonel Perry Milo Hoisington (see attached page for details); also a wooden plaque as memorial for former guard member who died in fishing accident, reading: In Memory/Major Clifton K. Dalbons/Friend Soldier Leader/; and three other wooden plaques witdh brass plates honoring the unit's Vietnam casualties, reading: In Memory of/Cpt. Jose S. Llamas/B 8 Nov 1926 K-VN 19 Aug 1969/; In Memory of/SP4 George F. Martinez/B 9 May 1926 K-VN 8 Jun 1969/; In Memory of/PFC Robert L. Boese/B 29 Dec 1946 K-VN 23 May 1969/.

Cannon or other weapons display: none

Artworks: none


Other: The Newton armory is unique in having a "time capsule" consisting of a small copper box containing 1955 coinage and a typed unit roster, placed into a small cavity in the cinder block wall bordering the offices and the garage bay. In addition, an "address block" (a brick incised with "400" indicating the address of 400 N Grandview) was placed in the wall above the entrance doors. In addition, another brick incised "1955" for the date of armory completion was placed into the wall above the entry porch. All three of these artifactual embellishments were set in place by long-time Guardsman Wally Bacon, now retired.

TEXT OF HOISINGTON PLAQUE, NEWTON ARMORY:

[all upper case, arranged as shown below]

Perry Milo Hoisington
Colonel

First CO 137th KSNG. Entered Mich NG
1875. Moved Newton and enlisted KNG
8 Aug 1890. Colonel 2nd KSNF KNG 1895.
WWI: Org. & Co 137 Inf (1st + 2nd Ks)
at Camp Doniphan 1917-1918
Retired 13 Oct 1921
Ks Military Bd 1899+
Sec'y NG Assoc of US 1917-1918 1919-1920.
1900 Grand Com Knights Templar of KS
Soldier Civic Leader Financier


Radio Tower
North Newton
BM 1452
Bethel College
City Hall
PO
Radio Tower
Northridge Sch
Centennial Park
NEWTON ARMORY
Central Kansas Area Voc-Tech Sch
High Sch
Northview Opportunity Sch
Newton BM 1502
Park
Main
Street Park
Thurman Park
Childrens Home
Santa Fe Middle Sch
Cooper Sch
BM 1464
Eastside U Ch
Sunset Sch
Lincoln Sch
Axtell Hosp
Roosevelt Sch
PO
Athletic Park
Fire Sta
NEWTON
Evergreen Cem
McKinley Sch
Chisholm Middle Sch
St Marys Cem
Bethel Deaconess Hospital
Washington Sch
Park
Oil Tank
Sand Creek
Sewage disposal
U665 NEWTON 1978
Newton Country Club
BM 1491
South Breeze Sch
BM 1460
Newton Ch
MERIDIAN
PRINCIPAL
SIXTH
BROADWAY
MAIN
BOYD
AVENUE
1460
1456
1455
1450
1445
1440
1435
1430
1425
1420
1415
1412

NORTON ARMORY

Street address: 1200 N State, Norton (Norton County) Kansas

Legal description: SE4 of SE4 of SE4 of Section 27, T2S, R23W

Date of completion: 1957; date of auxiliary building (formerly an OMS shop) is not known but probably later than armory

Construction materials: brick veneer over cinder blocks; a two-bay garage-style maintenance building (former OMS shop) behind armory is of similar construction. Inside armory, an "NCO club" has been built in northwest (rear) corner of garage bay; construction is drywall over stud walls.

Topographic/soil setting: Holdredge silt loam, an upland soil formed in loess

Archeological potential: little or none

Current unit: 170th Maint Company

Previous units: -- Ord Bn in 1971; 110th -- in 1977; 995th Maint Co from 1970 into late 1980s; 287th -- until 1991

Location of previous armory: unknown

Recommended source for more detailed information: Guardsman Dwight Heikes at Nickell Hall in Salina; Jake Durham (old Bn CO) in Norton


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none


NORTON AIRPORT
USGS NORTON 1978
T2 secs. GLOW
560 000 FEET
4411
4409
4408
50'
5 MI. TO JUNC. U.S. 36 & 383
PHILLIPSBURG (VIA U.S. 36) 30 MI.
(CALVERT) 6063 IV SE
C E N T E R
Norton Municipal Airport
Nortonport Beacon
Eisenhower Sch
Hospital
Jr High Sch
High Sch
Norton
Drive-In Theater
Courthouse
PO
BM 2269
Elmwood Park
Golf Course
Well
Well
Gaging Station
Radio Tower
Radio Towers
Horseshoe Hill
Dog Creek
Prairie Dog Creek
PACIFIC
Robinson
CEMETERY
WOODSFIELD ST
WAVERLY ST
MAIN ST
1ST
GRAVES AVE
WEST AVE
WABASH
Pk
WT
28
27
35
36
9
11

OLATHE ARMORY

Street address: 1601 W Hwy 56, Olathe (Johnson County) Kansas

Legal description: NE4 of SE4 of NW4 of Section 3, T14S, R23E

Date of completion: 1991

Construction materials: ashlar faced cinder blocks

Topographic/soil setting: mapped as Polo silt loam, an upland residual soil formed in material weathered from limestone and shale, but thought to be on fill dirt placed on low areas

Archeological potential: none

Current unit: various, including 174th CS Bn, 137th PLS, 35th Div Band, Det 1 of Batt B of 1/127th FA, and HQ of 169th Spt Bn

Previous units: none

Location of previous armory: unknown

Recommended source for more detailed information: no particular individual; no armory archives


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none


OLATHE ARMORY
USGS OLATHE 1975
OLATHE
CENTER ROAD
Lincoln Sch
Central Sch
Westview Sch
Trailer Park
Sewage Disposal
CEM
Park
Pit
Quarry
SANTA FE 3 TRACKS
Cedar Creek
SAN FRANCISCO
ELM
SPRUCE
CHESTNUT
KANSAS
PINE
WALNUT
LOULA
JEFFERSON
BM1055

OTTAWA ARMORY AND OMS #8

Street address: 208 W 17th, Ottawa (Franklin County) Kansas

Legal description: NW4 of SE4 of NE4 of Section 11, T17S, R19E

Date of completion: 1954 (dedicated 19 December 1954); date of OMS shop is uncertain but possibly after armory construction; north half of garage bay was converted to offices in 1997; date of metal building is probably quite recent

Construction materials: brick veneer over cinder blocks on both armory and OMS shop; offices constructed recently in old garage bay are drywall over wood stud walls, with the north garage door bricked over and an entrance door constructed; new metal windows replaced old ones on the east side of the armory in the remodeled offices section; an unattached metal building is located in vehicle storage area near OMS shop.

Topographic/soil setting: Woodson silt loam, an upland soil formed in ancient alluvium

Archeological potential: little or none

Current unit: HQ Batt, 1st Bn, 127th Field Artillery

Previous units: at time of construction: 127th FA Bn; apparently the only changes have been as various units of the 127th FA

Location of previous armory: unknown

Recommended source for more detailed information: former Guardsman (ret. WO) Gardner Campbell of Ottawa, who reportedly has scrapbooks of newspaper clippings, etc.


Notable artifacts: in foyer exhibit cases: a WWI German helmet; a WWI American helmet and uniform; a bugle inscribed as follows: Awarded to/Batt B/161 FA/Nov 6 1939/by/local/Amer Legion/Drum & Bugle Corps/; and a variety of ammunition including a 50-caliber machine gun round, a 30-caliber MG round, 37 mm and 20 mm antitank rounds, and 45 caliber pistol rounds.

Monuments: in foyer: memorial wood plaque dedicated to Loren L. Leikam (Cpt) who served 1955-79.

Cannon or other weapons display: none

Artworks: none

Other: none


38°37'30"
17'30"
2 920 000 FEET
PLEASANT GROVE 16 MI.
9 MI. TO JUNC. KANS. 33 AND 68
LOUISBURG (VIA KANS. 68) 33 MI.
OTTAWA
Forest Park
Ottawa Cem
Mt Calvary Cem
Sewage Disposal
Hope Cem
Waterworks
High Sch
Park
Hawthorne Sch
Field Sch
Ottawa University
Oil Well
Garfield Sch
Lyons Hospital
Highland Cemetery
Trailer Park
Radio Station (KOFO)
Hood Sch
Roselawn Cem
Big Bull Creek
Des Cygnes River
Marais des Cygnes
Missouri Pacific
Santa Fe
Kansas City 57 Mi.
Nugent Creek
Rock Creek
T. 16 S.
T. 17 S.
720 000 FEET
4276
4275
4274
4273
4271
35'
OTTAWA ARMORY
USGS OTTAWA South 1983

PAOLA ARMORY

Street address: 1010 Hedge Lane, Paola (Miami County) Kansas

Legal description: NE4 of NE4 of NE4 of Section 16, T17S, R23E

Date of completion: 1991

Construction materials:brick veneer over cinder blocks

Topographic/soil setting: Mapped as Summit silty clay loam, but sits on significant amount of fill and much of area was bulldozed due to removed farmstead

Archeological potential: none

Current unit: Batt A(-), 1st Bn, 127th Field Artillery

Previous units: none

Location of previous armory: none

Recommended source for more detailed information: no particular individual


Notable artifacts: a 105 howitzer round, and an old mortar round

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none


PAOLA ARMORY
Waterworks
Paola Golf Club
MISSOURI
RAILROAD
OLD
ST LOUIS
PACIFIC
SAN FRANCISCO
Bull Creek
PAOLA
North Sch
South Sch
City Hall
Ursuline Academy
St Patricks
Hospital
Holy Cross Cem.
Sewage Disposal
Oil Wells
Trailer Park
CEM
BM 857
USGS PAOLA EAST 1973

PHILLIPSBURG ARMORY

Street address: 520 S 7th St, Phillipsburg (Phillips County) Kansas

Legal description: SW4 of NW4 of NE4 of Section 35, TD3S, R18W

Date of completion: 1963

Construction materials: brick veneer over cinder blocks

Topographic/soil setting: Holdredge silt loam, an upland soil formed in loess

Archeological potential: little or none

Current unit: Det 3, 995th Maint Co

Previous units: Det 3, 735th Spt Bn; 170th Maint Co; 110th Ord Co; 731st Med Truck Co

Location of previous armory: unknown

Recommended source for more detailed information: former Guardsman (ret. WO) Fred Zillinger of rural Phillipsburg


Notable artifacts: in foyer: 155 mm howitzer shell and a 90 mm howitzer shell

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none



THIS MAP COMPLIES WITH NATIONAL MAP ACCURACY STANDARDS
FOR SALE BY U. S. GEOLOGICAL SURVEY, DENVER, COLORADO 80225, OR RESTON, VIRGINIA 22092
AND BY THE STATE GEOLOGICAL SURVEY, LAWRENCE, KANSAS 66044
A FOLDER DESCRIBING TOPOGRAPHIC MAPS AND SYMBOLS IS AVAILABLE ON REQUEST

PITTSBURG ARMORY

Street address: 1506 N Walnut St, Pittsburg (Crawford County) Kansas

Legal description: NE4 and NW4 of SE4 of NE4 of Section 19, T30S, R25E

Date of completion: 1956, with 1968 addition of one-story office/storage complex along north wall of original armory

Construction materials: brick veneer over cinder blocks

Topographic/soil setting: mapped as Dennis silt loam, an upland soil formed in weathered shale, but entire area has been landscaped on east or covered with fill on west and no natural soil surfaces remain.

Archeological potential: none

Current unit: Co A, 891st Engr Bn (since 1986)

Previous units: -- Ord Co; -- FA; -- Engr Co; A Co, 3rd Bn, 137th Infantry in 1968.

Location of previous armory: unknown

Recommended source for more detailed information: no particular person; armory has no archives


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none


Trailer Park
Claypit
Tailings
Sewage Disposal
MC Carmel Hospital
Strip Mines
Pittsburg Armory
Trailer Park
Tank
Lincoln Sch
Golf Course
LINCOLN PARK
High Sch
St Marys Sch
Reservoirs
Westside Sch
Field Sch
Schlanger Park
PITTSBURG
Washington Sch
Lakeside Sch
Jakes Park
Mount Olive Cemetery
Kansas State College of Pittsburg
Zion Cem
Radio Tower (KSEK)
SAN FRANCISCO
KANSAS CITY
ST LOUIS
BROADWAY
MICHIGAN
TAYLOR
JOPLIN
WASHINGTON
JEFFERSON
QUINCY
CLEVELAND
FORD
BM
WT
USGS PITTSBURG 1978

PRATT ARMORY

Street address: 207 Rochester St, Pratt (Pratt County) Kansas

Legal description: NE4 of NE4 of NW4 of Section 3, T28S, R13W

Date of completion: 1955

Construction materials: brick veneer over cinder blocks

Topographic/soil setting: mapped as Farnum loam, an upland soil formed in outwash and sandy windblown material, but armory area has been flattened and filled

Archeological potential: none

Current unit: Det 1, Batt B, 1st Bn, 161st Field Artillery

Previous units: unknown

Location of previous armory: unknown

Recommended source for more detailed information: Dave Stitt of Pratt; armory supposedly has a box of pictures and clippings "going back to the 60s" but it could not be found


Notable artifacts: none

Monuments: none

Cannon or other weapons display: none

Artworks: none

Other: none


USGS PRATT 1965
PRATT ARMORY
CENTER
SARATO
Well
BM 1943
Gravel Pits
Greenlawn Cemetery
Radio Towers
Radio Tower
Pratt Community Jr College
Rock Island Park
Drive-In Theater
Hospital
Park
Sewage Disposal
Sixth St
South
Gravel Pits
Lemon Park
Fairground
Well
ATCHISON
PACIFIC
AND
RT
ROCK ISLAND
CHICAGO
GREENSBURG 30 MI.
CULLISON 8 MI.
T. 27 S.
T. 28 S.
406
26 R 13W
PTH 20
PTH 407
350 000
FEET

RUSSELL ARMORY

Street address: 701 Fairway Drive, Russell (Russell County) Kansas

Legal description: NW4 of NE4 of SE4 of Section 26, T13S, R14W

Date of completion: 1956

Construction materials: brick veneer over cinder blocks

Topographic/soil setting: Crete silt loam, an upland soil formed in loess

Archeological potential: little or none

Current unit: Det 3, 170th Maint Co (since 1990)

Previous units: 995th Maint Co from 1982 to 1987; also 635th Armor from 1985 to 1992

Location of previous armory: unknown

Recommended source for more detailed information: Dick Godfrey of Salina; armory has no archives.


Notable artifacts: in foyer exhibit case: an Iraqi Army AK-47 assault rifle brought back from Operation Desert Storm by personnel of 170th Maint Co

Monuments: none

Cannon or other weapons display: none other than AK-47 described above

Artworks: none

Other: none



Mapped, edited, and published by the Geological Survey as part of the Department of the Interior program for the development of the Missouri River Basin

Control by USGS and USC&GS

Topography by photogrammetric methods from aerial photographs taken 1965. Field checked 1967

MN GN 10° 178 MILS 0°07' 2 MILS

1000 0 1000

Russell 1967

DEPARTMENTS OF THE ARMY AND THE AIR FORCE
JOINT FORCES HEADQUARTERS KANSAS
DIRECTORATE OF PUBLIC WORKS
2800 SOUTHWEST TOPEKA BOULEVARD
TOPEKA, KS 66611-1287

June 9, 2014

Environmental Management Branch

To whom it may concern:

Please find attached Notice of Intents For Stormwater Runoff from Industrial Activity. These Intents cover our Army Aviation Support Facilities in Topeka and Salina.

If you have any questions, please feel free to contact either myself at (758)-274-1152, julie.m.carey2.nfg@mail.mil or Dr. Sam Mryyan, Deputy Chief of the Environmental Branch, at (785)-274-1154, mahmoud.a.mryyan.nfg@mail.mil.

Sincerely,

Julie M. Carey
Environmental Scientist
Environmental Management Branch

Enclosures

Kansas
Department of Health and Environment

See Attached Sheet for Instructions

NOTICE OF INTENT (NOI)
For Stormwater Runoff from Industrial Activity
Authorized by a Kansas Water Pollution Control General Permit
Under the National Pollutant Discharge Elimination System

Submission of this Notice of Intent constitutes notice that the party identified in Section I of this form desires to be authorized by an NPDES permit issued for stormwater runoff from industrial activity in the State of Kansas. Becoming a permittee obligates the discharger to comply with the terms and conditions of the Kansas NPDES Stormwater Runoff from Industrial Activity General Permit. **Completion of this NOI does not provide automatic coverage under the general permit. Coverage is provided and discharge permitted when the Kansas Department of Health and Environment (KDHE) authorizes the NOI. A signed and dated copy of the authorized NOI will be provided to the owner or operator.** Upon authorization of the NOI, a Kansas permit number and a Federal permit number will be assigned to the industrial facility. ONLY COMPLETE NOI FORMS ACCOMPANIED BY THE $60 ANNUAL PERMIT FEE WILL BE PROCESSED. KDHE WILL NOTIFY PERSONS WHOSE NOI FORMS ARE INCOMPLETE, DEFICIENT, OR DENIED.

Please Print or Type.

I. FACILITY OWNER OR OPERATOR INFORMATION

Owner or Operator's Name: Kansas Army National Guard
Company Name:
Owner or Operator's Phone: 785-274-1152
Mailing Address: 2800 SW Topeka Blvd.
City: Topeka State: KS Zip Code: 66611

Contact Name: Julie Carey
Company Name: Kansas Army National Guard
Contact Phone: 785-274-1152
E-mail Address: julie.m.carey2.nfg@mail.mil

PERMIT FEE BILLING INFORMATION

Billing contact name: Julie Carey
Billing Address (if different):
City: State: Zip Code:

Phone: 785-274-1152
Email Address: julie.m.carey2.nfg@mail.mil

II. FACILITY INFORMATION

A. LOCATION

Industrial Facility Name: Army Aviation Support Facility 2
Street Address: 2917 Hein Ave.
City: Salina State: KS Zip Code: 67401
County: Saline
Physical Location:

Facility Contact Name: Julie Carey
Company Name: Kansas Army National Guard
Contact Phone: 785-274-1152
E-mail Address: julie.m.carey2.nfg@mail.mil

SW QTR, 34 Section, 14 South, Township, 3W Range □ E; □W; or

Deg.	Min.	Sec.	Latitude

Deg.	Min.	Sec.	Longitude

For Official Use Only:

Received	**Paid:**	**Authorized** □ Y; □ N
	Date:	
	Initials:	
	Check No.:	**Reviewer**
Secretary, Kansas Department of Health and Environment		**Date**
KS Permit No.	**Federal Permit No.**	

B. EXISTING CONDITIONS/USES

Is any part of the Facility located on Indian lands? ☐ Y; ☑ N

If yes, contact EPA regarding discharging stormwater runoff from industrial activities on Indian lands.

If stormwater runoff drains to or through a Municipal Separate Storm Sewer System; MS4 Name: Salina

Name of the first receiving water; stream; or lake: _____ River Basin: Smoky Hill-Saline

Are any Critical Water Quality Management Areas, Special Aquatic Life Use Waters, or Outstanding National Resource Waters located within ½ mile of the facility boundary? _____ ☐ Y; ☑ N

SIC/Activity Codes: _____ Primary: 4581 Secondary (if applicable): _____ _____ _____

If this facility has another existing NPDES or Kansas Water Pollution Control permit(s). Enter the permit number(s): _____

C. FACILITY DESCRIPTION

Facility Description: Support facility for Army National Guard aviation units, including maintenance and repair activities

Is this a new facility? ☐ Y; ☑ N

Approximate facility size 5 acres.

Provide an area location map that shows the boundaries of the industrial site and arrows showing direction(s) of stromwater flow from the industrial site to the first receiving water.

III. ANNUAL FEE

Enclose a check for the first year of the annual permit fee specified in K.A.R. 28-16-56 et seq. as amended. Make the check payable to "KDHE". Per K.A.R. 28-16-56, as amended, the current annual permit fee for this general permit is $60. An invoice for the annual permit fee will be sent to the identified billing contact person requesting a permit until such time as the permittee submits a Notice of Termination (NOT).

IV. NOI CERTIFICATIONS

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

I understand that continued coverage under the NPDES general permit for Stormwater Runoff from Industrial Activity is contingent upon maintaining eligibility as provided for in the requirements and conditions of the general permit, and paying the annual fee.

Sam Mryyan — Signature (owner, operator, or duly authorized representative)

6/9/14 — Date

SAM MRYYAN, Deputy Chief, Env. — Name and Official Title (Please Print)

To receive a hard copy of the general permit packet, check yes: ☒ Y; ☐ N

(Note: A copy of the permit can be obtained at www.kdheks.gov/stormwater)

Send completed form with original signature to:
Kansas Department of Health and Environment
Bureau of Water, Industrial Programs Section
1000 SW Jackson, Suite 420
Topeka, KS 66612 - 1367

KDHE Contact Information:
Phone: (785) 296-5545
E-mail: stormwater@kdheks.gov

Kansas
Department of Health and Environment

See Attached Sheet for Instructions

NOTICE OF INTENT (NOI)
For Stormwater Runoff from Industrial Activity
Authorized by a Kansas Water Pollution Control General Permit
Under the National Pollutant Discharge Elimination System

Submission of this Notice of Intent constitutes notice that the party identified in Section I of this form desires to be authorized by an NPDES permit issued for stormwater runoff from industrial activity in the State of Kansas. Becoming a permittee obligates the discharger to comply with the terms and conditions of the Kansas NPDES Stormwater Runoff from Industrial Activity General Permit. **Completion of this NOI does not provide automatic coverage under the general permit. Coverage is provided and discharge permitted when the Kansas Department of Health and Environment (KDHE) authorizes the NOI. A signed and dated copy of the authorized NOI will be provided to the owner or operator.** Upon authorization of the NOI, a Kansas permit number and a Federal permit number will be assigned to the industrial facility. ONLY COMPLETE NOI FORMS ACCOMPANIED BY THE $60 ANNUAL PERMIT FEE WILL BE PROCESSED. KDHE WILL NOTIFY PERSONS WHOSE NOI FORMS ARE INCOMPLETE, DEFICIENT, OR DENIED.

Please Print or Type.

I. FACILITY OWNER OR OPERATOR INFORMATION

Owner or Operator's Name: Kansas Army National Guard
Company Name:
Owner or Operator's Phone: 785-274-1152
Mailing Address: 2800 SW Topeka Blvd.
City: Topeka State: KS Zip Code: 66611

Contact Name: Julie Carey
Company Name: Kansas Army National Guard
Contact Phone: 785-274-1152
E-mail Address: julie.m.carey2.nfg@mail.mil

PERMIT FEE BILLING INFORMATION

Billing contact name: Julie Carey
Billing Address (if different):
City: State: Zip Code:

Phone: 785-274-1152
Email Address: julie.m.carey2.nfg@mail.mil

II. FACILITY INFORMATION

A. LOCATION

Industrial Facility Name: Army Aviation Support Facility 1
Street Address: 6700 SW Topeka Blvd
City: Topeka State: KS Zip Code: 66619
County: Shawnee
Physical Location:

Facility Contact Name: Julie Carey
Company Name: Kansas Army National Guard
Contact Phone: 785-274-1152
E-mail Address: julie.m.carey2.nfg@mail.mil

NW (QTR), 7 (Section), 13 (Township) South, 16E (Range) □ E; □W; or

Deg.	Min.	Sec.	
			Latitude
			Longitude

For Official Use Only:

Received	**Paid:**	**Authorized** □ Y; □ N
	Date:	
	Initials:	
	Check No.:	**Reviewer**
Secretary, Kansas Department of Health and Environment		**Date**
KS Permit No.	**Federal Permit No.**	

B. EXISTING CONDITIONS/USES

Is any part of the Facility located on Indian lands? ☐ Y; ☑ N

If yes, contact EPA regarding discharging stormwater runoff from industrial activities on Indian lands.

If stormwater runoff drains to or through a Municipal Separate Storm Sewer System; MS4 Name: Topeka

Name of the first receiving water; stream; or lake: _____ River Basin: Kansas-Lower Republican

Are any Critical Water Quality Management Areas, Special Aquatic Life Use Waters, or Outstanding National Resource Waters located within ½ mile of the facility boundary? _____ ☐ Y; ☑ N

SIC/Activity Codes: _____ Primary: 4581 Secondary (if applicable): _____ _____ _____

If this facility has another existing NPDES or Kansas Water Pollution Control permit(s). Enter the permit number(s): _____

C. FACILITY DESCRIPTION

Facility Description: Support facility for Army National Guard aviation units, including maintenance and repair activities

Is this a new facility? ☐ Y; ☑ N

Approximate facility size 31 acres.

Provide an area location map that shows the boundaries of the industrial site and arrows showing direction(s) of stromwater flow from the industrial site to the first receiving water.

III. ANNUAL FEE

Enclose a check for the first year of the annual permit fee specified in K.A.R. 28-16-56 et seq. as amended. Make the check payable to "KDHE". Per K.A.R. 28-16-56, as amended, the current annual permit fee for this general permit is $60. An invoice for the annual permit fee will be sent to the identified billing contact person requesting a permit until such time as the permittee submits a Notice of Termination (NOT).

IV. NOI CERTIFICATIONS

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

I understand that continued coverage under the NPDES general permit for Stormwater Runoff from Industrial Activity is contingent upon maintaining eligibility as provided for in the requirements and conditions of the general permit, and paying the annual fee.

Sam Mayfield — Signature (owner, operator, or duly authorized representative)

6/9/14 — Date

Sam Mayfield, Deputy chief. Env. — Name and Official Title (Please Print)

To receive a hard copy of the general permit packet, check yes: ☐Y; ☐ N

(Note: A copy of the permit can be obtained at www.kdheks.gov/stormwater)

Send completed form with original signature to:
Kansas Department of Health and Environment
Bureau of Water, Industrial Programs Section
1000 SW Jackson, Suite 420
Topeka, KS 66612 - 1367

KDHE Contact Information:
Phone: (785) 296-5545
E-mail: stormwater@kdheks.gov

SMART

Interfund Details

Interfund Id AA00125658 Delete Expand All Collapse All Notify

Accounts Receivable Transactions

Add Deposit Find Deposit Remove Deposit **Deposit BU** **Deposit ID**

Details

Deposit Status None Appl Contact Information

Posting Status Not Posted

Entered By

Entered Dt

Total Amt

AR Interfund Approval:
Not Approved **Approved**
Approved By
Approval Dt

Payment Find | View All First 1 of 1 Last

Payment ID **Budget Status** **Seq**

Customer ID

Distribution Details Customize | Find | View All | First 1 of 1 Last

Details More

Monetary Amount	Department	Fund	Budget Unit	Program	Account

Accounts Payable Transactions

Update Voucher Find Voucher Remove Voucher **AP BU** 03400 **Voucher** 00044579

Details

Vendor SetID SOKID **Post Status** Unposted **Budget Status** Not Chk'd

Vendor ID 0000020121 Contact Information

Invoice 19350

Invoice Date 06/09/2014

Total Amount 120.00

Entered By AG00DXL

Entered Dt 06/09/2014

AP Interfund Approval
Not Approved **Approved**
Approved By
Approval Dt

Distribution Details Customize | Find | View All | First 1 of 1 Last

Details More

Line	Dist	Monetary Amount	Department	Fund	Budget Unit	Program	Account
1	1	120.00	0347902000	3055	3300	96020	526900


Comments

Notice of Intent Application Fees Aviation Support Facilities 1 &2
Required under KAR 28-16-56


Schilling Air Force Base

Site Background

The former Schilling Air Force Base is a Formerly Used Defense Site (FUDS) located in southwest Salina, Kansas. The base was originally built as the Smoky Hill Army Airfield in 1942, and was used during World War II as a processing and staging area for heavy bombardment units going overseas, including B-17 and B-29 aircraft. In 1946 the name was changed to the Smoky Hill Air Force Base, and it served during the 1950's Korean conflict as a base for the Strategic Air Command and the 310th and 40th Bombardment Wings. In the late 1950's and early 1960's, the air force base underwent significant renovations resulting in the construction of a 12-silo Atlas F intercontinental ballistic missile complex, modifications to prepare for the next generation of aerial bombers and tankers, and another name change, the Schilling Air Force Base (Schilling AFB). The base was deactivated between 1965 and 1967; it is now used for the Salina Regional Airport and industrial, aviation, military, and educational facilities.



An aerial photograph of the Smoky Hill Army Air Field in 1943.



The Salina Municipal Airport in 2012.

The Salina Airport Authority (SAA), Kansas Department of Health and Environment (KDHE), the US Environmental Protection Agency (EPA), and the US Army Corps of Engineers (USACE) have conducted numerous environmental investigations and some limited remedial actions at the Schilling AFB Site since the mid-1990's. Contaminants of concern include volatile organic compounds (VOCs), semi-volatile organic compounds, and metals, which have been identified in soil and groundwater above their respective EPA maximum contaminant levels (MCLs) and KDHE Risk-based Standards for Kansas (RSKs). KDHE is also investigating the presence of perfluorinated chemicals (PFOS and PFOA), which are emerging contaminants. The former Schilling AFB Site has been divided into three Operable Units (OUs) based on the level of contamination and the highest potential risk to human health and the environment. OU-1 encompasses the northeastern portion of the former base, which now includes part of the Salina Regional Airport, Kansas State University-Salina, Salina TECH, various industrial and commercial businesses, and residential properties. OU-2 includes the southeastern portion of the former base and fire training area, which currently contains part of the Salina Regional Airport, Kansas National Guard Training facility, Schwans Plant, other various industrial and commercial businesses, and residential properties. OU-3 includes the western portion of the former base, runways, three former landfills, and other miscellaneous areas.

Activities between 1999 and 2012 were performed by USACE with KDHE oversight and included: removal of numerous underground storage tanks, installation of an air stripper at the Salina Vo-Tech School sump pump, vapor intrusion evaluation at select locations, a Remedial Investigation (RI) and Baseline Risk Assessment for OU-1, and long-term groundwater monitoring, At the conclusion of the USACE's RI, it was determined additional assessment was warranted in addition to completing a Feasibility Study (FS) to evaluate appropriate cleanup alternatives.

Current Investigation and Path Forward

In 2012 the Salina Public Entities (City of Salina, SAA, USD 305, and Kansas State University) negotiated a settlement with the USACE to complete the Remedial Investigation/Feasibility Study (RI/FS) scope of work under the oversight of KDHE. The Final RI work plan has been submitted to KDHE for review and was approved in August 2014. The Final RI Report was approved on June 18, 2018. The Draft Feasibility Study Report is currently under KDHE review.



Photo taken during the Remedial Investigation in 2015. Photo courtesy of Dragun Corporation.



Soil removal using large diameter augers. Photo courtesy of Dragun Corporation.

The Human Health Risk Assessment (HHRA), which quantitatively describes the potential excess human health risk posed by the Site in the absence of remediation, was approved on March 23, 2017. An addendum to the HHRA that evaluated the risk posed by PFOS/PFOA was approved on April 4, 2018.

The Final Groundwater Modeling Report was approved June 13, 2018. Groundwater models are computer models of groundwater systems that are used to simulate flow, contaminant fate and transport, and other hydrological conditions that are present at the Site.

Community Involvement

KDHE has solicited public comments regarding a proposal to address the environmental contamination. A Draft Corrective Action Decision (CAD) document that outlines the proposal for cleanup was made available for public review at the KDHE offices in Topeka and the Salina Public Library from April 8 to May 8, 2019. The Draft CAD and other pertinent information are also electronically available below. No further comments will be accepted.

A public availability session and hearing took place on May 1, 2019, at 6:00pm at the City of Salina City-County Building, 300 W. Ash Street, Salina. This session gave the public an opportunity to ask questions and provide comments on the Draft CAD.

KDHE prepared a Community Involvement Plan (CIP) to outline the Agency's community outreach program. KDHE is committed to promoting communication between the public and the Agency, and wants to make sure the community's concerns and information needs are considered as project activities progress. Ongoing input and involvement by citizens in the Salina community is essential for project success.

Additional Information

For additional information, please contact:

- Alex Richards (785-296-0969), KDHE-BER Project Manager

Site Documents

Portions of these reports may have been removed in order to make them web-ready. Complete copies are available by contacting Alex Richards or at SCHILLING AFB (PARENT SITE).

- Corrective Action Decision (Draft), April 2019 (.pdf)
- Feasibility Study Report, Revision 2, November 2018 (.pdf)
- Remedial Investigation Report - Revision 1, Part 01/14, February 2018 (.pdf)
- Supplemental Remedial Investigation #3 Report, Revision 1, March 2018 (.pdf)
- Pilot Studies Report Final, October 2017 (.pdf)
- Final Part III: Summary of Human Health Risk Assessment, January 2017 (.pdf)
- Summary of HHRA - Part III - Section 1 of 4 (January 2017)
- Groundwater Modeling Report - Revision 2, May 2018 (.pdf)
- Quarterly Progress Report #18 - 1st Quarter 2018, May 2018 (.pdf)
- Community Involvement Plan, August 2014 (.pdf)
- Consent Agreement and Final Order, Case No. 12-E-21 BER, November 2012 (.pdf)

Last updated on: 05/10/2019 14:50:23

Kansas.gov | *Privacy Notice* | *About KDHE* | *Contact Us* | *Directions* | *Open Records* | *WebMail* | *Webmaster*

© 1996-2018 Kansas Department of Health and Environment
Curtis State Office Building, 1000 SW Jackson, Topeka, Kansas 66612

NON-HAZARDOUS WASTE MANIFEST

1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Waste Tracking Number
KS3570090024	1	844-873-8723	003

GENERATOR

5. Generator's Name and Mailing Address

KANSAS ARNG/AASF 2
2917 HEIN (B)
SALINA, KS 67401

Generator's Phone: (785) 646-1152

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: TRADEBE TRANSPORTATION LLC — U.S. EPA ID Number: INR000123497

7. Transporter 2 Company Name — U.S. EPA ID Number

8. Designated Facility Name and Site Address

NORLITE LLC
628 SARATOGA STREET
COHOES, NY 12047

Facility's Phone: (518)235-0401

U.S. EPA ID Number: NYD080469935

	9. Waste Shipping Name and Description	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	
1.	NON DOT / NON RCRA REGULATED MATERIAL, (AFFF)	5	DM	2000	P	
2.						
3.						
4.						

13. Special Handling Instructions and Additional Information

[1] AFFF-MA-NR94C4 55GAL CLIN3

CONTRACT #SP450019D0002-SP450019F5849
TRADEBE TREATMENT AND RECYCLING, LLC
4343 KENNEDY AVENUE
E. CHICAGO, IN 46312

14. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations.

Generator's/Offeror's Printed/Typed Name: Kevin Durkes — Signature — Month: 8 — Day: 15 — Year: 19

INT'L

15. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:

Transporter Signature (for exports only): Date leaving U.S.:

TRANSPORTER

16. Transporter Acknowledgment of Receipt of Materials

Transporter 1 Printed/Typed Name: Zach Cooper — Signature — Month: 08 — Day: 15 — Year: 19

Transporter 2 Printed/Typed Name — Signature — Month — Day — Year

DESIGNATED FACILITY

17. Discrepancy

17a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection

Manifest Reference Number:

17b. Alternate Facility (or Generator) — U.S. EPA ID Number

Facility's Phone:

17c. Signature of Alternate Facility (or Generator) — Month — Day — Year

18. Designated Facility Owner or Operator: Certification of receipt of materials covered by the manifest except as noted in Item 17a

Printed/Typed Name — Signature — Month — Day — Year

ORDER FOR SUPPLIES OR SERVICES
(Contractor must submit four copies of invoice.)

Form approved CMB No. 0704-0187 Expires Dec 31, 1993

PAGE 1 of 3

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reveiwing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA, 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project(0704-0187), Washington, DC 20503.

MANIFEST # 12345

PLEASE DO NOT RETURN YOUR FORM TO EITHER OF THESE ADDRESSES
SEND YOUR COMPLETED FORM TO THE PROCUREMENT OFFICAL IDENTIFIED IN ITEM 6.

1. CONTRACT/PURCH ORDER NO.	2. DELIVERY ORDER NO.	3. DATE OF ORDER (YYMMDD)	4. REQUISITION/PURCH REQUEST NO.	5. PRIORITY
SP450019D0002	SP450019F5849	2019-07-15	SEE SCHEDULE	

6. ISSUED BY	CODE	SP4500	7. ADMINISTERED BY (if other than 6)	CODE	

8. DELIVERY FOB: [X] DEST [ ] OTHER (See Schedule if Other)

9. CONTRACTOR	CODE	0ZE15	FACILITY CODE	
NAME AND ADDRESS				

10. DELIVER TO FOB POINT BY (Date) (YYMMDD): 2020-05-29

11. MARK IF BUSINESS IS: [ ] SMALL [ ] SMALL DISAD-VANTAGED [ ] WOMEN-OWNED

12. DISCOUNT TERMS

13. MAIL INVOICES TO: SEE BLOCK 15

14. SHIP TO		15. PAYMENT WILL BE MADE BY	CODE	SL4701
SP450019D0002-SP450019F5849 SEE SCHEDULE				

MARK ALL PACKAGES AND PAPERS WITH CONTRACT OR ORDER NUMBER

16. TYPE OF ORDE: DELIVER [ ] PURCHASE [ ]

This delivery order is issued on another Government agency or in accordance with and subject to terms and conditions of above numbered contract.

Reference your ____ furnish the following on terms specified herein.

ACCEPTANCE. THE CONTRACTOR HEREBY ACCEPTS THE OFFER REPRESENTED BY THE NUMBERED PURCHASE ORDER AS IT MAY PREVIOUSLY HAVE BEEN OR IS NOW MODIFIED, SUBJECT TO ALL OF THE TERMS AND CONDITIONS SET FORTH, AND AGREES TO PERFORM THE SAME.

NAME OF CONTRACTOR	SIGNATURE	TYPED NAME AND TITLE	DATE SIGNED (YYMMDD)

[ ] If this box is marked, supplier must sign Acceptance and return the following number of copies:

17. ACCOUNTING AND APPROPRIATION DATA/LOCAL USE

01 97XXXXXXXX49305CBX80000120012520S33189 $ 3,720.30

18. ITEM NO.	19. SCHEDULE OF SUPPLIES/SERVICE	20. QUANTITY ORDERED/ ACCEPTED *	21. UNIT	22. UNIT PRICE	23. AMOUNT
0001	DOCUMENT NOUN DTID HIN ACC 9192KE1O W81NEE91780013 NR93C4 01 4210, W8111EE407190AFFF, AFFF WASTE, , , , , 9 55 GAL DRUM, 2019 04 18, , 1914, , APLD RCKR W81NEE 1914, , WT: 2512, ON FORT RILEY EPA ID KS6214020756 POC SHAWN LABONTE 785 239 8436 PICK UP DATE: 2020-05-29 PICKUP ADDR <W81NEE> ENV HAZ WASTE DISP BLDG 407 PERSHING CT FORT RILEY KS 664425936 USA	9	EA	$ 248.02	$ 2,232.18

* If quantity accepted by the government is same as quantity ordered, indicate by X. If different, enter actual quantity accepted below quantity ordered and encircle

24. UNITED STATES OF AMERICA
BY: Daniel Schuemann CONTRACTING/ORDERING OFFICER

25. TOTAL $ 3,720.30

29. DIFFERENCES

26. QUANTITY IN COLUMN 20 HAS BEEN
[ ] INSPECTED [ ] RECEIVED [ ] ACCEPTED AND CONFORMS TO THE CONTRACT EXCEPT AS NOTED

DATE SIGNATURE OF AUTHORIZED GOVERNMENT OFFICIAL

27. SHIP. NO. [ ] PARTIAL [ ] FINAL

28. D.O. VOUCHER NO.

30. INITIALS

32. PAID BY

33. AMOUNT VERIFIED CORRECT FOR

31. PAYMENT [ ] COMPLETE [ ] PARTIAL [ ] FINAL

34. CHECK NUMBER

35. BILL OF LADING NO.

36. I certify this account is correct and proper for payment.

DATE SIGNATURE AND TITLE OF CERTIFYING OFFICER

37. RECEIVED AT	38. RECEIVED BY (Print)	39. DATE RECEIVED (YYMMDD)	40. TOTAL CONTAINERS	41. S/R ACCOUNT NUMBER	42. S/R VOUCHER NO.

NAME OF OFFICER OR CONTRACTOR Pollution Control Industries MANIFEST # 12345

ITEM NO.						QUANTITY	UNIT	UNIT PRICE	AMOUNT
CLIN	DOCUMENT NOUN	DTID	HIN	ACC					
	EPA WASTE CODE _____ UD QTY PICKED UP 9 UO UNIT OF ISSUE EA								
	PICK UP MANIFEST 19D0219F5849 LINE CODE 1 PICKUP DATE _____								
0002	9192KE2A	W55LE691831001	NR94C4	01	1	EA	$ 248.02	$ 248.02	
	4210, W55LE691831, NOT REGULATED,AFFF WASTE NONE, , , , , 1 55 GL DM, 2019 07 02, , 1, , APLD RCKR W55LE6 1, , WT: 400, , KS4570090023 EPA ID POC KEVIN DURKES 785 646 0716								
	PICK UP DATE: 2020-05-30								
	PICKUP ADDR <W55LE6> 6700 TOPEKA AVE BLDG 688 J STREET AND GARY ORMSBY DR TOPEKA KS 666191441 USA								
	EPA WASTE CODE _____ UD QTY PICKED UP 1 UO UNIT OF ISSUE EA								
	PICK UP MANIFEST 19D0219F5849 LINE CODE 2 PICKUP DATE _____								
0003	9192KE3D	W81AWR91832001	NR94C4	01	5	EA	$ 248.02	$ 1,240.10	
	4210, W55LE691831, NOT REGULATED,AFFF , NONE, , , , , , , 5 55 GAL DM, 2019 07 02, , 1, , APLD RCKR W81AWR 1, , WT: 2000, , EPA ID KS3570090024 POC KEVIN DURKES 785 646 0716								
	PICK UP DATE: 2020-05-30								
	PICKUP ADDR <W81AWR> 2917 HEIN STREET SALINA KS 674011737 USA								
	EPA WASTE CODE _____ UD QTY PICKED UP 5 UO UNIT OF ISSUE EA								
	PICK UP MANIFEST 19D0219F5849 LINE CODE 3 PICKUP DATE _____								

continuation sheet	SP450019D0002-SP450019F5849	page of pages 3 | 3

NAME OF OFFICER OR CONTRACTOR Pollution Control Industries MANIFEST # 12345

ITEM NO.					QUANTITY	UNIT	UNIT PRICE	AMOUNT
CLIN	DOCUMENT NOUN	DTID	HIN	ACC				

DRMS

DOR: SP450019F5849

PROMPT PAYMENT (MAR 1994) FAR 52.232-25

AUTH TRANSPORTER NAME _____ AUTH TRANSPORTER EPA # _____

AUTH TSDF NAME _____ AUTH TSDF EPA # _____

TRANS SIGNATURE _____ TRANS PRINTED NAME _____

KTR SIGNATURE _____ KTR PRINTED NAME _____

AUTH COR SIGNATURE _____ AUTH COR PRINTED NAME _____

DOC	IDENT	RI FROM	VS	UNIT	ISSI	QUANTITY	SE	SUPPLEMENTARY ADDRESS	SIC	FUND	DISTRIBUTION	PROJECT	PRI	REQ	CEAT	ADV	RI	OP	CON	MGT
	A5J				Drum	5				92			R		S					H

1. TOTAL PRICE	UNIT PRICE DOLLARS	UNIT PRICE CTS	DOLLARS	CTS
	$248	02	$1240	10

2. SHIP FROM
W9QRF6 2917 HEIN STREET , SALINA, KS 67401-8129

3. SHIP TO
SZ3586

4. MARK FOR
KS3570090024

DEMIL A S

5. Doc Date	6. NMFC	7. FRT RATE	8. TYPE CARGO	9. PS
7/2/2019				

10. QTY. REC'D	11.UP	12. UNIT WEIGHT	13. UNIT CUBE	14. UFC	15. SL

24. DOCUMENT NUMBER & SUFFIX (30 - 44)
W81AWR91832001

25. NATIONAL STOCK NO. & ADD (8 - 22)
4210 - DSFIREEXI

PACKAGING EQUALS / EXCEEDS DOT 49 CER 170 - 189

16. FREIGHT CLASSIFICATION NOMENCLATURE
NOT REGULATED

17. ITEM NOMENCLATURE
ANSULITE 3% (AFC-3A) AFFF CONCENTRATE

18. TY CONT	19. NO CONT	20. TOTAL WEIGHT	21. TOTAL CUBE
55 GL-DM	5	2000 Pounds	

22. RECEIVED BY	23. DATE RECEIVED

26. Ric (4-6)
UI (23 - 24)
QTY (25 - 29)
CON CODE (71)
DIST (55 - 56)
UP (74 - 80)

THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIAL IS PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED AND LABELED AND IS IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO APPLICABLE REGULATIONS, FEDERAL DOT AND EPA.

27. ADDITIONAL DATA

EPA WASTE CODES:

STATE WASTE CODES:

DRUM NUMBERS:

SHIP FROM :
W8NA KS ARNG AASF 2
2917 HEIN STREET ,
SALINA ,KS 67401-8129

SHIP TO :
Riley
BLDG 1950 (CAMP FUNSTON) ,
Ft Rilev , KS 66442

WPS: W55LE691831 MSDS:

CLIN: NR91C4 UNIT PRICE: $248.02 TOTAL DISPOSAL COST: $1240.10 BILL TO DODAAC: W55RHF

FUND CITE: 21206510D19131G56VENQ3240A18KT40136707S210010 ACCUMULATED START DATE: 07/02/2019

EMERGENCY PHONE NUMBERS: SAM MYRRAN 785-806-2541

HAZARDOUS WASTE PROFILE SHEET

Prescribed by: DOD 4160.21 -M & DRMS-I 4160.14
Sponsor: Disposition Services

NOTE: Explosives, Shock Sensitive, Pyrophoric, Radioactive, and Etiological Waste are not normally accepted by the DLA Disposition Services Site.

Contact your DLA Disposition Services Site for further guidance if your waste meets any of these categories.

PART I

A. GENERAL INFORMATION

1. GENERATOR'S NAME: W89Z KS ARNG AASF 1

WASTE PROFILE NUMBER: W55LE691831

2. FACILITY ADDRESS: 6700 SW TOPEKA BLVD BLDG 682, J STREET AND GARY ORMSBY DR, Topeka, KS

3. ZIP CODE: 66619-1441

4. GENERATOR USEPA ID: KS4570090023

5. GENERATOR STATE ID: KS4570090023

6. TECHNICAL CONTACT: KEVIN DURKES

7. TITLE: HAZARDOUS WASTE MANAGER

8. PHONE: 785-646-0716

B. WASTE INFORMATION

1. NAME OF WASTE: ANSULITE 3% (AFC-3A) AFFF CONCENTRATE

2A. USEPA WASTE CODE(S):

2B. DEMIL CODE: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G ☐ P ☐ Q

2C. STATE / LOCAL / HOST - NATION WASTE CODES:

3. PROCESS GENERATING WASTE: G13 Cleaning out process equipment

4. PROJECTED ANNUAL VOL.: 0.0000

5. MODE OF COLLECTION: DM

6. IS THIS WASTE A DIOXIN LISTED WASTE AS DEFINED IN 40 CFR 261.31? ☐ YES ☒ NO

7. IS THIS WASTE RESTRICTED FROM LAND DISPOSAL? (40 CFR 268) ☐ YES ☒ NO

HAS AN EXEMPTION BEEN GRANTED? ☐ YES ☒ NO

DOES THE WASTE MEET APPLICABLE TREATMENT STANDARDS ALREADY? ☐ YES ☒ NO

(If Yes, Enter Reference Standards in Part II, Block 6)

PART II

1. MATERIAL CHARACTERIZATION *(Optional - Unless otherwise indicated)*

COLOR: LIGHT YELLOW

DENSITY: 0.000 BTU / LB

TOTAL SOLIDS: 0.00 ASH CONTENT: 0.00 LAYERING: ☐ MULTILAYERED ☐ BILAYERED ☐ SINGLE PHASE

PHYSICAL STATE (Mandatory): ☐ SOLID ☒ LIQUID ☐ SEMI-SOLID ☐ GAS ☐ OTHER

2. RCRA CHARACTERISTICS (Check all that apply) ☐ IGNITABLE (D001) ☐ CORROSIVE (D002) ☐ REACTIVE (D003)

☐ WATER REACTIVE ☐ CYANIDE REACT ☐ SULFIDE REACTIVE FLASH POINT: 212 PH: 7.5

☐ HIGH TOC (>10%) ☐ LOW TOC (<10%) TREATMENT GROUP ☐ WASTEWATER ☐ NON-WASTEWATER

☐ TOXICITY CHARACTERISTIC(D004 ☐ CORRODES STEEL

3. CHEMICAL / MATERIAL COMPOSITION (List all components and contaminants, including PCBs and any applicable F-Listed and Underlying Hazardous Constituents)

RANGE TOTAL MUST EQUAL AT LEAST 100%

4. SHIPPING INFORMATION

DOT HAZARDOUS MATERIAL? ☐ YES ☒ NO If "NO" skip to block 5)

PROPER SHIPPING NAME NOT REGULATED

HAZARD CLASS U.N or N.A. NO. PACKING GROUP

ADDITIONAL DESCRIPTION

METHOD OF SHIPMENT ☐ BULK ☒ DRUM OTHER

CERCLA REPORTABLE QTY (RQ) LBS (REF. 49 CFR 172.101, Appendix A)

EMERGENCY RESPONSE GUIDE EDITION 2016 EMERGENCY RESPONSE NO 111

5.SPECIAL HANDLING INFORMATION

6. GENERATOR CERTIFICATION ☐ CHEMICAL ANALYSIS *(ATTACH TEST RESULTS)* ☒ USER KNOWLEDGE *(ATTACH SUPPORTING DOCUMENTS)*

(Explain how and why these documents comply with RCRA requirements)

Additional Description: PRODUCT CODE 026700

Additional RCRA Requirements (MSDS Codes):

CERTIFICATION

I, KEVIN DURKES **HEREBY**

CERTIFY THAT ALL INFORMATION SUBMITTED IN THIS AND ALL ATTACHED DOCUMENTS IS TO THE BEST OF MY KNOWLEDGE AN ACCURATE REPRESENTATION OF THE WASTE TURNED IN TO THE DLA. ALL KNOWN OR SUSPECTED HAZARDS HAVE BEEN DISCLOSED.

DATE 07/02/2019

Signature of Generator's Representative

Safety Data Sheet

This safety data sheet complies with the requirements of: 2012 OSHA Hazard Communication Standard (29CFR 1910.1200)

Product name ANSULITE 3% (AFC-3A) AFFF Concentrate

1. Identification

1.1. Product Identifier

Product name ANSULITE 3% (AFC-3A) AFFF Concentrate

1.2. Other means of identification

Product code 026700
Synonyms None
Chemical Family No information available

1.3. Recommended use of the chemical and restrictions on use

Recommended use Fire extinguishing agent.
Uses advised against Consumer use.

1.4. Details of the Supplier of the Safety Data Sheet

Company Name Tyco Fire Protection Products
One Stanton Street
Marinette, WI 54143-2542
Telephone: 715-735-7411
Contact point Product Stewardship at 1-715-735-7411
E-mail address psra@tycofp.com

1.5. Emergency Telephone Number

Emergency telephone CHEMTREC 001-800-424-9300 or 001-703-527-3887

2. Hazards Identification

Classification

This product is not considered hazardous by the 2012 OSHA Hazard Communication Standard (29 CFR 1910.1200)

2.2. Label Elements

Hazard Statements

The product contains no substances which at their given concentration, are considered to be hazardous to health

Precautionary Statements

2.3. Hazards Not Otherwise Classified (HNOC)

Not Applicable.

2.4. Other Information

3. Composition/information on Ingredients

CERCLA
This material, as supplied, does not contain any substances regulated as hazardous substances under the Comprehensive Environmental Response Compensation and Liability Act (CERCLA) (40 CFR 302) or the Superfund Amendments and Reauthorization Act (SARA) (40 CFR 355). There may be specific reporting requirements at the local, regional, or state level pertaining to releases of this material

15.3. US State Regulations

California Proposition 65
This product contains the following Proposition 65 chemicals

Chemical name	California Proposition 65
Formaldehyde - 50-00-0	Carcinogen
Perfluorooctanoic acid - 335-67-1	Developmental Toxicity

U.S. State Right-to-Know Regulations

Chemical name	New Jersey	Massachusetts	Pennsylvania
2-(2-Butoxyethoxy)ethanol 112-34-5	X	-	X
t-Butanol 75-65-0	X	X	X
Formaldehyde 50-00-0	X	X	X

16. Other information, including date of preparation of the last revision

NFPA	**Health Hazards** 0	**Flammability** 0	**Instability** 0	**Physical and chemical properties** -
HMIS	**Health Hazards** 0	**Flammability** 0	**Physical Hazards** 0	**Personal Protection** X

Revision date 11-Jan-2019
Revision note 9, 16.
Disclaimer
The information provided in this Safety Data Sheet is correct to the best of our knowledge, information and belief at the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process, unless specified in the text.

End of Safety Data Sheet

Contaminated Packaging Do not reuse container.

14. Transport Information

DOT	NOT REGULATED
TDG	NOT REGULATED
MEX	NOT REGULATED
ICAO (air)	NOT REGULATED
IATA	NOT REGULATED
IMDG	NOT REGULATED

15. Regulatory Information

15.1. International Inventories

TSCA	Complies
DSL/NDSL	Does not comply
ENCS	Does not comply
IECSC	Does not comply
KECL	Complies
PICCS	Does not comply
AICS	Complies

Legend:

TSCA - United States Toxic Substances Control Act Section 8(b) Inventory
DSL/NDSL - Canadian Domestic Substances List/Non-Domestic Substances List
ENCS - Japan Existing and New Chemical Substances
IECSC - China Inventory of Existing Chemical Substances
KECL - Korean Existing and Evaluated Chemical Substances
PICCS - Philippines Inventory of Chemicals and Chemical Substances
AICS - Australian Inventory of Chemical Substances

15.2. US Federal Regulations

SARA 313

Section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1986 (SARA). This product contains a chemical or chemicals which are subject to the reporting requirements of the Act and Title 40 of the Code of Federal Regulations, Part 372

Chemical name	SARA 313 - Threshold Values %
2-(2-Butoxyethoxy)ethanol - 112-34-5	1.0

SARA 311/312 Hazard Categories

Acute Health Hazard	No
Chronic health hazard	No
Fire Hazard	No
Sudden Release of Pressure Hazard	No
Reactive Hazard	No

CWA (Clean Water Act)

This product does not contain any substances regulated as pollutants pursuant to the Clean Water Act (40 CFR 122.21 and 40 CFR 122.42)

Chemical name	Algae/aquatic plants	Fish	Crustacea
2-(2-Butoxyethoxy)ethanol 112-34-5	EC50 (96h) > 100 mg/L Desmodesmus subspicatus	LC50 (96h) static = 1300 mg/L Lepomis macrochirus	EC50 (48h) > 100 mg/L Daphnia magna EC50 (24h) = 2850 mg/L Daphnia magna
2-Methyl-2,4-pentanediol 107-41-5	-	LC50 (96h) static = 10700 mg/L Pimephales promelas LC50 (96h) static = 10000 mg/L Lepomis macrochirus LC50 (96h) flow-through = 8690 mg/L Pimephales promelas LC50 (96h) flow-through 10500 - 11000 mg/L Pimephales promelas	EC50 (48h) 2700 - 3700 mg/L Daphnia magna
t-Butanol 75-65-0	EC50 (72h) > 1000 mg/L Desmodesmus subspicatus	LC50 (96h) flow-through 6130 - 6700 mg/L Pimephales promelas	EC50 (48h) = 933 mg/L Daphnia magna EC50 (48h) Static 4607 - 6577 mg/L Daphnia magna
Sodium chloride 7647-14-5	-	LC50 (96h) flow-through 4747 - 7824 mg/L Oncorhynchus mykiss LC50 (96h) semi-static = 7050 mg/L Pimephales promelas LC50 (96h) static = 12946 mg/L Lepomis macrochirus LC50 (96h) static 6020 - 7070 mg/L Pimephales promelas LC50 (96h) flow-through 5560 - 6080 mg/L Lepomis macrochirus LC50 (96h) static 6420 - 6700 mg/L Pimephales promelas	EC50 (48h) Static 340.7 - 469.2 mg/L Daphnia magna EC50 (48h) = 1000 mg/L Daphnia magna
Polyethylene Glycol 25322-68-3	-	LC50 (24h) > 5000 mg/L Carassius auratus	-
Formaldehyde 50-00-0	-	LC50 (96h) static 100 - 136 mg/L Oncorhynchus mykiss LC50 (96h) flow-through 0.032 - 0.226 mL/L Oncorhynchus mykiss LC50 (96h) flow-through 22.6 - 25.7 mg/L Pimephales promelas LC50 (96h) static 23.2 - 29.7 mg/L Pimephales promelas LC50 (96h) static = 41 mg/L Brachydanio rerio LC50 (96h) static = 1510 µg/L Lepomis macrochirus	LC50 (48h) = 2 mg/L Daphnia magna EC50 (48h) Static 11.3 - 18 mg/L Daphnia magna

12.2. Persistence and Degradability
No information available.

12.3. Bioaccumulation
No information available.

12.4. Other Adverse Effects
No information available

13. Disposal Considerations

13.1. Waste Treatment Methods
Disposal of wastes Disposal should be in accordance with applicable regional, national and local laws and regulations.

10.4. Conditions to Avoid

Extremes of temperature and direct sunlight.

10.5. Incompatible Materials

Strong oxidizing agents. Strong acids. Strong bases.

10.6. Hazardous decomposition products

Carbon oxides. Nitrogen oxides (NOx). Oxides of sulfur. Fluorinated oxides.

11. Toxicological Information

11.1. Information on Likely Routes of Exposure

Product information No data available

Inhalation No data available.

Eye Contact No data available.

Skin contact No data available.

Ingestion No data available.

Component Information
Acute Toxicity

Chemical name	Oral LD50	Dermal LD50	Inhalation LC50
2-(2-Butoxyethoxy)ethanol 112-34-5	= 5660 mg/kg (Rat)	= 2700 mg/kg (Rabbit)	-

11.2. Information on Toxicological Effects

Symptoms No information available.

11.3. Delayed and immediate effects as well as chronic effects from short and long-term exposure

Carcinogenicity No information available.
Reproductive Toxicity No information available.
STOT - Single Exposure No information available.
STOT - Repeated Exposure No information available.
Aspiration Hazard No information available.

11.4. Numerical Measures of Toxicity - Product information

The following values are calculated based on chapter 3.1 of the GHS document

ATEmix (oral) 28637 mg/kg
ATEmix (dermal) 30928 mg/kg

12. Ecological Information

12.1. Ecotoxicity

Not classified.

required for high airborne contaminant concentrations. Respiratory protection must be provided in accordance with current local regulations.

Ventilation Use local exhaust or general dilution ventilation to control exposure with applicable limits

8.4. General hygiene considerations

Do not eat, drink or smoke when using this product. Handle in accordance with good industrial hygiene and safety practice.

9. Physical and Chemical Properties

9.1. Information on basic physical and chemical properties

Physical State	Liquid		
Odor	Characteristic	**Color**	Light yellow
Odor Threshold	No data available		

Property	Values	Remarks • Method
pH	7.5	
Melting point/freezing point	No data available	
Boiling point / boiling range	> 100 °C / 212 °F	
Flash Point	°C / °F	No flash up to boiling point.
Evaporation Rate	No data available	
Flammability (solid, gas)	No data available	
Flammability limit in air		
Upper flammability limit:	No data available	
Lower flammability limit:	No data available	
Vapor Pressure	No data available	
Vapor Density	No data available	
Specific gravity	No data available	
Water Solubility	No data available	
Solubility in Other Solvents	No data available	
Partition coefficient	No data available	
Autoignition Temperature	No data available	
Decomposition Temperature	No data available	
Kinematic viscosity	2.9 mm2/s	
VOC content (%)	9.21317	
Density	1.03	

10. Stability and Reactivity

10.1. Chemical Stability

Stable under recommended storage conditions.

10.2. Reactivity

No data available

10.3. Possibility of hazardous reactions

None under normal processing.

Hazardous Polymerization Hazardous polymerization does not occur.

6. Accidental release measures

6.1. Personal precautions, protective equipment and emergency procedures

Personal Precautions Ensure adequate ventilation, especially in confined areas.

For emergency responders Use personal protection recommended in Section 8.

6.2. Environmental Precautions

Environmental Precautions Prevent further leakage or spillage if safe to do so. Prevent entry into waterways, sewers, basements or confined areas. See Section 12 for additional Ecological Information.

6.3. Methods and material for containment and cleaning up

Methods for Containment Prevent further leakage or spillage if safe to do so.

Methods for Cleaning Up Pick up and transfer to properly labeled containers.

7. Handling and Storage

7.1. Precautions for Safe Handling

Advice on safe handling Avoid contact with skin and eyes. Handle in accordance with good industrial hygiene and safety practice.

7.2. Conditions for safe storage, including any incompatibilities

Storage Conditions Keep containers tightly closed in a dry, cool and well-ventilated place.

Incompatible Materials Strong oxidizing agents. Strong acids. Strong bases.

8. Exposure Controls/Personal Protection

8.1. Control Parameters

Exposure guidelines

Chemical name	ACGIH TLV	OSHA PEL	NIOSH IDLH	Mexico OEL
2-(2-Butoxyethoxy)ethanol 112-34-5	TWA: 10 ppm inhalable fraction and vapor	-	-	-

ACGIH (American Conference of Governmental Industrial Hygienists) OSHA (Occupational Safety and Health Administration of the US Department of Labor) NIOSH IDLH Immediately Dangerous to Life or Health

8.2. Appropriate Engineering Controls

Engineering controls Ensure adequate ventilation, especially in confined areas.

8.3. Individual protection measures, such as personal protective equipment

Eye/Face Protection Avoid contact with eyes. Tight sealing safety goggles.

Skin and Body Protection Wear protective gloves and protective clothing.

Respiratory Protection If exposure limits are exceeded or irritation is experienced, NIOSH/MSHA approved respiratory protection should be worn. Positive-pressure supplied air respirators may be

3.1. Mixture

The following component(s) in this product are considered hazardous under applicable OSHA(USA)

Chemical name	CAS No.	weight-%
2-(2-Butoxyethoxy)ethanol	112-34-5	5 - 10
Lauryl Imino Propionate, Sodium Salt	14960-06-6	1 - 5

4. First aid measures

4.1. Description of first aid measures

Eye Contact Rinse thoroughly with plenty of water for at least 15 minutes, lifting lower and upper eyelids. Consult a physician.

Skin contact Wash skin with soap and water. Get medical attention if irritation develops and persists.

Inhalation Remove to fresh air. If breathing is difficult, give oxygen. (Get medical attention immediately if symptoms occur.).

Ingestion Rinse mouth. Do not induce vomiting without medical advice. If swallowed, call a poison control center or physician immediately.

4.2. Most Important Symptoms and Effects, Both Acute and Delayed

Symptoms No information available.

4.3. Indication of Any Immediate Medical Attention and Special Treatment Needed

Note to physicians Treat symptomatically.

5. Fire-fighting measures

5.1. Suitable Extinguishing Media

Use extinguishing measures that are appropriate to local circumstances and the surrounding environment.

5.2. Unsuitable Extinguishing Media

None.

5.3. Specific Hazards Arising from the Chemical

None known.

Hazardous Combustion Products Carbon oxides, Fluorinated oxides, Nitrogen oxides (NOx), Oxides of sulfur

5.4. Explosion Data

Sensitivity to Mechanical Impact None.
Sensitivity to Static Discharge None.

5.5. Protective Equipment and Precautions for Firefighters

As in any fire, wear self-contained breathing apparatus pressure-demand, MSHA/NIOSH (approved or equivalent) and full protective gear.

TURN-IN SUMMARY REPORT

Turn-In File Name: W90RF6_2019183_1

Turn-In Date: 07/02/2019

DRMO Name: Riley

DRMO DoDAAC: SZ3586

DRMO RIC: SY4A

STATE: KS

DTID NO	INVENTORY NAME	PROPER SHIPPING NAME	WASTE PROFILE NO	FACILITY NAME	FACILITY EPA ID	CLIN	CNTR DESC	WGHT	UNIT	QTY	COST
W81AWR91832001	ANSULITE 3% (AFC-3A) AFFF CONCENTRATE	NOT REGULATED	W55LE691831	W8NA KS ARNG AASF 2	KS3570090024	NR91C4	55 GL-DM	2000	DR	5	1240.10

DD FORM 1348-1A, JUL 91 (EG) ISSUE RELEASE/RECEIPT REPRINT Page 1 of 1

DOC	IDENT	RI FROM	M&S	UNIT	ISSUE	QUANTITY	SER	SUPPLEMENTARY ADDRESS	SIG	FUND	DISTRIBUTION	PROJECT	PRI	REQ'D DEL DATE	ADV	RI	O/P	COND	MGT	UNIT PRICE DOLLARS	UNIT PRICE CTS	DOLLARS	CTS
A5A				EA		00008	W	81K4NA		92			13			A31		A		00000	00	0000000	00

1.TOTAL PRICE

2.SHIP FROM W81AWR

3.SHIP TO W81K4N

4. Mark For: W81K4N
W7M9 USPFO ACTIVITY KS ARNG
AWCF SSF
2737 S KANSAS AVE BLDG 202
TOPEKA KS 66611-1169
USA

24. DOCUMENT NUMBER & SUFFIX (30-44)

W81AWR91480001

Outbound Del Num:
8030027634/000010

25. NATIONAL STOCK NO & RDD (8-22)

421001C042172

26. RIC(4-6) UI(23-24) QTY(25-29) CON CODE(71) DIST(54-56) UP(74-80)

EA00008A0000000

27. ADDITIONAL DATA

5.DOC DATE	6.NMFC	7.FRT RATE	8.TYPE CARGO	9.PS
9148				U

10.QTY RECD	11.UP	12.UNIT WEIGHT	13.UNIT CUBE	14.UFC	15.SL
	EA	0.000	0.000		0

16.FREIGHT CLASSIFICATION NOMENCLATURE

17.ITEM NOMENCLATURE
EXTINGUISHER, FIRE WHEELED, GAS DISHCHAR

18. TY CONT	19.NO CONT	20.TOTAL WEIGHT	21.TOTAL CUBE
		0.000	0.000

22.RECEIVED BY

23.DATE RECEIVED

PROCESSED BY: KECK , J

90490977 090319-003 2098738

NON-HAZARDOUS WASTE MANIFEST

1. Generator ID Number: KS3570090024
2. Page 1 of: 1
3. Emergency Response Phone: 844-373-8723
4. Waste Tracking Number: 090319 — 003

5. Generator's Name and Mailing Address
KANSAS ARNG/AASF 2
2917 HEIN (B)
SALINA, KS 67401
Generator's Phone: (785) 646-1152

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name
TRADEBE TRANSPORTATION LLC
U.S. EPA ID Number: INR000123497

7. Transporter 2 Company Name
Basin Trans
U.S. EPA ID Number: OKR000031492

8. Designated Facility Name and Site Address
NORLITE LLC
628 SARATOGA STREET
COHOES, NY 12047
Facility's Phone: (518)235-0401
U.S. EPA ID Number: NYD080469935

	9. Waste Shipping Name and Description	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	
1.	NON DOT / NON RCRA REGULATED MATERIAL. (AFFF)	5	DM	2000	P	
2.						
3.						
4.						

13. Special Handling Instructions and Additional Information
[1] AFFF-MA-NR94C4 55GAL CLIN3
SO# 2098738
CONTRACT #SP450019D0002-SP450019F5849
TRADEBE TREATMENT AND RECYCLING, LLC
4343 KENNEDY AVENUE
E CHICAGO IN 46312

14. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations.

Generator's/Offeror's Printed/Typed Name: Kevin DuKes
Signature:
Month 8 Day 15 Year 19

15. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter Signature (for exports only): Date leaving U.S.:

16. Transporter Acknowledgment of Receipt of Materials

Transporter 1 Printed/Typed Name: Zach Cooper
Signature:
Month 08 Day 15 Year 19

Transporter 2 Printed/Typed Name: DAVID DERRY
Signature:
Month 08 Day 21 Year 19

17. Discrepancy

17a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection

Manifest Reference Number:

17b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:

17c. Signature of Alternate Facility (or Generator)
Month Day Year

18. Designated Facility Owner or Operator: Certification of receipt of materials covered by the manifest except as noted in Item 17a

Printed/Typed Name: Pamela Cyprian
Signature:
Month 9 Day 3 Year 19

GENERATOR
INT'L
TRANSPORTER
DESIGNATED FACILITY

169-BLC-O 6 10498 (Rev. 9/09)

DESIGNATED FACILITY TO GENERATOR

Salina AASF

2917 Hein Avenue

Salina, KS 67401

Inquiry Number: 5776851.5

September 04, 2019

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

09/04/19

Site Name:

Salina AASF
2917 Hein Avenue
Salina, KS 67401
EDR Inquiry # 5776851.5

Client Name:

AECOM
12120 Shamrock Plaza
Omaha, NE 68154
Contact: Hans Sund

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	Scale	Details	Source
2017	1"=500'	Flight Year: 2017	USDA/NAIP
2010	1"=500'	Flight Year: 2010	USDA/NAIP
2006	1"=500'	Flight Year: 2006	USDA/NAIP
2003	1"=500'	Acquisition Date: April 09, 2003	USGS/DOQQ
1997	1"=500'	Flight Date: April 16, 1997	USGS
1985	1"=500'	Flight Date: July 05, 1985	USDA
1982	1"=500'	Flight Date: June 22, 1982	USGS
1977	1"=750'	Flight Date: February 10, 1977	USGS
1973	1"=1000'	Flight Date: August 02, 1973	USGS
1954	1"=500'	Flight Date: July 09, 1954	USGS


When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2019 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.



INQUIRY #: 5776851.5

YEAR: 2017

= 500'

N

EDR




INQUIRY #: 5776851.5


YEAR: 2010

= 500'

N

EDR


INQUIRY #: 5776851.5
YEAR: 2006
= 500'
N
EDR


INQUIRY #: 5776851.5
YEAR: 2003
= 500'
N
EDR




INQUIRY #: 5776851.5

YEAR: 1997

= 500'

N

EDR



INQUIRY #: 5776851.5

YEAR: 1985

= 500'

N

EDR



INQUIRY #: 5776851.5

YEAR: 1982

= 500'

N

EDR



INQUIRY #: 5776851.5

YEAR: 1977

= 750'

N

EDR

Subject boundary not shown because it exceeds image extent or image is not georeferenced.



INQUIRY #: 5776851.5


YEAR: 1973

= 1000'

N

EDR

Subject boundary not shown because it exceeds image extent or image is not georeferenced.



INQUIRY #: 5776851.5

YEAR: 1954

= 500'

N

EDR

Subject boundary not shown because it exceeds image extent or image is not georeferenced.

Salina AASF
2917 Hein Avenue
Salina, KS 67401

Inquiry Number: 5776851.2s
September 04, 2019

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	555
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-9
Physical Setting Source Map Findings	A-11
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2019 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

2917 HEIN AVENUE
SALINA, KS 67401

COORDINATES

Latitude (North):	38.7850400 - 38° 47' 6.14''
Longitude (West):	97.6374700 - 97° 38' 14.89''
Universal Tranverse Mercator:	Zone 14
UTM X (Meters):	618345.4
UTM Y (Meters):	4293596.5
Elevation:	1256 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5691529 SALINA SW, KS
Version Date:	2012
Northeast Map:	5691501 SALINA, KS
Version Date:	2012

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150713
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
2917 HEIN AVENUE
SALINA, KS 67401

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	KS ARMY NATL GUARD-S	2917 HELM STREET	KS TIER 2		TP
A2	AC HELICOPTERS	2917 HEIN ST	SEMS-ARCHIVE, RCRA NonGen / NLR		TP
A3	KS ARMY NATL GUARD-S	2917 HEIN AVENUE	KS TIER 2		TP
A4	ARMY AVIATION SUPPOR	2917 HEIN AVE.	FINDS, ECHO		TP
A5	KANSAS ARNG/AASF 2	2917 HEIN (B)	RCRA-CESQG, FINDS, ECHO, WI MANIFEST		TP
A6	A C HELICOPTERS	2917 HEIN (A)	FINDS, ECHO		TP
A7	KS ARMY NATL GUARD-S	2917 HELM STREET	FINDS		TP
A8		2917 HEIN AVE.	KS SPILLS		TP
B9	SALINA AIRPORT AUTHO	2734 ARNOLD COURT	US BROWNFIELDS	Higher	1 ft.
C10	SFC GLOBAL SUPPLY CH	3019 SCANLAN AVE.	KS LUST, KS SPILLS, KS AIRS, KS TIER 2	Lower	1 ft.
D11	REGIONAL TRAINING SI	2750 SCANLAN	RCRA-CESQG, ICIS, FINDS, ECHO	Lower	1 ft.
C12	TONYS PIZZA SVC INC	3019 SCANLAN AVE	RCRA-SQG, KS UST, RMP, ICIS, US AIRS, FINDS, ECHO	Lower	1 ft.
E13	SAA	2846 CENTENNIAL RD.	KS LUST, KS UST	Lower	1 ft.
F14	AFK SOC	1605 W. SCHILLING RO	KS LUST, KS UST, KS Financial Assurance	Lower	1 ft.
G15	SALINA WASTE SYSTEMS	1848 SUMMERS	RCRA-CESQG, FINDS, ECHO	Higher	1 ft.
E16	S & K AUTOMOTIVE	2846 CENTENNIAL RD	EDR Hist Auto	Lower	1 ft.
E17	SALINA AIRPORT AUTH	2846 CENTENNIAL RD	RCRA NonGen / NLR	Lower	1 ft.
D18	SCHILLING FAM HOUSG		FUDS	Higher	1 ft.
19	OVATION CABINETRY IN	2804 ARNOLD	RCRA NonGen / NLR, FINDS, ECHO	Higher	1 ft.
H20	KOSS CONSTRUCTION CO	2782A ARNOLD RD	KS AST	Higher	1 ft.
21	SALINA CITY LANDFILL	RT 3 & BURMA RD.	KS SHWS	Lower	1 ft.
22	SALINA AIRPORT AUTHO	BERSCHEL AVE	US BROWNFIELDS, FINDS	Lower	1 ft.
B23	SALINA AIRPORT AUTHO	2734 ARNOLD COURT BU	KS SHWS, KS BROWNFIELDS	Higher	1 ft.
H24	SLN ATCT	2000 KNEUBUHL COURT	KS AST	Higher	1 ft.
H25	MID KANSAS REBUILDER	2775 ARNOLD STE G	RCRA NonGen / NLR, FINDS, ECHO	Higher	1 ft.
H26	FEDERAL EXPRESS	2770 ARNOLD	RCRA NonGen / NLR, FINDS, ECHO	Higher	1 ft.
H27	BLUE BEACON INTERNAT	2770 ARNOLD	KS LUST	Higher	1 ft.
F28	SCHILLING AFB OU2		KS SHWS	Lower	1 ft.
I29	LANDES OIL CO INC	2948 ARNOLD	EDR Hist Auto	Higher	1 ft.
F30	DIVERSIFIED NEON	3037 S CENTENNIAL	RCRA NonGen / NLR, FINDS, ECHO	Lower	1 ft.
31	NICKELL BARRACKS TRA	1844 JUMPER	KS LUST, KS UST, RCRA NonGen / NLR, FINDS, ECHO	Lower	1 ft.
I32	SAA, PUMPHOUSE BLDG	SALINA AIRPORT	KS UST, KS AST, KS Financial Assurance	Higher	1 ft.
I33	REGIONAL TRAINING SI	2931 ARNOLD (B)	RCRA NonGen / NLR, ICIS, US AIRS	Higher	1 ft.
I34	DEAN MARKLEY ELECTRO	2931 ARNOLD (A)	RCRA NonGen / NLR, FINDS, ECHO	Higher	1 ft.
I35	SALINA AIRPORT AUTHO	2934 ARNOLD AVENUE B	KS SHWS, KS BROWNFIELDS	Higher	1 ft.
I36	SALINA AIRPORT AUTHO	2934 ARNOLD AVENUE	US BROWNFIELDS	Higher	1 ft.
B37	PORTAPORT	2711 ARNOLD	RCRA NonGen / NLR, FINDS, ECHO	Higher	1 ft.
J38	KSU - SALINA REDEVEL	1732 SUMMERS ROAD	US BROWNFIELDS, FINDS	Lower	1 ft.
J39	KSU - SALINA REDEVEL	1732 SUMMERS ROADS	US BROWNFIELDS, FINDS	Lower	1 ft.

MAPPED SITES SUMMARY

Target Property Address:
2917 HEIN AVENUE
SALINA, KS 67401

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
F40	MR GS OF KANSAS	1605 W SCHILLING RD	EDR Hist Auto	Lower	1 ft.
G41	SALINA WASTE SYSTEMS	1848 SUMMERS RD	KS AST	Higher	1 ft.
J42	KSU - SALINA REDEVEL	1732 SUMMERS ROAD	US BROWNFIELDS, FINDS	Lower	1 ft.
E43	SUMMERS ROAD	INTERSECTION OF SUMM	SEMS	Lower	1 ft.
44	NICKELL BARRACKS TRA	RR #1, SMOKY HILL WE	KS UST	Lower	1 ft.
J45	KSU - SALINA REDEVEL	1732 SUMMERS ROAD	US BROWNFIELDS, FINDS	Lower	1 ft.
E46	SUMMERS ROAD		KS SHWS	Lower	1 ft.
K47	SMOKY HILL ANG RANGE	OLD OPS, 184 CES/DE	KS UST	Higher	6, 0.001, WSW
K48	SMOKY HILL ANG RANGE	BLDG 6010, 184 CES/D	KS UST	Higher	6, 0.001, WSW
K49	SMOKY HILL ANG RANGE	BLDG 6003, 184 CES/D	KS UST	Higher	6, 0.001, WSW
K50	SMOKY HILL ANG RANGE	BLDG 4001, 184 CES/D	KS UST	Higher	6, 0.001, WSW
K51	SMOKY HILL ANG RANGE	BLDG 6001, 184 CES/D	KS UST	Higher	6, 0.001, WSW
B52	FLOWER AVIATION	SALINA AIRPORT	KS LUST, KS UST, KS Financial Assurance	Higher	154, 0.029, NNW
L53	SCHILLING AFB (PAREN		KS SHWS	Higher	200, 0.038, NNW
54	SAA, BLDG #105	SALINA AIRPORT	KS UST	Higher	212, 0.040, SSW
M55	HAWKER BEECHCRAFT -	2656 SCANLAN AVENUE	KS LUST, KS UST, ICIS, FINDS	Lower	215, 0.041, NNE
M56	BEECH SALINA AIRPORT	SALINA AIRPORT	KS LUST, KS TIER 2	Lower	215, 0.041, NNE
M57	TISCHLEREI - FINE WO	2656 SCANLAN AVE	RCRA-SQG	Lower	215, 0.041, NNE
N58	PONY EXPRESS COURIER	3119 ARNOLD	KS UST	Higher	217, 0.041, SSW
N59	SALINA AIRPORT CELL	3119 ARNOLD AVE.	KS AST	Higher	217, 0.041, SSW
N60	SALINA AIRPORT AUTHO	3119-B ARNOLD AVE	KS LUST	Higher	217, 0.041, SSW
L61	SALINA AIRPORT REDEV	2720 ARNOLD AVE	US BROWNFIELDS, FINDS	Higher	221, 0.042, NNW
L62	SALINA AIRPORT REDEV	2720 ARNOLD COURT	KS SHWS	Higher	221, 0.042, NNW
O63	PAUL SCHWAN TECH CTR	3123 CENTENNIAL	RCRA-CESQG, FINDS, ECHO	Lower	291, 0.055, SE
O64	KANSAS VOC REHAB CTR	3140 CENTENNIAL	RCRA NonGen / NLR	Lower	327, 0.062, SE
O65	SCHWAN - SALINA DIST	3140 CENTENNIAL ROAD	KS LUST, KS UST, KS Financial Assurance	Lower	327, 0.062, SE
P66	PONY EXPRESS COURIER	3199 ARNOLD	KS LUST	Higher	563, 0.107, SSW
67	SCHILLING AFB AF FAC		FUDS	Lower	574, 0.109, NW
Q68	GAS INSTRUCTION AREA		UXO	Higher	591, 0.112, West
Q69	CONVENTIONAL TRAININ		UXO	Higher	591, 0.112, West
Q70	SCHILLING AFB		FUDS	Higher	591, 0.112, West
P71	KHP TROOP C HEADQUAR	3213 ARNOLD AVE	KS LUST, KS UST	Higher	623, 0.118, SSW
P72	SALINA AIRCRAFT SERV	3148 ARNOLD	KS UST, KS Financial Assurance	Higher	703, 0.133, SSW
P73	LEASE & RENTAL INC-A	3230 ARNOLD RD	KS UST	Higher	703, 0.133, SSW
P74	ADM MILLING	3140 ARNOLD	RCRA NonGen / NLR, FINDS, ECHO	Higher	703, 0.133, SSW
P75	BLUE BEACON INTERNAT	3140 ARNOLD	KS UST, KS AST, KS Financial Assurance	Higher	703, 0.133, SSW
R76	DEAL PET CO	2624 CENTENNIAL	RCRA NonGen / NLR, FINDS, ECHO	Lower	794, 0.150, NNE
77	SALINA AIRPORT AUTHO	BERSCHEL AVE & SCANL	KS SHWS, KS BROWNFIELDS	Lower	796, 0.151, NNE
R78	BUILDERS CHOICE CONC	2601 CENTENNIAL RD	KS AST	Lower	800, 0.152, NNE

MAPPED SITES SUMMARY

Target Property Address:
2917 HEIN AVENUE
SALINA, KS 67401

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
S79	STUDENT ACTIVITY FUN	2562 SCANLAN AVE	KS LUST, KS UST	Lower	842, 0.159, North
S80	USD #305	2562 SCANLON AVENUE	KS UST	Lower	842, 0.159, North
81	EL DORADO INDUSTRIES	614 LOWE	RCRA NonGen / NLR, FINDS, ECHO	Lower	944, 0.179, North
T82	SCHILLING DEF GUIDED	CORNER OF CENTENNIAL	KS SHWS, FINDS	Lower	951, 0.180, NNE
U83	MEMORIAL HALL		KS UST	Higher	981, 0.186, SSW
U84	SALINA RAILYARD		KS UST	Higher	981, 0.186, SSW
U85	SMOKY HILL WEAPONS R		KS SHWS	Higher	981, 0.186, SSW
U86	SCHILLING (EX) AIR F	3237 ARNOLD AVE	SEMS, RCRA NonGen / NLR, PRP, ICIS, FINDS, ECHO	Higher	983, 0.186, SSW
T87	SCHILLING DEF-GM FLD		FUDS	Lower	1001, 0.190, NNE
88	SCHILLING AFB AF FAC	NA	KS SHWS	Lower	1072, 0.203, NW
V89	SALINA AREA TECHNICA	2562 CENTENNIAL RD	RCRA-CESQG	Lower	1277, 0.242, North
V90	FORMER BEECH - SALIN	2562 CENTENNIAL ROAD	KS SHWS	Lower	1277, 0.242, North
91	FAA, SALINA	SALINA VORTAC	KS LUST	Lower	1279, 0.242, NW
92	LOVE BOX CO INC	3330 CENTENNIAL	RCRA-CESQG, FINDS, ECHO	Lower	1312, 0.248, SSE
93	ADM MILLING CO	2806 HEIN MUNCIPAL A	KS LUST, KS UST	Lower	1606, 0.304, North
94	SCHILLING FAMILY HOU	SCHILLING ROAD	KS SHWS, FINDS	Lower	1851, 0.351, East
95	FSLN RCAG	SALINA MUNICIPAL AIR	KS LUST, KS UST, KS AST	Higher	1892, 0.358, West
96	SMOKY HILL INC	1615 W MAGNOLIA	KS LUST, KS UST, KS AST	Lower	2016, 0.382, NNE
97	SALINA AIRPORT AUTHO	NW OF INTERSECTION S	KS SHWS, KS BROWNFIELDS	Higher	2181, 0.413, South
W98	SALINA AIRPORT AUTHO	2461 CENTENNIAL RD	US BROWNFIELDS, FINDS	Lower	2206, 0.418, NNE
W99	SALINA AIRPORT AUTHO	2461 CENTENNIAL RD	KS SHWS	Lower	2206, 0.418, NNE
100	KSU-SALINA	2409 SCANLAN AVE	KS LUST	Lower	2441, 0.462, North
101	SALINA AIRPORT AUTHO	SW INTERSECTION OF W	US BROWNFIELDS, FINDS	Higher	2503, 0.474, South
102	KSU-SALINA REDEVELOP	2310 CENTENNIAL ROAD	KS SHWS, KS SPILLS	Lower	3299, 0.625, North
103	SCHILLING AFB OU3		KS SHWS	Higher	3521, 0.667, West
104	SCHILLING AFB OU1		KS SHWS	Lower	3762, 0.712, North
105	SALINA AIRPORT AUTHO	VORTEX AVE & SCANLAN	KS SHWS, KS BROWNFIELDS	Higher	3814, 0.722, South
106	SALINA AIRPORT AUTHO	3600 AIRPORT ROAD BU	KS SHWS, KS BROWNFIELDS	Higher	4458, 0.844, SW
X107	SALINA AIRPORT AUTHO	SCANLAN RD. AND WATE	KS SHWS, KS BROWNFIELDS	Higher	4532, 0.858, South
X108	SALINA AIRPORT AUTHO	SCANLAN RD. AND WATE	KS SHWS, KS BROWNFIELDS	Higher	4532, 0.858, South

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
KS ARMY NATL GUARD-S 2917 HELM STREET SALINA, KS 67401	KS TIER 2 Facility Id: 372686	N/A
AC HELICOPTERS 2917 HEIN ST SALINA, KS 67401	SEMS-ARCHIVE Site ID: 0700550 EPA Id: KSD097705313 RCRA NonGen / NLR EPA ID:: KSD097705313	KSD097705313
KS ARMY NATL GUARD-S 2917 HEIN AVENUE SALINA, KS 67401	KS TIER 2 Facility Id: 372686	N/A
ARMY AVIATION SUPPOR 2917 HEIN AVE. SALINA, KS 67401	FINDS Registry ID:: 110060362664 ECHO Registry ID: 110060362664	N/A
KANSAS ARNG/AASF 2 2917 HEIN (B) SALINA, KS 67401	RCRA-CESQG EPA ID:: KS3570090024 FINDS Registry ID:: 110003144543 ECHO Registry ID: 110003144543 WI MANIFEST ACT Status: A FID: 0 EPA ID: KS3570090024	KS3570090024
A C HELICOPTERS 2917 HEIN (A) SALINA, KS 67401	FINDS Registry ID:: 110003163718 ECHO Registry ID: 110003163718	N/A
KS ARMY NATL GUARD-S 2917 HELM STREET SALINA, KS 67401	FINDS Registry ID:: 110044857517	N/A
2917 HEIN AVE. 2917 HEIN AVE. SALINA, KS	KS SPILLS Database: SPILLS, Date of Government Version: 04/05/2019	N/A

EXECUTIVE SUMMARY

Status: Closed

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing

Federal RCRA CORRACTS facilities list

CORRACTS ---------- Corrective Action Report

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal RCRA generators list

RCRA-LQG ---------- RCRA - Large Quantity Generators

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROL ---------- Sites with Institutional Controls

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State and tribal landfill and/or solid waste disposal site lists

KS SWF/LF ---------- Directory of Sanitary Landfills, Solid Waste Transfer Stations and Collector in Kansas

KS CITY DUMPS ---------- City Dump Listing

State and tribal leaking storage tank lists

KS LAST ---------- Leaking Aboveground Storage Tanks
INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

FEMA UST ---------- Underground Storage Tank Listing
INDIAN UST ---------- Underground Storage Tanks on Indian Land

State and tribal institutional control / engineering control registries

KS INST CONTROL ---------- Institutional Controls Information

State and tribal voluntary cleanup sites

KS VCP ---------- Identified Sites List
INDIAN VCP ---------- Voluntary Cleanup Priority Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

INDIAN ODI ---------- Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations
ODI ---------- Open Dump Inventory
IHS OPEN DUMPS ---------- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

KS AOCONCERN ---------- Area of Concern
US HIST CDL ---------- Delisted National Clandestine Laboratory Register
KS CDL ---------- Clandestine Laboratory Data
US CDL ---------- National Clandestine Laboratory Register

Local Land Records

LIENS 2 ---------- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---------- Hazardous Materials Information Reporting System

Other Ascertainable Records

DOD ---------- Department of Defense Sites
SCRD DRYCLEANERS ---------- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---------- Financial Assurance Information
EPA WATCH LIST ---------- EPA WATCH LIST
2020 COR ACTION ---------- 2020 Corrective Action Program List
TSCA ---------- Toxic Substances Control Act
TRIS ---------- Toxic Chemical Release Inventory System

SSTS Section 7 Tracking Systems
ROD Records Of Decision
RAATS RCRA Administrative Action Tracking System
PADS PCB Activity Database System
FTTS FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS Material Licensing Tracking System
COAL ASH DOE Steam-Electric Plant Operation Data
COAL ASH EPA Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER PCB Transformer Registration Database
RADINFO Radiation Information Database
HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS Incident and Accident Data
CONSENT Superfund (CERCLA) Consent Decrees
INDIAN RESERV Indian Reservations
FUSRAP Formerly Utilized Sites Remedial Action Program
UMTRA Uranium Mill Tailings Sites
LEAD SMELTERS Lead Smelter Sites
US MINES Mines Master Index File
ABANDONED MINES Abandoned Mines
DOCKET HWC Hazardous Waste Compliance Docket Listing
FUELS PROGRAM EPA Fuels Program Registered Listing
KS COAL ASH Coal Ash Disposal Site Listing
KS DRYCLEANERS Registered Drycleaning Facilities
KS NPDES Wastewater Permit Listing
KS UIC Underground Injection Wells Database Listing

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP EDR Proprietary Manufactured Gas Plants
EDR Hist Cleaner EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

KS RGA HWS Recovered Government Archive State Hazardous Waste Facilities List
KS RGA LF Recovered Government Archive Solid Waste Facilities List
KS RGA LUST Recovered Government Archive Leaking Underground Storage Tank

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

EXECUTIVE SUMMARY

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS list

SEMS: SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

A review of the SEMS list, as provided by EDR, and dated 07/19/2019 has revealed that there are 2 SEMS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SCHILLING (EX) AIR F Site ID: 0703124 EPA Id: KS0000597922	***3237 ARNOLD AVE***	***SSW 1/8 - 1/4 (0.186 mi.)***	***U86***	***453***

Lower Elevation	Address	Direction / Distance	Map ID	Page
SUMMERS ROAD Site ID: 0703594 EPA Id: KSSFN0703594	INTERSECTION OF SUMM	0 - 1/8 (0.000 mi.)	E43	298

Federal RCRA generators list

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 03/25/2019 has revealed that there are 2 RCRA-SQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TONYS PIZZA SVC INC EPA ID:: KSD984973958	***3019 SCANLAN AVE***	***0 - 1/8 (0.000 mi.)***	***C12***	***182***
TISCHLEREI - FINE WO EPA ID:: KSD049995426	2656 SCANLAN AVE	NNE 0 - 1/8 (0.041 mi.)	M57	370

EXECUTIVE SUMMARY

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 03/25/2019 has revealed that there are 5 RCRA-CESQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SALINA WASTE SYSTEMS EPA ID:: KSD984996850	***1848 SUMMERS***	***0 - 1/8 (0.000 mi.)***	***G15***	***228***

Lower Elevation	Address	Direction / Distance	Map ID	Page
REGIONAL TRAINING SI EPA ID:: KS6210490060	***2750 SCANLAN***	***0 - 1/8 (0.000 mi.)***	***D11***	***177***
PAUL SCHWAN TECH CTR EPA ID:: KSR000012054	***3123 CENTENNIAL***	***SE 0 - 1/8 (0.055 mi.)***	***O63***	***397***
SALINA AREA TECHNICA EPA ID:: KSD120780424	2562 CENTENNIAL RD	N 1/8 - 1/4 (0.242 mi.)	V89	463
LOVE BOX CO INC EPA ID:: KSD984988501	***3330 CENTENNIAL***	***SSE 1/8 - 1/4 (0.248 mi.)***	***92***	***480***

State- and tribal - equivalent CERCLIS

KS SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Health & Environment's list: Summary of Bureau of Environmental Remediation Sites in Kansas.

A review of the KS SHWS list, as provided by EDR, and dated 04/08/2019 has revealed that there are 22 KS SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SALINA AIRPORT AUTHO Facility Status: Resolved Project code: C508573089 Activity Status: C	***2734 ARNOLD COURT BU***	***0 - 1/8 (0.000 mi.)***	***B23***	***243***
SALINA AIRPORT AUTHO Facility Status: Resolved Project code: C508573090 Activity Status: C	***2934 ARNOLD AVENUE B***	***0 - 1/8 (0.000 mi.)***	***I35***	***282***
SCHILLING AFB (PAREN Facility Status: Active Project code: C508503013 Activity Status: C		NNW 0 - 1/8 (0.038 mi.)	L53	328
SALINA AIRPORT REDEV	2720 ARNOLD COURT	NNW 0 - 1/8 (0.042 mi.)	L62	393

Facility Status: Resolved
Project code: C508572093
Activity Status: C

SMOKY HILL WEAPONS R — SSW 1/8 - 1/4 (0.186 mi.) — U85 — 439
Facility Status: Active
Project code: C508500068
Activity Status: C

SALINA AIRPORT AUTHO — ***NW OF INTERSECTION S*** — ***S 1/4 - 1/2 (0.413 mi.)*** — ***97*** — ***496***
Facility Status: Resolved
Project code: C508573215
Activity Status: C

SCHILLING AFB OU3 — W 1/2 - 1 (0.667 mi.) — 103 — 532
Facility Status: Active
Project code: C508572186
Activity Status: C

SALINA AIRPORT AUTHO — ***VORTEX AVE & SCANLAN*** — ***S 1/2 - 1 (0.722 mi.)*** — ***105*** — ***542***
Facility Status: Resolved
Project code: C508572816
Activity Status: C

SALINA AIRPORT AUTHO — ***3600 AIRPORT ROAD BU*** — ***SW 1/2 - 1 (0.844 mi.)*** — ***106*** — ***546***
Facility Status: Resolved
Project code: C508573087
Activity Status: C

SALINA AIRPORT AUTHO — ***SCANLAN RD. AND WATE*** — ***S 1/2 - 1 (0.858 mi.)*** — ***X107*** — ***548***
Facility Status: Resolved
Project code: C508572649
Activity Status: C

SALINA AIRPORT AUTHO — ***SCANLAN RD. AND WATE*** — ***S 1/2 - 1 (0.858 mi.)*** — ***X108*** — ***551***
Facility Status: Resolved
Project code: C508572650
Activity Status: C

Lower Elevation	Address	Direction / Distance	Map ID	Page
SALINA CITY LANDFILL Facility Status: Transferred out of the bureau Project code: C508500036 Activity Status: C	RT 3 & BURMA RD.	0 - 1/8 (0.000 mi.)	21	236
SCHILLING AFB OU2 Facility Status: Active Project code: C508572185 Activity Status: C		0 - 1/8 (0.000 mi.)	F28	250
SUMMERS ROAD Facility Status: Active Project code: C508570765 Activity Status: C		0 - 1/8 (0.000 mi.)	E46	303
SALINA AIRPORT AUTHO Facility Status: Resolved Project code: C508572817 Activity Status: C	***BERSCHEL AVE & SCANL***	***NNE 1/8 - 1/4 (0.151 mi.)***	***77***	***422***
SCHILLING DEF GUIDED	***CORNER OF CENTENNIAL***	***NNE 1/8 - 1/4 (0.180 mi.)***	***T82***	***435***

Facility Status: Resolved Project code: C508571181 Activity Status: C				
SCHILLING AFB AF FAC Facility Status: Resolved Project code: C508571180 Activity Status: C	NA	NW 1/8 - 1/4 (0.203 mi.)	88	461
FORMER BEECH - SALIN Facility Status: Active Project code: C508572964 Activity Status: C	2562 CENTENNIAL ROAD	N 1/8 - 1/4 (0.242 mi.)	V90	475
SCHILLING FAMILY HOU Facility Status: Resolved Project code: C508571291 Activity Status: C	***SCHILLING ROAD***	***E 1/4 - 1/2 (0.351 mi.)***	***94***	***487***
SALINA AIRPORT AUTHO Facility Status: Resolved Project code: C508573216 Activity Status: C	2461 CENTENNIAL RD	NNE 1/4 - 1/2 (0.418 mi.)	W99	509
KSU-SALINA REDEVELOP Facility Status: Resolved Project code: C508572088 Activity Status: C	***2310 CENTENNIAL ROAD***	***N 1/2 - 1 (0.625 mi.)***	***102***	***523***
SCHILLING AFB OU1 Facility Status: Active Project code: C508572184 Activity Status: C		N 1/2 - 1 (0.712 mi.)	104	535

State and tribal leaking storage tank lists

KS LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Kansas Department of Environmental Protection's LUST Incident Report.

A review of the KS LUST list, as provided by EDR, and dated 04/01/2019 has revealed that there are 18 KS LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BLUE BEACON INTERNAT Facility Id: 27155 Facility Status: Closed	2770 ARNOLD	0 - 1/8 (0.000 mi.)	H27	249
FLOWER AVIATION Facility Id: 27195 Facility Status: Closed Facility Status: Active	***SALINA AIRPORT***	***NNW 0 - 1/8 (0.029 mi.)***	***B52***	***315***
SALINA AIRPORT AUTHO Facility Id: 80344 Facility Status: Closed	3119-B ARNOLD AVE	SSW 0 - 1/8 (0.041 mi.)	N60	389
PONY EXPRESS COURIER	3199 ARNOLD	SSW 0 - 1/8 (0.107 mi.)	P66	406

Facility Id: 27569 Facility Status: Closed				
KHP TROOP C HEADQUAR Facility Id: 29632 Facility Status: Closed	***3213 ARNOLD AVE***	***SSW 0 - 1/8 (0.118 mi.)***	***P71***	***412***
FSLN RCAG Facility Id: 25322 Facility Status: Closed	***SALINA MUNICIPAL AIR***	***W 1/4 - 1/2 (0.358 mi.)***	***95***	***489***

Lower Elevation	Address	Direction / Distance	Map ID	Page
SFC GLOBAL SUPPLY CH Facility Id: 23129 Facility Status: Closed	***3019 SCANLAN AVE.***	***0 - 1/8 (0.000 mi.)***	***C10***	***46***
SAA Facility Id: 03030 Facility Status: Closed	***2846 CENTENNIAL RD.***	***0 - 1/8 (0.000 mi.)***	***E13***	***220***
AFK SOC Facility Id: 04652 Facility Status: Monitor	***1605 W. SCHILLING RO***	***0 - 1/8 (0.000 mi.)***	***F14***	***224***
NICKELL BARRACKS TRA Facility Id: 27460 Facility Status: Closed	***1844 JUMPER***	***0 - 1/8 (0.000 mi.)***	***31***	***260***
HAWKER BEECHCRAFT - Facility Id: 26086 Facility Id: 81340 Facility Status: Closed	***2656 SCANLAN AVENUE***	***NNE 0 - 1/8 (0.041 mi.)***	***M55***	***357***
BEECH SALINA AIRPORT Facility Id: 81340 Facility Status: Closed	***SALINA AIRPORT***	***NNE 0 - 1/8 (0.041 mi.)***	***M56***	***365***
SCHWAN - SALINA DIST Facility Id: 80345 Facility Id: 81362 Facility Status: Closed	***3140 CENTENNIAL ROAD***	***SE 0 - 1/8 (0.062 mi.)***	***O65***	***403***
STUDENT ACTIVITY FUN Facility Id: 09121 Facility Status: Closed	***2562 SCANLAN AVE***	***N 1/8 - 1/4 (0.159 mi.)***	***S79***	***429***
FAA, SALINA Facility Id: 25323 Facility Status: Closed	SALINA VORTAC	NW 1/8 - 1/4 (0.242 mi.)	91	479
ADM MILLING CO Facility Id: 27527 Facility Status: Monitor	***2806 HEIN MUNCIPAL A***	***N 1/4 - 1/2 (0.304 mi.)***	***93***	***482***
SMOKY HILL INC Facility Id: 04845 Facility Status: Closed	***1615 W MAGNOLIA***	***NNE 1/4 - 1/2 (0.382 mi.)***	***96***	***492***
KSU-SALINA Facility Id: 00134 Facility Status: Closed	2409 SCANLAN AVE	N 1/4 - 1/2 (0.462 mi.)	100	519

State and tribal registered storage tank lists

KS UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Health & Environment's UST (Report) Listing Including Names.

A review of the KS UST list, as provided by EDR, and dated 04/01/2019 has revealed that there are 24 KS UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SAA, PUMPHOUSE BLDG Facility Id: 27196 Tank Status: Current In Use Tank Status: Temporarily Out Of Use	***SALINA AIRPORT***	***0 - 1/8 (0.000 mi.)***	***I32***	***266***
SMOKY HILL ANG RANGE Facility Id: 28835 Tank Status: Permanently Out Of Use	OLD OPS, 184 CES/DE	WSW 0 - 1/8 (0.001 mi.)	K47	309
SMOKY HILL ANG RANGE Facility Id: 28840 Tank Status: Permanently Out Of Use	BLDG 6010, 184 CES/D	WSW 0 - 1/8 (0.001 mi.)	K48	310
SMOKY HILL ANG RANGE Facility Id: 28839 Tank Status: Permanently Out Of Use	BLDG 6003, 184 CES/D	WSW 0 - 1/8 (0.001 mi.)	K49	311
SMOKY HILL ANG RANGE Facility Id: 28837 Tank Status: Permanently Out Of Use	BLDG 4001, 184 CES/D	WSW 0 - 1/8 (0.001 mi.)	K50	312
SMOKY HILL ANG RANGE Facility Id: 28838 Tank Status: Permanently Out Of Use	BLDG 6001, 184 CES/D	WSW 0 - 1/8 (0.001 mi.)	K51	313
FLOWER AVIATION Facility Id: 27195 Tank Status: Permanently Out Of Use	***SALINA AIRPORT***	***NNW 0 - 1/8 (0.029 mi.)***	***B52***	***315***
SAA, BLDG #105 Facility Id: 27197 Tank Status: Permanently Out Of Use	SALINA AIRPORT	SSW 0 - 1/8 (0.040 mi.)	54	353
PONY EXPRESS COURIER Facility Id: 27569 Tank Status: Permanently Out Of Use	3119 ARNOLD	SSW 0 - 1/8 (0.041 mi.)	N58	387
KHP TROOP C HEADQUAR Facility Id: 29632 Tank Status: Permanently Out Of Use	***3213 ARNOLD AVE***	***SSW 0 - 1/8 (0.118 mi.)***	***P71***	***412***
SALINA AIRCRAFT SERV Facility Id: 29734 Tank Status: Current In Use	***3148 ARNOLD***	***SSW 1/8 - 1/4 (0.133 mi.)***	***P72***	***414***
LEASE & RENTAL INC-A Facility Id: 19786 Tank Status: Permanently Out Of Use	3230 ARNOLD RD	SSW 1/8 - 1/4 (0.133 mi.)	P73	415
BLUE BEACON INTERNAT Facility Id: 29441 Tank Status: Current In Use	***3140 ARNOLD***	***SSW 1/8 - 1/4 (0.133 mi.)***	***P75***	***418***
MEMORIAL HALL		SSW 1/8 - 1/4 (0.186 mi.)	U83	437

Facility Id: 09066
Tank Status: Permanently Out Of Use

SALINA RAILYARD Facility Id: 25298 Tank Status: Permanently Out Of Use		SSW 1/8 - 1/4 (0.186 mi.)	U84	438

Lower Elevation	Address	Direction / Distance	Map ID	Page
TONYS PIZZA SVC INC Facility Id: 23129 Tank Status: Permanently Out Of Use	***3019 SCANLAN AVE***	***0 - 1/8 (0.000 mi.)***	***C12***	***182***
SAA Facility Id: 03030 Tank Status: Permanently Out Of Use	***2846 CENTENNIAL RD.***	***0 - 1/8 (0.000 mi.)***	***E13***	***220***
AFK SOC Facility Id: 04652 Tank Status: Permanently Out Of Use	***1605 W. SCHILLING RO***	***0 - 1/8 (0.000 mi.)***	***F14***	***224***
NICKELL BARRACKS TRA Facility Id: 27460 Tank Status: Permanently Out Of Use	***1844 JUMPER***	***0 - 1/8 (0.000 mi.)***	***31***	***260***
NICKELL BARRACKS TRA Facility Id: 29629 Tank Status: Permanently Out Of Use	RR #1, SMOKY HILL WE	0 - 1/8 (0.000 mi.)	44	299
HAWKER BEECHCRAFT - Facility Id: 26086 Tank Status: Permanently Out Of Use	***2656 SCANLAN AVENUE***	***NNE 0 - 1/8 (0.041 mi.)***	***M55***	***357***
SCHWAN - SALINA DIST Facility Id: 30352 Tank Status: Current In Use	***3140 CENTENNIAL ROAD***	***SE 0 - 1/8 (0.062 mi.)***	***O65***	***403***
STUDENT ACTIVITY FUN Facility Id: 20428 Tank Status: Permanently Out Of Use	***2562 SCANLAN AVE***	***N 1/8 - 1/4 (0.159 mi.)***	***S79***	***429***
USD #305 Facility Id: 09121 Tank Status: Permanently Out Of Use	2562 SCANLON AVENUE	N 1/8 - 1/4 (0.159 mi.)	S80	432

KS AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Health & Environment's AST (Report) Listing Including Names.

A review of the KS AST list, as provided by EDR, and dated 04/01/2019 has revealed that there are 7 KS AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
KOSS CONSTRUCTION CO Facility Id: 40076 Tank Status: Permanently Out Of Use	2782A ARNOLD RD	0 - 1/8 (0.000 mi.)	H20	235
SLN ATCT Facility Id: 44040 Tank Status: Current In Use	2000 KNEUBUHL COURT	0 - 1/8 (0.000 mi.)	H24	245
SAA, PUMPHOUSE BLDG	***SALINA AIRPORT***	***0 - 1/8 (0.000 mi.)***	***I32***	***266***

Facility Id: 27196 Tank Status: Current In Use				
SALINA WASTE SYSTEMS Facility Id: 44308 Tank Status: Current In Use	1848 SUMMERS RD	0 - 1/8 (0.000 mi.)	G41	294
SALINA AIRPORT CELL Facility Id: 44585 Tank Status: Current In Use	3119 ARNOLD AVE.	SSW 0 - 1/8 (0.041 mi.)	N59	388
BLUE BEACON INTERNAT Facility Id: 29441 Tank Status: Current In Use	***3140 ARNOLD***	***SSW 1/8 - 1/4 (0.133 mi.)***	***P75***	***418***

Lower Elevation	Address	Direction / Distance	Map ID	Page
BUILDERS CHOICE CONC Facility Id: 45092 Tank Status: Permanently Out Of Use Tank Status: Current In Use	2601 CENTENNIAL RD	NNE 1/8 - 1/4 (0.152 mi.)	R78	428

State and tribal Brownfields sites

Sites included in the Identified Sites List that are identified as Brownfields sites.

A review of the KS BROWNFIELDS list, as provided by EDR, and dated 04/08/2019 has revealed that there are 4 KS BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SALINA AIRPORT AUTHO Site Status: R Site ID: 3040	***2734 ARNOLD COURT BU***	***0 - 1/8 (0.000 mi.)***	***B23***	***243***
SALINA AIRPORT AUTHO Site Status: R Site ID: 3041	***2934 ARNOLD AVENUE B***	***0 - 1/8 (0.000 mi.)***	***I35***	***282***
SALINA AIRPORT AUTHO Site Status: R Site ID: 3166	***NW OF INTERSECTION S***	***S 1/4 - 1/2 (0.413 mi.)***	***97***	***496***

Lower Elevation	Address	Direction / Distance	Map ID	Page
SALINA AIRPORT AUTHO Site Status: R Site ID: 2768	***BERSCHEL AVE & SCANL***	***NNE 1/8 - 1/4 (0.151 mi.)***	***77***	***422***

EXECUTIVE SUMMARY

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 06/03/2019 has revealed that there are 10 US BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SALINA AIRPORT AUTHO ACRES property ID: 169744	2734 ARNOLD COURT	0 - 1/8 (0.000 mi.)	B9	43
SALINA AIRPORT AUTHO ACRES property ID: 169745	2934 ARNOLD AVENUE	0 - 1/8 (0.000 mi.)	I36	284
SALINA AIRPORT REDEV ACRES property ID: 32921	***2720 ARNOLD AVE***	***NNW 0 - 1/8 (0.042 mi.)***	***L61***	***390***
SALINA AIRPORT AUTHO ACRES property ID: 187381	***SW INTERSECTION OF W***	***S 1/4 - 1/2 (0.474 mi.)***	***101***	***520***

Lower Elevation	Address	Direction / Distance	Map ID	Page
SALINA AIRPORT AUTHO ACRES property ID: 137223	***BERSCHEL AVE***	***0 - 1/8 (0.000 mi.)***	***22***	***237***
KSU - SALINA REDEVEL ACRES property ID: 32864	***1732 SUMMERS ROAD***	***0 - 1/8 (0.000 mi.)***	***J38***	***288***
KSU - SALINA REDEVEL ACRES property ID: 32862	***1732 SUMMERS ROADS***	***0 - 1/8 (0.000 mi.)***	***J39***	***291***
KSU - SALINA REDEVEL ACRES property ID: 32861	***1732 SUMMERS ROAD***	***0 - 1/8 (0.000 mi.)***	***J42***	***295***
KSU - SALINA REDEVEL ACRES property ID: 32863	***1732 SUMMERS ROAD***	***0 - 1/8 (0.000 mi.)***	***J45***	***301***
SALINA AIRPORT AUTHO ACRES property ID: 187382	***2461 CENTENNIAL RD***	***NNE 1/4 - 1/2 (0.418 mi.)***	***W98***	***499***

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/25/2019 has revealed that there are 14 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
OVATION CABINETRY IN	***2804 ARNOLD***	***0 - 1/8 (0.000 mi.)***	***19***	***233***

EPA ID:: KSR000001792				
MID KANSAS REBUILDER EPA ID:: KSD985001403	***2775 ARNOLD STE G***	***0 - 1/8 (0.000 mi.)***	***H25***	***246***
FEDERAL EXPRESS EPA ID:: KSD187297064	***2770 ARNOLD***	***0 - 1/8 (0.000 mi.)***	***H26***	***248***
REGIONAL TRAINING SI EPA ID:: KSD984971200	***2931 ARNOLD (B)***	***0 - 1/8 (0.000 mi.)***	***I33***	***278***
DEAN MARKLEY ELECTRO EPA ID:: KSD981119704	***2931 ARNOLD (A)***	***0 - 1/8 (0.000 mi.)***	***I34***	***280***
PORTAPORT EPA ID:: KSD033560475	***2711 ARNOLD***	***0 - 1/8 (0.000 mi.)***	***B37***	***287***
ADM MILLING EPA ID:: KSR000013862	***3140 ARNOLD***	***SSW 1/8 - 1/4 (0.133 mi.)***	***P74***	***416***
SCHILLING (EX) AIR F EPA ID:: KS0000597922	***3237 ARNOLD AVE***	***SSW 1/8 - 1/4 (0.186 mi.)***	***U86***	***453***

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
SALINA AIRPORT AUTH EPA ID:: KSP000000945	2846 CENTENNIAL RD	0 - 1/8 (0.000 mi.)	E17	231
DIVERSIFIED NEON EPA ID:: KSD984997502	***3037 S CENTENNIAL***	***0 - 1/8 (0.000 mi.)***	***F30***	***258***
NICKELL BARRACKS TRA EPA ID:: KS0000225151	***1844 JUMPER***	***0 - 1/8 (0.000 mi.)***	***31***	***260***
KANSAS VOC REHAB CTR EPA ID:: KSP000000777	3140 CENTENNIAL	SE 0 - 1/8 (0.062 mi.)	O64	402
DEAL PET CO EPA ID:: KSD981117245	***2624 CENTENNIAL***	***NNE 1/8 - 1/4 (0.150 mi.)***	***R76***	***421***
EL DORADO INDUSTRIES EPA ID:: KSD063570386	***614 LOWE***	***N 1/8 - 1/4 (0.179 mi.)***	***81***	***433***

FUDS: The Listing includes locations of Formerly Used Defense Sites Properties where the US Army Corps Of Engineers is actively working or will take necessary cleanup actions.

A review of the FUDS list, as provided by EDR, and dated 05/15/2019 has revealed that there are 4 FUDS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
SCHILLING FAM HOUSG		0 - 1/8 (0.000 mi.)	D18	233
SCHILLING AFB		W 0 - 1/8 (0.112 mi.)	Q70	409

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
SCHILLING AFB AF FAC		NW 0 - 1/8 (0.109 mi.)	67	408
SCHILLING DEF-GM FLD		NNE 1/8 - 1/4 (0.190 mi.)	T87	461

UXO: A listing of unexploded ordnance site locations

A review of the UXO list, as provided by EDR, and dated 12/31/2017 has revealed that there are 2 UXO sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GAS INSTRUCTION AREA		W 0 - 1/8 (0.112 mi.)	Q68	408
CONVENTIONAL TRAININ		W 0 - 1/8 (0.112 mi.)	Q69	408

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 3 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LANDES OIL CO INC	2948 ARNOLD	0 - 1/8 (0.000 mi.)	I29	258


Lower Elevation	Address	Direction / Distance	Map ID	Page
S & K AUTOMOTIVE	2846 CENTENNIAL RD	0 - 1/8 (0.000 mi.)	E16	231
MR GS OF KANSAS	1605 W SCHILLING RD	0 - 1/8 (0.000 mi.)	F40	294

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 5 records.

Site Name	Database(s)
2634 MIDLAND ROAD	KS SHWS
SAA HYDRANT PIT 2-F	KS LUST
SALINA AIRPORT AUTHORITY V BTA	FINDS
SALINA AIRPORT AUTHORITY V BTA	KS RGA HWS
SALINA AIRPORT AUTHORITY IV BTA	KS RGA HWS

OVERVIEW MAP - 5776851.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

0 1/4 1/2 1 Miles

Indian Reservations BIA

Power transmission lines

100-year flood zone

500-year flood zone

National Wetland Inventory

State Wetlands


Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Salina AASF	CLIENT:	AECOM
ADDRESS:	2917 Hein Avenue Salina KS 67401	CONTACT:	Hans Sund
		INQUIRY #:	5776851.2s
LAT/LONG:	38.78504 / 97.63747	DATE:	September 04, 2019 5:08 pm

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 5776851.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

Sensitive Receptors

National Priority List Sites

Dept. Defense Sites

0 1/8 1/4 1/2 Miles

Indian Reservations BIA

100-year flood zone

500-year flood zone

National Wetland Inventory

State Wetlands

Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Salina AASF ADDRESS: 2917 Hein Avenue Salina KS 67401 LAT/LONG: 38.78504 / 97.63747	CLIENT: AECOM CONTACT: Hans Sund INQUIRY #: 5776851.2s DATE: September 04, 2019 5:13 pm

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		1	1	0	NR	NR	2
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500	1	0	0	0	NR	NR	1
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	0	NR	0
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		0	0	NR	NR	NR	0
RCRA-SQG	0.250		2	0	NR	NR	NR	2
RCRA-CESQG	0.250	1	3	2	NR	NR	NR	6
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
KS SHWS	1.000		7	5	3	7	NR	22
State and tribal landfill and/or solid waste disposal site lists								
KS SWF/LF	0.500		0	0	0	NR	NR	0
KS CITY DUMPS	0.500		0	0	0	NR	NR	0
State and tribal leaking storage tank lists								
KS LAST	0.500		0	0	0	NR	NR	0
KS LUST	0.500		12	2	4	NR	NR	18
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0
KS UST	0.250		17	7	NR	NR	NR	24
KS AST	0.250		5	2	NR	NR	NR	7
INDIAN UST	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
KS INST CONTROL	0.500		0	0	0	NR	NR	0
State and tribal voluntary cleanup sites								
KS VCP	0.500		0	0	0	NR	NR	0
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
KS BROWNFIELDS	0.500		2	1	1	NR	NR	4
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		8	0	2	NR	NR	10
Local Lists of Landfill / Solid Waste Disposal Sites								
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
KS AOCONCERN	1.000		0	0	0	0	NR	0
US HIST CDL	TP		NR	NR	NR	NR	NR	0
KS CDL	TP		NR	NR	NR	NR	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
Local Land Records								
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
KS SPILLS	TP	1	NR	NR	NR	NR	NR	1
Other Ascertainable Records								
RCRA NonGen / NLR	0.250	1	10	4	NR	NR	NR	15
FUDS	1.000		3	1	0	0	NR	4
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP	4	NR	NR	NR	NR	NR	4
UXO	1.000		2	0	0	0	NR	2
ECHO	TP	3	NR	NR	NR	NR	NR	3
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
KS AIRS	TP		NR	NR	NR	NR	NR	0
KS COAL ASH	0.500		0	0	0	NR	NR	0
KS DRYCLEANERS	0.250		0	0	NR	NR	NR	0
KS Financial Assurance	TP		NR	NR	NR	NR	NR	0
WI MANIFEST	0.250	1	0	0	NR	NR	NR	1
KS NPDES	TP		NR	NR	NR	NR	NR	0
KS TIER 2	TP	2	NR	NR	NR	NR	NR	2
KS UIC	TP		NR	NR	NR	NR	NR	0

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		3	NR	NR	NR	NR	3
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

KS RGA HWS	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
KS RGA LF	TP		NR	NR	NR	NR	NR	0
KS RGA LUST	TP		NR	NR	NR	NR	NR	0
- Totals --		14	75	25	10	7	0	131

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1
Target
Property

KS ARMY NATL GUARD-SALINA AASF #2
2917 HELM STREET
SALINA, KS 67401

KS TIER 2 **S122358110**
N/A

Site 1 of 8 in cluster A

Actual:
1256 ft.

TIER 2:

Facility Id:	372686
Facility Phone:	785-822-3297
FID Num:	SA00443
PID Num:	KS02467
NAICS:	48819
Report Year:	2012
New Facility:	Not reported
Nearest Cross Street:	Not reported
SIC Code:	4581
Section Code:	312
Emergency Name1:	RICHARD TUSZKIEWICZ
Emergency Title1:	MATERIALS EXAMINER
Emergency Phone1:	785-822-3450
Emergency 24phone1:	785-822-3471
Emergency Name2:	SAM MRYYAN
Emergency Title2:	ENV PROGRAM MGR
Emergency Phone2:	785-274-1154
Emergency 24phone2:	785-806-2541
Submitter:	Not reported
Created:	12/21/2011 3:41:27 PM
Updated:	12/21/2011 3:43:08 PM
Rep Name:	jay schalansky
Rep Title:	ESII
Zip Field:	Not reported
Facility Latitude:	Not reported
Facility Longitude:	Not reported
Emergency Email1:	Not reported
Emergency Email2:	Not reported
Tier2 Contact Name:	Not reported
Tier2 Title:	Not reported
Tier2 Phone:	Not reported
Tier2 Phone24:	Not reported
Tier2 EMail:	Not reported
Annual Revision:	Not reported
Max Occupants:	Not reported
Manned/Unmanned:	Not reported
Section:	Not reported
Township:	Not reported
Range0:	Not reported
Trifids:	Not reported
RMP Facid:	Not reported
Subject 302:	Not reported
Subject 112:	Not reported

Facility Id:	372686
Facility Phone:	785-822-3297
FID Num:	SA00443
PID Num:	KS02467
NAICS:	48819
Report Year:	2011
New Facility:	Not reported
Nearest Cross Street:	Not reported

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358110**

SIC Code:	4581
Section Code:	312
Emergency Name1:	RICHARD TUSZKIEWICZ
Emergency Title1:	MATERIALS EXAMINER
Emergency Phone1:	785-822-3450
Emergency 24phone1:	785-822-3471
Emergency Name2:	SAM MRYYAN
Emergency Title2:	ENV PROGRAM MGR
Emergency Phone2:	785-274-1154
Emergency 24phone2:	785-806-2541
Submitter:	Not reported
Created:	12/21/2011 3:41:27 PM
Updated:	12/21/2011 3:43:08 PM
Rep Name:	jay schalansky
Rep Title:	ESII
Zip Field:	Not reported
Facility Latitude:	Not reported
Facility Longitude:	Not reported
Emergency Email1:	Not reported
Emergency Email2:	Not reported
Tier2 Contact Name:	Not reported
Tier2 Title:	Not reported
Tier2 Phone:	Not reported
Tier2 Phone24:	Not reported
Tier2 EMail:	Not reported
Annual Revision:	Not reported
Max Occupants:	Not reported
Manned/Unmanned:	Not reported
Section:	Not reported
Township:	Not reported
Range0:	Not reported
Trifids:	Not reported
RMP Facid:	Not reported
Subject 302:	Not reported
Subject 112:	Not reported

Facility Id:	372686
Facility Phone:	785-822-3297
FID Num:	SA00443
PID Num:	KS02467
NAICS:	48819
Report Year:	2014
New Facility:	Not reported
Nearest Cross Street:	Not reported
SIC Code:	4581
Section Code:	312
Emergency Name1:	RICHARD TUSZKIEWICZ
Emergency Title1:	MATERIALS EXAMINER
Emergency Phone1:	785-822-3450
Emergency 24phone1:	785-822-3471
Emergency Name2:	SAM MRYYAN
Emergency Title2:	ENV PROGRAM MGR
Emergency Phone2:	785-274-1154
Emergency 24phone2:	785-806-2541
Submitter:	Not reported
Created:	2011-12-21 15:41:27
Updated:	2014-02-20 11:02:49

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358110**

Rep Name:	Jay Schalansky
Rep Title:	Env Scientist
Zip Field:	Not reported
Facility Latitude:	38.7850610
Facility Longitude:	-97.6417200
Emergency Email1:	Not reported
Emergency Email2:	Not reported
Tier2 Contact Name:	Jay Schalansky
Tier2 Title:	ESII
Tier2 Phone:	7852741962
Tier2 Phone24:	785-806-2541
Tier2 EMail:	jay.p.schalansky.nfg@mail.mil
Annual Revision:	annual
Max Occupants:	Not reported
Manned/Unmanned:	Not reported
Section:	Not reported
Township:	Not reported
Range0:	Not reported
Trifids:	Not reported
RMP Facid:	Not reported
Subject 302:	Not reported
Subject 112:	Not reported

Chemical:

FID Num:	SA00443
Chemical Id:	888562
Chemical Name:	JP-8 AVIATION FUEL
CAS:	NONE
Trade Secret:	No
EHS:	Not reported
Solid:	Not reported
Liquid:	Yes
Gas:	Not reported
Pure:	Not reported
Mix:	Yes
Fire:	Yes
Pressure:	Not reported
Reactive:	Not reported
Delayed:	Not reported
Immediate:	Yes
Max Daily Amt:	33350
Avg Daily Amt:	26680
Days On Site:	365
Opt Report:	Not reported

Storage:

Fid Num:	SA00443
Chemical Name:	JP-8 AVIATION FUEL
Storage Id:	1243355
Container:	Other
Pressure:	Ambient pressure
Temperature:	Ambient temperature
Storage Location:	MOBILE FUEL TANKERS

Fid Num:	SA00443
Chemical Name:	JP-8 AVIATION FUEL
Storage Id:	1243355

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358110**

Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

FID Num: SA00443
Chemical Id: 888562
Chemical Name: JP-8 AVIATION FUEL
CAS: NONE
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 33350
Avg Daily Amt: 26680
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358110**

Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

FID Num: SA00443
Chemical Id: 888562
Chemical Name: JP-8 AVIATION FUEL
CAS: NONE
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 33350
Avg Daily Amt: 26680
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00443

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358110**

Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

FID Num: SA00443
Chemical Id: 923085
Chemical Name: F-24 AVIATION FUEL
CAS: 8008-20-6
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Yes
Immediate: Yes
Max Daily Amt: 46509

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358110**

Avg Daily Amt: 38757
Days On Site: 365
Opt Report: 1

Storage:
Fid Num: SA00443
Chemical Name: F-24 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: F-24 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: F-24 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

FID Num: SA00443
Chemical Id: 923085
Chemical Name: F-24 AVIATION FUEL
CAS: 8008-20-6
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Yes
Immediate: Yes
Max Daily Amt: 29714
Avg Daily Amt: 22608
Days On Site: 365
Opt Report: 1

Storage:
Fid Num: SA00443
Chemical Name: F-24 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358110**

Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: F-24 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: F-24 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

FID Num: SA00443
Chemical Id: 923085
Chemical Name: F-24 AVIATION FUEL
CAS: 8008-20-6
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Yes
Immediate: Yes
Max Daily Amt: 52500
Avg Daily Amt: 42000
Days On Site: 365
Opt Report: 1

Storage:
Fid Num: SA00443
Chemical Name: F-24 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: F-24 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358110**

Chemical Name: F-24 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

FID Num: SA00443
Chemical Id: 888562
Chemical Name: JP-8 AVIATION FUEL
CAS: NONE
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 33350
Avg Daily Amt: 26680
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358110**

Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

FID Num: SA00443
Chemical Id: 888562
Chemical Name: JP-8 AVIATION FUEL
CAS: NONE
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 33350
Avg Daily Amt: 26680
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358110**

Fid Num:	SA00443
Chemical Name:	JP-8 AVIATION FUEL
Storage Id:	1243355
Container:	Other
Pressure:	Ambient pressure
Temperature:	Ambient temperature
Storage Location:	MOBILE FUEL TANKERS

Fid Num:	SA00443
Chemical Name:	JP-8 AVIATION FUEL
Storage Id:	1243355
Container:	Tote Bin
Pressure:	A
Temperature:	A
Storage Location:	MOBILE FUEL TANKERS

A2 **AC HELICOPTERS** **SEMS-ARCHIVE** **1003876237**
Target **2917 HEIN ST** **RCRA NonGen / NLR** **KSD097705313**
Property **SALINA, KS 67401**

Site 2 of 8 in cluster A

Actual: 1256 ft.

SEMS Archive:

Site ID:	0700550
EPA ID:	KSD097705313
Cong District:	01
FIPS Code:	20169
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	07
Site ID:	0700550
EPA ID:	KSD097705313
Site Name:	AC HELICOPTERS
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1985-02-01 06:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	07
Site ID:	0700550
EPA ID:	KSD097705313
Site Name:	AC HELICOPTERS
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA

AC HELICOPTERS (Continued) **1003876237**

SEQ: 1
Start Date: Not reported
Finish Date: 1985-02-01 06:00:00
Qual: N
Current Action Lead: EPA Perf

Region: 07
Site ID: 0700550
EPA ID: KSD097705313
Site Name: AC HELICOPTERS
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 1980-08-01 04:00:00
Finish Date: 1980-08-01 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf

RCRA NonGen / NLR:
Date form received by agency: 08/20/1980
Facility name: A C HELICOPTERS
Facility address: 2917 HEIN (A)
SALINA, KS 67401
EPA ID: KSD097705313
Mailing address: PO BOX 366
SALINA, KS 67401
Contact: ALAN DEAN
Contact address: PO BOX 366
SALINA, KS 67401
Contact country: US
Contact telephone: 785-263-3198
Contact email: Not reported
EPA Region: 07
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: A C HELICOPTERS
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

AC HELICOPTERS (Continued) **1003876237**

Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Hazardous Waste Summary:

. Waste code:	P044
. Waste name:	DIMETHOATE (OR) PHOSPHORODITHIOIC ACID, O,O-DIMETHYL S-[2-(METHYLAMINO)-2-OXOETHYL] ESTER
. Waste code:	P071
. Waste name:	METHYL PARATHION (OR) PHOSPHOROTHIOIC ACID, O,O,-DIMETHYL O-(4-NITROPHENYL) ESTER
. Waste code:	P089
. Waste name:	PARATHION (OR) PHOSPHOROTHIOIC ACID, O,O-DIETHYL-O-(4-NITROPHENYL) ESTER
. Waste code:	U240
. Waste name:	2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D
Violation Status:	No violations found

A3 **KS ARMY NATL GUARD-SALINA AASF #2** **KS TIER 2** **S122358109**
Target **2917 HEIN AVENUE** **N/A**
Property **SALINA, KS 67401**

Site 3 of 8 in cluster A

Actual: **1256 ft.**

TIER 2:

Facility Id:	372686
Facility Phone:	785-646-3452
FID Num:	SA00443
PID Num:	KS02467
NAICS:	488190
Report Year:	2016
New Facility:	Not reported
Nearest Cross Street:	ARNOLD AVE
SIC Code:	4581
Section Code:	312
Emergency Name1:	SGT Christopher A. Shields
Emergency Title1:	Materials Examiner/Identifier
Emergency Phone1:	785-646-3452
Emergency 24phone1:	785-212-0692
Emergency Name2:	Sam Mryyan
Emergency Title2:	Env. Program Manager

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358109**

Emergency Phone2:	785-646-1154
Emergency 24phone2:	785-215-3756
Submitter:	Not reported
Created:	2011-12-21 15:41:27
Updated:	2017-02-09 17:31:23
Rep Name:	Denise L. Moravec
Rep Title:	Env Compliance/Regulatory Spec
Zip Field:	Not reported
Facility Latitude:	38.7850610
Facility Longitude:	-97.6417200
Emergency Email1:	christopher.a.shields8.mil@mail.mil
Emergency Email2:	mahmoud.a.mryyan.nfg@mail.mil
Tier2 Contact Name:	Denise L. Moravec
Tier2 Title:	Compliance Manager
Tier2 Phone:	785-646-1962
Tier2 Phone24:	785-221-6941
Tier2 EMail:	denise.l.moravec2.nfg@mail.mil
Annual Revision:	annual
Max Occupants:	27
Manned/Unmanned:	manned
Section:	34
Township:	14S
Range0:	3W
Trifids:	n/a
RMP Facid:	n/a
Subject 302:	N
Subject 112:	N

Facility Id:	372686
Facility Phone:	785-646-3452
FID Num:	SA00443
PID Num:	KS02467
NAICS:	488190
Report Year:	2017
New Facility:	Not reported
Nearest Cross Street:	ARNOLD AVE
SIC Code:	4581
Section Code:	312
Emergency Name1:	SGT Jacob E. Higgins
Emergency Title1:	Materials Handler
Emergency Phone1:	785-646-3452
Emergency 24phone1:	785-447-3095
Emergency Name2:	Sam Mryyan
Emergency Title2:	Env. Program Manager
Emergency Phone2:	785-646-1154
Emergency 24phone2:	785-215-3756
Submitter:	Not reported
Created:	2011-12-21 15:41:27
Updated:	2018-02-07 12:00:19
Rep Name:	Denise L. Moravec
Rep Title:	Env Compliance/Regulatory Spec
Zip Field:	Not reported
Facility Latitude:	38.7850610
Facility Longitude:	-97.6417200
Emergency Email1:	jacob.e.higgins2.mil@mail.mil
Emergency Email2:	mahmoud.a.mryyan.nfg@mail.mil
Tier2 Contact Name:	Denise L. Moravec

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358109**

Tier2 Title:	Compliance Manager
Tier2 Phone:	785-646-1962
Tier2 Phone24:	785-221-6941
Tier2 EMail:	denise.l.moravec2.nfg@mail.mil
Annual Revision:	annual
Max Occupants:	27
Manned/Unmanned:	manned
Section:	34
Township:	14S
Range0:	3W
Trifids:	n/a
RMP Facid:	n/a
Subject 302:	N
Subject 112:	N

Facility Id:	372686
Facility Phone:	785-822-3456
FID Num:	SA00443
PID Num:	KS02467
NAICS:	488190
Report Year:	2015
New Facility:	Not reported
Nearest Cross Street:	ARNOLD AVE
SIC Code:	4581
Section Code:	312
Emergency Name1:	SGT CHRISTOPHER SHIELDS
Emergency Title1:	MATLS EXAMINER/IDENTIFIER
Emergency Phone1:	785-822-3452
Emergency 24phone1:	785-212-0692
Emergency Name2:	SAM MRYYAN
Emergency Title2:	ENV PROGRAM MGR
Emergency Phone2:	785-646-1154
Emergency 24phone2:	785-215-3756
Submitter:	Not reported
Created:	2011-12-21 15:41:27
Updated:	2016-04-08 13:34:35
Rep Name:	Denise L. Moravec
Rep Title:	Env Compliance/Regulatory Spec
Zip Field:	Not reported
Facility Latitude:	38.7850610
Facility Longitude:	-97.6417200
Emergency Email1:	christopher.a.shields8.mil@mail.mil
Emergency Email2:	mahmoud.a.mryyan.nfg@mail.mil
Tier2 Contact Name:	DENISE L MORAVEC
Tier2 Title:	COMPLIANCE MGR
Tier2 Phone:	785-646-1962
Tier2 Phone24:	785-221-6941
Tier2 EMail:	denise.l.moravec2.nfg@mail.mil
Annual Revision:	annual
Max Occupants:	27
Manned/Unmanned:	manned
Section:	34
Township:	14S
Range0:	3W
Trifids:	n/a
RMP Facid:	n/a
Subject 302:	N

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358109**

Subject 112: N

Chemical:
FID Num: SA00443
Chemical Id: 888562
Chemical Name: JP-8 AVIATION FUEL
CAS: NONE
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 33350
Avg Daily Amt: 26680
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358109**

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

FID Num: SA00443
Chemical Id: 888562
Chemical Name: JP-8 AVIATION FUEL
CAS: NONE
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 33350
Avg Daily Amt: 26680
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358109**

Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

FID Num: SA00443
Chemical Id: 888562
Chemical Name: JP-8 AVIATION FUEL
CAS: NONE
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 33350
Avg Daily Amt: 26680
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358109**

Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

FID Num: SA00443
Chemical Id: 923085
Chemical Name: F-24 AVIATION FUEL
CAS: 8008-20-6
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Yes
Immediate: Yes
Max Daily Amt: 46509
Avg Daily Amt: 38757
Days On Site: 365
Opt Report: 1

Storage:
Fid Num: SA00443
Chemical Name: F-24 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: F-24 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358109**

Chemical Name: F-24 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

FID Num: SA00443
Chemical Id: 923085
Chemical Name: F-24 AVIATION FUEL
CAS: 8008-20-6
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Yes
Immediate: Yes
Max Daily Amt: 29714
Avg Daily Amt: 22608
Days On Site: 365
Opt Report: 1

Storage:
Fid Num: SA00443
Chemical Name: F-24 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: F-24 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: F-24 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

FID Num: SA00443
Chemical Id: 923085
Chemical Name: F-24 AVIATION FUEL

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358109**

CAS:	8008-20-6
Trade Secret:	No
EHS:	Not reported
Solid:	Not reported
Liquid:	Yes
Gas:	Not reported
Pure:	Not reported
Mix:	Yes
Fire:	Yes
Pressure:	Not reported
Reactive:	Not reported
Delayed:	Yes
Immediate:	Yes
Max Daily Amt:	52500
Avg Daily Amt:	42000
Days On Site:	365
Opt Report:	1

Storage:

Fid Num:	SA00443
Chemical Name:	F-24 AVIATION FUEL
Storage Id:	1243355
Container:	Tote Bin
Pressure:	A
Temperature:	A
Storage Location:	MOBILE FUEL TANKERS

Fid Num:	SA00443
Chemical Name:	F-24 AVIATION FUEL
Storage Id:	1243355
Container:	Tote Bin
Pressure:	A
Temperature:	A
Storage Location:	MOBILE FUEL TANKERS

Fid Num:	SA00443
Chemical Name:	F-24 AVIATION FUEL
Storage Id:	1243355
Container:	Tote Bin
Pressure:	A
Temperature:	A
Storage Location:	MOBILE FUEL TANKERS

FID Num:	SA00443
Chemical Id:	888562
Chemical Name:	JP-8 AVIATION FUEL
CAS:	NONE
Trade Secret:	No
EHS:	Not reported
Solid:	Not reported
Liquid:	Yes
Gas:	Not reported
Pure:	Not reported
Mix:	Yes
Fire:	Yes
Pressure:	Not reported
Reactive:	Not reported

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358109**

Delayed: Not reported
Immediate: Yes
Max Daily Amt: 33350
Avg Daily Amt: 26680
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

FID Num: SA00443
Chemical Id: 888562
Chemical Name: JP-8 AVIATION FUEL
CAS: NONE
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported

KS ARMY NATL GUARD-SALINA AASF #2 (Continued) **S122358109**

Pure: Not reported
Mix: Yes
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 33350
Avg Daily Amt: 26680
Days On Site: 365
Opt Report: Not reported

Storage:

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: MOBILE FUEL TANKERS

Fid Num: SA00443
Chemical Name: JP-8 AVIATION FUEL
Storage Id: 1243355
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: MOBILE FUEL TANKERS

A4 **ARMY AVIATION SUPPORT FACILITY 2** **FINDS** **1017369878**
Target **2917 HEIN AVE.** **ECHO** **N/A**
Property **SALINA, KS 67401**

Site 4 of 8 in cluster A

Actual: **1256 ft.**

FINDS:

Registry ID: 110060362664

Environmental Interest/Information System
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1017369878
Registry ID: 110060362664
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110060362664

A5 **KANSAS ARNG/AASF 2** **RCRA-CESQG** **1000377651**
Target **2917 HEIN (B)** **FINDS** **KS3570090024**
Property **SALINA, KS 67401** **ECHO**
WI MANIFEST

Site 5 of 8 in cluster A

Actual: **1256 ft.**

RCRA-CESQG:
Date form received by agency: 01/29/2018
Facility name: KANSAS ARNG/AASF 2
Facility address: 2917 HEIN (B)
SALINA, KS 67401
EPA ID: KS3570090024
Mailing address: 2722 SW TOPEKA BLVD
TOPEKA, KS 66611
Contact: KEVIN DURKES
Contact address: AGKS DPW-EMB 2722 SW TOPEKA BLVD
TOPEKA, KS 66611
Contact country: US
Contact telephone: 785-646-1152
Contact email: KEVIN.L.DURKES.NFG@MAIL.MIL
EPA Region: 07
Land type: State
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less

KANSAS ARNG/AASF 2 (Continued) **1000377651**

of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	KANSAS ARMY NATIONAL GUARD
Owner/operator address:	2722 SW TOPEKA BLVD TOPEKA, KS 66611
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	02/03/2003
Owner/Op end date:	Not reported

Owner/operator name:	SALINA AIRPORT AUTHORITY
Owner/operator address:	2722 SW TOPEKA BLVD TOPEKA, KS 66611
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	02/03/2003
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/26/2017
Site name:	KANSAS ARNG/AASF 2
Classification:	Conditionally Exempt Small Quantity Generator

KANSAS ARNG/AASF 2 (Continued) **1000377651**

Date form received by agency: 03/03/2016
Site name: KANSAS ARNG/AASF 2
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/23/2015
Site name: KANSAS ARNG/AASF 2
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/21/2014
Site name: KANSAS ARNG/AASF 2
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 06/26/2013
Site name: KANSAS ARNG/AASF 2
Classification: Small Quantity Generator

Date form received by agency: 03/27/2013
Site name: KANSAS ARNG/AASF 2
Classification: Small Quantity Generator

Date form received by agency: 09/14/2012
Site name: KANSAS ARNG/AASF 2
Classification: Small Quantity Generator

Date form received by agency: 02/22/2012
Site name: KANSAS ARNG/AASF 2
Classification: Small Quantity Generator

Date form received by agency: 02/28/2011
Site name: KANSAS ARNG/AASF 2
Classification: Small Quantity Generator

Date form received by agency: 02/03/2010
Site name: KANSAS ARNG/AASF 2
Classification: Small Quantity Generator

Date form received by agency: 03/16/2009
Site name: KANSAS ARNG/AASF 2
Classification: Small Quantity Generator

Date form received by agency: 03/24/2008
Site name: KANSAS ARNG/AASF 2
Classification: Small Quantity Generator

Date form received by agency: 03/23/2007
Site name: KANSAS ARNG/AASF 2
Classification: Small Quantity Generator

Date form received by agency: 03/29/2006
Site name: KANSAS ARNG/AASF 2
Classification: Small Quantity Generator

Date form received by agency: 02/16/2005
Site name: KANSAS ARNG/AASF 2
Classification: Small Quantity Generator

Date form received by agency: 02/11/2004

KANSAS ARNG/AASF 2 (Continued) **1000377651**

Site name: KANSAS ARNG/ARMY AVN SPT FAC 2
Classification: Small Quantity Generator

Date form received by agency: 02/03/2003
Site name: KANSAS ARNG/ARMY AVN SPT FAC 2
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 04/09/2002
Site name: KANSAS ARNG/ARMY AVN SPT FAC 2
Classification: Small Quantity Generator

Date form received by agency: 02/17/1995
Site name: KANSAS ARNG/ARMY AVN SPT FAC 2
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D026
. Waste name: CRESOL

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039

KANSAS ARNG/AASF 2 (Continued) **1000377651**

. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U052
. Waste name: CRESOL (CRESYLIC ACID) (OR) PHENOL, METHYL-

. Waste code: U070
. Waste name: BENZENE, 1,2-DICHLORO- (OR) O-DICHLOROBENZENE

. Waste code: U088

KANSAS ARNG/AASF 2 (Continued) **1000377651**

. Waste name: 1,2-BENZENEDICARBOXYLIC ACID, DIETHYL ESTER (OR) DIETHYL PHTHALATE

. Waste code: U103
. Waste name: DIMETHYL SULFATE (OR) SULFURIC ACID, DIMETHYL ESTER

. Waste code: U117
. Waste name: ETHANE, 1,1'-OXYBIS-(I) (OR) ETHYL ETHER (I)

. Waste code: U151
. Waste name: MERCURY

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U220
. Waste name: BENZENE, METHYL- (OR) TOLUENE

. Waste code: U226
. Waste name: ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

. Waste code: U240
. Waste name: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

Facility Has Received Notices of Violations:
Regulation violated: SR - KAR 28 31 4 h 1 C
Area of violation: Generators - Pre-transport
Date violation determined: 11/28/2001
Date achieved compliance: 11/28/2001
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/28/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 h 1 F
Area of violation: Generators - Pre-transport
Date violation determined: 11/28/2001
Date achieved compliance: 11/28/2001
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: 04/12/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 h 1 F

KANSAS ARNG/AASF 2 (Continued) **1000377651**

Area of violation: Generators - Pre-transport
Date violation determined: 11/28/2001
Date achieved compliance: 11/28/2001
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/28/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 h 1 C
Area of violation: Generators - Pre-transport
Date violation determined: 11/28/2001
Date achieved compliance: 11/28/2001
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: 04/12/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 16
Area of violation: Generators - General
Date violation determined: 11/28/2001
Date achieved compliance: 11/28/2001
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/28/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 h 1 D
Area of violation: Generators - Pre-transport
Date violation determined: 11/28/2001
Date achieved compliance: 11/28/2001
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/28/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 h 1 D
Area of violation: Generators - Pre-transport

KANSAS ARNG/AASF 2 (Continued) **1000377651**

Date violation determined: 11/28/2001
Date achieved compliance: 11/28/2001
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: 04/12/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 16
Area of violation: Generators - General
Date violation determined: 11/28/2001
Date achieved compliance: 11/28/2001
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: 04/12/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 10/19/2011
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/03/2003
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/22/2002
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/28/2002
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/28/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 11/28/2001
Evaluation lead agency: State

KANSAS ARNG/AASF 2 (Continued) **1000377651**

Evaluation date: 11/28/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/28/2001
Evaluation lead agency: State

FINDS:

Registry ID: 110003144543

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000377651
Registry ID: 110003144543
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003144543

WI MANIFEST:
Name: KANSAS NATIONAL GUARD SUPPORT FACILITY#2
Address: 2917 HEIM ST
City,State,Zip: SALINA, KS 67401
Year: 2005
EPA ID: KS3570090024
FID: 0
ACT Code: 202
ACT Status: A
ACT Code 1: 202
ACT Name: HW Generator - Small
Contact Title: Not reported
Contact Name: RICHARD TUSZKIEWICZ
Contact Address: 2917 HEIN ST
Contact City/State/Zip: SALINA, KS 67401
Contact Telephone: 7858223471
Contact EMail Address: Not reported

Name: KANSAS NATIONAL GUARD SUPPORT FACILITY#2
Address: 2917 HEIM ST
City,State,Zip: SALINA, KS 67401
Year: 2004
EPA ID: KS3570090024
FID: 0
ACT Code: 202
ACT Status: A
ACT Code 1: 202
ACT Name: HW Generator - Small
Contact Title: Not reported

KANSAS ARNG/AASF 2 (Continued) **1000377651**

Contact Name: RICHARD TUSZKIEWICZ
Contact Address: 2917 HEIN ST
Contact City/State/Zip: SALINA, KS 67401
Contact Telephone: 7858223471
Contact EMail Address: Not reported

A6 **A C HELICOPTERS** **FINDS** **1016065052**
Target **2917 HEIN (A)** **ECHO** **N/A**
Property **SALINA, KS 67401**

Site 6 of 8 in cluster A

Actual: 1256 ft.

FINDS:

Registry ID: 110003163718

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016065052
Registry ID: 110003163718
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003163718

A7 **KS ARMY NATL GUARD-SALINA AASF #2** **FINDS** **1015977963**
Target **2917 HELM STREET** **N/A**
Property **SALINA, KS 67401**

Site 7 of 8 in cluster A

Actual: 1256 ft.

FINDS:

Registry ID: 110044857517

Environmental Interest/Information System
KS-FP (Kansas - Facility Profiler) is a geographically-based data warehouse site that presents information about facilities and locations of interest to the KDHE. This site has in excess of twenty environmental interest which contains information on closed facilities, completed cleanups, and past operations as well as data on current operations and activities.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A8
Target Property **2917 HEIN AVE.**
SALINA, KS

KS SPILLS **S108486360**
N/A

Site 8 of 8 in cluster A

Actual: 1256 ft.

SPILLS:

Spill ID:	KDHE-25436
Reported Cause:	other
Discharger Organization Type:	NC
Source:	motor vehicle
Spill Date:	07/16/2002
Discharge Name:	Kansas Army National Guard
Material Name:	other oil
Media Affected:	soil
Status:	Closed
Latitude:	38.79490
Longitude:	-97.64060

SPILLS as of July 2016:

Ref ID:	18145
Evacuation:	Not reported
Responders:	Not reported
Cause Description:	Not reported
Cleanup Description:	contaminated soil was containerized in 55 gal drum for proper disposal.
Cleanup Method:	physical removal
Comments:	Mr. Schroeder has contacted Richard Bronaugh, BWM, for special waste permit to dispose of soil. Bronaugh requested that spiller test oil for PCBs since the equipment and building was constructed during period of PCB use. Mr. Schoeder has scheduled to t
Damage Description:	Not reported
Damage Number Of Deaths:	Not reported
Damage Number If Injuries:	Not reported
Property Damage > $50,000:	Undetermined
Discovery Date:	07/16/2002
Discovery Time:	1045
Spill Date:	Not reported
Spill Time:	Not reported
Discharger Address:	131 SW 27th St
Discharger City:	Topeka
Discharger Contact:	Tobias Schroeder
Discharger Ext. 1:	Not reported
Discharger Ext. 2:	Not reported
Discharger Facility ID:	Not reported
Discharger:	Kansas Army National Guard
Discharger Org ID:	Not reported
Discharger Organization Type:	State
Discharger Phone 1:	Not reported
Discharger Phone 2:	Not reported
Discharger State:	KS
Discharger Zip:	66611
District:	NC
GPS Source:	district
Highway Designation:	Not reported
Highway Type:	Not reported
KCC District:	Wichita
Latitude:	38.7949
Lease Number:	Not reported

(Continued) **S108486360**

Longitude:	-97.6406
Mile Post:	Not reported
Incident Qtr1:	Not reported
Incident Qtr2:	Not reported
Incident Qtr3:	Not reported
Incident Qtr4:	Not reported
Incident Range:	Not reported
Incident Section:	Not reported
Incident Township:	Not reported
Did EPA Respond?:	Unknown
EPA Spill Number:	Not reported
Initial Entry By:	Kent Schierkolk
Initial Entry Completed:	Yes
KCC Spill Number:	Not reported
Method Receive Initial Call:	Not reported
Multiple Report:	Not reported
NRCNO:	Not reported
Old Spill Number:	Not reported
Incident Recorded By:	Kent Schierkolk
Reported Date:	07/16/2002
Reported Time:	1100
SSI Repor:	Not reported
Spill Number:	25436
Spill Or Complaint:	Spill
Spill Stage:	Initial Assessment
Through NRC:	Unknown
Updated By:	Scott Lang
Investigating Agency:	KDHE
State Visited By KDHE?:	No
Investigated By 1:	Scott Lang
Hours Worked 1:	0.5
Investigated By 2:	Not reported
Hours Worked 2:	Not reported
Investigated By 3:	Not reported
Hours Worked 3:	Not reported
Quantity Spilled 1:	5
Qty Spilled Comment 1:	estimated
Quantity Spilled 2:	Not reported
Qty Spilled Comment 2:	Not reported
Quantity Spilled 3:	Not reported
Qty Spilled Comment 3:	Not reported
Case Number 1:	Not reported
Case Number 2:	Not reported
Case Number 3:	Not reported
Class 1:	other oil
Class 2:	Not reported
Class 3:	Not reported
Qty Spilled In Water 1:	0
Qty Spilled In Water Comment 1:	actual
Qty Spilled In Water 2:	Not reported
Qty Spilled In Water Comment 2:	Not reported
Qty Spilled In Water 3:	Not reported
Qty Spilled In Water Comment 3:	Not reported
Material Name:	hydraulic oil/fluid
Material Name 2:	Not reported
Material Name 3:	Not reported
Qty Recovered 1:	Not reported

(Continued) **S108486360**

Qty Recovered Comment 1:	Not reported
Qty Recovered 2:	Not reported
Qty Recovered Comment 2:	Not reported
Qty Recovered 3:	Not reported
Qty Recovered Comment 3:	Not reported
Material UNDOT Number 1:	Not reported
Material UNDOT Number 2:	Not reported
Material UNDOT Number 3:	Not reported
Unit 1:	gallons
Unit 2:	Not reported
Unit 3:	Not reported
Media:	soil
Media Waterway:	Not reported
Media Waterway Type:	Not reported
Who Notified:	NCDO
Notified:	Not reported
Spill Report:	Yes
Description:	Not reported
Number Of Tanks:	Not reported
Source Of Spill:	motor vehicle
Tank Capacity:	Not reported
Tank Unit:	Not reported
Vehicle ID:	Not reported
Close Date:	07/17/2002
Follow-up Required:	Not reported
Response Required By:	Not reported
Facility Status:	Closed
Comments 1:	backhoe hydraulic reservoir.
Comments 2:	pipe was struck and damged by back hoe during excavation near building
Comments 3:	oil leaked from pipe into surrounding soil
Comments 4:	leak stopped and contaminated soil was removed

B9 **SALINA AIRPORT AUTHORITY VII** **US BROWNFIELDS** **1018164027**
2734 ARNOLD COURT **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Site 1 of 4 in cluster B

Relative: US BROWNFIELDS:
Higher

Name:	SALINA AIRPORT AUTHORITY VII
Address:	2734 ARNOLD COURT
City,State,Zip:	SALINA, KS 67401
Recipient Name:	Kansas Department of Health and Environment
Grant Type:	Section 128(a) State/Tribal
Property Number:	Not reported
Parcel size:	5.73
Latitude:	38.789948
Longitude:	-97.640859
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	169744
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported

Actual:
1260 ft.

SALINA AIRPORT AUTHORITY VII (Continued) **1018164027**

Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1601
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	98726204
Start Date:	01/21/2014 00:00:00
Ownership Entity:	Private
Completion Date:	02/24/2014 00:00:00
Current Owner:	Salina Airport Authority
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported

SALINA AIRPORT AUTHORITY VII (Continued) **1018164027**

Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	5.73
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	5.73
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	1954-2012 property had commercial structures as it does today, prior to 1954, area was greenspace with residential structures. The current property owner is the Salina Airport Authority who acquired the property in 1965 from the Smoky Hill/ Schilling Air force base.
Below Poverty Number:	34

SALINA AIRPORT AUTHORITY VII (Continued) **1018164027**

Below Poverty Percent:	20.6%
Meidan Income:	360
Meidan Income Number:	70
Meidan Income Percent:	42.4%
Vacant Housing Number:	4
Vacant Housing Percent:	6.4%
Unemployed Number:	5
Unemployed Percent:	3.0%

C10 **SFC GLOBAL SUPPLY CHAIN INC** **KS LUST** **1000853724**
3019 SCANLAN AVE. **KS SPILLS** **N/A**
< 1/8 **SALINA, KS 67401** **KS AIRS**
1 ft. **KS TIER 2**

Site 1 of 2 in cluster C

Relative: **Lower**
Actual: **1254 ft.**

LUST:

Facility ID:	23129
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	07/11/1992
Project Number:	U5-085-00715
Project Name:	Tony's Pizza
Legal Desc Section:	03
Legal Desc Township:	15S
Legal Desc Range:	03W
Discover Date:	07/11/1992
substrels:	diesel
Initial Ranking:	Not reported
Current Ranking:	Not reported
Facility Contact:	Steve Ascher
Facility Phone Number:	785-825-1671
Facility Owner Identification number:	27004
Facility Owner:	Schwan's Sales Ent
Owner Contact Person:	Not reported
Owner Address:	115 W College
Owner City:	Marshall
Owner State:	MN
Owner Zip Code:	56258
Owner Phone number:	785-825-1671
Contractor license number:	Not reported
Contractor phone number:	785-823-7800
Leak duration (if known):	Unkn
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Spill/Overfill
Reported By:	Scott Lang, Kdhe
Reported by persons phone number:	Not reported
Reported by person address:	Ncdo
Ground water Impacted (yes/no):	0-2' brown silty clay (topsoil). 2'-6' grey & grey brown clay. 6-10' light grey brown sandy silty clay. gw at -10' no visible contaminants & no petroleum odors detectable. gw depth = 10'. gw flow = east, northeast.
Static groundwater level:	Not reported
Groundwater flow direction:	Not reported
District staff names:	Scott Lang
Assessment of release:	1-4000 gal diesel ust & lines removed. shallow tank backfill materials contaminated with diesel from apparent overfills. soils removed to diehls farm for aeration/landfarming.

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Containamination assessement:	yes.
Extent of contamination impact:	none.
Updated information:	Not reported
Invoice initiated:	19924
Invoice on going:	Not reported
Invoice completetd:	19924
Release confirmed:	19924
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	19924
Cost recovery initiated by:	Responsible Party
Cost recovery completed:	19924
Cost recovery completed by:	Responsible Party
Appplication to trust fund:	Not reported

SPILLS:

Spill ID:	41266
Reported Cause:	Equipment Failure
Discharger Organization Type:	NC
Source:	Fixed Facility
Spill Date:	03/01/2017
Discharge Name:	Schwan's Global Supply Chain, Inc. (Tony's Pizza)
Material Name:	Form A Chemicals
Media Affected:	Air, Soil
Status:	Closed
Latitude:	38.78333
Longitude:	-97.63370

AIRS:

Facility ID:	1690050
Class Code:	A
NAICS Code:	311412
MA Label:	1
Prog Status:	O
Inventory Year:	1997
SIC Code:	2038
Type Code:	Class I expired
Description:	NONE GIVEN TO ANDY
Permit Number:	299
Facility Status:	Void
Disuse Date:	06/18/2001
DRCVD Date:	03/03/1997
Type:	Operation Permit

AIRS:

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.78
Longitude:	-97.64
NAICS Code:	Not reported
SIC Code:	Not reported
Year:	2013
NOX:	11.96
NH3:	Not reported
PM10:	0.23

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

PM25:	Not reported
PMCON:	Not reported
SOX:	0.07
SO2:	Not reported
CO:	10.04
VOC:	80.69
HAPS:	Not reported
UTM Zone:	14.00
UTM North:	4293528.80
UTM East:	618550.29
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.781318999999996
Longitude:	-97.636188000000004
NAICS Code:	Not reported
SIC Code:	2038
Year:	2011
NOX:	12.5775498
NH3:	Not reported
PM10:	0.23897499
PM25:	Not reported
PMCON:	Not reported
SOX:	7.54659999
SO2:	Not reported
CO:	10.565142
VOC:	229.323386
HAPS:	0
UTM Zone:	14
UTM North:	4293393
UTM East:	618460
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2017
NOX:	11.20297555
NH3:	Not reported
PM10:	0.85126625
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.06889265
CO:	9.39299525
VOC:	82.62364235
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2016
NOX:	12.1737755
NH3:	Not reported
PM10:	0.92504705
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.07471745
CO:	10.2084672
VOC:	85.9851658
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported

Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	Not reported
Year:	2015
NOX:	12.8
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.8
VOC:	94.5
HAPS:	0.2
UTM Zone:	14
UTM North:	4293529
UTM East:	618550

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.782530999999999
Longitude:	-97.635125000000002
NAICS Code:	Not reported
SIC Code:	2038
Year:	2012
NOX:	12.2877499
NH3:	Not reported
PM10:	0.23346900
PM25:	Not reported
PMCON:	Not reported
SOX:	7.37269999
SO2:	Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

CO:	10.3217100
VOC:	261.128117
HAPS:	0
UTM Zone:	14
UTM North:	4293528.8039999995
UTM East:	618550.28899999999
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	Not reported
SIC Code:	2038
Year:	2010
NOX:	9.91205000
NH3:	Not reported
PM10:	0.18833
PM25:	Not reported
PMCON:	Not reported
SOX:	5.94739999
SO2:	Not reported
CO:	8.32612199
VOC:	245.388858
HAPS:	0
UTM Zone:	14
UTM North:	4293.393
UTM East:	618.46000000000004
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2009
NOX:	9.82295000
NH3:	Not reported
PM10:	0
PM25:	Not reported
PMCON:	Not reported
SOX:	5.89379998
SO2:	Not reported
CO:	8.25127799
VOC:	341.605178
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

SIC Code:	2038
Year:	2008
NOX:	10.91535
NH3:	Not reported
PM10:	0.82956600
PM25:	Not reported
PMCON:	Not reported
SOX:	6.54919999
SO2:	Not reported
CO:	9.16889399
VOC:	263.215565
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0

Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	Not reported
SIC Code:	2038
Year:	2014
NOX:	12.6
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.5
VOC:	77.7
HAPS:	0.0
UTM Zone:	14
UTM North:	4293528.804
UTM East:	618550.289

Facility ID:	1690050
Class Code:	A
NAICS Code:	311412
MA Label:	1
Prog Status:	O
Inventory Year:	2016
SIC Code:	2038
Type Code:	Permit
Description:	NEW OVENS
Permit Number:	13317
Facility Status:	Existing
Disuse Date:	06/13/2016
DRCVD Date:	02/29/2016
Type:	Construction Permit

AIRS:

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Latitude:	38.78
Longitude:	-97.64
NAICS Code:	Not reported
SIC Code:	Not reported
Year:	2013
NOX:	11.96
NH3:	Not reported
PM10:	0.23
PM25:	Not reported
PMCON:	Not reported
SOX:	0.07
SO2:	Not reported
CO:	10.04
VOC:	80.69
HAPS:	Not reported
UTM Zone:	14.00
UTM North:	4293528.80
UTM East:	618550.29

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.781318999999996
Longitude:	-97.636188000000004
NAICS Code:	Not reported
SIC Code:	2038
Year:	2011
NOX:	12.5775498
NH3:	Not reported
PM10:	0.23897499
PM25:	Not reported
PMCON:	Not reported
SOX:	7.54659999
SO2:	Not reported
CO:	10.565142
VOC:	229.323386
HAPS:	0
UTM Zone:	14
UTM North:	4293393
UTM East:	618460

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2017
NOX:	11.20297555
NH3:	Not reported
PM10:	0.85126625
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.06889265
CO:	9.39299525

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

VOC:	82.62364235
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2016
NOX:	12.1737755
NH3:	Not reported
PM10:	0.92504705
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.07471745
CO:	10.2084672
VOC:	85.9851658
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	Not reported
Year:	2015
NOX:	12.8
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.8
VOC:	94.5
HAPS:	0.2
UTM Zone:	14
UTM North:	4293529
UTM East:	618550
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.782530999999999
Longitude:	-97.635125000000002
NAICS Code:	Not reported
SIC Code:	2038

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Year:	2012
NOX:	12.2877499
NH3:	Not reported
PM10:	0.23346900
PM25:	Not reported
PMCON:	Not reported
SOX:	7.37269999
SO2:	Not reported
CO:	10.3217100
VOC:	261.128117
HAPS:	0
UTM Zone:	14
UTM North:	4293528.8039999995
UTM East:	618550.28899999999
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	Not reported
SIC Code:	2038
Year:	2010
NOX:	9.91205000
NH3:	Not reported
PM10:	0.18833
PM25:	Not reported
PMCON:	Not reported
SOX:	5.94739999
SO2:	Not reported
CO:	8.32612199
VOC:	245.388858
HAPS:	0
UTM Zone:	14
UTM North:	4293.393
UTM East:	618.46000000000004
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2009
NOX:	9.82295000
NH3:	Not reported
PM10:	0
PM25:	Not reported
PMCON:	Not reported
SOX:	5.89379998
SO2:	Not reported
CO:	8.25127799
VOC:	341.605178
HAPS:	0
UTM Zone:	0
UTM North:	0

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

UTM East: 0

Facility ID: 1690050
Facility ID 2: Not reported
Class Code: Not reported
Latitude: 384659
Longitude: 973811
NAICS Code: 311412
SIC Code: 2038
Year: 2008
NOX: 10.91535
NH3: Not reported
PM10: 0.82956600
PM25: Not reported
PMCON: Not reported
SOX: 6.54919999
SO2: Not reported
CO: 9.16889399
VOC: 263.215565
HAPS: 0
UTM Zone: 0
UTM North: 0
UTM East: 0

Facility ID: 1690050
Facility ID 2: 20-169-0050
Class Code: A
Latitude: 38.782531
Longitude: -97.635125
NAICS Code: Not reported
SIC Code: 2038
Year: 2014
NOX: 12.6
NH3: Not reported
PM10: 0.2
PM25: 0.2
PMCON: 0.7
SOX: Not reported
SO2: 0.1
CO: 10.5
VOC: 77.7
HAPS: 0.0
UTM Zone: 14
UTM North: 4293528.804
UTM East: 618550.289

Facility ID: 1690050
Class Code: A
NAICS Code: 311412
MA Label: 1
Prog Status: O
Inventory Year: 2006
SIC Code: 2038
Type Code: Approval
Description: BAKERY LINES 1 AND 2 REPLACE
Permit Number: 6721

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Facility Status:	Existing
Disuse Date:	04/04/2006
DRCVD Date:	02/15/2006
Type:	Construction Permit

AIRS:

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.78
Longitude:	-97.64
NAICS Code:	Not reported
SIC Code:	Not reported
Year:	2013
NOX:	11.96
NH3:	Not reported
PM10:	0.23
PM25:	Not reported
PMCON:	Not reported
SOX:	0.07
SO2:	Not reported
CO:	10.04
VOC:	80.69
HAPS:	Not reported
UTM Zone:	14.00
UTM North:	4293528.80
UTM East:	618550.29

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.781318999999996
Longitude:	-97.636188000000004
NAICS Code:	Not reported
SIC Code:	2038
Year:	2011
NOX:	12.5775498
NH3:	Not reported
PM10:	0.23897499
PM25:	Not reported
PMCON:	Not reported
SOX:	7.54659999
SO2:	Not reported
CO:	10.565142
VOC:	229.323386
HAPS:	0
UTM Zone:	14
UTM North:	4293393
UTM East:	618460

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2017

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

NOX:	11.20297555
NH3:	Not reported
PM10:	0.85126625
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.06889265
CO:	9.39299525
VOC:	82.62364235
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2016
NOX:	12.1737755
NH3:	Not reported
PM10:	0.92504705
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.07471745
CO:	10.2084672
VOC:	85.9851658
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	Not reported
Year:	2015
NOX:	12.8
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.8
VOC:	94.5
HAPS:	0.2
UTM Zone:	14
UTM North:	4293529
UTM East:	618550

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.782530999999999
Longitude:	-97.635125000000002
NAICS Code:	Not reported
SIC Code:	2038
Year:	2012
NOX:	12.2877499
NH3:	Not reported
PM10:	0.23346900
PM25:	Not reported
PMCON:	Not reported
SOX:	7.37269999
SO2:	Not reported
CO:	10.3217100
VOC:	261.128117
HAPS:	0
UTM Zone:	14
UTM North:	4293528.8039999995
UTM East:	618550.28899999999

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	Not reported
SIC Code:	2038
Year:	2010
NOX:	9.91205000
NH3:	Not reported
PM10:	0.18833
PM25:	Not reported
PMCON:	Not reported
SOX:	5.94739999
SO2:	Not reported
CO:	8.32612199
VOC:	245.388858
HAPS:	0
UTM Zone:	14
UTM North:	4293.393
UTM East:	618.46000000000004

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2009
NOX:	9.82295000
NH3:	Not reported
PM10:	0
PM25:	Not reported
PMCON:	Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

SOX:	5.89379998
SO2:	Not reported
CO:	8.25127799
VOC:	341.605178
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2008
NOX:	10.91535
NH3:	Not reported
PM10:	0.82956600
PM25:	Not reported
PMCON:	Not reported
SOX:	6.54919999
SO2:	Not reported
CO:	9.16889399
VOC:	263.215565
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	Not reported
SIC Code:	2038
Year:	2014
NOX:	12.6
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.5
VOC:	77.7
HAPS:	0.0
UTM Zone:	14
UTM North:	4293528.804
UTM East:	618550.289
Facility ID:	1690050
Class Code:	A
NAICS Code:	311412

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

MA Label:	1
Prog Status:	O
Inventory Year:	2004
SIC Code:	2038
Type Code:	Permit
Description:	REPLACE BAKERY LINE #3
Permit Number:	5671
Facility Status:	Existing
Disuse Date:	06/02/2004
DRCVD Date:	04/14/2004
Type:	Construction Permit

AIRS:

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.78
Longitude:	-97.64
NAICS Code:	Not reported
SIC Code:	Not reported
Year:	2013
NOX:	11.96
NH3:	Not reported
PM10:	0.23
PM25:	Not reported
PMCON:	Not reported
SOX:	0.07
SO2:	Not reported
CO:	10.04
VOC:	80.69
HAPS:	Not reported
UTM Zone:	14.00
UTM North:	4293528.80
UTM East:	618550.29

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.781318999999996
Longitude:	-97.636188000000004
NAICS Code:	Not reported
SIC Code:	2038
Year:	2011
NOX:	12.5775498
NH3:	Not reported
PM10:	0.23897499
PM25:	Not reported
PMCON:	Not reported
SOX:	7.54659999
SO2:	Not reported
CO:	10.565142
VOC:	229.323386
HAPS:	0
UTM Zone:	14
UTM North:	4293393
UTM East:	618460

Facility ID:	1690050

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Facility ID 2:	Not reported
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2017
NOX:	11.20297555
NH3:	Not reported
PM10:	0.85126625
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.06889265
CO:	9.39299525
VOC:	82.62364235
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported

Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2016
NOX:	12.1737755
NH3:	Not reported
PM10:	0.92504705
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.07471745
CO:	10.2084672
VOC:	85.9851658
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported

Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	Not reported
Year:	2015
NOX:	12.8
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

SO2:	0.1
CO:	10.8
VOC:	94.5
HAPS:	0.2
UTM Zone:	14
UTM North:	4293529
UTM East:	618550
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.782530999999999
Longitude:	-97.635125000000002
NAICS Code:	Not reported
SIC Code:	2038
Year:	2012
NOX:	12.2877499
NH3:	Not reported
PM10:	0.23346900
PM25:	Not reported
PMCON:	Not reported
SOX:	7.37269999
SO2:	Not reported
CO:	10.3217100
VOC:	261.128117
HAPS:	0
UTM Zone:	14
UTM North:	4293528.8039999995
UTM East:	618550.28899999999
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	Not reported
SIC Code:	2038
Year:	2010
NOX:	9.91205000
NH3:	Not reported
PM10:	0.18833
PM25:	Not reported
PMCON:	Not reported
SOX:	5.94739999
SO2:	Not reported
CO:	8.32612199
VOC:	245.388858
HAPS:	0
UTM Zone:	14
UTM North:	4293.393
UTM East:	618.46000000000004
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

NAICS Code:	311412
SIC Code:	2038
Year:	2009
NOX:	9.82295000
NH3:	Not reported
PM10:	0
PM25:	Not reported
PMCON:	Not reported
SOX:	5.89379998
SO2:	Not reported
CO:	8.25127799
VOC:	341.605178
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2008
NOX:	10.91535
NH3:	Not reported
PM10:	0.82956600
PM25:	Not reported
PMCON:	Not reported
SOX:	6.54919999
SO2:	Not reported
CO:	9.16889399
VOC:	263.215565
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0

Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	Not reported
SIC Code:	2038
Year:	2014
NOX:	12.6
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.5
VOC:	77.7
HAPS:	0.0

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

UTM Zone:	14
UTM North:	4293528.804
UTM East:	618550.289
Facility ID:	1690050
Class Code:	A
NAICS Code:	311412
MA Label:	1
Prog Status:	O
Inventory Year:	2002
SIC Code:	2038
Type Code:	Permit
Description:	OVEN, BAGHOUSE
Permit Number:	4742
Facility Status:	Existing
Disuse Date:	03/27/2003
DRCVD Date:	10/15/2002
Type:	Construction Permit

AIRS:

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.78
Longitude:	-97.64
NAICS Code:	Not reported
SIC Code:	Not reported
Year:	2013
NOX:	11.96
NH3:	Not reported
PM10:	0.23
PM25:	Not reported
PMCON:	Not reported
SOX:	0.07
SO2:	Not reported
CO:	10.04
VOC:	80.69
HAPS:	Not reported
UTM Zone:	14.00
UTM North:	4293528.80
UTM East:	618550.29
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.781318999999996
Longitude:	-97.636188000000004
NAICS Code:	Not reported
SIC Code:	2038
Year:	2011
NOX:	12.5775498
NH3:	Not reported
PM10:	0.23897499
PM25:	Not reported
PMCON:	Not reported
SOX:	7.54659999
SO2:	Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

CO:	10.565142
VOC:	229.323386
HAPS:	0
UTM Zone:	14
UTM North:	4293393
UTM East:	618460
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2017
NOX:	11.20297555
NH3:	Not reported
PM10:	0.85126625
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.06889265
CO:	9.39299525
VOC:	82.62364235
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2016
NOX:	12.1737755
NH3:	Not reported
PM10:	0.92504705
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.07471745
CO:	10.2084672
VOC:	85.9851658
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

SIC Code:	Not reported
Year:	2015
NOX:	12.8
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.8
VOC:	94.5
HAPS:	0.2
UTM Zone:	14
UTM North:	4293529
UTM East:	618550
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.782530999999999
Longitude:	-97.635125000000002
NAICS Code:	Not reported
SIC Code:	2038
Year:	2012
NOX:	12.2877499
NH3:	Not reported
PM10:	0.23346900
PM25:	Not reported
PMCON:	Not reported
SOX:	7.37269999
SO2:	Not reported
CO:	10.3217100
VOC:	261.128117
HAPS:	0
UTM Zone:	14
UTM North:	4293528.8039999995
UTM East:	618550.28899999999
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	Not reported
SIC Code:	2038
Year:	2010
NOX:	9.91205000
NH3:	Not reported
PM10:	0.18833
PM25:	Not reported
PMCON:	Not reported
SOX:	5.94739999
SO2:	Not reported
CO:	8.32612199
VOC:	245.388858
HAPS:	0
UTM Zone:	14

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

UTM North:	4293.393
UTM East:	618.46000000000004
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2009
NOX:	9.82295000
NH3:	Not reported
PM10:	0
PM25:	Not reported
PMCON:	Not reported
SOX:	5.89379998
SO2:	Not reported
CO:	8.25127799
VOC:	341.605178
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2008
NOX:	10.91535
NH3:	Not reported
PM10:	0.82956600
PM25:	Not reported
PMCON:	Not reported
SOX:	6.54919999
SO2:	Not reported
CO:	9.16889399
VOC:	263.215565
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	Not reported
SIC Code:	2038
Year:	2014
NOX:	12.6
NH3:	Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.5
VOC:	77.7
HAPS:	0.0
UTM Zone:	14
UTM North:	4293528.804
UTM East:	618550.289

Facility ID:	1690050
Class Code:	A
NAICS Code:	311412
MA Label:	1
Prog Status:	O
Inventory Year:	2001
SIC Code:	2038
Type Code:	Other
Description:	Amend permit requirements
Permit Number:	3615
Facility Status:	Existing
Disuse Date:	06/18/2001
DRCVD Date:	01/18/2001
Type:	Construction Permit

AIRS:

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.78
Longitude:	-97.64
NAICS Code:	Not reported
SIC Code:	Not reported
Year:	2013
NOX:	11.96
NH3:	Not reported
PM10:	0.23
PM25:	Not reported
PMCON:	Not reported
SOX:	0.07
SO2:	Not reported
CO:	10.04
VOC:	80.69
HAPS:	Not reported
UTM Zone:	14.00
UTM North:	4293528.80
UTM East:	618550.29

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.781318999999996
Longitude:	-97.636188000000004
NAICS Code:	Not reported
SIC Code:	2038

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Year:	2011
NOX:	12.5775498
NH3:	Not reported
PM10:	0.23897499
PM25:	Not reported
PMCON:	Not reported
SOX:	7.54659999
SO2:	Not reported
CO:	10.565142
VOC:	229.323386
HAPS:	0
UTM Zone:	14
UTM North:	4293393
UTM East:	618460
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2017
NOX:	11.20297555
NH3:	Not reported
PM10:	0.85126625
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.06889265
CO:	9.39299525
VOC:	82.62364235
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2016
NOX:	12.1737755
NH3:	Not reported
PM10:	0.92504705
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.07471745
CO:	10.2084672
VOC:	85.9851658
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	Not reported
Year:	2015
NOX:	12.8
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.8
VOC:	94.5
HAPS:	0.2
UTM Zone:	14
UTM North:	4293529
UTM East:	618550
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.782530999999999
Longitude:	-97.635125000000002
NAICS Code:	Not reported
SIC Code:	2038
Year:	2012
NOX:	12.2877499
NH3:	Not reported
PM10:	0.23346900
PM25:	Not reported
PMCON:	Not reported
SOX:	7.37269999
SO2:	Not reported
CO:	10.3217100
VOC:	261.128117
HAPS:	0
UTM Zone:	14
UTM North:	4293528.8039999995
UTM East:	618550.28899999999
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	Not reported
SIC Code:	2038
Year:	2010
NOX:	9.91205000
NH3:	Not reported
PM10:	0.18833

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

PM25:	Not reported
PMCON:	Not reported
SOX:	5.94739999
SO2:	Not reported
CO:	8.32612199
VOC:	245.388858
HAPS:	0
UTM Zone:	14
UTM North:	4293.393
UTM East:	618.46000000000004
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2009
NOX:	9.82295000
NH3:	Not reported
PM10:	0
PM25:	Not reported
PMCON:	Not reported
SOX:	5.89379998
SO2:	Not reported
CO:	8.25127799
VOC:	341.605178
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2008
NOX:	10.91535
NH3:	Not reported
PM10:	0.82956600
PM25:	Not reported
PMCON:	Not reported
SOX:	6.54919999
SO2:	Not reported
CO:	9.16889399
VOC:	263.215565
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0
Facility ID:	1690050
Facility ID 2:	20-169-0050

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	Not reported
SIC Code:	2038
Year:	2014
NOX:	12.6
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.5
VOC:	77.7
HAPS:	0.0
UTM Zone:	14
UTM North:	4293528.804
UTM East:	618550.289

Facility ID:	1690050
Class Code:	A
NAICS Code:	311412
MA Label:	1
Prog Status:	O
Inventory Year:	1999
SIC Code:	2038
Type Code:	Approval
Description:	Boiler
Permit Number:	2244
Facility Status:	Existing
Disuse Date:	04/12/1999
DRCVD Date:	03/15/1999
Type:	Construction Permit

AIRS:

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.78
Longitude:	-97.64
NAICS Code:	Not reported
SIC Code:	Not reported
Year:	2013
NOX:	11.96
NH3:	Not reported
PM10:	0.23
PM25:	Not reported
PMCON:	Not reported
SOX:	0.07
SO2:	Not reported
CO:	10.04
VOC:	80.69
HAPS:	Not reported
UTM Zone:	14.00
UTM North:	4293528.80
UTM East:	618550.29

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.781318999999996
Longitude:	-97.636188000000004
NAICS Code:	Not reported
SIC Code:	2038
Year:	2011
NOX:	12.5775498
NH3:	Not reported
PM10:	0.23897499
PM25:	Not reported
PMCON:	Not reported
SOX:	7.54659999
SO2:	Not reported
CO:	10.565142
VOC:	229.323386
HAPS:	0
UTM Zone:	14
UTM North:	4293393
UTM East:	618460

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2017
NOX:	11.20297555
NH3:	Not reported
PM10:	0.85126625
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.06889265
CO:	9.39299525
VOC:	82.62364235
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported

Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2016
NOX:	12.1737755
NH3:	Not reported
PM10:	0.92504705
PM25:	Not reported
PMCON:	Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

SOX:	Not reported
SO2:	0.07471745
CO:	10.2084672
VOC:	85.9851658
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	Not reported
Year:	2015
NOX:	12.8
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.8
VOC:	94.5
HAPS:	0.2
UTM Zone:	14
UTM North:	4293529
UTM East:	618550
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.782530999999999
Longitude:	-97.635125000000002
NAICS Code:	Not reported
SIC Code:	2038
Year:	2012
NOX:	12.2877499
NH3:	Not reported
PM10:	0.23346900
PM25:	Not reported
PMCON:	Not reported
SOX:	7.37269999
SO2:	Not reported
CO:	10.3217100
VOC:	261.128117
HAPS:	0
UTM Zone:	14
UTM North:	4293528.8039999995
UTM East:	618550.28899999999
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Longitude:	973811
NAICS Code:	Not reported
SIC Code:	2038
Year:	2010
NOX:	9.91205000
NH3:	Not reported
PM10:	0.18833
PM25:	Not reported
PMCON:	Not reported
SOX:	5.94739999
SO2:	Not reported
CO:	8.32612199
VOC:	245.388858
HAPS:	0
UTM Zone:	14
UTM North:	4293.393
UTM East:	618.46000000000004
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2009
NOX:	9.82295000
NH3:	Not reported
PM10:	0
PM25:	Not reported
PMCON:	Not reported
SOX:	5.89379998
SO2:	Not reported
CO:	8.25127799
VOC:	341.605178
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2008
NOX:	10.91535
NH3:	Not reported
PM10:	0.82956600
PM25:	Not reported
PMCON:	Not reported
SOX:	6.54919999
SO2:	Not reported
CO:	9.16889399
VOC:	263.215565

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	Not reported
SIC Code:	2038
Year:	2014
NOX:	12.6
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.5
VOC:	77.7
HAPS:	0.0
UTM Zone:	14
UTM North:	4293528.804
UTM East:	618550.289
Facility ID:	1690050
Class Code:	A
NAICS Code:	311412
MA Label:	1
Prog Status:	O
Inventory Year:	1998
SIC Code:	2038
Type Code:	Other
Description:	OVEN
Permit Number:	1802
Facility Status:	Existing
Disuse Date:	06/23/1998
DRCVD Date:	03/23/1998
Type:	Construction Permit

AIRS:

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.78
Longitude:	-97.64
NAICS Code:	Not reported
SIC Code:	Not reported
Year:	2013
NOX:	11.96
NH3:	Not reported
PM10:	0.23
PM25:	Not reported
PMCON:	Not reported
SOX:	0.07

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

SO2:	Not reported
CO:	10.04
VOC:	80.69
HAPS:	Not reported
UTM Zone:	14.00
UTM North:	4293528.80
UTM East:	618550.29
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.781318999999996
Longitude:	-97.636188000000004
NAICS Code:	Not reported
SIC Code:	2038
Year:	2011
NOX:	12.5775498
NH3:	Not reported
PM10:	0.23897499
PM25:	Not reported
PMCON:	Not reported
SOX:	7.54659999
SO2:	Not reported
CO:	10.565142
VOC:	229.323386
HAPS:	0
UTM Zone:	14
UTM North:	4293393
UTM East:	618460
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2017
NOX:	11.20297555
NH3:	Not reported
PM10:	0.85126625
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.06889265
CO:	9.39299525
VOC:	82.62364235
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

NAICS Code:	311412
SIC Code:	2038
Year:	2016
NOX:	12.1737755
NH3:	Not reported
PM10:	0.92504705
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.07471745
CO:	10.2084672
VOC:	85.9851658
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported

Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	Not reported
Year:	2015
NOX:	12.8
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.8
VOC:	94.5
HAPS:	0.2
UTM Zone:	14
UTM North:	4293529
UTM East:	618550

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.782530999999999
Longitude:	-97.635125000000002
NAICS Code:	Not reported
SIC Code:	2038
Year:	2012
NOX:	12.2877499
NH3:	Not reported
PM10:	0.23346900
PM25:	Not reported
PMCON:	Not reported
SOX:	7.37269999
SO2:	Not reported
CO:	10.3217100
VOC:	261.128117
HAPS:	0

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

UTM Zone:	14
UTM North:	4293528.8039999995
UTM East:	618550.28899999999
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	Not reported
SIC Code:	2038
Year:	2010
NOX:	9.91205000
NH3:	Not reported
PM10:	0.18833
PM25:	Not reported
PMCON:	Not reported
SOX:	5.94739999
SO2:	Not reported
CO:	8.32612199
VOC:	245.388858
HAPS:	0
UTM Zone:	14
UTM North:	4293.393
UTM East:	618.46000000000004
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2009
NOX:	9.82295000
NH3:	Not reported
PM10:	0
PM25:	Not reported
PMCON:	Not reported
SOX:	5.89379998
SO2:	Not reported
CO:	8.25127799
VOC:	341.605178
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2008
NOX:	10.91535

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

NH3:	Not reported
PM10:	0.82956600
PM25:	Not reported
PMCON:	Not reported
SOX:	6.54919999
SO2:	Not reported
CO:	9.16889399
VOC:	263.215565
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0

Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	Not reported
SIC Code:	2038
Year:	2014
NOX:	12.6
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.5
VOC:	77.7
HAPS:	0.0
UTM Zone:	14
UTM North:	4293528.804
UTM East:	618550.289

Facility ID:	1690050
Class Code:	A
NAICS Code:	311412
MA Label:	1
Prog Status:	O
Inventory Year:	1997
SIC Code:	2038
Type Code:	Other
Description:	BOILER
Permit Number:	1178
Facility Status:	New
Disuse Date:	03/10/1997
DRCVD Date:	01/28/1997
Type:	Construction Permit

AIRS:

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.78
Longitude:	-97.64
NAICS Code:	Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

SIC Code:	Not reported
Year:	2013
NOX:	11.96
NH3:	Not reported
PM10:	0.23
PM25:	Not reported
PMCON:	Not reported
SOX:	0.07
SO2:	Not reported
CO:	10.04
VOC:	80.69
HAPS:	Not reported
UTM Zone:	14.00
UTM North:	4293528.80
UTM East:	618550.29
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.781318999999996
Longitude:	-97.636188000000004
NAICS Code:	Not reported
SIC Code:	2038
Year:	2011
NOX:	12.5775498
NH3:	Not reported
PM10:	0.23897499
PM25:	Not reported
PMCON:	Not reported
SOX:	7.54659999
SO2:	Not reported
CO:	10.565142
VOC:	229.323386
HAPS:	0
UTM Zone:	14
UTM North:	4293393
UTM East:	618460
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2017
NOX:	11.20297555
NH3:	Not reported
PM10:	0.85126625
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.06889265
CO:	9.39299525
VOC:	82.62364235
HAPS:	Not reported
UTM Zone:	Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

UTM North:	Not reported
UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2016
NOX:	12.1737755
NH3:	Not reported
PM10:	0.92504705
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.07471745
CO:	10.2084672
VOC:	85.9851658
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	Not reported
Year:	2015
NOX:	12.8
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.8
VOC:	94.5
HAPS:	0.2
UTM Zone:	14
UTM North:	4293529
UTM East:	618550
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.782530999999999
Longitude:	-97.635125000000002
NAICS Code:	Not reported
SIC Code:	2038
Year:	2012
NOX:	12.2877499
NH3:	Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

PM10:	0.23346900
PM25:	Not reported
PMCON:	Not reported
SOX:	7.37269999
SO2:	Not reported
CO:	10.3217100
VOC:	261.128117
HAPS:	0
UTM Zone:	14
UTM North:	4293528.8039999995
UTM East:	618550.28899999999
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	Not reported
SIC Code:	2038
Year:	2010
NOX:	9.91205000
NH3:	Not reported
PM10:	0.18833
PM25:	Not reported
PMCON:	Not reported
SOX:	5.94739999
SO2:	Not reported
CO:	8.32612199
VOC:	245.388858
HAPS:	0
UTM Zone:	14
UTM North:	4293.393
UTM East:	618.46000000000004
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2009
NOX:	9.82295000
NH3:	Not reported
PM10:	0
PM25:	Not reported
PMCON:	Not reported
SOX:	5.89379998
SO2:	Not reported
CO:	8.25127799
VOC:	341.605178
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0
Facility ID:	1690050

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2008
NOX:	10.91535
NH3:	Not reported
PM10:	0.82956600
PM25:	Not reported
PMCON:	Not reported
SOX:	6.54919999
SO2:	Not reported
CO:	9.16889399
VOC:	263.215565
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0

Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	Not reported
SIC Code:	2038
Year:	2014
NOX:	12.6
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.5
VOC:	77.7
HAPS:	0.0
UTM Zone:	14
UTM North:	4293528.804
UTM East:	618550.289

Facility ID:	1690050
Class Code:	A
NAICS Code:	311412
MA Label:	1
Prog Status:	O
Inventory Year:	2015
SIC Code:	2038
Type Code:	Class I
Description:	CLASS I RENEWAL
Permit Number:	13159
Facility Status:	Renewal
Disuse Date:	01/12/2018
DRCVD Date:	11/23/2015

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Type: Operation Permit

AIRS:

Facility ID: 1690050
Facility ID 2: Not reported
Class Code: Not reported
Latitude: 38.78
Longitude: -97.64
NAICS Code: Not reported
SIC Code: Not reported
Year: 2013
NOX: 11.96
NH3: Not reported
PM10: 0.23
PM25: Not reported
PMCON: Not reported
SOX: 0.07
SO2: Not reported
CO: 10.04
VOC: 80.69
HAPS: Not reported
UTM Zone: 14.00
UTM North: 4293528.80
UTM East: 618550.29

Facility ID: 1690050
Facility ID 2: Not reported
Class Code: Not reported
Latitude: 38.781318999999996
Longitude: -97.636188000000004
NAICS Code: Not reported
SIC Code: 2038
Year: 2011
NOX: 12.5775498
NH3: Not reported
PM10: 0.23897499
PM25: Not reported
PMCON: Not reported
SOX: 7.54659999
SO2: Not reported
CO: 10.565142
VOC: 229.323386
HAPS: 0
UTM Zone: 14
UTM North: 4293393
UTM East: 618460

Facility ID: 1690050
Facility ID 2: Not reported
Class Code: A
Latitude: 38.782531
Longitude: -97.635125
NAICS Code: 311412
SIC Code: 2038
Year: 2017
NOX: 11.20297555
NH3: Not reported
PM10: 0.85126625

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.06889265
CO:	9.39299525
VOC:	82.62364235
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2016
NOX:	12.1737755
NH3:	Not reported
PM10:	0.92504705
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.07471745
CO:	10.2084672
VOC:	85.9851658
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	Not reported
Year:	2015
NOX:	12.8
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.8
VOC:	94.5
HAPS:	0.2
UTM Zone:	14
UTM North:	4293529
UTM East:	618550
Facility ID:	1690050
Facility ID 2:	Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Class Code:	Not reported
Latitude:	38.782530999999999
Longitude:	-97.635125000000002
NAICS Code:	Not reported
SIC Code:	2038
Year:	2012
NOX:	12.2877499
NH3:	Not reported
PM10:	0.23346900
PM25:	Not reported
PMCON:	Not reported
SOX:	7.37269999
SO2:	Not reported
CO:	10.3217100
VOC:	261.128117
HAPS:	0
UTM Zone:	14
UTM North:	4293528.8039999995
UTM East:	618550.28899999999

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	Not reported
SIC Code:	2038
Year:	2010
NOX:	9.91205000
NH3:	Not reported
PM10:	0.18833
PM25:	Not reported
PMCON:	Not reported
SOX:	5.94739999
SO2:	Not reported
CO:	8.32612199
VOC:	245.388858
HAPS:	0
UTM Zone:	14
UTM North:	4293.393
UTM East:	618.46000000000004

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2009
NOX:	9.82295000
NH3:	Not reported
PM10:	0
PM25:	Not reported
PMCON:	Not reported
SOX:	5.89379998
SO2:	Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

CO:	8.25127799
VOC:	341.605178
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2008
NOX:	10.91535
NH3:	Not reported
PM10:	0.82956600
PM25:	Not reported
PMCON:	Not reported
SOX:	6.54919999
SO2:	Not reported
CO:	9.16889399
VOC:	263.215565
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	Not reported
SIC Code:	2038
Year:	2014
NOX:	12.6
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.5
VOC:	77.7
HAPS:	0.0
UTM Zone:	14
UTM North:	4293528.804
UTM East:	618550.289
Facility ID:	1690050
Class Code:	A
NAICS Code:	311412
MA Label:	1
Prog Status:	O

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Inventory Year:	2010
SIC Code:	2038
Type Code:	Class I expired
Description:	CLASS I RENEWAL
Permit Number:	9273
Facility Status:	Renewal
Disuse Date:	05/24/2011
DRCVD Date:	09/28/2010
Type:	Operation Permit

AIRS:

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.78
Longitude:	-97.64
NAICS Code:	Not reported
SIC Code:	Not reported
Year:	2013
NOX:	11.96
NH3:	Not reported
PM10:	0.23
PM25:	Not reported
PMCON:	Not reported
SOX:	0.07
SO2:	Not reported
CO:	10.04
VOC:	80.69
HAPS:	Not reported
UTM Zone:	14.00
UTM North:	4293528.80
UTM East:	618550.29

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.781318999999996
Longitude:	-97.636188000000004
NAICS Code:	Not reported
SIC Code:	2038
Year:	2011
NOX:	12.5775498
NH3:	Not reported
PM10:	0.23897499
PM25:	Not reported
PMCON:	Not reported
SOX:	7.54659999
SO2:	Not reported
CO:	10.565142
VOC:	229.323386
HAPS:	0
UTM Zone:	14
UTM North:	4293393
UTM East:	618460

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	A

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2017
NOX:	11.20297555
NH3:	Not reported
PM10:	0.85126625
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.06889265
CO:	9.39299525
VOC:	82.62364235
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported

Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2016
NOX:	12.1737755
NH3:	Not reported
PM10:	0.92504705
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.07471745
CO:	10.2084672
VOC:	85.9851658
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported

Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	Not reported
Year:	2015
NOX:	12.8
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.8

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

VOC:	94.5
HAPS:	0.2
UTM Zone:	14
UTM North:	4293529
UTM East:	618550
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.782530999999999
Longitude:	-97.635125000000002
NAICS Code:	Not reported
SIC Code:	2038
Year:	2012
NOX:	12.2877499
NH3:	Not reported
PM10:	0.23346900
PM25:	Not reported
PMCON:	Not reported
SOX:	7.37269999
SO2:	Not reported
CO:	10.3217100
VOC:	261.128117
HAPS:	0
UTM Zone:	14
UTM North:	4293528.8039999995
UTM East:	618550.28899999999
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	Not reported
SIC Code:	2038
Year:	2010
NOX:	9.91205000
NH3:	Not reported
PM10:	0.18833
PM25:	Not reported
PMCON:	Not reported
SOX:	5.94739999
SO2:	Not reported
CO:	8.32612199
VOC:	245.388858
HAPS:	0
UTM Zone:	14
UTM North:	4293.393
UTM East:	618.46000000000004
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Year:	2009
NOX:	9.82295000
NH3:	Not reported
PM10:	0
PM25:	Not reported
PMCON:	Not reported
SOX:	5.89379998
SO2:	Not reported
CO:	8.25127799
VOC:	341.605178
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2008
NOX:	10.91535
NH3:	Not reported
PM10:	0.82956600
PM25:	Not reported
PMCON:	Not reported
SOX:	6.54919999
SO2:	Not reported
CO:	9.16889399
VOC:	263.215565
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	Not reported
SIC Code:	2038
Year:	2014
NOX:	12.6
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.5
VOC:	77.7
HAPS:	0.0
UTM Zone:	14
UTM North:	4293528.804

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

UTM East: 618550.289

Facility ID: 1690050
Class Code: A
NAICS Code: 311412
MA Label: 1
Prog Status: O
Inventory Year: 2005
SIC Code: 2038
Type Code: Class I expired
Description: CLASS I RENEWAL
Permit Number: 6617
Facility Status: Void
Disuse Date: 04/04/2006
DRCVD Date: 12/14/2005
Type: Operation Permit

AIRS:
Facility ID: 1690050
Facility ID 2: Not reported
Class Code: Not reported
Latitude: 38.78
Longitude: -97.64
NAICS Code: Not reported
SIC Code: Not reported
Year: 2013
NOX: 11.96
NH3: Not reported
PM10: 0.23
PM25: Not reported
PMCON: Not reported
SOX: 0.07
SO2: Not reported
CO: 10.04
VOC: 80.69
HAPS: Not reported
UTM Zone: 14.00
UTM North: 4293528.80
UTM East: 618550.29

Facility ID: 1690050
Facility ID 2: Not reported
Class Code: Not reported
Latitude: 38.781318999999996
Longitude: -97.636188000000004
NAICS Code: Not reported
SIC Code: 2038
Year: 2011
NOX: 12.5775498
NH3: Not reported
PM10: 0.23897499
PM25: Not reported
PMCON: Not reported
SOX: 7.54659999
SO2: Not reported
CO: 10.565142
VOC: 229.323386

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

HAPS:	0
UTM Zone:	14
UTM North:	4293393
UTM East:	618460
Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2017
NOX:	11.20297555
NH3:	Not reported
PM10:	0.85126625
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.06889265
CO:	9.39299525
VOC:	82.62364235
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	2038
Year:	2016
NOX:	12.1737755
NH3:	Not reported
PM10:	0.92504705
PM25:	Not reported
PMCON:	Not reported
SOX:	Not reported
SO2:	0.07471745
CO:	10.2084672
VOC:	85.9851658
HAPS:	Not reported
UTM Zone:	Not reported
UTM North:	Not reported
UTM East:	Not reported
Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	311412
SIC Code:	Not reported
Year:	2015

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

NOX:	12.8
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7
SOX:	Not reported
SO2:	0.1
CO:	10.8
VOC:	94.5
HAPS:	0.2
UTM Zone:	14
UTM North:	4293529
UTM East:	618550

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	38.782530999999999
Longitude:	-97.635125000000002
NAICS Code:	Not reported
SIC Code:	2038
Year:	2012
NOX:	12.2877499
NH3:	Not reported
PM10:	0.23346900
PM25:	Not reported
PMCON:	Not reported
SOX:	7.37269999
SO2:	Not reported
CO:	10.3217100
VOC:	261.128117
HAPS:	0
UTM Zone:	14
UTM North:	4293528.8039999995
UTM East:	618550.28899999999

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	Not reported
SIC Code:	2038
Year:	2010
NOX:	9.91205000
NH3:	Not reported
PM10:	0.18833
PM25:	Not reported
PMCON:	Not reported
SOX:	5.94739999
SO2:	Not reported
CO:	8.32612199
VOC:	245.388858
HAPS:	0
UTM Zone:	14
UTM North:	4293.393
UTM East:	618.46000000000004

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2009
NOX:	9.82295000
NH3:	Not reported
PM10:	0
PM25:	Not reported
PMCON:	Not reported
SOX:	5.89379998
SO2:	Not reported
CO:	8.25127799
VOC:	341.605178
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0

Facility ID:	1690050
Facility ID 2:	Not reported
Class Code:	Not reported
Latitude:	384659
Longitude:	973811
NAICS Code:	311412
SIC Code:	2038
Year:	2008
NOX:	10.91535
NH3:	Not reported
PM10:	0.82956600
PM25:	Not reported
PMCON:	Not reported
SOX:	6.54919999
SO2:	Not reported
CO:	9.16889399
VOC:	263.215565
HAPS:	0
UTM Zone:	0
UTM North:	0
UTM East:	0

Facility ID:	1690050
Facility ID 2:	20-169-0050
Class Code:	A
Latitude:	38.782531
Longitude:	-97.635125
NAICS Code:	Not reported
SIC Code:	2038
Year:	2014
NOX:	12.6
NH3:	Not reported
PM10:	0.2
PM25:	0.2
PMCON:	0.7

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

SOX:	Not reported
SO2:	0.1
CO:	10.5
VOC:	77.7
HAPS:	0.0
UTM Zone:	14
UTM North:	4293528.804
UTM East:	618550.289

TIER 2:

Facility Id:	365006
Facility Phone:	(785)825-1671
FID Num:	SA00341
PID Num:	MN0006
NAICS:	311412
Report Year:	2011
New Facility:	Not reported
Nearest Cross Street:	SCHILLING RD
SIC Code:	2038
Section Code:	312
Emergency Name1:	BRYON DOWNEY
Emergency Title1:	MAINT SUPT
Emergency Phone1:	(785)825-1671
Emergency 24phone1:	(785)825-1671
Emergency Name2:	JAMES VAN BLARICON
Emergency Title2:	PSM COORD
Emergency Phone2:	(785)825-1671
Emergency 24phone2:	(785)825-1671
Submitter:	Not reported
Created:	Not reported
Updated:	9/14/2012 3:41:49 PM
Rep Name:	Don Johnson
Rep Title:	Sr. Capital Project Eng.
Zip Field:	Not reported
Facility Latitude:	Not reported
Facility Longitude:	Not reported
Emergency Email1:	Not reported
Emergency Email2:	Not reported
Tier2 Contact Name:	Not reported
Tier2 Title:	Not reported
Tier2 Phone:	Not reported
Tier2 Phone24:	Not reported
Tier2 EMail:	Not reported
Annual Revision:	Not reported
Max Occupants:	Not reported
Manned/Unmanned:	Not reported
Section:	Not reported
Township:	Not reported
Range0:	Not reported
Trifids:	Not reported
RMP Facid:	Not reported
Subject 302:	Not reported
Subject 112:	Not reported

Facility Id:	365006
Facility Phone:	785-825-1671

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

FID Num:	SA00341
PID Num:	MN0006
NAICS:	311412
Report Year:	2017
New Facility:	Not reported
Nearest Cross Street:	JUMPER RD
SIC Code:	2038
Section Code:	312
Emergency Name1:	MIKE WHITLOCK
Emergency Title1:	EHS MGR
Emergency Phone1:	785-825-1671
Emergency 24phone1:	904-610-4148
Emergency Name2:	PAUL STACHEWICZ
Emergency Title2:	EHS SR DIRECTOR
Emergency Phone2:	952-832-4446
Emergency 24phone2:	651-587-1887
Submitter:	Not reported
Created:	Not reported
Updated:	2018-02-28 10:02:32
Rep Name:	Randy Sharbono
Rep Title:	VP and Assistant General Counsel
Zip Field:	Not reported
Facility Latitude:	38.7821150
Facility Longitude:	-97.6332340
Emergency Email1:	mike.whitlock@schwans.com
Emergency Email2:	paul.stachewicz@schwans.com
Tier2 Contact Name:	RANDY SHARBONO
Tier2 Title:	VP & ASST GEN COUNSEL
Tier2 Phone:	507-537-8551
Tier2 Phone24:	612-812-9075
Tier2 EMail:	randy.sharbono@schwans.com
Annual Revision:	annual
Max Occupants:	1150
Manned/Unmanned:	manned
Section:	Not reported
Township:	Not reported
Range0:	Not reported
Trifids:	67401TNYSP3019S
RMP Facid:	1000 0012 3724
Subject 302:	Y
Subject 112:	Y

Chemical:

FID Num:	SA00341
Chemical Id:	860426
Chemical Name:	ANHYDROUS AMMONIA
CAS:	7664-41-7
Trade Secret:	No
EHS:	Yes
Solid:	Not reported
Liquid:	Yes
Gas:	Yes
Pure:	Yes
Mix:	Not reported
Fire:	Not reported
Pressure:	Yes
Reactive:	Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Delayed: Not reported
Immediate: Yes
Max Daily Amt: 488000
Avg Daily Amt: 488000
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

FID Num: SA00341
Chemical Id: 897701
Chemical Name: LEAD
CAS: 7439-92-1
Trade Secret: No
EHS: Not reported
Solid: Yes
Liquid: Not reported
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Not reported
Pressure: Not reported
Reactive: Not reported
Delayed: Yes
Immediate: Not reported
Max Daily Amt: 96531
Avg Daily Amt: 96531
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Below Ground Tank
Pressure: A

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

FID Num: SA00341
Chemical Id: 897702
Chemical Name: SULFURIC ACID
CAS: 7664-93-9
Trade Secret: No
EHS: Yes
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Reactive: Yes
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 25237
Avg Daily Amt: 25237
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF TREATMENT PLT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF TREATMENT PLT

Fid Num: SA00341

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

FID Num: SA00341
Chemical Id: 934208
Chemical Name: DIESEL FUEL
CAS: 68476-34-6
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 5890
Avg Daily Amt: 2945
Days On Site: 365
Opt Report: 1

Storage:
Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: FIRE PUMP BLDG 985

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1213803
Container: Below Ground Tank
Pressure: Ambient pressure

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Temperature: Ambient temperature
Storage Location: 2408 HEIN - 700 FT W OF GARAGE

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: NW corner of Jumper and Centennial Roads

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: NW corner of Jumper and Centennial Roads

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: FIRE PUMP BLDG 985

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1213803
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Storage Location: 2408 HEIN - 700 FT W OF GARAGE

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

FID Num: SA00341
Chemical Id: 934209
Chemical Name: PETROLEUM MINERAL OIL
CAS: 8042-47-5
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Yes
Immediate: Not reported
Max Daily Amt: 356329
Avg Daily Amt: 178165
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280825
Container: T
Pressure: A
Temperature: A
Storage Location: HYDRAULIC ROOMS

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280826
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: REFRIGERATION COMPRESSORS

Fid Num: SA00341

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280827
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: TRANSFORMERS

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280828
Container: S
Pressure: A
Temperature: A
Storage Location: DIE WASHING RM-CHEM BLDG

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280829
Container: T
Pressure: A
Temperature: A
Storage Location: CHEM STORAGE BLDG

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280825
Container: T
Pressure: A
Temperature: A
Storage Location: HYDRAULIC ROOMS

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280826
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: REFRIGERATION COMPRESSORS

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280827
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: TRANSFORMERS

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280828
Container: S
Pressure: A
Temperature: A
Storage Location: DIE WASHING RM-CHEM BLDG

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Storage Id: 1280829
Container: T
Pressure: A
Temperature: A
Storage Location: CHEM STORAGE BLDG

FID Num: SA00341
Chemical Id: 860426
Chemical Name: ANHYDROUS AMMONIA
CAS: 7664417
Trade Secret: No
EHS: Yes
Solid: Not reported
Liquid: Yes
Gas: Yes
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Yes
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 488000
Avg Daily Amt: 488000
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

FID Num: SA00341
Chemical Id: 860427
Chemical Name: CARBON DIOXIDE
CAS: 1124389
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Yes
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Yes
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 0
Avg Daily Amt: 0
Days On Site: 365
Opt Report: Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Storage:
Fid Num: SA00341
Chemical Name: CARBON DIOXIDE
Storage Id: 1213802
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: NORTH SIDE OF PLANT / Tank is empty, not in use

Fid Num: SA00341
Chemical Name: CARBON DIOXIDE
Storage Id: 1213802
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: NORTH SIDE OF PLANT / Tank is empty, not in use

FID Num: SA00341
Chemical Id: 860428
Chemical Name: DIESEL FUEL
CAS: Not reported
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 450000
Avg Daily Amt: 225000
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: FIRE PUMP BLDG 985

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1213803
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 2408 HEIN - 700 FT W OF GARAGE

Fid Num: SA00341

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: NW corner of Jumper and Centennial Roads

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: NW corner of Jumper and Centennial Roads

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: FIRE PUMP BLDG 985

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1213803
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 2408 HEIN - 700 FT W OF GARAGE

Fid Num: SA00341
Chemical Name: DIESEL FUEL

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

FID Num: SA00341
Chemical Id: 860429
Chemical Name: ETHYLENE GLYCOL
CAS: 107211
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 30000
Avg Daily Amt: 25000
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1289638
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF PLANT CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Temperature: A
Storage Location: S SIDE OF PLANT CP-4

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

FID Num: SA00341
Chemical Id: 860431
Chemical Name: PROPANE
CAS: 74986
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Yes
Pure: Yes
Mix: Not reported
Fire: Yes
Pressure: Yes

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 43000
Avg Daily Amt: 43000
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: PROPANE
Storage Id: 1213808
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: EAST SIDE OF PLANT / Emptied in Apr 2011 - offline

Fid Num: SA00341
Chemical Name: PROPANE
Storage Id: 1213808
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: EAST SIDE OF PLANT / Emptied in Apr 2011 - offline

FID Num: SA00341
Chemical Id: 860432
Chemical Name: SULFURIC ACID
CAS: 7664939
Trade Secret: No
EHS: Yes
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Not reported
Reactive: Yes
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 45000
Avg Daily Amt: 30000
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF TREATMENT PLT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF TREATMENT PLT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

FID Num: SA00341
Chemical Id: 860426
Chemical Name: ANHYDROUS AMMONIA
CAS: 7664417
Trade Secret: No
EHS: Yes
Solid: Not reported
Liquid: Yes
Gas: Yes
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Yes
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 488000
Avg Daily Amt: 488000
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

FID Num: SA00341
Chemical Id: 860427
Chemical Name: CARBON DIOXIDE
CAS: 1124389
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Yes
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Yes
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 0
Avg Daily Amt: 0
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: CARBON DIOXIDE
Storage Id: 1213802

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: NORTH SIDE OF PLANT / Tank is empty, not in use

Fid Num: SA00341
Chemical Name: CARBON DIOXIDE
Storage Id: 1213802
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: NORTH SIDE OF PLANT / Tank is empty, not in use

FID Num: SA00341
Chemical Id: 860428
Chemical Name: DIESEL FUEL
CAS: Not reported
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 450000
Avg Daily Amt: 225000
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: FIRE PUMP BLDG 985

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1213803
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 2408 HEIN - 700 FT W OF GARAGE

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Storage Location: NW corner of Jumper and Centennial Roads

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: NW corner of Jumper and Centennial Roads

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: FIRE PUMP BLDG 985

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1213803
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 2408 HEIN - 700 FT W OF GARAGE

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

FID Num: SA00341
Chemical Id: 860429
Chemical Name: ETHYLENE GLYCOL
CAS: 107211
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 30000
Avg Daily Amt: 25000
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1289638
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF PLANT CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S SIDE OF PLANT CP-4

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

FID Num: SA00341
Chemical Id: 860431
Chemical Name: PROPANE
CAS: 74986
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Yes
Pure: Yes
Mix: Not reported
Fire: Yes
Pressure: Yes
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 43000
Avg Daily Amt: 43000
Days On Site: 365

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: PROPANE
Storage Id: 1213808
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: EAST SIDE OF PLANT / Emptied in Apr 2011 - offline

Fid Num: SA00341
Chemical Name: PROPANE
Storage Id: 1213808
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: EAST SIDE OF PLANT / Emptied in Apr 2011 - offline

FID Num: SA00341
Chemical Id: 860432
Chemical Name: SULFURIC ACID
CAS: 7664939
Trade Secret: No
EHS: Yes
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Not reported
Reactive: Yes
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 45000
Avg Daily Amt: 30000
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF TREATMENT PLT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF TREATMENT PLT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

FID Num: SA00341

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Chemical Id:	860426
Chemical Name:	ANHYDROUS AMMONIA
CAS:	7664417
Trade Secret:	No
EHS:	Yes
Solid:	Not reported
Liquid:	Yes
Gas:	Yes
Pure:	Yes
Mix:	Not reported
Fire:	Not reported
Pressure:	Yes
Reactive:	Not reported
Delayed:	Not reported
Immediate:	Yes
Max Daily Amt:	488000
Avg Daily Amt:	488000
Days On Site:	365
Opt Report:	Not reported

Storage:

Fid Num:	SA00341
Chemical Name:	ANHYDROUS AMMONIA
Storage Id:	1213801
Container:	Above Ground Tank
Pressure:	Greater than ambient pressure
Temperature:	Ambient temperature
Storage Location:	S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num:	SA00341
Chemical Name:	ANHYDROUS AMMONIA
Storage Id:	1213801
Container:	Above Ground Tank
Pressure:	G
Temperature:	A
Storage Location:	S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num:	SA00341
Chemical Name:	ANHYDROUS AMMONIA
Storage Id:	1213801
Container:	Above Ground Tank
Pressure:	G
Temperature:	A
Storage Location:	S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num:	SA00341
Chemical Name:	ANHYDROUS AMMONIA
Storage Id:	1213801
Container:	Above Ground Tank
Pressure:	G
Temperature:	A
Storage Location:	S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num:	SA00341
Chemical Name:	ANHYDROUS AMMONIA
Storage Id:	1213801
Container:	Above Ground Tank
Pressure:	Greater than ambient pressure

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

FID Num: SA00341
Chemical Id: 860429
Chemical Name: ETHYLENE GLYCOL
CAS: 107211
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 30000
Avg Daily Amt: 25000
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1289638
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF PLANT CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S SIDE OF PLANT CP-4

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

FID Num:	SA00341
Chemical Id:	860426
Chemical Name:	ANHYDROUS AMMONIA
CAS:	7664417
Trade Secret:	No
EHS:	Yes
Solid:	Not reported
Liquid:	Yes
Gas:	Yes
Pure:	Yes
Mix:	Not reported
Fire:	Not reported
Pressure:	Yes
Reactive:	Not reported
Delayed:	Not reported
Immediate:	Yes
Max Daily Amt:	488000
Avg Daily Amt:	488000
Days On Site:	365
Opt Report:	Not reported

Storage:

Fid Num:	SA00341
Chemical Name:	ANHYDROUS AMMONIA
Storage Id:	1213801
Container:	Above Ground Tank
Pressure:	Greater than ambient pressure
Temperature:	Ambient temperature
Storage Location:	S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num:	SA00341
Chemical Name:	ANHYDROUS AMMONIA
Storage Id:	1213801
Container:	Above Ground Tank
Pressure:	G
Temperature:	A
Storage Location:	S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num:	SA00341
Chemical Name:	ANHYDROUS AMMONIA
Storage Id:	1213801
Container:	Above Ground Tank
Pressure:	G
Temperature:	A
Storage Location:	S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num:	SA00341
Chemical Name:	ANHYDROUS AMMONIA
Storage Id:	1213801
Container:	Above Ground Tank
Pressure:	G
Temperature:	A
Storage Location:	S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num:	SA00341
Chemical Name:	ANHYDROUS AMMONIA
Storage Id:	1213801
Container:	Above Ground Tank

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

FID Num: SA00341
Chemical Id: 860429
Chemical Name: ETHYLENE GLYCOL
CAS: 107211
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 30000
Avg Daily Amt: 25000
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1289638
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF PLANT CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S SIDE OF PLANT CP-4

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

FID Num:	SA00341
Chemical Id:	897701
Chemical Name:	LEAD
CAS:	7439-92-1
Trade Secret:	No
EHS:	Not reported
Solid:	Yes
Liquid:	Not reported
Gas:	Not reported
Pure:	Not reported
Mix:	Yes
Fire:	Not reported
Pressure:	Not reported
Reactive:	Not reported
Delayed:	Yes
Immediate:	Not reported
Max Daily Amt:	96531
Avg Daily Amt:	96531
Days On Site:	365
Opt Report:	Not reported

Storage:

Fid Num:	SA00341
Chemical Name:	LEAD
Storage Id:	1225642
Container:	Other
Pressure:	Ambient pressure
Temperature:	Ambient temperature
Storage Location:	FORKLIFT BATTERIES

Fid Num:	SA00341
Chemical Name:	LEAD
Storage Id:	1225642
Container:	Below Ground Tank
Pressure:	A
Temperature:	A
Storage Location:	FORKLIFTS

Fid Num:	SA00341
Chemical Name:	LEAD
Storage Id:	1225642
Container:	Below Ground Tank
Pressure:	A
Temperature:	A
Storage Location:	FORKLIFTS

Fid Num:	SA00341
Chemical Name:	LEAD
Storage Id:	1225642
Container:	Tote Bin
Pressure:	A
Temperature:	A
Storage Location:	FORKLIFT BATTERIES

Fid Num:	SA00341
Chemical Name:	LEAD
Storage Id:	1225642
Container:	Tote Bin

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

FID Num: SA00341
Chemical Id: 897702
Chemical Name: SULFURIC ACID
CAS: 7664-93-9
Trade Secret: No
EHS: Yes
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Not reported
Reactive: Yes
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 25237
Avg Daily Amt: 25237
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF TREATMENT PLT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF TREATMENT PLT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

FID Num: SA00341
Chemical Id: 860426
Chemical Name: ANHYDROUS AMMONIA
CAS: 7664417
Trade Secret: No
EHS: Yes
Solid: Not reported
Liquid: Yes
Gas: Yes
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Yes
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 488000
Avg Daily Amt: 488000
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

FID Num: SA00341
Chemical Id: 860429
Chemical Name: ETHYLENE GLYCOL
CAS: 107211
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 30000
Avg Daily Amt: 25000
Days On Site: 365
Opt Report: Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Storage:

Fid Num:	SA00341
Chemical Name:	ETHYLENE GLYCOL
Storage Id:	1213805
Container:	Above Ground Tank
Pressure:	Ambient pressure
Temperature:	Ambient temperature
Storage Location:	S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num:	SA00341
Chemical Name:	ETHYLENE GLYCOL
Storage Id:	1289638
Container:	Above Ground Tank
Pressure:	A
Temperature:	A
Storage Location:	W SIDE OF PLANT CP-2

Fid Num:	SA00341
Chemical Name:	ETHYLENE GLYCOL
Storage Id:	1213805
Container:	Above Ground Tank
Pressure:	A
Temperature:	A
Storage Location:	S SIDE OF PLANT CP-4

Fid Num:	SA00341
Chemical Name:	ETHYLENE GLYCOL
Storage Id:	1213805
Container:	Above Ground Tank
Pressure:	A
Temperature:	A
Storage Location:	S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num:	SA00341
Chemical Name:	ETHYLENE GLYCOL
Storage Id:	1213805
Container:	Above Ground Tank
Pressure:	Ambient pressure
Temperature:	Ambient temperature
Storage Location:	S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num:	SA00341
Chemical Name:	ETHYLENE GLYCOL
Storage Id:	1213805
Container:	Above Ground Tank
Pressure:	A
Temperature:	A
Storage Location:	S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num:	SA00341
Chemical Name:	ETHYLENE GLYCOL
Storage Id:	1213805
Container:	Above Ground Tank
Pressure:	A
Temperature:	A
Storage Location:	S. Side of Plant CP-4; W. Side of Plant CP-2

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

FID Num: SA00341
Chemical Id: 925105
Chemical Name: Petroleum Mineral Oil
CAS: 8042475
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Yes
Immediate: Not reported
Max Daily Amt: 209000
Avg Daily Amt: 104500
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: Petroleum Mineral Oil
Storage Id: 1280825
Container: T
Pressure: A
Temperature: A
Storage Location: Hydraulic Rooms

Fid Num: SA00341
Chemical Name: Petroleum Mineral Oil
Storage Id: 1280826
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: Refrigeration Compressors in various rooms

Fid Num: SA00341
Chemical Name: Petroleum Mineral Oil
Storage Id: 1280827
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: Transformers in various locations

Fid Num: SA00341
Chemical Name: Petroleum Mineral Oil
Storage Id: 1280828

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Container: S
Pressure: A
Temperature: A
Storage Location: Die Washing Room, Chemical storage building

Fid Num: SA00341
Chemical Name: Petroleum Mineral Oil
Storage Id: 1280829
Container: T
Pressure: A
Temperature: A
Storage Location: Chemical Storage Building

FID Num: SA00341
Chemical Id: 925773
Chemical Name: Diesel Fuel No. 2
CAS: 68476346
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 5890
Avg Daily Amt: 2945
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: Diesel Fuel No. 2
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: Inside Fire Pump Building 985

FID Num: SA00341
Chemical Id: 892648
Chemical Name: LEAD
CAS: 7439921
Trade Secret: No
EHS: Not reported
Solid: Yes
Liquid: Not reported
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Not reported
Pressure: Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Reactive: Not reported
Delayed: Yes
Immediate: Not reported
Max Daily Amt: 89698
Avg Daily Amt: 44849
Days On Site: 365
Opt Report: Not reported

Storage:

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

FID Num: SA00341
Chemical Id: 938248
Chemical Name: GLYCOL
CAS: 57-55-6
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 86811
Avg Daily Amt: 43406
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: GLYCOL
Storage Id: 1289638
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: +15 deg plate/frame

Fid Num: SA00341
Chemical Name: GLYCOL
Storage Id: 1293920
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: CP-2 Niagara glycol sys

Fid Num: SA00341
Chemical Name: GLYCOL
Storage Id: 1293921
Container: Above Ground Tank

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Pressure: A
Temperature: A
Storage Location: CP-4 Jacket glycol cool sys

Fid Num: SA00341
Chemical Name: GLYCOL
Storage Id: 1293924
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: Glycol Chillers

Fid Num: SA00341
Chemical Name: GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: Cream Yeast Glycol System

FID Num: SA00341
Chemical Id: 934208
Chemical Name: DIESEL FUEL
CAS: 68476-34-6
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 5890
Avg Daily Amt: 2945
Days On Site: 365
Opt Report: 1

Storage:

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: FIRE PUMP BLDG 985

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1213803
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 2408 HEIN - 700 FT W OF GARAGE

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: NW corner of Jumper and Centennial Roads

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: NW corner of Jumper and Centennial Roads

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: FIRE PUMP BLDG 985

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1213803
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 2408 HEIN - 700 FT W OF GARAGE

Fid Num: SA00341

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

FID Num: SA00341
Chemical Id: 934209
Chemical Name: PETROLEUM MINERAL OIL
CAS: 8042-47-5
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Yes
Immediate: Not reported
Max Daily Amt: 209000
Avg Daily Amt: 104500
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280825
Container: T
Pressure: A
Temperature: A
Storage Location: HYDRAULIC ROOMS

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280826
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: REFRIGERATION COMPRESSORS

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280827
Container: Tote Bin

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Pressure: A
Temperature: A
Storage Location: TRANSFORMERS

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280828
Container: S
Pressure: A
Temperature: A
Storage Location: DIE WASHING RM-CHEM BLDG

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280829
Container: T
Pressure: A
Temperature: A
Storage Location: CHEM STORAGE BLDG

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280825
Container: T
Pressure: A
Temperature: A
Storage Location: HYDRAULIC ROOMS

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280826
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: REFRIGERATION COMPRESSORS

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280827
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: TRANSFORMERS

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280828
Container: S
Pressure: A
Temperature: A
Storage Location: DIE WASHING RM-CHEM BLDG

Fid Num: SA00341
Chemical Name: PETROLEUM MINERAL OIL
Storage Id: 1280829
Container: T
Pressure: A

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Temperature: A
Storage Location: CHEM STORAGE BLDG

FID Num: SA00341
Chemical Id: 897700
Chemical Name: DIESEL FUEL
CAS: 68334-30-5
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 198327
Avg Daily Amt: 55531
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: FIRE PUMP BLDG 985

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1213803
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 2408 HEIN - 700 FT W OF GARAGE

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: NW corner of Jumper and Centennial Roads

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: NW corner of Jumper and Centennial Roads

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: FIRE PUMP BLDG 985

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1213803
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 2408 HEIN - 700 FT W OF GARAGE

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

FID Num:	SA00341
Chemical Id:	897701
Chemical Name:	LEAD
CAS:	7439-92-1
Trade Secret:	No
EHS:	Not reported
Solid:	Yes
Liquid:	Not reported
Gas:	Not reported
Pure:	Not reported
Mix:	Yes
Fire:	Not reported
Pressure:	Not reported
Reactive:	Not reported
Delayed:	Yes
Immediate:	Not reported
Max Daily Amt:	96531
Avg Daily Amt:	96531
Days On Site:	365
Opt Report:	Not reported

Storage:

Fid Num:	SA00341
Chemical Name:	LEAD
Storage Id:	1225642
Container:	Other
Pressure:	Ambient pressure
Temperature:	Ambient temperature
Storage Location:	FORKLIFT BATTERIES

Fid Num:	SA00341
Chemical Name:	LEAD
Storage Id:	1225642
Container:	Below Ground Tank
Pressure:	A
Temperature:	A
Storage Location:	FORKLIFTS

Fid Num:	SA00341
Chemical Name:	LEAD
Storage Id:	1225642
Container:	Below Ground Tank
Pressure:	A
Temperature:	A
Storage Location:	FORKLIFTS

Fid Num:	SA00341
Chemical Name:	LEAD
Storage Id:	1225642
Container:	Tote Bin
Pressure:	A
Temperature:	A
Storage Location:	FORKLIFT BATTERIES

Fid Num:	SA00341
Chemical Name:	LEAD
Storage Id:	1225642
Container:	Tote Bin

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

FID Num: SA00341
Chemical Id: 897702
Chemical Name: SULFURIC ACID
CAS: 7664-93-9
Trade Secret: No
EHS: Yes
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Not reported
Reactive: Yes
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 25237
Avg Daily Amt: 25237
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF TREATMENT PLT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF TREATMENT PLT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

FID Num: SA00341
Chemical Id: 860426
Chemical Name: ANHYDROUS AMMONIA
CAS: 7664417
Trade Secret: No
EHS: Yes
Solid: Not reported
Liquid: Yes
Gas: Yes
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Yes
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 488000
Avg Daily Amt: 488000
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

FID Num: SA00341
Chemical Id: 860429
Chemical Name: ETHYLENE GLYCOL
CAS: 107211
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 30000
Avg Daily Amt: 25000
Days On Site: 365
Opt Report: Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Storage:

Fid Num:	SA00341
Chemical Name:	ETHYLENE GLYCOL
Storage Id:	1213805
Container:	Above Ground Tank
Pressure:	Ambient pressure
Temperature:	Ambient temperature
Storage Location:	S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num:	SA00341
Chemical Name:	ETHYLENE GLYCOL
Storage Id:	1289638
Container:	Above Ground Tank
Pressure:	A
Temperature:	A
Storage Location:	W SIDE OF PLANT CP-2

Fid Num:	SA00341
Chemical Name:	ETHYLENE GLYCOL
Storage Id:	1213805
Container:	Above Ground Tank
Pressure:	A
Temperature:	A
Storage Location:	S SIDE OF PLANT CP-4

Fid Num:	SA00341
Chemical Name:	ETHYLENE GLYCOL
Storage Id:	1213805
Container:	Above Ground Tank
Pressure:	A
Temperature:	A
Storage Location:	S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num:	SA00341
Chemical Name:	ETHYLENE GLYCOL
Storage Id:	1213805
Container:	Above Ground Tank
Pressure:	Ambient pressure
Temperature:	Ambient temperature
Storage Location:	S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num:	SA00341
Chemical Name:	ETHYLENE GLYCOL
Storage Id:	1213805
Container:	Above Ground Tank
Pressure:	A
Temperature:	A
Storage Location:	S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num:	SA00341
Chemical Name:	ETHYLENE GLYCOL
Storage Id:	1213805
Container:	Above Ground Tank
Pressure:	A
Temperature:	A
Storage Location:	S. Side of Plant CP-4; W. Side of Plant CP-2

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

FID Num: SA00341
Chemical Id: 897700
Chemical Name: DIESEL FUEL
CAS: 68334-30-5
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 200200
Avg Daily Amt: 120357
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: FIRE PUMP BLDG 985

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1213803
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 2408 HEIN - 700 FT W OF GARAGE

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: NW corner of Jumper and Centennial Roads

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: NW corner of Jumper and Centennial Roads

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: FIRE PUMP BLDG 985

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1213803
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 2408 HEIN - 700 FT W OF GARAGE

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

FID Num: SA00341
Chemical Id: 897701
Chemical Name: LEAD
CAS: 7439-92-1
Trade Secret: No
EHS: Not reported
Solid: Yes
Liquid: Not reported
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Not reported
Pressure: Not reported
Reactive: Not reported
Delayed: Yes
Immediate: Not reported
Max Daily Amt: 96531
Avg Daily Amt: 96531
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

FID Num: SA00341
Chemical Id: 897702
Chemical Name: SULFURIC ACID
CAS: 7664-93-9
Trade Secret: No
EHS: Yes
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Not reported
Reactive: Yes
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 25237
Avg Daily Amt: 25237
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF TREATMENT PLT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF TREATMENT PLT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

FID Num: SA00341
Chemical Id: 897701
Chemical Name: LEAD
CAS: 7439-92-1
Trade Secret: No
EHS: Not reported
Solid: Yes
Liquid: Not reported
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Not reported
Pressure: Not reported
Reactive: Not reported
Delayed: Yes
Immediate: Not reported
Max Daily Amt: 96531
Avg Daily Amt: 96531
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

FID Num: SA00341
Chemical Id: 897702
Chemical Name: SULFURIC ACID
CAS: 7664-93-9
Trade Secret: No
EHS: Yes
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Not reported
Reactive: Yes
Delayed: Not reported
Immediate: Yes

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Max Daily Amt: 25237
Avg Daily Amt: 25237
Days On Site: 365
Opt Report: Not reported

Storage:

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF TREATMENT PLT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF TREATMENT PLT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

FID Num: SA00341
Chemical Id: 892648
Chemical Name: LEAD
CAS: 7439921
Trade Secret: No
EHS: Not reported
Solid: Yes
Liquid: Not reported
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Not reported
Pressure: Not reported
Reactive: Not reported
Delayed: Yes
Immediate: Not reported
Max Daily Amt: 89698
Avg Daily Amt: 44849
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

FID Num: SA00341
Chemical Id: 860426
Chemical Name: ANHYDROUS AMMONIA
CAS: 7664-41-7
Trade Secret: No
EHS: Yes
Solid: Not reported
Liquid: Yes

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Gas: Yes
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Yes
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 488000
Avg Daily Amt: 488000
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: G
Temperature: A
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

Fid Num: SA00341
Chemical Name: ANHYDROUS AMMONIA
Storage Id: 1213801
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: S & W SIDE OF PLANT CP-2 & CP-4 ENGINE RM

FID Num: SA00341
Chemical Id: 860429
Chemical Name: ETHYLENE GLYCOL
CAS: 107-21-1
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 30000
Avg Daily Amt: 25000
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1289638
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF PLANT CP-2

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S SIDE OF PLANT CP-4

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

Fid Num: SA00341
Chemical Name: ETHYLENE GLYCOL
Storage Id: 1213805
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: S. Side of Plant CP-4; W. Side of Plant CP-2

FID Num: SA00341
Chemical Id: 897700
Chemical Name: DIESEL FUEL
CAS: 68334-30-5
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 200200
Avg Daily Amt: 120357
Days On Site: 365
Opt Report: Not reported

Storage:

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: FIRE PUMP BLDG 985

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1213803
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 2408 HEIN - 700 FT W OF GARAGE

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: NW corner of Jumper and Centennial Roads

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T
Pressure: A
Temperature: A
Storage Location: NW corner of Jumper and Centennial Roads

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1259696
Container: T

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Pressure: A
Temperature: A
Storage Location: FIRE PUMP BLDG 985

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1213803
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 2408 HEIN - 700 FT W OF GARAGE

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

Fid Num: SA00341
Chemical Name: DIESEL FUEL
Storage Id: 1225619
Container: Below Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: 3140 CENTENNIAL RD

FID Num: SA00341
Chemical Id: 897701
Chemical Name: LEAD
CAS: 7439-92-1
Trade Secret: No
EHS: Not reported
Solid: Yes
Liquid: Not reported
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Not reported

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Pressure:	Not reported
Reactive:	Not reported
Delayed:	Yes
Immediate:	Not reported
Max Daily Amt:	96531
Avg Daily Amt:	96531
Days On Site:	365
Opt Report:	Not reported

Storage:

Fid Num:	SA00341
Chemical Name:	LEAD
Storage Id:	1225642
Container:	Other
Pressure:	Ambient pressure
Temperature:	Ambient temperature
Storage Location:	FORKLIFT BATTERIES

Fid Num:	SA00341
Chemical Name:	LEAD
Storage Id:	1225642
Container:	Below Ground Tank
Pressure:	A
Temperature:	A
Storage Location:	FORKLIFTS

Fid Num:	SA00341
Chemical Name:	LEAD
Storage Id:	1225642
Container:	Below Ground Tank
Pressure:	A
Temperature:	A
Storage Location:	FORKLIFTS

Fid Num:	SA00341
Chemical Name:	LEAD
Storage Id:	1225642
Container:	Tote Bin
Pressure:	A
Temperature:	A
Storage Location:	FORKLIFT BATTERIES

Fid Num:	SA00341
Chemical Name:	LEAD
Storage Id:	1225642
Container:	Tote Bin
Pressure:	A
Temperature:	A
Storage Location:	FORKLIFT BATTERIES

Fid Num:	SA00341
Chemical Name:	LEAD
Storage Id:	1225642
Container:	Tote Bin
Pressure:	A
Temperature:	A
Storage Location:	FORKLIFT BATTERIES

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: LEAD
Storage Id: 1225642
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

FID Num: SA00341
Chemical Id: 897702
Chemical Name: SULFURIC ACID
CAS: 7664-93-9
Trade Secret: No
EHS: Yes
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Yes
Mix: Not reported
Fire: Not reported
Pressure: Not reported
Reactive: Yes
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 25237
Avg Daily Amt: 25237
Days On Site: 365
Opt Report: Not reported

Storage:
Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF TREATMENT PLT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Below Ground Tank
Pressure: A
Temperature: A
Storage Location: FORKLIFTS

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: W SIDE OF TREATMENT PLT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin
Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Tote Bin

SFC GLOBAL SUPPLY CHAIN INC (Continued) **1000853724**

Pressure: A
Temperature: A
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: A
Temperature: A
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1213809
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: WEST SIDE OF TREATMENT PLANT AT EAST SIDE OF PLANT

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

Fid Num: SA00341
Chemical Name: SULFURIC ACID
Storage Id: 1225636
Container: Other
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: FORKLIFT BATTERIES

D11 **REGIONAL TRAINING SIT-MAINT** **RCRA-CESQG** **1004501209**
2750 SCANLAN **ICIS** **KS6210490060**
< 1/8 **SALINA, KS 67401** **FINDS**
1 ft. **ECHO**

Site 1 of 2 in cluster D

Relative: Lower

Actual: 1255 ft.

RCRA-CESQG:

Date form received by agency:	01/29/2018
Facility name:	REGIONAL TRAINING SITE-MAINT (RTSM)
Facility address:	2750 SCANLAN AVE SALINA, KS 67401
EPA ID:	KS6210490060
Mailing address:	2722 SW TOPEKA BLVD TOPEKA, KS 66611
Contact:	KEVIN DURKES
Contact address:	2722 SW TOPEKA BLVD TOPEKA, KS 66611
Contact country:	US
Contact telephone:	785-646-1152
Contact email:	KEVIN.L.DURKES.NFG@MAIL.MIL
EPA Region:	07
Land type:	Federal
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	KANSAS ARMY NATIONAL GUARD
Owner/operator address:	2722 SW TOPEKA BLVD TOPEKA, KS 66611
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Federal
Owner/Operator Type:	Operator
Owner/Op start date:	04/10/2002
Owner/Op end date:	Not reported

Owner/operator name:	ADJUTANT GENERAL OF KANSAS
Owner/operator address:	2722 SW TOPEKA BLVD TOPEKA, KS 66611
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported

REGIONAL TRAINING SIT-MAINT (Continued) **1004501209**

Owner/operator extension: Not reported
Legal status: Federal
Owner/Operator Type: Owner
Owner/Op start date: 04/10/2002
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/26/2017
Site name: REGIONAL TRAINING SITE-MAINT (RTSM)
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/03/2016
Site name: REGIONAL TRAINING SITE-MAINT (RTSM)
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/23/2015
Site name: REGIONAL TRAINING SITE-MAINT (RTSM)
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/21/2014
Site name: REGIONAL TRAINING SITE-MAINT (RTSM)
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/27/2013
Site name: REGIONAL TRAINING SITE-MAINT (RTSM)
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 09/14/2012
Site name: REGIONAL TRAINING SITE-MAINT (RTSM)
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/22/2012
Site name: REGIONAL TRAINING SITE-MAINT (RTSM)
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 04/10/2002
Site name: REGIONAL TRAINING SITE-MAINT
Classification: Conditionally Exempt Small Quantity Generator

REGIONAL TRAINING SIT-MAINT (Continued) **1004501209**

Date form received by agency: 12/04/1998
Site name: REGIONAL TRAINING SITE-MAINT
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D019
. Waste name: CARBON TETRACHLORIDE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE,

REGIONAL TRAINING SIT-MAINT (Continued) **1004501209**

1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U088
. Waste name: 1,2-BENZENEDICARBOXYLIC ACID, DIETHYL ESTER (OR) DIETHYL PHTHALATE

. Waste code: U103
. Waste name: DIMETHYL SULFATE (OR) SULFURIC ACID, DIMETHYL ESTER

. Waste code: U117
. Waste name: ETHANE, 1,1'-OXYBIS-(I) (OR) ETHYL ETHER (I)

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U220
. Waste name: BENZENE, METHYL- (OR) TOLUENE

. Waste code: U226
. Waste name: ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM

REGIONAL TRAINING SIT-MAINT (Continued) **1004501209**

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

. Waste code: U240
. Waste name: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/27/2013
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

ICIS:
Enforcement Action ID: 07-2000-0068
FRS ID: 110003144632
Action Name: DEPARTMENT OF THE ARMY; NATIONAL GUARD OF KANSAS
Facility Name: REGIONAL TRAINING SIT-MAINT
Facility Address: 2750 SCANLAN
SALINA, KS 67401
Enforcement Action Type: CAA 113A Admin Compliance Order (Non-Penalty)
Facility County: SALINE
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 113A
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 38.789127
Longitude in Decimal Degrees: -97.636003
Permit Type Desc: Not reported
Program System Acronym: 14564
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Facility Name: REGIONAL TRAINING SIT-MAINT
Address: 2750 SCANLAN
Tribal Indicator: N
Fed Facility: Yes
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: REGIONAL TRAINING SIT-MAINT
Address: 2750 SCANLAN
Tribal Indicator: N
Fed Facility: Yes
NAIC Code: Not reported
SIC Code: Not reported

FINDS:

Registry ID: 110003144632

Environmental Interest/Information System

REGIONAL TRAINING SIT-MAINT (Continued) **1004501209**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004501209
Registry ID:	110003144632
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003144632

C12 **TONYS PIZZA SVC INC** **RCRA-SQG** **1000470743**
3019 SCANLAN AVE **KS UST** **KSD984973958**
< 1/8 **SALINA, KS 67401** **RMP**
1 ft. **ICIS**
Site 2 of 2 in cluster C **US AIRS**
FINDS
Relative: Lower **ECHO**

Actual: 1254 ft.

RCRA-SQG:

Date form received by agency:	08/14/2018
Facility name:	TONYS PIZZA SVC INC
Facility address:	3019 SCANLAN AVE SALINA, KS 67401
EPA ID:	KSD984973958
Contact:	CHRISTOPHER WISEMAN
Contact address:	3019 SCANLAN AVE SALINA, KS 67401
Contact country:	US
Contact telephone:	785-825-1671
Telephone ext.:	62514
Contact email:	CHRISTOPHER.WISEMAN@SCHWANS.COM
EPA Region:	07
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of

TONYS PIZZA SVC INC (Continued) **1000470743**

hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	SCHWANS GLOBAL SUPPLY CHAIN INC
Owner/operator address:	3019 SCANLAN AVE
	SALINA, KS 67401
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	03/20/2006
Owner/Op end date:	Not reported

Owner/operator name:	SCHWANS GLOBAL SUPPLY CHAIN INC
Owner/operator address:	3019 SCANLAN AVE
	SALINA, KS 67401
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	03/20/2006
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/13/2017
Site name:	TONYS PIZZA SVC INC
Classification:	Small Quantity Generator

Date form received by agency:	04/04/2016
Site name:	TONYS PIZZA SVC INC
Classification:	Small Quantity Generator

TONYS PIZZA SVC INC (Continued) **1000470743**

Date form received by agency: 06/15/2015
Site name: TONYS PIZZA SVC INC
Classification: Small Quantity Generator

Date form received by agency: 04/01/2014
Site name: TONYS PIZZA SVC INC
Classification: Small Quantity Generator

Date form received by agency: 03/18/2013
Site name: TONYS PIZZA SVC INC
Classification: Small Quantity Generator

Date form received by agency: 03/26/2012
Site name: TONYS PIZZA SVC INC
Classification: Small Quantity Generator

Date form received by agency: 03/30/2011
Site name: TONYS PIZZA SVC INC
Classification: Small Quantity Generator

Date form received by agency: 03/26/2010
Site name: TONYS PIZZA SVC INC
Classification: Small Quantity Generator

Date form received by agency: 04/22/2009
Site name: TONYS PIZZA SVC INC
Classification: Small Quantity Generator

Date form received by agency: 03/31/2008
Site name: TONYS PIZZA SVC INC
Classification: Small Quantity Generator

Date form received by agency: 04/02/2007
Site name: TONYS PIZZA SVC INC
Classification: Small Quantity Generator

Date form received by agency: 04/02/2006
Site name: TONYS PIZZA SVC INC
Classification: Small Quantity Generator

Date form received by agency: 06/09/2005
Site name: TONYS PIZZA SVC INC
Classification: Small Quantity Generator

Date form received by agency: 04/12/2004
Site name: TONYS PIZZA SVC INC
Classification: Small Quantity Generator

Date form received by agency: 03/05/2003
Site name: TONYS PIZZA SVC INC
Classification: Small Quantity Generator

Date form received by agency: 05/11/2001
Site name: TONYS PIZZA SVC INC
Classification: Small Quantity Generator

Date form received by agency: 10/18/2000

TONYS PIZZA SVC INC (Continued) **1000470743**

Site name: TONYS PIZZA SVC INC
Classification: Small Quantity Generator

Date form received by agency: 04/19/1993
Site name: TONYS PIZZA SVC INC
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D023
. Waste name: O-CRESOL

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D025
. Waste name: P-CRESOL

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 01/15/2014

TONYS PIZZA SVC INC (Continued) **1000470743**

Date achieved compliance: 02/14/2014
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/15/2014
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 01/15/2014
Date achieved compliance: 01/15/2014
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/15/2014
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/15/2014
Date achieved compliance: 02/14/2014
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/15/2014
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Container Use and Management
Date violation determined: 01/15/2014
Date achieved compliance: 01/15/2014
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/15/2014
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-General Facility Standards
Date violation determined: 10/23/2007
Date achieved compliance: 12/19/2007

TONYS PIZZA SVC INC (Continued) **1000470743**

Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/23/2007
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-General Facility Standards
Date violation determined: 10/23/2007
Date achieved compliance: 12/19/2007
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/17/2007
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 10/23/2007
Date achieved compliance: 10/23/2007
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-General Facility Standards
Date violation determined: 10/23/2007
Date achieved compliance: 12/19/2007
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/20/2007
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Used Oil - Generators
Date violation determined: 10/23/2007
Date achieved compliance: 10/23/2007
Violation lead agency: State

TONYS PIZZA SVC INC (Continued) **1000470743**

Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Container Use and Management
Date violation determined: 10/23/2007
Date achieved compliance: 10/23/2007
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 01/15/2014
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 02/14/2014
Evaluation lead agency: State

Evaluation date: 01/15/2014
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Container Use and Management
Date achieved compliance: 01/15/2014
Evaluation lead agency: State

Evaluation date: 01/15/2014
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 02/14/2014
Evaluation lead agency: State

Evaluation date: 01/15/2014
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 01/15/2014
Evaluation lead agency: State

Evaluation date: 12/20/2007
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/17/2007
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported

TONYS PIZZA SVC INC (Continued) **1000470743**

Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/23/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Container Use and Management
Date achieved compliance: 10/23/2007
Evaluation lead agency: State

Evaluation date: 10/23/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-General Facility Standards
Date achieved compliance: 12/19/2007
Evaluation lead agency: State

Evaluation date: 10/23/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Used Oil - Generators
Date achieved compliance: 10/23/2007
Evaluation lead agency: State

Evaluation date: 10/23/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 10/23/2007
Evaluation lead agency: State

UST:
Facility ID: 23129
Facility 911 Address: 3019 SCANLAN
Facility 911 City: SALINA
Facility 911 State: KS
Facility 911 Zip: 67401
Date Removed: 1992-07-15 00:00:00
Capacity (Gals): 4000
Tank Internal Protection: None
24 Hour Phone Num: 785-825-1671
Tank External Protection: Painted
Piping: Other
Facility Location Method: Garmin GPS III Plus
Facility Feature: Facility Center
Facility Phone: 785-825-1671
Tank Empty: Not reported
Contact Name: James L Hilton
Contact Title: Engineering Manager
Owner ID: 27004
Owner Type: Current
Owner Name: SCHWAN'S GLOBAL %D. DYKES
Owner Address: 3019 SCANLAN AVE.
Owner City: SALINA
Owner State: KS
Owner Zip: 67401
Owner County: Not reported
Owner Phone: 785-825-1671
QTY Remaining in Tank: Not reported
Facility District: NC
Tank ID: 001
Tank Status: Permanently Out Of Use

TONYS PIZZA SVC INC (Continued) **1000470743**

Installation Year:	1985
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	071992
Material of Construction:	Steel
Petroleum Substance:	Diesel
Owner Replacement Name:	ELROY LAMPE
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.78191
Longitude:	-97.63590

RMP:

Facility ID:	1000067481
LEPC city:	Saline County Emergency Mngmt
Facility decimal latitude:	38.783611
Facility decimal longitude:	-097.635556
Is facility in county box:	T
LatLong method:	I2
LatLong description:	PU
Home page web address:	www.schwanscompany.com
Facility telephone:	7858251671
Facility email:	mike.whitlock@schwans.com
Facility DUNS #:	0
Parent's name:	SCHWANS COMPANY
Partner's name:	Not reported
Parent's DUNS #:	22865398
Partner's DUNS #:	22865398
Operator's name:	SCHWANS COMPANY
Operator's telephone:	5075323274
Operator's address:	115 W. COLLEGE DR.
Operators City,St,Zip:	MARSHALL, MN 56258
RMP implementation contact:	Paul Stachewicz
RMP contact title:	Sr. Director EHS
Emergency contact:	Wayne Holub
Emergency contact title:	PSM COORDINATOR
Emergency contact telephone:	7858251671
24 hour emergency telephone:	7854796603
Emergency contact ext/pin #:	60248
Number of full time employees:	1400
EPA ID:	67401TNYSP3019S
Facility ID provided by CEPPO:	100000123724
Is facility covered by OSHA PSM:	T
Is facility covered by EPCRA 302:	T
Is fac. covered by CAA Title V 112(2):	T
Clean air op. permit/State ID:	1690050
Last safety insp. dat:	2017-03-24 00:00:00
Inspected by:	OSHA
Is it OSHA approved with star/merit ranking:	False
Will RMP involve predictive filing:	False
Submission type:	Resubmission
RMP description:	Not reported
Facility has no accident hist. recs:	False
Foreign owner's address:	Not reported

TONYS PIZZA SVC INC (Continued) **1000470743**

Foreign owner's zip:	Not reported
Foreign owner's country:	Not reported
Claim # of employees as CBI:	False
Date RMP accepted by EPA:	2018-02-01 00:00:00
Date of error Report:	Not reported
Date RMP received:	2018-02-01 00:00:00
Does RMP contain graphics files:	False
Does RMP contain attachments:	False
Was certification letter received:	True
RMP submission method:	RMP*eSubmit
Does RMP contain CBI substantiation:	False
Does RMP contain electronic waiver:	False
Date RMP postmarked:	2018-02-01 00:00:00
Is RMP complete:	True
Date of de-registration:	Not reported
Date de-registration is effective:	Not reported
Aniversary date:	2023-02-01 00:00:00
Does RMP contain CBI data:	False
Does RMP contain unsanitized CBI version:	False
RMP version #:	1.0
FRS latitude:	38.783200000000001
FRS longitude:	-97.636189999999999
FRS Description:	PLANT ENTRANCE (GENERAL)
FRS Method:	ADDRESS MATCHING-HOUSE NUMBER

RMP:

Accident History ID:	1000052657
X:	1000067481
Accident Date:	2017-03-01 00:00:00
Accident Time:	0220
NAICS code:	31141
Accident release duration:	00303
Chemical released:	Ammonia (anhydrous)
Flammable chemical name:	Not reported
Quantity of chemical released in pounds:	168000
Percent weight of chemical released:	100
Release Event:	Spill
Release Source:	Piping
Wind speed:	15
Wind speed units:	a
Wind direction:	NW
Temperature:	39
Stability class:	D
Precipitation was present:	False
Weather was unknown:	False
Num. of on-site workers killed:	0
Num. of responders killed:	0
Num. of public deaths:	0
Num. of on-site workers injured:	0
Num. of responders injured:	0
Num. of public injured:	0
Property damage in dollars:	12600000
Num. of on-site deaths:	0
Num. of hospitalizations:	0
Num. of other medical treatments:	1
Num. of evacuated:	0
Num. of sheltered in place:	134

TONYS PIZZA SVC INC (Continued) **1000470743**

Off-site property damage in dollars: 0
Environmental damage: Kills, Water contamination
Initiating event: a
Contributing factor: Equipment failure, Process design failure
Were offsite responders notified: Notified and Responded
Changes Made: Improved equipment, Revised operating procedure, New process control, Revised ER plan
Record contains CBI data: False

RMP:
Process ID: 1000084658
NA & Industry Classification Sys.code(s): 31141
NAICS code description: Frozen Food Manufacturing
Optional facility description: REFRIGERATION
Program level: 3
Record contains CBI data: False

RMP:
Chemical name: Ammonia (anhydrous)
Process chemical qty in 100s lbs: 300000
Process flammable chemical name: Not reported

RMP:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

RMP:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

RMP:
Endpoint used: Not reported

TONYS PIZZA SVC INC (Continued) **1000470743**

LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

RMP:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported

TONYS PIZZA SVC INC (Continued) **1000470743**

Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

RMP:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 5
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

RMP:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: 10
Release rate in pounds per second: Not reported
Wind speed in meters/second: 1.5
Stability class: F
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

RMP:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported

TONYS PIZZA SVC INC (Continued) **1000470743**

Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

RMP:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported

TONYS PIZZA SVC INC (Continued) **1000470743**

Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

RMP:

ER plan:	Not reported
ER plan most recent review date:	2017-10-26 00:00:00
ER plan most recent employee training date:	2017-11-16 00:00:00
Local agency coordinating ER plan:	Saline County Emergency Response
Telephone of the coordinating local agency:	7858266511
Federal regulation:	True
OSHA 1910 120:	True
SPCC:	True
RCRA:	True
OPA 90:	False
EPCRA:	True
Other Regulations:	OSHA 29 CFR 1910.119

ICIS:

Enforcement Action ID:	KS000A0000201690005000041
FRS ID:	110000446893
Action Name:	SCHWANS GLOBAL SUPPLY CHAIN, INC. (TONYS 201690005000041
Facility Name:	SFC GLOBAL SUPPLY CHAIN, INC
Facility Address:	3019 SCANLAN AVE. SALINA, KS 67401
Enforcement Action Type:	Notice of Violation
Facility County:	SALINE
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	2038
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	38.783611
Longitude in Decimal Degrees:	-97.635556
Permit Type Desc:	Not reported
Program System Acronym:	KS0000002016900050
Facility NAICS Code:	311412
Tribal Land Code:	Not reported

Enforcement Action ID:	KS000A0000201690005000031
FRS ID:	110000446893
Action Name:	SCHWANS GLOBAL SUPPLY CHAIN, INC. (TONYS 201690005000031
Facility Name:	SFC GLOBAL SUPPLY CHAIN, INC
Facility Address:	3019 SCANLAN AVE. SALINA, KS 67401
Enforcement Action Type:	Notice of Violation
Facility County:	SALINE
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	2038
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	38.783611
Longitude in Decimal Degrees:	-97.635556

TONYS PIZZA SVC INC (Continued) **1000470743**

Permit Type Desc:	Not reported
Program System Acronym:	KS0000002016900050
Facility NAICS Code:	311412
Tribal Land Code:	Not reported
Enforcement Action ID:	KS000A0000201690005000005
FRS ID:	110000446893
Action Name:	SCHWANS GLOBAL SUPPLY CHAIN, INC. (TONYS 201690005000005
Facility Name:	SFC GLOBAL SUPPLY CHAIN, INC
Facility Address:	3019 SCANLAN AVE. SALINA, KS 67401
Enforcement Action Type:	Notice of Violation
Facility County:	SALINE
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	2038
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	38.783611
Longitude in Decimal Degrees:	-97.635556
Permit Type Desc:	Not reported
Program System Acronym:	KS0000002016900050
Facility NAICS Code:	311412
Tribal Land Code:	Not reported
Enforcement Action ID:	07-2005-0386
FRS ID:	110000446893
Action Name:	SCHWAN'S FOOD MANUFACTURING, INC
Facility Name:	SSE MANUFACTURING INCORPORATED SALINA KS PLANT
Facility Address:	3019 SCANLAN AVE. SALINA, KS 67401
Enforcement Action Type:	CAA 113D1 Action For Penalty - 112(r) Expedited Settlement Program
Facility County:	SALINE
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	113D1E
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	38.783611
Longitude in Decimal Degrees:	-97.635556
Permit Type Desc:	Not reported
Program System Acronym:	1872262
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Facility Name:	SCHWANS GLOBAL SUPPLY CHAIN, INC. (TONYS PIZZA)
Address:	3019 SCANLAN AVENUE
Tribal Indicator:	N
Fed Facility:	No
NAIC Code:	Not reported
SIC Code:	Not reported
Facility Name:	SCHWANS GLOBAL SUPPLY CHAIN, INC. (TONYS PIZZA)
Address:	3019 SCANLAN AVENUE
Tribal Indicator:	N
Fed Facility:	No

TONYS PIZZA SVC INC (Continued) **1000470743**

NAIC Code: Not reported
SIC Code: Not reported

Facility Name: SCHWANS GLOBAL SUPPLY CHAIN, INC. (TONYS PIZZA)
Address: 3019 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: SCHWANS GLOBAL SUPPLY CHAIN, INC. (TONYS PIZZA)
Address: 3019 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: SCHWANS GLOBAL SUPPLY CHAIN, INC. (TONYS PIZZA)
Address: 3019 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: SCHWANS GLOBAL SUPPLY CHAIN, INC. (TONYS PIZZA)
Address: 3019 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: SCHWANS GLOBAL SUPPLY CHAIN, INC. (TONYS PIZZA)
Address: 3019 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: SCHWANS GLOBAL SUPPLY CHAIN, INC. (TONYS PIZZA)
Address: 3019 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: SCHWANS GLOBAL SUPPLY CHAIN, INC. (TONYS PIZZA)
Address: 3019 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: SCHWANS GLOBAL SUPPLY CHAIN, INC. (TONYS PIZZA)
Address: 3019 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: SCHWANS GLOBAL SUPPLY CHAIN, INC. (TONYS PIZZA)
Address: 3019 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported

TONYS PIZZA SVC INC (Continued) **1000470743**

SIC Code: Not reported

Facility Name: SCHWANS GLOBAL SUPPLY CHAIN, INC. (TONYS PIZZA)
Address: 3019 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: SCHWANS GLOBAL SUPPLY CHAIN, INC. (TONYS PIZZA)
Address: 3019 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

US AIRS (AFS):
Envid: 1000470743
Region Code: 07
County Code: KS169
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
D and B Number: Not reported
Facility Site Name: SFC GLOBAL SUPPLY CHAIN, INC
Primary SIC Code: 2038
NAICS Code: 311412
Default Air Classification Code: MAJ
Facility Type of Ownership Code: POF
Air CMS Category Code: TVM
HPV Status: Not reported

US AIRS (AFS):
Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2014-07-23 00:00:00
Activity Status Date: 2014-09-19 13:10:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2015-09-15 00:00:00
Activity Status Date: 2015-11-24 11:23:21
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 07

TONYS PIZZA SVC INC (Continued) **1000470743**

Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2016-04-20 00:00:00
Activity Status Date: 2016-08-31 11:44:58
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2014-07-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2014-07-23 00:00:00
Activity Status Date: 2014-09-19 13:10:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2015-09-15 00:00:00
Activity Status Date: 2015-11-24 11:23:21
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

TONYS PIZZA SVC INC (Continued) **1000470743**

Activity Status:	Active
Region Code:	07
Programmatic ID:	AIR KS0000002016900050
Facility Registry ID:	110000446893
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	New Source Performance Standards
Activity Date:	2016-04-20 00:00:00
Activity Status Date:	2016-08-31 11:44:58
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	07
Programmatic ID:	AIR KS0000002016900050
Facility Registry ID:	110000446893
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	New Source Performance Standards
Activity Date:	2000-01-24 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	07
Programmatic ID:	AIR KS0000002016900050
Facility Registry ID:	110000446893
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	New Source Performance Standards
Activity Date:	2000-01-25 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	07
Programmatic ID:	AIR KS0000002016900050
Facility Registry ID:	110000446893
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	New Source Performance Standards
Activity Date:	2001-03-09 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	07
Programmatic ID:	AIR KS0000002016900050
Facility Registry ID:	110000446893
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	New Source Performance Standards
Activity Date:	2002-09-23 00:00:00

TONYS PIZZA SVC INC (Continued) **1000470743**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2003-02-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2003-09-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2004-01-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2005-03-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR

TONYS PIZZA SVC INC (Continued) **1000470743**

Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2006-08-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2007-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2008-03-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-09-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2010-06-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07

TONYS PIZZA SVC INC (Continued) **1000470743**

Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-09-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2012-08-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2014-07-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-07-23 00:00:00
Activity Status Date: 2014-09-19 13:10:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

TONYS PIZZA SVC INC (Continued) **1000470743**

Activity Status: Active

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-09-15 00:00:00
Activity Status Date: 2015-11-24 11:23:21
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-04-20 00:00:00
Activity Status Date: 2016-08-31 11:44:58
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-01-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-01-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-03-09 00:00:00

TONYS PIZZA SVC INC (Continued) **1000470743**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-09-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-02-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-09-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-01-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR

TONYS PIZZA SVC INC (Continued) **1000470743**

Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-10-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-03-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-08-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-03-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07

TONYS PIZZA SVC INC (Continued) **1000470743**

Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-09-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-06-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-09-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-08-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

TONYS PIZZA SVC INC (Continued) **1000470743**

Activity Status:	Not reported
Region Code:	07
Programmatic ID:	AIR KS0000002016900050
Facility Registry ID:	110000446893
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2014-07-23 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	07
Programmatic ID:	AIR KS0000002016900050
Facility Registry ID:	110000446893
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	Title V Permits
Activity Date:	2015-01-16 00:00:00
Activity Status Date:	2015-03-19 17:19:13
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	07
Programmatic ID:	AIR KS0000002016900050
Facility Registry ID:	110000446893
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	Title V Permits
Activity Date:	2015-07-20 00:00:00
Activity Status Date:	2015-07-20 16:47:23
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	07
Programmatic ID:	AIR KS0000002016900050
Facility Registry ID:	110000446893
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	Title V Permits
Activity Date:	2015-09-15 00:00:00
Activity Status Date:	2015-11-24 11:23:21
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	07
Programmatic ID:	AIR KS0000002016900050
Facility Registry ID:	110000446893
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	Title V Permits
Activity Date:	2016-01-19 00:00:00

TONYS PIZZA SVC INC (Continued) **1000470743**

Activity Status Date: 2016-01-20 13:03:44
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-04-20 00:00:00
Activity Status Date: 2016-08-31 11:44:58
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2002-09-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2003-02-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2003-07-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR

TONYS PIZZA SVC INC (Continued) **1000470743**

Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2004-07-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-03-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-07-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2006-07-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2006-08-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07

TONYS PIZZA SVC INC (Continued) **1000470743**

Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-07-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-03-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-07-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-07-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

TONYS PIZZA SVC INC (Continued) **1000470743**

Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-07-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-09-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-06-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-07-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-07-19 00:00:00

TONYS PIZZA SVC INC (Continued) **1000470743**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-07-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-09-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-09-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-08-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR

TONYS PIZZA SVC INC (Continued) **1000470743**

Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-08-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-08-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-07-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-07-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07

TONYS PIZZA SVC INC (Continued) **1000470743**

Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-07-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-07-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-07-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-07-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2002-08-06 00:00:00
Activity Status Date: 2002-08-06 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal

TONYS PIZZA SVC INC (Continued) **1000470743**

Activity Status: Achieved

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-09-01 00:00:00
Activity Status Date: 2009-09-01 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 07
Programmatic ID: AIR KS0000002016900050
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-08-23 00:00:00
Activity Status Date: 2012-08-23 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

US AIRS MINOR:
Envid: 1000470743
Region Code: 07
Programmatic ID: AIR KS00000020169C0015
Facility Registry ID: 110000446893
D and B Number: Not reported
Primary SIC Code: 2038
NAICS Code: 999999
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 07
Programmatic ID: AIR KS00000020169C0015
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-07-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Information Request
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS00000020169C0015
Facility Registry ID: 110000446893
Air Operating Status Code: OPR

TONYS PIZZA SVC INC (Continued) **1000470743**

Default Air Classification Code: MIN
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-02-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

US AIRS MINOR:
Envid: 1000470743
Region Code: 07
Programmatic ID: AIR KS00000020169C0015
Facility Registry ID: 110000446893
D and B Number: Not reported
Primary SIC Code: 2038
NAICS Code: 999999
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 07
Programmatic ID: AIR KS00000020169C0015
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-07-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Information Request
Activity Status: Not reported

Region Code: 07
Programmatic ID: AIR KS00000020169C0015
Facility Registry ID: 110000446893
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-02-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:

Registry ID: 110000446893

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for

TONYS PIZZA SVC INC (Continued) **1000470743**

information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

KS-FP (Kansas - Facility Profiler) is a geographically-based data warehouse site that presents information about facilities and locations of interest to the KDHE. This site has in excess of twenty environmental interest which contains information on closed facilities, completed cleanups, and past operations as well as data on current operations and activities.

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

CRITERIA AIR POLLUTANT MAJOR

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

COMPLIANCE AND EMISSIONS REPORTING

OSHA ESTABLISHMENT

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

AIR MAJOR

AIR MINOR

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA’s programs. The vision for ICIS is to replace EPA’s independent databases that contain Enforcement data with

TONYS PIZZA SVC INC (Continued) **1000470743**

a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

US EPA Risk Management Plan (RMP) database stores the risk management plans reported by companies that handle, manufacture, use, or store certain flammable or toxic substances, as required under section 112(r) of the Clean Air Act (CAA).

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000470743
Registry ID:	110000446893
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110000446893

E13 **SAA** **KS LUST U000870719**
2846 CENTENNIAL RD. **KS UST N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Site 1 of 5 in cluster E

Relative: Lower
Actual: 1245 ft.

LUST:

Facility ID:	03030
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	01/23/2002
Project Number:	U5-085-00503
Project Name:	Bldg. 495 (S &K Automotive)
Legal Desc Section:	34
Legal Desc Township:	14S
Legal Desc Range:	03W
Discover Date:	Not reported
substrels:	Not reported
Initial Ranking:	Not reported
Current Ranking:	Not reported
Facility Contact:	Ryan Rocha
Facility Phone Number:	785-827-3914
Facility Owner Identification number:	27195
Facility Owner:	Salina Airport Authority
Owner Contact Person:	Ryan Rocha
Owner Address:	3237 Arnold Ave, Salina
Owner City:	Salina
Owner State:	KS
Owner Zip Code:	67401
Owner Phone number:	785-827-3914
Contractor license number:	Not reported
Contractor phone number:	785-823-8877
Leak duration (if known):	Not reported

SAA (Continued) **U000870719**

Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Not reported
Reported By:	Howard Debauche
Reported by persons phone number:	785-827-9639
Reported by person address:	2501D Market Place, Salina, KS 67401
Ground water Impacted (yes/no):	The area consists of grayish brown silty clays.
Static groundwater level:	Not reported
Groundwater flow direction:	Not reported
District staff names:	Howard Debauche
Assessment of release:	No leaks were detected.
Contaimination assessement:	Yes
Extent of contamination impact:	None suspected.
Updated information:	There was no staining nor odor in or around the excavation. The UST had a small amount of sludge in it, which will be remediated on an abandoned runway west of the site. There was also a concrete oil/water separator removed from the same site. This is
Invoice initiated:	19921
Invoice on going:	Not reported
Invoice completetd:	19921
Release confirmed:	19921
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	19921
Cost recovery initiated by:	Responsible Party
Cost recovery completed:	19921
Cost recovery completed by:	Responsible Party
Appplication to trust fund:	Not reported

UST:

Facility ID:	03030
Facility 911 Address:	2846 CENTENNIAL RD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1991-05-15 00:00:00
Capacity (Gals):	8000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Unknown
Piping:	Unknown
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Donald Kneubuhl
Contact Title:	Operations Dir
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914

SAA (Continued) **U000870719**

QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1900
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	051991
Material of Construction:	Unknown
Petroleum Substance:	Gas (Incl Alcohol)
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.78601
Longitude:	-97.63260
Facility ID:	03030
Facility 911 Address:	2846 CENTENNIAL RD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1991-05-15 00:00:00
Capacity (Gals):	8000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Unknown
Piping:	Unknown
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Donald Kneubuhl
Contact Title:	Operations Dir
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	002
Tank Status:	Permanently Out Of Use
Installation Year:	1900
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	051991
Material of Construction:	Unknown
Petroleum Substance:	Gas (Incl Alcohol)
Owner Replacement Name:	KENNY BIEKER

SAA (Continued) **U000870719**

NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.78601
Longitude:	-97.63260

Facility ID:	03030
Facility 911 Address:	2846 CENTENNIAL RD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1991-05-15 00:00:00
Capacity (Gals):	4000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Unknown
Piping:	Unknown
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Donald Kneubuhl
Contact Title:	Operations Dir
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	003
Tank Status:	Permanently Out Of Use
Installation Year:	1900
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	051991
Material of Construction:	Unknown
Petroleum Substance:	Diesel
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.78601
Longitude:	-97.63260

F14 **AFK SOC** **KS LUST** **U000196090**
1605 W. SCHILLING ROAD **KS UST** **N/A**
< 1/8 **SALINA, KS 67401** **KS Financial Assurance**
1 ft.

Site 1 of 4 in cluster F

Relative: **Lower**

Actual: **1243 ft.**

LUST:

Facility ID:	04652
Site Status:	**Monitor**
Release Date:	Not reported
Initial Report Date:	03/04/2015
Project Number:	U5-085-14787
Project Name:	AFK SOC
Legal Desc Section:	02
Legal Desc Township:	15S
Legal Desc Range:	03W
Discover Date:	07/02/2015
substrels:	Gasoline
Initial Ranking:	40
Current Ranking:	40.00000
Facility Contact:	CAROL HERBER
Facility Phone Number:	785-827-9383
Facility Owner Identification number:	Not reported
Facility Owner:	AFK Properties LLC
Owner Contact Person:	Patrick Wallerius
Owner Address:	PO Box 1160
Owner City:	SALINA
Owner State:	KS
Owner Zip Code:	67402-1160
Owner Phone number:	785-827-9383
Contractor license number:	04652
Contractor phone number:	785-263-3472
Leak duration (if known):	Not reported
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Unknown
Reported By:	Scott Lang
Reported by persons phone number:	785-827-9639
Reported by person address:	Not reported
Ground water Impacted (yes/no):	Silty clay to groundwater @ 14'.
Static groundwater level:	14
Groundwater flow direction:	Eas
District staff names:	Scott Lang
Assessment of release:	Petroleum contamination was found in sand and soils below the tanks and in the east and south sidewalls. No tests were performed on the north and west walls as they were very unstable and kept caving off.
Contaimination assessement:	This is the only known source in the near vicinity.
Extent of contamination impact:	Undetermined, highly suspected as soil was severely contaminated and groundwater is shallow. Dry creek is just to the east of this property so depth to groundwater may be variable depending on creek flow.
Updated information:	Property owner applied to the Property Redevelopment Trust Fund. BTLA will be updated after tank removal. July, 2015 - See attached copies of nearby well logs from the KGS website for local groundwater depth and logs. The lines and pump islands were r
Invoice initiated:	20154
Invoice on going:	Not reported
Invoice completetd:	20154
Release confirmed:	20154
Emergencty contact:	Not reported

AFK SOC (Continued) **U000196090**

Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	20162
Cost recovery initiated by:	Responsible Party
Cost recovery completed:	Not reported
Cost recovery completed by:	Not reported
Appplication to trust fund:	20154

UST:

Facility ID:	04652
Facility 911 Address:	1605 W. SCHILLING ROAD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	2015-07-02 00:00:00
Capacity (Gals):	11750
Tank Internal Protection:	None
24 Hour Phone Num:	Not reported
Tank External Protection:	Painted
Piping:	Other
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	Not reported
Tank Empty:	Not reported
Contact Name:	PATRICK WALLERIUS
Contact Title:	CONTACT PERSON
Owner ID:	04652
Owner Type:	Current, Private Or Corp.
Owner Name:	AFK PROPERTIES, LLC
Owner Address:	P.O. BOX 1160
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67402
Owner County:	SALINE
Owner Phone:	Not reported
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1982
Last Permit Printed:	2013-06-18 00:00:00
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	07/02/
Material of Construction:	Steel
Petroleum Substance:	Gas Ethanol E-10
Owner Replacement Name:	PATRICK WALLERIUS
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.78323
Longitude:	-97.63196

Facility ID:	04652
Facility 911 Address:	1605 W. SCHILLING ROAD
Facility 911 City:	SALINA

AFK SOC (Continued) **U000196090**

Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	2015-07-02 00:00:00
Capacity (Gals):	11750
Tank Internal Protection:	None
24 Hour Phone Num:	Not reported
Tank External Protection:	Painted
Piping:	Other
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	Not reported
Tank Empty:	Not reported
Contact Name:	PATRICK WALLERIUS
Contact Title:	CONTACT PERSON
Owner ID:	04652
Owner Type:	Current, Private Or Corp.
Owner Name:	AFK PROPERTIES, LLC
Owner Address:	P.O. BOX 1160
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67402
Owner County:	SALINE
Owner Phone:	Not reported
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	002
Tank Status:	Permanently Out Of Use
Installation Year:	1982
Last Permit Printed:	2013-06-18 00:00:00
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	07/02/
Material of Construction:	Steel
Petroleum Substance:	Gas Unleaded Regular
Owner Replacement Name:	PATRICK WALLERIUS
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.78323
Longitude:	-97.63196

Facility ID:	04652
Facility 911 Address:	1605 W. SCHILLING ROAD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	2015-07-02 00:00:00
Capacity (Gals):	6000
Tank Internal Protection:	None
24 Hour Phone Num:	Not reported
Tank External Protection:	Painted
Piping:	Other
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	Not reported
Tank Empty:	Not reported

AFK SOC (Continued) **U000196090**

Contact Name:	PATRICK WALLERIUS
Contact Title:	CONTACT PERSON
Owner ID:	04652
Owner Type:	Current, Private Or Corp.
Owner Name:	AFK PROPERTIES, LLC
Owner Address:	P.O. BOX 1160
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67402
Owner County:	SALINE
Owner Phone:	Not reported
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	003
Tank Status:	Permanently Out Of Use
Installation Year:	1982
Last Permit Printed:	2013-06-18 00:00:00
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	07/02/
Material of Construction:	Steel
Petroleum Substance:	Diesel Clear
Owner Replacement Name:	PATRICK WALLERIUS
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	68476-34-6
Latitude:	38.78323
Longitude:	-97.63196

Facility ID:	04652
Facility 911 Address:	1605 W. SCHILLING ROAD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	2015-07-02 00:00:00
Capacity (Gals):	6000
Tank Internal Protection:	None
24 Hour Phone Num:	Not reported
Tank External Protection:	Painted
Piping:	Other
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	Not reported
Tank Empty:	Not reported
Contact Name:	PATRICK WALLERIUS
Contact Title:	CONTACT PERSON
Owner ID:	04652
Owner Type:	Current, Private Or Corp.
Owner Name:	AFK PROPERTIES, LLC
Owner Address:	P.O. BOX 1160
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67402
Owner County:	SALINE
Owner Phone:	Not reported
QTY Remaining in Tank:	Not reported

AFK SOC (Continued) **U000196090**

Facility District:	NC
Tank ID:	004
Tank Status:	Permanently Out Of Use
Installation Year:	1982
Last Permit Printed:	2013-06-18 00:00:00
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	07/02/
Material of Construction:	Steel
Petroleum Substance:	Gas Unleaded Premium
Owner Replacement Name:	PATRICK WALLERIUS
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.78323
Longitude:	-97.63196

KS Financial Assurance:

Facility ID:	04652
Financial Responsibility:	3rd Party Liability Insurance
Facility ID:	04652
Financial Responsibility:	3rd Party Liability Insurance
Facility ID:	04652
Financial Responsibility:	3rd Party Liability Insurance
Facility ID:	04652
Financial Responsibility:	3rd Party Liability Insurance

G15 **SALINA WASTE SYSTEMS INC** **RCRA-CESQG** **1000618579**
1848 SUMMERS **FINDS** **KSD984996850**
< 1/8 **SALINA, KS 67401** **ECHO**
1 ft.

Site 1 of 2 in cluster G

Relative: Higher
Actual: 1257 ft.

RCRA-CESQG:

Date form received by agency:	01/22/2003
Facility name:	SALINA WASTE SYS INC
Facility address:	1848 SUMMERS SALINA, KS 67401
EPA ID:	KSD984996850
Mailing address:	SUMMERS SALINA, KS 67401
Contact:	JOE PETERA
Contact address:	1848 SUMMERS SALINA, KS 67401
Contact country:	US
Contact telephone:	785-825-9155
Contact email:	Not reported
EPA Region:	07
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous

SALINA WASTE SYSTEMS INC (Continued) **1000618579**

waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	GLEN STROER
Owner/operator address:	1848 SUMMERS RD SALINA, KS 67401
Owner/operator country:	Not reported
Owner/operator telephone:	785-825-9155
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	WASTE CONNECTIONS INC
Owner/operator address:	IRON POINT CIR, SUITE 2OO FOLSOM, CA 95630
Owner/operator country:	US
Owner/operator telephone:	916-608-8200
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/22/2003
Owner/Op end date:	Not reported

Owner/operator name:	WASTE CONNECTIIONS INC
Owner/operator address:	IRON POINT CIR, SUITE 2OO FOLSOM, CA 95630
Owner/operator country:	US
Owner/operator telephone:	916-608-8200
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/22/2003
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No

SALINA WASTE SYSTEMS INC (Continued) **1000618579**

Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	11/01/1991
Site name:	SALINA WASTE SYS INC
Classification:	Small Quantity Generator

Hazardous Waste Summary:

. Waste code:	D001
. Waste name:	IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110003193446

Environmental Interest/Information System

KS-FP (Kansas - Facility Profiler) is a geographically-based data warehouse site that presents information about facilities and locations of interest to the KDHE. This site has in excess of twenty environmental interest which contains information on closed facilities, completed cleanups, and past operations as well as data on current operations and activities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

SALINA WASTE SYSTEMS INC (Continued) **1000618579**

ECHO:
Envid: 1000618579
Registry ID: 110003193446
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003193446

E16 **S & K AUTOMOTIVE** **EDR Hist Auto** **1020132123**
2846 CENTENNIAL RD **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Site 2 of 5 in cluster E

Relative: EDR Hist Auto
Lower

Actual:
1245 ft.

Year:	Name:	Type:
1987	S & K AUTOMOTIVE	Gasoline Service Stations
1988	S & K AUTOMOTIVE	Gasoline Service Stations
1989	S & K AUTOMOTIVE	Gasoline Service Stations
1990	S & K AUTOMOTIVE	Gasoline Service Stations
1991	S & K AUTOMOTIVE	Gasoline Service Stations
1992	S & K AUTOMOTIVE	Gasoline Service Stations
1993	S & K AUTOMOTIVE	Gasoline Service Stations
1994	S & K AUTOMOTIVE	Gasoline Service Stations
1995	S & K AUTOMOTIVE	Gasoline Service Stations
1996	S & K AUTOMOTIVE	Gasoline Service Stations
1997	S & K AUTOMOTIVE	Gasoline Service Stations
1998	S & K AUTOMOTIVE INC	Gasoline Service Stations
1999	S & K AUTOMOTIVE INC	Gasoline Service Stations
2000	S & K AUTOMOTIVE INC	Gasoline Service Stations

E17 **SALINA AIRPORT AUTH** **RCRA NonGen / NLR** **1007094405**
2846 CENTENNIAL RD **KSP000000945**
< 1/8 **SALINA, KS 67401**
1 ft.

Site 3 of 5 in cluster E

Relative: RCRA NonGen / NLR:
Lower
Date form received by agency: 01/28/2002

Actual:
1245 ft.

Facility name:	SALINA AIRPORT AUTH
Facility address:	2846 CENTENNIAL RD SALINA, KS 67401
EPA ID:	KSP000000945
Mailing address:	ARNOLD AVE SALINA, KS 67401
Contact:	Not reported
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	07
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No

SALINA AIRPORT AUTH (Continued) **1007094405**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 12/19/2001
Site name: SALINA AIRPORT AUTH
Classification: Not a generator, verified

Date form received by agency: 10/19/2001
Site name: SALINA AIRPORT AUTH
Classification: Not a generator, verified

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

SALINA AIRPORT AUTH (Continued) **1007094405**

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

D18 **SCHILLING FAM HOUSG SITE** **FUDS** **1024898533**
N/A

< 1/8 **SALINA, KS**
1 ft.

Site 2 of 2 in cluster D

Relative: FUDS:
Higher
Actual: EPA Region: 7
1257 ft. Installation ID: KS79799F031500
Congressional District Number: 1
Facility Name: SCHILLING FAM HOUSG SITE
FUDS Number: B07KS0271
City: SALINA
State: KS
County: SALINE
Telephone: 816-389-3072
USACE Division: Northwestern Division (NWD)
USACE District: Kansas City District (NWK)
Status: Properties without projects
Current Owner: Local Government; Private Sector
X Coord: -97.636944440133107
Y Coord: 38.7886111096159
Latitude: 38.788611109999998
Longitude: -97.636944439999994

---

19 **OVATION CABINETRY INC** **RCRA NonGen / NLR** **1004705361**
2804 ARNOLD **FINDS** **KSR000001792**
< 1/8 **SALINA, KS 67401** **ECHO**
1 ft.

RCRA NonGen / NLR:
Relative: Date form received by agency: 07/18/2002
Higher Facility name: OVATION CABINETRY INC
Actual: Facility address: 2804 ARNOLD
1260 ft. SALINA, KS 67401
EPA ID: KSR000001792
Mailing address: ARNOLD
SALINA, KS 67401
Contact: Not reported
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 07
Classification: Non-Generator

OVATION CABINETRY INC (Continued) **1004705361**

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: L SEIM, B GRAY, D GOODEN
Owner/operator address: 2804 ARNOLD
SALINA, KS 67401
Owner/operator country: Not reported
Owner/operator telephone: 785-452-9000
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/07/1995
Site name: OVATION CABINETRY INC
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL

OVATION CABINETRY INC (Continued) **1004705361**

BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

Violation Status: No violations found

FINDS:

Registry ID: 110003204602

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1004705361
Registry ID: 110003204602
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003204602

H20 **KOSS CONSTRUCTION CO** **KS AST** **A100053345**
2782A ARNOLD RD **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Site 1 of 5 in cluster H

Relative: Higher
Actual: 1260 ft.

AST:

Facility ID: 40076
Facility 911 Address: 2782A ARNOLD RD
Facility 911 City: SALINA
Facility 911 State: KS
Facility 911 Zip: 67401
Date Removed: 1995-12-15 00:00:00
Capacity (Gals): 10000
Tank Internal Protection: Not reported
24 Hour Phone Num: Not reported
Tank External Protection: Not reported
Piping: Not reported
Facility Location Method: Mapblast
Facility Feature: Facility Center

KOSS CONSTRUCTION CO (Continued) **A100053345**

Facility Phone:	Not reported
Tank Empty:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Owner ID:	00094
Owner Type:	Private Or Corp.
Owner Name:	KOSS CONSTRUCTION COMPANY
Owner Address:	5830 SW DRURY LANE
Owner City:	TOPEKA
Owner State:	KS
Owner Zip:	66604
Owner County:	Not reported
Owner Phone:	785-228-2928
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1900
Last Permit Printed:	1995-02-22 00:00:00
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	121995
Material of Construction:	Not reported
Petroleum Substance:	Empty
Owner Replacement Name:	BECKY HARMON
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Contact Person
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.78820
Longitude:	-97.64038

---

21 **SALINA CITY LANDFILL** **KS SHWS** **S104959504**
RT 3 & BURMA RD. **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Relative: **Lower**
Actual: **1250 ft.**

SHWS:

Site ID:	1591
Has Env Use Control:	No
Project code:	C508500036
PM Name:	TRANSFERRED
Site Status:	**Transferred out of the bureau**
District Office:	NCDO
Lat/Long:	38.76198 / -97.69624
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	KSD980632004
Discovery Date:	Not reported
Depth To GW:	21-30 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	S
Acres Affected:	Not reported
Waste Present:	No

SALINA CITY LANDFILL (Continued) **S104959504**

Product Present:	No
Program:	Landfill
Lead Agency:	BER - Assessment and Restoration
Contaminants:	VOC
Media Act:	Ground Water
Media Pot:	Ground Water
Source:	Not reported
Land Use:	Other (see Site Narrative)
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SALINE COUNTY LANDFILL
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Transfer Out of Bureau
Activity Status:	Completed
Activity Start Date:	Not reported
Activity End Date:	10/01/1997
Narrative:	Municipally operated landfill since 1976. Waste types reported to include phenol, mercury, cadmium, potentially other organics and heavy metals. City performed monitoring study, preliminary assessment in 1988. Continue monitoring, no additional action taken since then (11/90). City has contracted with engineering consultant for complete evaluation of facility. The investigation will lead to decision to upgrade facility to meet RCRA subtitle D statutes as active facility or will close under RCRA subtitle D. Review the engineering report and make recommendations to BWM when they repermit landfill (2/93). Subtitle D compliance date met. Quarterly background sampling began 10-9-94. Assessment monitoring program required. (10/97) Site being overseen by the Bureau of Waste Management (BWM). For more information contact BWM.

---

22 **SALINA AIRPORT AUTHORITY V** **US BROWNFIELDS** **1015867667**
BERSCHEL AVE **FINDS** **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

US BROWNFIELDS:

Relative: **Lower**
Actual: **1247 ft.**

Name:	SALINA AIRPORT AUTHORITY V
Address:	BERSCHEL AVE
City,State,Zip:	SALINA, KS 67401
Recipient Name:	Kansas Department of Health and Environment
Grant Type:	Section 128(a) State/Tribal
Property Number:	Not reported
Parcel size:	9.5
Latitude:	38.7925
Longitude:	-97.6351
HCM Label:	Address Matching-House Number
Map Scale:	Not reported

SALINA AIRPORT AUTHORITY V (Continued) **1015867667**

Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	137223
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2300
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	98726203
Start Date:	06/06/2011 00:00:00
Ownership Entity:	Government
Completion Date:	06/30/2011 00:00:00
Current Owner:	Salina Airport Authority
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported

SALINA AIRPORT AUTHORITY V (Continued) **1015867667**

Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Y
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	9.5
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	9.5
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported

SALINA AIRPORT AUTHORITY V (Continued) **1015867667**

Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Airforce base operations, including storage of ASTs
Below Poverty Number:	162
Below Poverty Percent:	20.3%
Meidan Income:	1738
Meidan Income Number:	336
Meidan Income Percent:	42.2%
Vacant Housing Number:	20
Vacant Housing Percent:	6.7%
Unemployed Number:	24
Unemployed Percent:	3.0%

Name:	SALINA AIRPORT AUTHORITY V
Address:	BERSCHEL AVE
City,State,Zip:	SALINA, KS 67401
Recipient Name:	Kansas Department of Health and Environment
Grant Type:	Section 128(a) State/Tribal
Property Number:	Not reported
Parcel size:	9.5
Latitude:	38.7925
Longitude:	-97.6351
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	137223
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	5741
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	98726204
Start Date:	07/20/2011 00:00:00
Ownership Entity:	Government
Completion Date:	12/12/2011 00:00:00
Current Owner:	Salina Airport Authority
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U

SALINA AIRPORT AUTHORITY V (Continued) **1015867667**

IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Y
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	9.5
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	9.5
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported

SALINA AIRPORT AUTHORITY V (Continued) **1015867667**

Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Airforce base operations, including storage of ASTs
Below Poverty Number:	162
Below Poverty Percent:	20.3%
Meidan Income:	1738
Meidan Income Number:	336
Meidan Income Percent:	42.2%
Vacant Housing Number:	20
Vacant Housing Percent:	6.7%
Unemployed Number:	24
Unemployed Percent:	3.0%

FINDS:

Registry ID: 110046425392

Environmental Interest/Information System

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

B23 **SALINA AIRPORT AUTHORITY VII BTA** **KS SHWS** **S116381150**
2734 ARNOLD COURT BUILDING 509 **KS BROWNFIELDS** **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Site 2 of 4 in cluster B

Relative: SHWS:
Higher

Actual:
1260 ft.

Site ID:	3040
Has Env Use Control:	No
Project code:	C508573089
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.78984 / -97.64114
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	5-25 acres
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	01/09/2014
Activity End Date:	02/24/2014
Narrative:	The Kansas Department of Health and Environment (KDHE) has completed a Phase I Brownfields Targeted Assessment (BTA) at 2734 Arnold Court in Salina, Saline County, Kansas. The BTA was conducted for the Salina Airport Authority who plans to lease the building. Based on the Phase I report, no ?Recognized Environmental Conditions? (RECs) were identified on the property. The Phase I report did, however, identify a contaminant plume at the nearby Schilling AFB site, which has the potential to migrate overtime. Therefore, it is recommended

SALINA AIRPORT AUTHORITY VII BTA (Continued) **S116381150**

that preventative measures (such as restricting groundwater use) are considered prior to future usage of the property in order to limit exposure to contaminated groundwater. A Phase II assessment is not recommended at this time and the property is cleared for redevelopment.

Site ID:	3040
Has Env Use Control:	No
Project code:	C508573089
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.78984 / -97.64114
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	5-25 acres
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	01/09/2014
Activity End Date:	02/24/2014
Narrative:	The Kansas Department of Health and Environment (KDHE) has completed a Phase I Brownfields Targeted Assessment (BTA) at 2734 Arnold Court in Salina, Saline County, Kansas. The BTA was conducted for the Salina Airport Authority who plans to lease the building. Based on the Phase I report, no ?Recognized Environmental Conditions? (RECs) were identified on the property. The Phase I report did, however, identify a contaminant plume at the nearby Schilling AFB site, which

SALINA AIRPORT AUTHORITY VII BTA (Continued) **S116381150**

has the potential to migrate overtime. Therefore, it is recommended that preventative measures (such as restricting groundwater use) are considered prior to future usage of the property in order to limit exposure to contaminated groundwater. A Phase II assessment is not recommended at this time and the property is cleared for redevelopment.

BROWNFIELDS:

Site ID:	3040
Project code:	C508573089
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
Lat/Long:	38.78984 / -97.64114
Program:	Brownfields

H24 **SLN ATCT** **KS AST** **A100271043**
2000 KNEUBUHL COURT **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Site 2 of 5 in cluster H

Relative: **Higher**
Actual: **1260 ft.**

AST:

Facility ID:	44040
Facility 911 Address:	2000 KNEUBUHL COURT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	2000
Tank Internal Protection:	Not reported
24 Hour Phone Num:	620-662-4851
Tank External Protection:	Not reported
Piping:	Other
Facility Location Method:	GARMIN 3 PLUS
Facility Feature:	FACILITY CENTER
Facility Phone:	620-662-4851
Tank Empty:	Not reported
Contact Name:	DAVID BRONKE
Contact Title:	SCC MANAGER
Owner ID:	23364
Owner Type:	Current
Owner Name:	FAA-%NICHOLE KOELLING
Owner Address:	280 S. ROGERS RD., STE. 2
Owner City:	OLATHE
Owner State:	KS
Owner Zip:	66062
Owner County:	JOHNSON
Owner Phone:	913-254-8610
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Current In Use
Installation Year:	2002
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-11 00:00:00
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported

SLN ATCT (Continued) **A100271043**

Material of Construction: Double Wall
Petroleum Substance: Diesel
Owner Replacement Name: CHRISTOPHER HOGUNIN
NonPetroleum Substance: Not reported
Owner Replacement Title: CONTACT PERSON
Hazards: Fire
Principal CERCLA Substance/Chem Abstract Service Num: 68476-34-6
Latitude: 38.87719
Longitude: -97.64140

H25 **MID KANSAS REBUILDERS** **RCRA NonGen / NLR** **1004704858**
2775 ARNOLD STE G **FINDS** **KSD985001403**
< 1/8 **SALINA, KS 67401** **ECHO**
1 ft.

Site 3 of 5 in cluster H

Relative: Higher
Actual: 1261 ft.

RCRA NonGen / NLR:
Date form received by agency: 09/25/1996
Facility name: MID KANSAS REBUILDERS
Facility address: 2775 ARNOLD STE G
SALINA, KS 67401
EPA ID: KSD985001403
Mailing address: ARNOLD STE G
SALINA, KS 67401
Contact: PAUL SEEHAFER
Contact address: 2775 ARNOLD STE G
SALINA, KS 67401
Contact country: US
Contact telephone: 785-827-8554
Contact email: Not reported
EPA Region: 07
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: SALINA AIRPORT AUTHORITY
Owner/operator address: 3237 ARNOLD AVE
SALINA, KS 67401
Owner/operator country: Not reported
Owner/operator telephone: 785-827-3914
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No

MID KANSAS REBUILDERS (Continued) **1004704858**

Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date:	09/24/1996
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State

FINDS:

Registry ID: 110003195836

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

MID KANSAS REBUILDERS (Continued) **1004704858**

ECHO:
Envid: 1004704858
Registry ID: 110003195836
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003195836

H26 **FEDERAL EXPRESS** **RCRA NonGen / NLR** **1004703041**
2770 ARNOLD **FINDS** **KSD187297064**
< 1/8 **SALINA, KS 67401** **ECHO**
1 ft.

Site 4 of 5 in cluster H

Relative: Higher
Actual: 1260 ft.

RCRA NonGen / NLR:
Date form received by agency: 06/18/1990
Facility name: FEDERAL EXPRESS
Facility address: 2770 ARNOLD
SALINA, KS 67401
EPA ID: KSD187297064
Mailing address: ARNOLD
SALINA, KS 67401
Contact: STAN MCDONALD
Contact address: 2770 ARNOLD
SALINA, KS 67401
Contact country: US
Contact telephone: 785-823-1807
Contact email: Not reported
EPA Region: 07
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: SALINA AP IND CENTER
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No

FEDERAL EXPRESS (Continued) **1004703041**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110003167206

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004703041
Registry ID: 110003167206
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003167206

H27 **BLUE BEACON INTERNATIONAL** **KS LUST** **S101836968**
2770 ARNOLD **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Site 5 of 5 in cluster H

Relative: Higher
Actual: 1260 ft.

LUST:
Facility ID: 27155
Site Status: **Closed**
Release Date: Not reported
Initial Report Date: 05/27/1994
Project Number: U5-085-00869
Project Name: Blue Beacon Intern'l
Legal Desc Section: 34
Legal Desc Township: 14S
Legal Desc Range: 03W
Discover Date: Not reported
substrels: Not reported
Initial Ranking: Not reported
Current Ranking: Not reported
Facility Contact: Morie Soderberg
Facility Phone Number: 785-825-2221
Facility Owner Identification number: 27155
Facility Owner: Blue Beacon International
Owner Contact Person: Morrie Soderberg

BLUE BEACON INTERNATIONAL (Continued) **S101836968**

Owner Address:	P.o. Box 856, 500 Graves Blvd
Owner City:	Salina
Owner State:	KS
Owner Zip Code:	67401
Owner Phone number:	785-825-2221
Contractor license number:	C0035
Contractor phone number:	785-825-2221
Leak duration (if known):	Not reported
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Not reported
Reported By:	Not reported
Reported by persons phone number:	Not reported
Reported by person address:	Not reported
Ground water Impacted (yes/no):	the area consists primarily of grayish brown silty clays.
Static groundwater level:	010
Groundwater flow direction:	Not reported
District staff names:	Howard Debauche
Assessment of release:	no leaks detected. no staining nor odor in or around excavtanks appeared in good condition. lines ran under building, so not possible to remove them; however, had been tightness-tested w/in last year, & trench area exposed showed no evidence contm
Contaimination assessement:	no leaks were detected
Extent of contamination impact:	none suspected.
Updated information:	Not reported
Invoice initiated:	19943
Invoice on going:	Not reported
Invoice completetd:	19943
Release confirmed:	Not reported
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	Not reported
Cost recovery initiated by:	Not reported
Cost recovery completed:	Not reported
Cost recovery completed by:	Not reported
Appplication to trust fund:	Not reported

F28 **SCHILLING AFB OU2** **KS SHWS** **S108047987**
N/A

< 1/8
1 ft.

SALINA, KS

Site 2 of 4 in cluster F

Relative:
Lower

Actual:
1250 ft.

SHWS:

Site ID:	2127
Has Env Use Control:	No
Project code:	C508572185
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.78353 / -97.63184
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported

SCHILLING AFB OU2 (Continued) **S108047987**

Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	NE
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Inorganic, SVOC, VOC, PCB
Media Act:	Ground Water, Soil
Media Pot:	Air, Indoor, Air, Outdoor
Source:	Facility Operations
Land Use:	Agricultural, Industrial, Residential
Private well:	Domestic, Lawn and Garden
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Human, Wildlife
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING OU2
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Baseline Risk Assessment
Activity Status:	Completed
Activity Start Date:	03/18/2015
Activity End Date:	03/23/2017
Narrative:	As part of the 2005 Remedial Investigation, Schilling AFB was broken into 3 Operable Units (OUs) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. For information prior to 2005, please refer to the Schilling AFB (parent site) file. OU 2 occupies approximately 520 acres in the southeast portion of th e former Schilling AFB, south of General Jim Road and east of Taxiway A(2). KDHE/BER has reviewed and submitted comments to USACE on a draft Rem edial Investigation/Feasibility Study Work Plan for OU 2. In Summer 2007, USACE stopped work at the site in preparation of an anticipated settlement with local entities in Salina. In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Schilling AFB Site; including OU2. A vapor intrustion (VI) assessment was initiated in February 2015 and will continue through the summer of 2015. The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent FS. For additional information regarding site activities peformed after 2012 please refer to the Schilling AFB parent site; C5-085-03013.
Site ID:	2127

SCHILLING AFB OU2 (Continued) **S108047987**

Has Env Use Control:	No
Project code:	C508572185
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.78353 / -97.63184
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	NE
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Inorganic, SVOC, VOC, PCB
Media Act:	Ground Water, Soil
Media Pot:	Air, Indoor, Air, Outdoor
Source:	Facility Operations
Land Use:	Agricultural, Industrial, Residential
Private well:	Domestic, Lawn and Garden
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Human, Wildlife
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING OU2
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Baseline Risk Assessment
Activity Status:	Completed
Activity Start Date:	03/18/2015
Activity End Date:	03/23/2017
Narrative:	As part of the 2005 Remedial Investigation, Schilling AFB was broken into 3 Operable Units (OUs) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. For information prior to 2005, please refer to the Schilling AFB (parent site) file. OU 2 occupies approximately 520 acres in the southeast portion of th e former Schilling AFB, south of General Jim Road and east of Taxiway A(2). KDHE/BER has reviewed and submitted comments to USACE on a draft Rem edial Investigation/Feasibility Study Work Plan for OU 2. In Summer 2007, USACE stopped work at the site in preparation of an anticipated settlement with local entities in Salina. In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University)

SCHILLING AFB OU2 (Continued) **S108047987**

negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Schilling AFB Site; including OU2. A vapor intrustion (VI) assessment was initiated in February 2015 and will continue through the summer of 2015.
The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent FS. For additional information regarding site activities peformed after 2012 please refer to the Schilling AFB parent site; C5-085-03013.

Site ID:	2127
Has Env Use Control:	No
Project code:	C508572185
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.78353 / -97.63184
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	NE
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Inorganic, SVOC, VOC, PCB
Media Act:	Ground Water, Soil
Media Pot:	Air, Indoor, Air, Outdoor
Source:	Facility Operations
Land Use:	Agricultural, Industrial, Residential
Private well:	Domestic, Lawn and Garden
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Human, Wildlife
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING OU2
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Baseline Risk Assessment
Activity Status:	Completed
Activity Start Date:	03/18/2015
Activity End Date:	03/23/2017
Narrative:	As part of the 2005 Remedial Investigation, Schilling AFB was broken into 3 Operable Units (OUs) based on level of contamination and

SCHILLING AFB OU2 (Continued) **S108047987**

highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. For information prior to 2005, please refer to the Schilling AFB (parent site) file.

OU 2 occupies approximately 520 acres in the southeast portion of th e former Schilling AFB, south of General Jim Road and east of Taxiway A(2).

KDHE/BER has reviewed and submitted comments to USACE on a draft Rem edial Investigation/Feasibility Study Work Plan for OU 2. In Summer 2007, USACE stopped work at the site in preparation of an anticipated settlement with local entities in Salina. In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Schilling AFB Site; including OU2. A vapor intrustion (VI) assessment was initiated in February 2015 and will continue through the summer of 2015.

The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent FS. For additional information regarding site activities peformed after 2012 please refer to the Schilling AFB parent site; C5-085-03013.

Site ID:	2127
Has Env Use Control:	No
Project code:	C508572185
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.78353 / -97.63184
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	NE
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Inorganic, SVOC, VOC, PCB
Media Act:	Ground Water, Soil
Media Pot:	Air, Indoor, Air, Outdoor
Source:	Facility Operations
Land Use:	Agricultural, Industrial, Residential
Private well:	Domestic, Lawn and Garden
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Human, Wildlife
Remed Air:	Not reported

SCHILLING AFB OU2 (Continued) **S108047987**

Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING OU2
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Baseline Risk Assessment
Activity Status:	Completed
Activity Start Date:	03/18/2015
Activity End Date:	03/23/2017
Narrative:	As part of the 2005 Remedial Investigation, Schilling AFB was broken into 3 Operable Units (OUs) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. For information prior to 2005, please refer to the Schilling AFB (parent site) file. OU 2 occupies approximately 520 acres in the southeast portion of th e former Schilling AFB, south of General Jim Road and east of Taxiway A(2). KDHE/BER has reviewed and submitted comments to USACE on a draft Rem edial Investigation/Feasibility Study Work Plan for OU 2. In Summer 2007, USACE stopped work at the site in preparation of an anticipated settlement with local entities in Salina. In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Schilling AFB Site; including OU2. A vapor intrustion (VI) assessment was initiated in February 2015 and will continue through the summer of 2015. The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent FS. For additional information regarding site activities peformed after 2012 please refer to the Schilling AFB parent site; C5-085-03013.
Site ID:	2127
Has Env Use Control:	No
Project code:	C508572185
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.78353 / -97.63184
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	NE
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	State Cooperative

SCHILLING AFB OU2 (Continued) **S108047987**

Lead Agency:	BER - Remedial
Contaminants:	Inorganic, SVOC, VOC, PCB
Media Act:	Ground Water, Soil
Media Pot:	Air, Indoor, Air, Outdoor
Source:	Facility Operations
Land Use:	Agricultural, Industrial, Residential
Private well:	Domestic, Lawn and Garden
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Human, Wildlife
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING OU2
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Baseline Risk Assessment
Activity Status:	Completed
Activity Start Date:	03/18/2015
Activity End Date:	03/23/2017
Narrative:	As part of the 2005 Remedial Investigation, Schilling AFB was broken into 3 Operable Units (OUs) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. For information prior to 2005, please refer to the Schilling AFB (parent site) file. OU 2 occupies approximately 520 acres in the southeast portion of th e former Schilling AFB, south of General Jim Road and east of Taxiway A(2). KDHE/BER has reviewed and submitted comments to USACE on a draft Rem edial Investigation/Feasibility Study Work Plan for OU 2. In Summer 2007, USACE stopped work at the site in preparation of an anticipated settlement with local entities in Salina. In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Schilling AFB Site; including OU2. A vapor intrustion (VI) assessment was initiated in February 2015 and will continue through the summer of 2015. The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent FS. For additional information regarding site activities peformed after 2012 please refer to the Schilling AFB parent site; C5-085-03013.
Site ID:	2127
Has Env Use Control:	No
Project code:	C508572185
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.78353 / -97.63184
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington

SCHILLING AFB OU2 (Continued) **S108047987**

Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	NE
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Inorganic, SVOC, VOC, PCB
Media Act:	Ground Water, Soil
Media Pot:	Air, Indoor, Air, Outdoor
Source:	Facility Operations
Land Use:	Agricultural, Industrial, Residential
Private well:	Domestic, Lawn and Garden
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Human, Wildlife
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING OU2
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Baseline Risk Assessment
Activity Status:	Completed
Activity Start Date:	03/18/2015
Activity End Date:	03/23/2017
Narrative:	As part of the 2005 Remedial Investigation, Schilling AFB was broken into 3 Operable Units (OUs) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. For information prior to 2005, please refer to the Schilling AFB (parent site) file. OU 2 occupies approximately 520 acres in the southeast portion of th e former Schilling AFB, south of General Jim Road and east of Taxiway A(2). KDHE/BER has reviewed and submitted comments to USACE on a draft Rem edial Investigation/Feasibility Study Work Plan for OU 2. In Summer 2007, USACE stopped work at the site in preparation of an anticipated settlement with local entities in Salina. In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Schilling AFB Site; including OU2. A vapor intrustion (VI) assessment was initiated in February 2015 and will continue through the summer of 2015. The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent FS. For additional information regarding site activities peformed after 2012 please refer to the

SCHILLING AFB OU2 (Continued) **S108047987**

Schilling AFB parent site; C5-085-03013.

I29 **LANDES OIL CO INC** **EDR Hist Auto** **1022256371**
2948 ARNOLD **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Site 1 of 6 in cluster I

Relative: EDR Hist Auto
Higher

Actual: Year: Name: Type:
1260 ft. 1982 LANDES OIL CO INC Petroleum Bulk Stations And Terminals
1983 LANDES OIL CO INC Petroleum Bulk Stations And Terminals

F30 **DIVERSIFIED NEON** **RCRA NonGen / NLR** **1004704779**
3037 S CENTENNIAL **FINDS** **KSD984997502**
< 1/8 **SALINA, KS 67401** **ECHO**
1 ft.

Site 3 of 4 in cluster F

Relative: RCRA NonGen / NLR:
Lower
Date form received by agency: 03/15/2011
Actual: Facility name: DIVERSIFIED NEON
1242 ft. Facility address: 3037 S CENTENNIAL
SALINA, KS 67401
EPA ID: KSD984997502
Mailing address: S CENTENNIAL
SALINA, KS 67401
Contact: CRAIG WALKER
Contact address: 3037 S CENTENNIAL
SALINA, KS 67401
Contact country: US
Contact telephone: 785-823-1715
Contact email: Not reported
EPA Region: 07
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: DIVERSIFIED NEON
Owner/operator address: 3037 CENTENNIAL RD
SALINA, KS 67401
Owner/operator country: Not reported
Owner/operator telephone: 785-823-1715
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

DIVERSIFIED NEON (Continued) **1004704779**

Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	11/25/1991
Site name:	DIVERSIFIED NEON
Classification:	Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code:	D001
. Waste name:	IGNITABLE WASTE
. Waste code:	F003
. Waste name:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
. Waste code:	F005
. Waste name:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Violation Status:	No violations found

Evaluation Action Summary:

Evaluation date:	03/08/2011
Evaluation:	FOCUSED COMPLIANCE INSPECTION
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	EPA

FINDS:

DIVERSIFIED NEON (Continued) **1004704779**

Registry ID: 110003193785

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004704779
Registry ID: 110003193785
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003193785

---

31 **NICKELL BARRACKS TRAINING CTR** **KS LUST** **1000907920**
1844 JUMPER **KS UST** **KS0000225151**
< 1/8 **SALINA, KS 67401** **RCRA NonGen / NLR**
1 ft. **FINDS**
ECHO

Relative: Lower
Actual: 1251 ft.

LUST:
Facility ID: 27460
Site Status: **Closed**
Release Date: Not reported
Initial Report Date: 06/29/1993
Project Number: U5-085-00810
Project Name: KANG, Firing Range
Legal Desc Section: 14
Legal Desc Township: 15S
Legal Desc Range: 04W
Discover Date: 06/29/1993
substrels: diesel fuel
Initial Ranking: Not reported
Current Ranking: Not reported
Facility Contact: Cornelius Vandermott
Facility Phone Number: 785-825-0203
Facility Owner Identification number: 27438
Facility Owner: Kansas Army National Guard
Owner Contact Person: Sam Mryyan
Owner Address: 131 Sw 27th
Owner City: Topeka
Owner State: KS
Owner Zip Code: 66611
Owner Phone number: 785-266-1147
Contractor license number: C0143
Contractor phone number: 785-825-7297
Leak duration (if known): Not reported
Quantity released (if known): Not reported
Quantity recorded: Not reported
Leak Type: Other
Reported By: Howard Debauche
Reported by persons phone number: 785-827-9639

NICKELL BARRACKS TRAINING CTR (Continued) **1000907920**

Reported by person address:	2501-d Market Place
Ground water Impacted (yes/no):	the area consists primarily of dark grayish brown silty clays, underlain by a reddish brown clay. some groundwater was present on the clay, but was seasonal due to heavy spring rains.
Static groundwater level:	0
Groundwater flow direction:	Not reported
District staff names:	Howard Debauche
Assessment of release:	there were two excav, which will be referrred to as e & w. both had water present. the e excav showed no evidence of contam. the w excav had some product on top of water. water was pumped out with a sump pump. site closed
Contaimination assessement:	yes
Extent of contamination impact:	the small amount of water present in the excavation was pumped out, and the contam material was removed and landfarmed on site. true grounwater contam is not suspected.
Updated information:	Not reported
Invoice initiated:	19934
Invoice on going:	Not reported
Invoice completetd:	19934
Release confirmed:	19934
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	19934
Cost recovery initiated by:	Responsible Party
Cost recovery completed:	19934
Cost recovery completed by:	Responsible Party
Appplication to trust fund:	Not reported
Facility ID:	27460
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	12/19/1995
Project Number:	U5-085-10790
Project Name:	Nickell Barracks Trng Ct
Legal Desc Section:	03
Legal Desc Township:	15S
Legal Desc Range:	03W
Discover Date:	12/07/1995
substrels:	gasoline/diesel
Initial Ranking:	Not reported
Current Ranking:	Not reported
Facility Contact:	Sam Mryyan
Facility Phone Number:	785-274-1154
Facility Owner Identification number:	27438
Facility Owner:	Adjutant General's Dept
Owner Contact Person:	Sam Mryyan
Owner Address:	2800 S. Topeka Blvd
Owner City:	Topeka
Owner State:	KS
Owner Zip Code:	66611
Owner Phone number:	785-274-1154
Contractor license number:	C0077
Contractor phone number:	785-582-5190
Leak duration (if known):	Not reported
Quantity released (if known):	Not reported
Quantity recorded:	Not reported

NICKELL BARRACKS TRAINING CTR (Continued) **1000907920**

Leak Type:	Other
Reported By:	Howard Debauche
Reported by persons phone number:	Not reported
Reported by person address:	Ncdo
Ground water Impacted (yes/no):	grayish brown silty clay to 10 ft, where it changes to a brown clay. gw was encountered.
Static groundwater level:	010
Groundwater flow direction:	Not reported
District staff names:	Howard Debauche
Assessment of release:	2 usts removed. staining/odor present in fill material ~ the ust. excavated to 12 ft. at this depth, a brown clay present = had no stain nor odor present.
Contaimination assessement:	yes
Extent of contamination impact:	gw contam appears to be minimal
Updated information:	07/00: site reexcavated & contam. soil taken to abandoned runway for remediation. water entering excav. showed no contam. status updated from hold to closed. Site closed by district staff in June, 2007.
Invoice initiated:	19962
Invoice on going:	Not reported
Invoice completetd:	19962
Release confirmed:	19962
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	20073
Cost recovery initiated by:	Responsible Party
Cost recovery completed:	20073
Cost recovery completed by:	Responsible Party
Appplication to trust fund:	Not reported

UST:

Facility ID:	27460
Facility 911 Address:	1844 JUMPER ROAD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1995-12-15 00:00:00
Capacity (Gals):	6000
Tank Internal Protection:	None
24 Hour Phone Num:	785-825-0203
Tank External Protection:	Painted
Piping:	Unknown
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-825-0203
Tank Empty:	Not reported
Contact Name:	Cornelius Vandermott
Contact Title:	Facility Manager
Owner ID:	27438
Owner Type:	Current
Owner Name:	ADJUTANT GENERAL'S - ATTN:DPW-
Owner Address:	2722 SW TOPEKA BLVD
Owner City:	TOPEKA
Owner State:	KS
Owner Zip:	66611
Owner County:	SHAWNEE
Owner Phone:	785-274-1154

NICKELL BARRACKS TRAINING CTR (Continued) **1000907920**

QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	002
Tank Status:	Permanently Out Of Use
Installation Year:	1976
Last Permit Printed:	1995-10-02 00:00:00
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	121995
Material of Construction:	Steel
Petroleum Substance:	Gas (Incl Alcohol)
Owner Replacement Name:	SAM MRYYAN
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.78301
Longitude:	-97.63810
Facility ID:	27460
Facility 911 Address:	1844 JUMPER ROAD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1995-12-15 00:00:00
Capacity (Gals):	2000
Tank Internal Protection:	None
24 Hour Phone Num:	785-825-0203
Tank External Protection:	Painted
Piping:	Unknown
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-825-0203
Tank Empty:	Not reported
Contact Name:	Cornelius Vandermott
Contact Title:	Facility Manager
Owner ID:	27438
Owner Type:	Current
Owner Name:	ADJUTANT GENERAL'S - ATTN:DPW-
Owner Address:	2722 SW TOPEKA BLVD
Owner City:	TOPEKA
Owner State:	KS
Owner Zip:	66611
Owner County:	SHAWNEE
Owner Phone:	785-274-1154
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	003
Tank Status:	Permanently Out Of Use
Installation Year:	1976
Last Permit Printed:	1995-10-02 00:00:00
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	121995
Material of Construction:	Steel
Petroleum Substance:	Diesel
Owner Replacement Name:	SAM MRYYAN

NICKELL BARRACKS TRAINING CTR (Continued) **1000907920**

NonPetroleum Substance: Not reported
Owner Replacement Title: Not reported
Hazards: Not reported
Principal CERCLA Substance/Chem Abstract Service Num: Not reported
Latitude: 38.78301
Longitude: -97.63810

RCRA NonGen / NLR:
Date form received by agency: 05/09/2001
Facility name: NICKELL BARRACKS TRAINING CTR
Facility address: 1844 JUMPER
SALINA, KS 67401
EPA ID: KS0000225151
Mailing address: JUMPER
SALINA, KS 67401
Contact: Not reported
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 07
Land type: Federal
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/27/2001
Site name: NICKELL BARRACKS TRAINING CTR
Classification: Not a generator, verified

Date form received by agency: 07/18/1994
Site name: NICKELL BARRACKS TRAINING CTR
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001

NICKELL BARRACKS TRAINING CTR (Continued) **1000907920**

. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 04/10/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003142019

Environmental Interest/Information System

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

KS-FP (Kansas - Facility Profiler) is a geographically-based data warehouse site that presents information about facilities and locations of interest to the KDHE. This site has in excess of twenty environmental interest which contains information on closed facilities, completed cleanups, and past operations as well as data on current operations and activities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000907920
Registry ID: 110003142019
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003142019

I32 **SAA, PUMPHOUSE BLDG 305** **KS UST** **U003542201**
SALINA AIRPORT **KS AST** **N/A**
< 1/8 **SALINA, KS 67401** **KS Financial Assurance**
1 ft.

Site 2 of 6 in cluster I

Relative: Higher
Actual: 1261 ft.

UST:

Facility ID:	27196
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	25000
Tank Internal Protection:	Cat Prot
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	KENNY BIEKER OR DAVID SORELL
Contact Title:	CONTACT PERSONS
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Current In Use
Installation Year:	1956
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-07 00:00:00
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Aviation Gas
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	64741-66-8
Latitude:	38.78441
Longitude:	-97.64081

Facility ID:	27196
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	25000

SAA, PUMPHOUSE BLDG 305 (Continued) **U003542201**

Tank Internal Protection:	Cat Prot, Int Lining
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	KENNY BIEKER OR DAVID SORELL
Contact Title:	CONTACT PERSONS
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	002
Tank Status:	Current In Use
Installation Year:	1956
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-07 00:00:00
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Jet Fuel
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.78441
Longitude:	-97.64081

Facility ID:	27196
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	25000
Tank Internal Protection:	Cat Prot, Int Lining
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	KENNY BIEKER OR DAVID SORELL
Contact Title:	CONTACT PERSONS
Owner ID:	27195
Owner Type:	Private Or Corp.

SAA, PUMPHOUSE BLDG 305 (Continued) **U003542201**

Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	003
Tank Status:	Current In Use
Installation Year:	1956
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-07 00:00:00
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Jet Fuel
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.78441
Longitude:	-97.64081

Facility ID:	27196
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	25000
Tank Internal Protection:	Int Lining
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	KENNY BIEKER OR DAVID SORELL
Contact Title:	CONTACT PERSONS
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	004
Tank Status:	Current In Use
Installation Year:	1956

SAA, PUMPHOUSE BLDG 305 (Continued) **U003542201**

Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-07 00:00:00
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Jet Fuel
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.78441
Longitude:	-97.64081
Facility ID:	27196
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	25000
Tank Internal Protection:	Int Lining
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	KENNY BIEKER OR DAVID SORELL
Contact Title:	CONTACT PERSONS
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	005
Tank Status:	Temporarily Out Of Use
Installation Year:	1956
Last Permit Printed:	2007-09-11 00:00:00
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Jet Fuel
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.78441

SAA, PUMPHOUSE BLDG 305 (Continued) **U003542201**

Longitude:	-97.64081
Facility ID:	27196
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	25000
Tank Internal Protection:	Int Lining
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	KENNY BIEKER OR DAVID SORELL
Contact Title:	CONTACT PERSONS
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	006
Tank Status:	Current In Use
Installation Year:	1956
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-07 00:00:00
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Jet Fuel
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute

Principal CERCLA Substance/Chem Abstract Service Num: Not reported

Latitude:	38.78441
Longitude:	-97.64081
Facility ID:	27196
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	25000
Tank Internal Protection:	Int Lining
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot

SAA, PUMPHOUSE BLDG 305 (Continued) **U003542201**

Piping:	Cat Prot
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	KENNY BIEKER OR DAVID SORELL
Contact Title:	CONTACT PERSONS
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	007
Tank Status:	Current In Use
Installation Year:	1956
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-07 00:00:00
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Jet Fuel
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.78441
Longitude:	-97.64081

Facility ID:	27196
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	25000
Tank Internal Protection:	Int Lining
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	KENNY BIEKER OR DAVID SORELL
Contact Title:	CONTACT PERSONS
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA

SAA, PUMPHOUSE BLDG 305 (Continued) **U003542201**

Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	008
Tank Status:	Current In Use
Installation Year:	1956
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-07 00:00:00
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Jet Fuel
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute

Principal CERCLA Substance/Chem Abstract Service Num: Not reported

Latitude:	38.78441
Longitude:	-97.64081
Facility ID:	27196
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	25000
Tank Internal Protection:	Int Lining
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	KENNY BIEKER OR DAVID SORELL
Contact Title:	CONTACT PERSONS
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	009
Tank Status:	Current In Use
Installation Year:	1956
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-07 00:00:00
Facility Datum:	WGS84

SAA, PUMPHOUSE BLDG 305 (Continued) **U003542201**

Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Jet Fuel
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.78441
Longitude:	-97.64081

Facility ID:	27196
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	25000
Tank Internal Protection:	Cat Prot, Int Lining
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	KENNY BIEKER OR DAVID SORELL
Contact Title:	CONTACT PERSONS
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	010
Tank Status:	Current In Use
Installation Year:	1956
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-07 00:00:00
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Jet Fuel
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.78441
Longitude:	-97.64081

Facility ID:	27196

SAA, PUMPHOUSE BLDG 305 (Continued) **U003542201**

Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	25000
Tank Internal Protection:	Cat Prot
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	KENNY BIEKER OR DAVID SORELL
Contact Title:	CONTACT PERSONS
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	011
Tank Status:	Current In Use
Installation Year:	1956
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-07 00:00:00
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Aviation Gas
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	64741-66-8
Latitude:	38.78441
Longitude:	-97.64081

Facility ID:	27196
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	25000
Tank Internal Protection:	Cat Prot, Int Lining
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center

SAA, PUMPHOUSE BLDG 305 (Continued) **U003542201**

Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	KENNY BIEKER OR DAVID SORELL
Contact Title:	CONTACT PERSONS
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	012
Tank Status:	Current In Use
Installation Year:	1956
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-07 00:00:00
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Jet Fuel
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.78441
Longitude:	-97.64081

Facility ID:	27196
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	1000
Tank Internal Protection:	None
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Bare Steel
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	KENNY BIEKER OR DAVID SORELL
Contact Title:	CONTACT PERSONS
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE

SAA, PUMPHOUSE BLDG 305 (Continued) **U003542201**

Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	013
Tank Status:	Current In Use
Installation Year:	1956
Last Permit Printed:	2000-07-18 00:00:00
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Not reported
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.78441
Longitude:	-97.64081

AST:

Facility ID:	27196
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	1000
Tank Internal Protection:	Not reported
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Painted
Piping:	Bare Steel
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	KENNY BIEKER OR DAVID SORELL
Contact Title:	CONTACT PERSONS
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Current In Use
Installation Year:	2008
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-11 00:00:00
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Double Wall

SAA, PUMPHOUSE BLDG 305 (Continued) **U003542201**

Petroleum Substance: Aviation Gas 100 LL
Owner Replacement Name: KENNY BIEKER
NonPetroleum Substance: Not reported
Owner Replacement Title: CONTACT PERSON
Hazards: Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num: 86290-81-5
Latitude: 38.78441
Longitude: -97.64081

KS Financial Assurance:
Facility ID: 27196
Financial Responsibility: 3rd Party Liability Insurance

Facility ID: 27196
Financial Responsibility: 3rd Party Liability Insurance

Facility ID: 27196
Financial Responsibility: 3rd Party Liability Insurance

Facility ID: 27196
Financial Responsibility: 3rd Party Liability Insurance

Facility ID: 27196
Financial Responsibility: 3rd Party Liability Insurance

Facility ID: 27196
Financial Responsibility: 3rd Party Liability Insurance

Facility ID: 27196
Financial Responsibility: 3rd Party Liability Insurance

Facility ID: 27196
Financial Responsibility: 3rd Party Liability Insurance

Facility ID: 27196
Financial Responsibility: 3rd Party Liability Insurance

Facility ID: 27196
Financial Responsibility: 3rd Party Liability Insurance

Facility ID: 27196
Financial Responsibility: 3rd Party Liability Insurance

Facility ID: 27196
Financial Responsibility: 3rd Party Liability Insurance

I33 **REGIONAL TRAINING SITE-MAINT** **RCRA NonGen / NLR** **1004704443**
2931 ARNOLD (B) **ICIS** **KSD984971200**
< 1/8 **SALINA, KS 67401** **US AIRS**
1 ft.

Site 3 of 6 in cluster I

Relative: Higher

Actual: 1259 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/15/2002
Facility name:	REGIONAL TRAINING SITE-MAINT
Facility address:	2931 ARNOLD (B) SALINA, KS 67401-8124
EPA ID:	KSD984971200
Mailing address:	SCANLAN AVE SALINA, KS 67401-8124
Contact:	TOBIAS SCHROEDER
Contact address:	AGKS-DOFE-E 131 SW 27TH ST TOPEKA, KS 66611-1159
Contact country:	US
Contact telephone:	785-274-1150
Contact email:	Not reported
EPA Region:	07
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ADJUTANT GENERAL OF KANSAS
Owner/operator address:	AGKS-DOFE-E 131 SW 27TH ST TOPEKA, KS 66611
Owner/operator country:	Not reported
Owner/operator telephone:	785-274-1150
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Federal
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	12/04/1998
Site name:	REGIONAL TRAINING SITE-MAINT

REGIONAL TRAINING SITE-MAINT (Continued) **1004704443**

Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

ICIS:
Enforcement Action ID: 07-2000-A063
FRS ID: 110001240425
Action Name: KANSAS ARMY NATIONAL GUARD 20169C000900001
Facility Name: KANSAS ARMY NATIONAL GUARD
Facility Address: 2931 ARNOLD AVENUE
SALINA, KS 67401
Enforcement Action Type: CAA 113A Admin Compliance Order (Non-Penalty)
Facility County: SALINE
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 113A
Facility SIC Code: 7389
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 38.7842
Longitude in Decimal Degrees: -97.63993
Permit Type Desc: Not reported
Program System Acronym: KS00000020169C0009
Facility NAICS Code: 999999
Tribal Land Code: Not reported

US AIRS MINOR:
Envid: 1004704443
Region Code: 07
Programmatic ID: AIR KS00000020169C0009
Facility Registry ID: 110001240425
D and B Number: Not reported
Primary SIC Code: 7389
NAICS Code: 999999
Default Air Classification Code: MIN
Facility Type of Ownership Code: FDF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 07
Programmatic ID: AIR KS00000020169C0009
Facility Registry ID: 110001240425
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: Stratospheric Ozone Protection
Activity Date: 1999-12-27 00:00:00
Activity Status Date: 1999-12-27 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

REGIONAL TRAINING SITE-MAINT (Continued) **1004704443**

US AIRS MINOR:
- Envid: 1004704443
- Region Code: 07
- Programmatic ID: AIR KS00000020169C0009
- Facility Registry ID: 110001240425
- D and B Number: Not reported
- Primary SIC Code: 7389
- NAICS Code: 999999
- Default Air Classification Code: MIN
- Facility Type of Ownership Code: FDF
- Air CMS Category Code: Not reported
- HPV Status: Not reported

US AIRS MINOR:
- Region Code: 07
- Programmatic ID: AIR KS00000020169C0009
- Facility Registry ID: 110001240425
- Air Operating Status Code: OPR
- Default Air Classification Code: MIN
- Air Program: Stratospheric Ozone Protection
- Activity Date: 1999-12-27 00:00:00
- Activity Status Date: 1999-12-27 00:00:00
- Activity Group: Enforcement Action
- Activity Type: Administrative - Formal
- Activity Status: Final Order Issued

I34 **DEAN MARKLEY ELECTRONICS** **RCRA NonGen / NLR** **1004703250**
2931 ARNOLD (A) **FINDS** **KSD981119704**
< 1/8 **SALINA, KS 67401** **ECHO**
1 ft.

Site 4 of 6 in cluster I

Relative: Higher
Actual: 1259 ft.

RCRA NonGen / NLR:
- Date form received by agency: 09/10/1985
- Facility name: DEAN MARKLEY ELECTRONICS
- Facility address: 2931 ARNOLD (A)
  SALINA, KS 67401
- EPA ID: KSD981119704
- Mailing address: PO BOX 1432
  SALINA, KS 67401
- Contact: GREG FARRES
- Contact address: PO BOX 1432
  SALINA, KS 67401
- Contact country: US
- Contact telephone: 785-825-7204
- Contact email: Not reported
- EPA Region: 07
- Classification: Non-Generator
- Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
- Owner/operator name: JOHN FLINCHER
- Owner/operator address: PO BOX 1432
  SALINA, KS 67401
- Owner/operator country: Not reported
- Owner/operator telephone: 785-825-7204

DEAN MARKLEY ELECTRONICS (Continued) **1004703250**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

FINDS:

Registry ID: 110003169865

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004703250
Registry ID: 110003169865
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003169865

I35 **SALINA AIRPORT AUTHORITY VIII BTA** **KS SHWS** **S116381151**
2934 ARNOLD AVENUE BUILDING 313 **KS BROWNFIELDS** **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Site 5 of 6 in cluster I

Relative: SHWS:
Higher

Actual:
1260 ft.

Site ID:	3041
Has Env Use Control:	No
Project code:	C508573090
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.78435 / -97.64045
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	<5 acres
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	01/09/2014
Activity End Date:	02/24/2014
Narrative:	The Kansas Department of Health and Environment (KDHE) has completed a Phase I Brownfields Targeted Assessment (BTA) at 2934 Arnold Avenue in Salina, Kansas. The BTA was conducted for the Salina Airport Authority who plans to lease the building. Based on the Phase I report, no ?Recognized Environmental Conditions? (RECs) were identified on the property. The Phase I report did, however, identify a contaminant plume at the nearby Schilling AFB site, which has the potential to migrate overtime. Therefore, it is recommended that

SALINA AIRPORT AUTHORITY VIII BTA (Continued) **S116381151**

preventative measures (such as restricting groundwater use) are considered prior to future usage of the property in order to limit exposure to contaminated groundwater. A Phase II assessment is not recommended at this time and the property is cleared for redevelopment.

Site ID:	3041
Has Env Use Control:	No
Project code:	C508573090
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.78435 / -97.64045
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	<5 acres
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	01/09/2014
Activity End Date:	02/24/2014
Narrative:	The Kansas Department of Health and Environment (KDHE) has completed a Phase I Brownfields Targeted Assessment (BTA) at 2934 Arnold Avenue in Salina, Kansas. The BTA was conducted for the Salina Airport Authority who plans to lease the building. Based on the Phase I report, no ?Recognized Environmental Conditions? (RECs) were identified on the property. The Phase I report did, however, identify a contaminant plume at the nearby Schilling AFB site, which has the

SALINA AIRPORT AUTHORITY VIII BTA (Continued) **S116381151**

potential to migrate overtime. Therefore, it is recommended that preventative measures (such as restricting groundwater use) are considered prior to future usage of the property in order to limit exposure to contaminated groundwater. A Phase II assessment is not recommended at this time and the property is cleared for redevelopment.

BROWNFIELDS:

Site ID:	3041
Project code:	C508573090
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
Lat/Long:	38.78435 / -97.64045
Program:	Brownfields

I36 **SALINA AIRPORT AUTHORITY VIII** **US BROWNFIELDS** **1018164028**
2934 ARNOLD AVENUE **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Site 6 of 6 in cluster I

Relative: Higher
Actual: 1260 ft.

US BROWNFIELDS:

Name:	SALINA AIRPORT AUTHORITY VIII
Address:	2934 ARNOLD AVENUE
City,State,Zip:	SALINA, KS 67401
Recipient Name:	Kansas Department of Health and Environment
Grant Type:	Section 128(a) State/Tribal
Property Number:	Not reported
Parcel size:	.78
Latitude:	38.78441
Longitude:	-97.640473
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	169745
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1726
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	98726204
Start Date:	01/21/2014 00:00:00

SALINA AIRPORT AUTHORITY VIII (Continued) **1018164028**

Ownership Entity:	Private
Completion Date:	02/24/2014 00:00:00
Current Owner:	Salina Airport Authority
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	.78
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported

SALINA AIRPORT AUTHORITY VIII (Continued) **1018164028**

Future use residential acreage:	Not reported
Future use commercial acreage:	.78
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	1884-1954 greenspace with residential structures 1954-2012 property has commercial building like it does today. The current property owner is the Salina Airport Authority who acquired the property in 1965 from the Smoky Hill/ Schilling Air force base.
Below Poverty Number:	34
Below Poverty Percent:	20.6%
Meidan Income:	360
Meidan Income Number:	70
Meidan Income Percent:	42.4%
Vacant Housing Number:	4
Vacant Housing Percent:	6.4%
Unemployed Number:	5
Unemployed Percent:	3.0%

B37 **PORTAPORT** **RCRA NonGen / NLR** **1004702049**
2711 ARNOLD **FINDS** **KSD033560475**
< 1/8 **SALINA, KS 67401** **ECHO**
1 ft.

Site 3 of 4 in cluster B

Relative: Higher

Actual: 1259 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/17/2000
Facility name:	PORTAPORT
Facility address:	2711 ARNOLD SALINA, KS 67401
EPA ID:	KSD033560475
Mailing address:	ARNOLD SALINA, KS 67401
Contact:	ART DAVIS
Contact address:	2711 ARNOLD SALINA, KS 67401
Contact country:	US
Contact telephone:	785-825-7211
Contact email:	Not reported
EPA Region:	07
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	PORTAPORT, INC.
Owner/operator address:	2711 ARNOLD AVENUE SALINA, KS 67401
Owner/operator country:	Not reported
Owner/operator telephone:	785-825-7211
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Hazardous Waste Summary:

PORTAPORT (Continued) **1004702049**

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 07/17/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003153701

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004702049
Registry ID: 110003153701
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003153701

J38 **KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 14** **US BROWNFIELDS** **1016346834**
1732 SUMMERS ROAD **FINDS** **N/A**
< 1/8 **SALINA, KS 66740**
1 ft.

Site 1 of 4 in cluster J

Relative: **Lower**
Actual: **1251 ft.**

US BROWNFIELDS:
Name: KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 14
Address: 1732 SUMMERS ROAD
City,State,Zip: SALINA, KS 66740-1
Recipient Name: Kansas Department of Health and Environment
Grant Type: Section 128(a) State/Tribal
Property Number: 085088340401000100001 Area 4/Subsection 14
Parcel size: 1.6
Latitude: 38.78677
Longitude: -97.63334
HCM Label: Address Matching-House Number
Map Scale: Not reported
Point of Reference: Entrance Point of a Facility or Station
Highlights: Not reported
Datum: World Geodetic System of 1984
Acres Property ID: 32864
IC Data Access: Not reported
Start Date: Not reported

KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 14 (Continued) **1016346834**

Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1008
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	98726201
Start Date:	02/24/2006 00:00:00
Ownership Entity:	Government
Completion Date:	02/24/2006 00:00:00
Current Owner:	Kansas Board of Regents
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported

KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 14 (Continued) **1016346834**

PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Military Mess Hall
Below Poverty Number:	201
Below Poverty Percent:	20.3%

KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 14 (Continued) **1016346834**

Meidan Income:	2156
Meidan Income Number:	417
Meidan Income Percent:	42.2%
Vacant Housing Number:	25
Vacant Housing Percent:	6.7%
Unemployed Number:	30
Unemployed Percent:	3.0%

FINDS:

Registry ID: 110038713069

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

J39 **KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 12** **US BROWNFIELDS** **1016346832**
1732 SUMMERS ROADS **FINDS** **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Site 2 of 4 in cluster J

Relative: **Lower**
Actual: **1251 ft.**

US BROWNFIELDS:

Name:	KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 12
Address:	1732 SUMMERS ROADS
City,State,Zip:	SALINA, KS 66740-1
Recipient Name:	Kansas Department of Health and Environment
Grant Type:	Section 128(a) State/Tribal
Property Number:	085088340401000300001 Area 4/Subsection 12
Parcel size:	2.1
Latitude:	38.78677
Longitude:	-97.63334
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	32862
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1008
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA

KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 12 (Continued) **1016346832**

Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	98726201
Start Date:	02/24/2006 00:00:00
Ownership Entity:	Government
Completion Date:	02/24/2006 00:00:00
Current Owner:	Kansas Board of Regents
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported

KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 12 (Continued) **1016346832**

Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Military Mess Hall
Below Poverty Number:	201
Below Poverty Percent:	20.3%
Meidan Income:	2156
Meidan Income Number:	417
Meidan Income Percent:	42.2%
Vacant Housing Number:	25
Vacant Housing Percent:	6.7%
Unemployed Number:	30
Unemployed Percent:	3.0%

FINDS:

Registry ID: 110038713041

KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 12 (Continued) **1016346832**

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

F40 **MR GS OF KANSAS** **EDR Hist Auto** **1021160311**
1605 W SCHILLING RD **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Site 4 of 4 in cluster F

Relative: EDR Hist Auto
Lower

Actual: **1243 ft.**

Year:	Name:	Type:
2006	MR GS OF KANSAS	Convenience Stores
2007	MR GS OF KANSAS	Convenience Stores
2008	MR GS OF KANSAS	Convenience Stores
2009	MR GS OF KANSAS	Convenience Stores
2010	MR GS OF KANSAS	Convenience Stores
2011	MR GS OF KANSAS	Convenience Stores
2012	MR GS OF KANSAS	Convenience Stores
2013	MR GS OF KANSAS	Convenience Stores
2014	MR GS OF KANSAS	Convenience Stores

G41 **SALINA WASTE SYSTEMS** **KS AST** **A100287113**
1848 SUMMERS RD **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Site 2 of 2 in cluster G

Relative: AST:
Higher

Actual: **1257 ft.**

Facility ID:	44308
Facility 911 Address:	1848 SUMMERS RD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	3000
Tank Internal Protection:	Not reported
24 Hour Phone Num:	785-825-9155
Tank External Protection:	Not reported
Piping:	Bare Steel
Facility Location Method:	Not reported
Facility Feature:	Not reported
Facility Phone:	785-825-9155
Tank Empty:	Not reported
Contact Name:	NATHAN FOSTER
Contact Title:	Not reported
Owner ID:	44308
Owner Type:	Private Or Corp.
Owner Name:	SALINA WASTE SYSTEMS %R. DEBAU
Owner Address:	1848 SUMMERS RD

SALINA WASTE SYSTEMS (Continued) **A100287113**

Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-825-9155
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Current In Use
Installation Year:	1989
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-11 00:00:00
Facility Datum:	Not reported
Out of service Mo/Yr:	Not reported
Material of Construction:	Not reported
Petroleum Substance:	Diesel Clear
Owner Replacement Name:	ROBERT DeBAUN
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	68476-34-6
Latitude:	Not reported
Longitude:	Not reported

J42 **KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 11** **US BROWNFIELDS** **1016346831**
1732 SUMMERS ROAD **FINDS** **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Site 3 of 4 in cluster J

Relative: **Lower**
Actual: **1251 ft.**

US BROWNFIELDS:

Name:	KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 11
Address:	1732 SUMMERS ROAD
City,State,Zip:	SALINA, KS 66740-1
Recipient Name:	Kansas Department of Health and Environment
Grant Type:	Section 128(a) State/Tribal
Property Number:	085088340401000400001 Area 4/Subsection 11
Parcel size:	2.1
Latitude:	38.78677
Longitude:	-97.63334
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	32861
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1008
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported

KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 11 (Continued) **1016346831**

Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	98726201
Start Date:	02/24/2006 00:00:00
Ownership Entity:	Government
Completion Date:	02/24/2006 00:00:00
Current Owner:	Kansas Board of Regents
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported

KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 11 (Continued) **1016346831**

Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Military Mess Hall
Below Poverty Number:	201
Below Poverty Percent:	20.3%
Meidan Income:	2156
Meidan Income Number:	417
Meidan Income Percent:	42.2%
Vacant Housing Number:	25
Vacant Housing Percent:	6.7%
Unemployed Number:	30
Unemployed Percent:	3.0%

FINDS:

KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 11 (Continued) **1016346831**

Registry ID: 110038713032

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

E43 **SUMMERS ROAD** **SEMS** **1003073169**
INTERSECTION OF SUMMERS RD & **KSSFN0703594**
< 1/8 **SALINA, KS 67402**
1 ft.

Site 4 of 5 in cluster E

Relative: **Lower**
Actual: **1246 ft.**

SEMS:
Site ID: 0703594
EPA ID: KSSFN0703594
Cong District: 01
FIPS Code: 20169
Latitude: Not reported
Longitude: Not reported
FF: N
NPL: Not on the NPL
Non NPL Status: Addressed as Part of Another non-NPL Site

SEMS Detail:
Region: 07
Site ID: 0703594
EPA ID: KSSFN0703594
Site Name: SUMMERS ROAD
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: 2005-12-01 05:00:00
Finish Date: 12/2/2005 5:00:00 AM
Qual: B
Current Action Lead: EPA Perf

Region: 07
Site ID: 0703594
EPA ID: KSSFN0703594
Site Name: SUMMERS ROAD
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 2000-03-30 05:00:00
Finish Date: 3/30/2000 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

SUMMERS ROAD (Continued) **1003073169**

Region:	07
Site ID:	0703594
EPA ID:	KSSFN0703594
Site Name:	SUMMERS ROAD
NPL:	N
FF:	N
OU:	00
Action Code:	HX
Action Name:	PRE-CERC
SEQ:	1
Start Date:	Not reported
Finish Date:	3/30/2000 5:00:00 AM
Qual:	Not reported
Current Action Lead:	St Perf

---

44 **NICKELL BARRACKS TRAINING CENT** **KS UST** **U001112543**
RR #1, SMOKY HILL WEAPONS RANGE **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Relative:
Lower

Actual:
1254 ft.

UST:

Facility ID:	29629
Facility 911 Address:	RR #1, SMOKY HILL WEAPONS RANGE
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1993-06-15 00:00:00
Capacity (Gals):	1000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-266-1147
Tank External Protection:	None
Piping:	Unknown
Facility Location Method:	GARMIN 3 PLUS
Facility Feature:	FACILITY CENTER
Facility Phone:	785-266-1147
Tank Empty:	Not reported
Contact Name:	Sam Mryyan
Contact Title:	Environmental Office
Owner ID:	27438
Owner Type:	Current
Owner Name:	ADJUTANT GENERAL'S - ATTN:DPW-
Owner Address:	2722 SW TOPEKA BLVD
Owner City:	TOPEKA
Owner State:	KS
Owner Zip:	66611
Owner County:	SHAWNEE
Owner Phone:	785-274-1154
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1953
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	061993
Material of Construction:	Unknown

NICKELL BARRACKS TRAINING CENT (Continued) **U001112543**

Petroleum Substance:	Kerosene
Owner Replacement Name:	SAM MRYYAN
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8008-20-6
Latitude:	38.74210
Longitude:	-97.73641

Facility ID:	29629
Facility 911 Address:	RR #1, SMOKY HILL WEAPONS RANGE
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1993-06-15 00:00:00
Capacity (Gals):	1200
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-266-1147
Tank External Protection:	None
Piping:	Unknown
Facility Location Method:	GARMIN 3 PLUS
Facility Feature:	FACILITY CENTER
Facility Phone:	785-266-1147
Tank Empty:	Not reported
Contact Name:	Sam Mryyan
Contact Title:	Environmental Office
Owner ID:	27438
Owner Type:	Current
Owner Name:	ADJUTANT GENERAL'S - ATTN:DPW-
Owner Address:	2722 SW TOPEKA BLVD
Owner City:	TOPEKA
Owner State:	KS
Owner Zip:	66611
Owner County:	SHAWNEE
Owner Phone:	785-274-1154
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	002
Tank Status:	Permanently Out Of Use
Installation Year:	1953
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	061993
Material of Construction:	Unknown
Petroleum Substance:	Kerosene
Owner Replacement Name:	SAM MRYYAN
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8008-20-6
Latitude:	38.74210
Longitude:	-97.73641

J45 **KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 13** **US BROWNFIELDS** **1016346833**
1732 SUMMERS ROAD **FINDS** **N/A**
< 1/8 **SALINA, KS 67401**
1 ft.

Site 4 of 4 in cluster J

Relative: **Lower**
Actual: **1251 ft.**

US BROWNFIELDS:

Name:	KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 13
Address:	1732 SUMMERS ROAD
City,State,Zip:	SALINA, KS 66740-1
Recipient Name:	Kansas Department of Health and Environment
Grant Type:	Section 128(a) State/Tribal
Property Number:	085088340401000200001 Area 4/Subsection 13
Parcel size:	2.1
Latitude:	38.78677
Longitude:	-97.63334
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	32863
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1008
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	98726201
Start Date:	02/24/2006 00:00:00
Ownership Entity:	Government
Completion Date:	02/24/2006 00:00:00
Current Owner:	Kansas Board of Regents
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported

KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 13 (Continued) **1016346833**

Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported

KSU - SALINA REDEVELOPMENT PROJECT, SUBSECTION 13 (Continued) **1016346833**

Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Military Mess Hall
Below Poverty Number:	201
Below Poverty Percent:	20.3%
Meidan Income:	2156
Meidan Income Number:	417
Meidan Income Percent:	42.2%
Vacant Housing Number:	25
Vacant Housing Percent:	6.7%
Unemployed Number:	30
Unemployed Percent:	3.0%

FINDS:

Registry ID: 110038713050

Environmental Interest/Information System

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

E46 **SUMMERS ROAD** **KS SHWS** **S105074656**
N/A

< 1/8 **SALINA, KS 67401**
1 ft.

Site 5 of 5 in cluster E

Relative: **Lower**

Actual: **1246 ft.**

SHWS:

Site ID:	1612
Has Env Use Control:	No
Project code:	C508570765
PM Name:	TOWNSEND, M.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.78561 / -97.63274

SUMMERS ROAD (Continued) **S105074656**

River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	KSSFN0703594
Discovery Date:	12/01/1998
Depth To GW:	21-30 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	E
Acres Affected:	5-25 acres
Waste Present:	No
Product Present:	No
Program:	FUDS (Formerly Used Defense Sites)
Lead Agency:	BER - Remedial
Contaminants:	VOC
Media Act:	Ground Water
Media Pot:	Soil
Source:	Facility Operations
Land Use:	Commercial, Industrial
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SALINA AIRPORT INDUSTRIAL PARK SUMMERS ROAD SITE; SCHILLING AFB SUMMERS ROAD SITE
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Initial Site Screening
Activity Status:	Completed
Activity Start Date:	11/03/1999
Activity End Date:	11/03/1999
Narrative:	The Summers Road site is located at the Salina Airport Industrial Park in Salina, Saline County, Kansas. The Salina Airport Industrial Park was developed from the Schilling Air Force Base, which was deactivated in June 1965. In December 1998, the U.S. Army Corp of Engineers (USACE) conducted a Site Investigation at the former Air Force base in an effort to evaluate any environmental impact the former air base may have had. Among other areas of contamination from the former air base, the site investigation identified carbon tetrachloride, chloroform, trichloroethylene (TCE), and tetrachloroethylene (PCE) in ground water in the vicinity of the intersection of Summers Road and Centennial Road. Carbon tetrachloride was detected at a maximum concentration of 94.0 ?g/l, chloroform at 20.0 ?g/l, TCE at 30.0 ?g/l, and PCE at 5.0 ?g/l. USACE has indicated that it does not intend to further investigate the contamination because no military operations occurred in this area. The Kansas Department of Health and Environment (KDHE) conducted a Site Reconnaissance and Evaluation (SRE) in an effort to determine potential source areas for contamination identified at Summers Road and

SUMMERS ROAD (Continued) **S105074656**

Centennial.
A review of available water well records has identified 155 domestic wells within four miles of the site, two of which are located about one mile down-gradient of the site. No public water supply wells are located within one mile of the site. Several of Salina?s public water supply wells are located between three and four miles northeast of the
site.
A KDHE field team collected ground water samples at the site in an effort to identify the source(s) for the contamination. Samples were collected from fifteen locations at the site using a Geoprobe ground water probe and from a sump located at 1340 Centennial Road.. The water samples were submitted to the KDHE Division of Health and Environmental Laboratories (DHEL) and analyzed for volatile organic compounds (VOCs) by EPA Method 8260. The analytical reports indicate that carbon tetrachloride was detected at concentrations up to 115?g/l, chloroform up to 77.4 ?g/l, TCE up to 37 ?g/l, and PCE up to 1.6 ?g/l in the samples. Concentrations of carbon tetrachloride, and TCE are above their respective federal Safe Drinking Water Act maximum contaminant levels (MCL) of 5.0
?g/l.
The distribution of the contaminants in the local ground water indic ates that three potential areas of contamination exist. The first area consists of TCE and its daughter products cis/trans 1,2-DCE and appears to originate at an unknown source located beyond the intersection of Jumper Road and Arnold Road. The plume extends at least 3,000 feet to the northeast to Summers Road and Centennial Road. The second plume consists of carbon tetrachloride and appears to originate in the vicinity of Scanlan Avenue and Schilling Road. The source for the carbon tetrachloride appears to be the property currently occupied by Tony?s Pizza Service. This conclusion is based primarily upon the non-detection of carbon tetrachloride in sample locations up gradient of the property. Tony?s Pizza Service has reported generating quantities of carbon tetrachloride through the requirements of the Resource Conservation and Recovery Act (RCRA). A third plume consists of low levels of PCE. PCE was detected in several sample locations along Jumper Road and to the north but were not detected in sample locations up gradient of the area. This property is also owned by Tony?s Pizza Service
(Schwan?s).
Additional Information collected during an ESI by EPA indicates that the source area may be further upgradient. The site is being addressed through the Schilling AFB Site.

Site ID:	1612
Has Env Use Control:	No
Project code:	C508570765
PM Name:	TOWNSEND, M.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.78561 / -97.63274
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	KSSFN0703594

SUMMERS ROAD (Continued) **S105074656**

Discovery Date:	12/01/1998
Depth To GW:	21-30 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	E
Acres Affected:	5-25 acres
Waste Present:	No
Product Present:	No
Program:	FUDS (Formerly Used Defense Sites)
Lead Agency:	BER - Remedial
Contaminants:	VOC
Media Act:	Ground Water
Media Pot:	Soil
Source:	Facility Operations
Land Use:	Commercial, Industrial
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SALINA AIRPORT INDUSTRIAL PARK SUMMERS ROAD SITE; SCHILLING AFB SUMMERS ROAD SITE
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Initial Site Screening
Activity Status:	Completed
Activity Start Date:	11/03/1999
Activity End Date:	11/03/1999
Narrative:	The Summers Road site is located at the Salina Airport Industrial Park in Salina, Saline County, Kansas. The Salina Airport Industrial Park was developed from the Schilling Air Force Base, which was deactivated in June 1965. In December 1998, the U.S. Army Corp of Engineers (USACE) conducted a Site Investigation at the former Air Force base in an effort to evaluate any environmental impact the former air base may have had. Among other areas of contamination from the former air base, the site investigation identified carbon tetrachloride, chloroform, trichloroethylene (TCE), and tetrachloroethylene (PCE) in ground water in the vicinity of the intersection of Summers Road and Centennial Road. Carbon tetrachloride was detected at a maximum concentration of 94.0 ?g/l, chloroform at 20.0 ?g/l, TCE at 30.0 ?g/l, and PCE at 5.0 ?g/l. USACE has indicated that it does not intend to further investigate the contamination because no military operations occurred in this area. The Kansas Department of Health and Environment (KDHE) conducted a Site Reconnaissance and Evaluation (SRE) in an effort to determine potential source areas for contamination identified at Summers Road and Centennial. A review of available water well records has identified 155 domestic wells within four miles of the site, two of which are located about one mile down-gradient of the site. No public water supply wells are located within one mile of the site. Several of Salina?s public water supply wells are located between three and four miles northeast

SUMMERS ROAD (Continued) **S105074656**

of the
site.
A KDHE field team collected ground water samples at the site in an effort to identify the source(s) for the contamination. Samples were collected from fifteen locations at the site using a Geoprobe ground water probe and from a sump located at 1340 Centennial Road.. The water samples were submitted to the KDHE Division of Health and Environmental Laboratories (DHEL) and analyzed for volatile organic compounds (VOCs) by EPA Method 8260. The analytical reports indicate that carbon tetrachloride was detected at concentrations up to 115?g/l, chloroform up to 77.4 ?g/l, TCE up to 37 ?g/l, and PCE up to 1.6 ?g/l in the samples. Concentrations of carbon tetrachloride, and TCE are above their respective federal Safe Drinking Water Act maximum contaminant levels (MCL) of 5.0
?g/l.
The distribution of the contaminants in the local ground water indic ates that three potential areas of contamination exist. The first area consists of TCE and its daughter products cis/trans 1,2-DCE and appears to originate at an unknown source located beyond the intersection of Jumper Road and Arnold Road. The plume extends at least 3,000 feet to the northeast to Summers Road and Centennial Road. The second plume consists of carbon tetrachloride and appears to originate in the vicinity of Scanlan Avenue and Schilling Road. The source for the carbon tetrachloride appears to be the property currently occupied by Tony?s Pizza Service. This conclusion is based primarily upon the non-detection of carbon tetrachloride in sample locations up gradient of the property. Tony?s Pizza Service has reported generating quantities of carbon tetrachloride through the requirements of the Resource Conservation and Recovery Act (RCRA). A third plume consists of low levels of PCE. PCE was detected in several sample locations along Jumper Road and to the north but were not detected in sample locations up gradient of the area. This property is also owned by Tony?s Pizza Service (Schwan?s).
Additional Information collected during an ESI by EPA indicates that the source area may be further upgradient. The site is being addressed through the Schilling AFB Site.

Site ID:	1612
Has Env Use Control:	No
Project code:	C508570765
PM Name:	TOWNSEND, M.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.78561 / -97.63274
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	KSSFN0703594
Discovery Date:	12/01/1998
Depth To GW:	21-30 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	E
Acres Affected:	5-25 acres

SUMMERS ROAD (Continued) **S105074656**

Waste Present:	No
Product Present:	No
Program:	FUDS (Formerly Used Defense Sites)
Lead Agency:	BER - Remedial
Contaminants:	VOC
Media Act:	Ground Water
Media Pot:	Soil
Source:	Facility Operations
Land Use:	Commercial, Industrial
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SALINA AIRPORT INDUSTRIAL PARK SUMMERS ROAD SITE; SCHILLING AFB SUMMERS ROAD SITE
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Initial Site Screening
Activity Status:	Completed
Activity Start Date:	11/03/1999
Activity End Date:	11/03/1999
Narrative:	The Summers Road site is located at the Salina Airport Industrial Park in Salina, Saline County, Kansas. The Salina Airport Industrial Park was developed from the Schilling Air Force Base, which was deactivated in June 1965. In December 1998, the U.S. Army Corp of Engineers (USACE) conducted a Site Investigation at the former Air Force base in an effort to evaluate any environmental impact the former air base may have had. Among other areas of contamination from the former air base, the site investigation identified carbon tetrachloride, chloroform, trichloroethylene (TCE), and tetrachloroethylene (PCE) in ground water in the vicinity of the intersection of Summers Road and Centennial Road. Carbon tetrachloride was detected at a maximum concentration of 94.0 ?g/l, chloroform at 20.0 ?g/l, TCE at 30.0 ?g/l, and PCE at 5.0 ?g/l. USACE has indicated that it does not intend to further investigate the contamination because no military operations occurred in this area. The Kansas Department of Health and Environment (KDHE) conducted a Site Reconnaissance and Evaluation (SRE) in an effort to determine potential source areas for contamination identified at Summers Road and Centennial. A review of available water well records has identified 155 domestic wells within four miles of the site, two of which are located about one mile down-gradient of the site. No public water supply wells are located within one mile of the site. Several of Salina?s public water supply wells are located between three and four miles northeast of the site. A KDHE field team collected ground water samples at the site in an effort to identify the source(s) for the contamination. Samples were collected from fifteen locations at the site using a Geoprobe ground water probe and from a sump located at 1340 Centennial Road.. The

SUMMERS ROAD (Continued) **S105074656**

water samples were submitted to the KDHE Division of Health and Environmental Laboratories (DHEL) and analyzed for volatile organic compounds (VOCs) by EPA Method 8260. The analytical reports indicate that carbon tetrachloride was detected at concentrations up to 115?g/l, chloroform up to 77.4 ?g/l, TCE up to 37 ?g/l, and PCE up to 1.6 ?g/l in the samples. Concentrations of carbon tetrachloride, and TCE are above their respective federal Safe Drinking Water Act maximum contaminant levels (MCL) of 5.0 ?g/l.

The distribution of the contaminants in the local ground water indic ates that three potential areas of contamination exist. The first area consists of TCE and its daughter products cis/trans 1,2-DCE and appears to originate at an unknown source located beyond the intersection of Jumper Road and Arnold Road. The plume extends at least 3,000 feet to the northeast to Summers Road and Centennial Road. The second plume consists of carbon tetrachloride and appears to originate in the vicinity of Scanlan Avenue and Schilling Road. The source for the carbon tetrachloride appears to be the property currently occupied by Tony?s Pizza Service. This conclusion is based primarily upon the non-detection of carbon tetrachloride in sample locations up gradient of the property. Tony?s Pizza Service has reported generating quantities of carbon tetrachloride through the requirements of the Resource Conservation and Recovery Act (RCRA). A third plume consists of low levels of PCE. PCE was detected in several sample locations along Jumper Road and to the north but were not detected in sample locations up gradient of the area. This property is also owned by Tony?s Pizza Service (Schwan?s).

Additional Information collected during an ESI by EPA indicates that the source area may be further upgradient. The site is being addressed through the Schilling AFB Site.

K47 **SMOKY HILL ANG RANGE** **KS UST** **U000718330**
WSW **OLD OPS, 184 CES/DE BLDG 15** **N/A**
< 1/8 **SALINA, KS 67401**
0.001 mi.
6 ft. **Site 1 of 5 in cluster K**

Relative: **Higher**

Actual: **1261 ft.**

UST:

Facility ID:	28835
Facility 911 Address:	8429 W FARRELLY RD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1993-10-15 00:00:00
Capacity (Gals):	1000
Tank Internal Protection:	None
24 Hour Phone Num:	Not reported
Tank External Protection:	Unknown
Piping:	Bare Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	Not reported
Tank Empty:	Not reported
Contact Name:	James Miller
Contact Title:	Major
Owner ID:	28761
Owner Type:	State Govt.

SMOKY HILL ANG RANGE (Continued) **U000718330**

Owner Name:	KANSAS AIR NATIONAL GUARD (KAN
Owner Address:	53260 JAYHAWK DR
Owner City:	MCCONELL AFB
Owner State:	KS
Owner Zip:	67221-9009
Owner County:	SEDGWICK
Owner Phone:	316-759-7534
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1953
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	101993
Material of Construction:	Steel
Petroleum Substance:	Not reported
Owner Replacement Name:	184TH CE ENVIRONMENTAL
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.66710
Longitude:	-97.81810

K48 **SMOKY HILL ANG RANGE, BLDG 601** **KS UST** **U000874222**
WSW **BLDG 6010, 184 CES/DE BLDG 15** **N/A**
< 1/8 **SALINA, KS 67401**
0.001 mi.
6 ft. **Site 2 of 5 in cluster K**

Relative: UST:
Higher

Actual:
1261 ft.

Facility ID:	28840
Facility 911 Address:	8429 W FARRELLY RD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	674019407
Date Removed:	1993-10-15 00:00:00
Capacity (Gals):	1000
Tank Internal Protection:	None
24 Hour Phone Num:	Not reported
Tank External Protection:	None
Piping:	Bare Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	Not reported
Tank Empty:	Not reported
Contact Name:	James Miller
Contact Title:	Major
Owner ID:	28761
Owner Type:	State Govt.
Owner Name:	KANSAS AIR NATIONAL GUARD (KAN
Owner Address:	53260 JAYHAWK DR
Owner City:	MCCONELL AFB
Owner State:	KS
Owner Zip:	67221-9009
Owner County:	SEDGWICK

SMOKY HILL ANG RANGE, BLDG 601 (Continued) **U000874222**

Owner Phone:	316-759-7534
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1964
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	101993
Material of Construction:	Steel
Petroleum Substance:	Not reported
Owner Replacement Name:	184TH CE ENVIRONMENTAL
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.75020
Longitude:	-97.97120

K49 **SMOKY HILL ANG RANGE** **KS UST** **U000718334**
WSW **BLDG 6003, 184 CES/DE BLDG 15** **N/A**
< 1/8 **SALINA, KS 67401**
0.001 mi.
6 ft. **Site 3 of 5 in cluster K**

Relative: **Higher**

Actual: **1261 ft.**

UST:

Facility ID:	28839
Facility 911 Address:	8429 W FARRELLY RD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1993-10-15 00:00:00
Capacity (Gals):	500
Tank Internal Protection:	None
24 Hour Phone Num:	Not reported
Tank External Protection:	Unknown
Piping:	Bare Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	Not reported
Tank Empty:	Not reported
Contact Name:	James Miller
Contact Title:	Major
Owner ID:	28761
Owner Type:	State Govt.
Owner Name:	KANSAS AIR NATIONAL GUARD (KAN
Owner Address:	53260 JAYHAWK DR
Owner City:	MCCONELL AFB
Owner State:	KS
Owner Zip:	67221-9009
Owner County:	SEDGWICK
Owner Phone:	316-759-7534
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1964

SMOKY HILL ANG RANGE (Continued) **U000718334**

Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	101993
Material of Construction:	Steel
Petroleum Substance:	Not reported
Owner Replacement Name:	184TH CE ENVIRONMENTAL
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.75390
Longitude:	-97.79030

K50 **SMOKY HILL ANG RANGE** **KS UST** **U003193988**
WSW **BLDG 4001, 184 CES/DE BLDG 15** **N/A**
< 1/8 **SALINA, KS 67401**
0.001 mi.
6 ft. **Site 4 of 5 in cluster K**

Relative: UST:
Higher

Actual:
1261 ft.

Facility ID:	28837
Facility 911 Address:	8429 W FARRELLY ROAD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1993-10-15 00:00:00
Capacity (Gals):	1000
Tank Internal Protection:	None
24 Hour Phone Num:	Not reported
Tank External Protection:	Unknown
Piping:	Bare Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	Not reported
Tank Empty:	Not reported
Contact Name:	James Miller
Contact Title:	Major
Owner ID:	28761
Owner Type:	State Govt.
Owner Name:	KANSAS AIR NATIONAL GUARD (KAN
Owner Address:	53260 JAYHAWK DR
Owner City:	MCCONELL AFB
Owner State:	KS
Owner Zip:	67221-9009
Owner County:	SEDGWICK
Owner Phone:	316-759-7534
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1968
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	101993
Material of Construction:	Steel
Petroleum Substance:	Not reported

SMOKY HILL ANG RANGE (Continued) **U003193988**

Owner Replacement Name: 184TH CE ENVIRONMENTAL
NonPetroleum Substance: Not reported
Owner Replacement Title: Not reported
Hazards: Not reported
Principal CERCLA Substance/Chem Abstract Service Num: Not reported
Latitude: 38.70520
Longitude: -97.84620

K51 **SMOKY HILL ANG RANGE** **KS UST** **U000874221**
WSW **BLDG 6001, 184 CES/DE BLDG 15** **N/A**
< 1/8 **SALINA, KS 67401**
0.001 mi.
6 ft. **Site 5 of 5 in cluster K**

Relative:
Higher

Actual:
1261 ft.

UST:
Facility ID: 28838
Facility 911 Address: 8429 W FARRELLY RD
Facility 911 City: SALINA
Facility 911 State: KS
Facility 911 Zip: 67401
Date Removed: 1993-10-15 00:00:00
Capacity (Gals): 500
Tank Internal Protection: None
24 Hour Phone Num: Not reported
Tank External Protection: Unknown
Piping: Bare Steel
Facility Location Method: Topozone
Facility Feature: Facility Center
Facility Phone: Not reported
Tank Empty: Not reported
Contact Name: James Miller
Contact Title: Major
Owner ID: 28761
Owner Type: State Govt.
Owner Name: KANSAS AIR NATIONAL GUARD (KAN
Owner Address: 53260 JAYHAWK DR
Owner City: MCCONELL AFB
Owner State: KS
Owner Zip: 67221-9009
Owner County: SEDGWICK
Owner Phone: 316-759-7534
QTY Remaining in Tank: Not reported
Facility District: NC
Tank ID: 001
Tank Status: Permanently Out Of Use
Installation Year: 1964
Last Permit Printed: Not reported
Current Permit Printed: Not reported
Facility Datum: WGS84
Out of service Mo/Yr: 101993
Material of Construction: Steel
Petroleum Substance: Not reported
Owner Replacement Name: 184TH CE ENVIRONMENTAL
NonPetroleum Substance: Not reported
Owner Replacement Title: Not reported
Hazards: Not reported
Principal CERCLA Substance/Chem Abstract Service Num: Not reported
Latitude: 38.75440

SMOKY HILL ANG RANGE (Continued) **U000874221**

Longitude:	-97.78910
Facility ID:	28838
Facility 911 Address:	8429 W FARRELLY RD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1993-10-15 00:00:00
Capacity (Gals):	1000
Tank Internal Protection:	None
24 Hour Phone Num:	Not reported
Tank External Protection:	Unknown
Piping:	Bare Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	Not reported
Tank Empty:	Not reported
Contact Name:	James Miller
Contact Title:	Major
Owner ID:	28761
Owner Type:	State Govt.
Owner Name:	KANSAS AIR NATIONAL GUARD (KAN
Owner Address:	53260 JAYHAWK DR
Owner City:	MCCONELL AFB
Owner State:	KS
Owner Zip:	67221-9009
Owner County:	SEDGWICK
Owner Phone:	316-759-7534
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	002
Tank Status:	Permanently Out Of Use
Installation Year:	1964
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	101993
Material of Construction:	Steel
Petroleum Substance:	Not reported
Owner Replacement Name:	184TH CE ENVIRONMENTAL
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.75440
Longitude:	-97.78910
Facility ID:	28838
Facility 911 Address:	8429 W FARRELLY RD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1993-10-15 00:00:00
Capacity (Gals):	6000
Tank Internal Protection:	None
24 Hour Phone Num:	Not reported
Tank External Protection:	Unknown

SMOKY HILL ANG RANGE (Continued) **U000874221**

Piping:	Bare Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	Not reported
Tank Empty:	Not reported
Contact Name:	James Miller
Contact Title:	Major
Owner ID:	28761
Owner Type:	State Govt.
Owner Name:	KANSAS AIR NATIONAL GUARD (KAN
Owner Address:	53260 JAYHAWK DR
Owner City:	MCCONELL AFB
Owner State:	KS
Owner Zip:	67221-9009
Owner County:	SEDGWICK
Owner Phone:	316-759-7534
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	003
Tank Status:	Permanently Out Of Use
Installation Year:	1964
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	101993
Material of Construction:	Steel
Petroleum Substance:	Not reported
Owner Replacement Name:	184TH CE ENVIRONMENTAL
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.75440
Longitude:	-97.78910

B52 **FLOWER AVIATION** **KS LUST** **U003542200**
NNW **SALINA AIRPORT** **KS UST** **N/A**
< 1/8 **SALINA, KS 67401** **KS Financial Assurance**
0.029 mi.
154 ft. **Site 4 of 4 in cluster B**

Relative: **Higher**

Actual: **1259 ft.**

LUST:

Facility ID:	27195
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	07/20/1994
Project Number:	U5-085-00998
Project Name:	SAA, Pumphouse #3
Legal Desc Section:	34
Legal Desc Township:	14S
Legal Desc Range:	03W
Discover Date:	07/07/1994
substrels:	av fuels
Initial Ranking:	18
Current Ranking:	18.00000
Facility Contact:	Don Kneubuhl
Facility Phone Number:	785-827-3914
Facility Owner Identification number:	27195

FLOWER AVIATION (Continued) **U003542200**

Facility Owner:	Salina Airport Authority
Owner Contact Person:	Don Kneubuhl
Owner Address:	3237 Arnold Avenue
Owner City:	Salina
Owner State:	KS
Owner Zip Code:	67401
Owner Phone number:	785-827-3914
Contractor license number:	C0211
Contractor phone number:	800-321-5479
Leak duration (if known):	Not reported
Quantity released (if known):	Not reported
Quantity recorded:	0
Leak Type:	Spill/Overfill
Reported By:	Scott Lang
Reported by persons phone number:	785-827-9639
Reported by person address:	Ncdo
Ground water Impacted (yes/no):	topsoil > silty clay > highly weathered shale
Static groundwater level:	015
Groundwater flow direction:	ENE
District staff names:	Scott Lang
Assessment of release:	soils contam w/aviation fuels were removed. perimeters of excav <kals. water w/in excav removed and treated via air strippers & dischargedto sanitary sewer. gw recharging the excav sampled and analyzed. several vocs detected above kals. site active
Contaimination assessement:	suspect most of contam from spills/overfills.
Extent of contamination impact:	undetermiend at this time. contam has been confirmed by groundwater samples within the excav.
Updated information:	Site closed by district staff in October 2007, Update - Oct. 16, 2007 - July 07 Analytical results sampled by GeoCore and tested by CAS Labs indicate that the BTEX, and Naphthalene at the site have decreased to non-detect. Based on the analytical resul
Invoice initiated:	19944
Invoice on going:	Not reported
Invoice completetd:	19944
Release confirmed:	19944
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	19944
Cost recovery initiated by:	Responsible Party
Cost recovery completed:	20081
Cost recovery completed by:	Responsible Party
Appplication to trust fund:	Not reported
Facility ID:	27195
Site Status:	**Active**
Release Date:	Not reported
Initial Report Date:	10/28/1994
Project Number:	U5-085-01023
Project Name:	SAA
Legal Desc Section:	34
Legal Desc Township:	14S
Legal Desc Range:	03W
Discover Date:	08/22/1994
substrels:	lube oil & fuel
Initial Ranking:	26
Current Ranking:	26.00000

FLOWER AVIATION (Continued) **U003542200**

Facility Contact:	Don Kneubuhl
Facility Phone Number:	785-827-3914
Facility Owner Identification number:	27195
Facility Owner:	Salina Airport Authority
Owner Contact Person:	Don Kneubuhl
Owner Address:	3237 Arnold
Owner City:	Salina
Owner State:	KS
Owner Zip Code:	67401
Owner Phone number:	785-827-3914
Contractor license number:	C0211
Contractor phone number:	800-321-5479
Leak duration (if known):	Not reported
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Piping
Reported By:	Scott Lang
Reported by persons phone number:	Not reported
Reported by person address:	Not reported
Ground water Impacted (yes/no):	topsoil 2' > silty clay 8' > highly weathered shale.
Static groundwater level:	015
Groundwater flow direction:	ENE
District staff names:	Scott Lang
Assessment of release:	3 gasoline, 4 lube oil & 4 av gas, alcohol & aquatrap ustsremoved. soils contam w/gasoline & lube oil removed. remaining <kals. water w/inexcav removed & treated via air strippers & discharged to sanitary sewer. no water recharge noted.
Contaimination assessement:	suspect most of the contam was from leaks at the pump island.
Extent of contamination impact:	undetermined at this time. several vocs detected >kalscontam has been confirmed by gw samples w/in nearby excavs.
Updated information:	Not reported
Invoice initiated:	19951
Invoice on going:	Not reported
Invoice completetd:	19951
Release confirmed:	19951
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	Not reported
Cost recovery initiated by:	Not reported
Cost recovery completed:	Not reported
Cost recovery completed by:	Not reported
Appplication to trust fund:	Not reported

UST:

Facility ID:	27195
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1994-07-15 00:00:00
Capacity (Gals):	50000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Unknown
Piping:	Bare Steel
Facility Location Method:	Topozone

FLOWER AVIATION (Continued) **U003542200**

Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Don Kneubuhlrt Autho
Contact Title:	Executive Director
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	0
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1953
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	071994
Material of Construction:	Steel
Petroleum Substance:	Empty
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.79074
Longitude:	-97.64040

Facility ID:	27195
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1994-07-15 00:00:00
Capacity (Gals):	50000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Unknown
Piping:	Bare Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Don Kneubuhlrt Autho
Contact Title:	Executive Director
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401

FLOWER AVIATION (Continued) **U003542200**

Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	0
Facility District:	NC
Tank ID:	002
Tank Status:	Permanently Out Of Use
Installation Year:	1953
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	071994
Material of Construction:	Steel
Petroleum Substance:	Not reported
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.79074
Longitude:	-97.64040

Facility ID:	27195
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1994-07-15 00:00:00
Capacity (Gals):	50000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Unknown
Piping:	Bare Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Don Kneubuhlrt Autho
Contact Title:	Executive Director
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	0
Facility District:	NC
Tank ID:	003
Tank Status:	Permanently Out Of Use
Installation Year:	1953
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	071994
Material of Construction:	Steel

FLOWER AVIATION (Continued) **U003542200**

Petroleum Substance: Not reported
Owner Replacement Name: KENNY BIEKER
NonPetroleum Substance: Not reported
Owner Replacement Title: Not reported
Hazards: Not reported
Principal CERCLA Substance/Chem Abstract Service Num: Not reported
Latitude: 38.79074
Longitude: -97.64040

Facility ID: 27195
Facility 911 Address: SALINA AIRPORT
Facility 911 City: SALINA
Facility 911 State: KS
Facility 911 Zip: 67401
Date Removed: 1994-07-15 00:00:00
Capacity (Gals): 50000
Tank Internal Protection: Unknown
24 Hour Phone Num: 785-827-3914
Tank External Protection: Unknown
Piping: Bare Steel
Facility Location Method: Topozone
Facility Feature: Facility Center
Facility Phone: 785-827-3914
Tank Empty: Not reported
Contact Name: Don Kneubuhlrt Autho
Contact Title: Executive Director
Owner ID: 27195
Owner Type: Private Or Corp.
Owner Name: SALINA AIRPORT AUTHORITY
Owner Address: 3237 ARNOLD AVENUE
Owner City: SALINA
Owner State: KS
Owner Zip: 67401
Owner County: SALINE
Owner Phone: 785-827-3914
QTY Remaining in Tank: 0
Facility District: NC
Tank ID: 004
Tank Status: Permanently Out Of Use
Installation Year: 1953
Last Permit Printed: Not reported
Current Permit Printed: Not reported
Facility Datum: WGS84
Out of service Mo/Yr: 071994
Material of Construction: Steel
Petroleum Substance: Gas (Incl Alcohol)
Owner Replacement Name: KENNY BIEKER
NonPetroleum Substance: Not reported
Owner Replacement Title: Not reported
Hazards: Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num: 8006-61-9
Latitude: 38.79074
Longitude: -97.64040

Facility ID: 27195
Facility 911 Address: SALINA AIRPORT
Facility 911 City: SALINA

FLOWER AVIATION (Continued) **U003542200**

Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1994-07-15 00:00:00
Capacity (Gals):	50000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Unknown
Piping:	Bare Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Don Kneubuhlrt Autho
Contact Title:	Executive Director
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	0
Facility District:	NC
Tank ID:	005
Tank Status:	Permanently Out Of Use
Installation Year:	1953
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	071994
Material of Construction:	Steel
Petroleum Substance:	Empty
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.79074
Longitude:	-97.64040

Facility ID:	27195
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1994-07-15 00:00:00
Capacity (Gals):	50000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Unknown
Piping:	Bare Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported

FLOWER AVIATION (Continued) **U003542200**

Contact Name:	Don Kneubuhlrt Autho
Contact Title:	Executive Director
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	0
Facility District:	NC
Tank ID:	006
Tank Status:	Permanently Out Of Use
Installation Year:	1953
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	071994
Material of Construction:	Steel
Petroleum Substance:	Not reported
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.79074
Longitude:	-97.64040

Facility ID:	27195
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1994-07-15 00:00:00
Capacity (Gals):	50000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Unknown
Piping:	Bare Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Don Kneubuhlrt Autho
Contact Title:	Executive Director
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	0

FLOWER AVIATION (Continued) **U003542200**

Facility District:	NC
Tank ID:	007
Tank Status:	Permanently Out Of Use
Installation Year:	1953
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	071994
Material of Construction:	Steel
Petroleum Substance:	Empty
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.79074
Longitude:	-97.64040
Facility ID:	27195
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1994-07-15 00:00:00
Capacity (Gals):	50000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Unknown
Piping:	Bare Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Don Kneubuhlrt Autho
Contact Title:	Executive Director
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	0
Facility District:	NC
Tank ID:	008
Tank Status:	Permanently Out Of Use
Installation Year:	1953
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	071994
Material of Construction:	Steel
Petroleum Substance:	Empty
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported

FLOWER AVIATION (Continued) **U003542200**

Owner Replacement Title: Not reported
Hazards: Not reported
Principal CERCLA Substance/Chem Abstract Service Num: Not reported
Latitude: 38.79074
Longitude: -97.64040

Facility ID: 27195
Facility 911 Address: SALINA AIRPORT
Facility 911 City: SALINA
Facility 911 State: KS
Facility 911 Zip: 67401
Date Removed: 1994-07-15 00:00:00
Capacity (Gals): 50000
Tank Internal Protection: Unknown
24 Hour Phone Num: 785-827-3914
Tank External Protection: Unknown
Piping: Bare Steel
Facility Location Method: Topozone
Facility Feature: Facility Center
Facility Phone: 785-827-3914
Tank Empty: Not reported
Contact Name: Don Kneubuhlrt Autho
Contact Title: Executive Director
Owner ID: 27195
Owner Type: Private Or Corp.
Owner Name: SALINA AIRPORT AUTHORITY
Owner Address: 3237 ARNOLD AVENUE
Owner City: SALINA
Owner State: KS
Owner Zip: 67401
Owner County: SALINE
Owner Phone: 785-827-3914
QTY Remaining in Tank: 0
Facility District: NC
Tank ID: 009
Tank Status: Permanently Out Of Use
Installation Year: 1953
Last Permit Printed: Not reported
Current Permit Printed: Not reported
Facility Datum: WGS84
Out of service Mo/Yr: 071994
Material of Construction: Steel
Petroleum Substance: Empty
Owner Replacement Name: KENNY BIEKER
NonPetroleum Substance: Not reported
Owner Replacement Title: Not reported
Hazards: Not reported
Principal CERCLA Substance/Chem Abstract Service Num: Not reported
Latitude: 38.79074
Longitude: -97.64040

Facility ID: 27195
Facility 911 Address: SALINA AIRPORT
Facility 911 City: SALINA
Facility 911 State: KS
Facility 911 Zip: 67401
Date Removed: 1994-06-15 00:00:00

FLOWER AVIATION (Continued) **U003542200**

Capacity (Gals):	50000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Unknown
Piping:	Bare Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Don Kneubuhlrt Autho
Contact Title:	Executive Director
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	0
Facility District:	NC
Tank ID:	010
Tank Status:	Permanently Out Of Use
Installation Year:	1953
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	061994
Material of Construction:	Steel
Petroleum Substance:	Empty
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.79074
Longitude:	-97.64040

Facility ID:	27195
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1994-06-15 00:00:00
Capacity (Gals):	50000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Unknown
Piping:	Bare Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Don Kneubuhlrt Autho
Contact Title:	Executive Director
Owner ID:	27195

FLOWER AVIATION (Continued) **U003542200**

Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	0
Facility District:	NC
Tank ID:	011
Tank Status:	Permanently Out Of Use
Installation Year:	1900
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	061994
Material of Construction:	Steel
Petroleum Substance:	Empty
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.79074
Longitude:	-97.64040

Facility ID:	27195
Facility 911 Address:	SALINA AIRPORT
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1994-06-15 00:00:00
Capacity (Gals):	50000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Unknown
Piping:	Bare Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Don Kneubuhlrt Autho
Contact Title:	Executive Director
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	0
Facility District:	NC
Tank ID:	012
Tank Status:	Permanently Out Of Use

FLOWER AVIATION (Continued) **U003542200**

Installation Year:	1900
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	061994
Material of Construction:	Steel
Petroleum Substance:	Empty
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.79074
Longitude:	-97.64040

KS Financial Assurance:

Facility ID:	27195
Financial Responsibility:	3rd Party Liability Insurance
Facility ID:	27195
Financial Responsibility:	3rd Party Liability Insurance
Facility ID:	27195
Financial Responsibility:	3rd Party Liability Insurance
Facility ID:	27195
Financial Responsibility:	3rd Party Liability Insurance
Facility ID:	27195
Financial Responsibility:	3rd Party Liability Insurance
Facility ID:	27195
Financial Responsibility:	3rd Party Liability Insurance
Facility ID:	27195
Financial Responsibility:	3rd Party Liability Insurance
Facility ID:	27195
Financial Responsibility:	3rd Party Liability Insurance
Facility ID:	27195
Financial Responsibility:	3rd Party Liability Insurance
Facility ID:	27195
Financial Responsibility:	3rd Party Liability Insurance
Facility ID:	27195
Financial Responsibility:	3rd Party Liability Insurance

L53
NNW
< 1/8
0.038 mi.
200 ft.

Relative:
Higher

Actual:
1260 ft.

SCHILLING AFB (PARENT SITE)
SALINA, KS 67401
Site 1 of 3 in cluster L

KS SHWS **S108954062**
N/A

SHWS:

Site ID:	1599
Has Env Use Control:	No
Project code:	C508503013
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.79087 / -97.64036
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	KS000597922
Discovery Date:	01/01/1991
Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Refined Petroleum, VOC
Media Act:	Ground Water, Soil
Media Pot:	Surface Water, Sediment
Source:	Abandoned Facility, Dumping/Drums, Facility Operations, Underground Tank/Piping
Land Use:	Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Lawn and Garden, Monitoring, PWS
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Private Well, Public Water Supply, Human
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SALINA AIRPORT INDUSTRIAL PARK; SALINA MUNICIPAL AIRPORT; SCHILLING AIR FORCE BASE; SMOKY HILL AAF; SMOKY HILL AIR FORCE BASE; SMOKY HILL ARMY AIR BASE; SMOKY HILL ARMY AIRFIELD
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Public Meeting
Activity Status:	Completed
Activity Start Date:	02/27/2015
Activity End Date:	02/27/2015
Narrative:	The former Schilling Air Force Base Site is the former location of a military air base that operated at various times from 1942 to 1967 and was transferred to the City of Salina upon closure. The site now contains the Salina Municipal Airport, industrial and commercial businesses, vocational and college programs, and limited residential

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

areas. Soils and groundwater at several locations at the site have been impacted from releases of volatile organic compounds (VOCs), semi-volatile organic compounds, and metals. The Salina Airport Authority (SAA), KDHE, US Environmental Protection Agency (EPA), and the US Army Corps of Engineers (USACE) have conducted numerous environmental investigations and some limited remedial actions at the Site since the mid-90's. USACE removed numerous underground storage tanks throughout the site and installed an air stripper at the Salina Tech school sump pump to remove VOCs from groundwater collecting in the sump.

Throughout 2004 to circa 2008, investigations were performed by USAC E with KDHE oversight. In 2004, the USACE and KDHE performed indoor air monitoring for TCE vapor intrusion at K-State Salina and Salina Vo-Tech which continued through March 2006. A Final Remedial Investigation (RI) and Baseline Risk Assessment for Operable Unit One (OU1) was completed in 2005. As part of the 2005 RI, Schilling AFB was broken into 3 Operable Units (Ous) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. Additional field activities for a RI Addendum and Feasibility Study was completed by USACE in 2007. Further information on environmental investigations prior to 2012 is presented in the respective OU site
files.

Multiple contaminants have been detected in various environmental me dia at the Site, on-Base and off-Base, at levels in excess of their respective EPA maximum contaminant levels (MCLs) and KDHE Risk-based Standards for Kansas (RSKs). In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Site; including all three previously identified operable units. Subsequently, the Salina Public Entities entered into a Consent Agreement and Final Order with the KDHE to complete the RI/FS scope of work; i.e., characterize the full nature and extent of contamination followed by selection, design, and implementation of appropriate
remedies.

The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent
FS.

A supplemental RI took place in November 2017 to determine whether t he emerging contaminants 1,4-dioxane and polyfluoroalkyl substances (PFAS) are present on the site. The results of the investigation showed that PFAS is present in groundwater at the site, generally co-located with the TCE
plumes.

Ther Final RI Report was approved in June 2018. The HHRA was approve d in its entirety in April 2018. The revised Groundwater Model was approved in June 2018. A draft Feasibility Study was submitted in February 2018. The revised version was submitted in August 2018; additional revisions were requested in October
2018.

The Draft CAD will be available for public comment from April 8 thro ugh May 8, 2019. A public availability session will take place on May 1, 2019 from 6:00 - 9:00 pm in Salina.

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

Site ID:	1599
Has Env Use Control:	No
Project code:	C508503013
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.79087 / -97.64036
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	KS000597922
Discovery Date:	01/01/1991
Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Refined Petroleum, VOC
Media Act:	Ground Water, Soil
Media Pot:	Surface Water, Sediment
Source:	Abandoned Facility, Dumping/Drums, Facility Operations, Underground Tank/Piping
Land Use:	Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Lawn and Garden, Monitoring, PWS
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Private Well, Public Water Supply, Human
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SALINA AIRPORT INDUSTRIAL PARK; SALINA MUNICIPAL AIRPORT; SCHILLING AIR FORCE BASE; SMOKY HILL AAF; SMOKY HILL AIR FORCE BASE; SMOKY HILL ARMY AIR BASE; SMOKY HILL ARMY AIRFIELD
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Public Meeting
Activity Status:	Completed
Activity Start Date:	02/27/2015
Activity End Date:	02/27/2015
Narrative:	The former Schilling Air Force Base Site is the former location of a military air base that operated at various times from 1942 to 1967 and was transferred to the City of Salina upon closure. The site now contains the Salina Municipal Airport, industrial and commercial businesses, vocational and college programs, and limited residential areas. Soils and groundwater at several locations at the site have been impacted from releases of volatile organic compounds (VOCs), semi-volatile organic compounds, and metals. The Salina Airport Authority (SAA), KDHE, US Environmental Protection Agency (EPA), and the US Army Corps of Engineers (USACE) have conducted numerous

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

environmental investigations and some limited remedial actions at the Site since the mid-90's. USACE removed numerous underground storage tanks throughout the site and installed an air stripper at the Salina Tech school sump pump to remove VOCs from groundwater collecting in the sump.

Throughout 2004 to circa 2008, investigations were performed by USAC E with KDHE oversight. In 2004, the USACE and KDHE performed indoor air monitoring for TCE vapor intrusion at K-State Salina and Salina Vo-Tech which continued through March 2006. A Final Remedial Investigation (RI) and Baseline Risk Assessment for Operable Unit One (OU1) was completed in 2005. As part of the 2005 RI, Schilling AFB was broken into 3 Operable Units (Ous) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. Additional field activities for a RI Addendum and Feasibility Study was completed by USACE in 2007. Further information on environmental investigations prior to 2012 is presented in the respective OU site files.

Multiple contaminants have been detected in various environmental me dia at the Site, on-Base and off-Base, at levels in excess of their respective EPA maximum contaminant levels (MCLs) and KDHE Risk-based Standards for Kansas (RSKs). In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Site; including all three previously identified operable units. Subsequently, the Salina Public Entities entered into a Consent Agreement and Final Order with the KDHE to complete the RI/FS scope of work; i.e., characterize the full nature and extent of contamination followed by selection, design, and implementation of appropriate remedies.

The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent FS.

A supplemental RI took place in November 2017 to determine whether t he emerging contaminants 1,4-dioxane and polyfluoroalkyl substances (PFAS) are present on the site. The results of the investigation showed that PFAS is present in groundwater at the site, generally co-located with the TCE plumes.

Ther Final RI Report was approved in June 2018. The HHRA was approve d in its entirety in April 2018. The revised Groundwater Model was approved in June 2018. A draft Feasibility Study was submitted in February 2018. The revised version was submitted in August 2018; additional revisions were requested in October 2018.

The Draft CAD will be available for public comment from April 8 thro ugh May 8, 2019. A public availability session will take place on May 1, 2019 from 6:00 - 9:00 pm in Salina.

Site ID: 1599
Has Env Use Control: No
Project code: C508503013
PM Name: RICHARDS, A.
Site Status: **Active**

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

District Office:	NCDO
Lat/Long:	38.79087 / -97.64036
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	KS000597922
Discovery Date:	01/01/1991
Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Refined Petroleum, VOC
Media Act:	Ground Water, Soil
Media Pot:	Surface Water, Sediment
Source:	Abandoned Facility, Dumping/Drums, Facility Operations, Underground Tank/Piping
Land Use:	Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Lawn and Garden, Monitoring, PWS
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Private Well, Public Water Supply, Human
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SALINA AIRPORT INDUSTRIAL PARK; SALINA MUNICIPAL AIRPORT; SCHILLING AIR FORCE BASE; SMOKY HILL AAF; SMOKY HILL AIR FORCE BASE; SMOKY HILL ARMY AIR BASE; SMOKY HILL ARMY AIRFIELD
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Public Meeting
Activity Status:	Completed
Activity Start Date:	02/27/2015
Activity End Date:	02/27/2015
Narrative:	The former Schilling Air Force Base Site is the former location of a military air base that operated at various times from 1942 to 1967 and was transferred to the City of Salina upon closure. The site now contains the Salina Municipal Airport, industrial and commercial businesses, vocational and college programs, and limited residential areas. Soils and groundwater at several locations at the site have been impacted from releases of volatile organic compounds (VOCs), semi-volatile organic compounds, and metals. The Salina Airport Authority (SAA), KDHE, US Environmental Protection Agency (EPA), and the US Army Corps of Engineers (USACE) have conducted numerous environmental investigations and some limited remedial actions at the Site since the mid-90's. USACE removed numerous underground storage tanks throughout the site and installed an air stripper at the Salina Tech school sump pump to remove VOCs from groundwater collecting in the sump.

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

Throughout 2004 to circa 2008, investigations were performed by USAC E with KDHE oversight. In 2004, the USACE and KDHE performed indoor air monitoring for TCE vapor intrusion at K-State Salina and Salina Vo-Tech which continued through March 2006. A Final Remedial Investigation (RI) and Baseline Risk Assessment for Operable Unit One (OU1) was completed in 2005. As part of the 2005 RI, Schilling AFB was broken into 3 Operable Units (Ous) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. Additional field activities for a RI Addendum and Feasibility Study was completed by USACE in 2007. Further information on environmental investigations prior to 2012 is presented in the respective OU site files.

Multiple contaminants have been detected in various environmental me dia at the Site, on-Base and off-Base, at levels in excess of their respective EPA maximum contaminant levels (MCLs) and KDHE Risk-based Standards for Kansas (RSKs). In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Site; including all three previously identified operable units. Subsequently, the Salina Public Entities entered into a Consent Agreement and Final Order with the KDHE to complete the RI/FS scope of work; i.e., characterize the full nature and extent of contamination followed by selection, design, and implementation of appropriate remedies.

The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent FS.

A supplemental RI took place in November 2017 to determine whether t he emerging contaminants 1,4-dioxane and polyfluoroalkyl substances (PFAS) are present on the site. The results of the investigation showed that PFAS is present in groundwater at the site, generally co-located with the TCE plumes.

Ther Final RI Report was approved in June 2018. The HHRA was approve d in its entirety in April 2018. The revised Groundwater Model was approved in June 2018. A draft Feasibility Study was submitted in February 2018. The revised version was submitted in August 2018; additional revisions were requested in October 2018.

The Draft CAD will be available for public comment from April 8 thro ugh May 8, 2019. A public availability session will take place on May 1, 2019 from 6:00 - 9:00 pm in Salina.

Site ID:	1599
Has Env Use Control:	No
Project code:	C508503013
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.79087 / -97.64036
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	KS000597922
Discovery Date:	01/01/1991
Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Refined Petroleum, VOC
Media Act:	Ground Water, Soil
Media Pot:	Surface Water, Sediment
Source:	Abandoned Facility, Dumping/Drums, Facility Operations, Underground Tank/Piping
Land Use:	Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Lawn and Garden, Monitoring, PWS
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Private Well, Public Water Supply, Human
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SALINA AIRPORT INDUSTRIAL PARK; SALINA MUNICIPAL AIRPORT; SCHILLING AIR FORCE BASE; SMOKY HILL AAF; SMOKY HILL AIR FORCE BASE; SMOKY HILL ARMY AIR BASE; SMOKY HILL ARMY AIRFIELD
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Public Meeting
Activity Status:	Completed
Activity Start Date:	02/27/2015
Activity End Date:	02/27/2015
Narrative:	The former Schilling Air Force Base Site is the former location of a military air base that operated at various times from 1942 to 1967 and was transferred to the City of Salina upon closure. The site now contains the Salina Municipal Airport, industrial and commercial businesses, vocational and college programs, and limited residential areas. Soils and groundwater at several locations at the site have been impacted from releases of volatile organic compounds (VOCs), semi-volatile organic compounds, and metals. The Salina Airport Authority (SAA), KDHE, US Environmental Protection Agency (EPA), and the US Army Corps of Engineers (USACE) have conducted numerous environmental investigations and some limited remedial actions at the Site since the mid-90's. USACE removed numerous underground storage tanks throughout the site and installed an air stripper at the Salina Tech school sump pump to remove VOCs from groundwater collecting in the sump. Throughout 2004 to circa 2008, investigations were performed by USAC E with KDHE oversight. In 2004, the USACE and KDHE performed indoor air monitoring for TCE vapor intrusion at K-State Salina and Salina Vo-Tech which continued through March 2006. A Final Remedial Investigation (RI) and Baseline Risk Assessment for Operable Unit One

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

(OU1) was completed in 2005. As part of the 2005 RI, Schilling AFB was broken into 3 Operable Units (Ous) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. Additional field activities for a RI Addendum and Feasibility Study was completed by USACE in 2007. Further information on environmental investigations prior to 2012 is presented in the respective OU site files.

Multiple contaminants have been detected in various environmental me dia at the Site, on-Base and off-Base, at levels in excess of their respective EPA maximum contaminant levels (MCLs) and KDHE Risk-based Standards for Kansas (RSKs). In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Site; including all three previously identified operable units. Subsequently, the Salina Public Entities entered into a Consent Agreement and Final Order with the KDHE to complete the RI/FS scope of work; i.e., characterize the full nature and extent of contamination followed by selection, design, and implementation of appropriate remedies.

The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent FS.

A supplemental RI took place in November 2017 to determine whether t he emerging contaminants 1,4-dioxane and polyfluoroalkyl substances (PFAS) are present on the site. The results of the investigation showed that PFAS is present in groundwater at the site, generally co-located with the TCE plumes.

Ther Final RI Report was approved in June 2018. The HHRA was approve d in its entirety in April 2018. The revised Groundwater Model was approved in June 2018. A draft Feasibility Study was submitted in February 2018. The revised version was submitted in August 2018; additional revisions were requested in October 2018.

The Draft CAD will be available for public comment from April 8 thro ugh May 8, 2019. A public availability session will take place on May 1, 2019 from 6:00 - 9:00 pm in Salina.

Site ID:	1599
Has Env Use Control:	No
Project code:	C508503013
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.79087 / -97.64036
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	KS000597922
Discovery Date:	01/01/1991
Depth To GW:	11-20 feet

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Refined Petroleum, VOC
Media Act:	Ground Water, Soil
Media Pot:	Surface Water, Sediment
Source:	Abandoned Facility, Dumping/Drums, Facility Operations, Underground Tank/Piping
Land Use:	Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Lawn and Garden, Monitoring, PWS
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Private Well, Public Water Supply, Human
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SALINA AIRPORT INDUSTRIAL PARK; SALINA MUNICIPAL AIRPORT; SCHILLING AIR FORCE BASE; SMOKY HILL AAF; SMOKY HILL AIR FORCE BASE; SMOKY HILL ARMY AIR BASE; SMOKY HILL ARMY AIRFIELD
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Public Meeting
Activity Status:	Completed
Activity Start Date:	02/27/2015
Activity End Date:	02/27/2015
Narrative:	The former Schilling Air Force Base Site is the former location of a military air base that operated at various times from 1942 to 1967 and was transferred to the City of Salina upon closure. The site now contains the Salina Municipal Airport, industrial and commercial businesses, vocational and college programs, and limited residential areas. Soils and groundwater at several locations at the site have been impacted from releases of volatile organic compounds (VOCs), semi-volatile organic compounds, and metals. The Salina Airport Authority (SAA), KDHE, US Environmental Protection Agency (EPA), and the US Army Corps of Engineers (USACE) have conducted numerous environmental investigations and some limited remedial actions at the Site since the mid-90's. USACE removed numerous underground storage tanks throughout the site and installed an air stripper at the Salina Tech school sump pump to remove VOCs from groundwater collecting in the sump. Throughout 2004 to circa 2008, investigations were performed by USAC E with KDHE oversight. In 2004, the USACE and KDHE performed indoor air monitoring for TCE vapor intrusion at K-State Salina and Salina Vo-Tech which continued through March 2006. A Final Remedial Investigation (RI) and Baseline Risk Assessment for Operable Unit One (OU1) was completed in 2005. As part of the 2005 RI, Schilling AFB was broken into 3 Operable Units (Ous) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. Additional field activities for a RI Addendum and Feasibility Study was completed by USACE in 2007.

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

Further information on environmental investigations prior to 2012 is presented in the respective OU site files.

Multiple contaminants have been detected in various environmental media at the Site, on-Base and off-Base, at levels in excess of their respective EPA maximum contaminant levels (MCLs) and KDHE Risk-based Standards for Kansas (RSKs). In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Site; including all three previously identified operable units. Subsequently, the Salina Public Entities entered into a Consent Agreement and Final Order with the KDHE to complete the RI/FS scope of work; i.e., characterize the full nature and extent of contamination followed by selection, design, and implementation of appropriate remedies.

The RI field activities have concluded. Interim groundwater monitoring and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent FS.

A supplemental RI took place in November 2017 to determine whether the emerging contaminants 1,4-dioxane and polyfluoroalkyl substances (PFAS) are present on the site. The results of the investigation showed that PFAS is present in groundwater at the site, generally co-located with the TCE plumes.

Ther Final RI Report was approved in June 2018. The HHRA was approved in its entirety in April 2018. The revised Groundwater Model was approved in June 2018. A draft Feasibility Study was submitted in February 2018. The revised version was submitted in August 2018; additional revisions were requested in October 2018.

The Draft CAD will be available for public comment from April 8 through May 8, 2019. A public availability session will take place on May 1, 2019 from 6:00 - 9:00 pm in Salina.

Site ID:	1599
Has Env Use Control:	No
Project code:	C508503013
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.79087 / -97.64036
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	KS000597922
Discovery Date:	01/01/1991
Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Refined Petroleum, VOC
Media Act:	Ground Water, Soil
Media Pot:	Surface Water, Sediment
Source:	Abandoned Facility, Dumping/Drums, Facility Operations, Underground Tank/Piping
Land Use:	Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Lawn and Garden, Monitoring, PWS
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Private Well, Public Water Supply, Human
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SALINA AIRPORT INDUSTRIAL PARK; SALINA MUNICIPAL AIRPORT; SCHILLING AIR FORCE BASE; SMOKY HILL AAF; SMOKY HILL AIR FORCE BASE; SMOKY HILL ARMY AIR BASE; SMOKY HILL ARMY AIRFIELD
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Public Meeting
Activity Status:	Completed
Activity Start Date:	02/27/2015
Activity End Date:	02/27/2015
Narrative:	The former Schilling Air Force Base Site is the former location of a military air base that operated at various times from 1942 to 1967 and was transferred to the City of Salina upon closure. The site now contains the Salina Municipal Airport, industrial and commercial businesses, vocational and college programs, and limited residential areas. Soils and groundwater at several locations at the site have been impacted from releases of volatile organic compounds (VOCs), semi-volatile organic compounds, and metals. The Salina Airport Authority (SAA), KDHE, US Environmental Protection Agency (EPA), and the US Army Corps of Engineers (USACE) have conducted numerous environmental investigations and some limited remedial actions at the Site since the mid-90's. USACE removed numerous underground storage tanks throughout the site and installed an air stripper at the Salina Tech school sump pump to remove VOCs from groundwater collecting in the sump. Throughout 2004 to circa 2008, investigations were performed by USAC E with KDHE oversight. In 2004, the USACE and KDHE performed indoor air monitoring for TCE vapor intrusion at K-State Salina and Salina Vo-Tech which continued through March 2006. A Final Remedial Investigation (RI) and Baseline Risk Assessment for Operable Unit One (OU1) was completed in 2005. As part of the 2005 RI, Schilling AFB was broken into 3 Operable Units (Ous) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. Additional field activities for a RI Addendum and Feasibility Study was completed by USACE in 2007. Further information on environmental investigations prior to 2012 is presented in the respective OU site files. Multiple contaminants have been detected in various environmental me dia at the Site, on-Base and off-Base, at levels in excess of their

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

respective EPA maximum contaminant levels (MCLs) and KDHE Risk-based Standards for Kansas (RSKs). In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Site; including all three previously identified operable units. Subsequently, the Salina Public Entities entered into a Consent Agreement and Final Order with the KDHE to complete the RI/FS scope of work; i.e., characterize the full nature and extent of contamination followed by selection, design, and implementation of appropriate
remedies.
The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent
FS.
A supplemental RI took place in November 2017 to determine whether t he emerging contaminants 1,4-dioxane and polyfluoroalkyl substances (PFAS) are present on the site. The results of the investigation showed that PFAS is present in groundwater at the site, generally co-located with the TCE
plumes.
Ther Final RI Report was approved in June 2018. The HHRA was approve d in its entirety in April 2018. The revised Groundwater Model was approved in June 2018. A draft Feasibility Study was submitted in February 2018. The revised version was submitted in August 2018; additional revisions were requested in October
2018.
The Draft CAD will be available for public comment from April 8 thro ugh May 8, 2019. A public availability session will take place on May 1, 2019 from 6:00 - 9:00 pm in Salina.

Site ID:	1599
Has Env Use Control:	No
Project code:	C508503013
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.79087 / -97.64036
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	KS000597922
Discovery Date:	01/01/1991
Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Refined Petroleum, VOC
Media Act:	Ground Water, Soil

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

Media Pot:	Surface Water, Sediment
Source:	Abandoned Facility, Dumping/Drums, Facility Operations, Underground Tank/Piping
Land Use:	Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Lawn and Garden, Monitoring, PWS
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Private Well, Public Water Supply, Human
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SALINA AIRPORT INDUSTRIAL PARK; SALINA MUNICIPAL AIRPORT; SCHILLING AIR FORCE BASE; SMOKY HILL AAF; SMOKY HILL AIR FORCE BASE; SMOKY HILL ARMY AIR BASE; SMOKY HILL ARMY AIRFIELD
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Public Meeting
Activity Status:	Completed
Activity Start Date:	02/27/2015
Activity End Date:	02/27/2015
Narrative:	The former Schilling Air Force Base Site is the former location of a military air base that operated at various times from 1942 to 1967 and was transferred to the City of Salina upon closure. The site now contains the Salina Municipal Airport, industrial and commercial businesses, vocational and college programs, and limited residential areas. Soils and groundwater at several locations at the site have been impacted from releases of volatile organic compounds (VOCs), semi-volatile organic compounds, and metals. The Salina Airport Authority (SAA), KDHE, US Environmental Protection Agency (EPA), and the US Army Corps of Engineers (USACE) have conducted numerous environmental investigations and some limited remedial actions at the Site since the mid-90's. USACE removed numerous underground storage tanks throughout the site and installed an air stripper at the Salina Tech school sump pump to remove VOCs from groundwater collecting in the sump. Throughout 2004 to circa 2008, investigations were performed by USAC E with KDHE oversight. In 2004, the USACE and KDHE performed indoor air monitoring for TCE vapor intrusion at K-State Salina and Salina Vo-Tech which continued through March 2006. A Final Remedial Investigation (RI) and Baseline Risk Assessment for Operable Unit One (OU1) was completed in 2005. As part of the 2005 RI, Schilling AFB was broken into 3 Operable Units (Ous) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. Additional field activities for a RI Addendum and Feasibility Study was completed by USACE in 2007. Further information on environmental investigations prior to 2012 is presented in the respective OU site files. Multiple contaminants have been detected in various environmental me dia at the Site, on-Base and off-Base, at levels in excess of their respective EPA maximum contaminant levels (MCLs) and KDHE Risk-based Standards for Kansas (RSKs). In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Site;

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

including all three previously identified operable units.
Subsequently, the Salina Public Entities entered into a Consent Agreement and Final Order with the KDHE to complete the RI/FS scope of work; i.e., characterize the full nature and extent of contamination followed by selection, design, and implementation of appropriate
remedies.
The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent
FS.
A supplemental RI took place in November 2017 to determine whether t he emerging contaminants 1,4-dioxane and polyfluoroalkyl substances (PFAS) are present on the site. The results of the investigation showed that PFAS is present in groundwater at the site, generally co-located with the TCE
plumes.
Ther Final RI Report was approved in June 2018. The HHRA was approve d in its entirety in April 2018. The revised Groundwater Model was approved in June 2018. A draft Feasibility Study was submitted in February 2018. The revised version was submitted in August 2018; additional revisions were requested in October
2018.
The Draft CAD will be available for public comment from April 8 thro ugh May 8, 2019. A public availability session will take place on May 1, 2019 from 6:00 - 9:00 pm in Salina.

Site ID:	1599
Has Env Use Control:	No
Project code:	C508503013
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.79087 / -97.64036
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	KS000597922
Discovery Date:	01/01/1991
Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Refined Petroleum, VOC
Media Act:	Ground Water, Soil
Media Pot:	Surface Water, Sediment
Source:	Abandoned Facility, Dumping/Drums, Facility Operations, Underground Tank/Piping
Land Use:	Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Lawn and Garden, Monitoring, PWS

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Private Well, Public Water Supply, Human
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SALINA AIRPORT INDUSTRIAL PARK; SALINA MUNICIPAL AIRPORT; SCHILLING AIR FORCE BASE; SMOKY HILL AAF; SMOKY HILL AIR FORCE BASE; SMOKY HILL ARMY AIR BASE; SMOKY HILL ARMY AIRFIELD
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Public Meeting
Activity Status:	Completed
Activity Start Date:	02/27/2015
Activity End Date:	02/27/2015
Narrative:	The former Schilling Air Force Base Site is the former location of a military air base that operated at various times from 1942 to 1967 and was transferred to the City of Salina upon closure. The site now contains the Salina Municipal Airport, industrial and commercial businesses, vocational and college programs, and limited residential areas. Soils and groundwater at several locations at the site have been impacted from releases of volatile organic compounds (VOCs), semi-volatile organic compounds, and metals. The Salina Airport Authority (SAA), KDHE, US Environmental Protection Agency (EPA), and the US Army Corps of Engineers (USACE) have conducted numerous environmental investigations and some limited remedial actions at the Site since the mid-90's. USACE removed numerous underground storage tanks throughout the site and installed an air stripper at the Salina Tech school sump pump to remove VOCs from groundwater collecting in the sump. Throughout 2004 to circa 2008, investigations were performed by USAC E with KDHE oversight. In 2004, the USACE and KDHE performed indoor air monitoring for TCE vapor intrusion at K-State Salina and Salina Vo-Tech which continued through March 2006. A Final Remedial Investigation (RI) and Baseline Risk Assessment for Operable Unit One (OU1) was completed in 2005. As part of the 2005 RI, Schilling AFB was broken into 3 Operable Units (Ous) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. Additional field activities for a RI Addendum and Feasibility Study was completed by USACE in 2007. Further information on environmental investigations prior to 2012 is presented in the respective OU site files. Multiple contaminants have been detected in various environmental me dia at the Site, on-Base and off-Base, at levels in excess of their respective EPA maximum contaminant levels (MCLs) and KDHE Risk-based Standards for Kansas (RSKs). In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Site; including all three previously identified operable units. Subsequently, the Salina Public Entities entered into a Consent Agreement and Final Order with the KDHE to complete the RI/FS scope of work; i.e., characterize the full nature and extent of contamination followed by selection, design, and implementation of

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

appropriate
remedies.
The RI field activities have concluded. Interim groundwater monitor
ing and vapor instrusion assessment are on-going during deveopment
of the RI Report and subsequent
FS.
A supplemental RI took place in November 2017 to determine whether t
he emerging contaminants 1,4-dioxane and polyfluoroalkyl substances
(PFAS) are present on the site. The results of the investigation
showed that PFAS is present in groundwater at the site, generally
co-located with the TCE
plumes.
Ther Final RI Report was approved in June 2018. The HHRA was approve
d in its entirety in April 2018. The revised Groundwater Model was
approved in June 2018. A draft Feasibility Study was submitted in
February 2018. The revised version was submitted in August 2018;
additional revisions were requested in October
2018.
The Draft CAD will be available for public comment from April 8 thro
ugh May 8, 2019. A public availability session will take place on May
1, 2019 from 6:00 - 9:00 pm in Salina.

Site ID:	1599
Has Env Use Control:	No
Project code:	C508503013
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.79087 / -97.64036
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	KS000597922
Discovery Date:	01/01/1991
Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Refined Petroleum, VOC
Media Act:	Ground Water, Soil
Media Pot:	Surface Water, Sediment
Source:	Abandoned Facility, Dumping/Drums, Facility Operations, Underground Tank/Piping
Land Use:	Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Lawn and Garden, Monitoring, PWS
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Private Well, Public Water Supply, Human
Remed Air:	Not reported

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

Remed Soil: Not reported
Remed Water: Not reported
Remedir: Not reported
Alias: SALINA AIRPORT INDUSTRIAL PARK; SALINA MUNICIPAL AIRPORT; SCHILLING AIR FORCE BASE; SMOKY HILL AAF; SMOKY HILL AIR FORCE BASE; SMOKY HILL ARMY AIR BASE; SMOKY HILL ARMY AIRFIELD
Eucan Number: Not reported
Date: Not reported
Activity Type: Public Meeting
Activity Status: Completed
Activity Start Date: 02/27/2015
Activity End Date: 02/27/2015
Narrative: The former Schilling Air Force Base Site is the former location of a military air base that operated at various times from 1942 to 1967 and was transferred to the City of Salina upon closure. The site now contains the Salina Municipal Airport, industrial and commercial businesses, vocational and college programs, and limited residential areas. Soils and groundwater at several locations at the site have been impacted from releases of volatile organic compounds (VOCs), semi-volatile organic compounds, and metals. The Salina Airport Authority (SAA), KDHE, US Environmental Protection Agency (EPA), and the US Army Corps of Engineers (USACE) have conducted numerous environmental investigations and some limited remedial actions at the Site since the mid-90's. USACE removed numerous underground storage tanks throughout the site and installed an air stripper at the Salina Tech school sump pump to remove VOCs from groundwater collecting in the sump.

Throughout 2004 to circa 2008, investigations were performed by USAC E with KDHE oversight. In 2004, the USACE and KDHE performed indoor air monitoring for TCE vapor intrusion at K-State Salina and Salina Vo-Tech which continued through March 2006. A Final Remedial Investigation (RI) and Baseline Risk Assessment for Operable Unit One (OU1) was completed in 2005. As part of the 2005 RI, Schilling AFB was broken into 3 Operable Units (Ous) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. Additional field activities for a RI Addendum and Feasibility Study was completed by USACE in 2007. Further information on environmental investigations prior to 2012 is presented in the respective OU site files.

Multiple contaminants have been detected in various environmental me dia at the Site, on-Base and off-Base, at levels in excess of their respective EPA maximum contaminant levels (MCLs) and KDHE Risk-based Standards for Kansas (RSKs). In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Site; including all three previously identified operable units. Subsequently, the Salina Public Entities entered into a Consent Agreement and Final Order with the KDHE to complete the RI/FS scope of work; i.e., characterize the full nature and extent of contamination followed by selection, design, and implementation of appropriate remedies.

The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

FS.
A supplemental RI took place in November 2017 to determine whether t he emerging contaminants 1,4-dioxane and polyfluoroalkyl substances (PFAS) are present on the site. The results of the investigation showed that PFAS is present in groundwater at the site, generally co-located with the TCE
plumes.
Ther Final RI Report was approved in June 2018. The HHRA was approve d in its entirety in April 2018. The revised Groundwater Model was approved in June 2018. A draft Feasibility Study was submitted in February 2018. The revised version was submitted in August 2018; additional revisions were requested in October
2018.
The Draft CAD will be available for public comment from April 8 thro ugh May 8, 2019. A public availability session will take place on May 1, 2019 from 6:00 - 9:00 pm in Salina.

Site ID:	1599
Has Env Use Control:	No
Project code:	C508503013
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.79087 / -97.64036
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	KS000597922
Discovery Date:	01/01/1991
Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Refined Petroleum, VOC
Media Act:	Ground Water, Soil
Media Pot:	Surface Water, Sediment
Source:	Abandoned Facility, Dumping/Drums, Facility Operations, Underground Tank/Piping
Land Use:	Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Lawn and Garden, Monitoring, PWS
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Private Well, Public Water Supply, Human
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SALINA AIRPORT INDUSTRIAL PARK; SALINA MUNICIPAL AIRPORT; SCHILLING AIR FORCE BASE; SMOKY HILL AAF; SMOKY HILL AIR FORCE BASE; SMOKY HILL

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

ARMY AIR BASE; SMOKY HILL ARMY AIRFIELD

Eucan Number: Not reported
Date: Not reported
Activity Type: Public Meeting
Activity Status: Completed
Activity Start Date: 02/27/2015
Activity End Date: 02/27/2015
Narrative: The former Schilling Air Force Base Site is the former location of a military air base that operated at various times from 1942 to 1967 and was transferred to the City of Salina upon closure. The site now contains the Salina Municipal Airport, industrial and commercial businesses, vocational and college programs, and limited residential areas. Soils and groundwater at several locations at the site have been impacted from releases of volatile organic compounds (VOCs), semi-volatile organic compounds, and metals. The Salina Airport Authority (SAA), KDHE, US Environmental Protection Agency (EPA), and the US Army Corps of Engineers (USACE) have conducted numerous environmental investigations and some limited remedial actions at the Site since the mid-90's. USACE removed numerous underground storage tanks throughout the site and installed an air stripper at the Salina Tech school sump pump to remove VOCs from groundwater collecting in the sump.

Throughout 2004 to circa 2008, investigations were performed by USAC E with KDHE oversight. In 2004, the USACE and KDHE performed indoor air monitoring for TCE vapor intrusion at K-State Salina and Salina Vo-Tech which continued through March 2006. A Final Remedial Investigation (RI) and Baseline Risk Assessment for Operable Unit One (OU1) was completed in 2005. As part of the 2005 RI, Schilling AFB was broken into 3 Operable Units (Ous) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. Additional field activities for a RI Addendum and Feasibility Study was completed by USACE in 2007. Further information on environmental investigations prior to 2012 is presented in the respective OU site
files.

Multiple contaminants have been detected in various environmental me dia at the Site, on-Base and off-Base, at levels in excess of their respective EPA maximum contaminant levels (MCLs) and KDHE Risk-based Standards for Kansas (RSKs). In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Site; including all three previously identified operable units. Subsequently, the Salina Public Entities entered into a Consent Agreement and Final Order with the KDHE to complete the RI/FS scope of work; i.e., characterize the full nature and extent of contamination followed by selection, design, and implementation of appropriate
remedies.

The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent
FS.

A supplemental RI took place in November 2017 to determine whether t he emerging contaminants 1,4-dioxane and polyfluoroalkyl substances (PFAS) are present on the site. The results of the investigation showed that PFAS is present in groundwater at the site, generally

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

co-located with the TCE
plumes.
Ther Final RI Report was approved in June 2018. The HHRA was approve
d in its entirety in April 2018. The revised Groundwater Model was
approved in June 2018. A draft Feasibility Study was submitted in
February 2018. The revised version was submitted in August 2018;
additional revisions were requested in October
2018.
The Draft CAD will be available for public comment from April 8 thro
ugh May 8, 2019. A public availability session will take place on May
1, 2019 from 6:00 - 9:00 pm in Salina.

Site ID:	1599
Has Env Use Control:	No
Project code:	C508503013
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.79087 / -97.64036
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	KS000597922
Discovery Date:	01/01/1991
Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Refined Petroleum, VOC
Media Act:	Ground Water, Soil
Media Pot:	Surface Water, Sediment
Source:	Abandoned Facility, Dumping/Drums, Facility Operations, Underground Tank/Piping
Land Use:	Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Lawn and Garden, Monitoring, PWS
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Private Well, Public Water Supply, Human
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SALINA AIRPORT INDUSTRIAL PARK; SALINA MUNICIPAL AIRPORT; SCHILLING AIR FORCE BASE; SMOKY HILL AAF; SMOKY HILL AIR FORCE BASE; SMOKY HILL ARMY AIR BASE; SMOKY HILL ARMY AIRFIELD
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Public Meeting
Activity Status:	Completed

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

Activity Start Date: 02/27/2015
Activity End Date: 02/27/2015
Narrative: The former Schilling Air Force Base Site is the former location of a military air base that operated at various times from 1942 to 1967 and was transferred to the City of Salina upon closure. The site now contains the Salina Municipal Airport, industrial and commercial businesses, vocational and college programs, and limited residential areas. Soils and groundwater at several locations at the site have been impacted from releases of volatile organic compounds (VOCs), semi-volatile organic compounds, and metals. The Salina Airport Authority (SAA), KDHE, US Environmental Protection Agency (EPA), and the US Army Corps of Engineers (USACE) have conducted numerous environmental investigations and some limited remedial actions at the Site since the mid-90's. USACE removed numerous underground storage tanks throughout the site and installed an air stripper at the Salina Tech school sump pump to remove VOCs from groundwater collecting in the sump.

Throughout 2004 to circa 2008, investigations were performed by USAC E with KDHE oversight. In 2004, the USACE and KDHE performed indoor air monitoring for TCE vapor intrusion at K-State Salina and Salina Vo-Tech which continued through March 2006. A Final Remedial Investigation (RI) and Baseline Risk Assessment for Operable Unit One (OU1) was completed in 2005. As part of the 2005 RI, Schilling AFB was broken into 3 Operable Units (Ous) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. Additional field activities for a RI Addendum and Feasibility Study was completed by USACE in 2007. Further information on environmental investigations prior to 2012 is presented in the respective OU site
files.

Multiple contaminants have been detected in various environmental me dia at the Site, on-Base and off-Base, at levels in excess of their respective EPA maximum contaminant levels (MCLs) and KDHE Risk-based Standards for Kansas (RSKs). In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Site; including all three previously identified operable units. Subsequently, the Salina Public Entities entered into a Consent Agreement and Final Order with the KDHE to complete the RI/FS scope of work; i.e., characterize the full nature and extent of contamination followed by selection, design, and implementation of appropriate
remedies.

The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent
FS.

A supplemental RI took place in November 2017 to determine whether t he emerging contaminants 1,4-dioxane and polyfluoroalkyl substances (PFAS) are present on the site. The results of the investigation showed that PFAS is present in groundwater at the site, generally co-located with the TCE
plumes.

Ther Final RI Report was approved in June 2018. The HHRA was approve d in its entirety in April 2018. The revised Groundwater Model was approved in June 2018. A draft Feasibility Study was submitted in

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

February 2018. The revised version was submitted in August 2018; additional revisions were requested in October 2018.
The Draft CAD will be available for public comment from April 8 thro ugh May 8, 2019. A public availability session will take place on May 1, 2019 from 6:00 - 9:00 pm in Salina.

Site ID:	1599
Has Env Use Control:	No
Project code:	C508503013
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.79087 / -97.64036
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	KS000597922
Discovery Date:	01/01/1991
Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Refined Petroleum, VOC
Media Act:	Ground Water, Soil
Media Pot:	Surface Water, Sediment
Source:	Abandoned Facility, Dumping/Drums, Facility Operations, Underground Tank/Piping
Land Use:	Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Lawn and Garden, Monitoring, PWS
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Private Well, Public Water Supply, Human
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SALINA AIRPORT INDUSTRIAL PARK; SALINA MUNICIPAL AIRPORT; SCHILLING AIR FORCE BASE; SMOKY HILL AAF; SMOKY HILL AIR FORCE BASE; SMOKY HILL ARMY AIR BASE; SMOKY HILL ARMY AIRFIELD
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Public Meeting
Activity Status:	Completed
Activity Start Date:	02/27/2015
Activity End Date:	02/27/2015
Narrative:	The former Schilling Air Force Base Site is the former location of a military air base that operated at various times from 1942 to 1967 and was transferred to the City of Salina upon closure. The site now

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

contains the Salina Municipal Airport, industrial and commercial businesses, vocational and college programs, and limited residential areas. Soils and groundwater at several locations at the site have been impacted from releases of volatile organic compounds (VOCs), semi-volatile organic compounds, and metals. The Salina Airport Authority (SAA), KDHE, US Environmental Protection Agency (EPA), and the US Army Corps of Engineers (USACE) have conducted numerous environmental investigations and some limited remedial actions at the Site since the mid-90's. USACE removed numerous underground storage tanks throughout the site and installed an air stripper at the Salina Tech school sump pump to remove VOCs from groundwater collecting in the sump.

Throughout 2004 to circa 2008, investigations were performed by USAC E with KDHE oversight. In 2004, the USACE and KDHE performed indoor air monitoring for TCE vapor intrusion at K-State Salina and Salina Vo-Tech which continued through March 2006. A Final Remedial Investigation (RI) and Baseline Risk Assessment for Operable Unit One (OU1) was completed in 2005. As part of the 2005 RI, Schilling AFB was broken into 3 Operable Units (Ous) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. Additional field activities for a RI Addendum and Feasibility Study was completed by USACE in 2007. Further information on environmental investigations prior to 2012 is presented in the respective OU site
files.

Multiple contaminants have been detected in various environmental me dia at the Site, on-Base and off-Base, at levels in excess of their respective EPA maximum contaminant levels (MCLs) and KDHE Risk-based Standards for Kansas (RSKs). In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Site; including all three previously identified operable units. Subsequently, the Salina Public Entities entered into a Consent Agreement and Final Order with the KDHE to complete the RI/FS scope of work; i.e., characterize the full nature and extent of contamination followed by selection, design, and implementation of appropriate
remedies.

The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent
FS.

A supplemental RI took place in November 2017 to determine whether t he emerging contaminants 1,4-dioxane and polyfluoroalkyl substances (PFAS) are present on the site. The results of the investigation showed that PFAS is present in groundwater at the site, generally co-located with the TCE
plumes.

Ther Final RI Report was approved in June 2018. The HHRA was approve d in its entirety in April 2018. The revised Groundwater Model was approved in June 2018. A draft Feasibility Study was submitted in February 2018. The revised version was submitted in August 2018; additional revisions were requested in October
2018.

The Draft CAD will be available for public comment from April 8 thro ugh May 8, 2019. A public availability session will take place on May

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

1, 2019 from 6:00 - 9:00 pm in Salina.

Site ID:	1599
Has Env Use Control:	No
Project code:	C508503013
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.79087 / -97.64036
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	KS000597922
Discovery Date:	01/01/1991
Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Refined Petroleum, VOC
Media Act:	Ground Water, Soil
Media Pot:	Surface Water, Sediment
Source:	Abandoned Facility, Dumping/Drums, Facility Operations, Underground Tank/Piping
Land Use:	Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Lawn and Garden, Monitoring, PWS
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Private Well, Public Water Supply, Human
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SALINA AIRPORT INDUSTRIAL PARK; SALINA MUNICIPAL AIRPORT; SCHILLING AIR FORCE BASE; SMOKY HILL AAF; SMOKY HILL AIR FORCE BASE; SMOKY HILL ARMY AIR BASE; SMOKY HILL ARMY AIRFIELD
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Public Meeting
Activity Status:	Completed
Activity Start Date:	02/27/2015
Activity End Date:	02/27/2015
Narrative:	The former Schilling Air Force Base Site is the former location of a military air base that operated at various times from 1942 to 1967 and was transferred to the City of Salina upon closure. The site now contains the Salina Municipal Airport, industrial and commercial businesses, vocational and college programs, and limited residential areas. Soils and groundwater at several locations at the site have been impacted from releases of volatile organic compounds (VOCs), semi-volatile organic compounds, and metals. The Salina Airport

SCHILLING AFB (PARENT SITE) (Continued) **S108954062**

Authority (SAA), KDHE, US Environmental Protection Agency (EPA), and the US Army Corps of Engineers (USACE) have conducted numerous environmental investigations and some limited remedial actions at the Site since the mid-90's. USACE removed numerous underground storage tanks throughout the site and installed an air stripper at the Salina Tech school sump pump to remove VOCs from groundwater collecting in the sump.

Throughout 2004 to circa 2008, investigations were performed by USAC E with KDHE oversight. In 2004, the USACE and KDHE performed indoor air monitoring for TCE vapor intrusion at K-State Salina and Salina Vo-Tech which continued through March 2006. A Final Remedial Investigation (RI) and Baseline Risk Assessment for Operable Unit One (OU1) was completed in 2005. As part of the 2005 RI, Schilling AFB was broken into 3 Operable Units (Ous) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. Additional field activities for a RI Addendum and Feasibility Study was completed by USACE in 2007. Further information on environmental investigations prior to 2012 is presented in the respective OU site
files.

Multiple contaminants have been detected in various environmental me dia at the Site, on-Base and off-Base, at levels in excess of their respective EPA maximum contaminant levels (MCLs) and KDHE Risk-based Standards for Kansas (RSKs). In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Site; including all three previously identified operable units. Subsequently, the Salina Public Entities entered into a Consent Agreement and Final Order with the KDHE to complete the RI/FS scope of work; i.e., characterize the full nature and extent of contamination followed by selection, design, and implementation of appropriate
remedies.

The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent
FS.

A supplemental RI took place in November 2017 to determine whether t he emerging contaminants 1,4-dioxane and polyfluoroalkyl substances (PFAS) are present on the site. The results of the investigation showed that PFAS is present in groundwater at the site, generally co-located with the TCE
plumes.

Ther Final RI Report was approved in June 2018. The HHRA was approve d in its entirety in April 2018. The revised Groundwater Model was approved in June 2018. A draft Feasibility Study was submitted in February 2018. The revised version was submitted in August 2018; additional revisions were requested in October
2018.

The Draft CAD will be available for public comment from April 8 thro ugh May 8, 2019. A public availability session will take place on May 1, 2019 from 6:00 - 9:00 pm in Salina.

54
SSW
< 1/8
0.040 mi.
212 ft.

SAA, BLDG #105
SALINA AIRPORT
SALINA, KS 67401

KS UST **U003542202**
N/A

Relative:
Higher

Actual:
1261 ft.

UST:

Facility ID:	27197
Facility 911 Address:	SALINA AIRPORT, BLDG 105
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1994-11-15 00:00:00
Capacity (Gals):	25000
Tank Internal Protection:	Cat Prot
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Dan Kneubuhl
Contact Title:	Contact
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1956
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	111994
Material of Construction:	Steel
Petroleum Substance:	Kerosene
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8008-20-6
Latitude:	38.78082
Longitude:	-97.64090

Facility ID:	27197
Facility 911 Address:	SALINA AIRPORT, BLDG 105
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1994-11-15 00:00:00
Capacity (Gals):	25000

SAA, BLDG #105 (Continued) **U003542202**

Tank Internal Protection:	Cat Prot
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Dan Kneubuhl
Contact Title:	Contact
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	002
Tank Status:	Permanently Out Of Use
Installation Year:	1956
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	111994
Material of Construction:	Steel
Petroleum Substance:	Kerosene
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8008-20-6
Latitude:	38.78082
Longitude:	-97.64090

Facility ID:	27197
Facility 911 Address:	SALINA AIRPORT, BLDG 105
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1994-11-15 00:00:00
Capacity (Gals):	25000
Tank Internal Protection:	Cat Prot
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Dan Kneubuhl
Contact Title:	Contact
Owner ID:	27195
Owner Type:	Private Or Corp.

SAA, BLDG #105 (Continued) **U003542202**

Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	003
Tank Status:	Permanently Out Of Use
Installation Year:	1956
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	111994
Material of Construction:	Steel
Petroleum Substance:	Gas (Incl Alcohol)
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.78082
Longitude:	-97.64090

Facility ID:	27197
Facility 911 Address:	SALINA AIRPORT, BLDG 105
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1994-11-15 00:00:00
Capacity (Gals):	25000
Tank Internal Protection:	Cat Prot
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Dan Kneubuhl
Contact Title:	Contact
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	004
Tank Status:	Permanently Out Of Use
Installation Year:	1956

SAA, BLDG #105 (Continued) **U003542202**

Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	111994
Material of Construction:	Steel
Petroleum Substance:	Gas (Incl Alcohol)
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.78082
Longitude:	-97.64090

Facility ID:	27197
Facility 911 Address:	SALINA AIRPORT, BLDG 105
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1994-11-15 00:00:00
Capacity (Gals):	25000
Tank Internal Protection:	Cat Prot
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Dan Kneubuhl
Contact Title:	Contact
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	005
Tank Status:	Permanently Out Of Use
Installation Year:	1956
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	111994
Material of Construction:	Steel
Petroleum Substance:	Gas (Incl Alcohol)
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.78082

SAA, BLDG #105 (Continued) **U003542202**

Longitude:	-97.64090
Facility ID:	27197
Facility 911 Address:	SALINA AIRPORT, BLDG 105
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1994-11-15 00:00:00
Capacity (Gals):	25000
Tank Internal Protection:	Cat Prot
24 Hour Phone Num:	785-827-3914
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-3914
Tank Empty:	Not reported
Contact Name:	Dan Kneubuhl
Contact Title:	Contact
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	006
Tank Status:	Permanently Out Of Use
Installation Year:	1956
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	111994
Material of Construction:	Steel
Petroleum Substance:	Gas (Incl Alcohol)
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.78082
Longitude:	-97.64090

M55 **HAWKER BEECHCRAFT - SALINA** **KS LUST** **1000169247**
NNE **2656 SCANLAN AVENUE** **KS UST** **N/A**
< 1/8 **SALINA, KS 67401** **ICIS**
0.041 mi. **FINDS**
215 ft. **Site 1 of 3 in cluster M**

Relative: LUST:
Lower

Facility ID:	26086
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	06/28/1994

Actual:
1254 ft.

HAWKER BEECHCRAFT - SALINA (Continued) **1000169247**

Project Number:	U5-085-00878
Project Name:	Beech Aero Club
Legal Desc Section:	34
Legal Desc Township:	14S
Legal Desc Range:	03W
Discover Date:	Not reported
substrels:	Not reported
Initial Ranking:	Not reported
Current Ranking:	Not reported
Facility Contact:	Loring Gordon
Facility Phone Number:	785-827-9684
Facility Owner Identification number:	27873
Facility Owner:	Beech Aircraft Corp.
Owner Contact Person:	Loring Gordon
Owner Address:	2656 Scanlan
Owner City:	Salina
Owner State:	KS
Owner Zip Code:	67401
Owner Phone number:	785-827-9684
Contractor license number:	C0035
Contractor phone number:	785-479-2106
Leak duration (if known):	Not reported
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Not reported
Reported By:	Howard Debauche
Reported by persons phone number:	Not reported
Reported by person address:	Ncdo
Ground water Impacted (yes/no):	the area consists primarly of grayish brown silts and silty clay. groundwater was at about 8'.
Static groundwater level:	008
Groundwater flow direction:	Not reported
District staff names:	Howard Debauche
Assessment of release:	1 gasoline ust removed. no staining or odor in or around excavation. sample from bottom showed no measurable contamination present. tank appeared to be in good condition. kdhe considers site closed. no further action required.
Contaimination assessement:	Not reported
Extent of contamination impact:	none suspected.
Updated information:	Not reported
Invoice initiated:	19943
Invoice on going:	Not reported
Invoice completetd:	19943
Release confirmed:	Not reported
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	Not reported
Cost recovery initiated by:	Not reported
Cost recovery completed:	Not reported
Cost recovery completed by:	Not reported
Appplication to trust fund:	Not reported
Facility ID:	81340
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	08/09/1995

HAWKER BEECHCRAFT - SALINA (Continued) **1000169247**

Project Number:	U5-085-10632
Project Name:	Beech, Bldg 655, Tank 98
Legal Desc Section:	34
Legal Desc Township:	14S
Legal Desc Range:	03W
Discover Date:	07/26/1995
substrels:	fuel oil
Initial Ranking:	Not reported
Current Ranking:	Not reported
Facility Contact:	L.l. Hensley
Facility Phone Number:	785-827-9684
Facility Owner Identification number:	27195
Facility Owner:	Salina Airport Authority
Owner Contact Person:	Don Kneubuhl
Owner Address:	3237 Arnold Ave
Owner City:	Salina
Owner State:	KS
Owner Zip Code:	67401
Owner Phone number:	785-827-3914
Contractor license number:	C0211
Contractor phone number:	785-826-9385
Leak duration (if known):	Not reported
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Not reported
Reported By:	Scott Lang
Reported by persons phone number:	Not reported
Reported by person address:	Ncdo
Ground water Impacted (yes/no):	topsoil > silty clay > highly weathered shale
Static groundwater level:	015
Groundwater flow direction:	ENE
District staff names:	Scott Lang
Assessment of release:	leak discovered during in-place abandonment of a 10,000 gal ust. site receives an active status as it didn't appear to be feasible to dig out of the contam. kdhe will require that an investigation be performed to delineate the full extent of contam
Contaimination assessement:	Not reported
Extent of contamination impact:	groundwater contam confirmed extent undetermined. 11-21-95 geoprobe invest performed on 11-7-95 with kdhe on-site determined that contam found in the initial assessment was limited to soils and gw within excav. contam is very isolated & #6 fuel very
Updated information:	Not reported
Invoice initiated:	Not reported
Invoice on going:	Not reported
Invoice completetd:	Not reported
Release confirmed:	Not reported
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	Not reported
Cost recovery initiated by:	Not reported
Cost recovery completed:	Not reported
Cost recovery completed by:	Not reported
Appplication to trust fund:	Not reported
Facility ID:	26086
Site Status:	**Closed**

HAWKER BEECHCRAFT - SALINA (Continued) **1000169247**

Release Date:	Not reported
Initial Report Date:	11/18/1996
Project Number:	U5-085-11219
Project Name:	Beech, Bldg 959
Legal Desc Section:	27
Legal Desc Township:	14S
Legal Desc Range:	03W
Discover Date:	Not reported
substrels:	Not reported
Initial Ranking:	Not reported
Current Ranking:	Not reported
Facility Contact:	Don Kneubuhl
Facility Phone Number:	785-827-3914
Facility Owner Identification number:	27195
Facility Owner:	Salina Airport Authority
Owner Contact Person:	Don Kneubuhl
Owner Address:	3237 Arnold Ave
Owner City:	Salina
Owner State:	KS
Owner Zip Code:	67401
Owner Phone number:	785-826-1616
Contractor license number:	C0332
Contractor phone number:	785-826-1616
Leak duration (if known):	Not reported
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Not reported
Reported By:	Howard Debauche
Reported by persons phone number:	785-827-9639
Reported by person address:	Salina Distr Ofc
Ground water Impacted (yes/no):	grayish brown silty clays
Static groundwater level:	Not reported
Groundwater flow direction:	Not reported
District staff names:	Howard Debauche
Assessment of release:	1 gas ust removed. no stain/odor in/around excavation. sample showed no measurable contamination. tank was in good condition. no further action required. closed.
Contaimination assessement:	Not reported
Extent of contamination impact:	Not reported
Updated information:	Not reported
Invoice initiated:	19971
Invoice on going:	Not reported
Invoice completetd:	19971
Release confirmed:	Not reported
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	Not reported
Cost recovery initiated by:	Not reported
Cost recovery completed:	Not reported
Cost recovery completed by:	Not reported
Appplication to trust fund:	Not reported

UST:

Facility ID:	26086
Facility 911 Address:	2656 SCANLAN AVE
Facility 911 City:	SALINA

HAWKER BEECHCRAFT - SALINA (Continued) **1000169247**

Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1994-06-15 00:00:00
Capacity (Gals):	500
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-827-9684
Tank External Protection:	Painted
Piping:	Galv Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-9684
Tank Empty:	Not reported
Contact Name:	L L Hensley
Contact Title:	Maintenance Foreman
Owner ID:	27873
Owner Type:	Private Or Corp.
Owner Name:	BEECH AIRCRAFT CORPORATION
Owner Address:	2656 SCANLAN
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	7858279684
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1982
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	061994
Material of Construction:	Steel
Petroleum Substance:	Gas (Incl Alcohol)
Owner Replacement Name:	Dick Tilgner
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.80761
Longitude:	-97.63820

Facility ID:	26086
Facility 911 Address:	2656 SCANLAN AVE
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1996-11-15 00:00:00
Capacity (Gals):	400
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-827-9684
Tank External Protection:	Unknown
Piping:	Other
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-827-9684
Tank Empty:	Not reported

HAWKER BEECHCRAFT - SALINA (Continued) **1000169247**

Contact Name:	L L Hensley
Contact Title:	Maintenance Foreman
Owner ID:	27873
Owner Type:	Private Or Corp.
Owner Name:	BEECH AIRCRAFT CORPORATION
Owner Address:	2656 SCANLAN
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	7858279684
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	002
Tank Status:	Permanently Out Of Use
Installation Year:	1957
Last Permit Printed:	1996-06-17 00:00:00
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	111996
Material of Construction:	Steel
Petroleum Substance:	Gas (Incl Alcohol)
Owner Replacement Name:	Dick Tilgner
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.80761
Longitude:	-97.63820

ICIS:

Enforcement Action ID:	07-2000-0421
FRS ID:	110011726374
Action Name:	RAYTHEON AIRCRAFT COMPANY, SALINA, KS
Facility Name:	RAYTHEON AIRCRAFT CORPORATION BEECH
Facility Address:	2656 SCANLAN AVE. SALINA, KS 67401
Enforcement Action Type:	RCRA 3008A AO For Comp And/Or Penalty
Facility County:	SALINE
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	3008A
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	38.791658
Longitude in Decimal Degrees:	-97.636163
Permit Type Desc:	Not reported
Program System Acronym:	14221
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Facility Name:	RAYTHEON AIRCRAFT CO SALINA DIV
Address:	2656 SCANLAN AVENUE
Tribal Indicator:	N
Fed Facility:	No
NAIC Code:	Not reported

HAWKER BEECHCRAFT - SALINA (Continued) **1000169247**

SIC Code: Not reported

Facility Name: RAYTHEON AIRCRAFT CO SALINA DIV
Address: 2656 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: RAYTHEON AIRCRAFT CO SALINA DIV
Address: 2656 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: RAYTHEON AIRCRAFT CO SALINA DIV
Address: 2656 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: RAYTHEON AIRCRAFT CO SALINA DIV
Address: 2656 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: RAYTHEON AIRCRAFT CO SALINA DIV
Address: 2656 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: RAYTHEON AIRCRAFT CO SALINA DIV
Address: 2656 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: RAYTHEON AIRCRAFT CO SALINA DIV
Address: 2656 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: RAYTHEON AIRCRAFT CO SALINA DIV
Address: 2656 SCANLAN AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

FINDS:

Registry ID: 110063869504

Environmental Interest/Information System
US National Pollutant Discharge Elimination System (NPDES) module of

HAWKER BEECHCRAFT - SALINA (Continued) **1000169247**

the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Registry ID: 110011726374

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

KS-FP (Kansas - Facility Profiler) is a geographically-based data warehouse site that presents information about facilities and locations of interest to the KDHE. This site has in excess of twenty environmental interest which contains information on closed facilities, completed cleanups, and past operations as well as data on current operations and activities.

AIR EMISSIONS CLASSIFICATION UNKNOWN

AIR SYNTHETIC MINOR

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

OSHA ESTABLISHMENT

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ICIS (Integrated Compliance Information System) is the Integrated

HAWKER BEECHCRAFT - SALINA (Continued) **1000169247**

Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

M56 **BEECH SALINA AIRPORT** **KS LUST** **S106423195**
NNE **SALINA AIRPORT** **KS TIER 2** **N/A**
< 1/8 **SALINA, KS 67401**
0.041 mi.
215 ft. **Site 2 of 3 in cluster M**

Relative: **Lower**

Actual: **1254 ft.**

LUST:

Facility ID:	81340
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	08/09/1995
Project Number:	U5-085-10635
Project Name:	Beech, Bldg 959, Tank 110/111
Legal Desc Section:	27
Legal Desc Township:	14S
Legal Desc Range:	03W
Discover Date:	08/07/1995
substrels:	fuel oil
Initial Ranking:	Not reported
Current Ranking:	Not reported
Facility Contact:	L.l. Hensley
Facility Phone Number:	785-827-9684
Facility Owner Identification number:	27195
Facility Owner:	Salina Airport Authority
Owner Contact Person:	Don Kneubuhl
Owner Address:	3237 Arnold Ave
Owner City:	Salina
Owner State:	KS
Owner Zip Code:	67401
Owner Phone number:	785-827-3914
Contractor license number:	C0211
Contractor phone number:	785-826-9385
Leak duration (if known):	Not reported
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Not reported
Reported By:	Howard Debauche
Reported by persons phone number:	Not reported
Reported by person address:	Ncdo
Ground water Impacted (yes/no):	topsoil > silty clay > highly weathered shale

BEECH SALINA AIRPORT (Continued) **S106423195**

Static groundwater level:	015
Groundwater flow direction:	ENE
District staff names:	Scott Lang
Assessment of release:	2-ust removed. some soils exhibited slight petro odors but were determined to be below the kals. kdhe will allow this soil to be placed back in to the excavation. this site receives a closed status.
Contaimination assessement:	Not reported
Extent of contamination impact:	none suspected as a result of releases from this system. groundwater may be contam via other sources.
Updated information:	Not reported
Invoice initiated:	Not reported
Invoice on going:	Not reported
Invoice completetd:	Not reported
Release confirmed:	Not reported
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	Not reported
Cost recovery initiated by:	Not reported
Cost recovery completed:	Not reported
Cost recovery completed by:	Not reported
Appplication to trust fund:	Not reported

TIER 2:

Facility Id:	364944
Facility Phone:	(785)827-9684
FID Num:	SA00023
PID Num:	KS0004
NAICS:	336411
Report Year:	2011
New Facility:	Not reported
Nearest Cross Street:	N SCANLAN & LUCAS ST
SIC Code:	3721
Section Code:	312
Emergency Name1:	CHRIS LADWIG
Emergency Title1:	DIRECTOR ENVIRONMENTAL HEALTH AND SAFETY
Emergency Phone1:	(316)676-2848
Emergency 24phone1:	(316)676-6911
Emergency Name2:	DARWIN DYKES
Emergency Title2:	MGR EHS - SALINA
Emergency Phone2:	(785)820-2405
Emergency 24phone2:	(785)820-2200
Submitter:	Not reported
Created:	Not reported
Updated:	1/12/2012 2:31:47 PM
Rep Name:	Chris Ladwig
Rep Title:	Director of EHS
Zip Field:	Not reported
Facility Latitude:	Not reported
Facility Longitude:	Not reported
Emergency Email1:	Not reported
Emergency Email2:	Not reported
Tier2 Contact Name:	Not reported
Tier2 Title:	Not reported
Tier2 Phone:	Not reported
Tier2 Phone24:	Not reported
Tier2 EMail:	Not reported

BEECH SALINA AIRPORT (Continued) **S106423195**

Annual Revision:	Not reported
Max Occupants:	Not reported
Manned/Unmanned:	Not reported
Section:	Not reported
Township:	Not reported
Range0:	Not reported
Trifids:	Not reported
RMP Facid:	Not reported
Subject 302:	Not reported
Subject 112:	Not reported

Chemical:

FID Num:	SA00023
Chemical Id:	860259
Chemical Name:	GASOLINE
CAS:	8006619
Trade Secret:	No
EHS:	Not reported
Solid:	Not reported
Liquid:	Yes
Gas:	Not reported
Pure:	Not reported
Mix:	Yes
Fire:	Yes
Pressure:	Not reported
Reactive:	Not reported
Delayed:	Not reported
Immediate:	Yes
Max Daily Amt:	9529
Avg Daily Amt:	6572
Days On Site:	365
Opt Report:	1

Storage:

Fid Num:	SA00023
Chemical Name:	GASOLINE
Storage Id:	1213559
Container:	Above Ground Tank
Pressure:	Ambient pressure
Temperature:	Ambient temperature
Storage Location:	TANK SOUTH SIDE OF B-606

Fid Num:	SA00023
Chemical Name:	GASOLINE
Storage Id:	1213559
Container:	Above Ground Tank
Pressure:	Ambient pressure
Temperature:	Ambient temperature
Storage Location:	TANK SOUTH SIDE OF B-606

FID Num:	SA00023
Chemical Id:	860260
Chemical Name:	PROPANE
CAS:	74986
Trade Secret:	No
EHS:	Not reported

BEECH SALINA AIRPORT (Continued) **S106423195**

Solid: Not reported
Liquid: Yes
Gas: Yes
Pure: Yes
Mix: Not reported
Fire: Yes
Pressure: Yes
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 4950
Avg Daily Amt: 4330
Days On Site: 365
Opt Report: 1

Storage:
Fid Num: SA00023
Chemical Name: PROPANE
Storage Id: 1213560
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: SOUTH OF BLDG 713

Fid Num: SA00023
Chemical Name: PROPANE
Storage Id: 1213560
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: SOUTH OF BLDG 713

FID Num: SA00023
Chemical Id: 860259
Chemical Name: GASOLINE
CAS: 8006619
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Not reported
Pure: Not reported
Mix: Yes
Fire: Yes
Pressure: Not reported
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 9529
Avg Daily Amt: 6572
Days On Site: 365
Opt Report: 1

Storage:
Fid Num: SA00023
Chemical Name: GASOLINE
Storage Id: 1213559

BEECH SALINA AIRPORT (Continued) **S106423195**

Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: TANK SOUTH SIDE OF B-606

Fid Num: SA00023
Chemical Name: GASOLINE
Storage Id: 1213559
Container: Above Ground Tank
Pressure: Ambient pressure
Temperature: Ambient temperature
Storage Location: TANK SOUTH SIDE OF B-606

FID Num: SA00023
Chemical Id: 860260
Chemical Name: PROPANE
CAS: 74986
Trade Secret: No
EHS: Not reported
Solid: Not reported
Liquid: Yes
Gas: Yes
Pure: Yes
Mix: Not reported
Fire: Yes
Pressure: Yes
Reactive: Not reported
Delayed: Not reported
Immediate: Yes
Max Daily Amt: 4950
Avg Daily Amt: 4330
Days On Site: 365
Opt Report: 1

Storage:
Fid Num: SA00023
Chemical Name: PROPANE
Storage Id: 1213560
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: SOUTH OF BLDG 713

Fid Num: SA00023
Chemical Name: PROPANE
Storage Id: 1213560
Container: Above Ground Tank
Pressure: Greater than ambient pressure
Temperature: Ambient temperature
Storage Location: SOUTH OF BLDG 713

M57
NNE
< 1/8
0.041 mi.
215 ft.

TISCHLEREI - FINE WOODWORKING LLC
2656 SCANLAN AVE
SALINA, KS 67401

Site 3 of 3 in cluster M

RCRA-SQG **1007093923** **KSD049995426**

Relative:
Lower

Actual:
1254 ft.

RCRA-SQG:

Date form received by agency:	02/20/2018
Facility name:	TISCHLEREI - FINE WOODWORKING LLC
Facility address:	2656 SCANLAN AVE SALINA, KS 67401
EPA ID:	KSD049995426
Contact:	OLAF GERHARDT
Contact address:	2656 SCANLAN AVE SALINA, KS 67401
Contact country:	US
Contact telephone:	785-404-3322
Contact email:	OLAF.GERHARDT@TFW-LLC.COM
EPA Region:	07
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	TISCHLEREI-FINE WOODWORKING LLC
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	05/01/2012
Owner/Op end date:	Not reported

Owner/operator name:	SALINA AIRPORT AUTHORITY
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2000
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No

TISCHLEREI - FINE WOODWORKING LLC (Continued) **1007093923**

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 02/06/2017
Site name: TISCHLEREI - FINE WOODWORKING LLC
Classification: Small Quantity Generator

Date form received by agency: 02/09/2016
Site name: TISCHLEREI - FINE WOODWORKING LLC
Classification: Small Quantity Generator

Date form received by agency: 03/23/2015
Site name: TISCHLEREI - FINE WOODWORKING LLC
Classification: Small Quantity Generator

Date form received by agency: 05/02/2014
Site name: TISCHLEREI - FINE WOODWORKING LLC
Classification: Small Quantity Generator

Date form received by agency: 03/28/2013
Site name: TISCHLEREI-FINE WOODWORKING LLC
Classification: Small Quantity Generator

Date form received by agency: 07/27/2012
Site name: TISCHLEREI-FINE WOODWORKING LLC
Classification: Small Quantity Generator

Date form received by agency: 02/28/2012
Site name: HAWKER BEECHCRAFT CORPORATION
Classification: Large Quantity Generator

Date form received by agency: 02/28/2012
Site name: HAWKER BEECHCRAFT CORP
Classification: Large Quantity Generator

Date form received by agency: 02/15/2011
Site name: HAWKER BEECHCRAFT CORP
Classification: Large Quantity Generator

Date form received by agency: 02/22/2010
Site name: HAWKER BEECHCRAFT CORPORATION
Classification: Large Quantity Generator

Date form received by agency: 02/22/2010
Site name: HAWKER BEECHCRAFT CORP
Classification: Large Quantity Generator

TISCHLEREI - FINE WOODWORKING LLC (Continued) **1007093923**

Date form received by agency: 02/18/2009
Site name: HAWKER BEECHCRAFT CORP
Classification: Large Quantity Generator

Date form received by agency: 02/04/2008
Site name: HAWKER BEECHCRAFT CORP
Classification: Large Quantity Generator

Date form received by agency: 01/31/2008
Site name: HAWKER BEECHCRAFT CORP
Classification: Large Quantity Generator

Date form received by agency: 02/23/2007
Site name: RAYTHEON AIRCRAFT CO
Classification: Large Quantity Generator

Date form received by agency: 02/17/2006
Site name: RAYTHEON AIRCRAFT CO
Classification: Large Quantity Generator

Date form received by agency: 02/10/2006
Site name: RAYTHEON AIRCRAFT CO
Classification: Large Quantity Generator

Date form received by agency: 01/25/2005
Site name: RAYTHEON AIRCRAFT CO
Classification: Large Quantity Generator

Date form received by agency: 03/16/2004
Site name: RAYTHEON AIRCRAFT CO
Classification: Large Quantity Generator

Date form received by agency: 03/01/2004
Site name: RAYTHEON AIRCRAFT CO
Classification: Large Quantity Generator

Date form received by agency: 02/21/2003
Site name: RAYTHEON AIRCRAFT CO
Classification: Large Quantity Generator

Date form received by agency: 08/29/2002
Site name: RAYTHEON AIRCRAFT CO
Classification: Large Quantity Generator

Date form received by agency: 02/28/2002
Site name: RAYTHEON AIRCRAFT CO
Classification: Large Quantity Generator

Date form received by agency: 01/25/2002
Site name: RAYTHEON AIRCRAFT CO
Classification: Large Quantity Generator

Date form received by agency: 11/02/2001
Site name: RAYTHEON AIRCRAFT CO
Classification: Large Quantity Generator

Date form received by agency: 02/21/2001

TISCHLEREI - FINE WOODWORKING LLC (Continued) **1007093923**

Site name: RAYTHEON AIRCRAFT CO - SALINA
Classification: Large Quantity Generator

Date form received by agency: 01/16/2001
Site name: RAYTHEON AIRCRAFT CO
Classification: Large Quantity Generator

Date form received by agency: 01/28/2000
Site name: RAYTHEON AIRCRAFT CO
Classification: Large Quantity Generator

Date form received by agency: 01/26/2000
Site name: RAYTHEON AIRCRAFT CO
Classification: Large Quantity Generator

Date form received by agency: 02/25/1994
Site name: BEECH AIRCRAFT CORPORATION
Classification: Large Quantity Generator

Date form received by agency: 03/28/1990
Site name: BEECH AIRCRAFT CORPORATION
Classification: Large Quantity Generator

Date form received by agency: 10/07/1980
Site name: RAYTHEON AIRCRAFT CO
Classification: Not a generator, verified

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D018
. Waste name: BENZENE

. Waste code: D028

TISCHLEREI - FINE WOODWORKING LLC (Continued) **1007093923**

. Waste name: 1,2-DICHLOROETHANE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D036
. Waste name: NITROBENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U223
. Waste name: BENZENE, 1,3-DIISOCYANATOMETHYL- (R,T) (OR) TOLUENE DIISOCYANATE (R,T)

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: TSD IS-Container Use and Management
Date violation determined: 09/17/2009
Date achieved compliance: 10/09/2009
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 01/24/2011
Enf. disposition status: Action Satisfied (Case Closed)

TISCHLEREI - FINE WOODWORKING LLC (Continued) **1007093923**

Enf. disp. status date: 02/24/2011
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 16500
Paid penalty amount: 16500

Regulation violated: Not reported
Area of violation: TSD IS-General Facility Standards
Date violation determined: 09/17/2009
Date achieved compliance: 03/17/2010
Violation lead agency: State
Enforcement action: LETTER OF INTENT TO INITIATE ENFORCEMENT ACTION
Enforcement action date: 01/29/2010
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 09/17/2009
Date achieved compliance: 09/17/2009
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 01/24/2011
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 02/24/2011
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 16500
Paid penalty amount: 16500

Regulation violated: Not reported
Area of violation: TSD IS-Container Use and Management
Date violation determined: 09/17/2009
Date achieved compliance: 10/09/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/13/2009
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Container Use and Management
Date violation determined: 09/17/2009
Date achieved compliance: 10/09/2009
Violation lead agency: State
Enforcement action: LETTER OF INTENT TO INITIATE ENFORCEMENT ACTION
Enforcement action date: 01/29/2010
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

TISCHLEREI - FINE WOODWORKING LLC (Continued) **1007093923**

Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Container Use and Management
Date violation determined: 09/17/2009
Date achieved compliance: 10/09/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/24/2009
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-General Facility Standards
Date violation determined: 09/17/2009
Date achieved compliance: 03/17/2010
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 01/24/2011
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 02/24/2011
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 16500
Paid penalty amount: 16500

Regulation violated: Not reported
Area of violation: Federal or State Statute
Date violation determined: 09/17/2009
Date achieved compliance: 09/17/2009
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 01/24/2011
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 02/24/2011
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 16500
Paid penalty amount: 16500

Regulation violated: Not reported
Area of violation: TSD IS-General Facility Standards
Date violation determined: 09/17/2009
Date achieved compliance: 03/17/2010
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/24/2009
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State

TISCHLEREI - FINE WOODWORKING LLC (Continued) **1007093923**

Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-General Facility Standards
Date violation determined: 09/17/2009
Date achieved compliance: 03/17/2010
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/13/2009
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Federal or State Statute
Date violation determined: 09/17/2009
Date achieved compliance: 09/17/2009
Violation lead agency: State
Enforcement action: LETTER OF INTENT TO INITIATE ENFORCEMENT ACTION
Enforcement action date: 01/29/2010
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-General Facility Standards
Date violation determined: 09/17/2009
Date achieved compliance: 03/17/2010
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/17/2010
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-General Facility Standards
Date violation determined: 09/17/2009
Date achieved compliance: 03/17/2010
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/05/2010
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported

TISCHLEREI - FINE WOODWORKING LLC (Continued) **1007093923**

Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 09/17/2009
Date achieved compliance: 09/17/2009
Violation lead agency: State
Enforcement action: LETTER OF INTENT TO INITIATE ENFORCEMENT ACTION
Enforcement action date: 01/29/2010
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 j 1 A
Area of violation: Generators - Pre-transport
Date violation determined: 09/19/2005
Date achieved compliance: 10/04/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/21/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 j 1 A
Area of violation: Generators - Pre-transport
Date violation determined: 09/19/2005
Date achieved compliance: 10/04/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/28/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 g1
Area of violation: Generators - Pre-transport
Date violation determined: 08/06/2002
Date achieved compliance: 08/26/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/03/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported

TISCHLEREI - FINE WOODWORKING LLC (Continued) **1007093923**

Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 g 1
Area of violation: Generators - Pre-transport
Date violation determined: 08/06/2002
Date achieved compliance: 08/26/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/03/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 g 1
Area of violation: Generators - Pre-transport
Date violation determined: 08/06/2002
Date achieved compliance: 08/26/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/06/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 c
Area of violation: Generators - General
Date violation determined: 08/06/2002
Date achieved compliance: 08/06/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/06/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 g 2
Area of violation: Generators - Pre-transport
Date violation determined: 08/06/2002
Date achieved compliance: 08/06/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/06/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

TISCHLEREI - FINE WOODWORKING LLC (Continued) **1007093923**

Regulation violated: SR - KAR 28 31 4 g 3
Area of violation: Generators - Pre-transport
Date violation determined: 08/06/2002
Date achieved compliance: 08/06/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/06/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 d
Area of violation: Generators - Manifest
Date violation determined: 08/06/2002
Date achieved compliance: 08/06/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/06/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 g1
Area of violation: Generators - Pre-transport
Date violation determined: 08/06/2002
Date achieved compliance: 08/26/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/06/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 j
Area of violation: Generators - Pre-transport
Date violation determined: 08/06/2002
Date achieved compliance: 08/06/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/06/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28-31-4(j), CFR 270.1(b)

TISCHLEREI - FINE WOODWORKING LLC (Continued) **1007093923**

Area of violation: Generators - Pre-transport
Date violation determined: 01/26/2000
Date achieved compliance: 02/10/2000
Violation lead agency: EPA
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 09/18/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: 20845
Paid penalty amount: 20845

Regulation violated: SR - KAR 28-31-4(b), CFR 261.2
Area of violation: Generators - General
Date violation determined: 01/26/2000
Date achieved compliance: 02/10/2000
Violation lead agency: EPA
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 06/30/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 30469
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28-31-4(d)
Area of violation: Generators - Manifest
Date violation determined: 01/26/2000
Date achieved compliance: 02/10/2000
Violation lead agency: EPA
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 09/18/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: 20845
Paid penalty amount: 20845

Regulation violated: SR - KAR 28-31-4(d)
Area of violation: Generators - Manifest
Date violation determined: 01/26/2000
Date achieved compliance: 02/10/2000
Violation lead agency: EPA
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 06/30/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 30469
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28-31-4(j), CFR 270.1(b)
Area of violation: Generators - Pre-transport

TISCHLEREI - FINE WOODWORKING LLC (Continued) **1007093923**

Date violation determined: 01/26/2000
Date achieved compliance: 02/10/2000
Violation lead agency: EPA
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 06/30/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 30469
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28-31-4(b), CFR 261.2
Area of violation: Generators - General
Date violation determined: 01/26/2000
Date achieved compliance: 02/10/2000
Violation lead agency: EPA
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 09/18/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: 20845
Paid penalty amount: 20845

Regulation violated: SR - KAR 28 31 4 J
Area of violation: Generators - Pre-transport
Date violation determined: 01/03/1997
Date achieved compliance: 01/03/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/03/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 14
Area of violation: LDR - General
Date violation determined: 01/03/1997
Date achieved compliance: 01/10/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/03/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/25/1990

TISCHLEREI - FINE WOODWORKING LLC (Continued) **1007093923**

Date achieved compliance: 02/23/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/26/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 01/25/1990
Date achieved compliance: 01/26/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/26/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 12/06/1985
Date achieved compliance: 12/19/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/30/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 02/20/2014
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/24/2011
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/17/2010
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

TISCHLEREI - FINE WOODWORKING LLC (Continued) **1007093923**

Evaluation date: 01/05/2010
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/18/2009
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/13/2009
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/17/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Container Use and Management
Date achieved compliance: 10/09/2009
Evaluation lead agency: State

Evaluation date: 09/17/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-General Facility Standards
Date achieved compliance: 03/17/2010
Evaluation lead agency: State

Evaluation date: 09/17/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Federal or State Statute
Date achieved compliance: 09/17/2009
Evaluation lead agency: State

Evaluation date: 09/17/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 09/17/2009
Evaluation lead agency: State

Evaluation date: 10/21/2005
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/19/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 10/04/2005
Evaluation lead agency: State

Evaluation date: 09/03/2002
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported

TISCHLEREI - FINE WOODWORKING LLC (Continued) **1007093923**

Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 08/06/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 08/06/2002
Evaluation lead agency: State

Evaluation date: 08/06/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/06/2002
Evaluation lead agency: State

Evaluation date: 08/06/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 08/26/2002
Evaluation lead agency: State

Evaluation date: 08/06/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 08/06/2002
Evaluation lead agency: State

Evaluation date: 09/18/2000
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 01/27/2000
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 01/26/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 02/10/2000
Evaluation lead agency: EPA

Evaluation date: 01/26/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 02/10/2000
Evaluation lead agency: EPA

Evaluation date: 01/26/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 02/10/2000
Evaluation lead agency: EPA

TISCHLEREI - FINE WOODWORKING LLC (Continued) **1007093923**

Evaluation date: 01/11/1997
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/03/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 01/10/1997
Evaluation lead agency: State

Evaluation date: 01/03/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 01/03/1997
Evaluation lead agency: State

Evaluation date: 03/07/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/26/1990
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/25/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 01/26/1990
Evaluation lead agency: State

Evaluation date: 01/25/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 02/23/1990
Evaluation lead agency: State

Evaluation date: 02/22/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/06/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 12/19/1986
Evaluation lead agency: State

N58 **PONY EXPRESS COURIER CORP** **KS UST** **U000873752**
SSW **3119 ARNOLD** **N/A**
< 1/8 **SALINA, KS 67401**
0.041 mi.
217 ft. **Site 1 of 3 in cluster N**

Relative: **Higher**

Actual: **1260 ft.**

UST:

Facility ID:	27569
Facility 911 Address:	3199 ARNOLD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1988-08-15 00:00:00
Capacity (Gals):	2000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-825-8136
Tank External Protection:	Unknown
Piping:	Unknown
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-825-8136
Tank Empty:	Not reported
Contact Name:	Von Scarrow
Contact Title:	Terminal Manager
Owner ID:	28030
Owner Type:	Not reported
Owner Name:	PONY EXPRESS COURIER CORP
Owner Address:	3119 ARNOLD
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	Not reported
Owner Phone:	7858258136
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1966
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	081988
Material of Construction:	Unknown
Petroleum Substance:	Gas (Incl Alcohol)
Owner Replacement Name:	Jim Johnston
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.78093
Longitude:	-97.63970

N59 **SALINA AIRPORT CELL TOWER** **KS AST** **A100320383**
SSW **3119 ARNOLD AVE.** **N/A**
< 1/8 **SALINA, KS 67401**
0.041 mi.
217 ft. **Site 2 of 3 in cluster N**

Relative:
Higher

Actual:
1260 ft.

AST:

Facility ID:	44585
Facility 911 Address:	3119 ARNOLD AVE.
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	2012
Tank Internal Protection:	Not reported
24 Hour Phone Num:	800-510-6091
Tank External Protection:	Painted
Piping:	Other
Facility Location Method:	Not reported
Facility Feature:	Not reported
Facility Phone:	773-355-3717
Tank Empty:	Not reported
Contact Name:	JOHN MATTHEWS
Contact Title:	Not reported
Owner ID:	44585
Owner Type:	Private Or Corp.
Owner Name:	U.S. CELLULAR %J.MATTHEWS
Owner Address:	PO BOX 628430
Owner City:	MIDDLETON
Owner State:	WI
Owner Zip:	53562-8430
Owner County:	SALINE
Owner Phone:	918-906-3983
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Current In Use
Installation Year:	2008
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-11 00:00:00
Facility Datum:	Not reported
Out of service Mo/Yr:	Not reported
Material of Construction:	Double Wall
Petroleum Substance:	Diesel Clear
Owner Replacement Name:	JOHN MATTHEWS
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	68476-34-6
Latitude:	Not reported
Longitude:	Not reported

N60 **SALINA AIRPORT AUTHORITY, HERTZ** **KS LUST** **S106423158**
SSW **3119-B ARNOLD AVE** **N/A**
< 1/8 **SALINA, KS 67401**
0.041 mi.
217 ft. **Site 3 of 3 in cluster N**

Relative:
Higher

Actual:
1260 ft.

LUST:

Facility ID:	80344
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	04/19/1991
Project Number:	U5-085-00668
Project Name:	Saa, Hertz Facility
Legal Desc Section:	03
Legal Desc Township:	15S
Legal Desc Range:	03W
Discover Date:	04/19/1991
substrels:	gasoline
Initial Ranking:	Not reported
Current Ranking:	Not reported
Facility Contact:	Donald Kneubuhl
Facility Phone Number:	785-827-3914
Facility Owner Identification number:	Not reported
Facility Owner:	Salina Airport Authority
Owner Contact Person:	Not reported
Owner Address:	3237 Arnold Ave, Salina
Owner City:	Not reported
Owner State:	KS
Owner Zip Code:	67401
Owner Phone number:	785-827-3914
Contractor license number:	Not reported
Contractor phone number:	785-827-3804
Leak duration (if known):	Ukwn
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Spill/Overfill
Reported By:	Scott Lang, Kdhe Ncdo
Reported by persons phone number:	Not reported
Reported by person address:	Ncdo
Ground water Impacted (yes/no):	alluvial deposits with relatively shallow groundwater. gw suspected at about 10'.
Static groundwater level:	Not reported
Groundwater flow direction:	Not reported
District staff names:	Scott Lang
Assessment of release:	1-1000 gal gas ust & lines removed. contam fill & soils encountered. dug out of contam @ ~9'. water seeped into excv, had sheen, probably from contam soils that fell into water. pumped excv & recharge water had no sheen or odors. no further action.
Contaimination assessement:	note: the pony express (state trust fund site) is located just upgradient to the west.
Extent of contamination impact:	none suspected.
Updated information:	Not reported
Invoice initiated:	19913
Invoice on going:	Not reported
Invoice completetd:	19913
Release confirmed:	19913
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported

SALINA AIRPORT AUTHORITY, HERTZ (Continued) **S106423158**

Cost recovery initiated:	19913
Cost recovery initiated by:	Responsible Party
Cost recovery completed:	19913
Cost recovery completed by:	Responsible Party
Appplication to trust fund:	Not reported

L61 **SALINA AIRPORT REDEVELOPMENT BTA** **US BROWNFIELDS** **1009324729**
NNW **2720 ARNOLD AVE** **FINDS** **N/A**
< 1/8 **SALINA, KS 67401**
0.042 mi.
221 ft. **Site 2 of 3 in cluster L**

Relative: **Higher**
Actual: **1259 ft.**

US BROWNFIELDS:

Name:	SALINA AIRPORT REDEVLOPMENT PROJECT, AREA 5
Address:	2720 ARNOLD ROAD
City,State,Zip:	SALINA, KS 67401
Recipient Name:	Kansas Department of Health and Environment
Grant Type:	Section 128(a) State/Tribal
Property Number:	08508834040060010001 Area 5
Parcel size:	2.98
Latitude:	38.79045
Longitude:	-97.64017
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	32921
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3664
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	98726201
Start Date:	02/24/2006 00:00:00
Ownership Entity:	Government
Completion Date:	02/24/2006 00:00:00
Current Owner:	Salina Airport Authority
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported

SALINA AIRPORT REDEVELOPMENT BTA (Continued) **1009324729**

IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported

SALINA AIRPORT REDEVELOPMENT BTA (Continued) **1009324729**

mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Former Pump House
Below Poverty Number:	34
Below Poverty Percent:	20.6%
Meidan Income:	360
Meidan Income Number:	70
Meidan Income Percent:	42.4%
Vacant Housing Number:	4
Vacant Housing Percent:	6.4%
Unemployed Number:	5
Unemployed Percent:	3.0%

FINDS:

Registry ID: 110024379607

Environmental Interest/Information System

KS-FP (Kansas - Facility Profiler) is a geographically-based data warehouse site that presents information about facilities and locations of interest to the KDHE. This site has in excess of twenty environmental interest which contains information on closed facilities, completed cleanups, and past operations as well as data on current operations and activities.

Registry ID: 110038753532

Environmental Interest/Information System

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

SALINA AIRPORT REDEVELOPMENT BTA (Continued) **1009324729**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

L62
NNW
< 1/8
0.042 mi.
221 ft.

SALINA AIRPORT REDEVELOPMENT BTA **KS SHWS** **S107554637**
2720 ARNOLD COURT **N/A**
SALINA, KS

Site 3 of 3 in cluster L

Relative:
Higher

Actual:
1259 ft.

SHWS:

Site ID:	2035
Has Env Use Control:	No
Project code:	C508572093
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.791134 / -97.640652
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	<5 acres
Waste Present:	No
Product Present:	No
Program:	FUDS (Formerly Used Defense Sites)
Lead Agency:	BER - Remedial
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Resolved
Activity Status:	Completed
Activity Start Date:	Not reported
Activity End Date:	01/08/2016
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Property Redevelopment Assessment (PRA) at the Salina Airport Redevelopment Area located at 2720 Arnold Court. The PRA was funded

SALINA AIRPORT REDEVELOPMENT BTA (Continued) **S107554637**

through a portion of the KDHE's Brownfields Program. The property was part of the Former Schilling Air Force Base and is located in the area of the former pumphouse No.3. The propery has been proposed for redevelopment as executive hangars and crew quarters. The Former Schilling Air Force Base is categorized as a Formerly Used Defense Site (FUDS). The Army Corps of Engineers generally investigates Department of Defense (DOD) source areas within a FUDS site. Several areas within the former Schilling Air Force Base are currently being addressed through the FUDS
program.
A Phase I assessment was completed for the property in February 2006 . Due to activities at the former pumphouse, the report determined historical activities may have impacted this property with environmental contamination and a Phase II assessment was recommended.
The area surrounding this redevelopment project is part of the Schil ling Air Force Base site (C5-085-03013) which is currently enrolled in the KDHE State Cooperative Program to address soil and groundwater contamination associated with associated with historical operations as an air force base. Therefore, this site is consdiered resolved under the Brownfields Program. Notwithstanding, the groundwater contaminant plumes associated with the Schilling AFB Site have the potential to migrate overtime and it is recommended that best management practices be carried out during future uses at the property.

Site ID:	2035
Has Env Use Control:	No
Project code:	C508572093
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.791134 / -97.640652
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	<5 acres
Waste Present:	No
Product Present:	No
Program:	FUDS (Formerly Used Defense Sites)
Lead Agency:	BER - Remedial
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported

SALINA AIRPORT REDEVELOPMENT BTA (Continued) **S107554637**

Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Resolved
Activity Status:	Completed
Activity Start Date:	Not reported
Activity End Date:	01/08/2016
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Property Redevelopment Assessment (PRA) at the Salina Airport Redevelopment Area located at 2720 Arnold Court. The PRA was funded through a portion of the KDHE's Brownfields Program. The property was part of the Former Schilling Air Force Base and is located in the area of the former pumphouse No.3. The propery has been proposed for redevelopment as executive hangars and crew quarters. The Former Schilling Air Force Base is categorized as a Formerly Used Defense Site (FUDS). The Army Corps of Engineers generally investigates Department of Defense (DOD) source areas within a FUDS site. Several areas within the former Schilling Air Force Base are currently being addressed through the FUDS program. A Phase I assessment was completed for the property in February 2006 . Due to activities at the former pumphouse, the report determined historical activities may have impacted this property with environmental contamination and a Phase II assessment was recommended. The area surrounding this redevelopment project is part of the Schil ling Air Force Base site (C5-085-03013) which is currently enrolled in the KDHE State Cooperative Program to address soil and groundwater contamination associated with associated with historical operations as an air force base. Therefore, this site is consdiered resolved under the Brownfields Program. Notwithstanding, the groundwater contaminant plumes associated with the Schilling AFB Site have the potential to migrate overtime and it is recommended that best management practices be carried out during future uses at the property.

Site ID:	2035
Has Env Use Control:	No
Project code:	C508572093
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.791134 / -97.640652
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported

SALINA AIRPORT REDEVELOPMENT BTA (Continued) **S107554637**

Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	<5 acres
Waste Present:	No
Product Present:	No
Program:	FUDS (Formerly Used Defense Sites)
Lead Agency:	BER - Remedial
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Resolved
Activity Status:	Completed
Activity Start Date:	Not reported
Activity End Date:	01/08/2016
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Property Redevelopment Assessment (PRA) at the Salina Airport Redevelopment Area located at 2720 Arnold Court. The PRA was funded through a portion of the KDHE's Brownfields Program. The property was part of the Former Schilling Air Force Base and is located in the area of the former pumphouse No.3. The propery has been proposed for redevelopment as executive hangars and crew quarters. The Former Schilling Air Force Base is categorized as a Formerly Used Defense Site (FUDS). The Army Corps of Engineers generally investigates Department of Defense (DOD) source areas within a FUDS site. Several areas within the former Schilling Air Force Base are currently being addressed through the FUDS program. A Phase I assessment was completed for the property in February 2006 . Due to activities at the former pumphouse, the report determined historical activities may have impacted this property with environmental contamination and a Phase II assessment was recommended. The area surrounding this redevelopment project is part of the Schil ling Air Force Base site (C5-085-03013) which is currently enrolled in the KDHE State Cooperative Program to address soil and groundwater contamination associated with associated with historical operations as an air force base. Therefore, this site is consdiered resolved under the Brownfields Program. Notwithstanding, the groundwater contaminant plumes associated with the Schilling AFB Site have the potential to migrate overtime and it is recommended that best management practices be carried out during future uses at the property.

O63 **PAUL SCHWAN TECH CTR** **RCRA-CESQG** **1001481878**
SE **3123 CENTENNIAL** **FINDS** **KSR000012054**
< 1/8 **SALINA, KS 67401** **ECHO**
0.055 mi.
291 ft. **Site 1 of 3 in cluster O**

Relative:
Lower

Actual:
1247 ft.

RCRA-CESQG:

Date form received by agency:	08/14/2018
Facility name:	PAUL SCHWAN TECH CTR
Facility address:	3123 CENTENNIAL SALINA, KS 67401
EPA ID:	KSR000012054
Mailing address:	3019 SCANLAN AVE SALINA, KS 67401
Contact:	MIKE WHITLOCK
Contact address:	3019 SCANLAN AVE SALINA, KS 67401
Contact country:	US
Contact telephone:	785-825-1671
Telephone ext.:	62514
Contact email:	MIKE.WHITLOCK@SCHWANS.COM
EPA Region:	07
Land type:	Private
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	SCHWANS GLOBAL SUPPLY CHAIN INC
Owner/operator address:	3019 SCANLAN AVE SALINA, KS 67401
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	03/20/2006
Owner/Op end date:	Not reported

Owner/operator name:	SCHWANS GLOBAL SUPPLY CHAIN INC
Owner/operator address:	3019 SCANLAN AVE SALINA, KS 67401
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported

PAUL SCHWAN TECH CTR (Continued) **1001481878**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 03/20/2006
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/04/2016
Site name: PAUL SCHWAN TECH CTR
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 06/15/2015
Site name: PAUL SCHWAN TECH CTR
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 04/01/2014
Site name: PAUL SCHWAN TECH CTR
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/28/2013
Site name: PAUL SCHWAN TECH CTR
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/26/2012
Site name: PAUL SCHWAN TECH CTR
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/30/2011
Site name: PAUL SCHWAN TECH CTR
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/26/2010
Site name: PAUL SCHWAN TECH CTR
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 04/29/2009
Site name: PAUL SCHWAN TECH CTR
Classification: Conditionally Exempt Small Quantity Generator

PAUL SCHWAN TECH CTR (Continued) **1001481878**

Date form received by agency: 03/31/2008
Site name: PAUL SCHWAN TECH CTR
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 04/02/2007
Site name: PAUL SCHWAN TECH CTR
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/31/2006
Site name: PAUL SCHWAN TECH CTR
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 04/04/2005
Site name: PAUL SCHWAN TECH CTR
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 04/12/2004
Site name: PAUL SCHWAN TECH CTR
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/05/2003
Site name: PAUL SCHWAN TECH CTR
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/12/1999
Site name: SCHWANS SALES ENTERPRISES
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

PAUL SCHWAN TECH CTR (Continued) **1001481878**

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 07/24/2018
Date achieved compliance: 08/07/2018
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/24/2018
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-General Facility Standards
Date violation determined: 07/24/2018
Date achieved compliance: 08/07/2018
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/24/2018
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 07/24/2018
Date achieved compliance: 08/07/2018
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/24/2018
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 08/10/2006
Date achieved compliance: 08/10/2006
Violation lead agency: State

PAUL SCHWAN TECH CTR (Continued) **1001481878**

Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 07/24/2018
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 08/07/2018
Evaluation lead agency: State

Evaluation date: 07/24/2018
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-General Facility Standards
Date achieved compliance: 08/07/2018
Evaluation lead agency: State

Evaluation date: 07/24/2018
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 08/07/2018
Evaluation lead agency: State

Evaluation date: 08/10/2006
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 08/10/2006
Evaluation lead agency: State

FINDS:

Registry ID: 110003212149

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1001481878
Registry ID: 110003212149
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003212149

O64 **KANSAS VOC REHAB CTR** **RCRA NonGen / NLR** **1004705194**
SE **3140 CENTENNIAL** **KSP000000777**
< 1/8 **SALINA, KS 67401**
0.062 mi.
327 ft. **Site 2 of 3 in cluster O**

Relative:
Lower

Actual:
1249 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/28/2002
Facility name:	KANSAS VOC REHAB CTR
Facility address:	3140 CENTENNIAL SALINA, KS 67401
EPA ID:	KSP000000777
Mailing address:	WESTCHESTER SALINA, KS 67401
Contact:	Not reported
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	07
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	12/10/1999
Site name:	KANSAS VOC REHAB CTR
Classification:	Not a generator, verified

Date form received by agency:	11/10/1998
Site name:	KANSAS VOC REHAB CTR
Classification:	Not a generator, verified

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

O65 **SCHWAN - SALINA DIST CENTER** **KS LUST** **U004044794**
SE **3140 CENTENNIAL ROAD** **KS UST** **N/A**
< 1/8 **SALINA, KS 67401** **KS Financial Assurance**
0.062 mi.
327 ft. **Site 3 of 3 in cluster O**

Relative:
Lower

Actual:
1249 ft.

LUST:

Facility ID:	80345
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	09/20/1991
Project Number:	U5-085-00707
Project Name:	Kansas Vocational Rehab
Legal Desc Section:	03
Legal Desc Township:	15S
Legal Desc Range:	03W
Discover Date:	08/30/1991
substrels:	naphthalene
Initial Ranking:	Not reported
Current Ranking:	Not reported
Facility Contact:	Ray Courtney
Facility Phone Number:	785-827-9356
Facility Owner Identification number:	Not reported
Facility Owner:	Not reported
Owner Contact Person:	Not reported
Owner Address:	Not reported
Owner City:	Not reported
Owner State:	Not reported
Owner Zip Code:	Not reported
Owner Phone number:	Not reported
Contractor license number:	Not reported
Contractor phone number:	316-262-8902
Leak duration (if known):	Unkn
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Not reported
Reported By:	Not reported
Reported by persons phone number:	Not reported
Reported by person address:	Not reported
Ground water Impacted (yes/no):	site site upon alluvial deposits from smokey hill river system. gw depth = ~13.0' and gw flow = easterly.
Static groundwater level:	Not reported
Groundwater flow direction:	Not reported
District staff names:	Scott Lang
Assessment of release:	1-16000 gal oil ust abandoned in-place.no contam above kals.gw sample detected 1.5ppb of naphthalene in 3a.other samples contained no hydrocarbons.tank posed no threat to heath & environment.
Contaimination assessement:	site east of former schilling air force base-contam of usts associated with air force base.
Extent of contamination impact:	none above kals.
Updated information:	Not reported
Invoice initiated:	19914
Invoice on going:	Not reported
Invoice completetd:	19914
Release confirmed:	Not reported
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	Not reported

SCHWAN - SALINA DIST CENTER (Continued) **U004044794**

Cost recovery initiated by:	Not reported
Cost recovery completed:	Not reported
Cost recovery completed by:	Not reported
Appplication to trust fund:	Not reported
Facility ID:	81362
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	10/23/1995
Project Number:	U5-085-10654
Project Name:	Saa, Bldg 197, Tank 76
Legal Desc Section:	03
Legal Desc Township:	15S
Legal Desc Range:	03W
Discover Date:	Not reported
substrels:	propane
Initial Ranking:	Not reported
Current Ranking:	Not reported
Facility Contact:	Ray Courtney
Facility Phone Number:	785-827-9356
Facility Owner Identification number:	99999
Facility Owner:	Ks Voctional Rehabilitation Ctr
Owner Contact Person:	Ray Courtney
Owner Address:	3140 Centennial Rd
Owner City:	Salina
Owner State:	KS
Owner Zip Code:	67401
Owner Phone number:	785-827-9356
Contractor license number:	C0211
Contractor phone number:	Not reported
Leak duration (if known):	Not reported
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Not reported
Reported By:	Not reported
Reported by persons phone number:	Not reported
Reported by person address:	Not reported
Ground water Impacted (yes/no):	topsoil > silty clay > highly weathered shale
Static groundwater level:	015
Groundwater flow direction:	NE
District staff names:	Scott Lang
Assessment of release:	1-ust propane removed. soils with in the tank excavation and beneath the lines exhibited no signs of contamination. kdhe considers this site to be in a closed status requiring no further action
Contaimination assessement:	Not reported
Extent of contamination impact:	none suspected
Updated information:	Not reported
Invoice initiated:	19961
Invoice on going:	Not reported
Invoice completetd:	19961
Release confirmed:	Not reported
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	Not reported
Cost recovery initiated by:	Not reported
Cost recovery completed:	Not reported

SCHWAN - SALINA DIST CENTER (Continued) **U004044794**

Cost recovery completed by: Not reported
Appplication to trust fund: Not reported

UST:
Facility ID: 30352
Facility 911 Address: 3140 CENTENNIAL ROAD
Facility 911 City: SALINA
Facility 911 State: KS
Facility 911 Zip: 67401
Date Removed: Not reported
Capacity (Gals): 18129
Tank Internal Protection: None
24 Hour Phone Num: 785-825-1671
Tank External Protection: Fbr Ref Plstc Coat
Piping: Fbr Ref Plstc
Facility Location Method: Not reported
Facility Feature: Not reported
Facility Phone: 785-825-1671
Tank Empty: Not reported
Contact Name: ELROY LAMPE
Contact Title: CONTACT PERSON
Owner ID: 27004
Owner Type: Current
Owner Name: SCHWAN'S GLOBAL %D. DYKES
Owner Address: 3019 SCANLAN AVE.
Owner City: SALINA
Owner State: KS
Owner Zip: 67401
Owner County: Not reported
Owner Phone: 785-825-1671
QTY Remaining in Tank: Not reported
Facility District: NC
Tank ID: 001
Tank Status: Current In Use
Installation Year: 2006
Last Permit Printed: 2017-06-12 00:00:00
Current Permit Printed: 2018-06-29 00:00:00
Facility Datum: Not reported
Out of service Mo/Yr: Not reported
Material of Construction: Steel
Petroleum Substance: Diesel Clear
Owner Replacement Name: ELROY LAMPE
NonPetroleum Substance: Not reported
Owner Replacement Title: Not reported
Hazards: Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num: 68476-34-6
Latitude: Not reported
Longitude: Not reported

Facility ID: 30352
Facility 911 Address: 3140 CENTENNIAL ROAD
Facility 911 City: SALINA
Facility 911 State: KS
Facility 911 Zip: 67401
Date Removed: Not reported
Capacity (Gals): 9039
Tank Internal Protection: None

SCHWAN - SALINA DIST CENTER (Continued) **U004044794**

24 Hour Phone Num:	785-825-1671
Tank External Protection:	Fbr Ref Plstc Coat
Piping:	Fbr Ref Plstc
Facility Location Method:	Not reported
Facility Feature:	Not reported
Facility Phone:	785-825-1671
Tank Empty:	Not reported
Contact Name:	ELROY LAMPE
Contact Title:	CONTACT PERSON
Owner ID:	27004
Owner Type:	Current
Owner Name:	SCHWAN'S GLOBAL %D. DYKES
Owner Address:	3019 SCANLAN AVE.
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	Not reported
Owner Phone:	785-825-1671
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	002
Tank Status:	Current In Use
Installation Year:	2006
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-29 00:00:00
Facility Datum:	Not reported
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Diesel Clear
Owner Replacement Name:	ELROY LAMPE
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	68476-34-6
Latitude:	Not reported
Longitude:	Not reported

KS Financial Assurance:

Facility ID:	30352
Financial Responsibility:	Insurance Policy

Facility ID:	30352
Financial Responsibility:	Insurance Policy

P66 **PONY EXPRESS COURIER CORP.** **KS LUST** **S101836846**
SSW **3199 ARNOLD** **N/A**
< 1/8 **SALINA, KS 67401**
0.107 mi.
563 ft. **Site 1 of 6 in cluster P**

Relative: LUST:
Higher

Facility ID:	27569
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	04/14/1989
Project Number:	U5-085-00099
Project Name:	Pony Express Courier

Actual:
1260 ft.

PONY EXPRESS COURIER CORP. (Continued) **S101836846**

Legal Desc Section:	03
Legal Desc Township:	15S
Legal Desc Range:	03W
Discover Date:	05/14/1989
substrels:	gasoline
Initial Ranking:	26
Current Ranking:	26.00000
Facility Contact:	Winnie
Facility Phone Number:	785-825-8136
Facility Owner Identification number:	28030
Facility Owner:	Pony Express Courier Corp.
Owner Contact Person:	Not reported
Owner Address:	3130 Terrace St., K.c.
Owner City:	Not reported
Owner State:	MO
Owner Zip Code:	64111
Owner Phone number:	816-913-0080
Contractor license number:	Not reported
Contractor phone number:	Not reported
Leak duration (if known):	0
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Piping
Reported By:	Not reported
Reported by persons phone number:	785-825-7297
Reported by person address:	1737 E. North, Salina
Ground water Impacted (yes/no):	11'ground water table
Static groundwater level:	Not reported
Groundwater flow direction:	Not reported
District staff names:	Erik Peterson
Assessment of release:	connection point between the fill pipe and tank corroded creating a leak. the tank was pitted and corroded to a small extent but no leaks. at least one delivery van was overfilled as reported to kdhe. the lines directly below the dispenser leaked.
Contaimination assessement:	tank removed
Extent of contamination impact:	ground water below tank contaminated. please see accompanying kdhe lab report. total extent of groundwater contamination is unknown at this time.
Updated information:	07/06/00: site assigned closed status by tf staff.
Invoice initiated:	19893
Invoice on going:	Not reported
Invoice completetd:	19893
Release confirmed:	19893
Emergencty contact:	Not reported
Enforcement action:	19911
Cost recovery:	Not reported
Cost recovery initiated:	19954
Cost recovery initiated by:	Responsible Party
Cost recovery completed:	20004
Cost recovery completed by:	Responsible Party
Appplication to trust fund:	19911

67
NW
< 1/8
0.109 mi.
574 ft.

SCHILLING AFB AF FAC C
OTTAWA, KS

FUDS **1024898530**
N/A

Relative:
Lower

Actual:
1255 ft.

FUDS:

EPA Region:	7
Installation ID:	KS79799F030200
Congressional District Number:	1
Facility Name:	SCHILLING AFB AF FAC C
FUDS Number:	B07KS0258
City:	OTTAWA
State:	KS
County:	SALINE
Telephone:	816-389-3072
USACE Division:	Northwestern Division (NWD)
USACE District:	Kansas City District (NWK)
Status:	Properties without projects
Current Owner:	Other Federal Government
X Coord:	-97.6452777803446
Y Coord:	38.791388889686402
Latitude:	38.79138889
Longitude:	-97.645277780000001

Q68
West
< 1/8
0.112 mi.
591 ft.

GAS INSTRUCTION AREA
SALINA, KS
Site 1 of 3 in cluster Q

UXO **1024715395**
N/A

Relative:
Higher

Actual:
1261 ft.

UXO:

DoD Component:	FUDS
Installation Name:	SCHILLING AFB
Facility Address 2:	Not reported
Site ID:	07OEW/CWM
Site Type:	Chemical Disposal
Latitude:	38.784722000000002
Longitude:	-97.645832999999996

Q69
West
< 1/8
0.112 mi.
591 ft.

CONVENTIONAL TRAINING AREAS
SALINA, KS
Site 2 of 3 in cluster Q

UXO **1024715100**
N/A

Relative:
Higher

Actual:
1261 ft.

UXO:

DoD Component:	FUDS
Installation Name:	SCHILLING AFB
Facility Address 2:	Not reported
Site ID:	04OEW
Site Type:	Multi Use Range
Latitude:	38.784722000000002
Longitude:	-97.645832999999996

Q70 **SCHILLING AFB** **FUDS** **1007211802**
West **N/A**
< 1/8 **SALINA, KS**
0.112 mi.
591 ft. **Site 3 of 3 in cluster Q**

Relative:
Higher

Actual:
1261 ft.

FUDS:

EPA Region:	7
Installation ID:	KS79799F093200
Congressional District Number:	1
Facility Name:	SCHILLING AFB
FUDS Number:	B07KS0256
City:	SALINA
State:	KS
County:	SALINE
Telephone:	816-389-3072
USACE Division:	Northwestern Division (NWD)
USACE District:	Kansas City District (NWK)
Status:	Properties with projects
Current Owner:	Local Government; Private Sector; State Government
X Coord:	-97.645833330243306
Y Coord:	38.784722219855396
Latitude:	38.784722219999999
Longitude:	-97.645833330000002

FUDS Detail as of Jan 2015:

Fiscal Year:	2013
Federal Facility ID:	KS9799F0932
RAB:	Not reported
NPL Status:	Not Listed
Description:	The property consists of 4,134.72 acres and is located southwest of the Salina, Kansas
History:	The facility was constructed in 1942 and was designated as the Smokey Hill Army Air Base. The facility was renamed Smokey Hill Air Force Base in 1946. The base was deactivated in 1949. It was reactivated in approximately 1951 to support the Korean Conflict at which time the facility underwent a process of extensive expansion, demolition, and construction during 1951-1952. The facility was renamed Schilling AFB (SAFB) in 1957. The 310th and 40th Bomb Wings were assigned to SAFB. Each wing consisted of B-47s and KC-97 tankers. In 1961, the facility became the support base for the 550th Strategic Missile Squadron for "Atlas "F" Inter Continental Ballistic Missile (ICBM) and Nike missiles, supporting 12 remote launch facilities. Industrial and maintenance support included conventional munitions assembly, storage and maintenance, Atlas missile assembly, jet engine repair, and vehicle maintenance. The base was permanently closed in 1967 and GSA conveyed the majority of the base to the City of Salina for use as a Municipal Airport. Light to heavy industry, aviation, and educational facilities are other current site operators. This property is suspected to contain military munitions and explosives of concern (e.g., unexploded ordnance). Alias: Smokey Hill Army Air Base, Smokey Hill Air Force Base, Salina Public Schools USD 305, Schilling Defense Area Guided Missile Field Maintenance Shop, Salina Municipal Airport & Industrial Area, Magnolia & Centennial Road, Vo-Tech Diesel Mechanics
CTC:	35046.900000000001
Current Program:	Not reported
Future Program:	Not reported
Institutional ID:	53673

SCHILLING AFB (Continued) **1007211802**

MRA:

Inst ID:	53673
FUDS Number:	B07KS0256
Facility Name:	SCHILLING AFB
PHASE:	4
ARC:	Y
DIST:	NWK
MMRP:	Y
MRA ID:	B07KS025604R05

Inst ID:	53673
FUDS Number:	B07KS0256
Facility Name:	SCHILLING AFB
PHASE:	4
ARC:	Y
DIST:	NWK
MMRP:	Y
MRA ID:	B07KS025604R01

Inst ID:	53673
FUDS Number:	B07KS0256
Facility Name:	SCHILLING AFB
PHASE:	4
ARC:	Y
DIST:	NWK
MMRP:	Y
MRA ID:	B07KS025604R01

Inst ID:	53673
FUDS Number:	B07KS0256
Facility Name:	SCHILLING AFB
PHASE:	4
ARC:	Y
DIST:	NWK
MMRP:	Y
MRA ID:	B07KS025604R01

Inst ID:	53673
FUDS Number:	B07KS0256
Facility Name:	SCHILLING AFB
PHASE:	4
ARC:	Y
DIST:	NWK
MMRP:	Y
MRA ID:	B07KS025604R01

Inst ID:	53673
FUDS Number:	B07KS0256
Facility Name:	SCHILLING AFB
PHASE:	4
ARC:	Y
DIST:	NWK
MMRP:	Y
MRA ID:	B07KS025604R01

MRS:

SCHILLING AFB (Continued) **1007211802**

Inst ID: 53673
FUDS Number: B07KS0256
Facility Name: SCHILLING AFB
PHASE: 4
Site ID: 07
DIST: NWK
MMRP: Y
MRA ID: B07KS025604R05
PROJ NO: B07KS025607

Inst ID: 53673
FUDS Number: B07KS0256
Facility Name: SCHILLING AFB
PHASE: 4
Site ID: 04
DIST: NWK
MMRP: Y
MRA ID: B07KS025604R01
PROJ NO: B07KS025604

Inst ID: 53673
FUDS Number: B07KS0256
Facility Name: SCHILLING AFB
PHASE: 4
Site ID: 04
DIST: NWK
MMRP: Y
MRA ID: B07KS025604R01
PROJ NO: B07KS025604

Inst ID: 53673
FUDS Number: B07KS0256
Facility Name: SCHILLING AFB
PHASE: 4
Site ID: 04
DIST: NWK
MMRP: Y
MRA ID: B07KS025604R01
PROJ NO: B07KS025604

Inst ID: 53673
FUDS Number: B07KS0256
Facility Name: SCHILLING AFB
PHASE: 4
Site ID: 04
DIST: NWK
MMRP: Y
MRA ID: B07KS025604R01
PROJ NO: B07KS025604

Inst ID: 53673
FUDS Number: B07KS0256
Facility Name: SCHILLING AFB
PHASE: 4
Site ID: 04
DIST: NWK
MMRP: Y

SCHILLING AFB (Continued) **1007211802**

MRA ID: B07KS025604R01
PROJ NO: B07KS025604

P71 **KHP TROOP C HEADQUARTERS** **KS LUST** **U001112546**
SSW **3213 ARNOLD AVE** **KS UST** **N/A**
< 1/8 **SALINA, KS 67401**
0.118 mi.
623 ft. **Site 2 of 6 in cluster P**

Relative: **Higher**

Actual: **1260 ft.**

LUST:

Facility ID:	29632
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	09/21/1995
Project Number:	U5-085-10563
Project Name:	KHP Troop C Hq
Legal Desc Section:	03
Legal Desc Township:	15S
Legal Desc Range:	03W
Discover Date:	Not reported
substrels:	Not reported
Initial Ranking:	Not reported
Current Ranking:	Not reported
Facility Contact:	Not reported
Facility Phone Number:	Not reported
Facility Owner Identification number:	23227
Facility Owner:	KDOT
Owner Contact Person:	Peter Carter
Owner Address:	DSOB, Room 856-W
Owner City:	Topeka
Owner State:	KS
Owner Zip Code:	66612
Owner Phone number:	785-296-3661
Contractor license number:	C0008
Contractor phone number:	316-473-3835
Leak duration (if known):	Not reported
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Not reported
Reported By:	Not reported
Reported by persons phone number:	Not reported
Reported by person address:	Not reported
Ground water Impacted (yes/no):	the area consists of grayish brown silty clays. gw was encountered in the bottom of the excavation.
Static groundwater level:	010
Groundwater flow direction:	N
District staff names:	Howard Debauche
Assessment of release:	1-ust removed. there was no staining nor odor in or around excav. the water in the bottom of the excav showed no visible contam present. a sample taken from the bottom showed no measurable contam present. kdhe considers site closed.
Contaimination assessement:	yes
Extent of contamination impact:	none suspected.
Updated information:	Not reported
Invoice initiated:	19954
Invoice on going:	Not reported
Invoice completetd:	19954

KHP TROOP C HEADQUARTERS (Continued) **U001112546**

Release confirmed:	Not reported
Emergency contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	Not reported
Cost recovery initiated by:	Not reported
Cost recovery completed:	Not reported
Cost recovery completed by:	Not reported
Appplication to trust fund:	Not reported

UST:

Facility ID:	29632
Facility 911 Address:	3213 ARNOLD AVE
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1995-09-15 00:00:00
Capacity (Gals):	10000
Tank Internal Protection:	None
24 Hour Phone Num:	785-827-3065
Tank External Protection:	Fbr Ref Plstc Coat
Piping:	Fbr Ref Plstc
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-827-3065
Tank Empty:	Not reported
Contact Name:	Capt. Alvie Furbeck
Contact Title:	Capt Ks Highway Patr
Owner ID:	23227
Owner Type:	Current
Owner Name:	KDOT MAINTENANCE
Owner Address:	700 SW HARRISON ST., 8TH FLOOR
Owner City:	TOPEKA
Owner State:	KS
Owner Zip:	66603
Owner County:	SHAWNEE
Owner Phone:	785-296-3576
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1991
Last Permit Printed:	1995-07-18 00:00:00
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	091995
Material of Construction:	Fbr Ref Plastic
Petroleum Substance:	Gas (Incl Alcohol)
Owner Replacement Name:	DIST.MAINT.ENGR/SUPER.
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.77988
Longitude:	-97.63950

P72
SSW
1/8-1/4
0.133 mi.
703 ft.

SALINA AIRCRAFT SERVICES, INC.
3148 ARNOLD
SALINA, KS 67401

Site 3 of 6 in cluster P

KS UST **U001960363**
KS Financial Assurance **N/A**

Relative:
Higher

Actual:
1261 ft.

UST:

Facility ID:	29734
Facility 911 Address:	3148 ARNOLD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	12000
Tank Internal Protection:	None
24 Hour Phone Num:	785-819-4090
Tank External Protection:	Fbr Ref Plstc Coat
Piping:	Fbr Ref Plstc
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-826-9681
Tank Empty:	Not reported
Contact Name:	DOUG BRADLEY
Contact Title:	PRESIDENT/TRUSTEE
Owner ID:	29734
Owner Type:	Current, Private Or Corp.
Owner Name:	DOUGLAS FRANCIS BRADLEY TRUST
Owner Address:	3380 SCENIC SLOPE ROAD
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-826-9681
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Current In Use
Installation Year:	1993
Last Permit Printed:	2017-06-19 00:00:00
Current Permit Printed:	2018-06-22 00:00:00
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Fbr Ref Plastic
Petroleum Substance:	Jet Fuel
Owner Replacement Name:	DOUG BRADLEY
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute

Principal CERCLA Substance/Chem Abstract Service Num: Not reported

Latitude:	38.77969
Longitude:	-97.64130

KS Financial Assurance:

Facility ID:	29734
Financial Responsibility:	3rd Party Liability Insurance

P73 **LEASE & RENTAL INC-AIRPORT** **KS UST** **U003542101**
SSW **3230 ARNOLD RD** **N/A**
1/8-1/4 **SALINA, KS 67401**
0.133 mi.
703 ft. **Site 4 of 6 in cluster P**

Relative:
Higher

Actual:
1261 ft.

UST:

Facility ID:	19786
Facility 911 Address:	3230 ARNOLD RD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1991-04-15 00:00:00
Capacity (Gals):	1000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	Not reported
Tank External Protection:	Unknown
Piping:	Galv Steel
Facility Location Method:	Mapblast
Facility Feature:	Facility Center
Facility Phone:	Not reported
Tank Empty:	Not reported
Contact Name:	Salina Airport Auth
Contact Title:	Owner
Owner ID:	27195
Owner Type:	Private Or Corp.
Owner Name:	SALINA AIRPORT AUTHORITY
Owner Address:	3237 ARNOLD AVENUE
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-827-3914
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1976
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	041991
Material of Construction:	Steel
Petroleum Substance:	Gas (Incl Alcohol)
Owner Replacement Name:	KENNY BIEKER
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.77863
Longitude:	-97.64038

P74 **ADM MILLING** **RCRA NonGen / NLR** **1001817109**
SSW **3140 ARNOLD** **FINDS** **KSR000013862**
1/8-1/4 **SALINA, KS 67401** **ECHO**
0.133 mi.
703 ft. **Site 5 of 6 in cluster P**

Relative:
Higher

Actual:
1261 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/13/2004
Facility name:	ADM MILLING
Facility address:	3140 ARNOLD SALINA, KS 67401
EPA ID:	KSR000013862
Mailing address:	ARNOLD SALINA, KS 67401
Contact:	MICHAEL PAUL
Contact address:	3140 ARNOLD SALINA, KS 67401
Contact country:	US
Contact telephone:	785-825-6550
Contact email:	Not reported
EPA Region:	07
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ARCHER DANIELS MIDLAND
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/08/2004
Owner/Op end date:	Not reported

Owner/operator name:	BLUE BEACON INTL
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/08/2004
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

ADM MILLING (Continued) **1001817109**

Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	10/25/1999
Site name:	ADM MILLING
Classification:	Small Quantity Generator

Hazardous Waste Summary:

. Waste code:	D001
. Waste name:	IGNITABLE WASTE
. Waste code:	D006
. Waste name:	CADMIUM
. Waste code:	D008
. Waste name:	LEAD
. Waste code:	D018
. Waste name:	BENZENE
. Waste code:	D027
. Waste name:	1,4-DICHLOROBENZENE
. Waste code:	D039
. Waste name:	TETRACHLOROETHYLENE
. Waste code:	D040
. Waste name:	TRICHLORETHYLENE
Violation Status:	No violations found

Evaluation Action Summary:

Evaluation date:	12/19/2003
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State

FINDS:

Registry ID: 110009573292

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

ADM MILLING (Continued) **1001817109**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001817109
Registry ID:	110009573292
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009573292

P75 **BLUE BEACON INTERNATIONAL-HANG** **KS UST** **U001112516**
SSW **3140 ARNOLD** **KS AST** **N/A**
1/8-1/4 **SALINA, KS 67401** **KS Financial Assurance**
0.133 mi.
703 ft. **Site 6 of 6 in cluster P**

Relative: Higher

Actual: 1261 ft.

UST:

Facility ID:	29441
Facility 911 Address:	3140 ARNOLD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	20000
Tank Internal Protection:	None
24 Hour Phone Num:	785-452-1119
Tank External Protection:	Cat Prot, Painted
Piping:	Cat Prot
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-826-8214
Tank Empty:	Not reported
Contact Name:	RAY FARMER
Contact Title:	CONTACT PERSON
Owner ID:	27155
Owner Type:	Current, Private Or Corp.
Owner Name:	BLUE BEACON INTERNATIONAL
Owner Address:	PO BOX 856
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67402-0856
Owner County:	SALINE
Owner Phone:	785-825-2221
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Current In Use
Installation Year:	1991
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-07 00:00:00
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Aviation Fuel Jet-A

BLUE BEACON INTERNATIONAL-HANG (Continued) **U001112516**

Owner Replacement Name: TINA PRICE
NonPetroleum Substance: Not reported
Owner Replacement Title: Not reported
Hazards: Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num: 8008-20-6
Latitude: 38.77972
Longitude: -97.64137

Facility ID: 29441
Facility 911 Address: 3140 ARNOLD
Facility 911 City: SALINA
Facility 911 State: KS
Facility 911 Zip: 67401
Date Removed: Not reported
Capacity (Gals): 20000
Tank Internal Protection: None
24 Hour Phone Num: 785-452-1119
Tank External Protection: Cat Prot, Painted
Piping: Cat Prot
Facility Location Method: Garmin GPS III Plus
Facility Feature: Facility Center
Facility Phone: 785-826-8214
Tank Empty: Not reported
Contact Name: RAY FARMER
Contact Title: CONTACT PERSON
Owner ID: 27155
Owner Type: Current, Private Or Corp.
Owner Name: BLUE BEACON INTERNATIONAL
Owner Address: PO BOX 856
Owner City: SALINA
Owner State: KS
Owner Zip: 67402-0856
Owner County: SALINE
Owner Phone: 785-825-2221
QTY Remaining in Tank: Not reported
Facility District: NC
Tank ID: 002
Tank Status: Current In Use
Installation Year: 1991
Last Permit Printed: 2017-06-12 00:00:00
Current Permit Printed: 2018-06-07 00:00:00
Facility Datum: WGS84
Out of service Mo/Yr: Not reported
Material of Construction: Steel
Petroleum Substance: Aviation Fuel Jet-A
Owner Replacement Name: TINA PRICE
NonPetroleum Substance: Not reported
Owner Replacement Title: Not reported
Hazards: Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num: 8008-20-6
Latitude: 38.77972
Longitude: -97.64137

AST:
Facility ID: 29441
Facility 911 Address: 3140 ARNOLD
Facility 911 City: SALINA

BLUE BEACON INTERNATIONAL-HANG (Continued) **U001112516**

Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	4000
Tank Internal Protection:	Not reported
24 Hour Phone Num:	785-452-1119
Tank External Protection:	Not reported
Piping:	Nonmetallic
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-826-8214
Tank Empty:	Not reported
Contact Name:	RAY FARMER
Contact Title:	CONTACT PERSON
Owner ID:	27155
Owner Type:	Current, Private Or Corp.
Owner Name:	BLUE BEACON INTERNATIONAL
Owner Address:	PO BOX 856
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67402-0856
Owner County:	SALINE
Owner Phone:	785-825-2221
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Current In Use
Installation Year:	2005
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-11 00:00:00
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Not reported
Petroleum Substance:	Aviation Gas 100 LL
Owner Replacement Name:	TINA PRICE
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	86290-81-5
Latitude:	38.77972
Longitude:	-97.64137

KS Financial Assurance:

Facility ID:	29441
Financial Responsibility:	Insurance Policy

Facility ID:	29441
Financial Responsibility:	Insurance Policy

R76 **DEAL PET CO** **RCRA NonGen / NLR** **1000616739**
NNE **2624 CENTENNIAL** **FINDS** **KSD981117245**
1/8-1/4 **SALINA, KS 67401** **ECHO**
0.150 mi.
794 ft. **Site 1 of 2 in cluster R**

Relative:
Lower

Actual:
1246 ft.

RCRA NonGen / NLR:

Date form received by agency:	08/22/2003
Facility name:	DEAL PET CO
Facility address:	2624 CENTENNIAL SALINA, KS 67401
EPA ID:	KSD981117245
Mailing address:	P.O. BOX 34 ROXBURY, KS 67476
Contact:	TERRY BUPP
Contact address:	P.O. BOX 34 ROXBURY, KS 67476
Contact country:	US
Contact telephone:	785-827-9239
Contact email:	Not reported
EPA Region:	07
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	DEAL PETROLEUM CO
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/22/1999

DEAL PET CO (Continued) **1000616739**

Site name: DEAL PET CO
Classification: Not a generator, verified

Date form received by agency: 08/19/1985
Site name: DEAL PET CO
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 01/20/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003168848

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000616739
Registry ID: 110003168848
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003168848

77
NNE
1/8-1/4
0.151 mi.
796 ft.

SALINA AIRPORT AUTHORITY V BTA
BERSCHEL AVE & SCANLAN RD
SALINA, KS

KS SHWS **S111095304**
KS BROWNFIELDS **N/A**

Relative:
Lower

Actual:
1250 ft.

SHWS:
Site ID: 2768
Has Env Use Control: No
Project code: C508572817
PM Name: BER - REDEVELOPMENT
Site Status: **Resolved**

SALINA AIRPORT AUTHORITY V BTA (Continued) **S111095304**

District Office:	NCDO
Lat/Long:	38.7925 / -97.6351
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Industrial
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Resolved
Activity Status:	Completed
Activity Start Date:	10/13/2011
Activity End Date:	10/13/2011
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Phase II Brownfields Targeted Assessment (BTA) at the Salina Airport Authority?Site V in Salina, Kansas. The BTA was conducted for the Salina Airport Authority to expedite the transfer and redevelopment of the property, which is located within the boundary of a Formally Used Defense Facility (FUD). A Phase I, dated June 30, 2011, was conducted through a Property Red evelopment Assessment (PRA) by the Formerly Used Defense Sites (FUDS) Installations Program. Based on the Phase I report, ?Recognized Environmental Conditions? (RECs) were identified as potential petroleum and hazardous substances associated with: historical database listings and known contamination from adjacent facilities, including but not limited to Schilling AFB, and two large above ground storage tanks former located on the property that were identified in historical aerial photographs. Therefore, a Phase II was recommended to commence. The Phase II consisted of collecting soil from two locations and gro undwater from five locations on the property. The samples were

SALINA AIRPORT AUTHORITY V BTA (Continued) **S111095304**

analyzed for volatile organic compounds (VOCs), total petroleum hydrocarbons (TPH) diesel range organics (DRO) and TPH gasoline range organics (GRO). Based on the conclusions of the investigation, groundwater has been impacted by petroleum and chlorinated solvents at levels exceeding Kansas Risk Based Standards. TPH GRO was detected at location GP-5 at a concentration of 1,100 ?g/l. In addition, TCE was detected at a concentration of 193 ?g/l at GP-5. Elevated concentrations of TCE were also detected at location GP-1. Both GP-1 and GP-5 are located along the western boundary of the property in a presumed ?upgradient? direction relative to the property itself.

In summary, the findings of this Phase II BTA indicate that the site itself is likely not a contaminant source area, but that offsite sources for TPH GRO and chlorinated VOCs (particularly, TCE) are located generally west of GP-5 and GP-1. The Phase I BTA for the site identified both the adjacent west to southwest Hawker-Beechcraft facility and the adjacent west Salina Area Technical School as ?closed? KDHE Leaking Underground Storage Tank (LUST) facilities, and further indicated that the waste stream of the Hawker-Beechcraft facility includes TCE. These facilities are possible sources for the contaminants detected in groundwater beneath the site. However, additional assessment or additional review of previous investigation data would be required to identify specific sources for contaminants detected at the site. Given the relatively shallow static water levels observed at the site (9 feet bgs), it is recommended that if the site is developed with structures that include basements or occupied sub-grade areas, that appropriate design measures be considered to prevent or mitigate possible vapor intrusion.

Site ID:	2768
Has Env Use Control:	No
Project code:	C508572817
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.7925 / -97.6351
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Industrial

SALINA AIRPORT AUTHORITY V BTA (Continued) **S111095304**

Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Resolved
Activity Status:	Completed
Activity Start Date:	10/13/2011
Activity End Date:	10/13/2011
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Phase II Brownfields Targeted Assessment (BTA) at the Salina Airport Authority?Site V in Salina, Kansas. The BTA was conducted for the Salina Airport Authority to expedite the transfer and redevelopment of the property, which is located within the boundary of a Formally Used Defense Facility (FUD). A Phase I, dated June 30, 2011, was conducted through a Property Red evelopment Assessment (PRA) by the Formerly Used Defense Sites (FUDS) Installations Program. Based on the Phase I report, ?Recognized Environmental Conditions? (RECs) were identified as potential petroleum and hazardous substances associated with: historical database listings and known contamination from adjacent facilities, including but not limited to Schilling AFB, and two large above ground storage tanks former located on the property that were identified in historical aerial photographs. Therefore, a Phase II was recommended to commence. The Phase II consisted of collecting soil from two locations and gro undwater from five locations on the property. The samples were analyzed for volatile organic compounds (VOCs), total petroleum hydrocarbons (TPH) diesel range organics (DRO) and TPH gasoline range organics (GRO). Based on the conclusions of the investigation, groundwater has been impacted by petroleum and chlorinated solvents at levels exceeding Kansas Risk Based Standards. TPH GRO was detected at location GP-5 at a concentration of 1,100 ?g/l. In addition, TCE was detected at a concentration of 193 ?g/l at GP-5. Elevated concentrations of TCE were also detected at location GP-1. Both GP-1 and GP-5 are located along the western boundary of the property in a presumed ?upgradient? direction relative to the property itself. In summary, the findings of this Phase II BTA indicate that the site itself is likely not a contaminant source area, but that offsite sources for TPH GRO and chlorinated VOCs (particularly, TCE) are located generally west of GP-5 and GP-1. The Phase I BTA for the site identified both the adjacent west to southwest Hawker-Beechcraft facility and the adjacent west Salina Area Technical School as ?closed? KDHE Leaking Underground Storage Tank (LUST) facilities, and further indicated that the waste stream of the Hawker-Beechcraft facility includes TCE. These facilities are possible sources for the contaminants detected in groundwater beneath the site. However, additional assessment or additional review of previous investigation data would be required to identify specific sources for contaminants

SALINA AIRPORT AUTHORITY V BTA (Continued) **S111095304**

detected at the site. Given the relatively shallow static water levels observed at the site (9 feet bgs), it is recommended that if the site is developed with structures that include basements or occupied sub-grade areas, that appropriate design measures be considered to prevent or mitigate possible vapor intrusion.

Site ID:	2768
Has Env Use Control:	No
Project code:	C508572817
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.7925 / -97.6351
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Industrial
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Resolved
Activity Status:	Completed
Activity Start Date:	10/13/2011
Activity End Date:	10/13/2011
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Phase II Brownfields Targeted Assessment (BTA) at the Salina Airport Authority?Site V in Salina, Kansas. The BTA was conducted for the Salina Airport Authority to expedite the transfer and redevelopment of the property, which is located within the boundary of a Formally Used Defense Facility (FUD). A Phase I, dated June 30, 2011, was conducted through a Property Red

SALINA AIRPORT AUTHORITY V BTA (Continued) **S111095304**

evelopment Assessment (PRA) by the Formerly Used Defense Sites (FUDS) Installations Program. Based on the Phase I report, ?Recognized Environmental Conditions? (RECs) were identified as potential petroleum and hazardous substances associated with: historical database listings and known contamination from adjacent facilities, including but not limited to Schilling AFB, and two large above ground storage tanks former located on the property that were identified in historical aerial photographs. Therefore, a Phase II was recommended to commence.

The Phase II consisted of collecting soil from two locations and gro undwater from five locations on the property. The samples were analyzed for volatile organic compounds (VOCs), total petroleum hydrocarbons (TPH) diesel range organics (DRO) and TPH gasoline range organics (GRO). Based on the conclusions of the investigation, groundwater has been impacted by petroleum and chlorinated solvents at levels exceeding Kansas Risk Based Standards. TPH GRO was detected at location GP-5 at a concentration of 1,100 ?g/l. In addition, TCE was detected at a concentration of 193 ?g/l at GP-5. Elevated concentrations of TCE were also detected at location GP-1. Both GP-1 and GP-5 are located along the western boundary of the property in a presumed ?upgradient? direction relative to the property itself.

In summary, the findings of this Phase II BTA indicate that the site itself is likely not a contaminant source area, but that offsite sources for TPH GRO and chlorinated VOCs (particularly, TCE) are located generally west of GP-5 and GP-1. The Phase I BTA for the site identified both the adjacent west to southwest Hawker-Beechcraft facility and the adjacent west Salina Area Technical School as ?closed? KDHE Leaking Underground Storage Tank (LUST) facilities, and further indicated that the waste stream of the Hawker-Beechcraft facility includes TCE. These facilities are possible sources for the contaminants detected in groundwater beneath the site. However, additional assessment or additional review of previous investigation data would be required to identify specific sources for contaminants detected at the site. Given the relatively shallow static water levels observed at the site (9 feet bgs), it is recommended that if the site is developed with structures that include basements or occupied sub-grade areas, that appropriate design measures be considered to prevent or mitigate possible vapor intrusion.

BROWNFIELDS:

Site ID:	2768
Project code:	C508572817
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
Lat/Long:	38.7925 / -97.6351
Program:	Brownfields

R78
NNE
1/8-1/4
0.152 mi.
800 ft.

BUILDERS CHOICE CONCRETE
2601 CENTENNIAL RD
SALINA, KS 67402

Site 2 of 2 in cluster R

KS AST **A100395126**
N/A

Relative:
Lower

Actual:
1246 ft.

AST:

Facility ID:	45092
Facility 911 Address:	2601 CENTENNIAL RD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67402
Date Removed:	2016-06-01 00:00:00
Capacity (Gals):	1000
Tank Internal Protection:	Not reported
24 Hour Phone Num:	785-822-5309
Tank External Protection:	Painted
Piping:	Bare Steel
Facility Location Method:	Not reported
Facility Feature:	Not reported
Facility Phone:	785-822-2444
Tank Empty:	Not reported
Contact Name:	MARK BLAHA
Contact Title:	Not reported
Owner ID:	42078
Owner Type:	Private Or Corp.
Owner Name:	CONCRETE SUPPLY OF TOPEKA %J.
Owner Address:	2500 SW 3RD ST
Owner City:	TOPEKA
Owner State:	KS
Owner Zip:	66606-2439
Owner County:	SHAWNEE
Owner Phone:	785-235-1585
QTY Remaining in Tank:	1,000
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	2011
Last Permit Printed:	2015-06-09 00:00:00
Current Permit Printed:	Not reported
Facility Datum:	Not reported
Out of service Mo/Yr:	062016
Material of Construction:	Steel
Petroleum Substance:	Not reported
Owner Replacement Name:	JERRY MARNEY
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported

Principal CERCLA Substance/Chem Abstract Service Num: Not reported

Latitude:	Not reported
Longitude:	Not reported

Facility ID:	45092
Facility 911 Address:	2601 CENTENNIAL RD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67402
Date Removed:	Not reported
Capacity (Gals):	8000

BUILDERS CHOICE CONCRETE (Continued) **A100395126**

Tank Internal Protection:	Not reported
24 Hour Phone Num:	785-822-5309
Tank External Protection:	Painted
Piping:	Bare Steel
Facility Location Method:	Not reported
Facility Feature:	Not reported
Facility Phone:	785-822-2444
Tank Empty:	Not reported
Contact Name:	MARK BLAHA
Contact Title:	Not reported
Owner ID:	42078
Owner Type:	Private Or Corp.
Owner Name:	CONCRETE SUPPLY OF TOPEKA %J.
Owner Address:	2500 SW 3RD ST
Owner City:	TOPEKA
Owner State:	KS
Owner Zip:	66606-2439
Owner County:	SHAWNEE
Owner Phone:	785-235-1585
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	002
Tank Status:	Current In Use
Installation Year:	2015
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-11 00:00:00
Facility Datum:	Not reported
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Diesel
Owner Replacement Name:	JERRY MARNEY
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	68476-34-6
Latitude:	Not reported
Longitude:	Not reported

S79 **STUDENT ACTIVITY FUND** **KS LUST** **U000872342**
North **2562 SCANLAN AVE** **KS UST** **N/A**
1/8-1/4 **SALINA, KS 67401**
0.159 mi.
842 ft. **Site 1 of 2 in cluster S**

Relative: LUST:
Lower

Facility ID:	09121
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	07/21/1989
Project Number:	U5-085-00134
Project Name:	Usd 305, Salina Area Vo-tech
Legal Desc Section:	34
Legal Desc Township:	14S
Legal Desc Range:	03W
Discover Date:	07/20/1989
substrels:	gasoline
Initial Ranking:	Not reported
Current Ranking:	Not reported

Actual:
1250 ft.

STUDENT ACTIVITY FUND (Continued) **U000872342**

Facility Contact:	Gerald Eck
Facility Phone Number:	785-825-2261
Facility Owner Identification number:	Not reported
Facility Owner:	Usd #305
Owner Contact Person:	Not reported
Owner Address:	Box 797,salina
Owner City:	Not reported
Owner State:	KS
Owner Zip Code:	67402
Owner Phone number:	785-825-0281
Contractor license number:	Not reported
Contractor phone number:	Not reported
Leak duration (if known):	0
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Not reported
Reported By:	Erik Peterson
Reported by persons phone number:	785-827-9639
Reported by person address:	2501-d Market Pl.salina
Ground water Impacted (yes/no):	0-1’ asphalt; 10’ medium light brown clay; 10-11’ ground water encountered.
Static groundwater level:	Not reported
Groundwater flow direction:	Not reported
District staff names:	Erik Peterson
Assessment of release:	soil and groundwater surrounding usts was contaminated some time during the tanks use although it is not known how.
Contaimination assessement:	tank removed.
Extent of contamination impact:	unknown until site assessment is performed by an environmental consultant. gw in tank hole has a sheen on it. 8-17-95 3 water samples were obtained from existing wells. lab analyses for all samples showed no measure hydrocabon contam present. closed.
Updated information:	Not reported
Invoice initiated:	19911
Invoice on going:	Not reported
Invoice completetd:	19911
Release confirmed:	19911
Emergencty contact:	Not reported
Enforcement action:	19911
Cost recovery:	Not reported
Cost recovery initiated:	19911
Cost recovery initiated by:	Responsible Party
Cost recovery completed:	19954
Cost recovery completed by:	Responsible Party
Appplication to trust fund:	19911
Facility ID:	09121
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	07/27/1995
Project Number:	U5-085-10491
Project Name:	Usd 305, Salina Area Vo Tech
Legal Desc Section:	34
Legal Desc Township:	14S
Legal Desc Range:	03W
Discover Date:	07/26/1995
substrels:	fuel oil
Initial Ranking:	Not reported

STUDENT ACTIVITY FUND (Continued) **U000872342**

Current Ranking:	Not reported
Facility Contact:	Jim Sweeney
Facility Phone Number:	785-825-2261
Facility Owner Identification number:	05878
Facility Owner:	Usd 305, Salina Vo-tech
Owner Contact Person:	Jim Sweeney
Owner Address:	2562 Scanlan Ave
Owner City:	Salina
Owner State:	KS
Owner Zip Code:	67401
Owner Phone number:	785-825-2261
Contractor license number:	C0211
Contractor phone number:	800-321-5479
Leak duration (if known):	Not reported
Quantity released (if known):	Not reported
Quantity recorded:	0
Leak Type:	Not reported
Reported By:	Scott Lang
Reported by persons phone number:	785-827-9639
Reported by person address:	Ncdo
Ground water Impacted (yes/no):	topsoil > silty clay > highly weathered shale.
Static groundwater level:	015
Groundwater flow direction:	ENE
District staff names:	Scott Lang
Assessment of release:	2-10,000 gal fuel oil tanks removed. soils contam with fuel oil removed by the contractor and taken to the landfarm for remediation. remaining soils were free of petroleum hydrocarbons. site closed upon proper treatment of removed soils.
Contaimination assessement:	spills/overfills.
Extent of contamination impact:	none suspected as a result of releases form this facility. groundwater may be contam via off-site sources.
Updated information:	Not reported
Invoice initiated:	Not reported
Invoice on going:	Not reported
Invoice completetd:	Not reported
Release confirmed:	Not reported
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	Not reported
Cost recovery initiated by:	Not reported
Cost recovery completed:	Not reported
Cost recovery completed by:	Not reported
Appplication to trust fund:	Not reported

UST:

Facility ID:	20428
Facility 911 Address:	2562 SCANLAN AVE
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1989-07-15 00:00:00
Capacity (Gals):	2000
Tank Internal Protection:	None
24 Hour Phone Num:	785-825-2261
Tank External Protection:	Painted
Piping:	Unknown

STUDENT ACTIVITY FUND (Continued) **U000872342**

Facility Location Method:	Mapblast
Facility Feature:	Facility Center
Facility Phone:	785-825-2261
Tank Empty:	Not reported
Contact Name:	Salina Vo-tech Schoo
Contact Title:	Not reported
Owner ID:	20428
Owner Type:	State Or Local Govt.
Owner Name:	SALINA VO-TECH SCHOOL
Owner Address:	2562 SCANLAN
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-825-2261
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1971
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	071989
Material of Construction:	Steel
Petroleum Substance:	Gas (Incl Alcohol)
Owner Replacement Name:	L W Reynonds
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.79338
Longitude:	-97.63683

S80 **USD #305** **KS UST** **U001112558**
North **2562 SCANLON AVENUE** **N/A**
1/8-1/4 **SALINA, KS**
0.159 mi.
842 ft. **Site 2 of 2 in cluster S**

Relative: UST:
Lower

Actual:
1250 ft.

Facility ID:	09121
Facility 911 Address:	2562 SCANLAN AVE
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1989-07-15 00:00:00
Capacity (Gals):	2000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-825-2261
Tank External Protection:	Unknown
Piping:	Unknown
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-825-2261
Tank Empty:	Not reported
Contact Name:	Roy Reynolds
Contact Title:	Ass't Dir Of Vo-tech

USD #305 (Continued) **U001112558**

Owner ID:	05878
Owner Type:	State Or Local Govt.
Owner Name:	USD #305
Owner Address:	300 WEST ASH
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-825-0281
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1975
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	071989
Material of Construction:	Steel
Petroleum Substance:	Gas (Incl Alcohol)
Owner Replacement Name:	Terry Terril
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.79411
Longitude:	-97.63550

81
North
1/8-1/4
0.179 mi.
944 ft.

EL DORADO INDUSTRIES INC **RCRA NonGen / NLR** **1004702377**
614 LOWE **FINDS** **KSD063570386**
SALINA, KS 67401 **ECHO**

Relative:
Lower

Actual:
1250 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/1980
Facility name:	EL DORADO INDUSTRIES INC
Facility address:	614 LOWE SALINA, KS 67401
EPA ID:	KSD063570386
Mailing address:	LOWE SALINA, KS 67401
Contact:	UNKNOWN UNKNOWN
Contact address:	614 LOWE SALINA, KS 67401
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	07
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	EL DORADO INDUSTRIES INC
Owner/operator address:	614 LOWE AVE SALINA, KS 67401
Owner/operator country:	Not reported

EL DORADO INDUSTRIES INC (Continued) **1004702377**

Owner/operator telephone: 999-999-9999
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110003158430

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004702377
Registry ID: 110003158430
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003158430

T82
NNE
1/8-1/4
0.180 mi.
951 ft.

SCHILLING DEF GUIDED MISSILE MAINTENANCE SHOP
CORNER OF CENTENNIAL AND DERUSSY
SALINA, KS 67401

Site 1 of 2 in cluster T

KS SHWS **1007469826**
FINDS **N/A**

Relative:
Lower

Actual:
1243 ft.

SHWS:

Site ID:	1619
Has Env Use Control:	No
Project code:	C508571181
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.79292 / -97.63277
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Wellington
Other Aquifers:	Alluvial
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	KSN000703171
Discovery Date:	01/01/1990
Depth To GW:	11-20 feet
Depth To Bedrock:	31-50 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	5-25 acres
Waste Present:	No
Product Present:	No
Program:	FUDS (Formerly Used Defense Sites)
Lead Agency:	BER - Remedial
Contaminants:	Other (see Site Narrative)
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Commercial, Industrial
Private well:	Domestic, Industrial
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING DEF-GM FLD
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Initial Site Screening
Activity Status:	Completed
Activity Start Date:	01/01/2001
Activity End Date:	02/01/2001
Narrative:	This site was part of the Schilling Air Force Base, and was leased from the Air Force by the Army to build a maintenance shop for Nike antiaircraft missile sites being built north and south of the base. The Nike missile sites were never completed, and the maintenance shop was never constructed. Therefore, no contamination is suspected to be associated with this site, and no further action is warranted.
Site ID:	1619

SCHILLING DEF GUIDED MISSILE MAINTENANCE SHOP (Continued) **1007469826**

Has Env Use Control:	No
Project code:	C508571181
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.79292 / -97.63277
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Wellington
Other Aquifers:	Alluvial
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	KSN000703171
Discovery Date:	01/01/1990
Depth To GW:	11-20 feet
Depth To Bedrock:	31-50 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	5-25 acres
Waste Present:	No
Product Present:	No
Program:	FUDS (Formerly Used Defense Sites)
Lead Agency:	BER - Remedial
Contaminants:	Other (see Site Narrative)
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Commercial, Industrial
Private well:	Domestic, Industrial
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING DEF-GM FLD
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Initial Site Screening
Activity Status:	Completed
Activity Start Date:	01/01/2001
Activity End Date:	02/01/2001
Narrative:	This site was part of the Schilling Air Force Base, and was leased from the Air Force by the Army to build a maintenance shop for Nike antiaircraft missile sites being built north and south of the base. The Nike missile sites were never completed, and the maintenance shop was never constructed. Therefore, no contamination is suspected to be associated with this site, and no further action is warranted.

FINDS:

Registry ID: 110017449974

Environmental Interest/Information System
KS-FP (Kansas - Facility Profiler) is a geographically-based data warehouse site that presents information about facilities and

SCHILLING DEF GUIDED MISSILE MAINTENANCE SHOP (Continued) **1007469826**

locations of interest to the KDHE. This site has in excess of twenty environmental interest which contains information on closed facilities, completed cleanups, and past operations as well as data on current operations and activities.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

U83 **MEMORIAL HALL** **KS UST** **U001111865**
SSW **N/A**
1/8-1/4 **SALINA, KS 67401**
0.186 mi.
981 ft. **Site 1 of 4 in cluster U**

Relative: UST:
Higher

Actual:
1262 ft.

Facility ID:	09066
Facility 911 Address:	Not reported
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	1000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	Not reported
Tank External Protection:	Unknown
Piping:	Bare Steel
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	Not reported
Tank Empty:	Not reported
Contact Name:	City Clerk
Contact Title:	Not reported
Owner ID:	08507
Owner Type:	Current
Owner Name:	CITY OF SALINA %RONALD ROUSE
Owner Address:	P.O. BOX 736
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-829-7915
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1965
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Empty
Owner Replacement Name:	RONALD ROUSE
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported

Principal CERCLA Substance/Chem Abstract Service Num: Not reported

MEMORIAL HALL (Continued) **U001111865**

Latitude: 38.84294
Longitude: -97.61323

U84 **SALINA RAILYARD** **KS UST** **U000718403**
SSW **N/A**
1/8-1/4 **SALINA, KS**
0.186 mi.
981 ft. **Site 2 of 4 in cluster U**

Relative: UST:
Higher

Actual:
1262 ft.

Facility ID:	25298
Facility 911 Address:	Not reported
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	Not reported
Date Removed:	Not reported
Capacity (Gals):	475
Tank Internal Protection:	None
24 Hour Phone Num:	785-357-2830
Tank External Protection:	None
Piping:	Bare Steel
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-357-2830
Tank Empty:	Not reported
Contact Name:	D C Clark
Contact Title:	Environmental Engr
Owner ID:	25281
Owner Type:	Private Or Corp.
Owner Name:	BNSF R.R. %M. CLIFT
Owner Address:	4515 KANSAS AVE
Owner City:	KANSAS CITY
Owner State:	KS
Owner Zip:	66106
Owner County:	105
Owner Phone:	913-551-3990
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1900
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Steel
Petroleum Substance:	Empty
Owner Replacement Name:	MICHAEL CLIFT
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.85131
Longitude:	-97.60681

U85 **SMOKY HILL WEAPONS RANGE** **KS SHWS** **S101713735**
SSW **N/A**
1/8-1/4 **SALINA, KS**
0.186 mi.
981 ft. **Site 3 of 4 in cluster U**

Relative:
Higher

Actual:
1262 ft.

SHWS:

Site ID:	1594
Has Env Use Control:	No
Project code:	C508500068
PM Name:	CHACE, M.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.73307 / -97.84983
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Dakota, Kiowa
Parent PC:	C208703010
Parent Name:	MCCONNELL AFB (PARENT SITE)
CERCLIS ID:	KS2572890026
Discovery Date:	01/01/1985
Depth To GW:	11-20 feet
Depth To Bedrock:	31-50 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	Department of Defense
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Inorganic, SVOC, VOC
Media Act:	Soil
Media Pot:	Ground Water, Soil, Surface Water
Source:	Other (see Site Narrative)
Land Use:	Other (see Site Narrative)
Private well:	Monitoring, Other (see Site Narrative)
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	KANSAS AIR NATIONAL GUARD 184TH INTELLIGENCE WING; MCCONNELL AFB SMOKY HILL WEAPONS RANGE; SMOKY HILL AIR NATIONAL GUARD RANGE
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Supplemental Site Sampling
Activity Status:	Completed
Activity Start Date:	04/20/2017
Activity End Date:	07/31/2018
Narrative:	Smoky Hill Weapons Range is located southwest of the town of Salina. The site is approximately 90 miles northwest of McConnell Air Force Base and encompasses approximately 34,000 acres. It is used as an active practice bombing range for the Kansas Air National Guard (KANG). Several subsites on the range were investigated by the Air Force (US AF) from approximately 1985 to 1995. These sites included a landfill

SMOKY HILL WEAPONS RANGE (Continued) **S101713735**

(DP009), ordnance disposal trench (DP012), drum disposal site (SS019), and a UST leak (SS020). The Air Force performed a preliminary investigation and published decision documents stating that no further action for the sites was required. However, these were internal documents and not submitted for regulatory approval.

Headquarters Disposal Site (DP009) was formerly used (1946-1983) as a landfill for disposal of oily wastes & solvents, using trench-&-burn methods. Currently, the landfill is closed and covered with soil & grass. Previous investigations indicated metals contamination (arsenic, mercury, lead). Further sampling will be conducted to characterize any soil & groundwater contamination. In 2018, a Remedial Investigation and Interim Measures were performed, including excavation and sampling of soil for dioxins/furans.

Open Burning / Open Detonation Site (DP012) is a small (70 by 150 fe et) area which was formerly used for disposal of unserviceable ordnance, starting in 1979, by open burning in a burn pit. Trench excavation confirmatory soil sample results from previous investigations indicate that soil contamination is below screening criteria. USAF requested no further action (NFA) in 2012; however, because groundwater (GW) has not been previously characterized, further investigation of GW at DP012 is required. GW samples will be collected from six (6) new monitoring wells, and analyzed for VOCs, SVOCs, TPH (LRH, MRH, HRH), and metals.

Drum Drainage Area Spill Site 19 (SS019) is a 1-acre area which was formerly used for empty drum storage. Small quantities of the drums? residual contents, reportedly deicing fluids and oils, were drained to the ground. Previous investigations indicated that metals were found in GW above screening criteria, but were possibly naturally occurring. USAF requested no further action (NFA) in 2012; however, KDHE requested additional GW samples be collected to further characterize the area of the surface spills, and follow up on previous metal exceedances in groundwater. In 2016, GW samples will be collected from four (4) new monitoring wells installed within the former surface release area (where only soil samples had been previously collected), and analyzed for VOCs, SVOCs, TPH (LRH, MRH, HRH), and metals.

Mobility Gasoline (MOGAS) UST Rupture Spill Site 20 (SS020) is a 1-a cre area which was formerly (approx. 1983-1991) used as a vehicle refueling facility. Previous investigations indicated that GW contamination has been present (1,2-DCA). GW samples were not collected within the historic spill site, so further evaluation of GW is required to determine the extent of contamination. Status of UST that failed leak test in 1991 is currently unknown.

As a result of further investigation, the Air Force will be performi ng additional activities on the site. U.S. Air Force recently entered into a Performance-Based Remediation contract with URS Group Inc., and began working with KDHE to further address the sites (discussed above) in 2014-2020.

Site ID:	1594
Has Env Use Control:	No
Project code:	C508500068
PM Name:	CHACE, M.
Site Status:	**Active**

SMOKY HILL WEAPONS RANGE (Continued) **S101713735**

District Office:	NCDO
Lat/Long:	38.73307 / -97.84983
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Dakota, Kiowa
Parent PC:	C208703010
Parent Name:	MCCONNELL AFB (PARENT SITE)
CERCLIS ID:	KS2572890026
Discovery Date:	01/01/1985
Depth To GW:	11-20 feet
Depth To Bedrock:	31-50 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	Department of Defense
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Inorganic, SVOC, VOC
Media Act:	Soil
Media Pot:	Ground Water, Soil, Surface Water
Source:	Other (see Site Narrative)
Land Use:	Other (see Site Narrative)
Private well:	Monitoring, Other (see Site Narrative)
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	KANSAS AIR NATIONAL GUARD 184TH INTELLIGENCE WING; MCCONNELL AFB SMOKY HILL WEAPONS RANGE; SMOKY HILL AIR NATIONAL GUARD RANGE
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Supplemental Site Sampling
Activity Status:	Completed
Activity Start Date:	04/20/2017
Activity End Date:	07/31/2018
Narrative:	Smoky Hill Weapons Range is located southwest of the town of Salina. The site is approximately 90 miles northwest of McConnell Air Force Base and encompasses approximately 34,000 acres. It is used as an active practice bombing range for the Kansas Air National Guard (KANG). Several subsites on the range were investigated by the Air Force (US AF) from approximately 1985 to 1995. These sites included a landfill (DP009), ordnance disposal trench (DP012), drum disposal site (SS019), and a UST leak (SS020). The Air Force performed a preliminary investigation and published decision documents stating that no further action for the sites was required. However, these were internal documents and not submitted for regulatory approval. Headquarters Disposal Site (DP009) was formerly used (1946-1983) as a landfill for disposal of oily wastes & solvents, using trench-&-burn methods. Currently, the landfill is closed and covered with soil & grass. Previous investigations indicated metals

SMOKY HILL WEAPONS RANGE (Continued) **S101713735**

contamination (arsenic, mercury, lead). Further sampling will be conducted to characterize any soil & groundwater contamination. In 2018, a Remedial Investigation and Interim Measures were performed, including excavation and sampling of soil for dioxins/furans.

Open Burning / Open Detonation Site (DP012) is a small (70 by 150 fe et) area which was formerly used for disposal of unserviceable ordnance, starting in 1979, by open burning in a burn pit. Trench excavation confirmatory soil sample results from previous investigations indicate that soil contamination is below screening criteria. USAF requested no further action (NFA) in 2012; however, because groundwater (GW) has not been previously characterized, further investigation of GW at DP012 is required. GW samples will be collected from six (6) new monitoring wells, and analyzed for VOCs, SVOCs, TPH (LRH, MRH, HRH), and metals.

Drum Drainage Area Spill Site 19 (SS019) is a 1-acre area which was formerly used for empty drum storage. Small quantities of the drums? residual contents, reportedly deicing fluids and oils, were drained to the ground. Previous investigations indicated that metals were found in GW above screening criteria, but were possibly naturally occurring. USAF requested no further action (NFA) in 2012; however, KDHE requested additional GW samples be collected to further characterize the area of the surface spills, and follow up on previous metal exceedances in groundwater. In 2016, GW samples will be collected from four (4) new monitoring wells installed within the former surface release area (where only soil samples had been previously collected), and analyzed for VOCs, SVOCs, TPH (LRH, MRH, HRH), and metals.

Mobility Gasoline (MOGAS) UST Rupture Spill Site 20 (SS020) is a 1-a cre area which was formerly (approx. 1983-1991) used as a vehicle refueling facility. Previous investigations indicated that GW contamination has been present (1,2-DCA). GW samples were not collected within the historic spill site, so further evaluation of GW is required to determine the extent of contamination. Status of UST that failed leak test in 1991 is currently unknown.

As a result of further investigation, the Air Force will be performi ng additional activities on the site. U.S. Air Force recently entered into a Performance-Based Remediation contract with URS Group Inc., and began working with KDHE to further address the sites (discussed above) in 2014-2020.

Site ID:	1594
Has Env Use Control:	No
Project code:	C508500068
PM Name:	CHACE, M.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.73307 / -97.84983
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Dakota, Kiowa
Parent PC:	C208703010
Parent Name:	MCCONNELL AFB (PARENT SITE)
CERCLIS ID:	KS2572890026
Discovery Date:	01/01/1985
Depth To GW:	11-20 feet

SMOKY HILL WEAPONS RANGE (Continued) **S101713735**

Depth To Bedrock:	31-50 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	Department of Defense
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Inorganic, SVOC, VOC
Media Act:	Soil
Media Pot:	Ground Water, Soil, Surface Water
Source:	Other (see Site Narrative)
Land Use:	Other (see Site Narrative)
Private well:	Monitoring, Other (see Site Narrative)
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	KANSAS AIR NATIONAL GUARD 184TH INTELLIGENCE WING; MCCONNELL AFB SMOKY HILL WEAPONS RANGE; SMOKY HILL AIR NATIONAL GUARD RANGE
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Supplemental Site Sampling
Activity Status:	Completed
Activity Start Date:	04/20/2017
Activity End Date:	07/31/2018
Narrative:	Smoky Hill Weapons Range is located southwest of the town of Salina. The site is approximately 90 miles northwest of McConnell Air Force Base and encompasses approximately 34,000 acres. It is used as an active practice bombing range for the Kansas Air National Guard (KANG). Several subsites on the range were investigated by the Air Force (US AF) from approximately 1985 to 1995. These sites included a landfill (DP009), ordnance disposal trench (DP012), drum disposal site (SS019), and a UST leak (SS020). The Air Force performed a preliminary investigation and published decision documents stating that no further action for the sites was required. However, these were internal documents and not submitted for regulatory approval. Headquarters Disposal Site (DP009) was formerly used (1946-1983) as a landfill for disposal of oily wastes & solvents, using trench-&-burn methods. Currently, the landfill is closed and covered with soil & grass. Previous investigations indicated metals contamination (arsenic, mercury, lead). Further sampling will be conducted to characterize any soil & groundwater contamination. In 2018, a Remedial Investigation and Interim Measures were performed, including excavation and sampling of soil for dioxins/furans. Open Burning / Open Detonation Site (DP012) is a small (70 by 150 fe et) area which was formerly used for disposal of unserviceable ordnance, starting in 1979, by open burning in a burn pit. Trench excavation confirmatory soil sample results from previous investigations indicate that soil contamination is below screening

SMOKY HILL WEAPONS RANGE (Continued) **S101713735**

criteria. USAF requested no further action (NFA) in 2012; however, because groundwater (GW) has not been previously characterized, further investigation of GW at DP012 is required. GW samples will be collected from six (6) new monitoring wells, and analyzed for VOCs, SVOCs, TPH (LRH, MRH, HRH), and metals.

Drum Drainage Area Spill Site 19 (SS019) is a 1-acre area which was formerly used for empty drum storage. Small quantities of the drums? residual contents, reportedly deicing fluids and oils, were drained to the ground. Previous investigations indicated that metals were found in GW above screening criteria, but were possibly naturally occurring. USAF requested no further action (NFA) in 2012; however, KDHE requested additional GW samples be collected to further characterize the area of the surface spills, and follow up on previous metal exceedances in groundwater. In 2016, GW samples will be collected from four (4) new monitoring wells installed within the former surface release area (where only soil samples had been previously collected), and analyzed for VOCs, SVOCs, TPH (LRH, MRH, HRH), and metals.

Mobility Gasoline (MOGAS) UST Rupture Spill Site 20 (SS020) is a 1-a cre area which was formerly (approx. 1983-1991) used as a vehicle refueling facility. Previous investigations indicated that GW contamination has been present (1,2-DCA). GW samples were not collected within the historic spill site, so further evaluation of GW is required to determine the extent of contamination. Status of UST that failed leak test in 1991 is currently unknown.

As a result of further investigation, the Air Force will be performi ng additional activities on the site. U.S. Air Force recently entered into a Performance-Based Remediation contract with URS Group Inc., and began working with KDHE to further address the sites (discussed above) in 2014-2020.

Site ID:	1594
Has Env Use Control:	No
Project code:	C508500068
PM Name:	CHACE, M.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.73307 / -97.84983
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Dakota, Kiowa
Parent PC:	C208703010
Parent Name:	MCCONNELL AFB (PARENT SITE)
CERCLIS ID:	KS2572890026
Discovery Date:	01/01/1985
Depth To GW:	11-20 feet
Depth To Bedrock:	31-50 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	Department of Defense
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Inorganic, SVOC, VOC
Media Act:	Soil

SMOKY HILL WEAPONS RANGE (Continued) **S101713735**

Media Pot:	Ground Water, Soil, Surface Water
Source:	Other (see Site Narrative)
Land Use:	Other (see Site Narrative)
Private well:	Monitoring, Other (see Site Narrative)
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	KANSAS AIR NATIONAL GUARD 184TH INTELLIGENCE WING; MCCONNELL AFB SMOKY HILL WEAPONS RANGE; SMOKY HILL AIR NATIONAL GUARD RANGE
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Supplemental Site Sampling
Activity Status:	Completed
Activity Start Date:	04/20/2017
Activity End Date:	07/31/2018
Narrative:	Smoky Hill Weapons Range is located southwest of the town of Salina. The site is approximately 90 miles northwest of McConnell Air Force Base and encompasses approximately 34,000 acres. It is used as an active practice bombing range for the Kansas Air National Guard (KANG). Several subsites on the range were investigated by the Air Force (US AF) from approximately 1985 to 1995. These sites included a landfill (DP009), ordnance disposal trench (DP012), drum disposal site (SS019), and a UST leak (SS020). The Air Force performed a preliminary investigation and published decision documents stating that no further action for the sites was required. However, these were internal documents and not submitted for regulatory approval. Headquarters Disposal Site (DP009) was formerly used (1946-1983) as a landfill for disposal of oily wastes & solvents, using trench-&-burn methods. Currently, the landfill is closed and covered with soil & grass. Previous investigations indicated metals contamination (arsenic, mercury, lead). Further sampling will be conducted to characterize any soil & groundwater contamination. In 2018, a Remedial Investigation and Interim Measures were performed, including excavation and sampling of soil for dioxins/furans. Open Burning / Open Detonation Site (DP012) is a small (70 by 150 fe et) area which was formerly used for disposal of unserviceable ordnance, starting in 1979, by open burning in a burn pit. Trench excavation confirmatory soil sample results from previous investigations indicate that soil contamination is below screening criteria. USAF requested no further action (NFA) in 2012; however, because groundwater (GW) has not been previously characterized, further investigation of GW at DP012 is required. GW samples will be collected from six (6) new monitoring wells, and analyzed for VOCs, SVOCs, TPH (LRH, MRH, HRH), and metals. Drum Drainage Area Spill Site 19 (SS019) is a 1-acre area which was formerly used for empty drum storage. Small quantities of the drums? residual contents, reportedly deicing fluids and oils, were drained to the ground. Previous investigations indicated that metals were found in GW above screening criteria, but were possibly naturally

SMOKY HILL WEAPONS RANGE (Continued) **S101713735**

occurring. USAF requested no further action (NFA) in 2012; however, KDHE requested additional GW samples be collected to further characterize the area of the surface spills, and follow up on previous metal exceedances in groundwater. In 2016, GW samples will be collected from four (4) new monitoring wells installed within the former surface release area (where only soil samples had been previously collected), and analyzed for VOCs, SVOCs, TPH (LRH, MRH, HRH), and metals.

Mobility Gasoline (MOGAS) UST Rupture Spill Site 20 (SS020) is a 1-a cre area which was formerly (approx. 1983-1991) used as a vehicle refueling facility. Previous investigations indicated that GW contamination has been present (1,2-DCA). GW samples were not collected within the historic spill site, so further evaluation of GW is required to determine the extent of contamination. Status of UST that failed leak test in 1991 is currently unknown.

As a result of further investigation, the Air Force will be performi ng additional activities on the site. U.S. Air Force recently entered into a Performance-Based Remediation contract with URS Group Inc., and began working with KDHE to further address the sites (discussed above) in 2014-2020.

Site ID:	1594
Has Env Use Control:	No
Project code:	C508500068
PM Name:	CHACE, M.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.73307 / -97.84983
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Dakota, Kiowa
Parent PC:	C208703010
Parent Name:	MCCONNELL AFB (PARENT SITE)
CERCLIS ID:	KS2572890026
Discovery Date:	01/01/1985
Depth To GW:	11-20 feet
Depth To Bedrock:	31-50 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	Department of Defense
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Inorganic, SVOC, VOC
Media Act:	Soil
Media Pot:	Ground Water, Soil, Surface Water
Source:	Other (see Site Narrative)
Land Use:	Other (see Site Narrative)
Private well:	Monitoring, Other (see Site Narrative)
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported

SMOKY HILL WEAPONS RANGE (Continued) **S101713735**

Remed Water: Not reported
Remedir: Not reported
Alias: KANSAS AIR NATIONAL GUARD 184TH INTELLIGENCE WING; MCCONNELL AFB SMOKY HILL WEAPONS RANGE; SMOKY HILL AIR NATIONAL GUARD RANGE
Eucan Number: Not reported
Date: Not reported
Activity Type: Supplemental Site Sampling
Activity Status: Completed
Activity Start Date: 04/20/2017
Activity End Date: 07/31/2018
Narrative: Smoky Hill Weapons Range is located southwest of the town of Salina. The site is approximately 90 miles northwest of McConnell Air Force Base and encompasses approximately 34,000 acres. It is used as an active practice bombing range for the Kansas Air National Guard (KANG).

Several subsites on the range were investigated by the Air Force (US AF) from approximately 1985 to 1995. These sites included a landfill (DP009), ordnance disposal trench (DP012), drum disposal site (SS019), and a UST leak (SS020). The Air Force performed a preliminary investigation and published decision documents stating that no further action for the sites was required. However, these were internal documents and not submitted for regulatory approval.

Headquarters Disposal Site (DP009) was formerly used (1946-1983) as a landfill for disposal of oily wastes & solvents, using trench-&-burn methods. Currently, the landfill is closed and covered with soil & grass. Previous investigations indicated metals contamination (arsenic, mercury, lead). Further sampling will be conducted to characterize any soil & groundwater contamination. In 2018, a Remedial Investigation and Interim Measures were performed, including excavation and sampling of soil for dioxins/furans.

Open Burning / Open Detonation Site (DP012) is a small (70 by 150 fe et) area which was formerly used for disposal of unserviceable ordnance, starting in 1979, by open burning in a burn pit. Trench excavation confirmatory soil sample results from previous investigations indicate that soil contamination is below screening criteria. USAF requested no further action (NFA) in 2012; however, because groundwater (GW) has not been previously characterized, further investigation of GW at DP012 is required. GW samples will be collected from six (6) new monitoring wells, and analyzed for VOCs, SVOCs, TPH (LRH, MRH, HRH), and metals.

Drum Drainage Area Spill Site 19 (SS019) is a 1-acre area which was formerly used for empty drum storage. Small quantities of the drums? residual contents, reportedly deicing fluids and oils, were drained to the ground. Previous investigations indicated that metals were found in GW above screening criteria, but were possibly naturally occurring. USAF requested no further action (NFA) in 2012; however, KDHE requested additional GW samples be collected to further characterize the area of the surface spills, and follow up on previous metal exceedances in groundwater. In 2016, GW samples will be collected from four (4) new monitoring wells installed within the former surface release area (where only soil samples had been previously collected), and analyzed for VOCs, SVOCs, TPH (LRH, MRH, HRH), and metals.

Mobility Gasoline (MOGAS) UST Rupture Spill Site 20 (SS020) is a 1-a cre area which was formerly (approx. 1983-1991) used as a vehicle

SMOKY HILL WEAPONS RANGE (Continued) **S101713735**

refueling facility. Previous investigations indicated that GW contamination has been present (1,2-DCA). GW samples were not collected within the historic spill site, so further evaluation of GW is required to determine the extent of contamination. Status of UST that failed leak test in 1991 is currently unknown.
As a result of further investigation, the Air Force will be performi ng additional activities on the site. U.S. Air Force recently entered into a Performance-Based Remediation contract with URS Group Inc., and began working with KDHE to further address the sites (discussed above) in 2014-2020.

Site ID:	1594
Has Env Use Control:	No
Project code:	C508500068
PM Name:	CHACE, M.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.73307 / -97.84983
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Dakota, Kiowa
Parent PC:	C208703010
Parent Name:	MCCONNELL AFB (PARENT SITE)
CERCLIS ID:	KS2572890026
Discovery Date:	01/01/1985
Depth To GW:	11-20 feet
Depth To Bedrock:	31-50 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	Department of Defense
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Inorganic, SVOC, VOC
Media Act:	Soil
Media Pot:	Ground Water, Soil, Surface Water
Source:	Other (see Site Narrative)
Land Use:	Other (see Site Narrative)
Private well:	Monitoring, Other (see Site Narrative)
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	KANSAS AIR NATIONAL GUARD 184TH INTELLIGENCE WING; MCCONNELL AFB SMOKY HILL WEAPONS RANGE; SMOKY HILL AIR NATIONAL GUARD RANGE
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Supplemental Site Sampling
Activity Status:	Completed
Activity Start Date:	04/20/2017
Activity End Date:	07/31/2018

SMOKY HILL WEAPONS RANGE (Continued) **S101713735**

Narrative: Smoky Hill Weapons Range is located southwest of the town of Salina. The site is approximately 90 miles northwest of McConnell Air Force Base and encompasses approximately 34,000 acres. It is used as an active practice bombing range for the Kansas Air National Guard (KANG).

Several subsites on the range were investigated by the Air Force (US AF) from approximately 1985 to 1995. These sites included a landfill (DP009), ordnance disposal trench (DP012), drum disposal site (SS019), and a UST leak (SS020). The Air Force performed a preliminary investigation and published decision documents stating that no further action for the sites was required. However, these were internal documents and not submitted for regulatory approval.

Headquarters Disposal Site (DP009) was formerly used (1946-1983) as a landfill for disposal of oily wastes & solvents, using trench-&-burn methods. Currently, the landfill is closed and covered with soil & grass. Previous investigations indicated metals contamination (arsenic, mercury, lead). Further sampling will be conducted to characterize any soil & groundwater contamination. In 2018, a Remedial Investigation and Interim Measures were performed, including excavation and sampling of soil for dioxins/furans.

Open Burning / Open Detonation Site (DP012) is a small (70 by 150 fe et) area which was formerly used for disposal of unserviceable ordnance, starting in 1979, by open burning in a burn pit. Trench excavation confirmatory soil sample results from previous investigations indicate that soil contamination is below screening criteria. USAF requested no further action (NFA) in 2012; however, because groundwater (GW) has not been previously characterized, further investigation of GW at DP012 is required. GW samples will be collected from six (6) new monitoring wells, and analyzed for VOCs, SVOCs, TPH (LRH, MRH, HRH), and metals.

Drum Drainage Area Spill Site 19 (SS019) is a 1-acre area which was formerly used for empty drum storage. Small quantities of the drums? residual contents, reportedly deicing fluids and oils, were drained to the ground. Previous investigations indicated that metals were found in GW above screening criteria, but were possibly naturally occurring. USAF requested no further action (NFA) in 2012; however, KDHE requested additional GW samples be collected to further characterize the area of the surface spills, and follow up on previous metal exceedances in groundwater. In 2016, GW samples will be collected from four (4) new monitoring wells installed within the former surface release area (where only soil samples had been previously collected), and analyzed for VOCs, SVOCs, TPH (LRH, MRH, HRH), and metals.

Mobility Gasoline (MOGAS) UST Rupture Spill Site 20 (SS020) is a 1-a cre area which was formerly (approx. 1983-1991) used as a vehicle refueling facility. Previous investigations indicated that GW contamination has been present (1,2-DCA). GW samples were not collected within the historic spill site, so further evaluation of GW is required to determine the extent of contamination. Status of UST that failed leak test in 1991 is currently unknown.

As a result of further investigation, the Air Force will be performi ng additional activities on the site. U.S. Air Force recently entered into a Performance-Based Remediation contract with URS Group Inc., and began working with KDHE to further address the sites

SMOKY HILL WEAPONS RANGE (Continued) **S101713735**

(discussed above) in 2014-2020.

Site ID:	1594
Has Env Use Control:	No
Project code:	C508500068
PM Name:	CHACE, M.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.73307 / -97.84983
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Dakota, Kiowa
Parent PC:	C208703010
Parent Name:	MCCONNELL AFB (PARENT SITE)
CERCLIS ID:	KS2572890026
Discovery Date:	01/01/1985
Depth To GW:	11-20 feet
Depth To Bedrock:	31-50 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	Department of Defense
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Inorganic, SVOC, VOC
Media Act:	Soil
Media Pot:	Ground Water, Soil, Surface Water
Source:	Other (see Site Narrative)
Land Use:	Other (see Site Narrative)
Private well:	Monitoring, Other (see Site Narrative)
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	KANSAS AIR NATIONAL GUARD 184TH INTELLIGENCE WING; MCCONNELL AFB SMOKY HILL WEAPONS RANGE; SMOKY HILL AIR NATIONAL GUARD RANGE
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Supplemental Site Sampling
Activity Status:	Completed
Activity Start Date:	04/20/2017
Activity End Date:	07/31/2018
Narrative:	Smoky Hill Weapons Range is located southwest of the town of Salina. The site is approximately 90 miles northwest of McConnell Air Force Base and encompasses approximately 34,000 acres. It is used as an active practice bombing range for the Kansas Air National Guard (KANG). Several subsites on the range were investigated by the Air Force (US AF) from approximately 1985 to 1995. These sites included a landfill (DP009), ordnance disposal trench (DP012), drum disposal site (SS019), and a UST leak (SS020). The Air Force performed a preliminary investigation and published decision documents stating

SMOKY HILL WEAPONS RANGE (Continued) **S101713735**

that no further action for the sites was required. However, these were internal documents and not submitted for regulatory approval.

Headquarters Disposal Site (DP009) was formerly used (1946-1983) as a landfill for disposal of oily wastes & solvents, using trench-&-burn methods. Currently, the landfill is closed and covered with soil & grass. Previous investigations indicated metals contamination (arsenic, mercury, lead). Further sampling will be conducted to characterize any soil & groundwater contamination. In 2018, a Remedial Investigation and Interim Measures were performed, including excavation and sampling of soil for dioxins/furans.

Open Burning / Open Detonation Site (DP012) is a small (70 by 150 fe et) area which was formerly used for disposal of unserviceable ordnance, starting in 1979, by open burning in a burn pit. Trench excavation confirmatory soil sample results from previous investigations indicate that soil contamination is below screening criteria. USAF requested no further action (NFA) in 2012; however, because groundwater (GW) has not been previously characterized, further investigation of GW at DP012 is required. GW samples will be collected from six (6) new monitoring wells, and analyzed for VOCs, SVOCs, TPH (LRH, MRH, HRH), and metals.

Drum Drainage Area Spill Site 19 (SS019) is a 1-acre area which was formerly used for empty drum storage. Small quantities of the drums? residual contents, reportedly deicing fluids and oils, were drained to the ground. Previous investigations indicated that metals were found in GW above screening criteria, but were possibly naturally occurring. USAF requested no further action (NFA) in 2012; however, KDHE requested additional GW samples be collected to further characterize the area of the surface spills, and follow up on previous metal exceedances in groundwater. In 2016, GW samples will be collected from four (4) new monitoring wells installed within the former surface release area (where only soil samples had been previously collected), and analyzed for VOCs, SVOCs, TPH (LRH, MRH, HRH), and metals.

Mobility Gasoline (MOGAS) UST Rupture Spill Site 20 (SS020) is a 1-a cre area which was formerly (approx. 1983-1991) used as a vehicle refueling facility. Previous investigations indicated that GW contamination has been present (1,2-DCA). GW samples were not collected within the historic spill site, so further evaluation of GW is required to determine the extent of contamination. Status of UST that failed leak test in 1991 is currently unknown.

As a result of further investigation, the Air Force will be performi ng additional activities on the site. U.S. Air Force recently entered into a Performance-Based Remediation contract with URS Group Inc., and began working with KDHE to further address the sites (discussed above) in 2014-2020.

Site ID:	1594
Has Env Use Control:	No
Project code:	C508500068
PM Name:	CHACE, M.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.73307 / -97.84983
River Basin:	Smoky Hills - Saline

SMOKY HILL WEAPONS RANGE (Continued) **S101713735**

Aquifer Yield:	Alluvial
Other Aquifers:	Dakota, Kiowa
Parent PC:	C208703010
Parent Name:	MCCONNELL AFB (PARENT SITE)
CERCLIS ID:	KS2572890026
Discovery Date:	01/01/1985
Depth To GW:	11-20 feet
Depth To Bedrock:	31-50 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	NE
Acres Affected:	>500 acres
Waste Present:	No
Product Present:	No
Program:	Department of Defense
Lead Agency:	BER - Remedial
Contaminants:	Heavy Metal, Inorganic, SVOC, VOC
Media Act:	Soil
Media Pot:	Ground Water, Soil, Surface Water
Source:	Other (see Site Narrative)
Land Use:	Other (see Site Narrative)
Private well:	Monitoring, Other (see Site Narrative)
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	KANSAS AIR NATIONAL GUARD 184TH INTELLIGENCE WING; MCCONNELL AFB SMOKY HILL WEAPONS RANGE; SMOKY HILL AIR NATIONAL GUARD RANGE
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Supplemental Site Sampling
Activity Status:	Completed
Activity Start Date:	04/20/2017
Activity End Date:	07/31/2018
Narrative:	Smoky Hill Weapons Range is located southwest of the town of Salina. The site is approximately 90 miles northwest of McConnell Air Force Base and encompasses approximately 34,000 acres. It is used as an active practice bombing range for the Kansas Air National Guard (KANG). Several subsites on the range were investigated by the Air Force (US AF) from approximately 1985 to 1995. These sites included a landfill (DP009), ordnance disposal trench (DP012), drum disposal site (SS019), and a UST leak (SS020). The Air Force performed a preliminary investigation and published decision documents stating that no further action for the sites was required. However, these were internal documents and not submitted for regulatory approval. Headquarters Disposal Site (DP009) was formerly used (1946-1983) as a landfill for disposal of oily wastes & solvents, using trench-&-burn methods. Currently, the landfill is closed and covered with soil & grass. Previous investigations indicated metals contamination (arsenic, mercury, lead). Further sampling will be conducted to characterize any soil & groundwater contamination. In 2018, a Remedial Investigation and Interim Measures were performed,

SMOKY HILL WEAPONS RANGE (Continued) **S101713735**

including excavation and sampling of soil for dioxins/furans.

Open Burning / Open Detonation Site (DP012) is a small (70 by 150 fe et) area which was formerly used for disposal of unserviceable ordnance, starting in 1979, by open burning in a burn pit. Trench excavation confirmatory soil sample results from previous investigations indicate that soil contamination is below screening criteria. USAF requested no further action (NFA) in 2012; however, because groundwater (GW) has not been previously characterized, further investigation of GW at DP012 is required. GW samples will be collected from six (6) new monitoring wells, and analyzed for VOCs, SVOCs, TPH (LRH, MRH, HRH), and metals.

Drum Drainage Area Spill Site 19 (SS019) is a 1-acre area which was formerly used for empty drum storage. Small quantities of the drums? residual contents, reportedly deicing fluids and oils, were drained to the ground. Previous investigations indicated that metals were found in GW above screening criteria, but were possibly naturally occurring. USAF requested no further action (NFA) in 2012; however, KDHE requested additional GW samples be collected to further characterize the area of the surface spills, and follow up on previous metal exceedances in groundwater. In 2016, GW samples will be collected from four (4) new monitoring wells installed within the former surface release area (where only soil samples had been previously collected), and analyzed for VOCs, SVOCs, TPH (LRH, MRH, HRH), and metals.

Mobility Gasoline (MOGAS) UST Rupture Spill Site 20 (SS020) is a 1-a cre area which was formerly (approx. 1983-1991) used as a vehicle refueling facility. Previous investigations indicated that GW contamination has been present (1,2-DCA). GW samples were not collected within the historic spill site, so further evaluation of GW is required to determine the extent of contamination. Status of UST that failed leak test in 1991 is currently unknown.

As a result of further investigation, the Air Force will be performi ng additional activities on the site. U.S. Air Force recently entered into a Performance-Based Remediation contract with URS Group Inc., and began working with KDHE to further address the sites (discussed above) in 2014-2020.

U86 **SCHILLING (EX) AIR FORCE BASE** **SEMS** **1000907989**
SSW **3237 ARNOLD AVE** **RCRA NonGen / NLR** **KS0000597922**
1/8-1/4 **SALINA, KS 67401** **PRP**
0.186 mi. **ICIS**
983 ft. **Site 4 of 4 in cluster U** **FINDS**
ECHO

Relative:
Higher

Actual:
1262 ft.

SEMS:

Site ID:	0703124
EPA ID:	KS0000597922
Cong District:	01
FIPS Code:	20169
Latitude:	Not reported
Longitude:	Not reported
FF:	N
NPL:	Not on the NPL
Non NPL Status:	Referred to Removal - NFRAP

SEMS Detail:

SCHILLING (EX) AIR FORCE BASE (Continued) **1000907989**

Region:	07
Site ID:	0703124
EPA ID:	KS0000597922
Site Name:	SCHILLING (EX) AIR FORCE BASE
NPL:	N
FF:	N
OU:	01
Action Code:	NH
Action Name:	FF RI
SEQ:	2
Start Date:	1998-08-25 04:00:00
Finish Date:	2/1/1999 5:00:00 AM
Qual:	Not reported
Current Action Lead:	Fed Fac

Region:	07
Site ID:	0703124
EPA ID:	KS0000597922
Site Name:	SCHILLING (EX) AIR FORCE BASE
NPL:	N
FF:	N
OU:	00
Action Code:	AR
Action Name:	ADMIN REC
SEQ:	1
Start Date:	2004-01-01 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	St Perf

Region:	07
Site ID:	0703124
EPA ID:	KS0000597922
Site Name:	SCHILLING (EX) AIR FORCE BASE
NPL:	N
FF:	N
OU:	00
Action Code:	CR
Action Name:	CI
SEQ:	1
Start Date:	2004-04-16 04:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	St Perf

Region:	07
Site ID:	0703124
EPA ID:	KS0000597922
Site Name:	SCHILLING (EX) AIR FORCE BASE
NPL:	N
FF:	N
OU:	00
Action Code:	RS
Action Name:	RV ASSESS
SEQ:	1
Start Date:	2000-09-19 04:00:00
Finish Date:	9/21/2000 4:00:00 AM

SCHILLING (EX) AIR FORCE BASE (Continued) **1000907989**

Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	07
Site ID:	0703124
EPA ID:	KS0000597922
Site Name:	SCHILLING (EX) AIR FORCE BASE
NPL:	N
FF:	N
OU:	00
Action Code:	LV
Action Name:	FF RV
SEQ:	2
Start Date:	1997-09-24 04:00:00
Finish Date:	3/17/1998 5:00:00 AM
Qual:	C
Current Action Lead:	Fed Fac
Region:	07
Site ID:	0703124
EPA ID:	KS0000597922
Site Name:	SCHILLING (EX) AIR FORCE BASE
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	3
Start Date:	Not reported
Finish Date:	7/30/1998 4:00:00 AM
Qual:	H
Current Action Lead:	EPA Perf
Region:	07
Site ID:	0703124
EPA ID:	KS0000597922
Site Name:	SCHILLING (EX) AIR FORCE BASE
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	2
Start Date:	Not reported
Finish Date:	10/1/1996 4:00:00 AM
Qual:	H
Current Action Lead:	EPA Perf
Region:	07
Site ID:	0703124
EPA ID:	KS0000597922
Site Name:	SCHILLING (EX) AIR FORCE BASE
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI

SCHILLING (EX) AIR FORCE BASE (Continued) **1000907989**

SEQ: 1
Start Date: 1996-02-21 05:00:00
Finish Date: 11/1/1996 5:00:00 AM
Qual: H
Current Action Lead: St Perf

Region: 07
Site ID: 0703124
EPA ID: KS0000597922
Site Name: SCHILLING (EX) AIR FORCE BASE
NPL: N
FF: N
OU: 00
Action Code: HR
Action Name: HAZRANK
SEQ: 1
Start Date: 2001-02-16 05:00:00
Finish Date: 10/23/2007 4:00:00 AM
Qual: W
Current Action Lead: EPA Perf

Region: 07
Site ID: 0703124
EPA ID: KS0000597922
Site Name: SCHILLING (EX) AIR FORCE BASE
NPL: N
FF: N
OU: 00
Action Code: ES
Action Name: ESI
SEQ: 1
Start Date: 1999-09-14 04:00:00
Finish Date: 3/19/2001 5:00:00 AM
Qual: G
Current Action Lead: EPA Perf

Region: 07
Site ID: 0703124
EPA ID: KS0000597922
Site Name: SCHILLING (EX) AIR FORCE BASE
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 2
Start Date: Not reported
Finish Date: 10/1/1989 4:00:00 AM
Qual: H
Current Action Lead: St Perf

Region: 07
Site ID: 0703124
EPA ID: KS0000597922
Site Name: SCHILLING (EX) AIR FORCE BASE
NPL: N
FF: N

SCHILLING (EX) AIR FORCE BASE (Continued) **1000907989**

OU: 00
Action Code: TY
Action Name: FF SI REV
SEQ: 1
Start Date: 1998-10-05 04:00:00
Finish Date: 9/17/1999 4:00:00 AM
Qual: H
Current Action Lead: EPA Perf

Region: 07
Site ID: 0703124
EPA ID: KS0000597922
Site Name: SCHILLING (EX) AIR FORCE BASE
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: 1996-02-21 05:00:00
Finish Date: 11/1/1996 5:00:00 AM
Qual: H
Current Action Lead: St Perf

Region: 07
Site ID: 0703124
EPA ID: KS0000597922
Site Name: SCHILLING (EX) AIR FORCE BASE
NPL: N
FF: N
OU: 00
Action Code: AS
Action Name: AIR SRVY
SEQ: 1
Start Date: 1998-10-19 04:00:00
Finish Date: 5/4/1999 4:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 07
Site ID: 0703124
EPA ID: KS0000597922
Site Name: SCHILLING (EX) AIR FORCE BASE
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 1996-02-21 05:00:00
Finish Date: 2/21/1996 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

RCRA NonGen / NLR:
Date form received by agency: 10/15/2004

SCHILLING (EX) AIR FORCE BASE (Continued) **1000907989**

Facility name:	SALINA AIRPORT AUTHORITY
Facility address:	3237 ARNOLD AVE SALINA, KS 67401
EPA ID:	KS0000597922
Mailing address:	ARNOLD AVE SALINA, KS 67401
Contact:	TIMOTHY F ROGERS
Contact address:	ARNOLD AVE SALINA, KS 67401
Contact country:	US
Contact telephone:	785-827-3914
Contact email:	Not reported
EPA Region:	07
Land type:	Municipal
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	SALINA AIRPORT AUTHORITY
Owner/operator address:	3237 ARNOLD AVE SALINA, KS 67401
Owner/operator country:	Not reported
Owner/operator telephone:	785-827-3914
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/02/2004
Site name:	CORPS OF ENGINEERS SCHILLING AFB
Classification:	Not a generator, verified
Date form received by agency:	08/19/2002
Site name:	CORPS OF ENGINEERS SCHILLING AFB
Classification:	Small Quantity Generator

SCHILLING (EX) AIR FORCE BASE (Continued) **1000907989**

Date form received by agency: 02/25/1998
Site name: CORPS OF ENGINEERS
Classification: Large Quantity Generator

Date form received by agency: 08/22/1994
Site name: CORPS OF ENGINEERS SCHILLING AFB
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

. Waste code: D019
. Waste name: CARBON TETRACHLORIDE

. Waste code: D029
. Waste name: 1,1-DICHLOROETHYLENE

. Waste code: D030
. Waste name: 2,4-DINITROTOLUENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: D043
. Waste name: VINYL CHLORIDE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 08/07/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

PRP:
PRP Name: SALINA, CITY OF
U.S. ARMY CORPS OF ENGINEERS
US DEPT. OF DEFENSE (DOD) - DC

ICIS:
Enforcement Action ID: 07-2010-0356
FRS ID: 110000793106
Action Name: SCHILLING (EX) AIR FORCE BASE
Facility Name: SCHILLING (EX) AIR FORCE BASE
Facility Address: 3237 ARNOLD AVE
SALINA, KS 674010000
Enforcement Action Type: Civil Judicial Action
Facility County: SALINE
Program System Acronym: ICIS
Enforcement Action Forum Desc: Judicial

SCHILLING (EX) AIR FORCE BASE (Continued) **1000907989**

EA Type Code: CIV
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 38.778705
Longitude in Decimal Degrees: -97.639532
Permit Type Desc: Not reported
Program System Acronym: 2200007652
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Facility Name: SALINA AIRPORT AUTHORITY
Address: 3237 ARNOLD AVE
Tribal Indicator: N
Fed Facility: Yes
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: SALINA AIRPORT AUTHORITY
Address: 3237 ARNOLD AVE
Tribal Indicator: N
Fed Facility: Yes
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: SALINA AIRPORT AUTHORITY
Address: 3237 ARNOLD AVE
Tribal Indicator: N
Fed Facility: Yes
NAIC Code: Not reported
SIC Code: Not reported

FINDS:

Registry ID: 110000793106

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

SUPERFUND (NON-NPL)

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also

SCHILLING (EX) AIR FORCE BASE (Continued) **1000907989**

has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000907989
Registry ID:	110000793106
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110000793106

T87 **SCHILLING DEF-GM FLD MAIN** **FUDS** **1024898516**
NNE **N/A**
1/8-1/4 **SALINA, KS**
0.190 mi.
1001 ft. **Site 2 of 2 in cluster T**

Relative: **Lower**

Actual: **1242 ft.**

FUDS:

EPA Region:	7
Installation ID:	KS79799F024900
Congressional District Number:	1
Facility Name:	SCHILLING DEF-GM FLD MAIN
FUDS Number:	B07KS0162
City:	SALINA
State:	KS
County:	SALINE
Telephone:	816-389-3072
USACE Division:	Northwestern Division (NWD)
USACE District:	Kansas City District (NWK)
Status:	Properties without projects
Current Owner:	Local Government
X Coord:	-97.632777780369594
Y Coord:	38.793055560066897
Latitude:	38.793055559999999
Longitude:	-97.632777779999998

---

88 **SCHILLING AFB AF FACILITY "C"** **KS SHWS** **S112062548**
NW **NA** **N/A**
1/8-1/4 **NA, KS NA**
0.203 mi.
1072 ft.

Relative: **Lower**

Actual: **1254 ft.**

SHWS:

Site ID:	1618
Has Env Use Control:	No
Project code:	C508571180
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.79258 / -97.64621
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013

SCHILLING AFB AF FACILITY "C" (Continued) **S112062548**

Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	01/01/1990
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	0-10 gpm
GW Flow Direction:	Not reported
Acres Affected:	>>500 acres
Waste Present:	No
Product Present:	No
Program:	FUDS (Formerly Used Defense Sites)
Lead Agency:	BER - Remedial
Contaminants:	Other (see Site Narrative)
Media Act:	Not reported
Media Pot:	Not reported
Source:	Abandoned Facility
Land Use:	Agricultural, Commercial, Industrial, Residential
Private well:	Domestic, Irrigation
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Initial Site Screening
Activity Status:	Completed
Activity Start Date:	01/01/2001
Activity End Date:	01/31/2001
Narrative:	This facility consists entirely of buried communications cables connecting the twelve Schilling Atlas F Missile sites to the former Schilling Air Force Base. No contamination is suspected, and no further action is warranted. Finding the actual cable runs would be very difficult and expensive.
Site ID:	1618
Has Env Use Control:	No
Project code:	C508571180
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.79258 / -97.64621
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	01/01/1990
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	0-10 gpm
GW Flow Direction:	Not reported

SCHILLING AFB AF FACILITY "C" (Continued) **S112062548**

Acres Affected:	>>500 acres
Waste Present:	No
Product Present:	No
Program:	FUDS (Formerly Used Defense Sites)
Lead Agency:	BER - Remedial
Contaminants:	Other (see Site Narrative)
Media Act:	Not reported
Media Pot:	Not reported
Source:	Abandoned Facility
Land Use:	Agricultural, Commercial, Industrial, Residential
Private well:	Domestic, Irrigation
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Initial Site Screening
Activity Status:	Completed
Activity Start Date:	01/01/2001
Activity End Date:	01/31/2001
Narrative:	This facility consists entirely of buried communications cables connecting the twelve Schilling Atlas F Missile sites to the former Schilling Air Force Base. No contamination is suspected, and no further action is warranted. Finding the actual cable runs would be very difficult and expensive.

V89 **SALINA AREA TECHNICAL COLLEGE** **RCRA-CESQG** **1000255605**
North **2562 CENTENNIAL RD** **KSD120780424**
1/8-1/4 **SALINA, KS 67401**
0.242 mi.
1277 ft. **Site 1 of 2 in cluster V**

Relative: RCRA-CESQG:
Lower

Date form received by agency:	02/01/2018
Facility name:	SALINA AREA TECHNICAL COLLEGE
Facility address:	2562 CENTENNIAL RD SALINA, KS 67401
EPA ID:	KSD120780424
Contact:	ANDREW T MANLEY
Contact address:	2562 CENTENNIAL RD SALINA, KS 67401
Contact country:	US
Contact telephone:	785-309-3120
Contact email:	ANDREW.MANLEY@SALINATECH.EDU
EPA Region:	07
Land type:	State
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or

Actual:
1248 ft.

SALINA AREA TECHNICAL COLLEGE (Continued) **1000255605**

other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	ANDREW MANLEY
Owner/operator address:	2562 CENTENNIAL RD SALINA, KS 67401
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	10/01/2012
Owner/Op end date:	Not reported

Owner/operator name:	SALINA AREA TECH COLL
Owner/operator address:	2562 CENTENNIAL RD SALINA, KS 67401
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	10/10/1966
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/25/2017

SALINA AREA TECHNICAL COLLEGE (Continued) **1000255605**

Site name: SALINA AREA TECHNICAL COLLEGE
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/01/2016
Site name: SALINA AREA TECHNICAL COLLEGE
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/30/2015
Site name: SALINA AREA TECHNICAL COLLEGE
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/03/2014
Site name: SALINA AREA TECHNICAL COLLEGE
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/28/2013
Site name: SALINA AREA TECHNICAL COLLEGE
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 11/15/2012
Site name: SALINA AREA TECHNICAL COLLEGE
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 05/04/2012
Site name: SALINA AREA TECHNICAL COLLEGE
Classification: Small Quantity Generator

Date form received by agency: 11/15/2011
Site name: SALINA AREA TECHNICAL COLLEGE
Classification: Small Quantity Generator

Date form received by agency: 03/21/2011
Site name: SALINA AREA VOTECH SCHOOL
Classification: Small Quantity Generator

Date form received by agency: 01/22/2010
Site name: SALINA AREA VOTECH SCHOOL
Classification: Small Quantity Generator

Date form received by agency: 02/12/2009
Site name: SALINA AREA VOTECH SCHOOL
Classification: Small Quantity Generator

Date form received by agency: 02/14/2008
Site name: SALINA AREA VOTECH SCHOOL
Classification: Small Quantity Generator

Date form received by agency: 03/19/2007
Site name: SALINA AREA VOTECH SCHOOL
Classification: Small Quantity Generator

Date form received by agency: 02/16/2006
Site name: SALINA AREA VOTECH SCHOOL
Classification: Small Quantity Generator

Date form received by agency: 04/19/2005
Site name: SALINA AREA VOTECH SCHOOL

SALINA AREA TECHNICAL COLLEGE (Continued) **1000255605**

Classification: Small Quantity Generator

Date form received by agency: 04/04/2005
Site name: SALINA AREA VOTECH SCHOOL
Classification: Small Quantity Generator

Date form received by agency: 09/26/1994
Site name: SALINA AREA TECHNICAL COLLEGE
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D009
. Waste name: MERCURY

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 11/08/2011
Date achieved compliance: 01/06/2012
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/24/2012
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

SALINA AREA TECHNICAL COLLEGE (Continued) **1000255605**

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 11/08/2011
Date achieved compliance: 01/06/2012
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/08/2011
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 11/08/2011
Date achieved compliance: 01/27/2012
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/24/2012
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Used Oil - Generators
Date violation determined: 11/08/2011
Date achieved compliance: 11/08/2011
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 11/08/2011
Date achieved compliance: 01/27/2012
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/08/2011
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 j 1 B

SALINA AREA TECHNICAL COLLEGE (Continued) **1000255605**

Area of violation: Generators - Pre-transport
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/18/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 j 1 B
Area of violation: Generators - Pre-transport
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/10/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 j 1 A
Area of violation: Generators - Pre-transport
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/18/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 j 1 A
Area of violation: Generators - Pre-transport
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/10/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 h 2 A
Area of violation: Generators - Pre-transport

SALINA AREA TECHNICAL COLLEGE (Continued) **1000255605**

Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/18/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 h 2 A
Area of violation: Generators - Pre-transport
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/07/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 c 1
Area of violation: Generators - General
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/18/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 f 1 A
Area of violation: Generators - Manifest
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/10/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 c 1
Area of violation: Generators - General
Date violation determined: 03/08/2005

SALINA AREA TECHNICAL COLLEGE (Continued) **1000255605**

Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/10/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 h 7
Area of violation: Generators - Pre-transport
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/18/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 f 1 A
Area of violation: Generators - Manifest
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/18/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 c 1
Area of violation: Generators - General
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/07/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 h 7
Area of violation: Generators - Pre-transport
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005

SALINA AREA TECHNICAL COLLEGE (Continued) **1000255605**

Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/07/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 h 2A
Area of violation: Generators - Pre-transport
Date violation determined: 03/08/2005
Date achieved compliance: 03/08/2005
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 h 2 A
Area of violation: Generators - Pre-transport
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/10/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 f 1 A
Area of violation: Generators - Manifest
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/07/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 10 g 3
Area of violation: Generators - General
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State

SALINA AREA TECHNICAL COLLEGE (Continued) **1000255605**

Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/10/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 j 1 A
Area of violation: Generators - Pre-transport
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/07/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 h 7
Area of violation: Generators - Pre-transport
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/10/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 10 g 3
Area of violation: Generators - General
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/18/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 10 g 3
Area of violation: Generators - General
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL

SALINA AREA TECHNICAL COLLEGE (Continued) **1000255605**

Enforcement action date: 04/07/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - KAR 28 31 4 j 1 B
Area of violation: Generators - Pre-transport
Date violation determined: 03/08/2005
Date achieved compliance: 04/18/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/07/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 12/11/1990
Date achieved compliance: 05/29/1991
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/13/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 01/30/2012
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/24/2012
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/08/2011
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 01/27/2012
Evaluation lead agency: State

Evaluation date: 11/08/2011
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

SALINA AREA TECHNICAL COLLEGE (Continued) **1000255605**

Area of violation: Used Oil - Generators
Date achieved compliance: 11/08/2011
Evaluation lead agency: State

Evaluation date: 11/08/2011
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 01/06/2012
Evaluation lead agency: State

Evaluation date: 04/18/2005
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/07/2005
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/08/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 04/18/2005
Evaluation lead agency: State

Evaluation date: 03/08/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 04/18/2005
Evaluation lead agency: State

Evaluation date: 03/08/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 04/18/2005
Evaluation lead agency: State

Evaluation date: 03/08/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 03/08/2005
Evaluation lead agency: State

Evaluation date: 06/05/1991
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/11/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/29/1991
Evaluation lead agency: State

V90 **FORMER BEECH - SALINA** **KS SHWS** **S115488782**
North **2562 CENTENNIAL ROAD** **N/A**
1/8-1/4 **SALINA, KS 67401**
0.242 mi.
1277 ft. **Site 2 of 2 in cluster V**

Relative: **Lower**

Actual: **1248 ft.**

SHWS:

Site ID:	2915
Has Env Use Control:	No
Project code:	C508572964
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.793734 / -97.636824
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	31-50 feet
Depth To Bedrock:	31-50 feet
Aquifer Yield:	11-50 gpm
GW Flow Direction:	E
Acres Affected:	<5 acres
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING AFB OU1
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Transfer Within Bureau
Activity Status:	Completed
Activity Start Date:	Not reported
Activity End Date:	11/02/2016
Narrative:	The Former Beech-Salina site is located at the intersection of Scanlan Avenue and Derussy Road at the Salina Municipal Airport. The site is currently used by Salina Area Technical School which has an address of 2562 Centennial Road, #A, Salina, KS 67401. The legal description of the site is Section 34, Township 14 South, Range 3 West. Hawker-Beechcraft filed for bankruptcy in 2012. As part of the bankruptcy proceedings, its former Salina facility was included. Beech began ceasing operations in Salina in 2009.

FORMER BEECH - SALINA (Continued) **S115488782**

A review of Kansas Department of Health and Environment (KDHE) site files indicated several Resource Conservation and Recovery Act (RCRA), air, and wastewater-pretreatment files for the Former Beech-Salina area. The Salina Municipal Airport has been an industrial park since the closure of the Schilling Air Force Base and reversion of the buildings and land to the Salina Airport Authority in 1965. Hakwer-Beechcraft began operating at Salina as Beechcraft in 1966.

The site also has an extensive history of previous Comprehensive Env ironmental Response, Compensation, and Liabilities Act (CERCLA) investigations, beginning with the Magnolia and Centennial investigation by KDHE in 1995. Subsequent investigations by KDHE, the U.S. Environmental Protection Agency (EPA), and the U.S. Department of Defense (DOD) have been conducted at the site.

Upon more specific review of the former Schilling Air Force Base sit e, the area containing the former Beechcraft facility in question is within the site boundaries of Operable Unit 1 of the Former Schilling Air Force Base DOD site. A review of the Remedial Investigation (RI) Report for Operable Unit 1 conducted for this ISS indicates that trichloroethylene (TCE) is present both up-and downgradient of the former Beechcraft buildings above Maximum Contaminant Levels, and from the RI no jump in TCE concentrations is present at or downgradient of the former Beechcraft buildings.

Since the former Beech-Salina site is within the Operable Unit 1 por tion of the Former Schilling Air Force Base site, and is being addressed by the Salina Public Entities, no further KDHE assessment is recommended.

Site ID:	2915
Has Env Use Control:	No
Project code:	C508572964
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.793734 / -97.636824
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	31-50 feet
Depth To Bedrock:	31-50 feet
Aquifer Yield:	11-50 gpm
GW Flow Direction:	E
Acres Affected:	<5 acres
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported

FORMER BEECH - SALINA (Continued) **S115488782**

Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING AFB OU1
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Transfer Within Bureau
Activity Status:	Completed
Activity Start Date:	Not reported
Activity End Date:	11/02/2016
Narrative:	The Former Beech-Salina site is located at the intersection of Scanlan Avenue and Derussy Road at the Salina Municipal Airport. The site is currently used by Salina Area Technical School which has an address of 2562 Centennial Road, #A, Salina, KS 67401. The legal description of the site is Section 34, Township 14 South, Range 3 West. Hawker-Beechcraft filed for bankruptcy in 2012. As part of the bankruptcy proceedings, its former Salina facility was included. Beech began ceasing operations in Salina in 2009. A review of Kansas Department of Health and Environment (KDHE) site files indicated several Resource Conservation and Recovery Act (RCRA), air, and wastewater-pretreatment files for the Former Beech-Salina area. The Salina Municipal Airport has been an industrial park since the closure of the Schilling Air Force Base and reversion of the buildings and land to the Salina Airport Authority in 1965. Hakwer-Beechcraft began operating at Salina as Beechcraft in 1966. The site also has an extensive history of previous Comprehensive Env ironmental Response, Compensation, and Liabilities Act (CERCLA) investigations, beginning with the Magnolia and Centennial investigation by KDHE in 1995. Subsequent investigations by KDHE, the U.S. Environmental Protection Agency (EPA), and the U.S. Department of Defense (DOD) have been conducted at the site. Upon more specific review of the former Schilling Air Force Base sit e, the area containing the former Beechcraft facility in question is within the site boundaries of Operable Unit 1 of the Former Schilling Air Force Base DOD site. A review of the Remedial Investigation (RI) Report for Operable Unit 1 conducted for this ISS indicates that trichloroethylene (TCE) is present both up-and downgradient of the former Beechcraft buildings above Maximum Contaminant Levels, and from the RI no jump in TCE concentrations is present at or downgradient of the former Beechcraft buildings. Since the former Beech-Salina site is within the Operable Unit 1 por tion of the Former Schilling Air Force Base site, and is being addressed by the Salina Public Entities, no further KDHE assessment is recommended.
Site ID:	2915
Has Env Use Control:	No
Project code:	C508572964
PM Name:	RICHARDS, A.

FORMER BEECH - SALINA (Continued) **S115488782**

Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.793734 / -97.636824
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	31-50 feet
Depth To Bedrock:	31-50 feet
Aquifer Yield:	11-50 gpm
GW Flow Direction:	E
Acres Affected:	<5 acres
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING AFB OU1
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Transfer Within Bureau
Activity Status:	Completed
Activity Start Date:	Not reported
Activity End Date:	11/02/2016
Narrative:	The Former Beech-Salina site is located at the intersection of Scanlan Avenue and Derussy Road at the Salina Municipal Airport. The site is currently used by Salina Area Technical School which has an address of 2562 Centennial Road, #A, Salina, KS 67401. The legal description of the site is Section 34, Township 14 South, Range 3 West. Hawker-Beechcraft filed for bankruptcy in 2012. As part of the bankruptcy proceedings, its former Salina facility was included. Beech began ceasing operations in Salina in 2009. A review of Kansas Department of Health and Environment (KDHE) site files indicated several Resource Conservation and Recovery Act (RCRA), air, and wastewater-pretreatment files for the Former Beech-Salina area. The Salina Municipal Airport has been an industrial park since the closure of the Schilling Air Force Base and reversion of the buildings and land to the Salina Airport Authority in 1965. Hakwer-Beechcraft began operating at Salina as Beechcraft in 1966. The site also has an extensive history of previous Comprehensive Env

FORMER BEECH - SALINA (Continued) **S115488782**

ironmental Response, Compensation, and Liabilities Act (CERCLA) investigations, beginning with the Magnolia and Centennial investigation by KDHE in 1995. Subsequent investigations by KDHE, the U.S. Environmental Protection Agency (EPA), and the U.S. Department of Defense (DOD) have been conducted at the site.

Upon more specific review of the former Schilling Air Force Base sit e, the area containing the former Beechcraft facility in question is within the site boundaries of Operable Unit 1 of the Former Schilling Air Force Base DOD site. A review of the Remedial Investigation (RI) Report for Operable Unit 1 conducted for this ISS indicates that trichloroethylene (TCE) is present both up-and downgradient of the former Beechcraft buildings above Maximum Contaminant Levels, and from the RI no jump in TCE concentrations is present at or downgradient of the former Beechcraft buildings.

Since the former Beech-Salina site is within the Operable Unit 1 por tion of the Former Schilling Air Force Base site, and is being addressed by the Salina Public Entities, no further KDHE assessment is recommended.

---

91 **FAA, SALINA** **KS LUST** **S101836860**
NW **SALINA VORTAC** **N/A**
1/8-1/4 **SALINA, KS 67401**
0.242 mi.
1279 ft.

Relative: **Lower**

Actual: **1253 ft.**

LUST:

Facility ID:	25323
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	10/13/1989
Project Number:	U5-085-00237
Project Name:	FAA, Salina VORTAC
Legal Desc Section:	35
Legal Desc Township:	13S
Legal Desc Range:	03W
Discover Date:	10/13/1989
substrels:	none
Initial Ranking:	Not reported
Current Ranking:	Not reported
Facility Contact:	Gary Grimsley
Facility Phone Number:	Not reported
Facility Owner Identification number:	23364
Facility Owner:	FAA
Owner Contact Person:	Not reported
Owner Address:	Wichita
Owner City:	Not reported
Owner State:	KS
Owner Zip Code:	67200
Owner Phone number:	316-946-4480
Contractor license number:	Not reported
Contractor phone number:	Not reported
Leak duration (if known):	0
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Not reported
Reported By:	Erik Peterson
Reported by persons phone number:	785-827-9639

FAA, SALINA (Continued) **S101836860**

Reported by person address:	2501-d Market Pl., Salina
Ground water Impacted (yes/no):	Not reported
Static groundwater level:	Not reported
Groundwater flow direction:	Not reported
District staff names:	Erik Peterson
Assessment of release:	1-515 gal steel gas ust removed. no contam encountered in excavation. site closed.
Contaimination assessement:	Not reported
Extent of contamination impact:	none
Updated information:	Not reported
Invoice initiated:	19901
Invoice on going:	Not reported
Invoice completetd:	19901
Release confirmed:	Not reported
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	Not reported
Cost recovery initiated by:	Not reported
Cost recovery completed:	Not reported
Cost recovery completed by:	Not reported
Appplication to trust fund:	Not reported

---

92 **LOVE BOX CO INC** **RCRA-CESQG** **1000470988**
SSE **3330 CENTENNIAL** **FINDS** **KSD984988501**
1/8-1/4 **SALINA, KS 67401** **ECHO**
0.248 mi.
1312 ft.

Relative: **Lower**
Actual: **1252 ft.**

RCRA-CESQG:

Date form received by agency:	01/19/1999
Facility name:	LOVE BOX CO INC
Facility address:	3330 CENTENNIAL SALINA, KS 67401
EPA ID:	KSD984988501
Mailing address:	CENTENNIAL SALINA, KS 67401
Contact:	STACEY GREEN
Contact address:	3330 CENTENNIAL SALINA, KS 67401
Contact country:	US
Contact telephone:	785-823-7354
Contact email:	Not reported
EPA Region:	07
Land type:	Private
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

LOVE BOX CO INC (Continued) **1000470988**

the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	ROBERT D LOVE
Owner/operator address:	700 E 37TH ST N WICHITA, KS 67219
Owner/operator country:	Not reported
Owner/operator telephone:	316-838-0851
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Hazardous Waste Summary:

. Waste code:	D001
. Waste name:	IGNITABLE WASTE
. Waste code:	D008
. Waste name:	LEAD
. Waste code:	D018
. Waste name:	BENZENE
. Waste code:	D039
. Waste name:	TETRACHLOROETHYLENE
. Waste code:	D040
. Waste name:	TRICHLORETHYLENE

Facility Has Received Notices of Violations:

Regulation violated:	FR - 40cfr 279.22c
Area of violation:	Used Oil - Burners of Off-Spec for Energy Recovery
Date violation determined:	12/01/1998

LOVE BOX CO INC (Continued) **1000470988**

Date achieved compliance: 12/01/1998
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/01/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 12/01/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Used Oil - Burners of Off-Spec for Energy Recovery
Date achieved compliance: 12/01/1998
Evaluation lead agency: State

FINDS:

Registry ID: 110003189665

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000470988
Registry ID: 110003189665
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003189665

93
North
1/4-1/2
0.304 mi.
1606 ft.

ADM MILLING CO **KS LUST U000873725**
2806 HEIN MUNCIPAL AIRPORT **KS UST N/A**
SALINA, KS 67401

Relative:
Lower

Actual:
1251 ft.

LUST:
Facility ID: 27527
Site Status: **Monitor**
Release Date: Not reported
Initial Report Date: 01/28/1992
Project Number: U5-085-00635
Project Name: SAA, Adm Milling
Legal Desc Section: 34
Legal Desc Township: 14S
Legal Desc Range: 03W
Discover Date: 01/27/1992
substrels: diesel

ADM MILLING CO (Continued) **U000873725**

Initial Ranking:	37
Current Ranking:	37.00000
Facility Contact:	Donald C Kneubuhl
Facility Phone Number:	785-827-3914
Facility Owner Identification number:	27527
Facility Owner:	Adm Milling Co
Owner Contact Person:	Not reported
Owner Address:	316 N Santa Fe, Salina
Owner City:	Not reported
Owner State:	KS
Owner Zip Code:	67401
Owner Phone number:	785-825-1541
Contractor license number:	Not reported
Contractor phone number:	785-479-2106
Leak duration (if known):	Ukwn
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Tank
Reported By:	Howard Debauche
Reported by persons phone number:	Not reported
Reported by person address:	Ncdo
Ground water Impacted (yes/no):	0-15’ brown & grayish rown silts & sands (mixed), >15’ fine to medium sand. gw depth = 15’.
Static groundwater level:	Not reported
Groundwater flow direction:	Not reported
District staff names:	Howard Debauche
Assessment of release:	2-20000, 2-10000 gal diesel usts & lines removed. area under tanks contam. gw encountered directly under tanks. evidence of fluctuating water table. 2/21/92: have removed fill & aerated. also pumping water & aerating on runway. still active.
Contaimination assessement:	yes.
Extent of contamination impact:	1/29/92: sampled 3 test excavations ~50’ from tank excv to the north ne & east. local gw flow is suspected to be to the ne. contamination appears to be restricted to tank excv area. sump to be installed. will continue to sample & pump water.
Updated information:	Not reported
Invoice initiated:	19922
Invoice on going:	Not reported
Invoice completetd:	19922
Release confirmed:	19922
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	19922
Cost recovery initiated by:	Responsible Party
Cost recovery completed:	Not reported
Cost recovery completed by:	Not reported
Appplication to trust fund:	Not reported

UST:

Facility ID:	27527
Facility 911 Address:	2806 HEIN
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1992-01-15 00:00:00
Capacity (Gals):	20000

ADM MILLING CO (Continued) **U000873725**

Tank Internal Protection:	None
24 Hour Phone Num:	785-825-6550
Tank External Protection:	Painted
Piping:	Bare Steel, Other
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-825-6550
Tank Empty:	Not reported
Contact Name:	James L Tullis
Contact Title:	Chief Pilot
Owner ID:	27527
Owner Type:	Private Or Corp.
Owner Name:	ADM MILLING COMPANY
Owner Address:	3140 ARNOLD
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-825-1541
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1981
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	011992
Material of Construction:	Steel
Petroleum Substance:	Diesel
Owner Replacement Name:	James L Tullis
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.77954
Longitude:	-97.64000

Facility ID:	27527
Facility 911 Address:	2806 HEIN
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1992-01-15 00:00:00
Capacity (Gals):	20000
Tank Internal Protection:	None
24 Hour Phone Num:	785-825-6550
Tank External Protection:	Painted
Piping:	Bare Steel, Other
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-825-6550
Tank Empty:	Not reported
Contact Name:	James L Tullis
Contact Title:	Chief Pilot
Owner ID:	27527
Owner Type:	Private Or Corp.

ADM MILLING CO (Continued) **U000873725**

Owner Name:	ADM MILLING COMPANY
Owner Address:	3140 ARNOLD
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-825-1541
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	002
Tank Status:	Permanently Out Of Use
Installation Year:	1981
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	011992
Material of Construction:	Steel
Petroleum Substance:	Diesel
Owner Replacement Name:	James L Tullis
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.77954
Longitude:	-97.64000

Facility ID:	27527
Facility 911 Address:	2806 HEIN
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1992-01-15 00:00:00
Capacity (Gals):	10000
Tank Internal Protection:	None
24 Hour Phone Num:	785-825-6550
Tank External Protection:	Painted
Piping:	Bare Steel
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-825-6550
Tank Empty:	Not reported
Contact Name:	James L Tullis
Contact Title:	Chief Pilot
Owner ID:	27527
Owner Type:	Private Or Corp.
Owner Name:	ADM MILLING COMPANY
Owner Address:	3140 ARNOLD
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-825-1541
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	003
Tank Status:	Permanently Out Of Use
Installation Year:	1981

ADM MILLING CO (Continued) **U000873725**

Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	011992
Material of Construction:	Steel
Petroleum Substance:	Diesel
Owner Replacement Name:	James L Tullis
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.77954
Longitude:	-97.64000
Facility ID:	27527
Facility 911 Address:	2806 HEIN
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1992-01-15 00:00:00
Capacity (Gals):	10000
Tank Internal Protection:	None
24 Hour Phone Num:	785-825-6550
Tank External Protection:	Painted
Piping:	Bare Steel, Other
Facility Location Method:	Topozone
Facility Feature:	Facility Center
Facility Phone:	785-825-6550
Tank Empty:	Not reported
Contact Name:	James L Tullis
Contact Title:	Chief Pilot
Owner ID:	27527
Owner Type:	Private Or Corp.
Owner Name:	ADM MILLING COMPANY
Owner Address:	3140 ARNOLD
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	SALINE
Owner Phone:	785-825-1541
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	004
Tank Status:	Permanently Out Of Use
Installation Year:	1981
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	011992
Material of Construction:	Steel
Petroleum Substance:	Diesel
Owner Replacement Name:	James L Tullis
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.77954

ADM MILLING CO (Continued) **U000873725**

Longitude: -97.64000

94
East
1/4-1/2
0.351 mi.
1851 ft.

SCHILLING FAMILY HOUSING
SCHILLING ROAD
SALINA, KS 67401

KS SHWS **1007469827**
FINDS **N/A**

Relative:
Lower

Actual:
1244 ft.

SHWS:

Site ID:	1623
Has Env Use Control:	No
Project code:	C508571291
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.78326148 / -97.62504861
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	01/01/1989
Depth To GW:	11-20 feet
Depth To Bedrock:	31-50 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	E-NE
Acres Affected:	26-500 acres
Waste Present:	No
Product Present:	No
Program:	FUDS (Formerly Used Defense Sites)
Lead Agency:	BER - Remedial
Contaminants:	Other (see Site Narrative)
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Residential
Private well:	Domestic
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Initial Site Screening
Activity Status:	Completed
Activity Start Date:	01/01/2003
Activity End Date:	04/30/2003
Narrative:	This site was originally part of the former Schilling Air Force Base (SAFB). Housing for base personnel was constructed on this site from 1958 to 1961. In January 1968 the Air Force designated this as a separate site. The site was excessed in 1977 and sold in 1979 to private owners who subdivided the site and resold it to numerous

SCHILLING FAMILY HOUSING (Continued) **1007469827**

individuals.
USACE performed a site visit on January 12, 1989, and did not identi fy any hazards or recommend any environmental restoration projects.
KDHE completed an Initial Site Screening report in April 2003, and c oncluded that no investigation or remedial action of the site appeared necessary.
Currently available data indicates that contamination migrating from Operable Unit 2 at SAFB extends beneath part of the Schilling Family Housing site. This contamination will be addressed under the environmental investigation and restoration activities at SAFB.

Site ID:	1623
Has Env Use Control:	No
Project code:	C508571291
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.78326148 / -97.62504861
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	01/01/1989
Depth To GW:	11-20 feet
Depth To Bedrock:	31-50 feet
Aquifer Yield:	0-10 gpm
GW Flow Direction:	E-NE
Acres Affected:	26-500 acres
Waste Present:	No
Product Present:	No
Program:	FUDS (Formerly Used Defense Sites)
Lead Agency:	BER - Remedial
Contaminants:	Other (see Site Narrative)
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Residential
Private well:	Domestic
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Initial Site Screening
Activity Status:	Completed
Activity Start Date:	01/01/2003
Activity End Date:	04/30/2003

SCHILLING FAMILY HOUSING (Continued) **1007469827**

Narrative: This site was originally part of the former Schilling Air Force Base (SAFB). Housing for base personnel was constructed on this site from 1958 to 1961. In January 1968 the Air Force designated this as a separate site. The site was excessed in 1977 and sold in 1979 to private owners who subdivided the site and resold it to numerous individuals.
USACE performed a site visit on January 12, 1989, and did not identi fy any hazards or recommend any environmental restoration projects.
KDHE completed an Initial Site Screening report in April 2003, and c oncluded that no investigation or remedial action of the site appeared necessary.
Currently available data indicates that contamination migrating from Operable Unit 2 at SAFB extends beneath part of the Schilling Family Housing site. This contamination will be addressed under the environmental investigation and restoration activities at SAFB.

FINDS:

Registry ID: 110017449983

Environmental Interest/Information System
KS-FP (Kansas - Facility Profiler) is a geographically-based data warehouse site that presents information about facilities and locations of interest to the KDHE. This site has in excess of twenty environmental interest which contains information on closed facilities, completed cleanups, and past operations as well as data on current operations and activities.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

95 West 1/4-1/2 0.358 mi. 1892 ft.

FSLN RCAG
SALINA MUNICIPAL AIRPORT
SALINA, KS 67401

KS LUST **U000872706**
KS UST **N/A**
KS AST

Relative: Higher

Actual: 1281 ft.

LUST:

Facility ID:	25322
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	09/09/1993
Project Number:	U5-085-00827
Project Name:	FAA, SLN RCAG
Legal Desc Section:	33
Legal Desc Township:	14S
Legal Desc Range:	03W
Discover Date:	Not reported
substrels:	Not reported
Initial Ranking:	Not reported
Current Ranking:	Not reported
Facility Contact:	Robert Eggert
Facility Phone Number:	316-941-1286
Facility Owner Identification number:	23364

FSLN RCAG (Continued) **U000872706**

Facility Owner:	Federal Aviation Administratio
Owner Contact Person:	Robert Eggert
Owner Address:	1801 Airport Rd Rm 105
Owner City:	Wichita
Owner State:	KS
Owner Zip Code:	67209
Owner Phone number:	316-941-1286
Contractor license number:	C0142
Contractor phone number:	913-342-1554
Leak duration (if known):	Not reported
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Not reported
Reported By:	Howard Debauche
Reported by persons phone number:	785-827-9639
Reported by person address:	Not reported
Ground water Impacted (yes/no):	The area consists primarily of brown sandy clay
Static groundwater level:	0
Groundwater flow direction:	Not reported
District staff names:	Howard Debauche
Assessment of release:	1-underground storage tank was removed. There was no staining nor odor in or around the excavation A sample taken from the bottom of the hole next to the concrete pad showed no evidence of contamination. KDHE considers this site to be in a closed statu
Contaimination assessement:	Yes
Extent of contamination impact:	None suspected.
Updated information:	Not reported
Invoice initiated:	19934
Invoice on going:	Not reported
Invoice completetd:	19934
Release confirmed:	Not reported
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	Not reported
Cost recovery initiated by:	Not reported
Cost recovery completed:	Not reported
Cost recovery completed by:	Not reported
Appplication to trust fund:	Not reported

UST:

Facility ID:	25322
Facility 911 Address:	33-14-03W
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1993-09-15 00:00:00
Capacity (Gals):	1000
Tank Internal Protection:	None
24 Hour Phone Num:	620-662-4851
Tank External Protection:	Painted
Piping:	Other
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	620-662-4851
Tank Empty:	Not reported
Contact Name:	DAVID BRONKE

FSLN RCAG (Continued) **U000872706**

Contact Title:	SSC MANAGER
Owner ID:	23364
Owner Type:	Current
Owner Name:	FAA-%NICHOLE KOELLING
Owner Address:	280 S. ROGERS RD., STE. 2
Owner City:	OLATHE
Owner State:	KS
Owner Zip:	66062
Owner County:	JOHNSON
Owner Phone:	913-254-8610
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001
Tank Status:	Permanently Out Of Use
Installation Year:	1955
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	091993
Material of Construction:	Steel
Petroleum Substance:	Diesel
Owner Replacement Name:	CHRISTOPHER HOGUNIN
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Not reported
Principal CERCLA Substance/Chem Abstract Service Num:	Not reported
Latitude:	38.78642
Longitude:	-97.65041

AST:

Facility ID:	25322
Facility 911 Address:	33-14-03W
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	Not reported
Capacity (Gals):	500
Tank Internal Protection:	Not reported
24 Hour Phone Num:	620-662-4851
Tank External Protection:	Not reported
Piping:	Not reported
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	620-662-4851
Tank Empty:	Not reported
Contact Name:	DAVID BRONKE
Contact Title:	SSC MANAGER
Owner ID:	23364
Owner Type:	Current
Owner Name:	FAA-%NICHOLE KOELLING
Owner Address:	280 S. ROGERS RD., STE. 2
Owner City:	OLATHE
Owner State:	KS
Owner Zip:	66062
Owner County:	JOHNSON
Owner Phone:	913-254-8610
QTY Remaining in Tank:	0

FSLN RCAG (Continued) **U000872706**

Facility District:	NC
Tank ID:	001
Tank Status:	Current In Use
Installation Year:	1969
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Not reported
Petroleum Substance:	Diesel Dyed Off-Road
Owner Replacement Name:	CHRISTOPHER HOGUNIN
NonPetroleum Substance:	Not reported
Owner Replacement Title:	CONTACT PERSON
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	68476-34-6
Latitude:	38.78642
Longitude:	-97.65041

96
NNE
1/4-1/2
0.382 mi.
2016 ft.

SMOKY HILL INC
1615 W MAGNOLIA
SALINA, KS 67401

KS LUST **U000870923**
KS UST **N/A**
KS AST

Relative:
Lower

Actual:
1241 ft.

LUST:

Facility ID:	04845
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	11/17/1989
Project Number:	U5-085-00401
Project Name:	Smoky Hill
Legal Desc Section:	35
Legal Desc Township:	14S
Legal Desc Range:	03W
Discover Date:	11/17/1989
substrels:	gasoline
Initial Ranking:	80
Current Ranking:	80.00000
Facility Contact:	Ed Summelink
Facility Phone Number:	785-825-0810
Facility Owner Identification number:	04845
Facility Owner:	Not reported
Owner Contact Person:	Not reported
Owner Address:	Not reported
Owner City:	Not reported
Owner State:	Not reported
Owner Zip Code:	Not reported
Owner Phone number:	Not reported
Contractor license number:	Not reported
Contractor phone number:	785-825-0810
Leak duration (if known):	Not reported
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Not reported
Reported By:	Erik Peterson
Reported by persons phone number:	785-827-9639
Reported by person address:	2501-d Market Pl, Salina, Ks
Ground water Impacted (yes/no):	ground water encountered at 10 and 12 feet below grade level. it is

SMOKY HILL INC (Continued) **U000870923**

	assumed this is a shallow perched water table.
Static groundwater level:	Not reported
Groundwater flow direction:	Not reported
District staff names:	Erik Peterson
Assessment of release:	two 16,000 gallon steel usts were removed from a location between the two large shop buildings on site. hydrocarbon contamination was encountered in the hole during the ust removal process. at kdhes request, the hole was excavated downward until wate
Contaimination assessement:	yes, as the entire ust petroleum system was dismantled. usts and lines were removed.
Extent of contamination impact:	through the installation of three monitor wells located the grondwater contamination appears to be localized in the immediate vicinity of the removed usts.
Updated information:	Site closed by district staff in Nov. 2005.
Invoice initiated:	19904
Invoice on going:	Not reported
Invoice completetd:	19904
Release confirmed:	19904
Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	19904
Cost recovery initiated by:	Responsible Party
Cost recovery completed:	20061
Cost recovery completed by:	Responsible Party
Appplication to trust fund:	Not reported

UST:

Facility ID:	04845
Facility 911 Address:	1615 W MAGNOLIA RD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1989-11-15 00:00:00
Capacity (Gals):	17000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-825-1224
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-825-1224
Tank Empty:	Not reported
Contact Name:	DOUG BOLEN
Contact Title:	Not reported
Owner ID:	04845
Owner Type:	Private Or Corp.
Owner Name:	SMOKY HILL INC
Owner Address:	1615 W. MAGNOLIA RD
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	Not reported
Owner Phone:	785-825-1224
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	001

SMOKY HILL INC (Continued) **U000870923**

Tank Status:	Permanently Out Of Use
Installation Year:	1944
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	111989
Material of Construction:	Steel
Petroleum Substance:	Gas (Incl Alcohol)
Owner Replacement Name:	DOUG BOLEN
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	8006-61-9
Latitude:	38.79734
Longitude:	-97.63230
Facility ID:	04845
Facility 911 Address:	1615 W MAGNOLIA RD
Facility 911 City:	SALINA
Facility 911 State:	KS
Facility 911 Zip:	67401
Date Removed:	1989-11-15 00:00:00
Capacity (Gals):	17000
Tank Internal Protection:	Unknown
24 Hour Phone Num:	785-825-1224
Tank External Protection:	Cat Prot
Piping:	Cat Prot
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-825-1224
Tank Empty:	Not reported
Contact Name:	DOUG BOLEN
Contact Title:	Not reported
Owner ID:	04845
Owner Type:	Private Or Corp.
Owner Name:	SMOKY HILL INC
Owner Address:	1615 W. MAGNOLIA RD
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	Not reported
Owner Phone:	785-825-1224
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	002
Tank Status:	Permanently Out Of Use
Installation Year:	1944
Last Permit Printed:	Not reported
Current Permit Printed:	Not reported
Facility Datum:	WGS84
Out of service Mo/Yr:	111989
Material of Construction:	Steel
Petroleum Substance:	Gas (Incl Alcohol)
Owner Replacement Name:	DOUG BOLEN
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute

SMOKY HILL INC (Continued) **U000870923**

Principal CERCLA Substance/Chem Abstract Service Num: 8006-61-9
Latitude: 38.79734
Longitude: -97.63230

AST:
Facility ID: 04845
Facility 911 Address: 1615 W MAGNOLIA RD
Facility 911 City: SALINA
Facility 911 State: KS
Facility 911 Zip: 67401
Date Removed: Not reported
Capacity (Gals): 10000
Tank Internal Protection: Not reported
24 Hour Phone Num: 785-825-1224
Tank External Protection: Not reported
Piping: Bare Steel
Facility Location Method: Garmin GPS III Plus
Facility Feature: Facility Center
Facility Phone: 785-825-1224
Tank Empty: Not reported
Contact Name: DOUG BOLEN
Contact Title: Not reported
Owner ID: 04845
Owner Type: Private Or Corp.
Owner Name: SMOKY HILL INC
Owner Address: 1615 W. MAGNOLIA RD
Owner City: SALINA
Owner State: KS
Owner Zip: 67401
Owner County: Not reported
Owner Phone: 785-825-1224
QTY Remaining in Tank: Not reported
Facility District: NC
Tank ID: 001
Tank Status: Current In Use
Installation Year: 1900
Last Permit Printed: 2017-06-12 00:00:00
Current Permit Printed: 2018-06-11 00:00:00
Facility Datum: WGS84
Out of service Mo/Yr: Not reported
Material of Construction: Not reported
Petroleum Substance: Gas Unleaded Regular
Owner Replacement Name: DOUG BOLEN
NonPetroleum Substance: Not reported
Owner Replacement Title: Not reported
Hazards: Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num: 8006-61-9
Latitude: 38.79734
Longitude: -97.63230

Facility ID: 04845
Facility 911 Address: 1615 W MAGNOLIA RD
Facility 911 City: SALINA
Facility 911 State: KS
Facility 911 Zip: 67401
Date Removed: Not reported
Capacity (Gals): 10000

SMOKY HILL INC (Continued) **U000870923**

Tank Internal Protection:	Not reported
24 Hour Phone Num:	785-825-1224
Tank External Protection:	Not reported
Piping:	Bare Steel
Facility Location Method:	Garmin GPS III Plus
Facility Feature:	Facility Center
Facility Phone:	785-825-1224
Tank Empty:	Not reported
Contact Name:	DOUG BOLEN
Contact Title:	Not reported
Owner ID:	04845
Owner Type:	Private Or Corp.
Owner Name:	SMOKY HILL INC
Owner Address:	1615 W. MAGNOLIA RD
Owner City:	SALINA
Owner State:	KS
Owner Zip:	67401
Owner County:	Not reported
Owner Phone:	785-825-1224
QTY Remaining in Tank:	Not reported
Facility District:	NC
Tank ID:	002
Tank Status:	Current In Use
Installation Year:	2004
Last Permit Printed:	2017-06-12 00:00:00
Current Permit Printed:	2018-06-11 00:00:00
Facility Datum:	WGS84
Out of service Mo/Yr:	Not reported
Material of Construction:	Not reported
Petroleum Substance:	Diesel No. 2
Owner Replacement Name:	DOUG BOLEN
NonPetroleum Substance:	Not reported
Owner Replacement Title:	Not reported
Hazards:	Fire, Chronic, Acute
Principal CERCLA Substance/Chem Abstract Service Num:	68476-34-6
Latitude:	38.79734
Longitude:	-97.63230

---

97 **SALINA AIRPORT AUTHORITY IX** **KS SHWS** **S118117469**
South **NW OF INTERSECTION SCANLAN AVE AND WALL ST** **KS BROWNFIELDS** **N/A**
1/4-1/2 **SALINA, KS 67401**
0.413 mi.
2181 ft.

Relative:
Higher

Actual:
1266 ft.

SHWS:

Site ID:	3166
Has Env Use Control:	No
Project code:	C508573215
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.77542 / -97.63748
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	Not reported

SALINA AIRPORT AUTHORITY IX (Continued) **S118117469**

Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	03/30/2015
Activity End Date:	05/26/2015
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Phase I Brownfields Targeted Assessment (BTA) at the northwest corner of Scanlan Ave. and Wall St. in Salina, Kansas. The BTA was completed for the Salina Airport Authority, who is the current owner and intends to sell or lease the vacant property to a prospective purchaser. Based on the Phase I report, ?Recognized Environmental Conditions? (RECs) were identified in connection with the BTA property as potential migration of hazardous substances onto the BTA site from the Schilling Air Force Base site (C5-085-03013), which encompasses the Salina Municipal Airport and adjoining areas. The Schilling site is currently enrolled in the KDHE State Cooperative Program due to the known trichloroethylene (TCE) groundwater plumes. These TCE plumes are currently being monitored and remediated through the State Cooperative Program; therefore no additional investigation is required at this time through the Brownfields Program and the property is cleared for redevelopment. Notwithstanding, there is a potential for vapor intrusion at the BTA site due to the known impacts to groundwater and best management practices should be carried out during future construction at the property.
Site ID:	3166
Has Env Use Control:	No
Project code:	C508573215
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO

SALINA AIRPORT AUTHORITY IX (Continued) **S118117469**

Lat/Long:	38.77542 / -97.63748
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	03/30/2015
Activity End Date:	05/26/2015
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Phase I Brownfields Targeted Assessment (BTA) at the northwest corner of Scanlan Ave. and Wall St. in Salina, Kansas. The BTA was completed for the Salina Airport Authority, who is the current owner and intends to sell or lease the vacant property to a prospective purchaser. Based on the Phase I report, ?Recognized Environmental Conditions? (RECs) were identified in connection with the BTA property as potential migration of hazardous substances onto the BTA site from the Schilling Air Force Base site (C5-085-03013), which encompasses the Salina Municipal Airport and adjoining areas. The Schilling site is currently enrolled in the KDHE State Cooperative Program due to the known trichloroethylene (TCE) groundwater plumes. These TCE plumes are currently being monitored and remediated through the State Cooperative Program; therefore no additional investigation is required at this time through the Brownfields Program and the property is cleared for redevelopment. Notwithstanding, there is a potential for vapor intrusion at the BTA site due to the known impacts to groundwater and best management practices should be carried out during future construction at the property.

SALINA AIRPORT AUTHORITY IX (Continued) **S118117469**

BROWNFIELDS:
Site ID: 3166
Project code: C508573215
PM Name: BER - REDEVELOPMENT
Site Status: Resolved
Lat/Long: 38.77542 / -97.63748
Program: Brownfields

W98 **SALINA AIRPORT AUTHORITY X** **US BROWNFIELDS** **1024008845**
NNE **2461 CENTENNIAL RD** **FINDS** **N/A**
1/4-1/2 **SALINA, KS 67401**
0.418 mi.
2206 ft. **Site 1 of 2 in cluster W**

Relative:
Lower

Actual:
1244 ft.

US BROWNFIELDS:

Name:	SALINA AIRPORT AUTHORITY X
Address:	2461 CENTENNIAL RD
City,State,Zip:	SALINA, KS 67401
Recipient Name:	Kansas Department of Health and Environment
Grant Type:	Section 128(a) State/Tribal
Property Number:	Not reported
Parcel size:	13.28
Latitude:	38.797242
Longitude:	-97.6343863
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	n
Datum:	North American Datum of 1983
Acres Property ID:	187382
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1800
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	98726205
Start Date:	03/30/2015 00:00:00
Ownership Entity:	Private
Completion Date:	05/12/2015 00:00:00
Current Owner:	Salina Airport Authority
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	N
Photo Available:	Y

SALINA AIRPORT AUTHORITY X (Continued) **1024008845**

Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	04/01/2015 00:00:00
State/tribal program ID:	C5-085-73216
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Y
Other contams found description:	Nitrate
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	13.28
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	13.28
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported

SALINA AIRPORT AUTHORITY X (Continued) **1024008845**

Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	The property was owned by private individuals until the U.S. Government bought the property in 1942, then sold it again in 1967 to the Salina Airport Authority. The property was used for agriculture until about 1954, when a structure was built and three large storage tanks were placed on site, converting the property to industrial use.
Below Poverty Number:	25
Below Poverty Percent:	20.2%
Meidan Income:	270
Meidan Income Number:	52
Meidan Income Percent:	41.9%
Vacant Housing Number:	3
Vacant Housing Percent:	6.4%
Unemployed Number:	4
Unemployed Percent:	3.2%

Name:	SALINA AIRPORT AUTHORITY X
Address:	2461 CENTENNIAL RD
City,State,Zip:	SALINA, KS 67401
Recipient Name:	Kansas Department of Health and Environment
Grant Type:	Section 128(a) State/Tribal
Property Number:	Not reported
Parcel size:	13.28
Latitude:	38.797242
Longitude:	-97.6343863
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	n

SALINA AIRPORT AUTHORITY X (Continued) **1024008845**

Datum:	North American Datum of 1983
Acres Property ID:	187382
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1772
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	98726205
Start Date:	07/13/2015 00:00:00
Ownership Entity:	Private
Completion Date:	10/05/2015 00:00:00
Current Owner:	Salina Airport Authority
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	04/01/2015 00:00:00
State/tribal program ID:	C5-085-73216
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Y

SALINA AIRPORT AUTHORITY X (Continued) **1024008845**

Other contams found description:	Nitrate
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	13.28
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	13.28
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported

SALINA AIRPORT AUTHORITY X (Continued) **1024008845**

Past Use: Multistory	Not reported
Property Description:	The property was owned by private individuals until the U.S. Government bought the property in 1942, then sold it again in 1967 to the Salina Airport Authority. The property was used for agriculture until about 1954, when a structure was built and three large storage tanks were placed on site, converting the property to industrial use.
Below Poverty Number:	25
Below Poverty Percent:	20.2%
Meidan Income:	270
Meidan Income Number:	52
Meidan Income Percent:	41.9%
Vacant Housing Number:	3
Vacant Housing Percent:	6.4%
Unemployed Number:	4
Unemployed Percent:	3.2%

Name:	SALINA AIRPORT AUTHORITY X
Address:	2461 CENTENNIAL RD
City,State,Zip:	SALINA, KS 67401
Recipient Name:	Kansas Department of Health and Environment
Grant Type:	Section 128(a) State/Tribal
Property Number:	Not reported
Parcel size:	13.28
Latitude:	38.797242
Longitude:	-97.6343863
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	n
Datum:	North American Datum of 1983
Acres Property ID:	187382
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1800
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	98726204
Start Date:	03/30/2015 00:00:00
Ownership Entity:	Private
Completion Date:	05/26/2015 00:00:00
Current Owner:	Salina Airport Authority
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	N

SALINA AIRPORT AUTHORITY X (Continued) **1024008845**

Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	04/01/2015 00:00:00
State/tribal program ID:	C5-085-73216
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Y
Other contams found description:	Nitrate
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	13.28
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	13.28
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported

SALINA AIRPORT AUTHORITY X (Continued) **1024008845**

Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	The property was owned by private individuals until the U.S. Government bought the property in 1942, then sold it again in 1967 to the Salina Airport Authority. The property was used for agriculture until about 1954, when a structure was built and three large storage tanks were placed on site, converting the property to industrial use.
Below Poverty Number:	25
Below Poverty Percent:	20.2%
Meidan Income:	270
Meidan Income Number:	52
Meidan Income Percent:	41.9%
Vacant Housing Number:	3
Vacant Housing Percent:	6.4%
Unemployed Number:	4
Unemployed Percent:	3.2%

Name:	SALINA AIRPORT AUTHORITY X
Address:	2461 CENTENNIAL RD
City,State,Zip:	SALINA, KS 67401
Recipient Name:	Kansas Department of Health and Environment
Grant Type:	Section 128(a) State/Tribal
Property Number:	Not reported
Parcel size:	13.28
Latitude:	38.797242
Longitude:	-97.6343863
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station

SALINA AIRPORT AUTHORITY X (Continued) **1024008845**

Highlights:	n
Datum:	North American Datum of 1983
Acres Property ID:	187382
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	6303
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	0
Cooperative Agreement Number:	98726205
Start Date:	05/12/2015 00:00:00
Ownership Entity:	Private
Completion Date:	09/09/2015 00:00:00
Current Owner:	Salina Airport Authority
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	04/01/2015 00:00:00
State/tribal program ID:	C5-085-73216
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported

SALINA AIRPORT AUTHORITY X (Continued) **1024008845**

Other contaminants found:	Y
Other contams found description:	Nitrate
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	13.28
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	13.28
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported

SALINA AIRPORT AUTHORITY X (Continued) **1024008845**

Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	The property was owned by private individuals until the U.S. Government bought the property in 1942, then sold it again in 1967 to the Salina Airport Authority. The property was used for agriculture until about 1954, when a structure was built and three large storage tanks were placed on site, converting the property to industrial use.
Below Poverty Number:	25
Below Poverty Percent:	20.2%
Meidan Income:	270
Meidan Income Number:	52
Meidan Income Percent:	41.9%
Vacant Housing Number:	3
Vacant Housing Percent:	6.4%
Unemployed Number:	4
Unemployed Percent:	3.2%

FINDS:

Registry ID: 110070149008

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

W99 **SALINA AIRPORT AUTHORITY X** **KS SHWS** **S118117470**
NNE **2461 CENTENNIAL RD** **N/A**
1/4-1/2 **SALINA, KS 67401**
0.418 mi.
2206 ft. **Site 2 of 2 in cluster W**

Relative:
Lower

Actual:
1244 ft.

SHWS:

Site ID:	3167
Has Env Use Control:	No
Project code:	C508573216
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.79482 / -97.63339
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	Not reported
Waste Present:	No

SALINA AIRPORT AUTHORITY X (Continued) **S118117470**

Product Present:	No
Program:	Department of Defense
Lead Agency:	BER - Remedial
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	05/25/2015
Activity End Date:	10/05/2015
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Phase I BTA at 2461 Centennial Rd. in Salina, Kansas. The BTA was completed for the Salina Airport Authority (SAA), who is the current owner and intends to sell or lease the property to a prospective purchaser. Based on the Phase I report, ?Recognized Environmental Conditions? (RECs) were identified in connection with the BTA property as the: historical use of the BTA property for petroleum storage since the 1942; the adjacent active Schilling Air Force Base site (C5-085-03013) and the potential for trichloroethylene (TCE) plume migration onto the BTA site; and the southwest-adjoining SAA V site (C5-085-72817) which has TPH DRO and TCE in the groundwater above the KDHE RSK levels. The BTA property was owned by the U.S. government from 1942 to 1965, and three aboveground storage tanks (ASTs) were used for aviation fuel storage during this time. The SAA took ownership of the property in 1967, and the storage tanks were out of use from 1967 to 1985. In 1985, the property was used for fertilizer storage and this use continues today, although one of the ASTs was removed from the property in 2013. The Schilling Air Force Base site is currently enrolled in the KDHE State Cooperative Program for monitoring and remediation of the contaminant plumes including TCE; therefore, the TCE requires no additional investigation at this time through the Brownfields Program. The detections of TCE in groundwater at the SAA V site are likely re lated to the Schilling site, but the source of the TPH DRO detections in groundwater at SAA V is unknown. Because the TPH DRO was identified in the upgradient-west side of the SAA V site, it is likely that there is an off-site source to the west. In addition, the SAA V site is located upgradient from the BTA property and there is a potential for TPH DRO to migrate on to the BTA site. A Phase II BTA was recommended to assess the potential migration of TPH DRO identified at the SAA V site and also to assess if historical

SALINA AIRPORT AUTHORITY X (Continued) **S118117470**

petroleum storage at the property has impacted on-site soil and groundwater.
The Phase II BTA consisted of four soil borings and two groundwater borings. 10 soil and three groundwater samples (including QA/QC samples) were analyzed for TPH DRO, TPH GRO. The groundwater samples were also analyzed for
VOCs.
All subsurface soil samples detected TPH GRO at levels exceeding the KDHE Risk-Based Standards for Kansas (RSK) soil to groundwater level of 79.3 milligrams per kilogram (mg/kg) including: SB-1 (9 to 10 feet) at 1,930 mg/kg, SB-2 (5 to 6 feet) at 426 mg/kg, SB-3 (10 to 11 feet) at 435 mg/kg, and SB-4 (7 to 8 feet) at 270 mg/kg. TPH DRO was detected in all surface soil samples at concentrations ranging from 38 mg/kg to 236 mg/kg, but none exceeded the KDHE RSK residential level of 2,000 mg/kg. No other analyzed Contaminants of Concern (COCs) were detected in the soil samples above laboratory reporting limits. No analyzed COCs were detected in the groundwater sample collected from MW-2 above laboratory reporting
limits.
TPH GRO-impacted soil appears to exist at depth beginning from appr oximately 2 to 7 feet below ground surface (bgs) and ending at 13 to 16 ft bgs. Groundwater does not appear to be impacted from petroleum constituents based on the one groundwater sample collected. Based on the Phase II data, it is likely that a release has occurred on the property from the historical use for bulk petroleum storage. As the petroleum impacts are likely associated with the former Schilling Air Force Base facility and operations, any future activities determined necessary will be addressed as part of the Schilling Air Force Base Site (C5-085-03013).

Site ID:	3167
Has Env Use Control:	No
Project code:	C508573216
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.79482 / -97.63339
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	Department of Defense
Lead Agency:	BER - Remedial
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported

SALINA AIRPORT AUTHORITY X (Continued) **S118117470**

Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	05/25/2015
Activity End Date:	10/05/2015
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Phase I BTA at 2461 Centennial Rd. in Salina, Kansas. The BTA was completed for the Salina Airport Authority (SAA), who is the current owner and intends to sell or lease the property to a prospective purchaser. Based on the Phase I report, ?Recognized Environmental Conditions? (RECs) were identified in connection with the BTA property as the: historical use of the BTA property for petroleum storage since the 1942; the adjacent active Schilling Air Force Base site (C5-085-03013) and the potential for trichloroethylene (TCE) plume migration onto the BTA site; and the southwest-adjoining SAA V site (C5-085-72817) which has TPH DRO and TCE in the groundwater above the KDHE RSK levels. The BTA property was owned by the U.S. government from 1942 to 1965, and three aboveground storage tanks (ASTs) were used for aviation fuel storage during this time. The SAA took ownership of the property in 1967, and the storage tanks were out of use from 1967 to 1985. In 1985, the property was used for fertilizer storage and this use continues today, although one of the ASTs was removed from the property in 2013. The Schilling Air Force Base site is currently enrolled in the KDHE State Cooperative Program for monitoring and remediation of the contaminant plumes including TCE; therefore, the TCE requires no additional investigation at this time through the Brownfields Program. The detections of TCE in groundwater at the SAA V site are likely re lated to the Schilling site, but the source of the TPH DRO detections in groundwater at SAA V is unknown. Because the TPH DRO was identified in the upgradient-west side of the SAA V site, it is likely that there is an off-site source to the west. In addition, the SAA V site is located upgradient from the BTA property and there is a potential for TPH DRO to migrate on to the BTA site. A Phase II BTA was recommended to assess the potential migration of TPH DRO identified at the SAA V site and also to assess if historical petroleum storage at the property has impacted on-site soil and groundwater. The Phase II BTA consisted of four soil borings and two groundwater borings. 10 soil and three groundwater samples (including QA/QC samples) were analyzed for TPH DRO, TPH GRO. The groundwater samples were also analyzed for VOCs.

SALINA AIRPORT AUTHORITY X (Continued) **S118117470**

All subsurface soil samples detected TPH GRO at levels exceeding the KDHE Risk-Based Standards for Kansas (RSK) soil to groundwater level of 79.3 milligrams per kilogram (mg/kg) including: SB-1 (9 to 10 feet) at 1,930 mg/kg, SB-2 (5 to 6 feet) at 426 mg/kg, SB-3 (10 to 11 feet) at 435 mg/kg, and SB-4 (7 to 8 feet) at 270 mg/kg. TPH DRO was detected in all surface soil samples at concentrations ranging from 38 mg/kg to 236 mg/kg, but none exceeded the KDHE RSK residential level of 2,000 mg/kg. No other analyzed Contaminants of Concern (COCs) were detected in the soil samples above laboratory reporting limits. No analyzed COCs were detected in the groundwater sample collected from MW-2 above laboratory reporting limits.

TPH GRO-impacted soil appears to exist at depth beginning from appr oximately 2 to 7 feet below ground surface (bgs) and ending at 13 to 16 ft bgs. Groundwater does not appear to be impacted from petroleum constituents based on the one groundwater sample collected. Based on the Phase II data, it is likely that a release has occurred on the property from the historical use for bulk petroleum storage. As the petroleum impacts are likely associated with the former Schilling Air Force Base facility and operations, any future activities determined necessary will be addressed as part of the Schilling Air Force Base Site (C5-085-03013).

Site ID:	3167
Has Env Use Control:	No
Project code:	C508573216
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.79482 / -97.63339
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	Department of Defense
Lead Agency:	BER - Remedial
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported

SALINA AIRPORT AUTHORITY X (Continued) **S118117470**

Remed Soil: Not reported
Remed Water: Not reported
Remedir: Not reported
Alias: Not reported
Eucan Number: Not reported
Date: Not reported
Activity Type: Brownfields Targeted Assessment
Activity Status: Completed
Activity Start Date: 05/25/2015
Activity End Date: 10/05/2015
Narrative: The Kansas Department of Health and Environment (KDHE) conducted a Phase I BTA at 2461 Centennial Rd. in Salina, Kansas. The BTA was completed for the Salina Airport Authority (SAA), who is the current owner and intends to sell or lease the property to a prospective purchaser. Based on the Phase I report, ?Recognized Environmental Conditions? (RECs) were identified in connection with the BTA property as the: historical use of the BTA property for petroleum storage since the 1942; the adjacent active Schilling Air Force Base site (C5-085-03013) and the potential for trichloroethylene (TCE) plume migration onto the BTA site; and the southwest-adjoining SAA V site (C5-085-72817) which has TPH DRO and TCE in the groundwater above the KDHE RSK levels.

The BTA property was owned by the U.S. government from 1942 to 1965, and three aboveground storage tanks (ASTs) were used for aviation fuel storage during this time. The SAA took ownership of the property in 1967, and the storage tanks were out of use from 1967 to 1985. In 1985, the property was used for fertilizer storage and this use continues today, although one of the ASTs was removed from the property in 2013.

The Schilling Air Force Base site is currently enrolled in the KDHE State Cooperative Program for monitoring and remediation of the contaminant plumes including TCE; therefore, the TCE requires no additional investigation at this time through the Brownfields Program.

The detections of TCE in groundwater at the SAA V site are likely re lated to the Schilling site, but the source of the TPH DRO detections in groundwater at SAA V is unknown. Because the TPH DRO was identified in the upgradient-west side of the SAA V site, it is likely that there is an off-site source to the west. In addition, the SAA V site is located upgradient from the BTA property and there is a potential for TPH DRO to migrate on to the BTA site. A Phase II BTA was recommended to assess the potential migration of TPH DRO identified at the SAA V site and also to assess if historical petroleum storage at the property has impacted on-site soil and groundwater.

The Phase II BTA consisted of four soil borings and two groundwater borings. 10 soil and three groundwater samples (including QA/QC samples) were analyzed for TPH DRO, TPH GRO. The groundwater samples were also analyzed for
VOCs.

All subsurface soil samples detected TPH GRO at levels exceeding the KDHE Risk-Based Standards for Kansas (RSK) soil to groundwater level of 79.3 milligrams per kilogram (mg/kg) including: SB-1 (9 to 10 feet) at 1,930 mg/kg, SB-2 (5 to 6 feet) at 426 mg/kg, SB-3 (10 to 11 feet) at 435 mg/kg, and SB-4 (7 to 8 feet) at 270 mg/kg. TPH DRO was detected in all surface soil samples at concentrations ranging from 38 mg/kg to 236 mg/kg, but none exceeded the KDHE RSK residential

SALINA AIRPORT AUTHORITY X (Continued) **S118117470**

level of 2,000 mg/kg. No other analyzed Contaminants of Concern (COCs) were detected in the soil samples above laboratory reporting limits. No analyzed COCs were detected in the groundwater sample collected from MW-2 above laboratory reporting limits.

TPH GRO-impacted soil appears to exist at depth beginning from appr oximately 2 to 7 feet below ground surface (bgs) and ending at 13 to 16 ft bgs. Groundwater does not appear to be impacted from petroleum constituents based on the one groundwater sample collected. Based on the Phase II data, it is likely that a release has occurred on the property from the historical use for bulk petroleum storage. As the petroleum impacts are likely associated with the former Schilling Air Force Base facility and operations, any future activities determined necessary will be addressed as part of the Schilling Air Force Base Site (C5-085-03013).

Site ID:	3167
Has Env Use Control:	No
Project code:	C508573216
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.79482 / -97.63339
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	Department of Defense
Lead Agency:	BER - Remedial
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment

SALINA AIRPORT AUTHORITY X (Continued) **S118117470**

Activity Status: Completed
Activity Start Date: 05/25/2015
Activity End Date: 10/05/2015
Narrative: The Kansas Department of Health and Environment (KDHE) conducted a Phase I BTA at 2461 Centennial Rd. in Salina, Kansas. The BTA was completed for the Salina Airport Authority (SAA), who is the current owner and intends to sell or lease the property to a prospective purchaser. Based on the Phase I report, ?Recognized Environmental Conditions? (RECs) were identified in connection with the BTA property as the: historical use of the BTA property for petroleum storage since the 1942; the adjacent active Schilling Air Force Base site (C5-085-03013) and the potential for trichloroethylene (TCE) plume migration onto the BTA site; and the southwest-adjoining SAA V site (C5-085-72817) which has TPH DRO and TCE in the groundwater above the KDHE RSK levels.

The BTA property was owned by the U.S. government from 1942 to 1965, and three aboveground storage tanks (ASTs) were used for aviation fuel storage during this time. The SAA took ownership of the property in 1967, and the storage tanks were out of use from 1967 to 1985. In 1985, the property was used for fertilizer storage and this use continues today, although one of the ASTs was removed from the property in 2013.

The Schilling Air Force Base site is currently enrolled in the KDHE State Cooperative Program for monitoring and remediation of the contaminant plumes including TCE; therefore, the TCE requires no additional investigation at this time through the Brownfields Program.

The detections of TCE in groundwater at the SAA V site are likely re lated to the Schilling site, but the source of the TPH DRO detections in groundwater at SAA V is unknown. Because the TPH DRO was identified in the upgradient-west side of the SAA V site, it is likely that there is an off-site source to the west. In addition, the SAA V site is located upgradient from the BTA property and there is a potential for TPH DRO to migrate on to the BTA site. A Phase II BTA was recommended to assess the potential migration of TPH DRO identified at the SAA V site and also to assess if historical petroleum storage at the property has impacted on-site soil and groundwater.

The Phase II BTA consisted of four soil borings and two groundwater borings. 10 soil and three groundwater samples (including QA/QC samples) were analyzed for TPH DRO, TPH GRO. The groundwater samples were also analyzed for VOCs.

All subsurface soil samples detected TPH GRO at levels exceeding the KDHE Risk-Based Standards for Kansas (RSK) soil to groundwater level of 79.3 milligrams per kilogram (mg/kg) including: SB-1 (9 to 10 feet) at 1,930 mg/kg, SB-2 (5 to 6 feet) at 426 mg/kg, SB-3 (10 to 11 feet) at 435 mg/kg, and SB-4 (7 to 8 feet) at 270 mg/kg. TPH DRO was detected in all surface soil samples at concentrations ranging from 38 mg/kg to 236 mg/kg, but none exceeded the KDHE RSK residential level of 2,000 mg/kg. No other analyzed Contaminants of Concern (COCs) were detected in the soil samples above laboratory reporting limits. No analyzed COCs were detected in the groundwater sample collected from MW-2 above laboratory reporting limits.

TPH GRO-impacted soil appears to exist at depth beginning from appr oximately 2 to 7 feet below ground surface (bgs) and ending at 13 to

SALINA AIRPORT AUTHORITY X (Continued) **S118117470**

16 ft bgs. Groundwater does not appear to be impacted from petroleum constituents based on the one groundwater sample collected. Based on the Phase II data, it is likely that a release has occurred on the property from the historical use for bulk petroleum storage. As the petroleum impacts are likely associated with the former Schilling Air Force Base facility and operations, any future activities determined necessary will be addressed as part of the Schilling Air Force Base Site (C5-085-03013).

Site ID:	3167
Has Env Use Control:	No
Project code:	C508573216
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.79482 / -97.63339
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	Department of Defense
Lead Agency:	BER - Remedial
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	05/25/2015
Activity End Date:	10/05/2015
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Phase I BTA at 2461 Centennial Rd. in Salina, Kansas. The BTA was completed for the Salina Airport Authority (SAA), who is the current owner and intends to sell or lease the property to a prospective

SALINA AIRPORT AUTHORITY X (Continued) **S118117470**

purchaser. Based on the Phase I report, ?Recognized Environmental Conditions? (RECs) were identified in connection with the BTA property as the: historical use of the BTA property for petroleum storage since the 1942; the adjacent active Schilling Air Force Base site (C5-085-03013) and the potential for trichloroethylene (TCE) plume migration onto the BTA site; and the southwest-adjoining SAA V site (C5-085-72817) which has TPH DRO and TCE in the groundwater above the KDHE RSK levels.

The BTA property was owned by the U.S. government from 1942 to 1965, and three aboveground storage tanks (ASTs) were used for aviation fuel storage during this time. The SAA took ownership of the property in 1967, and the storage tanks were out of use from 1967 to 1985. In 1985, the property was used for fertilizer storage and this use continues today, although one of the ASTs was removed from the property in 2013.

The Schilling Air Force Base site is currently enrolled in the KDHE State Cooperative Program for monitoring and remediation of the contaminant plumes including TCE; therefore, the TCE requires no additional investigation at this time through the Brownfields Program.

The detections of TCE in groundwater at the SAA V site are likely re lated to the Schilling site, but the source of the TPH DRO detections in groundwater at SAA V is unknown. Because the TPH DRO was identified in the upgradient-west side of the SAA V site, it is likely that there is an off-site source to the west. In addition, the SAA V site is located upgradient from the BTA property and there is a potential for TPH DRO to migrate on to the BTA site. A Phase II BTA was recommended to assess the potential migration of TPH DRO identified at the SAA V site and also to assess if historical petroleum storage at the property has impacted on-site soil and groundwater.

The Phase II BTA consisted of four soil borings and two groundwater borings. 10 soil and three groundwater samples (including QA/QC samples) were analyzed for TPH DRO, TPH GRO. The groundwater samples were also analyzed for
VOCs.

All subsurface soil samples detected TPH GRO at levels exceeding the KDHE Risk-Based Standards for Kansas (RSK) soil to groundwater level of 79.3 milligrams per kilogram (mg/kg) including: SB-1 (9 to 10 feet) at 1,930 mg/kg, SB-2 (5 to 6 feet) at 426 mg/kg, SB-3 (10 to 11 feet) at 435 mg/kg, and SB-4 (7 to 8 feet) at 270 mg/kg. TPH DRO was detected in all surface soil samples at concentrations ranging from 38 mg/kg to 236 mg/kg, but none exceeded the KDHE RSK residential level of 2,000 mg/kg. No other analyzed Contaminants of Concern (COCs) were detected in the soil samples above laboratory reporting limits. No analyzed COCs were detected in the groundwater sample collected from MW-2 above laboratory reporting
limits.

TPH GRO-impacted soil appears to exist at depth beginning from appr oximately 2 to 7 feet below ground surface (bgs) and ending at 13 to 16 ft bgs. Groundwater does not appear to be impacted from petroleum constituents based on the one groundwater sample collected. Based on the Phase II data, it is likely that a release has occurred on the property from the historical use for bulk petroleum storage. As the petroleum impacts are likely associated with the former Schilling Air Force Base facility and operations, any future activities determined necessary will be addressed as part of the Schilling Air Force Base

SALINA AIRPORT AUTHORITY X (Continued) **S118117470**

Site (C5-085-03013).

---

100 North 1/4-1/2 0.462 mi. 2441 ft. **KSU-SALINA**
2409 SCANLAN AVE
SALINA, KS 67401

KS LUST **S101836948**
N/A

Relative: Lower
Actual: 1245 ft.

LUST:

Facility ID:	00134
Site Status:	**Closed**
Release Date:	Not reported
Initial Report Date:	08/21/1992
Project Number:	U5-085-00741
Project Name:	Ksu, Salina, Ks Tech Inst
Legal Desc Section:	27
Legal Desc Township:	14S
Legal Desc Range:	03W
Discover Date:	08/24/1992
substrels:	gasoline/used oil
Initial Ranking:	Not reported
Current Ranking:	Not reported
Facility Contact:	Not reported
Facility Phone Number:	785-825-0275
Facility Owner Identification number:	00134
Facility Owner:	Ksu-salina (kans Tech Inst)
Owner Contact Person:	Not reported
Owner Address:	Dykstra Hall,2 Fl,se,manhattan
Owner City:	Not reported
Owner State:	KS
Owner Zip Code:	66506
Owner Phone number:	785-532-6377
Contractor license number:	Not reported
Contractor phone number:	785-479-2106
Leak duration (if known):	Unkn
Quantity released (if known):	Not reported
Quantity recorded:	Not reported
Leak Type:	Piping
Reported By:	Howard Debauche, Kdhe
Reported by persons phone number:	Not reported
Reported by person address:	Ncdo
Ground water Impacted (yes/no):	area consists primarily of dark grayish brown silty clays. gw generally shallow in area, but was not encountered in any of these excavations. gw depth = 14'. gw flow = east.
Static groundwater level:	Not reported
Groundwater flow direction:	Not reported
District staff names:	Howard Debauche
Assessment of release:	1-2000 gal gas, 1-550 gal gas, & 1-300 gal used oil usts & lines removed.piping had leaked beneath pump island at some time in past.used oil ust had been overfilled in past.contam soils removed/landfarmed-prop of contractor.~270yds.closed.no action.
Contaimination assessement:	yes.
Extent of contamination impact:	none suspected.
Updated information:	Not reported
Invoice initiated:	19931
Invoice on going:	Not reported
Invoice completetd:	19931
Release confirmed:	19931

KSU-SALINA (Continued) **S101836948**

Emergencty contact:	Not reported
Enforcement action:	Not reported
Cost recovery:	Not reported
Cost recovery initiated:	19931
Cost recovery initiated by:	Responsible Party
Cost recovery completed:	19931
Cost recovery completed by:	Responsible Party
Appplication to trust fund:	Not reported

---

101 South 1/4-1/2 0.474 mi. 2503 ft. **SALINA AIRPORT AUTHORITY IX** **US BROWNFIELDS 1024008844**
SW INTERSECTION OF WALL ST AND SCANLAN RD **FINDS N/A**
SALINA, KS 67401

Relative: Higher

Actual: 1267 ft.

US BROWNFIELDS:

Name:	SALINA AIRPORT AUTHORITY IX
Address:	SW INTERSECTION OF WALL ST AND SCANLAN RD
City,State,Zip:	SALINA, KS 67401
Recipient Name:	Kansas Department of Health and Environment
Grant Type:	Section 128(a) State/Tribal
Property Number:	Not reported
Parcel size:	10.36
Latitude:	38.7745386
Longitude:	-97.63599490000001
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	187381
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1800
Assessment Funding Source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	98726204
Start Date:	03/30/2015 00:00:00
Ownership Entity:	Not reported
Completion Date:	05/26/2015 00:00:00
Current Owner:	Salina Airport Authority
Did Owner Change:	N
Cleanup Required:	U
Video Available:	N
Photo Available:	Y

SALINA AIRPORT AUTHORITY IX (Continued) **1024008844**

Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	10.36
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	10.36
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported

SALINA AIRPORT AUTHORITY IX (Continued) **1024008844**

Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	The property has always been agricultural or pasture land. In 1947 the Common School District no.50 sold the property to a private individual, and the property changed ownership nine times from private individual to private individual until, in 1985, the Salina Airport Authority purchased the property.
Below Poverty Number:	19
Below Poverty Percent:	20.2%
Meidan Income:	205
Meidan Income Number:	40
Meidan Income Percent:	42.6%
Vacant Housing Number:	2
Vacant Housing Percent:	5.6%
Unemployed Number:	3
Unemployed Percent:	3.2%

FINDS:

Registry ID: 110070149007

Environmental Interest/Information System

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

~~Click this hyperlink~~ while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

102
North
1/2-1
0.625 mi.
3299 ft.

KSU-SALINA REDEVELOPMENT PROJECT BTA
2310 CENTENNIAL ROAD
SALINA, KS

KS SHWS **S107420869**
KS SPILLS **N/A**

Relative:
Lower

Actual:
1243 ft.

SHWS:

Site ID:	2030
Has Env Use Control:	No
Project code:	C508572088
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.798717 / -97.635412
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	26-500 acres
Waste Present:	No
Product Present:	No
Program:	FUDS (Formerly Used Defense Sites)
Lead Agency:	BER - Remedial
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Resolved
Activity Status:	Completed
Activity Start Date:	Not reported
Activity End Date:	01/08/2016
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Property Redevelopment Assessment (PRA) at the KSU-Salina Redevelopment Area which consists of approximately 40.6 acres of land located within the Former Schilling Air Force Base. The redevelopment area was divided into four major areas and 14 subareas. The PRA was funded through a portion of the KDHE's Brownfields Program. The Former Schilling Air Force Base is categorized as a Formerly Used Defense Site (FUDS). The Army Corps of Engineers

KSU-SALINA REDEVELOPMENT PROJECT BTA (Continued) **S107420869**

generally investigates Department of Defense (DOD) source areas within a FUDS site. Several areas within the former Schilling Air Force Base are currently being addressed through the FUDS program.
A Phase I assessment was completed for the property in February 2006 . Subareas 3 and 4 were cleared for redevelopment without warranting further investigation. Due to historical and current land uses identified in the Phase I report, Phase II assessments were recommended at subareas 1, 2, and 5 through 14.
The area surrounding this redevelopment project is part of the Schil ling Air Force Base site (C5-085-03013) which is currently enrolled in the KDHE State Cooperative Program to address soil and groundwater contamination associated with associated with historical operations as an air force base. Therefore, this site is consdiered resolved under the Brownfields Program. Notwithstanding, the groundwater contaminant plumes associated with the Schilling AFB Site have the potential to migrate overtime and it is recommended that best management practices be carried out during future uses at the property.

Site ID:	2030
Has Env Use Control:	No
Project code:	C508572088
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.798717 / -97.635412
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	26-500 acres
Waste Present:	No
Product Present:	No
Program:	FUDS (Formerly Used Defense Sites)
Lead Agency:	BER - Remedial
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported

KSU-SALINA REDEVELOPMENT PROJECT BTA (Continued) **S107420869**

Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Resolved
Activity Status:	Completed
Activity Start Date:	Not reported
Activity End Date:	01/08/2016
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Property Redevelopment Assessment (PRA) at the KSU-Salina Redevelopment Area which consists of approximately 40.6 acres of land located within the Former Schilling Air Force Base. The redevelopment area was divided into four major areas and 14 subareas. The PRA was funded through a portion of the KDHE's Brownfields Program. The Former Schilling Air Force Base is categorized as a Formerly Used Defense Site (FUDS). The Army Corps of Engineers generally investigates Department of Defense (DOD) source areas within a FUDS site. Several areas within the former Schilling Air Force Base are currently being addressed through the FUDS program. A Phase I assessment was completed for the property in February 2006 . Subareas 3 and 4 were cleared for redevelopment without warranting further investigation. Due to historical and current land uses identified in the Phase I report, Phase II assessments were recommended at subareas 1, 2, and 5 through 14. The area surrounding this redevelopment project is part of the Schil ling Air Force Base site (C5-085-03013) which is currently enrolled in the KDHE State Cooperative Program to address soil and groundwater contamination associated with associated with historical operations as an air force base. Therefore, this site is consdiered resolved under the Brownfields Program. Notwithstanding, the groundwater contaminant plumes associated with the Schilling AFB Site have the potential to migrate overtime and it is recommended that best management practices be carried out during future uses at the property.
Site ID:	2030
Has Env Use Control:	No
Project code:	C508572088
PM Name:	BER - REMEDIAL
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.798717 / -97.635412
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	26-500 acres
Waste Present:	No
Product Present:	No
Program:	FUDS (Formerly Used Defense Sites)

KSU-SALINA REDEVELOPMENT PROJECT BTA (Continued) **S107420869**

Lead Agency:	BER - Remedial
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Resolved
Activity Status:	Completed
Activity Start Date:	Not reported
Activity End Date:	01/08/2016
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Property Redevelopment Assessment (PRA) at the KSU-Salina Redevelopment Area which consists of approximately 40.6 acres of land located within the Former Schilling Air Force Base. The redevelopment area was divided into four major areas and 14 subareas. The PRA was funded through a portion of the KDHE's Brownfields Program. The Former Schilling Air Force Base is categorized as a Formerly Used Defense Site (FUDS). The Army Corps of Engineers generally investigates Department of Defense (DOD) source areas within a FUDS site. Several areas within the former Schilling Air Force Base are currently being addressed through the FUDS program. A Phase I assessment was completed for the property in February 2006 . Subareas 3 and 4 were cleared for redevelopment without warranting further investigation. Due to historical and current land uses identified in the Phase I report, Phase II assessments were recommended at subareas 1, 2, and 5 through 14. The area surrounding this redevelopment project is part of the Schil ling Air Force Base site (C5-085-03013) which is currently enrolled in the KDHE State Cooperative Program to address soil and groundwater contamination associated with associated with historical operations as an air force base. Therefore, this site is consdiered resolved under the Brownfields Program. Notwithstanding, the groundwater contaminant plumes associated with the Schilling AFB Site have the potential to migrate overtime and it is recommended that best management practices be carried out during future uses at the property.

SPILLS:

Spill ID:	KDHE-35173
Reported Cause:	equipment failure
Discharger Organization Type:	NC
Source:	motor vehicle
Spill Date:	02/27/2014
Discharge Name:	Kansas State University, Salina (hydraulic oil)

KSU-SALINA REDEVELOPMENT PROJECT BTA (Continued) **S107420869**

Material Name:	other oil
Media Affected:	soil
Status:	Closed
Latitude:	38.80098
Longitude:	-97.63709

Spill ID:	KDHE-35174
Reported Cause:	equipment failure
Discharger Organization Type:	NC
Source:	motor vehicle
Spill Date:	02/27/2014
Discharge Name:	Kansas State University (hydraulic oil)
Material Name:	other oil
Media Affected:	soil
Status:	Closed
Latitude:	38.79768
Longitude:	-97.63890

SPILLS as of July 2016:

Ref ID:	16378
Evacuation:	No
Responders:	Not reported
Cause Description:	Not reported
Cleanup Description:	Floor dry was used and picked up. Pavement staining and soil impacts remain. I recommend soil removal and replanting of grass in the impacted areas. Pavement areas need to be cleaned better as oil will damage pavement and may make a sheen during rain
Cleanup Method:	physical removal
Comments:	Rick Honeycutt is the police Sergeant that reported the problem to Kelly, who reported it to us. I met both Kelly and Rick on-site on 2-27-2014. I advised that additional clean-up will be necessary. They will call us after the clean-up is ready for a
Damage Description:	Not reported
Damage Number Of Deaths:	0
Damage Number If Injuries:	0
Property Damage > $50,000:	Undetermined
Discovery Date:	02/27/2014
Discovery Time:	0800
Spill Date:	02/04/2014
Spill Time:	0000
Discharger Address:	108 Edwards Hall
Discharger City:	Manhattan
Discharger Contact:	Kelly Greene
Discharger Ext. 1:	Not reported
Discharger Ext. 2:	Not reported
Discharger Facility ID:	Not reported
Discharger:	Kansas State University, Salina (hydraulic oil)
Discharger Org ID:	Not reported
Discharger Organization Type:	Not reported
Discharger Phone 1:	785-565-8971
Discharger Phone 2:	785-532-5856
Discharger State:	KS
Discharger Zip:	66502
District:	NC
GPS Source:	Not reported
Highway Designation:	Not reported
Highway Type:	Not reported

KSU-SALINA REDEVELOPMENT PROJECT BTA (Continued) **S107420869**

KCC District:	Wichita
Latitude:	38.800976
Lease Number:	Not reported
Longitude:	-97.637094
Mile Post:	Not reported
Incident Qtr1:	Not reported
Incident Qtr2:	Not reported
Incident Qtr3:	Not reported
Incident Qtr4:	Not reported
Incident Range:	Not reported
Incident Section:	Not reported
Incident Township:	Not reported
Did EPA Respond?:	Unknown
EPA Spill Number:	Not reported
Initial Entry By:	Scott Lang
Initial Entry Completed:	Yes
KCC Spill Number:	Not reported
Method Receive Initial Call:	Not reported
Multiple Report:	Not reported
NRCNO:	Not reported
Old Spill Number:	Not reported
Incident Recorded By:	Not reported
Reported Date:	02/27/2014
Reported Time:	1000
SSI Repor:	Not reported
Spill Number:	35173
Spill Or Complaint:	Spill
Spill Stage:	closed
Through NRC:	Unknown
Updated By:	Scott Lang
Investigating Agency:	KDHE
State Visited By KDHE?:	Yes
Investigated By 1:	Scott Lang
Hours Worked 1:	1.5
Investigated By 2:	Not reported
Hours Worked 2:	Not reported
Investigated By 3:	Not reported
Hours Worked 3:	Not reported
Quantity Spilled 1:	30
Qty Spilled Comment 1:	estimated
Quantity Spilled 2:	Not reported
Qty Spilled Comment 2:	Not reported
Quantity Spilled 3:	Not reported
Qty Spilled Comment 3:	Not reported
Case Number 1:	Not reported
Case Number 2:	Not reported
Case Number 3:	Not reported
Class 1:	other oil
Class 2:	Not reported
Class 3:	Not reported
Qty Spilled In Water 1:	0
Qty Spilled In Water Comment 1:	actual
Qty Spilled In Water 2:	Not reported
Qty Spilled In Water Comment 2:	Not reported
Qty Spilled In Water 3:	Not reported
Qty Spilled In Water Comment 3:	Not reported
Material Name:	hydraulic oil/fluid

KSU-SALINA REDEVELOPMENT PROJECT BTA (Continued) **S107420869**

Material Name 2:	Not reported
Material Name 3:	Not reported
Qty Recovered 1:	Not reported
Qty Recovered Comment 1:	unknown
Qty Recovered 2:	Not reported
Qty Recovered Comment 2:	Not reported
Qty Recovered 3:	Not reported
Qty Recovered Comment 3:	Not reported
Material UNDOT Number 1:	Not reported
Material UNDOT Number 2:	Not reported
Material UNDOT Number 3:	Not reported
Unit 1:	gallons
Unit 2:	Not reported
Unit 3:	Not reported
Media:	soil
Media Waterway:	Not reported
Media Waterway Type:	Not reported
Who Notified:	Not reported
Notified:	Not reported
Spill Report:	Yes
Description:	Not reported
Number Of Tanks:	Not reported
Source Of Spill:	motor vehicle
Tank Capacity:	Not reported
Tank Unit:	Not reported
Vehicle ID:	Not reported
Close Date:	03/28/2014
Follow-up Required:	Not reported
Response Required By:	Not reported
Facility Status:	Closed
Comments 1:	55 gal hydraulic tank on tractor for snow removal leaked
Comments 2:	hydraulic leak on tractor
Comments 3:	Pavement staining and minor soil impacts.
Comments 4:	Initial clean-up done needs additional clean-up
Ref ID:	16379
Evacuation:	No
Responders:	Not reported
Cause Description:	Not reported
Cleanup Description:	Initial clean-up with floor dry was incomplete. Needs to be finished and some soil removal performed.
Cleanup Method:	physical removal
Comments:	Met Kelly Greene and Rick Honeycutt on-site 2-27-2014 and inspected the spill. The initial clean-up was not good enough will need to remove staining from the pavement and some minor soil removal and grass planting. (sl) Met Rick and Maintanance Persone
Damage Description:	Not reported
Damage Number Of Deaths:	0
Damage Number If Injuries:	0
Property Damage > $50,000:	Undetermined
Discovery Date:	02/27/2014
Discovery Time:	0800
Spill Date:	Not reported
Spill Time:	Not reported
Discharger Address:	108 Edwards Hall
Discharger City:	Manhattan
Discharger Contact:	Kelly Greene

KSU-SALINA REDEVELOPMENT PROJECT BTA (Continued) **S107420869**

Discharger Ext. 1:	Not reported
Discharger Ext. 2:	Not reported
Discharger Facility ID:	Not reported
Discharger:	Kansas State University (hydraulic oil)
Discharger Org ID:	Not reported
Discharger Organization Type:	State
Discharger Phone 1:	785-565-8971
Discharger Phone 2:	785-532-5856
Discharger State:	KS
Discharger Zip:	66502
District:	NC
GPS Source:	Not reported
Highway Designation:	Not reported
Highway Type:	Not reported
KCC District:	Wichita
Latitude:	38.797683
Lease Number:	Not reported
Longitude:	-97.638898
Mile Post:	Not reported
Incident Qtr1:	Not reported
Incident Qtr2:	Not reported
Incident Qtr3:	Not reported
Incident Qtr4:	Not reported
Incident Range:	Not reported
Incident Section:	Not reported
Incident Township:	Not reported
Did EPA Respond?:	Unknown
EPA Spill Number:	Not reported
Initial Entry By:	Scott Lang
Initial Entry Completed:	Yes
KCC Spill Number:	Not reported
Method Receive Initial Call:	Not reported
Multiple Report:	Not reported
NRCNO:	Not reported
Old Spill Number:	Not reported
Incident Recorded By:	Not reported
Reported Date:	02/27/2014
Reported Time:	1000
SSI Repor:	Not reported
Spill Number:	35174
Spill Or Complaint:	Spill
Spill Stage:	closed
Through NRC:	Unknown
Updated By:	Scott Lang
Investigating Agency:	KDHE
State Visited By KDHE?:	Yes
Investigated By 1:	Scott Lang
Hours Worked 1:	1.5
Investigated By 2:	Not reported
Hours Worked 2:	Not reported
Investigated By 3:	Not reported
Hours Worked 3:	Not reported
Quantity Spilled 1:	45
Qty Spilled Comment 1:	estimated
Quantity Spilled 2:	Not reported
Qty Spilled Comment 2:	Not reported
Quantity Spilled 3:	Not reported

KSU-SALINA REDEVELOPMENT PROJECT BTA (Continued) **S107420869**

Qty Spilled Comment 3:	Not reported
Case Number 1:	Not reported
Case Number 2:	Not reported
Case Number 3:	Not reported
Class 1:	other oil
Class 2:	Not reported
Class 3:	Not reported
Qty Spilled In Water 1:	0
Qty Spilled In Water Comment 1:	actual
Qty Spilled In Water 2:	Not reported
Qty Spilled In Water Comment 2:	Not reported
Qty Spilled In Water 3:	Not reported
Qty Spilled In Water Comment 3:	Not reported
Material Name:	hydraulic oil/fluid
Material Name 2:	Not reported
Material Name 3:	Not reported
Qty Recovered 1:	Not reported
Qty Recovered Comment 1:	unknown
Qty Recovered 2:	Not reported
Qty Recovered Comment 2:	Not reported
Qty Recovered 3:	Not reported
Qty Recovered Comment 3:	Not reported
Material UNDOT Number 1:	Not reported
Material UNDOT Number 2:	Not reported
Material UNDOT Number 3:	Not reported
Unit 1:	gallons
Unit 2:	Not reported
Unit 3:	Not reported
Media:	soil
Media Waterway:	Not reported
Media Waterway Type:	none
Who Notified:	Not reported
Notified:	Not reported
Spill Report:	Yes
Description:	Not reported
Number Of Tanks:	Not reported
Source Of Spill:	motor vehicle
Tank Capacity:	Not reported
Tank Unit:	Not reported
Vehicle ID:	Not reported
Close Date:	04/10/2014
Follow-up Required:	Not reported
Response Required By:	Not reported
Facility Status:	Closed
Comments 1:	Snow removal tractor leaked approx. 45 gals from a 55 tank on the tractor
Comments 2:	leak in hydraulic system on a snow removal tractor.
Comments 3:	Pavement staining and minor soil impacts.
Comments 4:	initial clean-up with floor dry

103
West
1/2-1
0.667 mi.
3521 ft.

SCHILLING AFB OU3
SALINA, KS

KS SHWS **S108047943**
N/A

Relative:
Higher

Actual:
1272 ft.

SHWS:

Site ID:	2128
Has Env Use Control:	No
Project code:	C508572186
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.78576 / -97.65612
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	VOC
Media Act:	Not reported
Media Pot:	Not reported
Source:	Facility Operations
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING OU3
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Remedial Investigation
Activity Status:	Completed
Activity Start Date:	08/27/2012
Activity End Date:	04/19/2018
Narrative:	As part of the 2005 Remedial Investigation, Schilling AFB was broken into 3 Operable Units (OUs) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. For information prior to 2005, please refer to the Schilling AFB (parent site) file. USACE's contractor was working on a Remedial Investigation work plan in 2007; USACE stopped work at the site in preparation of an

SCHILLING AFB OU3 (Continued) **S108047943**

anticipated settlement with local entities in Salina. In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Schilling AFB Site; including OU3. For additional information regarding site activities peformed after 2012 please refer to the Schilling AFB parent site; C5-085-03013.

Site ID:	2128
Has Env Use Control:	No
Project code:	C508572186
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.78576 / -97.65612
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	VOC
Media Act:	Not reported
Media Pot:	Not reported
Source:	Facility Operations
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING OU3
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Remedial Investigation
Activity Status:	Completed
Activity Start Date:	08/27/2012
Activity End Date:	04/19/2018
Narrative:	As part of the 2005 Remedial Investigation, Schilling AFB was broken into 3 Operable Units (OUs) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. For information prior to 2005, please refer to the Schilling AFB (parent site)

SCHILLING AFB OU3 (Continued) **S108047943**

file.
USACE's contractor was working on a Remedial Investigation work plan in 2007; USACE stopped work at the site in preparation of an anticipated settlement with local entities in Salina. In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Schilling AFB Site; including OU3. For additional information regarding site activities peformed after 2012 please refer to the Schilling AFB parent site; C5-085-03013.

Site ID:	2128
Has Env Use Control:	No
Project code:	C508572186
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.78576 / -97.65612
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	VOC
Media Act:	Not reported
Media Pot:	Not reported
Source:	Facility Operations
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING OU3
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Remedial Investigation
Activity Status:	Completed
Activity Start Date:	08/27/2012
Activity End Date:	04/19/2018
Narrative:	As part of the 2005 Remedial Investigation, Schilling AFB was broken into 3 Operable Units (OUs) based on level of contamination and

SCHILLING AFB OU3 (Continued) **S108047943**

highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. For information prior to 2005, please refer to the Schilling AFB (parent site) file.

USACE's contractor was working on a Remedial Investigation work plan in 2007; USACE stopped work at the site in preparation of an anticipated settlement with local entities in Salina. In 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Schilling AFB Site; including OU3. For additional information regarding site activities peformed after 2012 please refer to the Schilling AFB parent site; C5-085-03013.

---

104 North 1/2-1 0.712 mi. 3762 ft.

SCHILLING AFB OU1 **KS SHWS** **S108047940**
SALINA, KS **N/A**

Relative: Lower

Actual: 1241 ft.

SHWS:

Site ID:	2126
Has Env Use Control:	No
Project code:	C508572184
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.80064 / -97.63444
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	>1000 gpm
GW Flow Direction:	NE
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Inorganic, SVOC, VOC
Media Act:	Air, Indoor, Ground Water, Soil
Media Pot:	Air, Outdoor
Source:	Facility Operations
Land Use:	Agricultural, Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Monitoring
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Human, Wildlife
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported

SCHILLING AFB OU1 (Continued) **S108047940**

Alias:	SCHILLING OU1
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Risk Analysis
Activity Status:	Completed
Activity Start Date:	03/18/2015
Activity End Date:	03/23/2017
Narrative:	As part of the 2005 Remedial Investigation, Schilling AFB was broken into 3 Operable Units (OUs) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. For information prior to 2005, please refer to the Schilling AFB (parent site C5-085-03013) file. From December 2004 through November 2006, KDHE performed sub-slab va por and indoor air monitoring at KSU and SATS. KDHE also installed vapor mitigation systems, tested indoor air in 2 private homes, and completed a soil-gas investigation. USACE performed groundwater long term monitoring; USACE has also per formed a Pilot Scale Treatability Study, and a Vapor Intrusion investigation. Air sampling at buildings on the Kansas State University (KSU) and Salina Area Technical School (SATS) campuses was also being conducted. The OU 1 Remedial Investigation Addendum/Feasibility Study field work concluded in Summer 2007, and a Final Data Report was received from USACE on January 31, 2008; the customary RI report was not issued by USACE as it stopped work at the site in preparation of an anticipated settlement with local entities in Salina. On March 6, 2012, KDHE received from USACE a letter report detailing the abandonment of 5 wells used for a pump test during the OU-1 RI/FS addendum work. Also in 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Schilling AFB Site; including OU1. In December 2014, an additonal vapor intrustion (VI) investigation was completed. The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent FS. For additional information regarding site activities peformed after 2012 please refer to the Schilling AFB parent site; C5-085-03013.
Site ID:	2126
Has Env Use Control:	No
Project code:	C508572184
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.80064 / -97.63444
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported

SCHILLING AFB OU1 (Continued) **S108047940**

Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	>1000 gpm
GW Flow Direction:	NE
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Inorganic, SVOC, VOC
Media Act:	Air, Indoor, Ground Water, Soil
Media Pot:	Air, Outdoor
Source:	Facility Operations
Land Use:	Agricultural, Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Monitoring
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Human, Wildlife
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING OU1
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Risk Analysis
Activity Status:	Completed
Activity Start Date:	03/18/2015
Activity End Date:	03/23/2017
Narrative:	As part of the 2005 Remedial Investigation, Schilling AFB was broken into 3 Operable Units (OUs) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. For information prior to 2005, please refer to the Schilling AFB (parent site C5-085-03013) file. From December 2004 through November 2006, KDHE performed sub-slab va por and indoor air monitoring at KSU and SATS. KDHE also installed vapor mitigation systems, tested indoor air in 2 private homes, and completed a soil-gas investigation. USACE performed groundwater long term monitoring; USACE has also per formed a Pilot Scale Treatability Study, and a Vapor Intrusion investigation. Air sampling at buildings on the Kansas State University (KSU) and Salina Area Technical School (SATS) campuses was also being conducted. The OU 1 Remedial Investigation Addendum/Feasibility Study field work concluded in Summer 2007, and a Final Data Report was received from USACE on January 31, 2008; the customary RI report was not issued by USACE as it stopped work at the site in preparation of an anticipated settlement with local entities in Salina. On March 6, 2012, KDHE received from USACE a letter report detailing the abandonment of 5 wells used for a pump test during the OU-1 RI/FS addendum work. Also in 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility

SCHILLING AFB OU1 (Continued) **S108047940**

of completing the RI and Feasibility Study (FS) for the Schilling AFB Site; including OU1. In December 2014, an additonal vapor intrustion (VI) investigation was completed.
The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent FS. For additional information regarding site activities peformed after 2012 please refer to the Schilling AFB parent site; C5-085-03013.

Site ID:	2126
Has Env Use Control:	No
Project code:	C508572184
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.80064 / -97.63444
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	>1000 gpm
GW Flow Direction:	NE
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Inorganic, SVOC, VOC
Media Act:	Air, Indoor, Ground Water, Soil
Media Pot:	Air, Outdoor
Source:	Facility Operations
Land Use:	Agricultural, Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Monitoring
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Human, Wildlife
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING OU1
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Risk Analysis
Activity Status:	Completed
Activity Start Date:	03/18/2015
Activity End Date:	03/23/2017
Narrative:	As part of the 2005 Remedial Investigation, Schilling AFB was broken into 3 Operable Units (OUs) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. For information prior to 2005, please refer to the

SCHILLING AFB OU1 (Continued) **S108047940**

Schilling AFB (parent site C5-085-03013)
file.
From December 2004 through November 2006, KDHE performed sub-slab va por and indoor air monitoring at KSU and SATS. KDHE also installed vapor mitigation systems, tested indoor air in 2 private homes, and completed a soil-gas
investigation.
USACE performed groundwater long term monitoring; USACE has also per formed a Pilot Scale Treatability Study, and a Vapor Intrusion investigation. Air sampling at buildings on the Kansas State University (KSU) and Salina Area Technical School (SATS) campuses was also being conducted. The OU 1 Remedial Investigation Addendum/Feasibility Study field work concluded in Summer 2007, and a Final Data Report was received from USACE on January 31, 2008; the customary RI report was not issued by USACE as it stopped work at the site in preparation of an anticipated settlement with local entities
in
Salina.
On March 6, 2012, KDHE received from USACE a letter report detailing the abandonment of 5 wells used for a pump test during the OU-1 RI/FS addendum work. Also in 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Schilling AFB Site; including OU1. In December 2014, an additonal vapor intrustion (VI) investigation was completed.
The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent FS. For additional information regarding site activities peformed after 2012 please refer to the Schilling AFB parent site; C5-085-03013.

Site ID:	2126
Has Env Use Control:	No
Project code:	C508572184
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.80064 / -97.63444
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	>1000 gpm
GW Flow Direction:	NE
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Inorganic, SVOC, VOC
Media Act:	Air, Indoor, Ground Water, Soil

SCHILLING AFB OU1 (Continued) **S108047940**

Media Pot:	Air, Outdoor
Source:	Facility Operations
Land Use:	Agricultural, Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Monitoring
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Human, Wildlife
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING OU1
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Risk Analysis
Activity Status:	Completed
Activity Start Date:	03/18/2015
Activity End Date:	03/23/2017
Narrative:	As part of the 2005 Remedial Investigation, Schilling AFB was broken into 3 Operable Units (OUs) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. For information prior to 2005, please refer to the Schilling AFB (parent site C5-085-03013) file. From December 2004 through November 2006, KDHE performed sub-slab va por and indoor air monitoring at KSU and SATS. KDHE also installed vapor mitigation systems, tested indoor air in 2 private homes, and completed a soil-gas investigation. USACE performed groundwater long term monitoring; USACE has also per formed a Pilot Scale Treatability Study, and a Vapor Intrusion investigation. Air sampling at buildings on the Kansas State University (KSU) and Salina Area Technical School (SATS) campuses was also being conducted. The OU 1 Remedial Investigation Addendum/Feasibility Study field work concluded in Summer 2007, and a Final Data Report was received from USACE on January 31, 2008; the customary RI report was not issued by USACE as it stopped work at the site in preparation of an anticipated settlement with local entities in Salina. On March 6, 2012, KDHE received from USACE a letter report detailing the abandonment of 5 wells used for a pump test during the OU-1 RI/FS addendum work. Also in 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Schilling AFB Site; including OU1. In December 2014, an additonal vapor intrustion (VI) investigation was completed. The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent FS. For additional information regarding site activities peformed after 2012 please refer to the Schilling AFB parent site; C5-085-03013.
Site ID:	2126
Has Env Use Control:	No

SCHILLING AFB OU1 (Continued) **S108047940**

Project code:	C508572184
PM Name:	RICHARDS, A.
Site Status:	**Active**
District Office:	NCDO
Lat/Long:	38.80064 / -97.63444
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Alluvial
Other Aquifers:	Wellington
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	11-20 feet
Depth To Bedrock:	21-30 feet
Aquifer Yield:	>1000 gpm
GW Flow Direction:	NE
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	State Cooperative
Lead Agency:	BER - Remedial
Contaminants:	Inorganic, SVOC, VOC
Media Act:	Air, Indoor, Ground Water, Soil
Media Pot:	Air, Outdoor
Source:	Facility Operations
Land Use:	Agricultural, Commercial, Industrial, Other (see Site Narrative)
Private well:	Domestic, Monitoring
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Human, Wildlife
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	SCHILLING OU1
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Risk Analysis
Activity Status:	Completed
Activity Start Date:	03/18/2015
Activity End Date:	03/23/2017
Narrative:	As part of the 2005 Remedial Investigation, Schilling AFB was broken into 3 Operable Units (OUs) based on level of contamination and highest potential health risk. OU 1 is the highest priority, followed by OU 2 and OU 3. For information prior to 2005, please refer to the Schilling AFB (parent site C5-085-03013) file. From December 2004 through November 2006, KDHE performed sub-slab va por and indoor air monitoring at KSU and SATS. KDHE also installed vapor mitigation systems, tested indoor air in 2 private homes, and completed a soil-gas investigation. USACE performed groundwater long term monitoring; USACE has also per formed a Pilot Scale Treatability Study, and a Vapor Intrusion investigation. Air sampling at buildings on the Kansas State University (KSU) and Salina Area Technical School (SATS) campuses was

SCHILLING AFB OU1 (Continued) **S108047940**

also being conducted. The OU 1 Remedial Investigation Addendum/Feasibility Study field work concluded in Summer 2007, and a Final Data Report was received from USACE on January 31, 2008; the customary RI report was not issued by USACE as it stopped work at the site in preparation of an anticipated settlement with local entities in
Salina.
On March 6, 2012, KDHE received from USACE a letter report detailing the abandonment of 5 wells used for a pump test during the OU-1 RI/FS addendum work. Also in 2012, the Salina Public Entities (City of Salina, SAA, USD 501 and Kansas State University) negotiated a settlement agreement with the USACE to take over the responsibility of completing the RI and Feasibility Study (FS) for the Schilling AFB Site; including OU1. In December 2014, an additonal vapor intrustion (VI) investigation was completed.
The RI field activities have concluded. Interim groundwater monitor ing and vapor instrusion assessment are on-going during deveopment of the RI Report and subsequent FS. For additional information regarding site activities peformed after 2012 please refer to the Schilling AFB parent site; C5-085-03013.

---

105 South 1/2-1 0.722 mi. 3814 ft. **SALINA AIRPORT AUTHORITY IV BTA** **KS SHWS** **S111095303**
VORTEX AVE & SCANLAN RD **KS BROWNFIELDS** **N/A**
SALINA, KS

Relative: Higher

Actual: 1282 ft.

SHWS:

Site ID:	2767
Has Env Use Control:	No
Project code:	C508572816
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.7718 / -97.6374
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	5-25 acres
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Industrial
Private well:	Not reported
Waste Present:	Not reported

SALINA AIRPORT AUTHORITY IV BTA (Continued) **S111095303**

Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	08/08/2011
Activity End Date:	12/12/2011
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Phase II Brownfields Targeted Assessment (BTA) at the Salina Airport Authority?Site IV in Salina, Kansas. The BTA was conducted for the Salina Airport Authority to expedite the transfer and redevelopment of the property, which is located within the boundary of a Formally Used Defense Facility (FUD). A Phase I, dated June 30, 2011, was conducted through a Property Red evelopment Assessment (PRA) by the Formerly Used Defense Sites (FUDS) Installations Program. Based on the Phase I report, ?Recognized Environmental Conditions? (RECs) were identified as potential petroleum and hazardous substances associated with: historical database listings and known contamination from adjacent facilities, including but not limited to Schilling AFB Operable Unit 2 and proximal location to Schilling AFB Fire training Burn Area, Area of Interest 07 (AOI 07) to the northwest. Therefore, a Phase II was recommended to commence. The Phase II scope of work was to collect groundwater samples from f our locations on the property. However, it become apparent during the field investigation that groundwater was not readily available. Therefore, the scope of work was modified by KDHE. One temporary piezometer was installed on the property and left overnight. After approximately 24 hours, groundwater had not entered the casing so the piezometer was removed and plugged. Due to the shallow bedrock and the absence of groundwater above a confining bedrock layer, the potential for shallow groundwater contamination at the site resulting from off-site sources is unlikely. No further assessment is being recommended at this time and the site is cleared for redevelopment.
Site ID:	2767
Has Env Use Control:	No
Project code:	C508572816
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.7718 / -97.6374
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported

SALINA AIRPORT AUTHORITY IV BTA (Continued) **S111095303**

Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	5-25 acres
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Industrial
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	08/08/2011
Activity End Date:	12/12/2011
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Phase II Brownfields Targeted Assessment (BTA) at the Salina Airport Authority?Site IV in Salina, Kansas. The BTA was conducted for the Salina Airport Authority to expedite the transfer and redevelopment of the property, which is located within the boundary of a Formally Used Defense Facility (FUD). A Phase I, dated June 30, 2011, was conducted through a Property Red evelopment Assessment (PRA) by the Formerly Used Defense Sites (FUDS) Installations Program. Based on the Phase I report, ?Recognized Environmental Conditions? (RECs) were identified as potential petroleum and hazardous substances associated with: historical database listings and known contamination from adjacent facilities, including but not limited to Schilling AFB Operable Unit 2 and proximal location to Schilling AFB Fire training Burn Area, Area of Interest 07 (AOI 07) to the northwest. Therefore, a Phase II was recommended to commence. The Phase II scope of work was to collect groundwater samples from f our locations on the property. However, it become apparent during the field investigation that groundwater was not readily available. Therefore, the scope of work was modified by KDHE. One temporary piezometer was installed on the property and left overnight. After approximately 24 hours, groundwater had not entered the casing so the piezometer was removed and plugged. Due to the shallow bedrock and the absence of groundwater above a confining bedrock layer, the potential for shallow groundwater contamination at the site resulting from off-site sources is unlikely. No further assessment is being recommended at this time and the site is cleared for redevelopment.

SALINA AIRPORT AUTHORITY IV BTA (Continued) **S111095303**

Site ID:	2767
Has Env Use Control:	No
Project code:	C508572816
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.7718 / -97.6374
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	5-25 acres
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Industrial
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	08/08/2011
Activity End Date:	12/12/2011
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Phase II Brownfields Targeted Assessment (BTA) at the Salina Airport Authority?Site IV in Salina, Kansas. The BTA was conducted for the Salina Airport Authority to expedite the transfer and redevelopment of the property, which is located within the boundary of a Formally Used Defense Facility (FUD). A Phase I, dated June 30, 2011, was conducted through a Property Red evelopment Assessment (PRA) by the Formerly Used Defense Sites (FUDS) Installations Program. Based on the Phase I report, ?Recognized Environmental Conditions? (RECs) were identified as potential petroleum and hazardous substances associated with: historical database listings and known contamination from adjacent facilities, including but not limited to Schilling AFB Operable Unit 2 and

SALINA AIRPORT AUTHORITY IV BTA (Continued) **S111095303**

proximal location to Schilling AFB Fire training Burn Area, Area of Interest 07 (AOI 07) to the northwest. Therefore, a Phase II was recommended to commence.

The Phase II scope of work was to collect groundwater samples from f our locations on the property. However, it become apparent during the field investigation that groundwater was not readily available. Therefore, the scope of work was modified by KDHE. One temporary piezometer was installed on the property and left overnight. After approximately 24 hours, groundwater had not entered the casing so the piezometer was removed and plugged. Due to the shallow bedrock and the absence of groundwater above a confining bedrock layer, the potential for shallow groundwater contamination at the site resulting from off-site sources is unlikely. No further assessment is being recommended at this time and the site is cleared for redevelopment.

BROWNFIELDS:

Site ID:	2767
Project code:	C508572816
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
Lat/Long:	38.7718 / -97.6374
Program:	Brownfields

106
SW
1/2-1
0.844 mi.
4458 ft.

SALINA AIRPORT AUTHORITY VI BTA **KS SHWS** **S116381149**
3600 AIRPORT ROAD BUILDING 1021 **KS BROWNFIELDS** **N/A**
SALINA, KS 67401

Relative:
Higher

Actual:
1280 ft.

SHWS:

Site ID:	3038
Has Env Use Control:	No
Project code:	C508573087
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.77285 / -97.6549
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	5-25 acres
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported

SALINA AIRPORT AUTHORITY VI BTA (Continued) **S116381149**

Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	01/24/2014
Activity End Date:	02/24/2014
Narrative:	The Kansas Department of Health and Environment (KDHE) has completed a Phase I Brownfields Targeted Assessment (BTA) at 3600 Airport Road in Salina, Saline County, Kansas. The BTA was conducted for the Salina Airport Authority who plans to lease the property. The Phase I BTA was completed in February, 2014, and no Recognized Environmental Conditions (RECs) were identified. The Phase I report did, however, identify a contaminant plume at the nearby Schilling AFB site, which has the potential to migrate overtime. Therefore, it is recommended that preventative measures (such as restricting groundwater use) are considered prior to future usage of the property in order to limit exposure to contaminated groundwater. A Phase II assessment is not recommended at this time and the property is cleared for redevelopment.
Site ID:	3038
Has Env Use Control:	No
Project code:	C508573087
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.77285 / -97.6549
River Basin:	Smoky Hills - Saline
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	Not reported
Parent Name:	Not reported
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	5-25 acres
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported

SALINA AIRPORT AUTHORITY VI BTA (Continued) **S116381149**

Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	01/24/2014
Activity End Date:	02/24/2014
Narrative:	The Kansas Department of Health and Environment (KDHE) has completed a Phase I Brownfields Targeted Assessment (BTA) at 3600 Airport Road in Salina, Saline County, Kansas. The BTA was conducted for the Salina Airport Authority who plans to lease the property. The Phase I BTA was completed in February, 2014, and no Recognized Environmental Conditions (RECs) were identified. The Phase I report did, however, identify a contaminant plume at the nearby Schilling AFB site, which has the potential to migrate overtime. Therefore, it is recommended that preventative measures (such as restricting groundwater use) are considered prior to future usage of the property in order to limit exposure to contaminated groundwater. A Phase II assessment is not recommended at this time and the property is cleared for redevelopment.

BROWNFIELDS:

Site ID:	3038
Project code:	C508573087
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
Lat/Long:	38.77285 / -97.6549
Program:	Brownfields

X107 **SALINA AIRPORT AUTHORITY I BTA** **KS SHWS** **S110311216**
South **SCANLAN RD. AND WATER WELL ROAD** **KS BROWNFIELDS** **N/A**
1/2-1 **SALINA, KS 67401**
0.858 mi.
4532 ft. **Site 1 of 2 in cluster X**

Relative:
Higher

Actual:
1286 ft.

SHWS:

Site ID:	2597
Has Env Use Control:	No
Project code:	C508572649
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.77089 / -97.6398
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported

SALINA AIRPORT AUTHORITY I BTA (Continued) **S110311216**

Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	Not reported
Activity End Date:	06/26/2010
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Phase I Brownfields Targeted Assessment (BTA) on 80.4 acres of vacant property located on the southwest corner of Scanlan Rd and Water Well Rd. The BTA applicant is the Salina Airport Authority, who owns the property and intends to sell/ lease the property for commercial/ industrial use. Based on the Phase I, Recognized Environmental Conditions (RECs) were discovered in connection with the BTA site as potential hazardous substances due to the historical use of the property as agricultural land since at least 1938, and the potential for historical use of pesticides and/ or herbicides. This REC, however, does not warrant the completion of a Phase II, based solely on the property site use of pesticides or herbicides at application rates per manufacturer?s instructions.
Site ID:	2597
Has Env Use Control:	No
Project code:	C508572649
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.77089 / -97.6398
River Basin:	Not reported
Aquifer Yield:	Not reported

SALINA AIRPORT AUTHORITY I BTA (Continued) **S110311216**

Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	Not reported
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	Not reported
Activity End Date:	06/26/2010
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Phase I Brownfields Targeted Assessment (BTA) on 80.4 acres of vacant property located on the southwest corner of Scanlan Rd and Water Well Rd. The BTA applicant is the Salina Airport Authority, who owns the property and intends to sell/ lease the property for commercial/ industrial use. Based on the Phase I, Recognized Environmental Conditions (RECs) were discovered in connection with the BTA site as potential hazardous substances due to the historical use of the property as agricultural land since at least 1938, and the potential for historical use of pesticides and/ or herbicides. This REC, however, does not warrant the completion of a Phase II, based solely on the property site use of pesticides or herbicides at application rates per manufacturer?s instructions.

BROWNFIELDS:

Site ID:	2597
Project code:	C508572649
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
Lat/Long:	38.77089 / -97.6398
Program:	Brownfields

X108 **SALINA AIRPORT AUTHORITY II BTA** **KS SHWS** **S110311218**
South **SCANLAN RD. AND WATER WELL ROAD** **KS BROWNFIELDS** **N/A**
1/2-1 **SALINA, KS**
0.858 mi.
4532 ft. **Site 2 of 2 in cluster X**

Relative:
Higher

Actual:
1286 ft.

SHWS:

Site ID:	2598
Has Env Use Control:	No
Project code:	C508572650
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.768978 / -97.63634
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	5-25 acres
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	Not reported
Activity End Date:	06/22/2010
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Phase II Brownfields Targeted Assessment (BTA) at the Salina Airport Authority?Site II in Salina, Kansas. The BTA was conducted for the Salina Airport Authority to expedite the transfer and redevelopment of the property, which is located within the boundary of a Formally Used Defense Facility (FUD). A Phase I, dated June 3, 2010, was conducted through a Property Rede velopment Assessment (PRA) by the Formerly Used Defense Sites (FUDS)

SALINA AIRPORT AUTHORITY II BTA (Continued) **S110311218**

Installations Program. Based on the Phase I report, ?Recognized Environmental Conditions? (RECs) were identified as potential petroleum and hazardous substances associated with: historical database listings and known contamination from adjacent facilities, including but not limited to Schilling AFB Operable Unit 2 and proximal location to Schilling AFB Fire training Burn Area, Area of Interest 07 (AOI 07) to the northwest. Therefore, a Phase II was recommended to commence.

The Phase II scope of work was to collect groundwater samples from f our locations on the property. However, it become apparent during the field investigation that groundwater was not readily available. Therefore, the scope of work was modified by KDHE. One temporary piezometer was installed on the property and left overnight. After approximately 24 hours, groundwater had not entered the casing so the piezometer was removed and plugged. Due to the shallow bedrock and the absence of groundwater above a confining bedrock layer, the potential for shallow groundwater contamination at the site resulting from off-site sources is unlikely. No further assessment is being recommended at this time and the site is cleared for redevelopment.

Site ID:	2598
Has Env Use Control:	No
Project code:	C508572650
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.768978 / -97.63634
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	5-25 acres
Waste Present:	No
Product Present:	No
Program:	Brownfields
Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported

SALINA AIRPORT AUTHORITY II BTA (Continued) **S110311218**

Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	Not reported
Activity End Date:	06/22/2010
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Phase II Brownfields Targeted Assessment (BTA) at the Salina Airport Authority?Site II in Salina, Kansas. The BTA was conducted for the Salina Airport Authority to expedite the transfer and redevelopment of the property, which is located within the boundary of a Formally Used Defense Facility (FUD). A Phase I, dated June 3, 2010, was conducted through a Property Rede velopment Assessment (PRA) by the Formerly Used Defense Sites (FUDS) Installations Program. Based on the Phase I report, ?Recognized Environmental Conditions? (RECs) were identified as potential petroleum and hazardous substances associated with: historical database listings and known contamination from adjacent facilities, including but not limited to Schilling AFB Operable Unit 2 and proximal location to Schilling AFB Fire training Burn Area, Area of Interest 07 (AOI 07) to the northwest. Therefore, a Phase II was recommended to commence. The Phase II scope of work was to collect groundwater samples from f our locations on the property. However, it become apparent during the field investigation that groundwater was not readily available. Therefore, the scope of work was modified by KDHE. One temporary piezometer was installed on the property and left overnight. After approximately 24 hours, groundwater had not entered the casing so the piezometer was removed and plugged. Due to the shallow bedrock and the absence of groundwater above a confining bedrock layer, the potential for shallow groundwater contamination at the site resulting from off-site sources is unlikely. No further assessment is being recommended at this time and the site is cleared for redevelopment.
Site ID:	2598
Has Env Use Control:	No
Project code:	C508572650
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
District Office:	NCDO
Lat/Long:	38.768978 / -97.63634
River Basin:	Not reported
Aquifer Yield:	Not reported
Other Aquifers:	Not reported
Parent PC:	C508503013
Parent Name:	SCHILLING AFB (PARENT SITE)
CERCLIS ID:	Not reported
Discovery Date:	Not reported
Depth To GW:	Not reported
Depth To Bedrock:	Not reported
Aquifer Yield:	Not reported
GW Flow Direction:	Not reported
Acres Affected:	5-25 acres
Waste Present:	No
Product Present:	No
Program:	Brownfields

SALINA AIRPORT AUTHORITY II BTA (Continued) **S110311218**

Lead Agency:	BER - Redevelopment
Contaminants:	Not reported
Media Act:	Not reported
Media Pot:	Not reported
Source:	Not reported
Land Use:	Not reported
Private well:	Not reported
Waste Present:	Not reported
Product:	Not reported
Receptor Act:	Not reported
Receptor Pot:	Not reported
Remed Air:	Not reported
Remed Soil:	Not reported
Remed Water:	Not reported
Remedir:	Not reported
Alias:	Not reported
Eucan Number:	Not reported
Date:	Not reported
Activity Type:	Brownfields Targeted Assessment
Activity Status:	Completed
Activity Start Date:	Not reported
Activity End Date:	06/22/2010
Narrative:	The Kansas Department of Health and Environment (KDHE) conducted a Phase II Brownfields Targeted Assessment (BTA) at the Salina Airport Authority?Site II in Salina, Kansas. The BTA was conducted for the Salina Airport Authority to expedite the transfer and redevelopment of the property, which is located within the boundary of a Formally Used Defense Facility (FUD). A Phase I, dated June 3, 2010, was conducted through a Property Rede velopment Assessment (PRA) by the Formerly Used Defense Sites (FUDS) Installations Program. Based on the Phase I report, ?Recognized Environmental Conditions? (RECs) were identified as potential petroleum and hazardous substances associated with: historical database listings and known contamination from adjacent facilities, including but not limited to Schilling AFB Operable Unit 2 and proximal location to Schilling AFB Fire training Burn Area, Area of Interest 07 (AOI 07) to the northwest. Therefore, a Phase II was recommended to commence. The Phase II scope of work was to collect groundwater samples from f our locations on the property. However, it become apparent during the field investigation that groundwater was not readily available. Therefore, the scope of work was modified by KDHE. One temporary piezometer was installed on the property and left overnight. After approximately 24 hours, groundwater had not entered the casing so the piezometer was removed and plugged. Due to the shallow bedrock and the absence of groundwater above a confining bedrock layer, the potential for shallow groundwater contamination at the site resulting from off-site sources is unlikely. No further assessment is being recommended at this time and the site is cleared for redevelopment.

BROWNFIELDS:

Site ID:	2598
Project code:	C508572650
PM Name:	BER - REDEVELOPMENT
Site Status:	**Resolved**
Lat/Long:	38.768978 / -97.63634
Program:	Brownfields

Count: 5 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BAVARIA	S123496319	2634 MIDLAND ROAD	2634 MIDLAND ROAD	67401	KS SHWS
SALINA	S115570877	SALINA AIRPORT AUTHORITY V BTA	BERSCHEL AVE & SCANLAN RD		KS RGA HWS
SALINA	1016358736	SALINA AIRPORT AUTHORITY V BTA	BERSCHEL AVE & SCANLAN RD	67401	FINDS
SALINA	1007477397	SAA HYDRANT PIT 2-F	SALINA MUNICIPAL AIRPORT	67401	KS LUST
SALINA	S115571533	SALINA AIRPORT AUTHORITY IV BTA	VORTEX AVE & SCANLAN RD		KS RGA HWS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 07/19/2019
Date Data Arrived at EDR: 07/30/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 35

Source: EPA
Telephone: N/A
Last EDR Contact: 07/30/2019
Next Scheduled EDR Contact: 10/14/2019
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 10
Telephone 206-553-8665

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 07/19/2019
Date Data Arrived at EDR: 07/30/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 35

Source: EPA
Telephone: N/A
Last EDR Contact: 07/30/2019
Next Scheduled EDR Contact: 10/14/2019
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 07/19/2019
Date Data Arrived at EDR: 07/30/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 35

Source: EPA
Telephone: N/A
Last EDR Contact: 07/30/2019
Next Scheduled EDR Contact: 10/14/2019
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 04/03/2019
Date Data Arrived at EDR: 04/05/2019
Date Made Active in Reports: 05/14/2019
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 07/03/2019
Next Scheduled EDR Contact: 10/14/2019
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 07/19/2019
Date Data Arrived at EDR: 07/30/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 35

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 07/30/2019
Next Scheduled EDR Contact: 10/28/2019
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 07/19/2019
Date Data Arrived at EDR: 07/30/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 35

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 07/30/2019
Next Scheduled EDR Contact: 10/28/2019
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/25/2019
Date Data Arrived at EDR: 03/27/2019
Date Made Active in Reports: 04/17/2019
Number of Days to Update: 21

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/26/2019
Next Scheduled EDR Contact: 10/07/2019
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/25/2019
Date Data Arrived at EDR: 03/27/2019
Date Made Active in Reports: 04/17/2019
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: 913-551-7003
Last EDR Contact: 06/26/2019
Next Scheduled EDR Contact: 10/07/2019
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/25/2019
Date Data Arrived at EDR: 03/27/2019
Date Made Active in Reports: 04/17/2019
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: 913-551-7003
Last EDR Contact: 06/26/2019
Next Scheduled EDR Contact: 10/07/2019
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/25/2019
Date Data Arrived at EDR: 03/27/2019
Date Made Active in Reports: 04/17/2019
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: 913-551-7003
Last EDR Contact: 06/26/2019
Next Scheduled EDR Contact: 10/07/2019
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/25/2019
Date Data Arrived at EDR: 03/27/2019
Date Made Active in Reports: 04/17/2019
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: 913-551-7003
Last EDR Contact: 06/26/2019
Next Scheduled EDR Contact: 10/07/2019
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 08/13/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 08/26/2019
Number of Days to Update: 6

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 08/07/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 08/19/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 08/26/2019
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/20/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 08/19/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 08/26/2019
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/20/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 03/25/2019
Date Data Arrived at EDR: 03/26/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 36

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 06/26/2019
Next Scheduled EDR Contact: 10/07/2019
Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

SHWS: Identified Sites List

State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 04/08/2019
Date Data Arrived at EDR: 04/11/2019
Date Made Active in Reports: 05/06/2019
Number of Days to Update: 25

Source: Department of Health and Environment
Telephone: 785-296-1660
Last EDR Contact: 07/03/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: Quarterly

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Directory of Sanitary Landfills, Solid Waste Transfer Stations and Collector in Kansas

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 04/01/2019
Date Data Arrived at EDR: 04/03/2019
Date Made Active in Reports: 05/06/2019
Number of Days to Update: 33

Source: Department of Health and Environment
Telephone: 785-296-1590
Last EDR Contact: 07/12/2019
Next Scheduled EDR Contact: 10/28/2019
Data Release Frequency: Annually

CITY DUMPS: City Dump Listing

The City Dump Cleanup Program provides funds to cities or counties for the repair of old, unused municipal dump sites. These sites primarily operated between the 1940s and the 1970s before many counties had landfills and prior to the current regulations for solid waste disposal.

Date of Government Version: 05/28/2019
Date Data Arrived at EDR: 05/29/2019
Date Made Active in Reports: 07/22/2019
Number of Days to Update: 54

Source: Department of Health & Environment
Telephone: 785-296-6377
Last EDR Contact: 08/27/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: Varies

State and tribal leaking storage tank lists

LAST: Leaking Aboveground Storage Tanks

Leaking aboveground storage tank site locations.

Date of Government Version: 04/01/2019
Date Data Arrived at EDR: 04/03/2019
Date Made Active in Reports: 05/06/2019
Number of Days to Update: 33

Source: Department of Health & Environment
Telephone: 785-296-1685
Last EDR Contact: 07/19/2019
Next Scheduled EDR Contact: 10/14/2019
Data Release Frequency: Quarterly

LUST: Leaking Underground Storage Tank Data

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 04/01/2019
Date Data Arrived at EDR: 04/03/2019
Date Made Active in Reports: 05/06/2019
Number of Days to Update: 33

Source: Department of Health and Environment
Telephone: 785-296-1685
Last EDR Contact: 07/19/2019
Next Scheduled EDR Contact: 10/14/2019
Data Release Frequency: Quarterly

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 10/12/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 10/10/2018
Date Data Arrived at EDR: 03/08/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 54

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 10/17/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 10/16/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 02/19/2019
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 11/01/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 09/24/2018
Date Data Arrived at EDR: 03/12/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 50
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 07/23/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 10/13/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 05/15/2017
Date Data Arrived at EDR: 05/30/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 136
Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 08/26/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: Varies

UST: Underground Storage Tank Data
Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 04/01/2019
Date Data Arrived at EDR: 04/03/2019
Date Made Active in Reports: 05/03/2019
Number of Days to Update: 30
Source: Department of Health and Environment
Telephone: 785-296-1685
Last EDR Contact: 06/26/2019
Next Scheduled EDR Contact: 10/14/2019
Data Release Frequency: Quarterly

AST: Aboveground Storage Tank Data
Registered Aboveground Storage Tanks.

Date of Government Version: 04/01/2019
Date Data Arrived at EDR: 04/03/2019
Date Made Active in Reports: 05/03/2019
Number of Days to Update: 30
Source: Department of Health and Environment
Telephone: 785-296-1685
Last EDR Contact: 06/26/2019
Next Scheduled EDR Contact: 10/14/2019
Data Release Frequency: Quarterly

INDIAN UST R7: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 11/07/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 10/12/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/05/2019
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 10/16/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 08/05/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 10/10/2018
Date Data Arrived at EDR: 03/08/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 54

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 10/17/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 10/03/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 09/24/2018
Date Data Arrived at EDR: 03/12/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 50

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 07/23/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 11/01/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

INST CONTROL: Institutional Controls Information

Sites that have institutional control information entered into the Identified Sites List database.

Date of Government Version: 04/08/2019
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/06/2019
Number of Days to Update: 26

Source: Department of Health & Environment
Telephone: 785-296-8049
Last EDR Contact: 07/03/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: Quarterly

State and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 06/20/2019
Next Scheduled EDR Contact: 10/07/2019
Data Release Frequency: Varies

VCP: Identified Sites List

Sites included in the Identified Sites List that are identified as Voluntary Cleanup sites.

Date of Government Version: 04/08/2019
Date Data Arrived at EDR: 04/11/2019
Date Made Active in Reports: 05/06/2019
Number of Days to Update: 25

Source: Department of Health & Environment
Telephone: 785-296-8049
Last EDR Contact: 07/03/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: Quarterly

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Identified Sites List

Sites included in the Identified Sites List that are identified as Brownfields sites.

Date of Government Version: 04/08/2019
Date Data Arrived at EDR: 04/11/2019
Date Made Active in Reports: 05/06/2019
Number of Days to Update: 25

Source: Department of Health & Environment
Telephone: 785-296-8049
Last EDR Contact: 07/03/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 06/03/2019
Date Data Arrived at EDR: 06/04/2019
Date Made Active in Reports: 08/26/2019
Number of Days to Update: 83

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 06/04/2019
Next Scheduled EDR Contact: 09/30/2019
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 07/25/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/19/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 08/02/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

AOCONCERN: Area of Concern

The City of Wichita has taken the lead for the investigation and remediation efforts with the Kansas Department of Health & Environment, Bureau of Remediation. The primary contaminates of concern are chlorinated solvents and their degradation products.

Date of Government Version: N/A
Date Data Arrived at EDR: 04/25/2002
Date Made Active in Reports: 06/28/2002
Number of Days to Update: 64

Source: Department of Environmental Health
Telephone: 315-268-8351
Last EDR Contact: 03/13/2007
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 06/11/2019
Date Data Arrived at EDR: 06/13/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/21/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: No Update Planned

CDL: Clandestine Laboratory Data

Clandestine meth lab location

Date of Government Version: 08/09/2018
Date Data Arrived at EDR: 08/09/2018
Date Made Active in Reports: 09/12/2018
Number of Days to Update: 34

Source: Department of Health and Environment
Telephone: 785-368-7301
Last EDR Contact: 08/07/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: No Update Planned

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 06/11/2019
Date Data Arrived at EDR: 06/13/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/21/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: Quarterly

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 07/30/2019
Date Data Arrived at EDR: 07/30/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 35

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 07/30/2019
Next Scheduled EDR Contact: 10/14/2019
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/25/2019
Date Data Arrived at EDR: 03/26/2019
Date Made Active in Reports: 05/14/2019
Number of Days to Update: 49

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 06/26/2019
Next Scheduled EDR Contact: 10/07/2019
Data Release Frequency: Quarterly

SPILLS: Kansas Spills Database

All spills reported under the regulatory authority of the Department of Health & Environment and the Kansas Corporation Commission.

Date of Government Version: 04/05/2019
Date Data Arrived at EDR: 04/09/2019
Date Made Active in Reports: 05/06/2019
Number of Days to Update: 27

Source: Department of Health and Environment
Telephone: 785-296-1660
Last EDR Contact: 07/03/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: Semi-Annually

SPILLS 2: Spills Database

All spills reported under the regulatory authority of the Kansas Corporation Commission.

Date of Government Version: 04/11/2019
Date Data Arrived at EDR: 04/16/2019
Date Made Active in Reports: 05/06/2019
Number of Days to Update: 20

Source: Kansas Corporation Commission
Telephone: 316-337-6626
Last EDR Contact: 07/03/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: Varies

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/25/2019
Date Data Arrived at EDR: 03/27/2019
Date Made Active in Reports: 04/17/2019
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: 913-551-7003
Last EDR Contact: 06/26/2019
Next Scheduled EDR Contact: 10/07/2019
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 05/15/2019
Date Data Arrived at EDR: 05/21/2019
Date Made Active in Reports: 08/08/2019
Number of Days to Update: 79

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 08/23/2019
Next Scheduled EDR Contact: 12/02/2019
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/09/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/10/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 08/16/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 03/25/2019
Date Data Arrived at EDR: 03/26/2019
Date Made Active in Reports: 05/07/2019
Number of Days to Update: 42

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 06/26/2019
Next Scheduled EDR Contact: 10/07/2019
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 08/05/2019
Next Scheduled EDR Contact: 11/18/2019
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 08/09/2019
Next Scheduled EDR Contact: 11/18/2019
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/21/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 198

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/18/2019
Next Scheduled EDR Contact: 09/30/2019
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 01/10/2018
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 2

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 08/23/2019
Next Scheduled EDR Contact: 12/02/2019
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 09/30/2018
Date Data Arrived at EDR: 04/24/2019
Date Made Active in Reports: 08/08/2019
Number of Days to Update: 106

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 07/26/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 07/19/2019
Date Data Arrived at EDR: 07/30/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 35

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 07/30/2019
Next Scheduled EDR Contact: 09/16/2019
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/25/2019
Date Data Arrived at EDR: 05/02/2019
Date Made Active in Reports: 05/23/2019
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 07/22/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 04/11/2019
Date Data Arrived at EDR: 04/18/2019
Date Made Active in Reports: 05/23/2019
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 07/30/2019
Next Scheduled EDR Contact: 11/18/2019
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 03/20/2019
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/14/2019
Number of Days to Update: 34

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/12/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 07/03/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 06/20/2019
Date Data Arrived at EDR: 06/20/2019
Date Made Active in Reports: 08/08/2019
Number of Days to Update: 49
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 07/22/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 06/07/2019
Next Scheduled EDR Contact: 09/16/2019
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 09/03/2019
Next Scheduled EDR Contact: 12/16/2019
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 05/24/2017
Date Data Arrived at EDR: 11/30/2017
Date Made Active in Reports: 12/15/2017
Number of Days to Update: 15
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 08/09/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 04/02/2019
Date Data Arrived at EDR: 04/02/2019
Date Made Active in Reports: 05/14/2019
Number of Days to Update: 42

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 07/01/2019
Next Scheduled EDR Contact: 10/14/2019
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 04/01/2019
Date Data Arrived at EDR: 04/30/2019
Date Made Active in Reports: 08/08/2019
Number of Days to Update: 100

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 07/31/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 03/31/2019
Date Data Arrived at EDR: 04/23/2019
Date Made Active in Reports: 05/23/2019
Number of Days to Update: 30

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 07/08/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 09/28/2017
Number of Days to Update: 218

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 06/26/2019
Next Scheduled EDR Contact: 10/07/2019
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 07/10/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 08/08/2017
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 07/30/2019
Next Scheduled EDR Contact: 11/18/2019
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 06/23/2017
Date Data Arrived at EDR: 10/11/2017
Date Made Active in Reports: 11/03/2017
Number of Days to Update: 23

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 08/21/2019
Next Scheduled EDR Contact: 12/02/2019
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 07/19/2019
Date Data Arrived at EDR: 07/30/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 35

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 07/30/2019
Next Scheduled EDR Contact: 10/14/2019
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 05/03/2019
Date Data Arrived at EDR: 05/29/2019
Date Made Active in Reports: 08/08/2019
Number of Days to Update: 71

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 08/27/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 12/05/2005
Date Data Arrived at EDR: 02/29/2008
Date Made Active in Reports: 04/18/2008
Number of Days to Update: 49

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/30/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/30/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 03/27/2019
Date Data Arrived at EDR: 03/28/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 34

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 08/27/2019
Next Scheduled EDR Contact: 09/23/2019
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 05/03/2019
Date Data Arrived at EDR: 06/05/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 90

Source: EPA
Telephone: (913) 551-7003
Last EDR Contact: 06/05/2019
Next Scheduled EDR Contact: 09/16/2019
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 07/26/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 71

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 08/21/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: Varies

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 01/17/2019
Date Made Active in Reports: 04/01/2019
Number of Days to Update: 74

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 07/15/2019
Next Scheduled EDR Contact: 10/28/2019
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 04/07/2019
Date Data Arrived at EDR: 04/09/2019
Date Made Active in Reports: 05/23/2019
Number of Days to Update: 44

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 07/09/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 05/20/2019
Date Data Arrived at EDR: 05/21/2019
Date Made Active in Reports: 08/08/2019
Number of Days to Update: 79

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 08/20/2019
Next Scheduled EDR Contact: 12/02/2019
Data Release Frequency: Quarterly

AIRS: Title V Source Information

A listing of title V sources, including emissions information.

Date of Government Version: 05/28/2018
Date Data Arrived at EDR: 02/26/2019
Date Made Active in Reports: 05/06/2019
Number of Days to Update: 69

Source: Department of Health & Environment
Telephone: 785-296-6427
Last EDR Contact: 06/20/2019
Next Scheduled EDR Contact: 10/07/2019
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal combustion waste landfills.

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 04/17/2018
Date Made Active in Reports: 05/31/2018
Number of Days to Update: 44

Source: Department of Health & Environment
Telephone: 785-296-1600
Last EDR Contact: 07/31/2019
Next Scheduled EDR Contact: 10/28/2019
Data Release Frequency: Varies

DRYCLEANERS: Registered Drycleaning Facilities
A listing of registered drycleaners.

Date of Government Version: 06/05/2019
Date Data Arrived at EDR: 06/06/2019
Date Made Active in Reports: 07/22/2019
Number of Days to Update: 46

Source: Department of Health & Environment
Telephone: 785-291-3250
Last EDR Contact: 08/21/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: Varies

Financial Assurance: Financial Assurance Information Listing
A listing of financial assurance information for underground storage tank facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 04/01/2019
Date Data Arrived at EDR: 04/03/2019
Date Made Active in Reports: 05/03/2019
Number of Days to Update: 30

Source: Department of Health & Environment
Telephone: 785-296-1685
Last EDR Contact: 06/26/2019
Next Scheduled EDR Contact: 10/14/2019
Data Release Frequency: Quarterly

NPDES: Wastewater Permit Listing
A listing of facilities with wastewater permits.

Date of Government Version: 06/12/2019
Date Data Arrived at EDR: 06/14/2019
Date Made Active in Reports: 07/30/2019
Number of Days to Update: 46

Source: Department of Health & Environment
Telephone: 785-296-5517
Last EDR Contact: 06/17/2019
Next Scheduled EDR Contact: 09/30/2019
Data Release Frequency: Varies

TIER 2: Tier 2 Information Listing
A listing of facilities which store or manufacture hazardous materials and submit a chemical inventory report.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 06/19/2018
Date Made Active in Reports: 07/18/2018
Number of Days to Update: 29

Source: Department of Health & Environment
Telephone: 785-296-1688
Last EDR Contact: 07/11/2019
Next Scheduled EDR Contact: 09/30/2019
Data Release Frequency: Annually

UIC: Underground Injection Wells Database Listing
A listing of underground injection wells.

Date of Government Version: 03/15/2019
Date Data Arrived at EDR: 03/19/2019
Date Made Active in Reports: 05/06/2019
Number of Days to Update: 48

Source: Department of Health & Environment
Telephone: 785-296-1367
Last EDR Contact: 07/22/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Health and Environment in Kansas.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/03/2014
Number of Days to Update: 186

Source: Department of Health and Environment
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Health and Environment in Kansas.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/20/2014
Number of Days to Update: 203

Source: Department of Health and Environment
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank

The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Health and Environment in Kansas.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/03/2014
Number of Days to Update: 186

Source: Department of Health and Environment
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 05/14/2019
Date Data Arrived at EDR: 05/14/2019
Date Made Active in Reports: 08/05/2019
Number of Days to Update: 83

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 08/07/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 05/01/2019
Date Made Active in Reports: 06/21/2019
Number of Days to Update: 51

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: Quarterly

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 02/23/2018
Date Made Active in Reports: 04/09/2018
Number of Days to Update: 45

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/16/2019
Next Scheduled EDR Contact: 12/02/2019
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 06/10/2019
Next Scheduled EDR Contact: 09/23/2019
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: PennWell Corporation
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Electric Power Transmission Line Data
Source: PennWell Corporation
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: US Fish & Wildlife Service
Telephone: 703-358-2171

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

SALINA AASF
2917 HEIN AVENUE
SALINA, KS 67401

TARGET PROPERTY COORDINATES

Latitude (North):	38.78504 - 38° 47' 6.14''
Longitude (West):	97.63747 - 97° 38' 14.89''
Universal Tranverse Mercator:	Zone 14
UTM X (Meters):	618345.4
UTM Y (Meters):	4293596.5
Elevation:	1256 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5691529 SALINA SW, KS
Version Date:	2012
Northeast Map:	5691501 SALINA, KS
Version Date:	2012

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General East

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
2003190015B	FEMA Q3 Flood data

Additional Panels in search area:	FEMA Source Type
2003160070B	FEMA Q3 Flood data
2003160090B	FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
NOT AVAILABLE	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Paleozoic
System:	Permian
Series:	Lower part of Leonardian Series
Code:	P2a *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratifed Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 5776851.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	Salina AASF	CLIENT:	AECOM
ADDRESS:	2917 Hein Avenue Salina KS 67401	CONTACT:	Hans Sund
LAT/LONG:	38.78504 / 97.63747	INQUIRY #:	5776851.2s
		DATE:	September 04, 2019 5:14 pm

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Crete

Soil Surface Texture: silt loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Moderately well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	7 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 14.11 Min: 1.411	Max: 8.4 Min: 7.4
2	7 inches	14 inches	silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 14.11 Min: 1.411	Max: 8.4 Min: 7.4
3	14 inches	33 inches	silty clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 14.11 Min: 1.411	Max: 8.4 Min: 7.4
4	33 inches	59 inches	silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 14.11 Min: 1.411	Max: 8.4 Min: 7.4

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	KS9000000110454	0 - 1/8 Mile WSW
A2	KS9000000093949	1/4 - 1/2 Mile East
A3	KS9000000093947	1/4 - 1/2 Mile East
A4	KS9000000094644	1/4 - 1/2 Mile East
A5	KS9000000093952	1/4 - 1/2 Mile East
B6	KS9000000252781	1/4 - 1/2 Mile ENE
B7	KS9000000252782	1/4 - 1/2 Mile ENE
C8	KS9000000059866	1/4 - 1/2 Mile SW
C9	KS9000000059867	1/4 - 1/2 Mile SW
C10	KS9000000059863	1/4 - 1/2 Mile SW
C11	KS9000000059865	1/4 - 1/2 Mile SW
C12	KS9000000059870	1/4 - 1/2 Mile SW
C13	KS9000000059871	1/4 - 1/2 Mile SW
C14	KS9000000059868	1/4 - 1/2 Mile SW
C15	KS9000000059869	1/4 - 1/2 Mile SW
A16	KS9000000252632	1/4 - 1/2 Mile ESE
D17	KS9000000110435	1/4 - 1/2 Mile NNW
D18	KS9000000110436	1/4 - 1/2 Mile NNW
D19	KS9000000110437	1/4 - 1/2 Mile NNW
E20	KS9000000245048	1/4 - 1/2 Mile SSE

STATE DATABASE WELL INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
E21	KS9000000245049	1/4 - 1/2 Mile SSE
E22	KS9000000245046	1/4 - 1/2 Mile SSE
E23	KS9000000245047	1/4 - 1/2 Mile SSE
E24	KS9000000245053	1/4 - 1/2 Mile SSE
E25	KS9000000245054	1/4 - 1/2 Mile SSE
E26	KS9000000245050	1/4 - 1/2 Mile SSE
E27	KS9000000245051	1/4 - 1/2 Mile SSE
F28	KS9000000108758	1/4 - 1/2 Mile SW
F29	KS9000000227899	1/4 - 1/2 Mile SW
30	KS9000000059471	1/4 - 1/2 Mile East
31	KS9000000260865	1/4 - 1/2 Mile ENE
32	KS9000000110434	1/4 - 1/2 Mile NW
G33	KS9000000249122	1/4 - 1/2 Mile WNW
G34	KS9000000249121	1/4 - 1/2 Mile WNW
G35	KS9000000249120	1/4 - 1/2 Mile WNW
G36	KS9000000249125	1/4 - 1/2 Mile WNW
G37	KS9000000249124	1/4 - 1/2 Mile WNW
G38	KS9000000249123	1/4 - 1/2 Mile WNW
39	KS9000000094019	1/4 - 1/2 Mile North
H40	KS9000000110438	1/4 - 1/2 Mile NNW
H41	KS9000000096445	1/4 - 1/2 Mile NNW
H42	KS9000000115654	1/4 - 1/2 Mile NNW
H43	KS9000000193448	1/4 - 1/2 Mile NNW
H44	KS9000000193447	1/4 - 1/2 Mile NNW
H45	KS9000000094032	1/4 - 1/2 Mile NNW
H46	KS9000000094030	1/4 - 1/2 Mile NNW
H47	KS9000000094038	1/4 - 1/2 Mile NNW
H48	KS9000000096444	1/4 - 1/2 Mile NNW
H49	KS9000000096443	1/4 - 1/2 Mile NNW
H50	KS9000000193449	1/4 - 1/2 Mile NNW
H51	KS9000000225550	1/4 - 1/2 Mile NNW
H52	KS9000000225549	1/4 - 1/2 Mile NNW
H53	KS9000000225551	1/4 - 1/2 Mile NNW
H54	KS9000000225553	1/4 - 1/2 Mile NNW
H55	KS9000000225552	1/4 - 1/2 Mile NNW
H56	KS9000000225545	1/4 - 1/2 Mile NNW
H57	KS9000000225544	1/4 - 1/2 Mile NNW
H58	KS9000000225546	1/4 - 1/2 Mile NNW
H59	KS9000000225548	1/4 - 1/2 Mile NNW
H60	KS9000000225547	1/4 - 1/2 Mile NNW
61	KS9000000115652	1/4 - 1/2 Mile NNE
62	KS9000000115656	1/4 - 1/2 Mile NW
63	KS9000000059472	1/2 - 1 Mile NE
I64	KS9000000094034	1/2 - 1 Mile North
I65	KS9000000094028	1/2 - 1 Mile North
I66	KS9000000115653	1/2 - 1 Mile North
I67	KS9000000094036	1/2 - 1 Mile North
J68	KS9000000110439	1/2 - 1 Mile North
J69	KS9000000094025	1/2 - 1 Mile North
J70	KS9000000115655	1/2 - 1 Mile North
J71	KS9000000110444	1/2 - 1 Mile North
K72	KS9000000108757	1/2 - 1 Mile NNE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
K73	KS9000000115650	1/2 - 1 Mile NNE
L74	KS9000000110440	1/2 - 1 Mile NNW
L75	KS9000000110441	1/2 - 1 Mile NNW
I76	KS9000000253581	1/2 - 1 Mile North
77	KS9000000091434	1/2 - 1 Mile South
78	KS9000000091433	1/2 - 1 Mile SSE
79	KS9000000128134	1/2 - 1 Mile WNW
M80	KS9000000110448	1/2 - 1 Mile North
M81	KS9000000110449	1/2 - 1 Mile North
M82	KS9000000145972	1/2 - 1 Mile North
N83	KS9000000110426	1/2 - 1 Mile SSE
N84	KS9000000115643	1/2 - 1 Mile SSE
O85	KS9000000110445	1/2 - 1 Mile North
O86	KS9000000110457	1/2 - 1 Mile North
O87	KS9000000214971	1/2 - 1 Mile North
P88	KS9000000110443	1/2 - 1 Mile NNW
P89	KS9000000110442	1/2 - 1 Mile NNW
P90	KS9000000162231	1/2 - 1 Mile NNW
P91	KS9000000110447	1/2 - 1 Mile NNW
Q92	KS9000000110446	1/2 - 1 Mile NNE
Q93	KS9000000115651	1/2 - 1 Mile NNE
94	KS9000000175179	1/2 - 1 Mile East
R95	KS9000000091430	1/2 - 1 Mile South
R96	KS9000000153731	1/2 - 1 Mile South
S97	KS9000000091436	1/2 - 1 Mile South
S98	KS9000000091438	1/2 - 1 Mile South
99	KS9000000059864	1/2 - 1 Mile SW
T100	KS9000000110452	1/2 - 1 Mile North
T101	KS9000000110453	1/2 - 1 Mile North
U102	KS9000000110451	1/2 - 1 Mile North
U103	KS9000000214970	1/2 - 1 Mile North
V104	KS9000000115649	1/2 - 1 Mile North
V105	KS9000000115665	1/2 - 1 Mile North
106	KS9000000245052	1/2 - 1 Mile South
107	KS9000000110450	1/2 - 1 Mile NNW
108	KS9000000091431	1/2 - 1 Mile SSW
W109	KS9000000153349	1/2 - 1 Mile NNE
W110	KS9000000153350	1/2 - 1 Mile NNE
W111	KS9000000154317	1/2 - 1 Mile NNE
112	KS9000000108752	1/2 - 1 Mile SW
113	KS9000000131945	1/2 - 1 Mile ENE
X114	KS9000000108750	1/2 - 1 Mile WSW
X115	KS9000000108751	1/2 - 1 Mile WSW
116	KS9000000115664	1/2 - 1 Mile North
117	KS9000000153352	1/2 - 1 Mile NNE
118	KS9000000245056	1/2 - 1 Mile WSW
119	KS9000000108759	1/2 - 1 Mile NNW

PHYSICAL SETTING SOURCE MAP - 5776851.2s



- County Boundary
- Major Roads
- Contour Lines
- Airports
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- Oil, gas or related wells

SITE NAME: Salina AASF	CLIENT: AECOM
ADDRESS: 2917 Hein Avenue Salina KS 67401	CONTACT: Hans Sund INQUIRY #: 5776851.2s
LAT/LONG: 38.78504 / 97.63747	DATE: September 04, 2019 5:14 pm

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
WSW
0 - 1/8 Mile
Higher

KS WELLS **KS9000000110454**

Well ID:	113043	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	06-Dec-1996
DWR #:	0	Well Depth:	23.4
Elevation:	0	Static Depth to Water:	6.9
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113043		

A2
East
1/4 - 1/2 Mile
Lower

KS WELLS **KS9000000093949**

Well ID:	96172	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	21-Dec-1994
DWR #:	0	Well Depth:	20
Elevation:	1249	Static Depth to Water:	10.5
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=96172		

A3
East
1/4 - 1/2 Mile
Lower

KS WELLS **KS9000000093947**

Well ID:	96170	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	21-Dec-1994
DWR #:	0	Well Depth:	20
Elevation:	1250	Static Depth to Water:	9.7
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=96170		

A4
East
1/4 - 1/2 Mile
Lower

KS WELLS **KS9000000094644**

Well ID:	96877	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	21-Dec-1994
DWR #:	0	Well Depth:	20
Elevation:	1250	Static Depth to Water:	8.4
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=96877		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A5
East
1/4 - 1/2 Mile
Lower

KS WELLS **KS9000000093952**

Well ID:	96175	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	21-Dec-1994
DWR #:	0	Well Depth:	20
Elevation:	1250	Static Depth to Water:	10.1
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=96175		

B6
ENE
1/4 - 1/2 Mile
Lower

KS WELLS **KS9000000252781**

Well ID:	491171	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	29-Jun-2015
DWR #:	0	Well Depth:	50
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Plains Environmental Services
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=491171		

B7
ENE
1/4 - 1/2 Mile
Lower

KS WELLS **KS9000000252782**

Well ID:	491172	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	29-Jun-2015
DWR #:	0	Well Depth:	35
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Plains Environmental Services
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=491172		

C8
SW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000059866**

Well ID:	60740	Owner:	PONY EXPRESS
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	07-Jun-1991
DWR #:	0	Well Depth:	13
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=60740		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

C9
SW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000059867**

Well ID:	60741	Owner:	PONY EXPRESS
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	07-Jun-1991
DWR #:	0	Well Depth:	13
Elevation:	0	Static Depth to Water:	5
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=60741		

C10
SW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000059863**

Well ID:	60737	Owner:	PONY EXPRESS
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	11-Jun-1991
DWR #:	0	Well Depth:	25
Elevation:	0	Static Depth to Water:	5
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=60737		

C11
SW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000059865**

Well ID:	60739	Owner:	PONY EXPRESS
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	07-Jun-1991
DWR #:	0	Well Depth:	13
Elevation:	0	Static Depth to Water:	5
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=60739		

C12
SW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000059870**

Well ID:	60744	Owner:	PONY EXPR CR CO
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	07-Jun-1991
DWR #:	0	Well Depth:	13
Elevation:	0	Static Depth to Water:	5
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=60744		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

C13
SW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000059871**

Well ID:	60745	Owner:	PONY EXPRESS
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	07-Jun-1991
DWR #:	0	Well Depth:	25
Elevation:	0	Static Depth to Water:	5
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=60745		

C14
SW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000059868**

Well ID:	60742	Owner:	PONY EXPRSS COU
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	07-Jun-1991
DWR #:	0	Well Depth:	13
Elevation:	0	Static Depth to Water:	6
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=60742		

C15
SW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000059869**

Well ID:	60743	Owner:	PONY EXPRSS COR
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	07-Jun-1991
DWR #:	0	Well Depth:	13
Elevation:	0	Static Depth to Water:	5
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=60743		

A16
ESE
1/4 - 1/2 Mile
Lower

KS WELLS **KS9000000252632**

Well ID:	500610		
Owner:	Wallerius, Patrick/AFK Properties LLC		
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	21-Jun-2016
DWR #:	0	Well Depth:	20
Elevation:	1249.7	Static Depth to Water:	7.31
Est Yield:	0	Driller:	Associated Environmental, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=500610		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

D17
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000110435**

Well ID:	113024	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	30-Oct-1996
DWR #:	0	Well Depth:	9.4
Elevation:	0	Static Depth to Water:	7
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113024		

D18
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000110436**

Well ID:	113025	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	30-Oct-1996
DWR #:	0	Well Depth:	20.4
Elevation:	0	Static Depth to Water:	15.1
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113025		

D19
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000110437**

Well ID:	113026	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	04-Dec-1996
DWR #:	0	Well Depth:	5.9
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113026		

E20
SSE
1/4 - 1/2 Mile
Lower

KS WELLS **KS9000000245048**

Well ID:	485798	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	16-Oct-2014
DWR #:	0	Well Depth:	50
Elevation:	1257.49	Static Depth to Water:	12
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=485798		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

E21
SSE
1/4 - 1/2 Mile
Lower

KS WELLS **KS9000000245049**

Well ID:	485799	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	20-Oct-2014
DWR #:	0	Well Depth:	17
Elevation:	1257.59	Static Depth to Water:	12
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=485799		

E22
SSE
1/4 - 1/2 Mile
Lower

KS WELLS **KS9000000245046**

Well ID:	485796	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	16-Oct-2014
DWR #:	0	Well Depth:	19
Elevation:	1258.56	Static Depth to Water:	12
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=485796		

E23
SSE
1/4 - 1/2 Mile
Lower

KS WELLS **KS9000000245047**

Well ID:	485797	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	16-Oct-2014
DWR #:	0	Well Depth:	38
Elevation:	1258.49	Static Depth to Water:	12
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=485797		

E24
SSE
1/4 - 1/2 Mile
Lower

KS WELLS **KS9000000245053**

Well ID:	485803	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	27-Oct-2014
DWR #:	0	Well Depth:	25
Elevation:	1250.58	Static Depth to Water:	12
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		

URL: http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=485803

E25
SSE **KS WELLS** **KS9000000245054**
1/4 - 1/2 Mile
Lower

Well ID:	485804	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	04-Nov-2014
DWR #:	0	Well Depth:	21
Elevation:	1280.59	Static Depth to Water:	12
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=485804		

E26
SSE **KS WELLS** **KS9000000245050**
1/4 - 1/2 Mile
Lower

Well ID:	485800	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	20-Oct-2014
DWR #:	0	Well Depth:	27
Elevation:	1257.55	Static Depth to Water:	12
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=485800		

E27
SSE **KS WELLS** **KS9000000245051**
1/4 - 1/2 Mile
Lower

Well ID:	485801	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	20-Oct-2014
DWR #:	0	Well Depth:	37
Elevation:	1257.72	Static Depth to Water:	12
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=485801		

F28
SW **KS WELLS** **KS9000000108758**
1/4 - 1/2 Mile
Higher

Well ID:	111332	Owner:	U.S. Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	21-Oct-1996
DWR #:	0	Well Depth:	19.5
Elevation:	0	Static Depth to Water:	7.15

Est Yield:	0	Driller:	Not Reported
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=111332		

F29
SW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000227899**

Well ID:	454524	Owner:	US Army Corps of Eng
Well Use:	Monitoring well/observation/piezometer		
Status:	PLUGGED	Completion Date:	26-Apr-2012
DWR #:	0	Well Depth:	19.5
Elevation:	0	Static Depth to Water:	7.5
Est Yield:	0	Driller:	Plains Environmental Services
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=454524		

30
East
1/4 - 1/2 Mile
Lower

KS WELLS **KS9000000059471**

Well ID:	60345	Owner:	Western Resources
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	14-Mar-1994
DWR #:	0	Well Depth:	22
Elevation:	0	Static Depth to Water:	12
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=60345		

31
ENE
1/4 - 1/2 Mile
Lower

KS WELLS **KS9000000260865**

Well ID:	478972	Owner:	Storage Mart, LLC
Well Use:	Lawn and Garden - domestic only		
Status:	CONSTRUCTED	Completion Date:	30-Jun-2014
DWR #:	0	Well Depth:	45.5
Elevation:	1238	Static Depth to Water:	10
Est Yield:	15	Driller:	Peterson Irrigation, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=478972		

32
NW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000110434**

Well ID:	113023	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	06-Dec-1996
DWR #:	0	Well Depth:	5.3
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113023		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G33
WNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000249122**

Well ID:	485599	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	15-Oct-2014
DWR #:	0	Well Depth:	26
Elevation:	1250.12	Static Depth to Water:	12
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=485599		

G34
WNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000249121**

Well ID:	485598	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	15-Oct-2014
DWR #:	0	Well Depth:	35
Elevation:	1252.58	Static Depth to Water:	12
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=485598		

G35
WNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000249120**

Well ID:	485597	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	15-Oct-2014
DWR #:	0	Well Depth:	25
Elevation:	1252.58	Static Depth to Water:	12
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=485597		

G36
WNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000249125**

Well ID:	485602	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	15-Oct-2014
DWR #:	0	Well Depth:	34
Elevation:	1257.82	Static Depth to Water:	12
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		

URL: http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=485602

G37
WNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000249124**

Well ID:	485601	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	15-Oct-2014
DWR #:	0	Well Depth:	23
Elevation:	1257.91	Static Depth to Water:	12
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=485601		

G38
WNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000249123**

Well ID:	485600	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	15-Oct-2014
DWR #:	0	Well Depth:	39
Elevation:	1250.12	Static Depth to Water:	12
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=485600		

39
North
1/4 - 1/2 Mile
Lower

KS WELLS **KS9000000094019**

Well ID:	96242	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	08-Dec-1994
DWR #:	0	Well Depth:	23
Elevation:	0	Static Depth to Water:	8.3
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=96242		

H40
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000110438**

Well ID:	113027	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	08-Nov-1996
DWR #:	0	Well Depth:	13.2
Elevation:	0	Static Depth to Water:	8.5
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.

URL: http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113027

H41
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000096445**

Well ID:	98708	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	23-Mar-1995
DWR #:	0	Well Depth:	26
Elevation:	0	Static Depth to Water:	6.5
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=98708		

H42
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000115654**

Well ID:	118354	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	05-Aug-1997
DWR #:	0	Well Depth:	22
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=118354		

H43
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000193448**

Well ID:	407089	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	PLUGGED	Completion Date:	06-Aug-2007
DWR #:	0	Well Depth:	17.5
Elevation:	0	Static Depth to Water:	8.71
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=407089		

H44
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000193447**

Well ID:	407088	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	PLUGGED	Completion Date:	06-Aug-2007
DWR #:	0	Well Depth:	29.3
Elevation:	0	Static Depth to Water:	8.93
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=407088		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H45
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000094032**

Well ID:	96255	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	07-Dec-1994
DWR #:	0	Well Depth:	20
Elevation:	1240	Static Depth to Water:	8.3
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=96255		

H46
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000094030**

Well ID:	96253	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	08-Dec-1994
DWR #:	0	Well Depth:	20
Elevation:	1240	Static Depth to Water:	9.3
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=96253		

H47
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000094038**

Well ID:	96261	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	07-Dec-1994
DWR #:	0	Well Depth:	20
Elevation:	1240	Static Depth to Water:	9.1
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=96261		

H48
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000096444**

Well ID:	98707	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	23-Mar-1995
DWR #:	0	Well Depth:	17
Elevation:	0	Static Depth to Water:	6.1
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=98707		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H49
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000096443**

Well ID:	98706	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	23-Mar-1995
DWR #:	0	Well Depth:	17
Elevation:	0	Static Depth to Water:	8.3
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=98706		

H50
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000193449**

Well ID:	407090	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	PLUGGED	Completion Date:	06-Aug-2007
DWR #:	0	Well Depth:	17.7
Elevation:	0	Static Depth to Water:	8.96
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=407090		

H51
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000225550**

Well ID:	451802	Owner:	US Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	04-Oct-2006
DWR #:	0	Well Depth:	17.47
Elevation:	0	Static Depth to Water:	11.99
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=451802		

H52
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000225549**

Well ID:	451801	Owner:	US Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	04-Oct-2006
DWR #:	0	Well Depth:	17.57
Elevation:	0	Static Depth to Water:	14.42
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=451801		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H53
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000225551**

Well ID:	451803	Owner:	US Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	04-Oct-2006
DWR #:	0	Well Depth:	17.64
Elevation:	0	Static Depth to Water:	13.33
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=451803		

H54
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000225553**

Well ID:	451805	Owner:	US Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	04-Oct-2006
DWR #:	0	Well Depth:	16.54
Elevation:	0	Static Depth to Water:	14.3
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=451805		

H55
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000225552**

Well ID:	451804	Owner:	US Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	07-Oct-2006
DWR #:	0	Well Depth:	17.42
Elevation:	0	Static Depth to Water:	17.1
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=451804		

H56
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000225545**

Well ID:	451797	Owner:	US Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	04-Oct-2006
DWR #:	0	Well Depth:	18.13
Elevation:	0	Static Depth to Water:	17.91
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		

URL: http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=451797

H57
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000225544**

Well ID:	451796	Owner:	US Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	05-Oct-2006
DWR #:	0	Well Depth:	16.5
Elevation:	0	Static Depth to Water:	16
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=451796		

H58
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000225546**

Well ID:	451798	Owner:	US Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	04-Oct-2006
DWR #:	0	Well Depth:	18.11
Elevation:	0	Static Depth to Water:	14.94
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=451798		

H59
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000225548**

Well ID:	451800	Owner:	US Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	04-Oct-2006
DWR #:	0	Well Depth:	16.77
Elevation:	0	Static Depth to Water:	15.55
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=451800		

H60
NNW
1/4 - 1/2 Mile
Higher

KS WELLS **KS9000000225547**

Well ID:	451799	Owner:	US Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	04-Oct-2006
DWR #:	0	Well Depth:	18.12
Elevation:	0	Static Depth to Water:	12.87

Est Yield:	0
Driller:	Environmental Priority Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=451799

61
NNE **KS WELLS** **KS9000000115652**
1/4 - 1/2 Mile
Lower

Well ID:	118352	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	29-Jul-1997
DWR #:	0	Well Depth:	27
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=118352		

62
NW **KS WELLS** **KS9000000115656**
1/4 - 1/2 Mile
Higher

Well ID:	118356	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	12-Jul-1997
DWR #:	0	Well Depth:	20.7
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=118356		

63
NE **KS WELLS** **KS9000000059472**
1/2 - 1 Mile
Lower

Well ID:	60346	Owner:	Hills, Darrell
Well Use:	Domestic	Status:	CONSTRUCTED
Completion Date:	26-Nov-1993	DWR #:	0
Well Depth:	47	Elevation:	0
Static Depth to Water:	10	Est Yield:	7
Driller:	Peterson Irrigation, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=60346		

I64
North **KS WELLS** **KS9000000094034**
1/2 - 1 Mile
Lower

Well ID:	96257	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	07-Dec-1994
DWR #:	0	Well Depth:	20
Elevation:	1240	Static Depth to Water:	8.1
Est Yield:	0	Driller:	GeoCore, Inc.

URL: http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=96257

I65
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000094028**

Well ID:	96251	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	08-Dec-1994
DWR #:	0	Well Depth:	22
Elevation:	1240	Static Depth to Water:	10.6
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=96251		

I66
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000115653**

Well ID:	118353	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	09-Aug-1997
DWR #:	0	Well Depth:	21
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=118353		

I67
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000094036**

Well ID:	96259	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	07-Dec-1994
DWR #:	0	Well Depth:	22
Elevation:	1240	Static Depth to Water:	12.1
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=96259		

J68
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000110439**

Well ID:	113028	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	10-Nov-1996
DWR #:	0	Well Depth:	20.8
Elevation:	0	Static Depth to Water:	8.5
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113028		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

J69
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000094025**

Well ID:	96248	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	08-Dec-1994
DWR #:	0	Well Depth:	22
Elevation:	1240	Static Depth to Water:	7.2
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=96248		

J70
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000115655**

Well ID:	118355	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	28-Jul-1997
DWR #:	0	Well Depth:	15
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=118355		

J71
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000110444**

Well ID:	113033	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	11-Nov-1996
DWR #:	0	Well Depth:	11.5
Elevation:	0	Static Depth to Water:	7.5
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113033		

K72
NNE
1/2 - 1 Mile
Lower

KS WELLS **KS9000000108757**

Well ID:	111331	Owner:	U.S. Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	24-Oct-1996
DWR #:	0	Well Depth:	19.3
Elevation:	0	Static Depth to Water:	15.88
Est Yield:	0	Driller:	US Army Corps of Engineers
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=111331		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

K73
NNE
1/2 - 1 Mile
Lower

KS WELLS **KS9000000115650**

Well ID:	118350	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	27-Jul-1997
DWR #:	0	Well Depth:	28.5
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=118350		

L74
NNW
1/2 - 1 Mile
Lower

KS WELLS **KS9000000110440**

Well ID:	113029	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	10-Nov-1996
DWR #:	0	Well Depth:	15.4
Elevation:	0	Static Depth to Water:	10
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113029		

L75
NNW
1/2 - 1 Mile
Lower

KS WELLS **KS9000000110441**

Well ID:	113030	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	09-Nov-1996
DWR #:	0	Well Depth:	9.8
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113030		

I76
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000253581**

Well ID:	487120	Owner:	Pestinger Heating and Air
Well Use:	Geothermal, Closed Loop, Vertical		
Status:	CONSTRUCTED	Completion Date:	27-Jan-2015
DWR #:	0	Well Depth:	185
Elevation:	1244	Static Depth to Water:	0
Est Yield:	20	Driller:	Associated Drilling, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=487120		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

77
South
1/2 - 1 Mile
Higher

KS WELLS **KS9000000091434**

Well ID:	93616	Owner:	SALINA AIRPORT
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	09-Aug-1994
DWR #:	0	Well Depth:	30
Elevation:	0	Static Depth to Water:	17
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=93616		

78
SSE
1/2 - 1 Mile
Higher

KS WELLS **KS9000000091433**

Well ID:	93615	Owner:	SALINA AIRPORT
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	09-Aug-1994
DWR #:	0	Well Depth:	32
Elevation:	0	Static Depth to Water:	17
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=93615		

79
WNW
1/2 - 1 Mile
Lower

KS WELLS **KS9000000128134**

Well ID:	312026	Owner:	Salina Airport Authority
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	04-Feb-2000
DWR #:	0	Well Depth:	13
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=312026		

M80
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000110448**

Well ID:	113037	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	12-Nov-1996
DWR #:	0	Well Depth:	18.9
Elevation:	0	Static Depth to Water:	7.1
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113037		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

M81
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000110449**

Well ID:	113038	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	20-Nov-1996
DWR #:	0	Well Depth:	30
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113038		

M82
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000145972**

Well ID:	331613	Owner:	Salina Area Technical School
Well Use:	Monitoring well/observation/piezometer		
Status:	PLUGGED	Completion Date:	29-Jun-2001
DWR #:	0	Well Depth:	18.91
Elevation:	0	Static Depth to Water:	14
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=331613		

N83
SSE
1/2 - 1 Mile
Higher

KS WELLS **KS9000000110426**

Well ID:	113015	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	05-Nov-1996
DWR #:	0	Well Depth:	21.5
Elevation:	0	Static Depth to Water:	15.9
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113015		

N84
SSE
1/2 - 1 Mile
Higher

KS WELLS **KS9000000115643**

Well ID:	118343	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	PLUGGED	Completion Date:	25-Aug-1997
DWR #:	0	Well Depth:	21
Elevation:	0	Static Depth to Water:	15
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=118343		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O85
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000110445**

Well ID:	113034	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	09-Nov-1996
DWR #:	0	Well Depth:	19.5
Elevation:	0	Static Depth to Water:	9.6
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113034		

O86
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000110457**

Well ID:	113046	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	04-Dec-1996
DWR #:	0	Well Depth:	23.8
Elevation:	0	Static Depth to Water:	7.4
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113046		

O87
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000214971**

Well ID:	436509	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	PLUGGED	Completion Date:	03-Aug-2010
DWR #:	0	Well Depth:	53
Elevation:	0	Static Depth to Water:	18
Est Yield:	0	Driller:	Peterson Irrigation, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=436509		

P88
NNW
1/2 - 1 Mile
Lower

KS WELLS **KS9000000110443**

Well ID:	113032	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	11-Nov-1996
DWR #:	0	Well Depth:	23.3
Elevation:	0	Static Depth to Water:	8.2
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113032		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

P89
NNW
1/2 - 1 Mile
Lower

KS WELLS **KS9000000110442**

Well ID:	113031	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	03-Dec-1996
DWR #:	0	Well Depth:	23.3
Elevation:	0	Static Depth to Water:	7.6
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113031		

P90
NNW
1/2 - 1 Mile
Lower

KS WELLS **KS9000000162231**

Well ID:	350982	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	19-Jul-2004
DWR #:	0	Well Depth:	23.3
Elevation:	0	Static Depth to Water:	8
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=350982		

P91
NNW
1/2 - 1 Mile
Lower

KS WELLS **KS9000000110447**

Well ID:	113036	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	13-Nov-1996
DWR #:	0	Well Depth:	25.4
Elevation:	0	Static Depth to Water:	5.7
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113036		

Q92
NNE
1/2 - 1 Mile
Lower

KS WELLS **KS9000000110446**

Well ID:	113035	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	12-Nov-1996
DWR #:	0	Well Depth:	18.3
Elevation:	0	Static Depth to Water:	9.4
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113035		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q93
NNE
1/2 - 1 Mile
Lower

KS WELLS **KS9000000115651**

Well ID:	118351	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	06-Aug-1997
DWR #:	0	Well Depth:	20
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=118351		

94
East
1/2 - 1 Mile
Lower

KS WELLS **KS9000000175179**

Well ID:	376481	Owner:	Marriott
Well Use:	Lawn and Garden - domestic only		
Status:	CONSTRUCTED	Completion Date:	06-Oct-2005
DWR #:	0	Well Depth:	42
Elevation:	0	Static Depth to Water:	23
Est Yield:	60		
Driller:	Pestinger Pump & Water Well Drlg., Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=376481		

R95
South
1/2 - 1 Mile
Higher

KS WELLS **KS9000000091430**

Well ID:	93612	Owner:	SALINA AIRPORT
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	09-Aug-1994
DWR #:	0	Well Depth:	32
Elevation:	0	Static Depth to Water:	24
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=93612		

R96
South
1/2 - 1 Mile
Higher

KS WELLS **KS9000000153731**

Well ID:	340260	Owner:	U.S. Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	10-Jul-2003
DWR #:	0	Well Depth:	56.5
Elevation:	0	Static Depth to Water:	23
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=340260		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

S97
South
1/2 - 1 Mile
Higher

KS WELLS **KS9000000091436**

Well ID:	93618	Owner:	SALINA AIRPORT
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	09-Aug-1994
DWR #:	0	Well Depth:	20
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=93618		

S98
South
1/2 - 1 Mile
Higher

KS WELLS **KS9000000091438**

Well ID:	93620	Owner:	SALINA AIRPORT
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	09-Aug-1994
DWR #:	0	Well Depth:	24
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=93620		

99
SW
1/2 - 1 Mile
Higher

KS WELLS **KS9000000059864**

Well ID:	60738	Owner:	PONY EXPRESS
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	07-Jul-1989
DWR #:	0	Well Depth:	20
Elevation:	0	Static Depth to Water:	7
Est Yield:	0		
Driller:	Pestinger Pump & Water Well Drlg., Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=60738		

T100
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000110452**

Well ID:	113041	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	22-Nov-1996
DWR #:	0	Well Depth:	19.8
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113041		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

T101
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000110453**

Well ID:	113042	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	21-Nov-1996
DWR #:	0	Well Depth:	23
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113042		

U102
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000110451**

Well ID:	113040	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	23-Nov-1996
DWR #:	0	Well Depth:	19
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113040		

U103
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000214970**

Well ID:	436508	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	PLUGGED	Completion Date:	03-Aug-2010
DWR #:	0	Well Depth:	56
Elevation:	0	Static Depth to Water:	18
Est Yield:	0	Driller:	Peterson Irrigation, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=436508		

V104
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000115649**

Well ID:	118349	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	25-Jul-1997
DWR #:	0	Well Depth:	25.6
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=118349		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

V105
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000115665**

Well ID:	118365	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	09-Jul-1997
DWR #:	0	Well Depth:	30
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=118365		

106
South
1/2 - 1 Mile
Higher

KS WELLS **KS9000000245052**

Well ID:	485802	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	27-Oct-2014
DWR #:	0	Well Depth:	32
Elevation:	1261.81	Static Depth to Water:	12
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=485802		

107
NNW
1/2 - 1 Mile
Lower

KS WELLS **KS9000000110450**

Well ID:	113039	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	24-Nov-1996
DWR #:	0	Well Depth:	19
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=113039		

108
SSW
1/2 - 1 Mile
Higher

KS WELLS **KS9000000091431**

Well ID:	93613	Owner:	SALINA AIRPORT
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	09-Aug-1994
DWR #:	0	Well Depth:	27
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	GeoCore, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=93613		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

W109
NNE
1/2 - 1 Mile
Lower

KS WELLS **KS9000000153349**

Well ID:	339854	Owner:	U.S. Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	26-Jul-2003
DWR #:	0	Well Depth:	24
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Plains Environmental Services
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=339854		

W110
NNE
1/2 - 1 Mile
Lower

KS WELLS **KS9000000153350**

Well ID:	339855	Owner:	U.S. Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	28-Jul-2003
DWR #:	0	Well Depth:	12
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Plains Environmental Services
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=339855		

W111
NNE
1/2 - 1 Mile
Lower

KS WELLS **KS9000000154317**

Well ID:	340895	Owner:	U.S. Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	PLUGGED	Completion Date:	01-Aug-2003
DWR #:	0	Well Depth:	12
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Plains Environmental Services
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=340895		

112
SW
1/2 - 1 Mile
Higher

KS WELLS **KS9000000108752**

Well ID:	111326	Owner:	U.S. Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	19-Oct-1996
DWR #:	0	Well Depth:	21.9
Elevation:	0	Static Depth to Water:	12.4
Est Yield:	0	Driller:	Not Reported
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=111326		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

113
ENE
1/2 - 1 Mile
Lower

KS WELLS **KS9000000131945**

Well ID:	315930	Owner:	Hills, Darrell
Well Use:	Lawn and Garden - domestic only		
Status:	CONSTRUCTED	Completion Date:	30-Sep-2000
DWR #:	0	Well Depth:	50
Elevation:	0	Static Depth to Water:	11
Est Yield:	7	Driller:	Peterson Irrigation, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=315930		

X114
WSW
1/2 - 1 Mile
Higher

KS WELLS **KS9000000108750**

Well ID:	111324	Owner:	U.S. Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	17-Oct-1996
DWR #:	0	Well Depth:	24.7
Elevation:	0	Static Depth to Water:	1.85
Est Yield:	0	Driller:	Not Reported
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=111324		

X115
WSW
1/2 - 1 Mile
Higher

KS WELLS **KS9000000108751**

Well ID:	111325	Owner:	U.S. Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	18-Oct-1996
DWR #:	0	Well Depth:	24.5
Elevation:	0	Static Depth to Water:	5.3
Est Yield:	0	Driller:	Not Reported
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=111325		

116
North
1/2 - 1 Mile
Lower

KS WELLS **KS9000000115664**

Well ID:	118364	Owner:	USACE
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	23-Jul-1997
DWR #:	0	Well Depth:	31.5
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Cahoy Pump Service, Inc.
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=118364		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

117
NNE
1/2 - 1 Mile
Lower

KS WELLS **KS9000000153352**

Well ID:	339857	Owner:	U.S. Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	26-Jul-2003
DWR #:	0	Well Depth:	56
Elevation:	0	Static Depth to Water:	0
Est Yield:	0	Driller:	Plains Environmental Services
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=339857		

118
WSW
1/2 - 1 Mile
Higher

KS WELLS **KS9000000245056**

Well ID:	485806	Owner:	City of Salina
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	03-Dec-2014
DWR #:	0	Well Depth:	48
Elevation:	1273.74	Static Depth to Water:	12
Est Yield:	0		
Driller:	Environmental Priority Service, Inc.		
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=485806		

119
NNW
1/2 - 1 Mile
Lower

KS WELLS **KS9000000108759**

Well ID:	111333	Owner:	U.S. Army Corps of Engineers
Well Use:	Monitoring well/observation/piezometer		
Status:	CONSTRUCTED	Completion Date:	22-Oct-1996
DWR #:	0	Well Depth:	15.5
Elevation:	0	Static Depth to Water:	6.25
Est Yield:	0	Driller:	U.S. Army Corps of Engineers
URL:	http://chasm.kgs.ku.edu/ords/wwc5.wwc5d2.well_details?well_id=111333		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: KS Radon

Radon Test Results

Zipcode	Avg Radon	Max Radon	Num Tests
67401	5.9	58.0	1131

Federal EPA Radon Zone for SALINE County: 1

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 67401

Number of sites tested: 24

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	2.567 pCi/L	100%	0%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	5.804 pCi/L	50%	46%	4%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: US Fish & Wildlife Service
Telephone: 703-358-2171

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Kansas Water Well Completion Records Database
Source: Kansas Geological Survey
Telephone: 913-864-3965

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Location Database Listing
Source: Kansas Geological Survey
Telephone: 785-864-3965

RADON

State Database: KS Radon
Source: Department of Health & Environment
Telephone: 785-296-1500
Kansas Indoor Radon Measurements

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

Salina AASF

2917 Hein Avenue

Salina, KS 67401

Inquiry Number: 5776851.3

September 04, 2019

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

09/04/19

Site Name:	Client Name:
Salina AASF	AECOM
2917 Hein Avenue	12120 Shamrock Plaza
Salina, KS 67401	Omaha, NE 68154
EDR Inquiry # 5776851.3	Contact: Hans Sund

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by AECOM were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # FC1E-4799-8089

PO # NA

Project Salina AASF

UNMAPPED PROPERTY

This report certifies that the complete holdings of the Sanborn Library, LLC collection have been searched based on client supplied target property information, and fire insurance maps covering the target property were not found.

Sanborn® Library search results

Certification #: FC1E-4799-8089

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

AECOM (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2019 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Appendix B
Preliminary Assessment Documentation

Appendix B.1
Interview Records

PA Interview Questionnaire - Other

Facility: Topeka AASF #1 and Salina AASF #2
Interviewer: [redacted]
Date/Time: 8/27/19 1100 and 8/28/19 0900

Interviewee: [redacted] **Title: EPAS Compliance Manager** **Phone Number:** [redacted] **Email:** [redacted]	Can your name/role be used in the PA Report? **Y** or N Can you recommend anyone we can interview? Y or **N** _____

Roles or activities with the Facility/Years working at the Facility:

[redacted] is currently the EPAS Compliance Manager for the Topeka AASF #1 and Salina AASF #2.

PFAS Use: Identify accidental/intentional release locations, time frame of release, frequency of releases, storage container size (maintenance, fire training, firefighting, buildings with suppression systems (as builts), fueling stations, crash sites, pest management, recreational, dining facilities, metals plating, or waterproofing). How are materials ordered/purchased/disposed/shared with others?

[redacted] provided clarity on the type of AFFF fire extinguisher that was at the Topeka AASF #1 and Salina AASF #2. Both AASFs had Alcohol Resistant AFFF foam Ansul™ fire extinguishers (Ansul™ AR-33-D) with a 15% AFFF solution. After the contents were containerized, the actual fire extinguishers were shipped to the USP&FO/Quality Recycling Program (QRP) in Topeka for recycling as scrap metal.

[redacted] also provided photo documentation of the Ansul™ AR-33-D fire extinguishers for Topeka AASF and Salina AASF.

Known Uses
Use
Procurement
Disposition
Storage (Mixed)
Storage (Solution)
Inventory, Off-Spec
Containment
SOP on Filling
Leaking Vehicles
Nozzle and Suppression System Testing
Dining Facilities
Vehicle Washing
Ramp Washing
Fuel Spill Washing and Fueling Stations
Chrome Plating or Waterproofing

PA Interview Questionnaire - Environmental Manager

Facility: AASF #2
Interviewer:
Date/Time: 15 AUG 19

Interviewee: [redacted] **Title:** OPERATIONS OFFICER **Phone Number:** [redacted] **Email:** [redacted]	Can your name/role be used in the PA Report? (Y) or N Can you recommend anyone we can interview? Y or (N)

1. Roles or activities with the Facility/years working at the Facility.
   FULL TIME SINCE JULY 2000, PART TIME FROM 1987 – 2000.
   PILOT / INSTRUCTOR PILOT / OPERATIONS OFFICER

2. Where can I find previous facility ownership information?
   SALINA AIRPORT AUTHORITY
   [redacted]

3. What can you tell us about the history of PFAS including aqueous film forming foam (AFFF) at the Facility? Was it used for any of the following activities, circle all that apply and indicate years of active use, if known? Identify these locations on a facility map.

   Maintenance
   Fire Training Areas
   Firefighting (Active Fire)
   Crash
   Fire Suppression Systems (Hangers/Dining Facilities)
   (Fire Protection at Fueling Stations)
   Non-Technical/Recreational/ Pest Management
   Metals Plating Facility
   Waterproofing Uniforms (Laundry Facilities)
   Other

   IN USE APPROX EARLY 90's FOR A SHORT NUMBER OF YEARS

   NO RELEASE OF AGENT AT AASF 2

4. Fill out CSM Information worksheet with the Environmental Manager.

5. Are any current buildings constructed with AFFF dispensing systems or fire suppression systems? NO
   What are the AFFF/suppression system test requirements? What is the frequency of testing the AFFF/suppression system? Do you have "As Built" drawings for the buildings?

   NO INSTALLED SYSTEM

PA Interview Questionnaire - Environmental Manager

Facility: AASF #2
Interviewer:
Date/Time: 15 AUG 19

6. Are fire suppression systems currently charged with AFFF or have they been retrofitted for use of high expansion foam? If retrofitted, when was that done?

   NONE INSTALLED

7. How is AFFF procured? Do you have an inventory/procurement system that tracks use?

   NA

8. What type of AFFF has been/is being used (3%, 6%, Mil Spec Mil-F-24385, High Expansion)? Manufacturer (3M, Dupont, Ansul, National Foam, Angus, Chemguard, Buckeye, Fire Service Plus)?

   I DO NOT HAVE RECORD OF TYPE

9. Where is the AFFF stored? How is it stored (tanks, 55-gallon drums, 5-gallon buckets)? What size are the storage tanks? Is the AFFF stored as a mixed solution (3% or 6%) or concentrated material?

   NA

10. How many FTAs are/were on this facility and where are they? Locate on a map. How many FTAs are active and inactive? For inactive FTAs, when was the last time that fire training using AFFF was conducted at them?

    NO FIRE TRAINING AREA ESTABLISHED AT AASF #2

PA Interview Questionnaire - Environmental Manager

Facility: AASF #2
Interviewer:
Date/Time: 15 AUG 19

11. When a release of AFFF occurs during a fire training exercise, now and in the past, how is the AFFF cleaned and disposed of? Were retention ponds built to store discharged AFFF? Was the AFFF trickled to the sanitary sewer or left in the pond to infiltrate?

NO RELEASE OF AGENT FOR TRAINING

12. Can you recall specific times when city, county, and/or state personnel came on-post for training? If so, please state which state/county agency or military entity? Do you have any records, including photographs to share with us?

NO

13. Did military routinely or occasionally fire train off-post? List the units that you can recall used/trained at various areas.

NO

14. Did individual units come with their own safety personnel, did they also bring their own AFFF? Was training with AFFF part of these exercises? How were emergencies handled under these circumstances?

NO AGENT USE AT AASF2 FROM 1985 - TO CURRENT EITHER BY MIL OR CIV FIRE FIGHTING TEAMS / CIVE OR TRAINING

15. Are there specific emergency response incident reports (i.e., aircraft or vehicle crash sites and fires)? If so, may we please copy these reports? Who (entity) was the responder?

NONE

PA Interview Questionnaire - Environmental Manager

Facility: AASF#2
Interviewer:
Date/Time: 15 AUG 19

16. Do you have records of fuel spill logs? Was it common practice to wash away fuel spills with AFFF? Is/was AFFF used as a precaution in response to fuel releases or emergency runway landings to prevent fires?

NO AFFF USED ON FUEL SPILLS

17. Was AFFF used for forest fires or fire management on-post/off-post? If so, please describe what happened and who was involved?

NO USED

18. Are there mutual aid/use agreements between county, city, and local fire department? Please list, even if informal. If formalized, may we have a copy of the agreement?

NO

19. Can you provide any other locations where AFFF has been stored, released, or used (i.e. hangars, buildings, fire stations, firefighting equipment testing and maintenance areas, emergency response sites, storm water/surface water, waste treatment plants, and AFFF ponds)?

NONE IN OUR AREA.

20. Are you aware of any other creative uses of AFFF? If so, how was AFFF used? What entities were involved?

NONE

PA Interview Questionnaire - Environmental Manager

Facility: AASF # 2
Interviewer:
Date/Time: 15 AUG 19

21. Are there past studies you are aware of with environmental information on plants/animals/ groundwater/soil types, etc., such as Integrated Cultural Resources Management Plans or Integrated Natural Resources Management Plans?

I AM NOT AWARE

22. What other records might be helpful to us (environmental compliance, investigation records, admin record) and where can we find them?

OUR ~~ENVIRONMENTAL~~ HAZMAT RECORDS / SALINA AIRPORT AUTHORITY

23. Do you have or did you have a chrome plating shop on base? What were/are the years of operation of that chrome plating shop?

NO

24. Do you know whether the shop has/had a foam blanket mist suppression system or used a fume hood for emissions control? If foam blanket mist suppression was used, where was the foam stored, mixed, applied, etc.?

NA

25. How is off-spec AFFF disposed (used for training, turned in, or given to a local Fire Station)? If applicable, do you know the name of the vendor that removes off-spec AFFF? Do you have copies of the manifest or B/L?

NA

PA Interview Questionnaire - Environmental Manager

Facility: AA SF #2
Interviewer:
Date/Time: 15AUG19

26. Do you recommend anyone else we can interview? If so, do you have contact information for them?

Preliminary Assessment – Pre-Interview Form

1. Installation Name: Salina AASF #2

2. Primary Points of Contact:(Name/Title/Telephone Number/Email Address):

ARNG:	[redacted], EPAS Compliance Manager, [redacted]; [redacted]
USACE:	Unknown
Installation:	Bldg. Mgr.: [redacted] (while CW4 Hoover is deployed); [redacted] [redacted] EC: [redacted] Facility Commander: [redacted]; ([redacted]; [redacted]

3. Suggested Personnel to Interview (Name/Title/Number of Years at Installation/Retired):

[redacted] – former facility personnel

[redacted] – former facility personnel

4. Is the ARNG property an enclave of a larger facility? What command or authority controls that facility? DoD or non-DoD? Does the facility have other DoD enclaves?

Not an enclave. Salina Airport Authority owns the property. KSARNG is a Real Property Accountable Officer (RPAO). KSARNG has a lease from Salina Airport Authority, signed March 1, 1988 and leased for 99 years.

5. Installation History (dates of operation, types of activity, active airfield, firefighting training):

1942-1943 – Smoky Hill Army Airfield (AAF) is built on 2,600 acres SW of Salina, KS.

Sep 1, 1942 – Smoky Hill Army Airfield is officially activated.

Sep 1, 1945 – Smoky Hill Army Airfield was designated a permanent airfield by HQ USAAF.

Mar 21, 1946 – Continental Air Forces (CAFs) were disestablished and reorganized by the USAAF into bases for Strategic Air Command (SAC).

Sep 1947 – Establishment of the United States Air Force (USAF).

Jan 1948 – The USAF changed the name to Smoky Hill Air Force Base.

1949 – SAC decides to close Smoky Hill AFB due to budget constraints.

Aug 1, 1951 – Smoky Hill AFB reactivated by SAC due to Air Force's needs from the Korean War.

1952 – Significant construction and upgrades add a 12,300 foot jet runway and expanded parking apron and jet fuel facilities.

Mar 16, 1957 – Smoky Hill AFB re-designated Schilling Air Force Base.

1959 – U.S. Army Surface-to-air missile sites were constructed near Bennington and Smolan, KS but never made operational.

(Attach to the front of the Interview Form)

Preliminary Assessment – Pre-Interview Form

Mar 1, 1962 – Strategic Missile Squadron re-designated as 310th Strategic Aerospace Wing.

May 1965 – Salina Airport Authority is created and begins conversion of Schilling AFB to the Salina Municipal Airport and Salina Airport Industrial Center.

Oct 1, 1965 – Schilling AFB was officially closed after phase out of strategic missile squadron (1964).

1973 – Kansas Air National Guard assumed all operating and maintenance authority for the 34,000 acre Smoky Hill Air National Guard (ANG) Range, located 10 miles south of Salina, KS.

[Jan 1, 1974 – Kansas Army National Guard takes occupation at Salina AASF 2, according to Real Property FISP.]

Today - Salina Regional Airport (formerly Salina Municipal Airport) – owned by Salina Airport Authority. Also home to Kansas State University Polytechnic Campus Aviation Program.

6. Potential Sites to Investigate (hangars, airstrips, FTAs, TAs, paint shops and kitchen AFFF, plating areas):

Hangars, airstrips (flight line)

FTAs (Fire-Training Areas) – unknown; TAs (Training Areas) - unknown

No paint shop, kitchen AFFF or plating areas

7. Have we requested the following information from ARNG?

Lease Information	**YES** / NO	Comment: KSARNG has a lease from Salina Airport Authority, signed March 1, 1988 and leased for 99 years.
Material Purchase Information	YES / **NO**	Comment: Purchase information for AFFF products (procurement & disposal); service reg. of extinguishers? – No information found by CW2 Burgoon, USP&FO Federal Warehouse Supervisor
Permit/Transfer Documents	**YES** / NO	Comment: Permits and transfer of AFFF products? – Have former inventory of AFFF extinguishers at AASF 1 and AASF 2 (See below for disposal information)
Disposition Records for AFFF	**YES** / NO	Comment: Memo to NGB 12 Sep 2016 – four canisters drained on AASF 1. One more canister at AASF 1 and 8 canisters at AASF 2 marked "unserviceable" have been disposed of. KSARNG Hazardous Waste Manager will be providing disposal documentation.

8. Does the Installation have an Administrative Record or a Document Repository? If so, does the installation have the following types of documents? Circle all that apply.

Historical Records Review	Some
Preliminary Assessment	Unknown
Site Inspections	Copy of Safety inspections – with Facility Safety Officers

(Attach to the front of the Interview Form)

Preliminary Assessment – Pre-Interview Form

	(Copy of IEPAS/EPAS Environmental Inspections are available upon request)
Remedial Investigation	KDHE - Schilling Remedial Investigation Rpt Rev1pt1_2018 May 18 KDHE - Schilling_Remedial Investigation 3_GW test_2018 Apr 11
Remedial Action Documentation	KDHE – Schilling_Draft_Corrective Action Decision_2019 Apr 08
Cultural Resources Management Plan	KSARNG 2010 ICRMP
~~**Natural Resources Management Plan**~~	KSARNG INRMP only applies to KSTC.
~~**Annual TAG Reports**~~	N/A
Firefighting Training Records (if documented)	Unknown
~~**As Built Drawings for Buildings with AFFF Systems**~~	Current buildings have no AFFF systems
~~**Fire Suppression in Dining Facilities**~~	No dining facility at AASF 2
Responded to an Aircraft Crash	No aircraft crashes in recent history
Responded to Forest Fires	No forest fires in recent history
Federal Facility Agreement	Unknown
State Permit	Have: NPDES Industrial Stormwater Permit (included in SWPPP) KDHE Emergency Power Generator Construction Approval (AASF 2)
RCRA Permit	HW Verification Report and KDHE/EPA ID permit
NPDES Permit	Included in Topeka AASF #2 SWPPP
Environmental Baseline Study	Unknown
Groundwater Flow Information	KDHE – Schilling_GWModeling_2018 May 30 KDHE – Schilling_Supp Remedial Investigation 3_GW test_2018 Apr 11 **(*Total PFAS reported)**
Groundwater Studies	KDHE – Schilling_GWModeling_2018 May 30 KDHE – Schilling_Supp Remedial Investigation 3_GW test_2018 Apr 11 **(*Total PFAS reported)**
Groundwater Treatment Units	None
Groundwater Monitoring Well Location Map	KDHE – Schilling_GWModeling_2018 May 30

(Attach to the front of the Interview Form)

Preliminary Assessment – Pre-Interview Form

	KDHE – Schilling_Supp Remedial Investigation 3_GW test_2018 Apr 11 **(*Total PFAS reported)**
Surface Water Flow Information	Included in Salina AASF #2 SWPPP.
Historical Aerials	USGS_Salina Regional Airport_1991 Schilling AFB_USGS_2006

9. What GIS data do we have (e.g., HQANG GIS)? Do we need (e.g., State GIS)? Will aerial photographs be needed? (These files will be asked for during the interview)

NOTE: Nothing is mapped outside of the facility boundary lines.

Available GIS information:

- Aerial Photo Layers (historic if available) – Digital Globe
- Roads with labels (but no names)
- Buildings with labels
- Lease/ownership-related boundaries with labels
- AASF 2 parking ramp only (no runways)
- Surface Waterways (lakes, creeks, streams, ponds, etc.)
- Sanitary Sewer – with DI's/cleanouts, etc.
- Water main/secondary water piping

(Attach to the front of the Interview Form)

PA Interview Questionnaire - Other

Facility: Salina AASF #2
Interviewer: [redacted]
Date/Time: 8/28/19 0900

Interviewee: [redacted] **Title: Back Shops Supervisor** **Phone Number:** [redacted] **Email:** [redacted]	Can your name/role be used in the PA Report? **Y** or N Can you recommend anyone we can interview? Y or **N** _____

Roles or activities with the Facility/Years working at the Facility:

[redacted] has been with the Salina AASF #2 for 10 years and currently serves as the Back Shops Supervisor.

PFAS Use: Identify accidental/intentional release locations, time frame of release, frequency of releases, storage container size (maintenance, fire training, firefighting, buildings with suppression systems (as builts), fueling stations, crash sites, pest management, recreational, dining facilities, metals plating, or waterproofing). How are materials ordered/purchased/disposed/shared with others?

The AASF opened in 1985. In approximately 2001, AFFF fire extinguishers (unknown type) arrived at the facility. The AASF was required to have 1 fire extinguisher on the ramp area for every 3 aircrafts. At the time, there were 7 total AFFF fire extinguishers on the ramp area. They had one AFFF fire extinguisher filled with water only for a one-time training event. They used one of their ABC indoor fire extinguishers to conduct yearly fire training. In 2015, the AFFF fire extinguishers were stored outside on the northwest perimeter of the main hangar. There was no report of any leaking from the fire extinguishers. The 7 AFFF fire extinguishers were stored there until August 2019, when the contents were containerized into 55-gallon drums then brought to Topeka AASF for further disposal. [redacted] stated that there were no spills or leaking when containerizing the AFFF.

The AFFF fire extinguishers were never dispensed on the ramp area or used in any fire.

The Salina Airport Authority responds to emergencies at the AASF. The Salina Airport Authority Fire Department has AFFF and Purple K fire extinguishers, however they have never responded to any emergencies at the airport in his time at the AASF.

Known Uses
Use
Procurement
Disposition
Storage (Mixed)
Storage (Solution)
Inventory, Off-Spec
Containment
SOP on Filling
Leaking Vehicles
Nozzle and Suppression System Testing
Dining Facilities
Vehicle Washing
Ramp Washing
Fuel Spill Washing and Fueling Stations
Chrome Plating or Waterproofing

PA Interview Questionnaire - Other

Facility: Salina AASF #2
Interviewer: [redacted]
Date/Time: 8/28/19 0900

Interviewee: [redacted] **Title: Environmental Coordinator** **Phone Number:** [redacted] **Email:** [redacted]	Can your name/role be used in the PA Report? **Y** or N Can you recommend anyone we can interview? Y or **N** _____

Roles or activities with the Facility/Years working at the Facility:

[redacted] has been at the facility for 6 months and currently serves as the Environmental Coordinator.

PFAS Use: Identify accidental/intentional release locations, time frame of release, frequency of releases, storage container size (maintenance, fire training, firefighting, buildings with suppression systems (as builts), fueling stations, crash sites, pest management, recreational, dining facilities, metals plating, or waterproofing). How are materials ordered/purchased/disposed/shared with others?

[redacted] confirms that there was 7 AFFF fire extinguishers and 1 fire extinguisher that only had water in it for training purposes. In August 2019, the 7 AFFF fire extinguishers were containerized into five 55-gallon drums and we brought to the Topeka AASF for further disposal. The 7 AFFF fire extinguishers were on the ramp area for approximately 15 years and were serviced by contractors. There were no releases of AFFF. The AFFF fire extinguishers were replaced by Purple K mobile fire extinguishers.

Known Uses
Use
Procurement
Disposition
Storage (Mixed)
Storage (Solution)
Inventory, Off-Spec
Containment
SOP on Filling
Leaking Vehicles
Nozzle and Suppression System Testing
Dining Facilities
Vehicle Washing
Ramp Washing
Fuel Spill Washing and Fueling Stations
Chrome Plating or Waterproofing

Appendix B.2
Visual Site Inspection Checklists

Visual Site Inspection Checklist

Names(s) of people performing VSI: [redacted]

Recorded by: [redacted]

ARNG Contact: [redacted]

Date and Time: 8/28/19 0900

Method of visit (walking, driving, adjacent): walking, driving

Source/Release Information

Site Name / Area Name / Unique ID: Salina AASF #2

Site / Area Acreage: approximately 12 acres

Historic Site Use (Brief Description):

The AASF was built in 1942 as the Smoky Hill Army Airfield. In 1974, the Kansas Army National Guard took occupation as Salina AASF #2. In 1988, the Salina Airport Authority issued a license for the KSARNG to use the facility for a term of 99 years.

Current Site Use (Brief Description):

The AASF supports the Kansas Army National Guard (KSARNG).

Physical barriers or access restrictions:

Access to the area is restricted to KSARNG.

1. Was PFAS used (or spilled) at the site/area? Y / **N**

1a. If yes, document how PFAS was used and usage time (e.g., fire fighting training 2001 to 2014):

Never actually dispensed.

2. Has usage been documented? Y / **N**

2a. If yes, keep a record (place electronic files on a disk):

N/A

3. What types of businesses are located near the site? **Industrial / Commercial / Plating / Waterproofing / Residential**

3a. Indicate what businesses are located near the site

Salina Municipal Airport

4. Is this site located at an airport/flightline? **Y** / N

4a. If yes, provide a description of the airport/flightline tenants:

Salina Municipal Airport

Visual Site Inspection Checklist

Other Significant Site Features:

1. Does the facility have a fire suppression system? Y / **N**

1a. If yes, indicate which type of AFFF has been used:
N/A

1b. If yes, describe maintenance schedule/leaks:
N/A

1c. If yes, how often is the AFFF replaced:
N/A

1d. If yes, does the facility have floor drains and where do they lead? Can we obtain an as built drawing?
The floor drains lead to an oil/water separator then to the sanitary WWTP.

Transport / Pathway Information

Migration Potential:

1. Does site/area drainage flow off installation? **Y** / N

1a. If so, note observation and location:
Surface water flows to the north off the installation.

2. Is there channelized flow within the site/area? Y / **N**

2a. If so, please note observation and location:

3. Are monitoring or drinking water wells located near the site? **Y** / N

3a. If so, please note the location:
There are monitoring wells surrounding the facility, and
domestic wells to the east of the facility (across the road and creek).

4. Are surface water intakes located near the site? Y / **N**

4a. If so, please note the location:

5. Can wind dispersion information be obtained? Y / **N**

5a. If so, please note and observe the location.
N/A

6. Does an adjacent non-ARNG PFAS source exist? **Y** / N

6a. If so, please note the source and location.
Yes, potentially Salina Municipal Airport.

6b. Will off-site reconnaissance be conducted? Y / **N**

Visual Site Inspection Checklist

Significant Topographical Features:

1. Has the infrastructure changed at the site/area? Y / **N**

1a. If so, please describe change (ex. Structures no longer exist):

2. Is the site/area vegetated? **Y** / N

2a. If not vegetated, briefly describe the site/area composition:

vegetated except for ramp and parking areas

3. Does the site or area exhibit evidence of erosion? Y / **N**

3a. If yes, describe the location and extent of the erosion:

4. Does the site/area exhibit any areas of ponding or standing water? Y / **N**

4a. If yes, describe the location and extent of the ponding:

Receptor Information

1. Is access to the site restricted? **Y** / N

1a. If so, please note to what extent:

The facility has controlled access

2. Who can access the site? **Site Workers / Construction Workers / Trespassers / Residential / Recreational Users / Ecological**

2a. Circle all that apply, note any not covered above:

3. Are residential areas located near the site? **Y** / N

3a. If so, please note the location/distance:

Residents to the east

4. Are any schools/day care centers located near the site? **Y** / N

4a. If so, please note the location/distance/type:

There is 1 elementary school within 1 mile.

5. Are any wetlands located near the site? Y / **N**

5a. If so, please note the location/distance/type:

Visual Site Inspection Checklist

Additional Notes

Photographic Log

Photo ID/Name	Date & Location	Photograph Description
1	8/28/19, north side of hangar	One of the Ansul fire extinguishers that was containerized and sent to Topeka AASF #1. Fire extinguishers were not on facility during VSI. Picture curtesy of KSARNG.
2	8/28/19, north side of hangar	Close up of one of the Ansul fire extinguishers that was containerized and sent to Topeka AASF #1. Fire extinguishers were not on facility during VSI. Picture curtesy of KSARNG.
3	8/28/19, north side of hangar	All the AFFF fire extinguishers in storage on the north side of the hangar. Fire extinguishers were not on facility during VSI. Picture curtesy of KSARNG.
4	8/28/19, north side of hangar	The same location as Picture No. 3, but after the AFFF fire extinguishers were removed and sent to Topeka AASF #1.

Appendix B.3
Conceptual Site Model Information

Preliminary Assessment – Conceptual Site Model Information

Site Name: Salina Army Aviation Support Facility #2

Why has this location been identified as a site?
Facility is an aviation support site with aircraft hangars, high probability of release due to asset type and historical site usage.

Are there any other activities nearby that could also impact this location?
Yes, the potential adjacent sources include the Salina Municipal Airport.

Training Events

Have any training events with AFFF occurred at this site? *No*

If so, how often? *n/a.*

How much material was used? Is it documented*? n/a.*

Identify Potential Pathways: Do we have enough information to fully understand over land surface water flow, groundwater flow, and geological formations on and around the facility? Any direct pathways to larger water bodies?

Surface Water:

Surface water flow direction? *To the north*

Average rainfall? *30.6 inches*

Any flooding during rainy season? *unknown*

Direct or indirect pathway to ditches? *indirect*

Direct or indirect pathway to larger bodies of water? *indirect to Dry Creek.*

Does surface water pond any place on site? *Did not appear to be areas with ponded water.*

Any impoundment areas or retention ponds? *No*

Any NPDES location points near the site? *unknown*

How does surface water drain on and around the flight line? *Around the flight line, the surface water drains east to Dry Creek.*

Groundwater:

Groundwater flow direction? *Groundwater flow is generally from the west to the east following surface topography.*

Depth to groundwater? *22-60 feet*

Uses (agricultural, drinking water, irrigation)? *Not used.*

Any groundwater treatment systems? *unknown*

Any groundwater monitoring well locations near the site? Y*es*

Preliminary Assessment – Conceptual Site Model Information

Is groundwater used for drinking water? *Drinking water is supplied by the City of Salina, which sources drinking water from 17 groundwater wells within the city, and surface water from the Smoky Hill River.*

Are there drinking water supply wells on installation? *No*

Do they serve off-post populations? n/a

Are there off-post drinking water wells downgradient? *Yes, there are two downgradient and several to the east of the facility.*

Waste Water Treatment Plant:

Has the installation ever had a WWTP, past or present? *No*

If so, do we understand the process and which water is/was treated at the plant? *N/A*

Do we understand the fate of sludge waste? *N/A*

Is surface water from potential contaminated sites treated? *N/A*

Equipment Rinse Water

1. Is firefighting equipment washed? Where does the rinse water go?
No firefighting equipment ever washed at the AASF.

2. Are nozzles tested? How often are nozzles tested? Where are nozzles tested? Are nozzles cleaned after use? Where does the rinse water flow after cleaning nozzles?
n/a

3. Other?
Firefighting services for the AASF are provided by the Salina Airport Authority FD.

Identify Potential Receptors:

Site Worker *Yes*

Construction Worker *Yes*

Recreational User *No*

Residential *No*

Child *No*

Ecological *No*

Note what is located near by the site (e.g. daycare, schools, hospitals, churches, agricultural, livestock)?
One school is within one mile of the facility.

Documentation

Ask for Engineering drawings (if applicable). Has there been a reconstruction or changes to the drainage system? When did that occur? *No.*

Appendix C
Photographic Log

APPENDIX C – Photographic Log

Army National Guard, Preliminary Assessment for PFAS	Salina AASF #2	Kansas

Photograph No. 1

Description:

One of the Ansul fire extinguishers that was containerized and sent to Topeka AASF #1. Fire extinguishers were not on facility during VSI.

Photo courtesy of KSARNG.

30 August 2019



Photograph No. 2

Description:

Close up of one of the Ansul fire extinguishers that was containerized and sent to Topeka AASF #1. Fire extinguishers were not on facility during VSI.

Photo courtesy of KSARNG.

30 August 2019



APPENDIX C – Photographic Log

Army National Guard, Preliminary Assessment for PFAS	Salina AASF #2	Kansas

Photograph No. 3

Description:

All the AFFF fire extinguishers in storage on the north side of the hangar. Fire extinguishers were not on facility during VSI.

Photo courtesy of KSARNG

30 August 2019



Photograph No. 4

Description:

The same location as Photo No. 3, the AFFF fire extinguishers are no longer present at the AASF.

28 August 2019

